

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE Cardinal Health REPORT NUMBER(S) 2006-017		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-36973	4. LICENSE NUMBER(S) 34-29200-01MD	5. DATE(S) OF INSPECTION 07/28/2006	
6. INSPECTION PROCEDURES USED 87127	7. INSPECTION FOCUS AREAS 3/01-07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 2500	2. PRIORITY 2	3. LICENSEE CONTACT Sharon Jackson	4. TELEPHONE NUMBER 818/737-4515
----------------------------	------------------	---------------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: 07/08

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE
Program Scope
87127

The licensee is a regional division of the Cardinal Health chain located in Swartz Creek, MI. This radiopharmacy employs three pharmacists, two pharmacy techs and approximately twelve drivers. Currently the licensee has approximately 300+ customers located in the north eastern Michigan area. The pharmacy serves its customers from approximately 4:00am to 3:00pm daily including Saturdays and Sundays. Licensee's first run starts about 4:30am and continues throughout the day. This pharmacy receives Mo99/Tc99m generators each week for the preparation of unit doses to be distributed to clients. This pharmacy prepares approximately 100mCi. of iodine-131 for distribution weekly. All iodine work is performed in a room with dedicated air handling systems.

Performance Observations

During the inspection, the inspector toured the facility and observed the preparation of unit doses destined for clients. The inspector observed shipping procedures being performed and interviewed the staff concerning their roles in the process. The inspector determined that they possessed an adequate level of knowledge of shipping requirements. The inspector performed confirmatory surveys of the restricted area and the results were similar to those of the licensee. Conversations between the inspector and licensee staff provided assurances that licensee staff had an adequate knowledge of radiation safety.

Independent surveys performed by the inspector did not detect any unusual or unexpected readings. No abnormal conditions were detected.