Official Use O	nly - Security-R	elated Information

NRC FORM 591M PART 1 (10-2003)		U.S. NUCLEAR REGULATORY	COMMISSION
10 CFR 2.201 SAFETY II	NSPECTION REPORT A	ND COMPLIANCE INSPECTION	
LICENSEE/LOCATION INSPECTED: Cabrera Services, Inc./Lake City A		NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III, 2443 Warrenville Road	
Plant Area 31, Independence, Mis		Suite 210 Lisle Illinois, 60532-4352	
REPORT 03035316/06-001			
B. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION	
030-35316	06-30556-01	11/8-9/2006	
ICENSEE: Cabrera Services, Inc.			
Regulatory Commission (NRC) rules and regul	lations and the conditions of you ews with personnel, and observ	nse as they relate to radiation safety and to compliance with ir license. The inspection consisted of selective examinatio ations by the inspector. The inspection findings are as follo	ns of
		non-cited violations, are not being cited because they were a emaining criteria in the NRC Enforcement Policy, NUREG-1	
Non-Cited Violation(s) was/v	vere discussed involving the follo	owing requirement(s) and Corrective Action(s):	
		w and/or attached, were in violation of NRC requirements ar	nd are being
		w and/or attached, were in violation of NRC requirements ar to posting in accordance with 10 CFR 19.11.	nd are being
			nd are being
			nd are being
			nd are being
L cited. This form is a NOTICE OF VIO	LATION, which may be subject	to posting in accordance with 10 CFR 19.11.	nd are being
Licensee	LATION, which may be subject	to posting in accordance with 10 CFR 19.11.	
Licensee hereby state that, within 30 days, the actions is porrective actions is made in accordance with	LATION, which may be subject a's Statement of Correct described by me to the inspecto the requirements of 10 CFR 2.2	to posting in accordance with 10 CFR 19.11.	ment of rill be taken,
Licensee bereby state that, within 30 days, the actions corrective actions is made in accordance with late when full compliance will be achieved). I	LATION, which may be subject a's Statement of Correct described by me to the inspecto the requirements of 10 CFR 2.2	to posting in accordance with 10 CFR 19.11. Tive Actions for Item 4, above. r will be taken to correct the violations identified. This state 01 (corrective steps already taken, corrective steps which w	ment of rill be taken,
Licensee bereby state that, within 30 days, the actions corrective actions is made in accordance with late when full compliance will be achieved). It	PLATION, which may be subject P's Statement of Correct described by me to the inspecto the requirements of 10 CFR 2.2 understand that no further writte	to posting in accordance with 10 CFR 19.11. Tive Actions for Item 4, above. r will be taken to correct the violations identified. This state 01 (corrective steps already taken, corrective steps which w n response to NRC will be required, unless specifically requ	ment of rill be taken, jested.
Licensee hereby state that, within 30 days, the actions is corrective actions is made in accordance with late when full compliance will be achieved). In Title F LICENSEE'S	PLATION , which may be subject e's Statement of Correct described by me to the inspecto the requirements of 10 CFR 2.2 understand that no further writte Printed Name	to posting in accordance with 10 CFR 19.11. Eive Actions for Item 4, above. r will be taken to correct the violations identified. This state 01 (corrective steps already taken, corrective steps which w n response to NRC will be required, unless specifically requing Signature	ment of rill be taken, jested.

NRC FORM 591M PART 2 (10-2003) 10 CFR 2.201			U.S. NUCLEAR REGULATORY COMMISSION
	SAFETY INSPE AND COMPLIAN	ECTION REPORT	
1. LICENSEE Cabrera Services, Inc. REPORT NUMBER(S) 030-35316/06-001		2. NRC/REGIONAL OFF Region III 2443 Warrenville Road Lisle, Illinois 60532	ICE
3. DOCKET NUMBER(S) 030-35316	4. LICENSE NUMBER(S) 06-30556-01		5. DATE(S) OF INSPECTION November 8-9, 2006
(Continued)			

NRC FORM 591M PART 2 (10-2003)

NRC FORM 591M PART 3		U.S. NUCLEAR REGULATORY COMMIS
(10-2003) 10 CFB 2.201	Docket File Informat	tion
	SAFETY INSPECTION RI AND COMPLIANCE INSPI	EPORT ECTION
1. LICENSEE Cabrera Services, Inc. 030-35316/06-001		renville Road, Suite 210
REPORT NUMBER(S) USU-353 10/00-00 1 3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-35316	06-30556-01	November 8-9, 2006
5. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS	
88005, 83822, 87104	03.01-03.07 SUPPLEMENTAL INSPECTION INF	
I. PROGRAM CODE(S) 2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
03219 2. PHIOHITT	Joe Voegtli, Construction Super	
Main Office Inspection		nspection Date:
Field Office		
	ke City Army Ammunition Plant, Area 31,	Independence MO
	PROGRAM SCOPE	
and special nuclear materials incident to facilities and grounds, equipment, and c Packaging for transport; (5) Transport in transfer to licensees authorized to receiv or an Agreement States; and (6) As calibre equipment.	the following activities: (1) Decontami ontainers; (2) Site characterization; (3) p packages or containers approved for us the materials, in accordance with the ration sources and reference standards	nation, decommissioning, and remediation of Solidification and treatment of wastes; (4) se under the provisions of 10 CFR Part 71, for terms and conditions of licenses issued by the NRC for operational testing of radiation detection
 and special nuclear materials incident to facilities and grounds, equipment, and created and grounds, equipment, and created and transfer to licensees authorized to receive or an Agreement States; and (6) As calible equipment. During July 2006, a site contractor was p City Army Ammunition Plant (LCAAP, what testing of munitions containing depleted started decommissioning of the former prodecommissioning project. During these activities the contractor four excavated from the land-fill to ensure the rubbish. This inspection focused on the 	the following activities: (1) Decontami ontainers; (2) Site characterization; (3) a packages or containers approved for u- ve the materials, in accordance with the ration sources and reference standards erforming remediation activities in a ge- nich is in Independence, Missouri. The uranium (DU), until the licensee ceased production and testing areas. The land-fu- und 4 DU targeting rounds. The Army co at the soil was free of any additional per safety aspects related to and the condu- which was incorporated into the Army's	Solidification and treatment of wastes; (4) use under the provisions of 10 CFR Part 71, for terms and conditions of licenses issued by the NRC for operational testing of radiation detection meral rubbish land-fill located in Area 31 of the Lake Army facilities were used for the production and I these activities during the 1990s and subsequently fill clean-up activities were not part of the entracted with Cabrera to conduct surveys on the so nentrators prior to disposal of the soil and general loc of survey activities described in the "AREA 31 License No. SUC-1380, Docket No. 040-08767
and special nuclear materials incident to facilities and grounds, equipment, and co Packaging for transport; (5) Transport in transfer to licensees authorized to receiv or an Agreement States; and (6) As calibi- equipment. During July 2006, a site contractor was p City Army Ammunition Plant (LCAAP, wh testing of munitions containing depleted started decommissioning of the former p decommissioning project. During these activities the contractor fou excavated from the land-fill to ensure th rubbish. This inspection focused on the FINAL STATUS SURVEY WORK PLAN," v amendment No. 45.	the following activities: (1) Decontamiontainers; (2) Site characterization; (3) a packages or containers approved for use the materials, in accordance with the ration sources and reference standards derforming remediation activities in a genich is in Independence, Missouri. The arranium (DU), until the licensee ceased broduction and testing areas. The land-forduction and testing areas. The land-forduction and testing areas. The land-forduction and testing areas are after soli was free of any additional per safety aspects related to and the conduction which was incorporated into the Army's Performance Observations	nation, decommissioning, and remediation of Solidification and treatment of wastes; (4) ise under the provisions of 10 CFR Part 71, for terms and conditions of licenses issued by the NRC for operational testing of radiation detection neral rubbish land-fill located in Area 31 of the Lake Army facilities were used for the production and I these activities during the 1990s and subsequently fill clean-up activities were not part of the potracted with Cabrera to conduct surveys on the so nentrators prior to disposal of the soil and general loct of survey activities described in the "AREA 31 License No. SUC-1380, Docket No. 040-08767
 and special nuclear materials incident to facilities and grounds, equipment, and consistent of facilities and grounds, equipment, and consistent of facilities and grounds, equipment, and consistent of transfer to licensees authorized to receive or an Agreement States; and (6) As calible equipment. During July 2006, a site contractor was point of the former point (LCAAP, which is the contractor was point of the former point. During these activities the contractor four excavated from the land-fill to ensure the rubbish. This inspection focused on the FINAL STATUS SURVEY WORK PLAN," ware and ment No. 45. The NRC inspectors observed and evaluation the conduct of radiation surveys conduct instruments and their calibration was define service licensee had complied with poinsure appropriate and separate license in the service license. 	the following activities: (1) Decontamiontainers; (2) Site characterization; (3) packages or containers approved for use the materials, in accordance with the ration sources and reference standards performing remediation activities in a genich is in Independence, Missouri. The source of the licensee ceased production and testing areas. The land-fund 4 DU targeting rounds. The Army coat the soil was free of any additional per safety aspects related to and the conductions and corporated into the Army's performance Observations ated the licensee's performance related ted in work areas and soils being remediated in work areas and soils being remediated in the NRC and oversight controls; that is, Army license formed in Area 31. The inspectors determined to be appropriate and according the source oversight controls and the inspectors determined in Area 31. The inspectors determined to be appropriate and according the source oversight controls and the inspectors determined in Area 31. The inspectors determined to be appropriate and according the performance of the test of test of the test of the test of test	nation, decommissioning, and remediation of Solidification and treatment of wastes; (4) ise under the provisions of 10 CFR Part 71, for terms and conditions of licenses issued by the NRC for operational testing of radiation detection meral rubbish land-fill located in Area 31 of the Lake Army facilities were used for the production and i these activities during the 1990s and subsequently ill clean-up activities were not part of the entracted with Cabrera to conduct surveys on the so- nentrators prior to disposal of the soil and general loc of survey activities described in the "AREA 31 License No. SUC-1380, Docket No. 040-08767 to radiological posting and labeling, placarding, an- liated. The contractor's use of radiological ing to the survey plan. The inspectors determined the d the implementation of administrative controls to control versus service licensee control and rmined that appropriate certified and trained
 and special nuclear materials incident to facilities and grounds, equipment, and consistent of facilities and grounds, equipment, and consistent of licensees authorized to receive or an Agreement States; and (6) As calible equipment. During July 2006, a site contractor was point of munitions containing depleted started decommissioning of the former prodecommissioning project. During these activities the contractor four excavated from the land-fill to ensure the rubbish. This inspection focused on the FINAL STATUS SURVEY WORK PLAN," warendment No. 45. The NRC inspectors observed and evaluation the service licensee had compiled with prinsure appropriate and separate license or responsibility, while work was being per personnel, as required by license comming contractor for purposes of determining contractor for purposes of determined purposes of determined purposes of determined purposes of determined purpo	the following activities: (1) Decontamiontainers; (2) Site characterization; (3) a packages or containers approved for use the materials, in accordance with the ration sources and reference standards derforming remediation activities in a genich is in Independence, Missouri. The arranium (DU), until the licensee ceased broduction and testing areas. The land-for duction and testing areas are solid was free of any additional per safety aspects related to and the conduction which was incorporated into the Army's duction work areas and soils being remediated in work areas and soils being remediated in work areas and soils being remediated in Area 31. The inspectors determent, were conducting the radiological lent radiation surveys, as well as conductions istency of measurements. The inspector	nation, decommissioning, and remediation of Solidification and treatment of wastes; (4) ise under the provisions of 10 CFR Part 71, for terms and conditions of licenses issued by the NRC for operational testing of radiation detection meral rubbish land-fill located in Area 31 of the Lake Army facilities were used for the production and I these activities during the 1990s and subsequently fill clean-up activities were not part of the entracted with Cabrera to conduct surveys on the so nentrators prior to disposal of the soil and general loct of survey activities described in the "AREA 31 License No. SUC-1380, Docket No. 040-08767 to radiological posting and labeling, placarding, an- liated. The contractor's use of radiological of the implementation of administrative controls to control versus service licensee control and rmined that appropriate certified and trained i surveys and sampling activities. cting side-by-side instrument measurements with th ectors survey readings were determined to be interviewed licensee personnel during the

.