

April 4, 2007

Mr. Christopher M. Crane
President and Chief Nuclear Officer
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

SUBJECT: BYRON STATION, UNIT NOS. 1 AND 2, AND BRAIDWOOD STATION,
UNITS 1 AND 2 - REQUEST FOR ADDITIONAL INFORMATION RELATED TO
BULLETIN 2004-01, "INSPECTION OF ALLOY 82/182/600 MATERIALS USED
IN THE FABRICATION OF PRESSURIZER PENETRATIONS AND STEAM
SPACE PIPING CONNECTIONS AT PRESSURIZED WATER REACTORS,"
(TAC NOS. MC3461, MC3462, MC3463, AND MC3464)

Dear Mr. Crane:

By letter to the Nuclear Regulatory Commission (NRC) dated July 27, 2004, Exelon Generation Company, LLC submitted a 60-day response to NRC Bulletin 2004-01, "Inspection of Alloy 82/182/600 Materials Used in the Fabrication of Pressurizer Penetrations and Steam Space Piping Connections at Pressurized Water Reactors," for Byron Station, Unit Nos. 1 and 2, and Braidwood Station, Units 1 and 2.

The NRC staff is reviewing your response and has determined that additional information is required to complete the review. The specific information requested is addressed in the enclosure to this letter. So that the NRC staff can complete its review, provide a response within 30 days from the date of this letter.

The NRC staff considers that timely responses to requests for additional information help ensure sufficient time is available for staff review and contribute toward the NRC's goal of efficient and effective use of staff resources. If circumstances result in the need to revise the requested response date, please contact me at (301) 415-3733.

Sincerely,

/RA/

Robert F. Kuntz, Project Manager
Plant Licensing Branch III-2
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455,
STN 50-456 and STN 50-457

Enclosure:
Request for Additional Information

cc w/encl: See next page

April 4, 2007

Mr. Christopher M. Crane
President and Chief Nuclear Officer
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

SUBJECT: BYRON STATION, UNIT NOS. 1 AND 2, AND BRAIDWOOD STATION,
UNITS 1 AND 2 - REQUEST FOR ADDITIONAL INFORMATION RELATED TO
BULLETIN 2004-01, "INSPECTION OF ALLOY 82/182/600 MATERIALS USED
IN THE FABRICATION OF PRESSURIZER PENETRATIONS AND STEAM
SPACE PIPING CONNECTIONS AT PRESSURIZED WATER REACTORS,"
(TAC NOS. MC3461, MC3462, MC3463, AND MC3464)

Dear Mr. Crane:

By letter to the Nuclear Regulatory Commission (NRC) dated July 27, 2004, Exelon Generation Company, LLC submitted a 60-day response to NRC Bulletin 2004-01, "Inspection of Alloy 82/182/600 Materials Used in the Fabrication of Pressurizer Penetrations and Steam Space Piping Connections at Pressurized Water Reactors," for Byron Station, Unit Nos. 1 and 2, and Braidwood Station, Units 1 and 2.

The NRC staff is reviewing your response and has determined that additional information is required to complete the review. The specific information requested is addressed in the enclosure to this letter. So that the NRC staff can complete its review, provide a response within 30 days from the date of this letter.

The NRC staff considers that timely responses to requests for additional information help ensure sufficient time is available for staff review and contribute toward the NRC's goal of efficient and effective use of staff resources. If circumstances result in the need to revise the requested response date, please contact me at (301) 415-3733.

Sincerely,
/RA/
Robert F. Kuntz, Project Manager
Plant Licensing Branch III-2
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455,
STN 50-456 and STN 50-457

Enclosure:
Request for Additional Information

cc w/encl: See next page

DISTRIBUTION:

PUBLIC	LPL3-2 R/F	RidsNrrDorlLpl3-2
RidsNrrPMRKuntz	RidsNrrLAEWhitt	RidsAcrsAcnwMailCenter
RidsOgcRp	RidsRgn3MailCenter	RidsNrrDorlDpr
ADAMS Accession Number: ML070240022		NRR-088

OFFICE	LPL3-2/PM	LPL3-2/LA	LPL3-2/BC
NAME	RKuntz:mw	EWhitt	RGibbs
DATE	4/4/2007	4/2/2007	4/4/2007

OFFICIAL RECORD COPY

Byron/Braidwood Stations

cc:

Dwain W. Alexander, Project Manager
Westinghouse Electric Corporation
Energy Systems Business Unit
Post Office Box 355
Pittsburgh, PA 15230-0355

Howard A. Learner
Environmental Law and Policy
Center of the Midwest
35 East Wacker Dr., Suite 1300
Chicago, IL 60601-2110

U.S. Nuclear Regulatory Commission
Byron Resident Inspectors Office
4448 N. German Church Road
Byron, IL 61010-9750

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
Suite 210
2443 Warrenville Road
Lisle, IL 60532-4351

Ms. Lorraine Creek
RR 1, Box 182
Manteno, IL 60950

Chairman, Ogle County Board
Post Office Box 357
Oregon, IL 61061

Mrs. Phillip B. Johnson
1907 Stratford Lane
Rockford, IL 61107

Attorney General
500 S. Second Street
Springfield, IL 62701

Illinois Emergency Management
Agency
Division of Disaster Assistance &
Preparedness
110 East Adams Street
Springfield, IL 62701-1109

Plant Manager - Byron Station
Exelon Generation Company, LLC
4450 N. German Church Road
Byron, IL 61010-9794

Site Vice President - Byron
Exelon Generation Company, LLC
4450 N. German Church Road
Byron, IL 61010-9794

U.S. Nuclear Regulatory Commission
Braidwood Resident Inspectors Office
35100 S. Rt. 53, Suite 79
Braceville, IL 60407

County Executive
Will County Office Building
302 N. Chicago Street
Joliet, IL 60432

Plant Manager - Braidwood Station
Exelon Generation Company, LLC
35100 S. Rt. 53, Suite 84
Braceville, IL 60407-9619

Ms. Bridget Little Rorem
Appleseed Coordinator
117 N. Linden Street
Essex, IL 60935

Document Control Desk - Licensing
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Site Vice President - Braidwood
Exelon Generation Company, LLC
35100 S. Rt. 53, Suite 84
Braceville, IL 60407-9619

Senior Vice President - Operations Support
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Director - Licensing and Regulatory
Affairs
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Senior Vice President - Midwest Operations
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Manager Regulatory Assurance - Braidwood
Exelon Generation Company, LLC
35100 S. Rt. 53, Suite 84
Braceville, IL 60407-9619

Manager Regulatory Assurance - Byron
Exelon Generation Company, LLC
4450 N. German Church Road
Byron, IL 61010-9794

Assistant General Counsel
Exelon Generation Company, LLC
200 Exelon Way
Kennett Square, PA 19348

Vice President - Regulatory & Legal Affairs
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Manager Licensing - Braidwood/Byron
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

REQUEST FOR ADDITIONAL INFORMATION

BYRON STATION, UNIT NOS. 1 AND 2,

AND BRAIDWOOD STATION, UNITS 1 AND 2

DOCKET NOS. STN 50-454, STN 50-455,

STN 50-456 AND STN 50-457

The NRC is reviewing Exelon Generation Company's (Exelon's) 60 day response to NRC Bulletin 2004-01, "Inspection of Alloy 82/182/600 Materials Used in the Fabrication of Pressurizer Penetrations and Steam Space Piping Connections at Pressurized Water Reactors" for the Byron Station, Unit Nos. 1 and 2 (Byron) and Braidwood Station, Units 1 and 2 (Braidwood), dated July 27, 2004. Based on the NRC staff's review, additional information is needed. Please provide a supplemental response which addresses the following question:

Item 1(c) in Bulletin 2004-01 states in part, "If leaking pressurizer penetrations or steam space piping connections are found, indicate what followup NDE [nondestructive examination] will be performed to characterize flaws in the leaking penetrations. Provide your plans for expansion of the scope of NDE to be performed if circumferential flaws are found in any portion of the leaking pressurizer penetrations or steam space piping connections." Provide a response that addresses whether NDE that is capable of determining crack orientation will be performed in order to accurately characterize the flaw, its orientation and its extent where evidence of apparent reactor coolant pressure boundary leakage is discovered by visual examination. The response should also provide your plans for expansion of the scope of NDE to other components in the pressurizer to be performed if circumferential flaws are found in any portion of the leaking pressurizer penetrations or steam space piping connections. Alternatively, if you will not supplement your original response to address the comments above, please provide a technical justification for not doing so.

Enclosure