

February 9, 2007

Mr. Donald R. Metzler
Moab Federal Project Director
U.S. Department of Energy
2597 B³/₄ Road
Grand Junction, CO 81503

SUBJECT: MOAB PROJECT - REQUEST FOR ADDITIONAL INFORMATION - DRAFT
REMEDIAL ACTION PLAN (TAC JU0118)

Dear Mr. Metzler:

The U.S. Nuclear Regulatory Commission (NRC) has completed a detailed technical review of the U.S. Department of Energy's (DOE's) Draft Remedial Action Plan and Site Design for Stabilization of Moab Title I Uranium Mill Tailings at the Crescent Junction, Utah, Disposal Site (DRAP). Additionally, several NRC staff visited the Moab mill site and the proposed Crescent Junction disposal site in December 2006. Our review has identified deficiencies in the DRAP; we will need the additional information identified in the enclosure in order for us to complete our review.

If you have any questions concerning this letter, please contact me, either by telephone at (301) 415-6629, or by e-mail, at mhf1@nrc.gov.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice for Domestic Licensing Proceedings and Issuance of Orders," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records component of NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Sincerely,

/RA/

Myron Fliegel, Project Manager
Uranium Recovery Licensing Branch
Division of Waste Management
and Environmental Protection
Office of Federal and State Materials and
Environmental Management Programs

Docket No. WM-110

Enclosure: Request for Additional Information

cc: D. Finerfrock - Utah DRC

February 9, 2007

Mr. Donald R. Metzler
Moab Federal Project Director
U.S. Department of Energy
2597 B³/₄ Road
Grand Junction, CO 81503

SUBJECT: MOAB PROJECT - REQUEST FOR ADDITIONAL INFORMATION - DRAFT REMEDIAL ACTION PLAN (TAC JU0118)

Dear Mr. Metzler:

The U.S. Nuclear Regulatory Commission (NRC) has completed a detailed technical review of the U.S. Department of Energy's (DOE's) Draft Remedial Action Plan and Site Design for Stabilization of Moab Title I Uranium Mill Tailings at the Crescent Junction, Utah, Disposal Site (DRAP). Additionally, several NRC staff visited the Moab mill site and the proposed Crescent Junction disposal site in December 2006. Our review has identified deficiencies in the DRAP; we will need the additional information identified in the enclosure in order for us to complete our review.

If you have any questions concerning this letter, please contact me, either by telephone at (301) 415-6629, or by e-mail, at mhf1@nrc.gov.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice for Domestic Licensing Proceedings and Issuance of Orders," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records component of NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Sincerely,
/RA/

Myron Fliegel, Project Manager
Uranium Recovery Branch
Division of Waste Management
and Environmental Protection
Office of Federal and State Materials and
Environmental Management Programs

Docket No. WM-110

Enclosure: Request for Additional Information

cc: D. Finerfrock - Utah DRC

DISTRIBUTION:

DURLD r/f RLinton DGillen TJohnson RLukes Albrahim

ML070380173

OFC	FSME/DWMEP	FSME/DWMEP	FSME/DWMEP: BC
NAME	MFliegel	B Garrett	B VonTill
DATE	2/09/07	2/09/07	2/09/07

OFFICIAL RECORD COPY

**U.S. Department of Energy Moab Project
Draft Remedial Action Plan Review
Request for Additional Information**

GEOLOGY AND SEISMOLOGY

G1 Geomorphology

Comment: Provide additional evidence that the discontinuous east-striking line of low, north-dipping, cuesta-like mounds just north of the disposal cell footprint near the top of the Prairie Canyon Member of the Mancos Shale are formed by resistant dolomitic siltstone concretions.

Basis: RASR, page 2-7, section 2.3.3. The text indicates “geomorphic features include.....(4) a discontinuous east-striking line of low, north-dipping, cuesta-like mounds formed by resistant dolomitic siltstone concretions near the top of the Prairie Canyon Member of the Mancos Shale just north of the disposal cell footprint.” This linear feature also shows up on most aerial photographs of the site and was visited during the site visit in December 2006. These cuesta-like mounds may have been formed by resistant dolomitic siltstone concretions, but additional evidence should be provided that this is the case and is not a structurally-controlled feature, possibly a fault. Are there analogous mounds in other locations away from the site where the top of the Prairie Canyon Member of the Mancos Shale outcrops producing similar cuesta-like features or is there other evidence to support the mounds have been formed due to resistant dolomitic siltstone concretions?

G2 Geomorphology

Comment: Evaluate headcutting rates for West Branch Kendall Wash and evaluate the possibility of stream capture of Crescent Wash by West Branch Kendall Wash.

Basis: RASR, page 2-7, section 2.3.3. The text indicates “geomorphic features include.....(6) incised channels of the West and East Branches of Kendall Wash and the slow northward advance of headward incision of the West Branch of Kendall Wash.” West Branch Kendall Wash is experiencing headcutting. This head cutting is progressing toward Crescent Wash. Text in section 2.4.1 indicates this headward advance will have to be monitored. Additionally, in the RASR Appendix A, DOE has committed to obtaining aerial photographs from 1944 to try to determine headcutting rates. Stream capture was verified on the abandoned wash shown as number 5 on the high-altitude vertical photographs, and this possibility should be explored for West Branch Kendall Wash.

G3 Geomorphology

Comment: Determine why constant roadway maintenance is required for Route 70 in the vicinity of the site and determine if similar problems could occur with the disposal cell.

Basis: RASR, page 2-7, section 2.3.4. The text describes “constant roadway maintenance required for Interstate Highway 70, which traverses Mancos Shale just south of the site.” The text indicates that “analyses of the Mancos Shale and Mancos Shale-derived soils did not show the presence of swelling clay or highly plastic materials at the Crescent Junction disposal site.” It appears DOE has assumed that road failures are due to montmorillonite clays and since montmorillonite clays are not present at the cell site the hazard does not exist. Has DOE considered that road failure is due to something other than montmorillonite swelling clay that may also be present at the Crescent Junction cell site? Interstate 70 and the cell will be located on the same geologic material and the maintenance problems encountered on I-70 should be investigated fully to determine if they could occur on or within the cell.

G4 Geomorphology

Comment: Clarify the depth of the disposal cell and on what material the cell will be constructed.

Basis: RASR, page 4-3, section 4.1.2. Text in this section indicates “the disposal cell excavation is anticipated to be into the Quaternary materials, as well as into upper portions of the weathered and fractured Mancos Shale.” On page 7-1, section 7.0, the text indicates the anticipated depth of excavation is 15 to 20 feet. Figure 7.2 shows the excavation limits as approximately 10 feet below bedrock. Figure 7-3 shows the cell directly on the weathered Mancos Shale contact. It is unclear how far the cell will be placed into the Quaternary alluvial material and/or the weathered and fractured shale. Will the top several feet of weathered shale be removed or will the cell be placed directly on the first contact of the weathered Mancos Shale? The depth of the cell and what material the cell will be placed on should be clearly stated and consistent throughout the Report.

G5 Geomorphology

Comment: Discuss slump features identified near the site. Indicate why slumping will or will not have an impact on the site during the compliance period.

Basis: Attachment 2, Appendix G, High-Altitude Vertical Photographs (6.), page 3. There is mention of a slump block or mass-wasting feature on the north side on the Book Cliffs in Horse Haven and at several other locations. The text indicates the slides were likely initiated in wetter times during the Pleistocene. What is the basis for this conclusion that the slides likely occurred in wetter times during the Pleistocene? Wetter Pleistocene could have been the condition at the site only about 12,000 years ago and may be relevant to the next 1000 years projection. Are there analogous site(s) along Book Cliffs that have known high or higher (and/or low or lower) rates of slumping hazards similar to those at Crescent Junction?

G6 Geomorphology

Comment: Explain the origin and age of the pediment-mantling deposits and surfaces located near the site.

Basis: Attachment 2, Appendix B, page 7, Section 2.5, discusses the “pediment - mantling deposits” reported by the applicant. Has DOE considered that these deposits might be indicative of former, uplifted pediments? If they are tectonic-geomorphic features, what clues do they provide to rates of erosion, episodes of differential uplift, possibly faulting? If the surfaces are tectonic-geomorphic in nature, is the age of the surfaces known, or is it possible to determine the approximate age, and if tectonic activity produced the surfaces, is this significant to the design of the disposal cell?

G7 Mining, Oil & Gas

Comment: Discuss current or past mining, mineral, and oil and gas claims for the site or within a radius near the site that have similar geologic characteristics.

Basis: RASR, page 3-4, section 3.4. The statement is made that “Pockets of natural gas were encountered during the drilling conducted as part of this project. Commercial exploration for oil and gas has been, and continues to be, common in the Crescent Flat area.” Also, many boreholes are noted on the USGS quadrangle as well as mining pits. Is there a possibility that this site could cause a conflict with future mining claims?

G8 Mining, Oil & Gas

Comment: Discuss past mining, mineral, and oil and gas activities that may have occurred at the site.

Basis: Attachment 2, Appendix A, Resource Development, page. 5, para 1. This section refers to a petroleum accumulation 3 mi SSW, without extrapolating the potential significance. However, there is an oil accumulation about 3 mi WNW of the site that is not mentioned. It is not known if this play is in the Mancos or deeper (reference is a booklet on Grand County geology by Utah Geol Survey dated 1987). The statement is made, "Data concerning the targeted gas horizons and the actual results of this exploration are not currently available." When will additional data be obtained on oil and gas targets in the site vicinity and on pressurized gas pockets? This may bear on potential future disruptive activities that may be safety related.

Has DOE checked for past drilling activities at the proposed site? Old drill sites and improperly abandoned drill-holes may provide a pathway for water and transient drainage from the cell to impact groundwater. Geophysical survey logs, borehole logs, geological descriptions and cross sections may be available for the site area. Also, driller’s reports of subsurface conditions such as groundwater, brines, pressurized gas, deformable holes and other information may be available.

G9 Seismology

Comment: Describe the association of the earthquakes that are located close to the Little Grand fault No. 9 and the proposed site. Examine the possibility that the two earthquakes in the vicinity of the Little Grand fault may have resulted from movement on this fault.

Basis: Attachment 2, Appendix F, Figure 7, page 13. There are earthquakes located very close to Fault No. 9. Does Fault No. 9 have a bearing as to the design earthquake for the site? Earthquake locations are not known accurately due to lack of instrumentations in the vicinity of the site. Provide good evidence that the Little Grand fault is not capable.

G10 Seismology

Comment: Explain why some faults that show no evidence of Quaternary faulting are considered capable while others are not.

Basis: Attachment 2, Appendix F, Table 3, page 16. Table 3 indicates that Fault No. 7 shows no evidence of Quaternary faulting, but it is considered as a potential design fault. Meanwhile, Faults 4, 5, and 6 also do not show Quaternary faulting but they are not potential design faults. Please provide appropriate rationale to explain this discrepancy.

G11 Geology

Comment: Discuss additional field work that has taken place to confirm or deny the existence of faults.

Basis: Attachment 2, Appendix A, Structural Setting, page 5, para. 2. The statement is made, "Surface field work and an additional search for well data in the area will be undertaken to confirm or deny the existence of the fault." Clearly indicate what additional field work has taken place and document the findings.

G12 Geology

Comment: Explain the origin of the fault associated with the axis of the Thompson anticline and why this fault shows up to 90 feet of displacement in some locations but no apparent displacement of the Mancos.

Basis: Attachment 2, Appendix G, Low sun-angle photographs (e.), page 4. Potential fault. The graben strikes N20W and is located 2 miles from withdrawal area, at Thompson anticline. One fault shows displacement of up to 90 feet. No displacement of these faults is discerned at contact with Mancos. There is no additional evidence to support that no displacement has occurred at the contact with the Mancos. Clearly identify this fault on the seismic map and explain why there is no apparent displacement in underlying Mancos. How small a displacement could have been detected given the methods used?

G13 Geology

Comment: Discuss the two pediment remnants near the site identified by DOE that are vertically offset.

Basis: Attachment 2, Appendix G, Low sun-angle photographs (g), page 5. A potential fault has been identified by DOE. Two pediment remnants are vertically offset about 45 +/- 5 ft, center of Sec 33. It is uncertain whether the surfaces are two

different pediment surfaces or is the same surface that is faulted. If it's a fault, it appears to be young and is close to the site and could be a capable fault. This potential fault warrants further assessment.

G14 Geology

Comment: Investigate the linear feature striking N 70 E, that appears on the Plate 1 aerial photograph extending from Horse Heaven to the northeast and through Crescent Wash to the southwest.

Basis: This linear feature is not noted by DOE in the RASR. However, it was noted and discussed by NRC staff during the site visit in December 2006. Additional field investigation should be considered to determine if there is any evidence that this feature is a fault, and if so, if it is capable.

G15 Seismology

Comment: Provide the basis for choosing the parameter values, in Attachment 1, Appendix D, Liquefaction Analysis, for water content, type of sand (clean/silty), and relative density, and provide their uncertainties. Provide the necessary justification for using Fig. 11.8 mentioned in the calculations, although the design earthquake for the site is less than that mentioned in the figure.

Basis: Justification for the parameter values was not provided. Changes in these parameters may change the condition of the layer from being non-liquefiable to being liquefiable.

GEOTECHNICAL STABILITY

GT1 Characterization of Site Stratigraphy and Tailings

DOE and Golder Associates have indicated several data quality issues with test data from the laboratory used for geotechnical testing. As examples, there are questions on permeability test inconsistencies (Attachment 5, Appendix K), and there are several open comments on data quality from a Golder letter dated March 23, 2006 (Attachment 5, Appendix J). Provide a list of all unresolved issues with the test data quality and discuss the status of resolution of each of the issues.

GT2 Characterization of Site Stratigraphy and Tailings

In Section 4.1.2 of the Remedial Action Selection Report, DOE indicates that all of the materials that will be used in construction of the disposal cell cover will be obtained from the cell excavation. Based on the boreholes and test pits conducted at the disposal site, provide representative cross sections of the Quaternary materials and weathered Mancos Shale. Using these cross sections, provide estimates of the volumes of materials available from the excavation and a demonstration that the volumes will be adequate to construct both alternative covers being considered without the need for additional borrow areas.

GT3 Characterization of Site Stratigraphy and Tailings

In Section 2.5 of the Remedial Action Selection Report, DOE indicates that the presence of swelling clays in the Mancos Shale is a potential geologic hazard. Provide discussion of the samples tested and the corresponding test results that demonstrate that swelling clays will not be a problem at the Crescent Junction disposal cell.

GT4 Slope Stability

In general, the various analyses make it unclear what exactly the cover and clean-fill dike are composed of. The slope stability analyses were performed using only the Alternative Cover. In the Remedial Action Selection Report (Figure 5.1), DOE indicates that the cover is composed of a mixture of "slopewash, eolian soils, and weathered Mancos Shale." The slope stability analysis considers the cover (radon barrier) to be composed of only "sheet wash and eolian soils" (Attachment 1, Appendix C, Table 1). There is a similar discrepancy for the clean-fill dike. Table 1 of the slope stability analysis shows the clean-fill dike material to be recompacted "weathered Mancos Shale," while Attachment 1, Appendix C, page 7, describes the clean-fill dike as "recompacted weathered Mancos Shale, alluvial, and eolian soils." Provide clarification of these discrepancies and discussion of any resulting impact on the slope stability analyses.

GT5 Settlement

Include additional information as part of the settlement analysis presented in Attachment 1, Appendix D. Provide a tabulation of the material layers considered in the analysis, references to the tests performed (or other basis) to determine each layer's settlement analysis parameters, and the resulting engineering parameters. Also provide a description or figure indicating the locations chosen for settlement analysis to demonstrate that the worst, average, and best settlement conditions have been selected and the largest differential settlement conditions have been analyzed.

GT6 Settlement

In Section 4.2.2 of the Remedial Action Selection Report, DOE indicates that settlement will be low due to the methods of mixing, placement, and compaction of the tailings in relocating the contaminated material to the Crescent Junction disposal cell. Provide additional description of the procedures for bringing the excavated wet tailings to optimum moisture at placement and compaction.

GT7 Settlement

Provide a discussion of whether or not there are plans for monitoring settlement during and following construction of the disposal cell. If there are plans, provide details of the monitoring plan; if there are no plans, provide the basis for not monitoring.

GT8 Cover Design

In Section 5.0 and Figure 5-1, DOE discusses and portrays two different cover alternatives, but does not indicate which is planned or preferred. Provide a discussion on the factors that will determine which of the two covers will be used.

GT9 Cover Design

In its settlement analysis (Attachment 1, Appendix D), DOE analyzes settlement and cracking for only the UMTRCA cover. In its slope stability analysis (Attachment 1, Appendix C), DOE only analyzes the stability with the Alternative cover. Provide a discussion of why different covers are used from analysis to analysis and how the analyses presented conservatively band both covers being considered.

GT10 Cover Design

In Section 4.1.2 of the Remedial Action Selection Report, regarding the potential for “bathtubbing”, DOE indicates that the excavation will be into the weathered Mancos Shale, which has hydraulic conductivities of from 10^{-4} to 10^{-3} cm/sec. Elsewhere, DOE estimates the hydraulic conductivity of the cover to be 7×10^{-5} cm/sec. Discuss the basis for concluding that both of the covers being considered have conductivities as low as 7×10^{-5} cm/sec. In addition, discuss the potential for the cell excavation to extend to a depth that removes most of the weathered Mancos, and thus result in a base conductivity much less than the assumed 10^{-4} cm/sec.

SURFACE WATER HYDROLOGY AND EROSION PROTECTION

SW1 Design of Erosion Protection for North Diversion Channel.

The RAP indicates that riprap will be provided for the north slope of the disposal cell and the left side of the diversion channel and that the rock will be designed to protect against velocities produced by the PMF in the channel. However, it appears that the design of the riprap may also need to be based on velocities and shear stresses that will occur in gullies that discharge into the diversion channel. It appears that a significant number of gullies have formed and will discharge into the diversion channel in an unpredictable manner. The staff concludes that these gullies are likely to produce the design condition for the rock in the channel.

Staff review of the RAP indicates that DOE computed the scour depth, using assumptions associated with flows occurring perpendicular to the diversion channel, and the staff concludes that DOE's assumptions related to gully size and discharge are appropriately conservative. However, the size of the riprap should also be based on similar assumptions. It is likely that the flow velocities occurring in these gullies will exceed the velocities in the diversion channel, thus requiring larger riprap sizes. In addition, the proposed rock cutoff wall and/or rock toes should be designed for the gully velocities, and the size and volume of rock should be adjusted accordingly.

DOE should either revise the design to account for velocities in the gullies, or provide additional justification for the current design.

SW2 Design of Riprap for the Diversion Channel Outlet

Staff review of the design of the riprap for the diversion channel outlet indicates that the rock size and volume may not be adequate to prevent head-cutting and gully intrusion into the channel. The assumptions related to flow distribution across the outlet structure do not appear to account for localized flow concentrations. Further, the volume of the rock provided does not appear to be adequate to fill in scoured areas during the occurrence of major floods.

During the December site visit, the staff observed significant gullies downstream of the site, relatively close to the southwest corner of the proposed cell. Because the drainage area to this area will be increased by diverting flows in the diversion channel, there is a significant potential for large gullies to form and migrate upstream toward the disposal cell.

The design condition for computing the rock size and volume should be based on assumed areas of flow concentrations occurring downstream of the outlet structure. The velocities in these areas of flow concentration should then be used to compute the scour depth, rock size, and rock volume, based on collapse of the rock structure on a slope of about 1V on 2 H. It is relatively obvious that flows occurring on the steep 1V on 2H collapsed slope will likely result in very large rock sizes. Alternately, DOE could provide a design where the downstream slope of the structure is constructed on a pre-formed specific slope, such as 1V on 10H, thus reducing the rock size requirements.

DOE should revise the design or provide additional justification that the design is adequate to prevent head-cutting into the diversion channel. If DOE chooses to make revisions, the design of the outlet for this diversion channel could be similar to other Title I designs that have been previously approved. Guidance may also be found in NUREG-1623.

SW3 Design of West Slope and Toe of Disposal Cell

Based on observations of on-site gullies during the site visit, the staff considers that flows discharging from the currently-proposed location of the diversion channel outlet could potentially erode the west side slope and/or toe of the disposal cell. Based on the size, depth, and relative closeness of the existing gullies immediately downstream of the southwest corner of the proposed cell, it appears that gullies of similar size and depth could form immediately adjacent to the toe and could erode to a depth that could undercut the rock toe.

DOE should revise the design of the west slope and toe of the disposal cell by: (1) increasing the rock size and volume of the toe; (2) extending the outlet of the diversion to the west so that the west side slope of the cell is not affected; or (3) changing the footprint and alignment of the west side of the cell.

SW4 Definition of Competent Mancos Shale

On page 5 of Appendix G, DOE indicates that riprap will extend to the computed scour depth or to where competent Mancos Shale is encountered. In general, the staff considers that many Mancos Shale formations may not be extremely hard or durable if exposed to weathering. If riprap is keyed into such formations, erosion and loss of rock volume could occur. Further, during the site visit where the test pit was observed, the staff did not observe any competent shale layers that would provide suitable protection if exposed by erosion.

DOE should provide a clear description and definition of what will be done to determine the competency of Mancos Shale in those areas where riprap will be extended below grade or where erosion is expected to occur. Alternately, DOE could provide rock of sufficient volume to extend to the expected depth of scour.

SW5 QA/QC Procedures for Rock Production

Based on observations made during the December site visit, it appears that the rock in either of the proposed quarries is somewhat variable, depending on the location where rock will be

produced within the quarry. DOE should provide additional information to document the quality assurance and quality control (QA/QC) procedures that will be implemented during rock production at the quarries to address this variability and to assure that rock of acceptable quality will consistently be produced. DOE should discuss how acceptable rock will be identified and unacceptable rock avoided as part of the QA/QC procedures for rock production.

DOE should describe the lithologic variability of the rock sources and identify features adverse to rock durability and resistance to weathering. Variability is also the basis for selecting representative samples for durability tests and petrographic analysis. Discuss how representative samples were obtained. Potential features could include mudstone/clay interbeds, conglomerate/calcrete beds, bedding planes, or fractures that could be vulnerabilities to freeze thaw and reduction in rock size. Explain how the mudstones and limestones above and below the sandstone will be able to be avoided in producing the sandstone.

Petrographic analysis, together with published literature, should be used to identify the minerals and percentages. Petrographic analysis should clearly identify the rock source of the sample. Mineralogy of the sandstone cement should be identified and the type of clays, if present.

In addressing the above items, consider the sedimentologic, stratigraphic, and petrologic analysis given in Currie, Brian S. "Upper Jurassic-Lower Cretaceous Morrison, and Cedar Mountain Formations, NE Utah-NW Colorado: Relationships between Nonmarine Deposition and Early Cordilleran Foreland-Basin Development", Journal of Sedimentary Research, Vol. 68, No. 4, July 1998.

WATER RESOURCES PROTECTION

GW1

Comment: Discuss how tailings drainage will be confined to the weathered and unweathered Mancos Shale and be precluded from seeping along the contact between the weathered Mancos Shale and the overlying unconsolidated alluvial/colluvial material and possibly migrating offsite.

Basis: RASR (Remedial Action Selection Report), page 2-7, section 2.3.2. There is NRC interest in the contact between the weathered Mancos and the overlying alluvial sediments to determine if this contact could provide a pathway for tailings drainage, especially where paleochannels exist and cut into the Mancos Shale bedrock as noted in this section. Up to 25 feet of weathered alluvial material mantles Mancos Shale at the site. Horizontal hydraulic conductivity and vertical hydraulic conductivity have been determined for the weathered Mancos Shale, but hydraulic conductivity has not been determined for the alluvial material overlying the weathered Mancos. If hydraulic conductivity is greater within the unconsolidated overlying material, which is likely the case, this may allow for preferred pathway or a "path of least resistance" for tailings drainage to seep from the tailing pile along this contact and migrate downgradient and offsite.

GW2

Comment: Calculate the approximate volume of leachate that may drain from the tailings and the volume of water that is expected to seep through the cover. Estimate the distance and depth this volume of leachate may seep from the tailings impoundment.

Basis: RASR, page 4-8, section 4.3.4. The statement is made that “the average moisture content of the tailings will probably be biased on the wet side of optimum, leaving enough residual moisture to drain from the tailings under the influence of gravity.” The cover will have a lower hydraulic conductivity than the underlying Mancos Shale to prevent “bathtubbing.” Has DOE attempted to calculate the approximate amount of leachate that may drain from the volume of tails expected based on an approximation of “the wet side of optimum?” If so, has the volume of water calculated been modeled to determine its approximate flow path and distance from the site? There is a concern that leachate may not penetrate the weathered Mancos Shale and prefer to migrate along the weathered Mancos Shale and Quaternary alluvial material contact. If this were to occur, would this result in offsite drainage or the possible development of seeps in either Crescent or Kendall Washes, especially if leachate were to migrate along the paleochannel(s) cited in the text?

The text in this section also notes that DOE will monitor the accumulation of transient drainage with a standpipe tapping a sump at the downgradient toe of the disposal cell. How far into the weathered Mancos Shale is the sump to be constructed or will it only be in the alluvial material? Is only one sump anticipated, or will a series of sumps be considered at the downgradient toe of the cell? Please clarify or develop a plan and basis for location of the sumps. Clarify the “action level” and the plan for pumping and disposal of water from the sump(s).

GW3

Comment: Provide additional data, evidence, or research to support the claim that water in the Mancos Shale beneath the cell location is connate water.

Basis: Attachment 3, Appendix D, page 4. The statement is made that “Coreholes 0201, 0203, 0204, and 0208 have continued to yield water at relatively constant rates, signifying that the connate water intercepted by these coreholes is stored in larger compartments, which will require more pumping to deplete. The continued pumping from these larger compartments is deemed unnecessary because the concept that the connate water is trapped in porous zones with limited volume was already demonstrated at corehole 0202.” Provide a basis that water in four coreholes is stored in larger compartments. Has DOE considered that fractures may have provided a connection for groundwater flow, thus indicating that behavior of water in the four coreholes is more indicative of groundwater flow than that of corehole 0202?

GW4

Comment: Attachment 4, Appendix B, page 35, section 8.7.2. Discuss proposed modifications to the model based on the likelihood that much of the groundwater transport through the Mancos Shale is through fractures or other large-scale features.

Basis: On the very last line of section 8.7.2, the comment is made that, "Thus, if ground water moves dominantly by fracture flow, some modifications will likely be required." In section 8.8, paragraph two, the statement is made, "Because of the low-bulk hydraulic conductivity, much of the ground water transport through the Mancos shale is likely to be through fractures or other large-scale features. Based on the two statements, modifications of the model may be required." Discuss what modifications have been made to the model to resolve this discrepancy.

GW5

Comment: Attachment 4, Appendix B, page 35, section 9.0, paragraph 2. Discuss what hydrologic investigations are to be used to yield more useful units of travel time and distance for the model, or alternatively, provide a sensitivity analysis to assess the impact of chemical attenuation at the site.

Basis: One of the conclusions of Appendix B is that project personnel will need to couple the results from the model with the results from hydrologic investigations to yield more useful units of travel time and distance. Furthermore, in lieu of further investigations, a sensitivity analysis is proposed to assess the impact of chemical attenuation at the site. Provide the additional analysis as based on the conclusion in this Appendix.

RADON ATTENUATION AND SITE CLEANUP

R1

Please provide more detail on the process for inclusion or exclusion of identified vicinity properties.

R2

Please provide more detail on which areas will require supplemental standards and the justification for use of supplemental standards on these areas.