

PR

Integrated Action Item Database Revision Form

PR06.0318.01

Revision: 3

EVALUATION

Date: 07/12/97

Responsible Manager: LOOMIS, L. PLG81

Status: ~~OPEN~~ **CLOSED**

Group: NUC SVCS

Significance: 2

Department: CHEMISTRY

Strategy:

Priority: A0

Sub Department:

Doc Type/Number:

ENTERED

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: 11

Due Date: 08/01/97

Assign Date: 09/24/96

Dead Date: 08/30/97

Start Date: 10/01/96

Completion Date: 11

Action

CONDUCT AN EVALUATION TO DETERMINE THE CAUSE OF THE HIGH NITRATE LEVELS IN THE TBCCW SYSTEM. DETERMINE CORRECTIVE ACTIONS AND ACTIONS TO PRECLUDE RECURRENCE.

Closure Requirements

COMPLETE EVALUATION PER NCR92A1, SECTION 6.4

See attached response for closure

Notes/Basis for Change(s)

DATE EXTENSION REVIEW (11/29/96, FOUNTAIN, D) MORE TIME NEEDED FOR EVALUATION. IN HOUSE TESTING IS INCLUSIVE AND EFFORTS ARE BEING MADE TO HAVE SAMPLES BY VENDOR LABORATORY.

14/18/97, C. GODDARD; EXTEND DUE TO MANPOWER RESTRAINTS

02/15/97, LANDAHL; EXTEND DUE/DEADS DUE TO MANPOWER RESTRAINTS

Recommended closure based on attached

Change(s) Approved By:

[Signature]
Manager

Date:

11/7/14/97

Change(s) Accepted By:

[Signature]
PR Coordinator

Date:

11/2/97

9. The Significance should: Be Upgraded Be Downgraded Remain the Same

If applicable, the reason for the upgraded:

Completed By: Jenny Gormin Date: 7/18/97
Evaluator/Mentor

Approved By: [Signature] Date: 7/15/97
Manager

005000

PR

Integrated Action Item Database Revision Form

PR08.0398.02

Estimate: 0

Date: 08/27/96

EVALUATION

Responsible Manager: PACE, R
Division: NESC
Department: CIV MECH
Sub Division:

ENTERED

Status: OPEN
Significance: 2
Priority: A2

Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: //	Due Date: 11/01/96
Assign Date: 08/24/96	Dead Date: 12/01/96
Start Date: 10/01/96	Completion Date: //

Action

DETERMINE THE EFFECTS OF THE ELEVATED NITRATE LEVELS ON THE CARBON STEEL PIPING OF THE TBCCW SYSTEM.

Closure Requirements

MEMO DETAILING THE RESULTS THE EVALUATION AND THE REQUIRED CORRECTIVE ACTIONS. CONCURRENCE MUST BE OBTAINED FROM ACTION ITEM OWNERS.

NOTE: CHEMISTRY HAS ALSO BEEN ASSIGNED AN ACTION TO DETERMINE THE CAUSE OF THE EXCESS NITRATE AND SHOULD BE ABLE TO PROVIDE ADDITIONAL INFORMATION TO ASSIST IN YOUR EVALUATION

Notes/Basis for Change(s)

Change(s) Approved By: T. White Date: 11/2/97
 Manager

Change(s) Accepted By: [Signature] Date: 11/2/97
 PR Coordinator

PROBLEM REPORT

PROBLEM REPORT No. 96-0396-R5 02

1. Problem Description:

High Nitrate levels exist in the TBCCW System. High Nitrate concentrations have been associated with stress corrosion cracking of carbon steel piping.

2. Apparent/Direct Cause:

Based on a study of literature on this subject, the likely direct cause is Nitrobacter bacteria conversion of Nitrites to Nitrates. An action item should be given Chemistry to sample and analyze the RBCCW and TBCCW, including the make-up water source, for the presence of Nitrobacter bacteria.

3. Repeat Occurrence: YES NO

4. Maintenance Rule Functional Failure: YES NO Unknown

5. Corrective Actions Completed (include Dates if possible)

A literature search (See Attached Letter for details and date completed) was performed to determine the most probable cause of the Nitrate build-up and its affect on carbon steel piping. Based on this research for the Nitrate concentration, system operating conditions and the duration of the present problem, the probability of developing stress corrosion cracking is low. However due to the lack of conclusive data at the appropriate operating conditions there is sufficient probability of stress corrosion cracking that an action item should be given to the MSTP Group to develop a program of sufficient duration to inspect TBCCW piping welds. Civ/ Struct/ Mech will assist the MSTP Group in the selection of inspection locations, as necessary.

6. Corrective Actions Required

(check "N/R" if not required) N/R

a) Action Required

Chemistry to sample and analyze the RBCCW and TBCCW, including the make-up water source, for the presence of Nitrobacter bacteria.

Closure Requirement

If Nitrobacter bacteria are found a biocide should be introduced as a part of a chemical treatment program to eliminate the bacteria and reduce the Nitrate concentration. Provide memo documenting details of this completion

Responsible Manager Dave Fountain

Due Date 04/01/97

Dead Date 05/29/97

b) Action Required

MSTP Group develop a weld inspection program.

Closure Requirement

ENTERED

17932 0050

MSTP Group develop a weld inspection program of sufficient duration for TBCCW piping welds. Provide more documented details of this completion.

Responsible Manager Kevin Burke

Due Date 04/31/97

Dead Date 05/30/97

7. Corrective Actions Required to Preclude Recurrence (check "N/R" if not required) N/R

a) Action Required

Mechanical select inspection points.

Closure Requirement

Mechanical/Civil/Structural selection of 4 to 10 inspection points based on the attached letter with proposed Altran criteria.

Responsible Manager Thomas White, Jr.

Due Date 04/31/97

Dead Date 05/31/97

b) Action Required

Closure Requirement

Responsible Manager

Due Date / /

Dead Date / /

8. Trend Data for Apparent Cause (check "N/R" for Direct Cause Analysis) N/R

NOTE

If more than 2 Inappropriate Actions are defined, use Exhibit 14.

a) Inappropriate Action (IA) Description:

0059
0000
0002

IA Job Title _____ IA Group _____ IA Department _____
IA Job Title _____ IA Group _____ IA Department _____

BECO _____ Contractor _____

Work Process _____ Key Activity _____
Work Process _____ Key Activity _____

O&P Failure Mechanism _____ HEIA Failure Mechanism _____

Human Error Type (Circle 1): Skill Based Rule Based Knowledge Based

Procedure Number(s) _____ Event Type _____

b) Inappropriate Action (IA) Description:

IA Job Title _____ IA Group _____ IA Department _____
IA Job Title _____ IA Group _____ IA Department _____

BECO _____ Contractor _____

Work Process _____ Key Activity _____
Work Process _____ Key Activity _____


O&P Failure Mechanism _____ HEIA Failure Mechanism _____


Human Error Type (Circle 1): Skill Based Rule Based Knowledge Based

Procedure Number(s) _____ Event Type _____

9. The Significance should: _____ Be Upgraded Remain the Same

If applicable, the reason for the upgraded:

Completed By: Raymond M. Pace  Date: 02/02/97
Evaluator/Mentor

Approved By: Thomas White  Date: 2/5/97
Manager

1793520360



Altran Corporation • 200 High Street • Boston, MA 02110

Tel. 617/330-1130 • Fax 617/330-1055

Mr. Raymond Pace
Boston Edison Company
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, MA 02360

December 31, 1996
96205.3

SUBJECT: Effects of Elevated Nitrate Concentrations on TBCCW and RBCCW Systems

Dear Mr. Pace:

Altran Corporation, at the request of Boston Edison Company (BECO), has performed a literature search for technical data on the effects of elevated nitrate concentrations on corrosion of carbon steels. Pilgrim Nuclear Power Station staff have measured nitrate concentrations of approximately 39 ppm in the RBCCW system and 945 ppm in the TBCCW system. A concern has been raised for possible stress corrosion cracking of the carbon steel system components as a result of the elevated nitrate concentrations.

Mechanism

The stress corrosion cracking of carbon steel discussed in the literature involves either high temperature/high concentration conditions typical in chemical processing facilities or laboratory testing under aggressive test conditions [1], [2]. Service temperatures referenced in the data were approximately 195°F and higher and laboratory testing typically was performed at boiling temperatures. Nitrate concentrations were 1 weight percent (10,000 ppm) and higher.

Stress corrosion cracking of carbon steel in nitrate solutions tends to be intergranular [1], [2], [3], [4]. The cracking typically is preceded by intergranular attack of the surface. One theory of the mechanism includes formation of iron oxide (Fe_3O_4) in the grain boundaries ahead of the crack by solid-state anodic reaction, anodic dissolution at the crack tip, and rapid rupture of the oxide film or oxide-metal interface [5]. Because local stresses at a weld can exceed the yield point of the steel, the stress corrosion cracking often occurs at welds [3].

Occurrences at Other Plants

Stress corrosion cracking of carbon steel by elevated nitrate concentrations is not a common corrosion mechanism in nuclear power plants. However, stress corrosion cracking of carbon steel components in cooling water systems treated with sodium nitrite have been documented at Duke Power's McGuire Station [6], [7] and Nebraska Public Power District's

¹Numbers in [] indicate references listed at the end of this letter.

Mr. Raymond Pace
December 31, 1996
96205.3
Page 2

Cooper Station [8]. Failures of carbon steel components in a cooling water system of similar chemistry also has been documented at a power plant in Japan [9].

At McGuire Station, stress corrosion cracking was identified as the failure mechanism for a carbon steel weld heat affected zone (HAZ) in the component cooling water system. Additional inspection revealed similar through-wall cracking in the HAZ of other welds in the system, primarily in dead legs such as drain lines and supply lines to deactivated (or removed) equipment. Subsequent investigation determined that each of the crack sites was covered with a deposit. Analysis of these deposits revealed the presence of iron oxidizing bacteria (*Gallionella*) and nitrogen fixing bacteria (*Nitrobacteraceae* or *Nitrobacter*). The *Nitrobacter*, which converts nitrite to nitrate, was identified as the most likely cause of a nitrate build-up in the cooling water system to levels reportedly as high as 3500 ppm. The deposit analysis also revealed a typical nitrate concentration factor of 10:1 within the deposit.

Corrosion products found within the cracks at McGuire indicated the cracks were not new. The component cooling water system had a history of high conductivity and bacteria population problems in the mid 1980's. Additionally, the chemical treatment program was not as well controlled or implemented during that period. Attempts to correlate the crack locations with biocide treatments in the mid 1980's indicated that the biocide may not have been adequately introduced into the areas which exhibited the recent cracks. This system history and the presence of corrosion products in the cracks suggest the cracks developed in the mid to late 1980's, but were just recently discovered.

Stress corrosion cracking was detected in welds in the carbon steel RBCCW system at Cooper Station in 1978 after approximately 4 years of service [8]. During that period of service, the system was treated with sodium nitrite. The cracking was thought to be the result of nitrates concentrated in the crevices formed by backing rings at the welds. In 1980, at the recommendation of GE, the plant ceased the sodium nitrite treatment and used only DI water with no chemical treatment in the RBCCW system. Another failure occurred in 1994 and was identified as stress corrosion cracking. However, in this case, the cracking was determined to be the result of oxygen cell corrosion.

Cooper Station continues to treat the Emergency Diesel generator jacket water cooling system with sodium nitrite. There have been no stress corrosion cracking failures identified in that system.

A stress corrosion cracking failure similar to that at McGuire was reported at a Japanese power station [9]. In that failure, intergranular cracking occurred at the welds in a carbon steel circulating cooling water system. Make-up water was provided from a storage tank vented to the atmosphere and filled with demineralized river water. The system was treated with sodium nitrite as a corrosion inhibitor along with sodium carbonate, sodium borate, and benzotriazole. Most of the crack sites were covered with tubercles.

Mr. Raymond Pace
December 31, 1996
96205.3
Page 3

Sodium nitrite concentration was maintained at approximately 200 ppm with a conductivity limit of 1000 μ S/cm at pH 9-9.5. The plant observed a decrease in sodium nitrite concentration a few days after addition of the inhibitor. A blow down of the system failed to halt the decrease. Typical water chemistry was 50-500 ppm NaNO_2 , 100-1000 ppm NaNO_3 , and pH 9.3.

The cause of the high nitrate concentration was determined to be the result of nitrobacteria activity. A series of tests were performed which demonstrated the conversion of nitrite to nitrate by reaction with molecular oxygen (dissolved oxygen in the water) had no appreciable effect on either the nitrite or nitrate concentrations over a test duration of 20 days. However, testing with and without (either sterilized or filtered) the bacteria showed a significant decrease in nitrite concentration and corresponding increase in nitrate concentration throughout the 10-11 days duration of the tests.

Additional testing performed by the Japanese showed the conditions within the tubercles to be much more aggressive than the bulk water chemistry [9]. Ferric nitrate formed within the tubercle is hydrolyzed to form nitric acid, driving the pH down. Depending upon the ferric nitrate concentration, pH values could be less than 3. At this pH, the nitrite ion will self-decompose to nitrate.

The conditions/mechanisms involved in the Japanese power plant cooling water system leading to the cracking were presented as:

- a 4 month period between initial system operation and the first addition of chemical treatment
- demineralized, but not sterilized or disinfected, make-up water
- development of tubercles
- bacteria conversion of nitrite to nitrate and corrosion of the steel beneath the tubercles
- lowering pH by hydrolyzation of ferric nitrate under the tubercles and in the corrosion pits
- further conversion of nitrite to nitrate in the acidic conditions
- more severe corrosion beneath the tubercles
- cracking of the carbon steel

It also was noted that the sodium carbonate component of the chemical treatment served as a carbon source for the bacteria.

Correlation to Pilgrim

There are a number of factors which affect this corrosion mechanism and prevent direct correlation of the data presented in the literature to the conditions in the Pilgrim TBCCW and RBCCW systems. Temperatures in the Pilgrim systems are normally in the range of 80-130°F [10]. Attempts to extrapolate from the higher temperature data to service temperatures similar to those at Pilgrim are not possible.

Mr. Raymond Pace
December 31, 1996
96205.3
Page 4

Personnel at the McGuire Station reported that the stress corrosion cracking in the component cooling water system occurred in low flow and stagnant fluid areas of the system [6], [7]. Much of the literature data fails to discuss flow conditions. Additionally, McGuire and the Japanese plant [9] identified nitrogen fixing bacteria (*Mitrobacter*) as the predominate source of the nitrate concentration through conversion of nitrite in the corrosion inhibitor. No bacteria or nitrite corrosion inhibitors are mentioned in the cracking occurrences or used in the laboratory testing discussed in the literature.

Although direct correlations may not be made between the literature and the Pilgrim systems, several statements can be made. Test data reported in the literature indicate carbon steel with a carbon content of 0.25 percent or less is more susceptible to stress corrosion cracking in nitrate solutions than steel with a higher carbon content [1], [2]. Much of carbon steel in the Pilgrim TBCCW and RBCCW systems has a specified maximum carbon limit of 0.30 weight percent. Therefore, from a material composition perspective, the system materials are susceptible.

Heat treatment of the material also is identified as a contributing factor to the stress corrosion cracking problem [1], [3], [4]. Specifically, carbon steel welds which are post weld heat treated are less susceptible to stress corrosion cracking. In the petrochemical industry, it had been common to post weld heat treat all carbon steel welds for use in service temperatures above 200°F in certain systems. After several occurrences of stress corrosion cracking of carbon steel welds in these systems, the industry practice is changing to post weld all carbon steel welds, regardless of service temperature. In nuclear power plants, the fabrication code, either ANSI B31.1 Piping or ASME Boiler and Pressure Vessel Code, does not require post weld heat treatment for most carbon steel welds which would be used in the closed loop cooling water systems. This lack of post weld heat treatment makes the Pilgrim TBCCW and RBCCW system welds more susceptible to stress corrosion cracking than heat treated welds.

Bulk water concentrations of nitrates in the Pilgrim TBCCW system reportedly reached 945 ppm, or approximately one tenth of the lowest nitrate concentration reported in the literature as being associated with stress corrosion cracking of carbon steel in nitrate solutions [8]. This concentration is approximately the same as that reported in the Japanese cooling water system [9]. McGuire Station personnel reported an estimated maximum bulk water nitrate concentration of approximately 3500 ppm [9]. However, they also reported that their analysis indicated a nitrate concentration factor of 10:1 under deposits found on each of the crack locations, as compared to the bulk fluid. Using this concentration factor and the lack of stress corrosion cracking incidents reported in the literature for nitrate concentration less than 1 weight percent, McGuire Station established an interim bulk limit of 1000 ppm nitrate concentration in the component cooling water system. Stress corrosion coupon testing is currently in progress to validate or adjust this limit. At Pilgrim, a 10:1 concentration factor can result in an approximate concentration of 9450 ppm nitrate in a deposit in the system, if such deposits exist.

The conditions reported for the Pilgrim TBCCW system indicate a potential for degradation as a result of the elevated nitrate concentration. However, additional definition of the actual conditions in the system is required to more thoroughly evaluate this potential.

Specifically, the chemical treatment program information provided by BECO indicates that no microbiocide is used. Because McGuire and the Japanese plant found nitrobacteria to be a significant contributor to the problem, the Pilgrim system should be sampled and analyzed for this bacteria. Although BECO indicates a leak required injection of air saturated makeup water to the system starting in June 1996, the conductivity to nitrite ratio indicated a sharp change in early May 1996. This suggests that a factor other than the introduction of oxygen into the system may have affected the nitrate concentration or that some other contaminant had been introduced into the system. Additionally, the testing performed by the Japanese indicates conversion of nitrites to nitrates by reaction with dissolved oxygen is minimal.

McGuire Station and the Japanese plant indicated the presence of deposits at each crack location which tended to concentrate the nitrate concentration. The crack locations at McGuire also correlated to low flow and stagnant fluid areas of the system which were suspected of not being adequately treated with a biocide. The presence of similar deposits at welds in the Pilgrim TBCCW would be indicative of a potential corrosion site.

Recommendations

When corrosion tests being performed by McGuire are complete, more conclusive data may be available. The following actions may be useful considerations in determining the effects of the elevated nitrate concentration in the TBCCW system.

- Sample and analyze the TBCCW water for the presence of *Nitrobacter* bacteria. Sample the RBCCW also, particularly if make-up water for both systems is provided from the same source. If nitrobacteria are found, sample and analyze the make-up water source.
- Visually inspect the exterior of the system for evidence of leakage at welds (dripping water, wetted insulation, rust staining, etc.). Investigate any leakage discovered.
- Select a sample of the welds in the system for insulation removal and more thorough inspection. Because the corrosion condition of the system is unknown and bacteria activity is a potential concern, it is not feasible to identify a sample size which could be used to assess the entire system. Data provided by inspection of sample welds will provide only an indication of the potential corrosion activity in the system. The welds selected for insulation removal should include welds from various system conditions such as:

Mr. Raymond Pace
December 31, 1996
96205.3
Page 6

- areas of the system with low flow or stagnant fluid conditions, such as drain lines, supply lines to standby components, and portions of the system in wet lay-up.
 - welds with backing rings installed.
 - welds subjected to higher stress loading (in long spans between supports, potential cold spring, cyclic or vibrating loading, etc.).
- **Nondestructive examination (NDE) methods should be considered for inspection of the welds exposed by insulation removal.** Because the potential cracking initiates on the wetted (interior) surface, volumetric examinations (UT and RT) would be the most useful. Surface examination by MT or PT would not detect defects which have not reached the exterior surface.
 - **Inspect the interior surfaces of the system which may become available for inspection during the outage due to system/component opening for other reasons (e.g., heat exchangers, pumps, valves, strainers, etc.).** Inspect the interior surfaces for evidence of deposit accumulations or corrosion activity at the welds.
 - **Take action to reduce the nitrate concentration.** In the absence of detailed information on the conditions within the system, the nitrate concentration should be lowered to a level similar to that reported in the RBCCW system. Although the nitrate concentration of 945 ppm at Pilgrim is below the 3500 ppm concentration reported at the McGuire Station, it is within the range of bulk water nitrate concentration reported for the Japanese plant which experienced cracking in the cooling water system.

As previously stated, there is little information in the literature on stress corrosion cracking of carbon steel in sodium nitrate solutions at near ambient temperatures and low nitrate concentrations. Only three occurrences of this degradation in other power plants was identified. The few references cited in this letter proved to be the most useful. Listed after the references are additional documents discussing stress corrosion cracking of carbon steels.

Please note that the information provided in this letter is an interpretation based on a limited literature search. This letter is intended to provide background information and is not intended to be used as a basis for nuclear safety related design input.

Mr. Raymond Pace
December 31, 1996
96205.3
Page 7

Should you have any questions, please do not hesitate to call. We will be pleased to assist your efforts to more thoroughly define the TBCCW system condition and effects of the elevated nitrate concentration and to determine appropriate mitigative actions.

Very truly yours,

ALTRAN CORPORATION



Dick Martin
Project Engineer

cc W. McBrine
O. Van Der Schijff

0067

2

Additional Sources of Information

K. Zhao, *Effect of Temperature, Concentration of Medium, and Potential on Intergranular stress Corrosion Cracking of Mild Steel in NaNO₃ Solution*. 10th International Congress on Metallic Corrosion. Madras, India, November 7-11, 1987.

W. Dahl, *Investigations on the Influence of Temperature, Nitrate Concentration and Potential, as Well as Molybdenum Content and Structure on Stress Corrosion Cracking of Carbon Steels*. Werkst. Korros. May 1987. (German language)

R. Raicheff, and L. Fachikov, *Stress-Corrosion Cracking of Low-Carbon Steel in Nitrate Solutions*. Eurocorr Conference, Budapest, Hungary. GTE Rendezvény Iroda Gondozasaban. October 21-25, 1991.

S. W. Ciaraldi, *Stress-Corrosion Cracking of Carbon and Low-Alloy Steels (Yield Strengths Less than 1241 MPa)*. Stress Corrosion Cracking: Materials Performance and Evaluation, ASM International, 1992, pp.41-61.

Z. Chen, G. Zhou, and J. Dong, *Stress Corrosion Cracking of Welded Joints in caustic and Nitrate Solutions*. 10th International Congress on Metallic Corrosion. Madras, India, November 7-11, 1987.

C. M. Rangel and R. N. Parkins, *Aspects of the Inhibition by Nitrite of the Stress Corrosion Cracking of Mild Steel in Nitrate Solutions*. 6th European Symposium on corrosion Inhibitors, Ferrara, Italy, September 16-20, 1985. (Russian language)

J. Zuo, G. Wang, and Y. Xu, *Investigation of Chemical and Electrochemical Changes Within Crevices and Stress Corrosion cracks in Mild Steel in Nitrate Solution*. International Congress on Metallic Corrosion. Toronto, Canada, June 3-7, 1984.

M. S. de Santa Maria, J. I. Verdeja, and J. A. Perosanz, *Failure Analysis of a Low-Carbon Steel Structure: a Stress Corrosion Problem*. 13th Annual Technical Meeting, International Metallographic Society, Brighton, England, August 18-20, 1980.

J. I. Mickalonis, *Corrosion Study for Waste Tanks to High Salt Concentration Conditions*. Westinghouse Savannah River Company Report No. WSRC-TR-95-0116, March 10, 1995.

PR

Integrated Action Item Database Revision Form

PR96.0396.03

Extension: 3

Date: 04/02/1998

CA

ADDITIONALLY, SAMPLES WERE TAKEN FOR TOTAL BACTERIA ON THESE SYSTEMS AND ZERO COLONIES WERE DETECTED. MONTHLY SAMPLING FOR TOTAL BACTERIA IS NOW ROUTINELY PERFORMED ON ALL CLOSED COOLING WATER SYSTEMS.

SAMPLING FOR NITRATE LEVELS IN THE TBCCW SYSTEM (AND RBCCW) ARE ALSO PERFORMED MONTHLY. NO SIGNIFICANT TRENDS IN NITRATE HAVE BEEN IDENTIFIED.

THE RATIO OF THE SYSTEM CONDUCTIVITY TO NITRITE IS ALSO CALCULATED DURING WEEKLY ANALYSIS. THIS IS ANOTHER METHOD TO DETERMINE IF ANY ADVERSE TRENDS ARE OCCURRING WITHIN A CLOSED COOLING SYSTEM. AGAIN NO SIGNIFICANT TRENDS HAVE BEEN IDENTIFIED.

DUE TO THE LACK OF TOTAL BACTERIA AND NITROBACTERIA AS DETERMINED BY GRAB SAMPLING THIS ITEM IS CLOSED. NO ADDITIONAL ACTIONS ARE REQUIRED UNLESS FUTURE ROUTINE TESTING WERE TO REVEAL ADVERSE TRENDS. A NEW PROBLEM REPORT WOULD BE GENERATED AT THAT TIME.

Change(s) Approved By: _____

Manager

Date: _____

11/10/95 4/3/98

Change(s) Accepted By: _____

PR Coordinator

Date: _____

11/7/98

08
08
11732

ENTERED

PR
Date: 05/20/97

PR# 0358.04
CA

Estimate: 0

Responsible Manager: BURKE, K.
Group: PLANT
Department: OPS
Sub Department: OPS SUP

Status: OPEN
Significance: N.
Priority: 90
Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: //	Due Date: 04/01/97
Assign Date: 02/06/97	Dead Date: 05/30/97
Start Date: 02/06/97	Completion Date: //

Action

MSTP GROUP DEVELOP A WELD INSPECTION PROGRAM.

Closure Requirements

MSTP GROUP DEVELOP A WELD INSPECTION PROGRAM OF SUFFICIENT DURATION FOR TBCW PIPING WELDS. PROVIDE MEMO DOCUMENTING DETAILS OF TASK COMPLETION.

Notes/Basis for Change(s)

MSTP NO DR 5601262 CREATS TO TRACK WELD QUALITY AND EXAMINATION (SEE ATTACHMENT)

Change(s) Approved By: [Signature] Date: 11/5/20/97

Change(s) Accepted By: [Signature] Date: 11/5/22/97
PR Coordinator
Jowid 6/2/97

NFW

1 Title: **EXAMINATION OF TBCCW SPECIFICATION FOR PIPING EROSION/CORROSION MONITORING FOR STRESS CORROSION CRACKING SPEC N-577 QRS 50.80**

2 Procedure Number: **5001262**

Node Number: ~~6000~~ **5001262**

Rep Task Number: ~~5001000~~

Task Type: **B**
~~Regulatory commitment~~ **INTERNAL COMMITMENT**

Frequency: **46 1/NO**

Schedule Basis: **1**

Lead Division: **18 QUALITY CONTROL**

Owner: **18 QUALITY CONTROL**

Notes/Work Instructions: ~~PERFORM UT INSPECTION OF POINTS SELECTED BY HER 285084 & 285085. THIS SHOULD BE DONE EVERY INSPECTING OUTAGE. ANY~~ **EXP 250.**

Current Node: **1**

Next Tasks to Generate: **COLD SHUTDOWN**

Exit Node:

System:

**UT- EXAMINATION OF 5 OF 11 COMPONENTS
11 COMPANIES ARE IN PROGRAM AND
ALL MUST BE INSPECTED TWICE IN SRFU'S**

Standard/Requirement: ~~BLANK 2.70.149, IRL MEMO LETTER BY US, 2800~~ **PROBLEM REPORT 96-039606**

Issues: ~~RESPONSE BY 487~~

Equipment Tested: **AJ P; P**

Local Tests: **PIPING**

Preceding Tests: **IDENTIFY INSPECTION LOCATIONS**

Preceding Tests:

Issue Info: **NFW**

Start On: ~~05/15/95; 05/12/95~~

End On: ~~RFO-12(8); RFO-11(8); RFO-10(8)~~

Status: ~~RFO-12(8); RFO-11(8); RFO-10(8)~~

Test Results: **NO**

Test Results: **N/A**

Components: **N/A**

NO OUTAGE_1; NO_OB; NO_OUTAGE_2; NO_OUTAGE_3; SRR

Submitter: **Cheryl G...** **51810**

Rep Task Coord.: **...** **51017**

Source Rep.: **R. Johnson** **51017**

System Eng.: **...**

Task Coord.: **...** **51997**

ACR Impact Y/N **N**

For non-conservative commitment/requirement changes
Technical Basis is required for changes to the NETP Database.

PR

Integrated Action Item Database Revision Form

PR95.0396.05

Revision: 0

CA

Date: 05/13/97

Responsible Manager: PACE, R

ENTERED

Status: ~~COMPLETED~~ *Ch*

Group: KESG

Significance: N.

Department: CIV MECH

Strategy: DE

Priority: 90

Sub Department:

Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: //

Due Date: 04/01/97

Assign Date: 02/06/97

Dead Date: 05/31/97

Start Date: 02/06/97

Completion Date: 05/08/97

Action

MECHANICAL SEAL INSPECTION POINTS.

Closure Requirements

MECHANICAL/CIVIL/STRUCTURAL SELECTION OF 5 TO 10 INSPECTION POINTS BASED ON THE ATTACHED LETTER WITH PROPOSED ALTRAM CRITERIA

PROBLEM REPORT

PROBLEM REPORT No. PR95.0396.05

1. Problem Description:

High nitrate levels exist in the TBCCW system. High nitrate concentrations have been associated with stress corrosion cracking of carbon steel piping.

2. Apparent/ Direct Cause

Based on a study of literature on this subject, the likely direct cause is Nitrosobacter bacteria conversion of Nitrites to Nitrates.

3. Repeat Occurrence: YES NO

4. Maintenance Rule Functional Failure YES NO Unknown

5. Corrective Actions Completed (include Dates if possible)

A test action item (PR 0396.02) was given Chemistry to sample and analyze the RBCCW and TBCCW, including the make-up water source, for the presence of Nitrosobacter bacteria.

Mechanical/Civil/Structural selection of 5 to 10 inspection points based on the Altran Letter with proposed criteria

6. Corrective Actions Required (check "N/R" if not required) N/R

a) Action Required

Visual inspection program developed for selected points. See Attached.

Closure Requirement

Visual inspection program implemented. See Attached

Responsible Manager C. Garow

PR

Integrated Action Item Database Revision Form

PR98.0398.05

Extension: 0

CA

Date: 05/13/97

Due Date: 06/30/97

Dead Date: 08/31/97

7. Corrective Actions Required to Preclude Recurrence (check "N/R" if not required) 4 N/R

8. Trend Data for Apparent Cause (check "N/R" for Direct Cause Analysis) X N/R

9. The Significance should: Be Upgraded 4. Remain the Same

If applicable, the reason for the upgraded N/A

Completed By R. PACE Date 4/8/97
Evaluator/Manager

Approved By T. WHITE Date 4/8/97
Manager

ENTERED

PROBLEM STATEMENT

As discussed in PR 98.0398.02 [3] it has been determined that elevated nitrate concentrations can result in intergranular stress corrosion cracking (IGSCC) of carbon steel (CS) piping. Because Pilgrim Nuclear Power Station (PNPS) has had a short duration of marginally unacceptable nitrate concentrations, PR 98.0398.05 requests that NESC, Mechanical/Civil Structural select 5 to 10 inspection locations on the affected Turbine Building Closed Cooling Water (TBCCW) system [4].

SUMMARY

Eleven inspection locations have been selected for the in-service inspection (ISI) of the TBCCW piping for IGSCC. It is recommended that an inspection program be implemented that is 10 years in duration with 2 year inspection intervals. The duration of the program is selected to cover the incubation period necessary for the formation of IGSCC. Five inspection locations should be selected for each inspection interval and results reported to NESC (Mechanical/Civil Structural). All locations should be visually inspected at a minimum of two inspection intervals over the program duration.

If problems are discovered during later inspections the scope would be expanded by the addition of several new locations for inspection and the use of volumetric inspection techniques. In this case, criteria for scope expansion will be developed based on the inspection results and water chemistry history. Therefore nitrate concentration history is an important input to the program. Chemistry was given an action item [2] to develop a program and document this information to NESC. If no IGSCC is found over the recommended program duration and low nitrate levels (<500 PPM) are maintained the inspection program can be discontinued.

A closed cooling water/ plant heating corrosion monitoring system will be installed in the near future. If a corrosion sample for the TBCCW system containing a carbon steel weld (P1) can be incorporated into the program the piping inspections may be eliminated. The monitoring of the corrosion sample is a more accurate predictor of the system condition.

ASSUMPTIONS

As stated in the Altran Corporation letter attached to the problem report, IGSCC is not common to CS piping. The interaction of the contributing factors: temperature, stress and water chemistry have not been adequately addressed in the literature and test data to date. This lack of information makes it difficult to determine the degree of susceptibility of the TBCCW piping to IGSCC at Pilgrim, although susceptibility is believed to be low based on present knowledge of the interaction parameters. The conservative assumption that it is necessary to monitor the TBCCW for IGSCC, requires development of a program. Therefore, potentially susceptible locations are identified for sampling, based on the best information currently available, to assess the adequacy of the entire system. At a later date, as further industry information becomes available and based on the inspection data, the program duration and inspection interval may be reconsidered by NESC, Mechanical/Civil Structural.

In addition to the work performed by Altran, the problem and proposed inspection program were discussed (04/24/97) with Messrs. Ken Wilens and Eric Semler of Yankee and George Lucina of Structural Integrity Associates (SIA) to obtain their industry experience with IGSCC of CS piping. In a low stress system such as TBCCW the potential for cracking is greatest in the heat affected zone (HAZ) of the circumferential girth welds primarily due to the residual weld stresses. That is, since stress is an important initiation parameter. Cracking generally propagates normal to the weld (pipe longitudinal direction) and arrests once the crack propagates beyond the HAZ due to reduced stress levels.

INPUT DATA

The PR 98.0398.05 provided (Altran) inspection criteria for determining susceptibility to stress corrosion cracking that are based on:

PR

Integrated Action Item Database Revision Form

PR06.0396.06

Extension: 0

CA

Date: 06/13/97

1. Locations of low flow and/or stagnant fluid areas (e.g., drain lines, etc.)
2. High stress weld locations, especially those which have not been post weld heat treated (PWHT).

METHOD OF EVALUATION

Inspection locations are to be selected based on the criteria listed above (see Input Data) which include low flow and high stress weld locations. Generally, operational stresses in the TBCCW piping systems are low. Therefore, more locations are selected in potential low flow/stagnant flow locations (including adjacent weld HAZ) than at high operational stress locations.

A review of BECo Welding Specification M305 [2] indicates that none of the TBCCW piping welds have been PWHT. Therefore, none are eliminated from the sample population. The selection of points based on the criteria is biased to the portion of the system that is designated Pressure Boundary Only (PBO). That is, those parts of the TBCCW that are in the TBCCW pump compartments but not required for safety-related operation [1]. Large bore TBCCW system piping in these compartments designated as PBO, is stress analyzed [3] and detailed stress information is available for reference.

POINT SELECTION

The following locations have been selected for inclusion in the TBCCW IOSCC program. The selections were whittled down for inspection accessibility to each of the locations. Notes are provided describing potential access problems. Some of the locations will require access using scaffolding or ladders. Five of the locations should be selected and inspected at each inspection interval. All locations should be placed in the program and inspected at a minimum of two inspection intervals over the program duration.

1. TBCCW Pumps (P-110 A & B) Suctions [sic], HX "A" loop discharge piping (16"-HE-30, El. 12'-4 1/2") to the TBCCW pump suction header, located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect elbow downstream of valve 30-HO-670 and run of piping to anchor H-30-1-208R. Include adjacent elbow butt weld and the accessible piping in the heat affected zone formed by the anchor stanchion welds. Point selection criteria - stress.
2. TBCCW Pumps (P-110 A & B) Suctions [sic], makeup line from the condensate storage tank T-104 to TBCCW pump suction header (27"-HB-30, El. 12'-4 1/2") located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect a 12' length of the horizontal piping (3"-HE-30, El. 17'-8 1/4") immediately upstream of the 900 elbow and vertical run to the branch connection at the suction header. Include piping in the heat affected zone formed by the elbow socket weld. Areas obstructed by the support brace or duct work need not be inspected. Point selection criteria - flow.
3. TBCCW Pumps (P-110 A & B) Suctions [sic], heater bypass piping (16"-HE-30, El. 12'-4 1/2") from HX "A" loop discharge piping, located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect the horizontal run of piping from the branch connection at the pump suction header (16"-HE-30, El. 12'-4 1/2") upstream to the first (900) elbow. Include adjacent piping in the heat affected zone formed by the branch connection and elbow butt welds. Point selection criteria - flow.
4. TBCCW System (from 531 to HX-E-122 A & B Inlet) [sic], heater bypass piping (16"-HE-30, El. 4'-6") to HX inlet header (20"-HE-30, El. 12'-4 1/2"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect elbow between valves 30-HO-695 and TV-4161. Include elbow butt welds. Point selection criteria - flow.
5. TBCCW System (from 531 to HX-E-122 A & B Inlet) [sic], return piping (4"-HE-30, El. 13'-6 1/4") to HX inlet header (20"-HE-30, El. 12'-4 1/2"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect a 12' length of the horizontal piping run immediately upstream of the 450 elbow that branches into the TBCCW HX supply header. Include the adjacent elbow butt weld. It may be somewhat difficult to gain access to this area due to an overhead lighting fixture. Point selection criteria - stress.
6. TBCCW System P-110 A Discharge [sic], pump discharge piping (14"-HE-30, El. 8'-6"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect the elbow downstream of valve 30-HO-683. Include the elbow butt welds. Point selection criteria - flow.
7. TBCCW System P-110 B Discharge [sic], pump discharge piping (14"-HE-30, El. 8'-6"), located in the "B" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect the elbow downstream of valve 30-HO-682. Include the elbow butt welds. Point selection criteria - flow.
8. TBCCW Discharge to Air Condition System [sic], branch piping (4"-HE-30, El. 13'-6 1/4") from the pump discharge header (20"-HE-30, El. 12'-6 1/4"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect a 12' length of the horizontal piping and first 900 elbow upstream of the branch connection to the pump discharge header. Include the elbow butt welds. Point selection criteria - stress.
9. TBCCW Discharge to Air Condition System [sic], branch piping (4"-HE-30, El. 12'-6 1/4") from the pump discharge header (20"-HE-30, El. 12'-6 1/4"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect a 12' length of 450 piping at the branch connection to the pump discharge header. This point will be extremely difficult to inspect due to congestion from surrounding piping and conduit. However, it is the system

PR

Integrated Action Item Database Revision Form

PR96.0396.05

Estimate: 0

CA

Date: 05/13/97

High stress location and an important data point. Include the adjacent elbow butt welds and piping in the heat affected zone formed by the branch connection welds. Point selection criteria - stress.

10. Chemical Addition Tank T-211 C Outlet Process line (8), branch piping (1"-HE-30, El. 14'-1") from the TBCCW pump suction piping (18"-HE-30, El. 12'-43"), located in the "B" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect the S-D bend branch piping component downstream of valve 30-MO-672. It is not necessary to inspect the underside of the pipe in the area obstructed by the Unistrut support brace. Point selection criteria - flow.

11. Chemical Addition Tank T-211 C Inlet Process line (8g), branch piping (1"-HE-30, El. 15'-10") from the TBCCW pump discharge piping (20"-HE-30, El. 12'-43"), located in the Aux. Bay condenser transfer and plant heat pump compartment (Floor El. 3'-0"). Inspect the 12' length of horizontal piping, upstream from the branch connection to the pump discharge piping and valve 30-MO-686, immediately beyond the first 900 elbow. Include piping in the heat affected zone formed by the elbow socket weld. Point selection criteria - flow.

INSPECTION CRITERIA

A leak-before-break approach is advocated for this P&O system, based on a study performed using Code Case N-463-1 to determine critical flaw sizes in CS piping. The results are provided below for the bounding pipe sizes of concern. From inspection of the table it is evident that a through-wall crack will be discovered long before it reaches critical flaw size. In fact, based on the above discussion (see Assumptions) the cracks will arrest prior to reaching critical flaw size. Therefore should a problem arise it would be discovered as minor water leakage during the current schedule of Aux. Bay operator tours. The drains in the Aux. Bay are equipped to handle leakage far in excess of that anticipated from a through wall IGSCC crack. The current levels of operator tours and training are sufficient. While this level of inspection is adequate it will be augmented by a visual inspection program, specific to the locations described above.

NPS Critical Flaw Size (inches)

(inches)Circumferential Axial

3 3 42

20 16 41

The purpose of the augmented VT-1 inspections is to identify any reportable indications that suggest the presence of IGSCC in the TBCCW carbon steel piping and associated welds to NESC, Mechanical Civil Structural. This piping shall be inspected using VT-1 visual examination methods, conforming to ASME XI, 1999 Edition, with crack like indications causing rejection or further evaluation by a BECo Level III examiner. Any detectable crack or linear indications shall be reported by a Non-Conformance Report.

REFERENCES

1. PNPS O-List
2. PNPS Welding Requirements of Field Erected Piping, Specification M305
3. PR 96.0396.02
4. P & ID M216
5. Piping Analysis Index, M561
6. PNPS Stress Isometric Numbers (See Attachment)
 - a) 6495-629
 - b) 6495-630
 - c) 6495-631-1
 - d) 6495-631-2
 - e) M1004 SHE 5
 - f) M1004 SHE 6
7. ASME Nuclear Code Case N-463-1

ATTACHMENT —

PNPS Stress Isometric Numbers

6495-629

6495-630

6495-631-1

6495-631-2

M1004 SHE 5

M1004 SHE 6

PR

Integrated Action Item Database Revision Form

PR96.0396.05

Extension: 0

CA

Date: 05/13/97

Notes/Basis for Change(s)

Change(s) Approved By: See attached Date: 11
Manager

Change(s) Accepted By: SHATAS A Date: 05/13/97
PR Coordinator

0 0 7 4
1 1 2 2

PROBLEM REPORT
PROBLEM REPORT No. PR#0396.05

ENTERED

PROBLEM DESCRIPTION

1. Problem Description:

High nitrate levels exist in the TBCCW system. High nitrate concentrations have been associated with stress corrosion cracking of carbon steel piping.

2. Apparent/ Direct Cause:

Based on a study of literature on this subject, the likely direct cause is Nitrobacter bacteria conversion of Nitrites to Nitrates.

3. Repeat Occurrence: YES NO

4. Maintenance Rule Functional Failure: YES NO Unknown

5. Corrective Actions Completed (include Dates if possible)

A past action item (PR.0396.02) was given Chemistry to sample and analyze the RBCCW and TBCCW, including the make-up water source, for the presence of Nitrobacter bacteria.

Mechanical/ Civil/ Structural selection of 5 to 10 inspection points based on the Altran Letter with proposed criteria.

6. Corrective Actions Required

(check "N/R" if not required) N/R

a) Action Required

Visual inspection program developed for selected points. See Attached.

Closure Requirement

Visual inspection program implemented. See Attached.

Responsible Manager C. Garrow

Due Date: 06 / 30 / 97

Dead Date: 06 / 31 / 97

b) Action Required

Closure Requirement

Responsible Manager

Due Date ___/___/___

Dead Date ___/___/___

0377
PR.0396

7. Corrective Actions Required to Preclude Recurrence (check "NR" if not required) NR

a) Action Required

Closure Requirement

Responsible Manager

Due Date ___/___/___

Dead Date ___/___/___

b) Action Required

Closure Requirement

Responsible Manager

Due Date ___/___/___

Dead Date ___/___/___

8. Trend Data for Apparent Cause (check "NR" for Direct Cause Analysis) _____ NR

NOTE

If more than 2 Inappropriate Actions are defined, use Exhibit 14.

a) Inappropriate Action (IA) Description:

IA Job Title _____ IA Group _____ IA Department _____
IA Job Title _____ IA Group _____ IA Department _____

BECO _____ Contractor _____

Work Process _____ Key Activity _____
Work Process _____ Key Activity _____

O&P Failure Mechanism _____ HEIA Failure Mechanism _____

Human Error Type (Circle 1): Skill Based Rule Based Knowledge Based

Procedure Number(s) _____ Event Type _____

b) Inappropriate Action (IA) Description:

IA Job Title _____ IA Group _____ IA Department _____
IA Job Title _____ IA Group _____ IA Department _____

BECO _____ Contractor _____

Work Process _____ Key Activity _____
Work Process _____ Key Activity _____

O&P Failure Mechanism _____ HEIA Failure Mechanism _____

Human Error Type (Circle 1): Skill Based Rule Based Knowledge Based

Procedure Number(s) _____ Event Type _____

9. The Significance should: _____ Be Upgraded Remain the Same

If applicable, the reason for the upgraded:

Completed By: Raymond R. Rose Date: 05/02/97
Evaluator/Monitor

Approved By: Thomas White Date: 5/7/97
Manager

**Selection of TBCCW
Piping Inspection Locations
For Detection of
Intergranular Stress Corrosion Cracking**

PROBLEM STATEMENT

As discussed in PR 96.0396.02 [3] it has been determined that elevated nitrate concentrations can result in intergranular stress corrosion cracking (IGSCC) of carbon steel (CS) piping. Because Pilgrim Nuclear Power Station (PNPS) has had a short duration of marginally unacceptable nitrate concentrations, PR 96.0396.05 requests that NESG, Mechanical/ Civil/ Structural select 5 to 10 inspection locations on the affected Turbine Building Closed Cooling Water (TBCCW) system [4].

SUMMARY

Eleven inspection locations have been selected for the inservice inspection (ISI) of the TBCCW piping for IGSCC. It is recommended that an inspection program be implemented that is 10 years in duration with 2 year inspection intervals. The duration of the program is selected to cover the incubation period necessary for the formation of IGSCC. Five inspection locations should be selected for each inspection interval and results reported to NESG (Mechanical/ Civil/ Structural). All locations should be visually inspected at a minimum of two inspection intervals over the program duration.

If problems are discovered during later inspections the scope would be expanded by the addition of several new locations for inspection and the use of volumetric inspection techniques. In this case, criteria for scope expansion will be developed based on the inspection results and water chemistry history. Therefore nitrate concentration history is an important input to the program. Chemistry was given an action item [3] to develop a program and document this information to NESG. If no IGSCC is found over the recommended program duration and low nitrate levels (<500 PPM) are maintained the inspection program can be discontinued.

A closed cooling water/ plant heating corrosion monitoring system will be installed in the near future. If a corrosion sample for the TBCCW system containing a carbon steel weld (P1) can be incorporated into the program the piping inspections may be eliminated. The monitoring of the corrosion sample is a more accurate predictor of the system condition.

ASSUMPTIONS

As stated in the Altran Corporation letter attached to the problem report, IGSCC is not common to CS piping. The interaction of the contributing factors: temperature, stress and water chemistry have not been adequately addressed in the literature and test data to date. This lack of information makes it difficult to determine the degree of susceptibility of the TBCCW piping to IGSCC at Pilgrim, although susceptibility is believed to be low based on present knowledge of the interaction parameters. The conservative assumption that it is necessary to monitor the TBCCW for IGSCC, requires development of a program. Therefore, potentially susceptible locations are identified for sampling, based on the best information currently available, to assess the adequacy of the entire system. At a later date, as further industry information becomes available and based on the inspection data, the program duration and inspection interval may be reconsidered by NESG, Mechanical/ Civil/ Structural.

In addition to the work performed by Altran, the problem and proposed inspection program were discussed (04/24/97) with Messrs. Ken Willens and Eric Bemiller of Yankee and George Lucins of Structural Integrity Associates (SIA) to obtain their industry experience with IGSCC of CS piping. In a low stress system such as TBCCW the potential for cracking is greatest in the heat affected zone (HAZ) of the circumferential girth welds primarily due to

R. Pace

2
0
0
0
2
1

**Selection of TBCCW
Piping Inspection Locations
For Detection of
Intergranular Stress Corrosion Cracking**

the residual weld stresses. That is, since stress is an important initiation parameter. Cracking generally propagates normal to the weld (pipe longitudinal direction) and arrests once the crack propagates beyond the HAZ due to reduced stress levels.

INPUT DATA

The PR 96.0396.05 provided (Altran) inspection criteria for determining susceptibility to stress corrosion cracking that are based on:

1. Locations of low flow and/ or stagnant fluid areas (e.g., drain lines, etc.).
2. High stress weld locations, especially those which have not been post weld heat treated (PWHT).

METHOD OF EVALUATION

Inspection locations are to be selected based on the criteria listed above (see Input Data) which include low flow and high stress weld locations. Generally, operational stresses in the TBCCW piping systems are low. Therefore, more locations are selected in potential low/ stagnant flow locations (including adjacent weld HAZ) than at high operational stress locations.

A review of BECo Welding Specification M305 [2] indicates that none of the TBCCW piping welds have been PWHT. Therefore, none are eliminated from the sample population. The selection of points based on the criteria is biased to the portion of the system that is designated Pressure Boundary Only (PBO). That is, those parts of the TBCCW that are in the RBCCW pump compartments but not required for safety-related operation [1]. Large bore TBCCW system piping in these compartments designated as PBO, is stress analyzed [5] and detailed stress information is available for reference.

POINT SELECTION

The following locations have been selected for inclusion in the TBCCW IGSCC program. The selections were walked down for inspection accessibility to each of the locations. Notes are provided describing potential access problems. Some of the locations will require access using scaffolding or ladders. Five of the locations should be selected and inspected at each inspection interval. All locations should be placed in the program and inspected at a minimum of two inspection intervals over the program duration.

1. TBCCW Pumps (P-110 A & B) Suctions (6a), HX "A" loop discharge piping (16"-HE-30, El. 12'-4 1/2") to the TBCCW pump suction header, located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect elbow downstream of valve 30-HO-670 and run of piping to anchor H-30-1-20SR. Include adjacent elbow butt weld and the accessible piping in the heat affected zone formed by the anchor stanchion welds. Point selection criteria - stress.
2. TBCCW Pumps (P-110 A & B) Suctions (6a), makeup line from the condensate storage tank T-104 to TBCCW pump suction header (22"-HB-30, El. 12'-4 1/2"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect a 12" length of the horizontal piping (3"-HE-30, El. 17'-5 1/2") immediately upstream of the 90° elbow and vertical run to the branch connection at the suction header. Include piping in the heat affected zone formed by the elbow socket weld. Areas obstructed by the support brace or duct work need not be inspected. Point selection criteria - flow.

R. Pace

P:\RAY_PACE\ECCSLOOP\POINTS.DOC

**Selection of TBCCW
Piping Inspection Locations
For Detection of
Intergranular Stress Corrosion Cracking**

3. TBCCW Pumps (P-110 A & B) Suctions (6a), heater bypass piping (16"-HE-30, El. 12'-4 1/2") from HX "A" loop discharge piping, located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect the horizontal run of piping from the branch connection at the pump suction header (16"-HE-30, El. 12'-4 1/2") upstream to the first (90°) elbow. Include adjacent piping in the heat affected zone formed by the branch connection and elbow butt welds. Point selection criteria - flow.
4. TBCCW System (from 531 to HX-E-122 A & B Inlet) (6b), heater bypass piping (16"-HE-30, El. 4'-6") to HX inlet header (20"-HE-30, El. 12'-4 1/2"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect elbow between valves 30-HO-685 and TV-4161. Include elbow butt welds. Point selection criteria - flow.
5. TBCCW System (from 531 to HX-E-122 A & B Inlet) (6b), return piping (4"-HE-30, El. 13'-6 1/2") to HX inlet header (20"-HE-30, El. 12'-4 1/2"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect a 12" length of the horizontal piping run immediately upstream of the 45° elbow that branches into the TBCCW HX supply header. Include the adjacent elbow butt weld. It may be somewhat difficult to gain access to this area due to an overhead lighting fixture. Point selection criteria - stress.
6. TBCCW System P-110 A Discharge (6c), pump discharge piping (14"-HE-30, El. 8'-9"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect the elbow downstream of valve 30-HO-683. Include the elbow butt welds. Point selection criteria - flow.
7. TBCCW System P-110 B Discharge (6d), pump discharge piping (14"-HE-30, El. 8'-9"), located in the "B" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect the elbow downstream of valve 30-HO-682. Include the elbow butt welds. Point selection criteria - flow.
8. TBCCW Discharge to Air Condition System (6e), branch piping (4"-HE-30, El. 12'-6 1/2") from the pump discharge header (20"-HE-30, El. 12'-6 1/2"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect a 12" length of the horizontal piping and first 90° elbow upstream of the branch connection to the pump discharge header. Include the elbow butt welds. Point selection criteria - stress.
9. TBCCW Discharge to Air Condition System (6e), branch piping (4"-HE-30, El. 12'-6 1/2") from the pump discharge header (20"-HE-30, El. 12'-6 1/2"), located in the "A" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect a 12" length of 45° piping at the branch connection to the pump discharge header. This point will be extremely difficult to inspect due to congestion from surrounding piping and conduit. However, it is the system high stress location and an important data point. Include the adjacent elbow butt welds and piping in the heat affected zone formed by the branch connection welds. Point selection criteria - stress.
10. Chemical Addition Tank T-211 C Outlet Process line (6f), branch piping (1"-HE-30, El. 14'-1") from the TBCCW pump suction piping (16"-HE-30, El. 12'-4 1/2"), located in the "B" loop compartment of the Aux. Bay (Floor El. 3'-0"). Inspect the 5-D bend branch

1 7 3 3 2
0 0 0 4

R. Pace

**Selection of TBCCW
Piping Inspection Locations
For Detection of
Intergranular Stress Corrosion Cracking**

piping component downstream of valve 30-HO-872. It is not necessary to inspect the underside of the pipe in the area obstructed by the Unistrut support brace. Point selection criteria - flow.

11. Chemical Addition Tank T-211 C Inlet Process line (6g), branch piping (1"-HE-30, El. 15'-10") from the TBCCW pump discharge piping (20"-HE-30, El. 12'-6 1/2"), located in the Aux. Bay condensate transfer and plant heat pump compartment (Floor El. 3'-0"). Inspect the 12" length of horizontal piping, upstream from the branch connection to the pump discharge piping and valve 30-HO-686, immediately beyond the first 90° elbow. Include piping in the heat affected zone formed by the elbow socket weld. Point selection criteria - flow.

INSPECTION CRITERIA

A leak-before-break approach is advocated for this PBO system, based on a study performed using Code Case N-463-1 to determine critical flow sizes in CS piping. The results are provided below for the bounding pipe sizes of concern. From inspection of the table it is evident that a through-wall crack will be discovered long before it reaches critical flow size. In fact, based on the above discussion (see Assumptions) the cracks will arrest prior to reaching critical flow size. Therefore should a problem arise it would be discovered as minor water leakage during the current schedule of Aux. Bay operator tours. The drains in the Aux. Bay are equipped to handle leakage far in excess of that anticipated from a through wall IGSCC crack. The current levels of operator tours and training are sufficient. While this level of inspection is adequate it will be augmented by a visual inspection program, specific to the locations described above.

NPS (inches)	Critical Flaw Size (inches)	
	Circumferential	Axial
3	3	42
20	16	41

The purpose of the augmented VT-1 inspections is to identify any reportable indications that suggest the presence of IGSCC in the TBCCW carbon steel piping and associated welds to NESG, Mechanical/ Civil/ Structural. This piping shall be inspected using VT-1 visual examination methods, conforming to ASME XI, 1989 Edition, with crack-like indications causing rejection or further evaluation by a BECo Level III examiner. Any detectable crack or linear indications shall be reported by a Non-Conformance Report.

R. Pace

P:\RAY_PACE ECCSLOOPPOINTS.DOC

**Selection of TSCCN
Piping Inspection Locations
For Detection of
Intergranular Stress Corrosion Cracking**

REFERENCES

1. PNPS Q-List
2. PNPS Welding Requirements of Field Erected Piping, Specification M305.
3. PR 96.0396.02
4. P & ID M216
5. Piping Analysis Index, M581
6. PNPS Stress Isometric Numbers (See Attachment):
 - a) 6498-629
 - b) 6498-630
 - c) 6498-631-1
 - d) 6498-631-2
 - e) M1004 Sht. 5
 - f) M1004 Sht. 6
7. ASME Nuclear Code Case N-463-1

0
3
0
2


6/2/87

**Selection of TBCCW
Piping Inspection Locations
For Detection of
Intergranular Stress Corrosion Cracking**

- ATTACHMENT --
FNPS Stress Isometric Numbers:**
6498-629
6498-630
6498-631-1
6498-631-2
M1004 Sht. 5
M1004 Sht. 6

0
3
0
7

6



ALL dimensions in this drawing are based on the drawings of the equipment and shall be subject to change without notice. The drawings are for information only and shall not be used for construction purposes without the approval of the design engineer.


- REFERENCE:
1. IS BULLETIN 70-40 INSPECTION FOR STATION PROCEDURE UP TO 21 AND RESULTS EVALUATION AS INDICATED IN THE COMPUTER STATE REPORT A-478
 2. STRESS CALCULATION NO. 817 REV. 4

- NOTES:
1. DESIGN NO PROVIDES "AS-BUILT" DIMENSIONS IN AGREEMENT WITH STATION PROCEDURE UP TO 21
 2. THE DRAWING SUPPLEMENT DRAWING NO. 817 REV. 4

DATE	12/12/51
BY	(S) (S) (S) (S)
BECHTEL SAN FRANCISCO	
UNIT NO. 1 PUMP HOUSE NO. 10 WATER SYSTEM DIVISION	
TURBINE BLDG. COOLING WATER SYSTEM PUMPS PIDAS SECTION	
ISSUED	6498-629

RESTRAINT	SNUBBER	GUIDE SIGN	SPRING HANGER	ANCHOR	RIGID HANGER
-----------	---------	------------	---------------	--------	--------------

NO DIMENSIONS TO BE SHOWN UNLESS SPECIFICALLY NOTED OTHERWISE



It is the intent of this drawing to show the location of the main discharge pipe, the location of the main discharge pipe, and the location of the main discharge pipe. The drawing is intended to show the location of the main discharge pipe, the location of the main discharge pipe, and the location of the main discharge pipe.



- REFERENCE:
1. E. BULLER'S 1944 INSPECTION FOR STATION PROCEEDING TO 10-21 AND REVISIONS OBTAINING AS INDICATED IN THE COMPUTER STATUS REPORT, 1.1.1.1.
 2. STUCKE CALCULATION NO. 577 REV. 2

- NOTES:
1. DESIGNER TO PROVIDE "AS-BUILT" DRAWINGS IN ACCORDANCE WITH STATION PROCEEDING TO 10-21.
 2. THE DRAWING IS FOR INFORMATION ONLY. NO DIMS. SHALL BE USED.

DATE	10/15/50	BY	J. J. [unclear]
NO.	6498-63-1	REV.	00
BEUTEL SAN FRANCISCO			
UNIT NO. 1 PACIFIC COASTAL CO. STEAM ENGINE COMPANY			
TURBINE BUILDING COOLING WATER SYSTEM P-110A DISCHARGE			
SCALE	AS SHOWN	PROJECT NO.	6498-63-1

RESTRAINT	SPREADER	QUIDWAY	SPRING HANGER	ANCHOR	RIG HANGER
-----------	----------	---------	---------------	--------	------------

0000 20000



See page 10-11 of the final structural design report. The system, structure, and connections are designed in accordance with the design criteria of the design report. The design is based on the design criteria of the design report. The design is based on the design criteria of the design report.

- REFERENCE:
1. SEE SHEET 10-11 INJECTION FOR STATION ELEVATIONS UP TO 31 AND HEADLINE ELEVATIONS AS INDICATED IN THE COMPUTER DESIGN REPORT. **DATE: 1/27/70**
 2. STRESS CALCULATION NO. **321** REV. **2**

- NOTES:
1. REVIEWED BY PROJECT "DESIGN" ENGINEER IN ACCORDANCE WITH STATION PROCEDURE OF 10-1
 2. THE DRAWING APPROVED DRAWING NO. **321** REV. **2**

DATE	1/27/70
BY	[Signature]
BECHTEL SAN FRANCISCO	
UNIT NO. 1 PLANT DESIGN NO. 60 DESIGN DESIGN COMPANY	
TURBINE BLDG. COOLING WATER SYSTEM F-110B DISCHARGE	
NO.	6498-631-210

RESTRAINT	ENDS	GUIDE (WAY)	SPRING HANGER	ANCHOR	RIGID HANGER
-----------	------	-------------	---------------	--------	--------------

01



PR

Integrated Action Item Database Revision Form

PR00.0300.00

Edition: 0

CA

Date: 05/14/97

Responsible Manager: Garrett, G. #1

Status: OPEN

Group: CAS

Significance: 2

Department: OC

Strategy:

Priority: 9

Sub Department:

Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: 11	Due Date: 08/30/97
Assign Date: 05/14/97	Dead Date: 08/31/97
Start Date: 05/20/97	Completion Date: 11

Action

VISUAL INSPECTION PROGRAM DEVELOPED FOR SELECTED POINTS.

Closure Requirements

VISUAL INSPECTION PROGRAM IMPLEMENTED

Notes/Basis for Change(s)

ENTERED

Change(s) Approved By: Chad C. Hunter ^{5/21/97} Date: 5/19/97
Manager

Change(s) Accepted By: Joyce Date: 11 5/20/97
PR Coordinator

BASIS

THE EXAMINATION REQUIREMENTS WILL BE TRACKED BY THE MST TRACKING PROGRAM (ATTACHED FORM) WITH EXAMINATION PERFORMED TO EXISTING PROCEDURES. THE INSPECTIONS WILL BE IMPLEMENTED WITH AN M ? AS WITH ALL OTHER I.S.I EXAMINATIONS. CC Node # 5001262

REPORT DATE: 08:58:15 19 MAY 1997
SSEL CODE: 8006800

0 8 9 /
MASTER SURVEILLANCE TRACKING PROGRAM
SEMI-ANNUAL REPORT/CHANGE FORM

7 3 3 2
EVALUATION OF TBCW
SPECIFICATION FOR PIPING DESIGN/CONSTRUCTION
MULTIPLIERS, THESE COMMON QUALITY
SPEC-497 RLS 50.80

NEW

1 Title:
2 Procedure Number:
4 Node Number:
Rep Task Number:

5001262
8006800

6 Task Type: Regulatory Requirement INTERNAL COMMITMENT

7 Frequency: 46 1/NO
8 Schedule Basis: 1
9 Lead Division: 18 QUALITY CONTROL
10 Owner: 18 QUALITY CONTROL

11 Notes/Work Instructions: PERFORM UT INSPECTION OF TUBES SELECTION OF THE DESIGN A UT EVALUATION OF 5 OR 11 COMPONENTS
NO PROCEEDING FROM A UT - ALL SHOULD BE DONE FROM RFO. 11 COMPONENTS ARE IN PROGRAM AND
EVERY KEYFLEXOR CHANGE ALL MUST BE INSPECTED TWICE IN SRFO'S

12 Current Node:
13 Max Tasks to Generate: 1
14 Unit Node: COLD STARTDOWN
15 Systems:

17 Commitment/Requirement: ~~FORM 8-70-147, INC URBAN LETTER OF 02/02/80~~ PROBLEM REPORT 96.0 39606
~~RESPONSE 09-107~~

18 Notices: A; P; F
19 Equipment Tested: PIPING

21 Preceding Tests: IDENTIFY INSPECTION LOCATIONS

22 Concurrent Tests:
23 Preceding Tests: NEW
Schedule Info
Done On: 03/15/95; 05/12/95
Due On: RFO-12(S); RFO-11(S); RFO-10(S)
Dead On: RFO-12(E); RFO-11(E); RFO-10(E)
28 IST Status: NO

29 1ST Test Results: N/A
30 1ST Test Results: N/A
31 Alert Components: N/A

32 Triggers:
33 Triggered By:
34 Comments: NO_OUTAGE_1; NO_OUTAGE_2; NO_OUTAGE_3; SWR

Submitter: Chad Gump 51810
Div. Rep Task Coord.: Alenka 51817
*Source Nbr.: R. Johnston 51817
*System Engr.:
Plant Rep Task Coord.: 51897

FOR IMPACT Y/N N

*required for non-conservative commitment/requirement changes
Note: A Technical Basis is required for changes to the MSTP Database.

1 TITAN
25 To 3 1982

ORIGINAL

EXHIBIT 1
Sheet 1 of 2

Problem Report 96-0396

PROBLEM REPORT

PROBLEM REPORT

Problem Reported By: DAVID FOUNTAIN Group/Dept: CHEMISTRY Date: 9-23-96 Ext: 2511

Problem Date: 9-23-96 Time: 1200

1. Describe the Problem and how found: High nitrate levels exist in the TBCCW system. Chemistry trending of the TBCCW system indicated decreasing nitrite levels and increasing conductivity. Special testing for nitrates was performed and indicated 945 PPM. By comparison R/B RBCCW have 39 PPM. High nitrate concentrations have been associated with stress corrosion cracking of carbon steel piping.

2. Identify the System, Component, or Part involved (if known):

	Name	Number	Location
a. System/Loop	<u>TBCCW</u>	_____	_____
b. Component	_____	_____	_____
c. Part	_____	_____	_____

3. Describe the System Component or Part Function(s) (if known)

Name	Description
_____	_____
_____	_____

4. What was the Probable Cause of the Problem? corrosion inhibitor sodium nitrite being converted to nitrate by excess oxygen or bacteria

5. Was a Work Request Tag placed on the Identified Component? Yes No WRT# _____

6. Radiological Problems? Yes No

NOTE
If the problem meets the criteria on the back of this page, hand carry this form to the NWE immediately.

(Front of Form)

Problem Report 96-0394

ORIGINAL PROBLEM REPORT

RType GT.07



1. N/A Findings:
 - Comparable internal problems or recurring deficiencies
 - Comparable external (OER and NPROS) problems
 - Duplicate problem (exact)
 - Adverse trend (preliminary)

2. N/A Significance:
 - Level I Notification
 - Level II Yes No
 - Level III Date: _____
 - Level IV Criterion (If yes, complete Exhibit 11)

3. N/A Recommendation:
 - Accept
 - Reject
 - Incorporate into PR AI # _____

4. N/A Disposition:
 - Critique
 - RCA
 - Evaluation *Probable Cause @ Effects on material (Carbon steel)*
 - Corrective Action
 - Close
 - 10CFR21 Applicability Review

5. N/A
 - a. Hardware Nonconforming Condition: Yes No Additional Actions: Yes No
 If Yes: Rework Use-As-Is AIP: _____
 Scrap or Return Repair
 - b. Hardware Degraded Condition: Yes No Additional Actions: Yes No
 AIP: _____
 - c. System, Structure, Component Is Operable: Yes No
 If Yes, Basis: _____

6. N/A Distribution:
 - Yes No Nuclear Network submission Yes No Copy to Regulatory Affairs Dept

7. Submitted: *A. Shattell* Date: 9/12/96
 Screening Coordinator

8. N/A Other PAC Reviews
 - Yes No After all evaluations
 - Yes No After all corrective actions
 - Yes No Other: _____

9. Approved: *[Signature]* Date: 24 Sep 96
 PAC Chairman

0892
17932

ALERT

THE IADB ITEM DETAILED HERE HAS NOT BEEN COMPLETED AND HAS PASSED ITS DUE DATE OR WILL PASS ITS DUE DATE IF IT FALLS ON A HOLIDAY OR WEEKEND.

ENTERED

IADB ID: PR96.0398.02

TITLE: HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN

Document Type:

Document No.:

Action Type:

EVALUATION

STATUS:

OPEN

SIGNIFICANCE:

2

PRIORITY:

A1

Rec'd DATE:

11

Start Date:

10/01/96

DUE DATE:

~~11/01/96~~ 10/15/96

DEAD DATE:

~~10/01/96~~ 1/15/97

RESPONSIBLE MANAGER:

PAGE R

DEPARTMENT:

NESG

DIVISION:

CIV MECH

Strategy:

QUERY: UPPER(SRC_CODE) = 'PR'

Start Date: 10/31/96

End Date: 11/04/96

Awaiting Altran analysis inputs. Change due/dead date as indicated.
Thomas White
11/29/96

Tom
Can we move this 2 month out?

Thanks
[Signature]

A. Shatas 12/2/96

0000 22211

PR

Integrated Action Item Database Revision Form

PR96.0396.01
EVALUATION

Estimate: 0

Date: 11/28/96

Responsible Manager: FOUNTAIN, D.

Status: OPEN

Division: NUC SVCS

Significance: 2

Department: CHEMISTRY

Priority: A0

Sub Division:

Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: 11	Due Date: 11/01/96	3/15/97
Assign Date: 09/24/96	Dead Date: 12/01/96	4/15/97
Start Date: 10/01/96	Completion Date: 11	


Action

CONDUCT AN EVALUATION TO DETERMINE THE CAUSE OF THE HIGH NITRATE LEVELS IN THE TBCCW SYSTEM. DETERMINE CORRECTIVE ACTIONS AND ACTIONS TO PRECLUDE RECURRENCE.

Closure Requirements

COMPLETE EVALUATION PER NCR2A1, SECTION 6.4

Notes/Basis for Change(s)



Change(s) Approved By: [Signature]

Manager

Date: 11/29/96

Change(s) Accepted By: [Signature]

PR Coordinator

Date: 11/21/96

More time needed for evaluation, in house testing is inclusive and efforts are being made to have samples analyzed by vendor laboratory

PR

Integrated Action Item Database Revision Form

PR98.0398.01

Extension: 2

EVALUATION

Date: 06/24/97

Responsible Manager: LOOMIS, L

Status: OPEN

Group: NUC SVCS

Significance: 2

Department: CHEMISTRY

Strategy:

Priority: A0

Sub Department:

Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: //

Due Date: 08/15/97

8/1/97

Assign Date: 09/24/96

Dead Date: 08/30/97

8/24/97

Start Date: 10/01/96

Completion Date: //

Action

CONDUCT AN EVALUATION TO DETERMINE THE CAUSE OF THE HIGH NITRATE LEVELS IN THE TBCCW SYSTEM. DETERMINE CORRECTIVE ACTIONS AND ACTIONS TO PRECLUDE RECURRENCE.

Closure Requirements

COMPLETE EVALUATION PER NUP92A1, SECTION 6.4

Notes/Basis for Change(s)

DATE EXTENSION REVIEW (11/29/96, FOUNTAIN, D) MORE TIME NEEDED FOR EVALUATION. IN HOUSE TESTING IS INCLUSIVE AND EFFORTS ARE BEING MADE TO HAVE SAMPLES BY VENDOR LABORATORY

4/18/97, C. GODDARD; EXTEND DUE TO MANPOWER RESTRAINTS

extended due to manpower restraints

Change(s) Approved By:

L. Fountain
L. Fountain
Manager

Date:

11/6-24-97

Change(s) Accepted By:

A. Phatar
A. Phatar
PR Coordinator

Date:

11/6/26/97

RECEIVED

PR

Integrated Action Item Database Revision Form

PR98.0396.03

Estimate: 0

CA

Date: 02/06/97

Responsible Manager: [Redacted]

Status: OPEN

Division: NUC SVCS

Significance: N.

Department: CHEMISTRY

Priority: 9

Sub Division:

Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: 11	Due Date: 04/01/97 9/1/97
Assign Date: 02/06/97	Dead Date: 06/06/97 9/30/97
Start Date: 02/06/97	Completion Date: 11

Action

CHEMISTRY TO SAMPLE AND ANALYZE THE RBCCW AND TBCCW, INCLUDING THE MAKE-UP WATER SOURCE, FOR THE PRESENCE OF NITROBACTER BACTERIA.

Closure Requirements

IF NITROBACTER BACTERIA ARE FOUND A BIOCIDES SHOULD BE INTRODUCED AS A PART OF A CHEMICAL TREATMENT PROGRAM TO ELIMINATE THE BACTERIA AND REDUCE THE NITRATE CONCENTRATION. PROVIDE MEMO DOCUMENTING DETAILS OF TASK COMPLETION.

Notes/Basis for Change(s)

Change(s) Approved By: David W. Foudair Date: 11.5.28.97
 Manager

Change(s) Accepted By: Joweth Date: 11.6.12.97
 PR Coordinator

Adjusted due and dead dates due to restraints in procedural revisions to allow samples to be sent off site for vendor analysis.

ENTERED

PR

Integrated Action Item Database Revision Form

PR# 0396.03

Revision: 2

CA

Date: 01/07/1998

Responsible Manager: FOUNTAIN, D.

Status: OPEN

Group: NUC SVCS

Significance: N.

Department: CHEMSTY

Strategy:

Priority: 90

Sub Department:

Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: //

Due Date: 12/01/97 3/1/98

Assign Date: 02/06/1997

Dead Date: 12/31/97 4/1/98

Start Date: 02/06/1997

Completion Date: //

Action

CHEMISTRY TO SAMPLE AND ANALYZE THE RBCCW AND TBCCW, INCLUDING THE MAKE-UP WATER SOURCE, FOR THE PRESENCE OF NITROBACTER BACTERIA.

Closure Requirements

IF NITROBACTER BACTERIA ARE FOUND A BIOCIDES SHOULD BE INTRODUCED AS A PART OF A CHEMICAL TREATMENT PROGRAM TO ELIMINATE THE BACTERIA AND REDUCE THE NITRATE CONCENTRATION. PROVIDE MEMO DOCUMENTING DETAILS OF TASK COMPLETION.

Notes/Basis for Change(s)

5/28/97 FOUNTAIN, D: EXTEND DUE AND DEAD DATES DUE TO RESTRAINTS IN PROCEDURAL REVISIONS TO ALLOW SAMPLES TO BE SENT OFF SITE FOR VENDOR ANALYSIS.

7/14/97 FOUNTAIN, D: MORE TIME NEEDED TO COMPLETE REVISED ACTION PLAN (SEE RESPONSE TO PR# 0396.01)

1) CHEMISTRY WILL DEVELOP A P.O. FOR VENDOR LAB ASSISTANCE THAT WILL ANALYZE FOR THE PRESENCE OF BACTERIA KNOWN TO CAUSE THE PROBLEM SEEN IN TBCCW 9/16/97

2) CHEMISTRY WILL SAMPLE FOR BACTERIA IN TBCCW AND SEND TO VENDOR FOR ANALYSIS 10/15/97

3) CHEMISTRY WILL FURTHER EVALUATE THE CAUSE TO TBCCW HIGH NITRATES AFTER RESULTS OF LAB ANALYSIS ARE RECEIVED 12/1/97

1/7/98 FOUNTAIN, D: PLEASE EXTEND DUE AND DEAD DATES. ADDITIONAL TIME IS NEEDED BECAUSE SAMPLING MUST COINCIDE WITH MAINTENANCE OF SLIPSTREAM FILTER. MAINTENANCE IS SCHEDULED FOR MARCH 98. IN HOUSE TESTING HAS SHOWN NO INDICATION OF BACTERIA.

EXTENDING THIS ACTION ITEM

1) WILL NOT IMPACT NUCLEAR, INDUSTRIAL OR RADIOLOGICAL SAFETY

2) WILL NOT ADVERSELY AFFECT QUALITY

Change(s) Approved By: [Signature]

Manager

Date: 11/18/98

Change(s) Accepted By: [Signature]

PR Coordinator

Date: 11/13/98

PR

Integrated Action Item Database Revision Form

PR# 0396.02

Revision: 0

EVALUATION

Date: 09/24/96

Free, R.

Responsible Manager: *BURNS, T. #4*

Status: OPEN

Division: NESG

Significance: 2

Department: PEQE

Priority: A

Sub Division:

Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: //	Due Date: 11/01/96
Assign Date: 09/24/96	Dead Date: 12/01/96
Start Date: 10/01/96	Completion Date: //

Action

DETERMINE THE EFFECTS OF THE ELEVATED NITRATE LEVELS ON THE CARBON STEEL PIPING OF THE TBCCW SYSTEM.

Closure Requirements

MEMO DETAILING THE RESULTS THE EVALUATION AND THE REQUIRED CORRECTIVE ACTIONS. CONCURRENCE MUST BE OBTAINED FROM ACTION ITEM OWNERS

NOTE: CHEMISTRY HAS ALSO BEEN ASSIGNED AN ACTION TO DETERMINE THE CAUSE OF THE EXCESS NITRATE AND SHOULD BE ABLE TO PROVIDE ADDITIONAL INFORMATION TO ASSIST IN YOUR EVALUATION

Notes/Basis for Change(s)

See below

Change(s) Approved By *[Signature]* Date: *10/26/96*
 Manager

Change(s) Accepted By PR Coordinator Date: //

Please review this PR to Mechanical - Civil/Structural department with Tom White so that we will support as an initial basis, if management decides that Tom White will own matters.

PR

PR96.0396.03

Revision: 1

Date: 07/14/97

CA

Responsible Manager: FOUNTAIN, D. PLG52

Status: OPEN

Group: NUC SVCS

Significance: N.

Department: CHEMISTRY

Strategy:

Priority: Y3

Sub Department:

Doc Type/Number:

Title

HIGH NITRATE LEVELS EXIST IN THE TBCCW SYSTEM. HIGH NITRATE CONCENTRATIONS HAVE BEEN ASSOCIATED WITH STRESS CORROSION CRACKING OF CARBON STEEL PIPING.

Rec'd Date: 11	Due Date: -00/04/97 12/1/97
Assign Date: 02/08/97	Dead Date: 02/30/97 12/31/97
Start Date: 02/08/97	Completion Date: 11

Action

CHEMISTRY TO SAMPLE AND ANALYZE THE RBCCW AND TBCCW, INCLUDING THE MAKE-UP WATER SOURCE, FOR THE PRESENCE OF NITROBACTER BACTERIA.

Closure Requirements

IF NITROBACTER BACTERIA ARE FOUND A BIOCIDES SHOULD BE INTRODUCED AS A PART OF A CHEMICAL TREATMENT PROGRAM TO ELIMINATE THE BACTERIA AND REDUCE THE NITRATE CONCENTRATION. PROVIDE MEMO DOCUMENTING DETAILS OF TASK COMPLETION.

Notes/Basis for Change(s)

[5/28/97, FOUNTAIN, D.] EXTEND DUE AND DEAD DATES DUE TO RESTRAINTS IN PROCEDURAL REVISIONS TO ALLOW SAMPLES TO BE SENT OFFSITE FOR VENDOR ANALYSIS.

MORE TIME NEEDED TO COMPLETE

REVISED ACTION PLAN: (SEE RESPONSE TO PR 960396.01.)

Change(s) Approved By: [Signature] Date: 11/7/14/97

Change(s) Accepted By: [Signature] Date: 11/7/15/97

ENTERED

- 1) CHEMISTRY WILL DEVELOP A P.O. FOR VENDOR LAB ASSISTANCE THAT WILL ANALYZE FOR THE PRESENCE OF BACTERIA KNOWN TO CAUSE THE PROBLEM SEEN IN TBCCW. 9/15/97
- 2) CHEMISTRY WILL SAMPLE FOR BACTERIA IN TBCCW AND SEND TO VENDOR FOR ANALYSIS 10/15/97
- 3) CHEMISTRY WILL FURTHER EVALUATE THE CAUSE OF TBCCW HIGH NITRATES AFTER RESULTS OF LAB ANALYSIS ARE RECEIVED. 12/1/97