

Exelon Generation  
Zion Station  
101 Shiloh Boulevard  
Zion, IL 60099-2797  
Tel 847-746-2084

www.exeloncorp.com

March 15, 2007  
CZE-07-002

10 CFR 50.73  
10 CFR 20.2201

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

Zion Nuclear Power Station, Units 1 and 2  
Facility Operating License Nos. DPR-39 and DPR-48  
NRC Docket Nos. 50-295 and 50-304

Subject: Submittal of Licensee Event Report Number 2007-001-00 – Units 1 and 2, “Inadequate Special Nuclear Material (SNM) Record Keeping Practices for Exempt Quantities”

The enclosed Licensee Event Report (LER) is being submitted in accordance with 10 CFR 50.73, “License event report system,” and 10 CFR 20.2201, “Reports of theft or loss of licensed material,” paragraph (b), “Written reports.” 10 CFR 20.2201 requires a written report be submitted within 30 days following the telephone notification in accordance with 10 CFR 20.2201 paragraph (a) after the occurrence of any lost, stolen, or missing licensed material in a quantity greater than 10 times the quantity specified in Appendix C to Part 20.

There are no regulatory commitments contained in the attached report. Should you have any questions concerning this submittal, please contact Mr. James Ashley, Licensing Engineer, at (847) 379-2978.

Respectfully,



Ron Schuster  
Decommissioning Plant Manager  
Zion Nuclear Power Station

Enclosure: LER Number 2007-001-00

cc: Regional Administrator- NRC Region III  
Office of Nuclear Facility Safety-IEEMA Division of Nuclear Safety

IE22

bcc: Vice President – Licensing and Regulatory Affairs  
Director – Licensing and Regulatory Affairs  
Licensing Engineer – Zion Nuclear Power Station  
Zion Nuclear Licensing Administrator  
Manager, Licensing – Braidwood, Byron and LaSalle County Stations  
Exelon Document Control Desk Licensing  
Commitment Tracking Coordinator – Cantera  
Zion Station Master File

# LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

<b>1. FACILITY NAME</b> Zion Station, Unit 1	<b>2. DOCKET NUMBER</b> 05000295	<b>3. PAGE</b> 1 of 4
---	-------------------------------------	--------------------------

**4. TITLE**  
Inadequate Special Nuclear Material (SNM) Record Keeping Practices for Exempt Quantities

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
02	28	2007	2007	- 001 -	00	03	15	2007	Zion Station, Unit 2	05000304
									N/A	N/A

<b>9. OPERATING MODE</b> Permanently Defueled	<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§:</b> (Check all that apply)									
<b>10. POWER LEVEL</b>  N/A	<input checked="" type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)						
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)						
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)						
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)						
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)						
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)						
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER							
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A							

**12. LICENSEE CONTACT FOR THIS LER**

<b>NAME</b> James Ashley, Licensing Engineer	<b>TELEPHONE NUMBER (include Area Code)</b> (847) 379-2978
---	---

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

<b>14. SUPPLEMENTAL REPORT EXPECTED</b> <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	<b>15. EXPECTED SUBMISSION DATE</b>	MONTH	DAY	YEAR

**ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)**

In the process of reviewing Special Nuclear Material (SNM) records, it was identified that all disposition records for reactor incore detectors could not be found. The reactor incore detectors contain very small quantities of U-235 and were used to monitor reactor power during plant operation. The unaccounted for material was classified as missing on February 28, 2007 due to lack of records documenting the current location of forty-three detectors that were received onsite between 1972 and 1987. Based on interviews with former Zion Nuclear Material Custodians and other relevant personnel, it is believed that these detectors were shipped as radioactive waste to the Barnwell Low-Level Radioactive Waste Disposal Facility located in South Carolina. Additionally, select historical records indicate that it was common practice for Zion Station to dispose of detectors as radioactive waste. A search of storage locations at Zion was performed, but the detectors were not located. There is no evidence of theft or diversion of these detectors.



**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Zion, Unit 1	05000295	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 4
		2007	- 001	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

**C. Cause of Event**

This event resulted from inadequate accounting practices related to exempt quantities of SNM. The inadequate accounting practices occurred from 1972 through 1988. This event is attributed to lack of attention to detail regarding Federal Regulations and lack of procedural guidance for SNM control.

**D. Safety Consequences:**

The detectors contained an extremely small amount of SNM and pose no significant safety concern. Depending on design, each incore detector contained between approximately 0.0004 grams and 0.0027 grams of Uranium 235, resulting in an aggregate quantity of approximately 0.102 grams of Uranium 235. It is believed that the detectors were disposed of as radioactive waste at the Barnwell Low-Level Radioactive Waste Disposal Facility and therefore, no inadvertent radiation exposures are believed to have occurred as a result of this situation.

**E. Corrective Actions:**

A review of historical documentation was completed, including site and corporate regulatory correspondence, SNM records, and Barnwell Low-Level Radioactive Waste Disposal Facility records. A search of storage locations was also completed.

Former NMCs were interviewed regarding record keeping and disposal practices, which identified that it was a common practice to dispose of detectors as radioactive waste via shipment to the Barnwell Low-Level Radioactive Waste Disposal Facility.

All other SNM material was accounted for. In addition, a review of current Exelon proceduralized requirements for exempt quantity SNM controls has concluded that existing requirements are adequate to prevent recurrence of this event.

**F. Previous Occurrences:**

There have been no previous similar events at Zion Station.

**G. Component Failure Data:**

<u>Manufacturer</u>	<u>Nomenclature</u>	<u>Model</u>	<u>Mfg. Part Number</u>
N/A	N/A	N/A	N/A

The following information is required by 10 CFR 20.2201(b):

**DESCRIPTION OF LICENSED MATERIAL INVOLVED, INCLUDING KIND, QUANTITY, AND CHEMICAL AND PHYSICAL FORM**

Forty-three incore detectors manufactured by Reuter-Stokes with a stainless steel outer shell. Detector dimensions are approximately 2.2 inches long and 0.2 inches in diameter. The aggregate quantity of Uranium 235 contained in the detectors is approximately 0.102 grams.

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Zion, Unit 1	05000295	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 4
		2007	- 001	- 00	

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

**DESCRIPTION OF CIRCUMSTANCES UNDER WHICH THE LOSS OR THEFT OCCURRED**

The detectors are believed to have been disposed of as radioactive waste. Detailed disposal records for the detectors have not been found. They are classified as missing due to the lack of disposal documentation.

**A STATEMENT OF DISPOSITION, OR PROBABLE DISPOSITION, OF THE LICENSED MATERIAL INVOLVED**

The detectors were probably disposed of as radioactive waste at the Barnwell Low-Level Radioactive Waste Disposal Facility located in South Carolina.

**EXPOSURES OF INDIVIDUALS TO RADIATION, CIRCUMSTANCES UNDER WHICH THE EXPOSURES OCCURRED, AND THE POSSIBLE TOTAL EFFECTIVE DOSE EQUIVALENT TO PERSONS IN UNRESTRICTED AREAS**

There is no known exposure to individuals. It is believed that the detectors were disposed of as radioactive waste and therefore, no inadvertent radiation exposures are believed to have occurred as a result of this situation.

**ACTIONS THAT HAVE BEEN TAKEN, OR WILL BE TAKEN, TO RECOVER THE MATERIAL**

All actions related to this event are complete.

**PROCEDURES OR MEASURES THAT HAVE BEEN, OR WILL BE, ADOPTED TO ENSURE AGAINST A RECURRENCE OF THE LOSS OR THEFT OF LICENSED MATERIAL**

A review of current Exelon proceduralized requirements for exempt quantity SNM controls has concluded that existing requirements are adequate to prevent recurrence of this event.