

(10-2003)
10 CFR 2.201

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Ridgewater College
Willmar and Hutchinson Technical College
2 Century Ave.
Hutchinson, MN 55350

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road, Suite No. 210
Lisle, IL 60532-4351

REPORT

2005/00/

3. DOCKET NUMBER(S)

030-09331

4. LICENSEE NUMBER(S)

22-15554-01

5. DATE(S) OF INSPECTION

07/2/2005

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



1. Based on the inspection findings, no violations were identified.



2. Previous violation(s) closed.



3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):




4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Tony S. Go		07/2/05

Issue Date: 11/25/03

E8-1

2800, Enclosure 8

Docket File Information
**SAFETY INSPECTION REPORT
 AND COMPLIANCE INSPECTION**

1. LICENSEE Ridgewater College REPORT NUMBER(S) 2005/001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III	
3. DOCKET NUMBER(S) 030-09331	4. LICENSE NUMBER(S) 22-15554-01	5. DATE(S) OF INSPECTION 07/ 20 /05	
6. INSPECTION PROCEDURES 87121	7. INSPECTION FOCUS AREAS 03.01 - 03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM 3320	2. PRIORITY 1	3. LICENSEE CONTACT Dennis Berndt	4. TELEPHONE NUMBER 320-234-0201
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: 07/06	
<input type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			
PROGRAM SCOPE			

NRC FORM 591M PART 3 (10-2003)

Program Scope

The licensee is a Technical College that offers non destructive testing courses that also included the use of radiographic cameras. Currently, the licensee possesses various radiographic cameras containing Ir-192 and Co-60 sealed sources, only three of these cameras were use for teaching purposes at the college, and stored in locked boxes at the licensee's two permanent radiographic cells. In addition, the licensee also possessed instrument calibration source containing one Cs-137 sealed source. The Cs-137 source was used routinely to calibrate the licensee's radiation survey meters used at the college. The licensee also maintained two permanent cells for "mockup" temporary job sites in leu of going to temporary job sites outside the facility; however, on occasion the licensee conducted a temporary job site activities with the licensee's simulated radiography truck within the licensee' property away from the main campus buildings. In addition, one of the permanent cell is located in separate building away from the main campus buildings. According to the RSO, this outside building will be decommissioned in the near future, and all activities will be done at only one permanent cell. The RSO is the principal user in class 2005. During the inspection, the RSO, an ASNT-CERTIFIED radiographer was the only qualified radiographer at this time, he trained his students as his assistant radiographers during "mockup" shots. The utilization records indicated that all licensed activities were conducted inside the cells at this time. During the inspection, the inspector toured the two storage areas, and the storage areas were found to be secured and locked, only the certified radiographer/ RSO had keys to these storage areas.

Performance Observations

During the inspection, there were no activities at the site. However, the inspector was able to interview a radiographer/RSO. The records indicated that during "mockup" training inside the two cells, the radiographer possessed all necessary safety equipments, such as radiation survey meters such as Model NDS 2000, dosimeters and SRD pocket dosimeters, and alarming dosimeters. Since the licensee did not transport the licensed devices, the licensee is not required to possess shipping papers or followed DOT requirements. The inspector did not observed health and safety concerns associated with the inspection.