

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

FEB 28 1979

09 MAR 5 9:00

REGION II
GEORGIA

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - NRC-OIE REGION II LETTER RII:EHC
50-390/79-02, 50-391/79-02 - INSPECTION REPORT - RESPONSE TO INFRACTION
50-390/79-02-01

The subject letter dated February 7, 1979, cited TVA with one infraction.
Enclosed is our response to that infraction.

If you have any questions concerning this matter, please get in touch
with M. R. Wisenburg at FTS 854-2581.

Very truly yours,



J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

OFFICIAL COPY

79031600/6

79006

ENCLOSURE

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2
RESPONSE TO DEFICIENCY 50-390/79-02-01

Deficiency

As required by Criterion V of Appendix B to 10 CFR 50 and implemented by WBNP FSAR paragraph 17.1A.5, "Activities affecting quality shall be prescribed by documented instructions, procedures or drawings. . .and shall be accomplished in accordance with these instructions, procedures or drawings."

Contrary to the above, on December 1, 1978, an installed piping subassembly had different subassembly and manufacturer's serial numbers than specified by the applicable drawing. Subassembly 62-CVCS-46, sketch 2876-278, Serial No. 6509 was located where the drawing E2879-1C-22R1 indicated subassembly 62A-CVCS-40, sketch 2879-273, Serial No. 6503 should be. As the incorrectly installed subassembly was of the same material and configuration as the subassembly specified by drawing, the safety significance of this non-compliance is considered minimal.

Corrective Action Taken and Results Achieved

The incorrectly located subassembly was replaced returning the system to drawing configuration. (E2879-1C-22R1)

Corrective Action to be Taken to Avoid Further Noncompliance

All mechanical engineering personnel have been cautioned to ensure the installed piping configuration duplicates the documentation requirements.

Date When Full Compliance will be Achieved

We are now in compliance.