



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
230 PEACHTREE STREET, N.W. SUITE 1217
ATLANTA, GEORGIA 30303

NOV 4 1977

Central file

*50-390
391*

In Reply Refer To:

RII:JPO

50-438, 50-439

50-259, 50-260

50-296, 50-518

50-519, 50-520

50-521, 50-553

50-554, 50-327

50-328, 50-390

50-391, 50-566

50-567

Tennessee Valley Authority
Attn: Mr. Godwin Williams, Jr.
Manager of Power
830 Power Building
Chattanooga, Tennessee 37401

Gentlemen:

Enclosed is IE Bulletin No. 77-04 which requires action by you with regard to your power reactor facility(ies) with an operating license or a construction permit.

Should you have questions regarding this Bulletin or the actions required of you, please contact this office.

Sincerely,

For James P. O'Reilly
Director

Enclosures:

1. IE Bulletin No. 77-04
2. List of IE Bulletins
Issued in 1977

cc: J. E. Gilleland
Assistant Manager of Power
830 Power Building
Chattanooga, Tennessee 37401

*A0 2
GD*

cc: W. W. Aydelott, Project Manager
Bellefonte Nuclear Plant
P. O. Box 2000
Hollywood, Alabama 35752

Stan Duhan
400 Commerce Street
E4D112
Knoxville, Tennessee 37902

J. G. Dewease, Plant Superintendent
Box 2000
Decatur, Alabama 35602

R. T. Hathcote, Project Manager
Hartsville Nuclear Plant
P. O. Box 2000
Hartsville, Tennessee 37074

G. G. Stack, Project Manager
Sequoyah Nuclear Plant
P. O. Box 2000
Daisy, Tennessee 37319

J. M. Ballentine
Plant Superintendent
Sequoyah Nuclear Plant
P. O. Box 2000
Daisy, Tennessee 37319

T. B. Northern, Jr.
Project Manager
Watts Bar Nuclear Plant
P. O. Box 2000
Spring City, Tennessee 37381

NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D. C. 20555

November 4, 1977

IE Bulletin 77-04

CALCULATIONAL ERROR AFFECTING THE DESIGN PERFORMANCE OF A SYSTEM FOR
CONTROLLING pH OF CONTAINMENT SUMP WATER FOLLOWING A LOCA

Description of Circumstances:

On September 29, 1977, the Baltimore Gas and Electric Company reported that for Calvert Cliffs Unit 1 and Unit 2, the amount of trisodium phosphate dodecahydrate (TSP) specified in the technical specifications may not be sufficient under all operating conditions to perform its intended design function.

The TSP is used to control the pH of the containment sump water following a LOCA in order to reduce the probability of chloride stress corrosion cracking leading to equipment failure or loss of containment integrity and to ensure low volatility of dissolved radioiodines. At Calvert Cliffs, the TSP is stored in three dissolving baskets located on the lowest level of the containment. Original design specifications (FSAR) required a sufficient quantity of TSP to raise the pH of the sump water to approximately 7.0. The more recent guidance provided by the Standard Review Plan (SRP) states that, for Post Accident Chemistry, the optimum pH control consists of stabilizing pH between 7 and 8 within four hours.

For the Calvert Cliffs facilities, the quantity of TSP required to meet the FSAR design specifications was initially calculated to be 75 cubic feet. However, these calculations were not based on maximum boron concentrations and water volumes permitted by the technical specifications for the containment sump water sources, e.g., Refueling Water Tank (RWT), Safety Injection Tanks (SIT), Boric Acid Tanks (BAT) and the Reactor Coolant System (RCS). Revised calculations indicated that the quantity of TSP required to meet design specifications under worst case conditions was approximately 82 cubic feet.

As a result, administrative controls have been implemented at the Calvert Cliffs facilities to limit the maximum boron concentration in the RWT and SITs to 2200 ppm. The minimum boron concentration specified in the technical specifications will still apply. Although the problem described above occurred at a facility utilizing TSP for pH control of containment sump water, this problem may be applicable to facilities utilizing different methods of pH control of containment sump water e.g., sodium hydroxide (NaOH). This would be the case if chemical requirements for pH control were based on values less than the maximum values for boron concentrations and water volume permitted by the technical specifications for the containment sump water sources.

Action to be Taken by Licensees and Permit Holders:

For all PWR Power Reactor Facilities with an operating license or a construction permit:

1. If your facility utilizes or plans to utilize a system for pH control of containment sump post LOCA solution, describe what action you have taken or plan to take to assure that the system design specifications will be met for all operating conditions permitted by the technical specifications, as applicable to the containment sump water sources.
2. Report in writing within 45 days for facilities with an operating license and within 60 days for facilities with a construction permit, your plan of action and schedule with regard to Item 1. Reports should be submitted to the Director of the appropriate NRC Regional Office and a copy should be forwarded to the NRC Office of Inspection and Enforcement, Division of Reactor Operations Inspection, Washington, D.C. 20555.

Approved by GAO, B-180225 (R0072); clearance expires 7-31-80. Approval was given under a blanket clearance specifically for identified generic problems.

LISTING OF IE BULLETINS
ISSUED IN 1977

Bulletin No.	Subject	Date Issued	Issued To
77-03	On-Linda Testing of the W Solid State Protection System	9/12/77	All W Power Reactor Facilities with an Operating License or Construction Permit
77-02	Potential Failure Mechanism in Certain W AR Relays with Relays with Latch Attachments	9/12/77	All Holders of Operating Licenses (OL) or Construction Permits (CP)
77-01	Pneumatic Time Delay Set Point Drift	4/29/77	All Holders of Operating Licenses (OL) or Construction Permits (CP)