



830 Power Building

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

*Reactor Facilities
Branch*

SEP 9 1976

Mr. Norman C. Moseley, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 818
230 Peachtree Street, NW.
Atlanta, Georgia 30303

Dear Mr. Moseley:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - REPORTABLE DEFICIENCY -
GENERAL ELECTRIC 6900-VOLT AUXILIARY POWER SWITCHBOARDS -
BLACK LEXAN COIL SPOOLS

The subject deficiency was initially reported to NRC-OIE Region II Inspector V. L. Brownlee, on June 11, 1976, in accordance with 10 CFR 50.55(e). Our first interim report was transmitted to you on July 9, 1976. The following is our second interim report:

TVA will reinspect all class IE General Electric HFA type relays and plans to replace those relays containing defective coil spools. This inspection and replacement program will be completed before preoperational testing. TVA is working with the manufacturer in resolving this problem.

Our next report will be transmitted by November 1, 1976.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

CC: Dr. Ernst Volgenau, Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

6 4998