An exam analysis was conducted on the NRC written exam that was given on June 8, 2007. Angie Orgeron, HLO Lead Instructor, and Joey Clark, Assistant Operations Manager, Training, reviewed all questions that were missed by at least 50% of the students. In addition, all questions that were missed by the student who failed the exam were reviewed. With the exception of one question, all questions that were reviewed were determined to be valid and accurate questions. One question was submitted to the NRC for consideration in changing the answer to two possible choices.

Mike Wagner Supervisor, Operations Training River Bend Nuclear Station



June 15, 2007

Mr. Anthony T. Gody U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011-8064

Subject: River Bend Station - Unit 1 Docket No. 50-458 License No. NPF-47 Operator License Examination

Dear Mr. Gody,

In accordance with the guidance provided in NUREG-1021, "Operator Licensing Examination Standards for Power Reactors," Entergy hereby submits for your consideration a change to the initial written examination conducted at River Bend Station on June 8, 2007.

Specifically, it is recommended that the answer key for question no. 25 on the reactor operator and senior reactor operator examinations be changed to accept both answers C'' and D'' as correct.

Attached are the subject question, the justification for the requested change, and pertinent reference material that supports the change.

If you have any questions regarding this matter please contact me at 225-378-3500.

Sincerely t Chur

Marvin L. Chase Manager, Training & Development

Attachment 1: Question No. 25 and Justification Attachment 2: References

cc: Mr. Michael E. Murphy U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011-8064

## Attachment 1

- Question No. 25
- Justification for Change

## **River Bend Station Initial Licensed Operator Exam June 2007**

## **QUESTION NO. 25**

Which of the following would require entering a Technical Specification Limiting Condition of Operation (LCO)?

A. 100 psig in the Primary Airlock Seal Air Flask

B. 2 gallons per minute unidentified leakage

C. 130°F in the RHR Equipment Area

D. 10 psig RCIC turbine exhaust diaphragm pressure

Answer: A. > 90 psig	С				
B. Less than or equal to 2 gpm $D_{c} \leq 20$ min					
D. < 20 psig K/A Statement:	Ability to determine and/or interpret equipment operability as it relates to High Secondary Containment Area Temperature.				
<u>K/A</u>	RO	<u>SRO</u>	<u>10 CFR 55</u>	TECHNICAL REF	<b>OBJECTIVE REF</b>
295032 EA2.02	3.3	3.5	41.10 43.5	TS 3.3.6.1 TS 3.1.3 TS 3.4.5 TS 3.6.1.2	None
Tier/Group Origin:	1/2 NRC	LOK:	Н	LOD:	2
History:	New NRC			BANK QID:	N/A

## Justification:

The 10 psig RCIC turbine exhaust diaphragm high pressure is a RCIC system isolation signal. Abnormal Operating Procedure (AOP)-0003 "Automatic Isolations" (attached) Page 11 of 20, Signal "S", indicates that this signal isolates Group 2 valves. The Group 2 valves, as listed on Page 15 of 20, are: E51-F064, E51-F031, E51-F063, & E51-F076. When RCIC turbine exhaust diaphragm pressure reaches 10 psig, the listed RCIC valves will isolate, causing the system to become inoperable. This condition requires entry into Technical Specification LCO 3.5.3. Condition A.

In addition to the correct answer, the answer key contains information regarding the reason for the distracters. For "D" it states "<20 psig". This corresponds to the allowable value provided in TS 3.3.6.1 "Primary Containment and Drywell Isolation Instrumentation" (page 3.3-55, attached). The key does not consider, however, the nominal setpoint of 10 psig provided in TR 3.3.6.1 (page TR 3.3-34, attached). This 10 psig setpoint is in agreement with the AOP-0003 information referenced above.

In conclusion, the receipt of a 10 psig signal at the RCIC turbine exhaust diaphragm results in the isolation of the RCIC steam supply rendering RCIC unable to perform its function, requiring entry into TS LCO 3.5.3 Condition A.