## TVA FAX COVER

Send To:		
Name:	DUTY OFFICEL	
Address:	IRC OPERATIONS CENTER.	, B91430A, HO.
		Number of Pages: 1+COVE
Verification N	umber: (301) 951-0550	
Message:		
-		
		· · · · · · · · · · · · · · · · · · ·
From:	Watts Bar Nuclear Pla	ant - TVA
Name:	P.L. PACE, COMPLIANCE	LICEISILIS HALVASSE
Organization:	WBN Site Licensi	ing
Address:	FSB 2K-WBN	
Fax Number: _	(615) 365-8000	
Telephone Nui	mber: <u>(6/87365-188</u>	14

IMPORTANTI IF YOU DO NOT RECEIVE ALL PAGES, PLEASE CALL US BACK IMMEDIATELY.

7312020321 731117 PDR ADDCK 05000370 S PDR

I É27

OTHER 10 CFR 50.55(E)(3)

Office Medical

Offsite Notification

Attachment 1 IN 89-89 December 26, 1989 Page 1 of 2

U.S. NUCLEAR REGULATORY COMMISSION **OPERATIONS CENTER EVENT NOTIFICATION WORKSHEET** FACILITY OR ORGANIZATION CALL BACK : ENS NOTIFICATION TIME P.L. PACE C15) 365-1884 WATTS BAL LUCUSAL PLANT Los Offsite Commi EVENT DATE EVENT TIME & ZONE Mr Non-Emergency 10 CFR 50.72(b)(1) (14) 09 14 193 Toxic Ges ILKKOWLI TE Conincia SID (vi) Red Release TS Deviltion POWER/MODE AFTER (1)(B) (vi) OWER/MODE BEFORE Degraded Consider Oth Membering Sale Co (11) ДД Unemyzed Condition (ii)(A) 4-Hr Non-Emergency 10 CFR 50,72(b)(2) Outside Design Basis **EVENT CLASSIFICATIONS** Decrade White S/D (41)(C) Not Covered by OPI/EPI RPS Actuation (scram) (66) Earthouse GENERAL EMERGENCY ESF Amunion 40) SITE AREA EMERGENCY. Flood Safe S/D Capability Hunter (iiii) ALERT (iii)(B) RAN Combiny UNUSUAL EVENT Ice/Hail (iii)(C) Comrol of Ged Release Lightning BO.72 NON-EMERGENCY parting mediaca (0](III) PHYSICAL SECURITY (73.71) an (iv)(A) Air Release > 2X ADD B TRANSPORTATION (66) ECCO Discharge to RCS (iv)(B) Lig Release > 2X App 8 fivi 20,403 MATERIAL/EXPOSURE

DESCRIPTION

Lon Emers, Assessment

TOR ENS

While performing verification for Quality Maintenance Data Sheets on September 14, 1993, day shift craft personnel discovered that the night shift craft personnel had incorrectly wired the magnetic starter that operates the DC ventilating fan for the Turbine Driven Auxiliary Feedwater Pump (TDAFWP) room. This condition was identified after Quality Control inspectors had signed off on the work performed and would not have been discovered through the normal closure process for the specific workplan or associated design change notice package.

The magnetic starter breaker is normally used for three phase power cables and uses all three conductors of a cable. The cable being terminated was for a DC circuit and only uses two conductors of the cable for power feed. The third conductor of the cable was being used as part of the control circuit for the fan. This third conductor was incorrectly terminated at point L3 instead of point Z.

There is a design basis event (small break Loss of Coolant Accident concurrent with Loss of Offsite Power and failure of a diesel generator) which requires that one motor driven auxiliary feedwater and the TDAFWP be available to provide the required flow. For this event, the DC ventilating fan is the only means available to maintain the TDAFWP room temperature below maximum allowed. Incorrect wiring of the DC fan starter would prevent the fan from operating when the TDAFWP is running. The TDAFWP room temperature will increase to the point where room temperature switches would sense a TDAFWP steam line break and close the Train A and B steam supply isolation valves to the TDAFWP. Insufficient feedwater flow would be available to mitigate the postulated design basis event.

If left uncorrected, the above condition could have created a substantial safety hazard and is reportable under 10 CFR 50.55(e)(3).

NOTIFICATIONS NRC RESIDENT	YES	NO	WILL BE	ANYTHING UNUSUAL OR NOT U	IDERSTOOD?	YES (Explain above)	<b>V</b>	NO
STATE(I)		₹/		DID ALL SYSTEMS FUNCTION AS REQUIRED?		YES		NO (Explain above)
LOCAL		<b>V</b>			LIA			
OTHER GOV AGENCIES		V	•	MODE OF OPERATION	RESTART DATE	1111		ON BACK LO- LA
MEDIA PRESS RELEASE		V		UNTIL CORRECTED: AUT		E: /4//		ON BACK 755