

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

*Radiology Associates, P.C.
Elmhurst, IL 60120
Bingham Farms & Flint, MI clinics
REPORT 2007-001*

2. NRC REGIONAL OFFICE

**U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road
Suite 210
Lisle, Illinois 60532-4351**

3. DOCKET NUMBER(S)

030-11590

4. LICENSEE NUMBER(S)

21-16754-01

5. DATE(S) OF INSPECTION

Nov 29, 2007

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title

Printed Name

Signature

Date

**LICENSEE'S
REPRESENTATIVE**

NRC INSPECTOR

Deborah A. Piskura

Deborah A. Piskura

11/29/07

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Radiology Associates, P.C. REPORT 2007-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-11590	4. LICENSE NUMBER(S) 21-16754-01	5. DATE(S) OF INSPECTION Nov. 26, 27, and 29, 2007	
6. INSPECTION PROCEDURES USED 87130 & 87131	7. INSPECTION FOCUS AREAS 03.01, 03.02, 03.03, 03.04, 03.05, 03.06, 03.07, and 03.08		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02120	2. PRIORITY G 3	3. LICENSEE CONTACT John David Mellen, M.D., RSO	4. TELEPHONE NUMBER 248.646.9806
-----------------------------	--------------------	---	-------------------------------------

☐ Main Office Inspection Next Inspection Date: Nov. 2010

☒ Field 30400 Telegraph Rd, Bingham Farms, MI & 2284 Ballenger Hwy, Flint, MI

☐ Temporary Job Site _____

PROGRAM SCOPE

This licensee was a physicians group office with four locations of use in the Detroit area and authorized to use licensed material permitted by Sections 35.100, 35.200, and 35.300 (limited to I-131 for treatment of hyperthyroidism). The nuclear medicine activities were performed by three full-time technologists who performed approximately 3-12 diagnostic procedures daily at each site. The licensee received unit doses from a licensed radiopharmacy. Currently, the licensee's use of radioiodine was limited to thyroid uptake studies in quantities not requiring a written directive. Radioiodine was obtained from the pharmacy in capsule form (3-4 cases per year).

This inspection consisted of interviews with licensee personnel, demonstrations of survey techniques, a review of select records, tour of the nuclear medicine department, and independent measurements. At the time of this inspection the licensee's camera was non-functional and diagnostic studies could not be observed.