

**From:** Bo Pham  
**To:** <dtynes@entergy.com>,"MICHAEL D STROUD" <MSTROUD@entergy.com>  
**Date:** 10/10/2007 8:22:36 AM  
**Subject:** Fwd: AMR Questions  
**cc:** "Kimberly Green" <KJG1@nrc.gov>,<IPNonPublicHearingFile@nrc.gov>

Mike & Donna,

Please disregard this version sent last night. I will resend an updated version of the AMR questions this morning.  
Thanks.

Bo Pham  
Project Manager  
Division of License Renewal  
U.S. Nuclear Regulatory Commission  
301-415-8450  
O-7B1  
[bmp@nrc.gov](mailto:bmp@nrc.gov)

>>> Bo Pham 10/9/07 7:54 PM >>>

Mike & Donna,

Attached are AMR questions to be discussed during the 10/22 AMR Audit week.

Bo Pham  
Project Manager  
Division of License Renewal  
U.S. Nuclear Regulatory Commission  
301-415-8450  
O-7B1  
[bmp@nrc.gov](mailto:bmp@nrc.gov)

>>> James Davis 10/7/07 11:40 AM >>>

Attached are the AMR questions

**Hearing Identifier:** IndianPointUnits2and3NonPublic  
**Email Number:** 184

**Mail Envelope Properties** (47669802.HQGWDO01.OWGWPO04.200.2000006.1.1528DA.1)

**Subject:** Fwd: AMR Questions  
**Creation Date:** 10/10/2007 8:22:36 AM  
**From:** Bo Pham

**Created By:** BMP@nrc.gov

**Recipients**

"Kimberly Green" <KJG1@nrc.gov>  
<IPNonPublicHearingFile@nrc.gov>  
<dtynere@entergy.com>  
"MICHAEL D STROUD" <MSTROUD@entergy.com>

**Post Office**  
OWGWPO04.HQGWDO01

**Route**  
nrc.gov

| <b>Files</b>                        | <b>Size</b> | <b>Date &amp; Time</b> |
|-------------------------------------|-------------|------------------------|
| MESSAGE                             | 612         | 10/10/2007 8:22:36 AM  |
| TEXT.htm                            | 1166        | 12/17/2007 3:38:42 PM  |
| AMR questions for indian pointi.doc |             | 80384                  |
| 3:38:42 PM                          |             | 12/17/2007             |

**Options**

**Priority:** Standard  
**Reply Requested:** No  
**Return Notification:** None  
None

**Concealed Subject:** No  
**Security:** Standard

Mike & Donna,

Please disregard this version sent last night. I will resend an updated version of the AMR questions this morning. Thanks.

Bo Pham  
Project Manager  
Division of License Renewal  
U.S. Nuclear Regulatory Commission  
301-415-8450  
O-7B1  
[bmp@nrc.gov](mailto:bmp@nrc.gov)

>>> Bo Pham 10/9/07 7:54 PM >>>  
Mike & Donna,

Attached are AMR questions to be discussed during the 10/22 AMR Audit week.

Bo Pham  
Project Manager  
Division of License Renewal  
U.S. Nuclear Regulatory Commission  
301-415-8450  
O-7B1  
[bmp@nrc.gov](mailto:bmp@nrc.gov)

>>> James Davis 10/7/07 11:40 AM >>>  
Attached are the AMR questions

## AMR questions from Mano Subudhi

1. In LRA Tables 3.1.2-3 and 3.1.2-4, Entergy credits water chemistry control – primary and secondary AMP to manage fouling in SG and HX tubes in three line items for each IP unit. The LRA marks generic note H for these line items for tubes exposed to treated or treated borated water, indicating that there is no NUREG-1801 (or GALL) line item for the component, material and environment combination. Describe how the water chemistry control – primary and secondary AMP will prevent fouling in SG and HX tubes in the RCS and what method(s) would evaluate that this aging effect is not occurring in these components and thus, the effectiveness of the water chemistry control – primary and secondary AMP.
2.
  - a) In LRA Section 3.1.2.2.1 and the discussion in LRA Table 3.1.1, item number 3.1.1-1, Entergy indicates that the reactor vessels at IP2/3 are not supported by support skirts and therefore, cumulative fatigue damage (as a TLAA) for support skirts is not applicable to IP2/3 reactor vessels. However, the corresponding Table 2 line item indicates that the reactor vessels are supported on support pads, which are usually welded to the underside of the coolant nozzles and rests on steel base plates atop a support structure attached to the concrete foundation. Discuss how the fatigue cracking of support pad attachment welds are managed for IP2/3 reactor vessels.
  - b) In LRA Section 3.1.2.2.1, Entergy states that no fatigue analysis was required for the pressurizer support skirts since the inservice inspection program will manage the cracking due to fatigue. In accordance with 10CFR54.21(c)(iii), demonstrate that the IP2/3 ISI program adequately manages the cracking due to fatigue for the period of extended operation. Specifically, include in the discussion the inspection methods, frequency, acceptance criteria, and past operating experience on the pressurizer support skirts at IP2/3.
  - c) LRA Table 3.1.1, item 3.1.1-7 addresses cracking due to fatigue (as a TLAA) for support skirts, attachment welds, and pressurizer relief tank (PRT) components (in addition to RCPB closure bolting and studs, SG components, piping external surfaces and bolting) in the RCS, made out of carbon or stainless steel. In LRA Table 3.1.2-3, Entergy indicates a TLAA line item referring to Table 3.1.1-7 for the RCS components. The corresponding GALL Table 2-item IV.C2-10 (R-18) referencing RCS components for this TLAA, includes piping and pipe components external surfaces and bolting.  
  
LRA Table 2 line items associated with this TLAA do not include the support skirts and/or attachment welds for RCS components (e.g., RCP, SG, PRT) other than the pressurizer and PRT components. Clarify if these components (except RV attachment weld and pressurizer support skirts) are within the scope of LR for IP2/3. If such components are within the scope of the license renewal, then provide technical justification why these components are not subject to cracking due to fatigue for IP2/3 and included in the Table 2 items of the RCS.
3. In LRA Table 3.1.2-4 there are several line items referencing Table 1 item 3.1.1-12 and Table 2 line item IV.D2-8 (R-224) for secondary side once-through steam generator components and crediting water chemistry control – primary and secondary to manage loss of material. Only one line item referring to carbon steel SG tubesheet with Ni-alloy clad on the primary side is subject to one-time inspection (in accordance with plant-

specific note 104) for detecting and evaluating the effectiveness of managing the aging effect by the water chemistry control program. It is noted that Table 2 line items (IV.D1.9 and IV.D1.12) for recirculating SG components require SG integrity AMP to evaluate the effectiveness of the water chemistry control – primary and secondary for loss of material. Similarly, GALL Table 2 line item IV.D2-8 (R-224) for once-through SG requires a plant-defined method to evaluate the effectiveness of the water chemistry program to manage loss of material. Discuss what aging management activity will evaluate the effectiveness of the water chemistry control – primary and secondary for managing loss of material in these SG components (other than the tubesheet) exposed to treated water in the secondary side.

4. In LRA Table 3.1.2-4, IP2/3 ISI program and water chemistry control – primary and secondary AMPs manage loss of material in carbon steel SG shell components consistent with GALL Table 1 item 3.1.1-16 and Table 2 item IV.D1-12 (R-34). Explain why this line item in the LRA is marked with “Note E” indicating that the credited AMPs are not consistent with GALL recommendations. Note that similar Note E in Table 2 line items exist throughout the AMR Section 3.1 Tables whenever the IP2/3 ISI AMP (a plant-specific program) is credited for managing aging effects.
5. In LRA Table 1 item 3.1.1-17, Entergy states in its discussion, “The nozzles are not controlling for the TLAA evaluations.” This Table 1 item refers to a TLAA for the loss of fracture toughness due to neutron irradiation embrittlement in the vessel beltline region. Demonstrate why the materials of the nozzles are not controlling for the TLAA evaluations.
6. In LRA Table 1 item 3.1.1-21 and LRA Section 3.1.2.2.5, Entergy states, “SA508-CI 2 forgings clad with stainless steel using a high-heat input welding process were not used in the IP2 or IP3 vessels.” This line item is identified as not applicable to IP2/3. Describe the quantitative criteria that define “high-heat input welding process” and compare it to the welding parameters used for deposition of the SS cladding in the IP2 and IP3 vessels.
7. In LRA Section 3.1.2.2.7, item 2 Entergy states that the water chemistry control – primary and secondary and thermal aging embrittlement of CASS AMPs manage cracking due to SCC in CASS RCS piping components. Entergy also states that the ISI program for some components supplements these AMPs. In LRA Table 3.1.2-3, only the CASS pipe fittings credit the ISI program in addition to water chemistry control – primary and secondary and thermal aging embrittlement of CASS AMPs. Discuss the criteria that require the IP2/3 ISI program for certain RCS components to be added as supplement to water chemistry control – primary and secondary and thermal aging embrittlement of CASS AMPs.
8. In LRA Section 3.1.2.2.9, Entergy states that stress relaxation in stainless steel and nickel alloy reactor vessel internals screws, bolts, tie rods, and hold-down springs are not applicable since these components operate at a temperature  $\leq 700^{\circ}\text{F}$  in accordance with ASME Code, Section II, Part D, Table 4. Provide specific details of the materials of these IP2/3 RVI components and their operating temperature conditions in comparison to the Code threshold temperatures.
9. In LRA Table 3.1.2-1, Entergy credits water chemistry control – primary and secondary and nickel alloy inspection AMPs to manage cracking in nickel alloy vessel internal

attachment core support lugs (pads). This line item also references Table 1 item 3.1.1-31 and Table 2 item IV.A2-12 (R-88), which require the ISI program in addition to water chemistry control – primary and secondary and nickel alloy inspection AMPs. Clarify this discrepancy.

10. In LRA Section 3.1.2.2.14, Entergy credits visual inspections under SG integrity AMP to manage wall thinning due to FAC that could occur in carbon steel FW rings and supports, as noted in NRC IN 91-19 at San Onofre 2/3. Although the description of the SG integrity AMP includes other mechanically induced phenomena, such as denting, wear, impingement damage, and fatigue, no details are found in the LRA about how the inspection methods and their evaluation are performed with regard to loss of material in carbon steel FW inlet ring and supports in the IP2/3 SGs. Discuss the type of visual inspections that could detect the wall thinning of these SG components, the acceptance criteria and operating experience associated with these activities at IP2/3.
11. In LRA Section 3.1.2.2.16, Entergy credits water chemistry control – primary and secondary and steam generator integrity program for managing cracking in carbon steel with Ni-alloy clad in steam generator tubesheet primary side. The Table 2 line item in LRA Table 3.1.2-4 references Table 1 item 3.1.1-35 and GALL item IV.D2-4 (R-35); these both specify the implementation of applicable plant commitments to (1) NRC Orders, Bulletins and Generic Letters associated with nickel alloys and (2) staff-accepted industry guidelines. LRA Section A.2.1.34, which documents the UFSAR updates for the SG Integrity AMP, does not contain this commitment. Explain why this is not specifically documented in LRA Section A.2.1.34 as a LR commitment.
12. In LRA Table 1 item 3.1.1-52, Entergy provides an explanation why cracking due to SCC, loss of material due to wear, loss of preload due to thermal effects, gasket creep, and self-loosening are not applicable to IP2/3 CS and SS RCPB pump valve closure bolting, and those in high pressure and high temperature environment. In fact, there were no Table 2 line items addressing these aging effects in both LRA Tables 3.1.2-3 and -4. GALL Table 2 items IV.C2-7, and IV.D1-1 and -2 for cracking, and items IV.C2-8 and IV.D1-10 for loss of preload due to thermal effects, gasket creep, and self-loosening credits the bolting integrity AMP for managing these aging effects. Moreover, loss of material due to corrosion in bolts exposed to indoor air environment is managed by the bolting integrity AMP [LRA Table 1 item 3.1.2-23, and LRA Table 2 item V.E-4 (EP-25)]. Note that IP2/3 bolting integrity AMP is consistent with GALL AMP XI.M18, bolting integrity program and based on the LRA, the IP2/3 bolting integrity AMP manages all the above-mentioned aging effects. Provide technical justification for the following:
  - a) Applied stress for SS closure bolting applications at IP2/3 is much less than 100ksi. What is the basis for a threshold of 100ksi in the bolting materials at IP2/3 when cracking of bolting due to SCC is not an aging effect requiring aging management?
  - b) Loss of material due to wear is not a significant aging effect for the bolting based on industry experience. Event driven conditions such as galling are not aging-related degradation.
  - c) Loss of preload due to stress relaxation is not an applicable aging effect. Note that temperature condition is one of many factors (e.g., vibration, thermal cycles) that may cause loosening of bolts even in a benign thermal environment.
13. In LRA Table 3.1.1 item 3.1.1-59, Entergy states, “The steam outlet nozzle contains a nickel alloy flow restrictor and the feedwater nozzle contains a nickel alloy thermal

sleeve that isolate the carbon steel nozzles from high fluid velocities; therefore these components are not susceptible to FAC.” Based on this argument, Entergy includes no Table 2 item for this aging effect. GALL Table 1 item 3.1.1-59 recommends flow-accelerated corrosion AMP to manage wall thinning in carbon steel SG nozzles and safe ends for the main steam, feedwater and AFW exposed to secondary water. Explain how the Ni-alloy flow restrictor isolates the steam nozzle and safe end; Ni-alloy thermal sleeves isolate the FW and AFW nozzles and safe ends, from exposure to high velocity treated water flow into or out of the SG, thus, requiring no aging management of wall thinning in the subject SG components.

14. In LRA Table 3.1.1, item 3.1.1-62, Entergy states that cracking due to cyclic loading is addressed as cracking due to fatigue (presumably, as a TLAA). Entergy also states that the ISI program manages the cracking of SS piping >4” NPS. However, no Table 2 line item addresses cracking due to cyclic loading for SS and CS with SS clad piping in the RCS (i.e., hot leg, cold leg, surge line, and spray line) exposed to reactor coolant as required by 10CFR54.21(a). The GALL item 3.1.1-62 addresses cracking due to cyclic loading and recommends ISI program to monitor the cracking in the piping and pipe fittings. This is required in addition to the establishment of the cumulative usage factors due to fatigue (or cyclic) loadings in accordance with 10CFR54.21(c). Provide technical justification for not including these Table 2 line items in the LRA Table 3.1.2-3 for RCS components.
15. In LRA Table 3.1.1, item 3.1.1-64, Entergy states, “The Inservice Inspection and Water Chemistry Control – Primary and Secondary Programs manage cracking in steel with stainless steel or nickel alloy clad components. Cracking of stainless steel components is addressed in other lines.” Identify which other lines address cracking of stainless steel components in the pressurizer exposed to treated borated water.
16. In LRA Table 3.1.1, item 3.1.1-65, Entergy addresses cracking due to PWSCC in Ni-alloy RV upper head penetration nozzles, instrument tubes, and head vent pipe, and welds exposed to treated borated water. GALL recommends ISI, water chemistry control and Ni-alloy penetration nozzles (XI.M11A) AMPs, while Entergy credits water chemistry control and Ni-alloy inspection program.

The IP2/3 AMP B.1.31 corresponds to the GALL AMP XI.M11A and manages PWSCC of Ni-based penetrations exposed to treated borated water. The Ni-Alloy inspection program (LRA B.1.21) manages Ni-alloy components that are not covered by the RVH penetration inspection (B.1.31) and SG integrity (B.1.35) AMPs.

- a) Provide technical justification for not crediting the GALL-recommended ISI, water chemistry control and Ni-alloy penetration nozzles (XI.M11A) AMPs to manage cracking due to PWSCC in Ni-alloy RV upper head penetration nozzles, instrument tubes, and head vent pipe, and welds exposed to treated borated water.
- b) Discuss how the water chemistry control – primary and secondary and the Ni-alloy inspection AMPs would manage cracking in Ni-alloy nozzle safe end and welds (inlet/outlet safe ends and closure head vent), as indicated in LRA Table 2 items referencing Table 1 item 3.1.1-65. Note that the Table 2 item IV.A2-18 (R-90) referenced for these line items in LRA Table 3.1.2-1 also recommends ISI, water chemistry control, and Ni-alloy penetration nozzles (XI.M11A) AMPs, consistent with GALL Table 1 item 3.1.1-65.

17. In LRA Table 3.1.1, item 3.1.1-66, Entergy states, "This line was not used. Erosion at manways and handholes is the result of damage from leaking joints that have not been corrected. At IPEC leaks are fixed as soon as practical. If damage due to erosion has occurred, it would also be repaired." Based on this, Entergy has not included this line item in the LRA Table 3.1.2-4. GALL recommends ISI program (Class 2: which requires visual inspections during pressure testing) to manage loss of material due to erosion in carbon steel steam generator secondary manways and handholes (cover only) exposed to air with leaking secondary-side water and/or steam. Provide technical justification how Entergy ensures the preventive (that detect the damage due to erosion) and corrective measures (that repair the leakage) for leaking joints and thus, would manage loss of material due to erosion in these SG components.
18. In LRA Table 3.1.1, item 3.1.1-68, Entergy states, "The Water Chemistry Control – Primary and Secondary and Inservice Inspection Programs manage cracking in most stainless steel and steel with stainless steel clad Class 1 components. For some components not subject to the Inservice Inspection Program, the Water Chemistry Control – Primary and Secondary Program manages cracking. The pressurizer spray head coupling and locking bar supports flow distribution within the pressurizer and are not part of the pressure boundary. The One-Time Inspection Program will be used to verify the effectiveness of the water chemistry program." LRA Table 3.1.2-3 line item referring to these components and the Table 1 item 3.1.1-68 [Table 2 item IV.C2-20 (R-217)] indicates that the water chemistry control AMP would manage the cracking. This is inconsistent with GALL recommendations as well as Entergy's statement in the Table 1 item 3.1.1-68. Clarify this discrepancy.
19. In LRA Table 3.1.1, item 3.1.1-69, Entergy states, "The Water Chemistry Control – Primary and Secondary and Inservice Inspection Programs manage cracking in stainless steel nozzles and penetrations. Nickel alloy used for such applications is compared to other lines." Identify which other lines applicable to Ni-alloy components exposed to reactor coolant and manage cracking due to SCC and PWSCC.
20. In LRA Table 3.1.1, item 3.1.1-74, Entergy states, "Consistent with NUREG-1801 for some components. The Water Chemistry Control – Primary and Secondary and Steam Generator Integrity Programs manage cracking and loss of material of stainless steel and nickel alloy steam generator components exposed to secondary feedwater and steam. For some components, loss of material is managed by the Water Chemistry Control – Primary and Secondary Program. The One-Time Inspection Program will be used to verify the effectiveness of the water chemistry program." LRA Table 3.1.2-4 line item referring to secondary handhole cover RTD well as well as boss for IP3 and the Table 1 item 3.1.1-70 [Table 2 items IV.D1-14 (RP-14) and IV.D1-15 (RP-15)] indicates that the water chemistry control AMP would manage the cracking. This is inconsistent with GALL recommendations as well as Entergy's statement in the Table 1 item 3.1.1-74.
  - a) GALL Table 2 items IV.D1-14 (RP-14) and IV.D1-15 (RP-15) recommend SG integrity and water chemistry control AMPs. Justify why for some components the one-time inspection AMP is credited instead of GALL-recommended SG integrity AMP in LRA Table 1 item 3.1.1-74, specifically to manage cracking in the secondary handhole cover RTD well for IP3.

- b) Clarify why the plant-specific note 104 is not indicated for secondary handhole cover RTD well and boss for IP3 to manage cracking of secondary handhole cover RTD well and loss of material in secondary handhole cover RTD boss. The note would ensure that one-time inspection AMP is applicable to these two Table 2 line items.
  - c) Since both IP2 and IP3 steam generators are Westinghouse Model 44F, explain why LRA Table 3.1.2-4-IP2 does not include line items for secondary handhole cover RTD well and boss, similar to LRA Table 3.1.2-4-IP3.
21. In LRA Table 3.1.1, item 3.1.1-84, Entergy states, "The Water Chemistry Control – Primary and Secondary Program manages cracking in one nickel alloy steam generator component exposed to secondary feedwater or steam. The One-Time Inspection Program will be used to verify the effectiveness of the water chemistry program." LRA Table 3.1.2-4 line item referring to secondary handhole cover RTD boss cracking for IP3 and the Table 1 item 3.1.1-84 [Table 2 item IV.D2-9 (R-36)] indicates that the water chemistry control and one-time inspection AMPs would manage the cracking. Since both IP2 and IP3 steam generators are Westinghouse Model 44F, explain why LRA Table 3.1.2-4-IP2 does not include the line item for secondary handhole cover RTD boss, similar to LRA Table 3.1.2-4-IP3.
22. In LRA Table 3.3.1, item 3.3.1-8, Entergy states, "Stainless steel components of some heat exchangers to which this NUREG-1801 line item applies, including the regenerative heat exchanger, are in the reactor coolant systems in series 3.1.2-x tables. The Water Chemistry Control – Primary and Secondary and Inservice Inspection Programs manage cracking of stainless steel heat exchanger bonnets and shells exposed to treated borated water. The Water Chemistry Control – Primary and Secondary Program manages cracking of stainless steel heat exchanger tubes. The program is augmented by the One-Time Inspection Program which will verify the absence of cracking in similar material environment combinations since the regenerative heat exchanger cannot be inspected internally." In LRA Table 3.1.2-3, Entergy credits water chemistry control – primary and secondary AMP to manage cracking in stainless steel HX tubes exposed to treated borated water and references Table 1 item 3.3.1-8. Clarify why the plant-specific note 314 that verifies effectiveness of the Water Chemistry Control – Primary and Secondary Program, is not indicated for HX tubes to manage cracking.
23. In LRA Table 3.4.1, line items 3.4.1-14 (for cracking) and 3.4.1-16 (for loss of material), Entergy states that consistent with NUREG-1801, Water Chemistry Control – Primary and Secondary Program manages cracking and loss of material in stainless steel components exposed to treated water. The One-Time Inspection Program is used to verify the effectiveness of the water chemistry program. In LRA Table 3.1.2-4, Entergy credits water chemistry control – primary and secondary AMP to manage cracking and loss of material in stainless steel piping, tubes and valves exposed to treated water and references Table 1 items 3.4.1-14 and 3.4.1-16. Plant-specific notes for the steam and power conversion system do not include one that verifies the effectiveness of the Water Chemistry Control – Primary and Secondary Program for managing cracking and loss of material. Discuss how Entergy intends to verify the effectiveness of the Water Chemistry Control – Primary and Secondary Program for managing cracking and loss of material in SS components exposed to treated water.

Q1 - LRA Table 1 item 3.3.1-1: How is SRP 4.7 generic guidance implemented to address cumulative fatigue damage of "steel cranes-structural girders?"

Q2 - LRA Table 1 item 3.3.1-5 states that the only stainless steel heat exchanger components exposed to treated water in the auxiliary systems are in the steam generator secondary side sample coolers, which are addressed in other lines. Where and how is this addressed?

Q3 - LRA Table 1 item 3.3.1-6: Does the diesel exhaust piping have an intended function for LR? Define. Is it subject to aging management under any credited AMP?

Q4 - LRA Table 1 item 3.3.1-8: Confirm that the Inservice Inspection Program mentioned in the first paragraph is credited for managing cracking due to SCC for the regenerative heat exchanger components, consistent with the reactor coolant systems in series 3.1.2-x tables. Correct the second paragraph to be consistent with this.

Q5 - LRA Table 1 items 3.3.1-10, -41: Compare the bolting used in IP 2/3 auxiliary systems to the high-strength bolting addressed by this GALL Table 1 line item. Are the IP 2/3 bolts replaced during maintenance?

Q6 - LRA Table 1 item 3.3.1-15,-16: LRA Section 3.3.2.2.7 item 1 states "Steel piping components and tanks of the reactor coolant pump oil collection system are not continuously exposed to a lubricating oil environment that is maintained by the Oil Analysis Program. Therefore this program is not credited for managing loss of material on these components. Instead these components are managed by the One-Time Inspection Program. This program will use visual or volumetric NDE techniques to inspect a representative sample of the internal surfaces to assure there is no significant corrosion." The OTI program is NOT a program that manages aging. It confirms the absence of degradation. If degradation is found, then an aging management program needs to be developed. Revise the LRA accordingly and identify what actions will be taken if degradation is discovered by the OTI.

Q7 - LRA Table 1 item 3.3.1-42: Does IP 2/3 have bolting exposed to air with steam or water leakage in Auxiliary Systems? If yes, why is this line item not used?

Q8 - LRA Table 1 item 3.3.1-45: How is loss of preload currently managed at IP 2/3, if not by the existing Bolting Integrity Program? Describe the IP 2/3 operating experience with loss of bolt pre-load. How is the absence of loss of bolt pre-load confirmed?

Q9 - LRA Table 1 items 3.3.1-46, 47, 50, 51 and 52 state that the One-Time Inspection Program for Water Chemistry will use visual inspections or non-destructive examinations of representative samples to verify that the Water Chemistry Control – Auxiliary Systems and Water Chemistry Control – Closed Cooling Water Programs have been effective at managing aging effects. Explain why Table 2 line items that reference Table 1 items 3.3.1-46, 47, 50, 51 and 52 do not refer to OTI.

Q10 - LRA Table 1 item 3.3.1-53: Compare the Periodic Surveillance and Preventive Maintenance Program, which is credited to manage loss of material for carbon steel station air system components exposed internally to condensation, to the GALL- recommended Compressed Air Monitoring Program.

Q11 - LRA Table 1 item 3.3.1-54: GALL recommends a periodic monitoring program (Compressed Air Monitoring) for this line item. Explain why confirmation of the lack of degradation is sufficient for IP 2/3.

Q12 - LRA Table 1 item 3.3.1-72: Identify and describe the applications of the External Surfaces Monitoring Program to manage loss of material for internal surfaces exposed to condensation. How is the environment determined to be the "same"?

Q13 - LRA Table 1 item 3.3.1-79: Explain the differences between those components that require the Service Water Integrity AMP and those components that only require OTI confirmation of lack of degradation. The material, environment, and function appear to be the same in both cases.

Q14 - In accordance with Table 1 item 3.3.1-87, the Boraflex Monitoring Program, supplemented by the Water Chemistry Control – Primary and Secondary Program, manages the degradation of Boraflex. LRA Table 3.3.2-1-IP2/3 credits Water Chemistry Control for managing loss of material and cracking and Boraflex Monitoring for change in material properties. Confirm that the Boraflex Monitoring Program, supplemented by the Water Chemistry Control – Primary and Secondary Program manages all three Table 2 items addressing loss of material, cracking and change in material properties.

Q15 - In accordance with LRA Table 1 item 3.3.1-13, the Boral Surveillance Program, supplemented by the Water Chemistry Control – Primary and Secondary Program, manages the degradation of Boral including the reduction of neutron-absorbing capacity. Confirm that the Table 3.3.2-1-IP2/3 line item also includes the aging effect reduction of neutron-absorbing capacity.

Q16 - In LRA Table 3.3.2-2-IP2/3 one line item for Cu alloy (>15% Zn) HX tubes exposed to treated water (ext), Service Water Integrity manages loss of material due to wear. Explain how the Service Water Integrity AMP manages components exposed to treated water.

Q17 - In LRA Table 3.3.2-3-IP2/3 for Cu alloy (>15% Zn) HX tubes exposed to treated water (ext), there are two line items, one credits HX Monitoring and the other Service Water Integrity, to manage the same aging effect (loss of material due to wear). Explain the difference.

Q18 - LRA Table 1 items 3.3.1-7 and -8 indicate that the water chemistry program is augmented by the One-Time Inspection Program, which will verify the absence of cracking. Explain why Table 2 line items in Table 3.3.2-6-IP2/3 and for other systems referring to these Table 1 items do not credit OTI.

Q19 - Provide technical justification why One-Time Inspection is not credited for verifying the effectiveness of the Oil Analysis AMP to manage cracking in stainless steel components exposed to lubricating oil, as listed in LRA Tables 3.3.2.14-IP2, 3.3.2.14-IP3, and 3.3.2.16-IP3.

Q20 - LRA Tables 3.3.2-11-IP2, -IP3, 3.3.2-14-IP2, -IP3, 3.3.2-15-IP2, -IP3, and 3.3.2-16-IP2, -IP3 all identify the aging effect "cracking-fatigue" associated with the environment "exhaust gas (int.)". The components are all parts of exhaust systems for diesel generators. Three different approaches are identified for aging management:

Fire Protection AMP in Tables 3.3.2-11-IP2, -IP3; Periodic Surveillance and Preventive Maintenance AMP in Tables 3.3.2-15-IP2, -IP3 and 3.3.2-16-IP3; TLAA-Metal Fatigue in Tables 3.3.2-14-IP2, -IP3 and 3.3.2-16-IP2. Describe the physical behavior that results in cracking due

to fatigue, and the basis for the selected approach to managing this aging effect, for each of these 8 systems. Identify where in the LRA the applicable TLAA's are described. Also identify the associated TLAA documents that will be available for audit.

Q21 – In the series of LRA Tables 3.3.2-19-xx-IP2 and 3.3.2-19-xx-IP3, there are numerous line items (over 100) that specify “cracking-fatigue” as the aging effect and “TLAA-metal fatigue” as the aging management program. The components are mostly piping and valve bodies, but also include tubing, filter housing, heater housing, strainer housing, steam trap, flex joint, sight glass, thermowell, and flow element. Identify where in the LRA the applicable TLAA's are described. Also identify the associated TLAA documents that will be available for audit.

#### **AMR-3.4-1-Arora**

The GALL Report (NUREG-1801) includes the Steam Turbine System and Extraction Steam System as part of the steam and power conversion system. Why are these two systems not included in the scope description of Steam and power conversion System, Section 3.4, included in Indian Point license renewal application?

#### **AMR-3.4-2-Arora**

LRA Section 3.4.2.1, Materials, Environment, Aging Effects Requiring management and Aging Management Programs includes the list of AMPs applicable to each system covered under Section 3.4, Steam and Power Conversion Systems. It is observed that One-Time Inspection AMP is missing from the AMP lists provided for the Main Steam, Main Feedwater and Steam Generator Blowdown Systems. Since the GALL Report (NUREG-1801) recommends that One-Time Inspection Program is to be used to verify the effectiveness of Water Chemistry Control Program used by Indian Point in these systems, the list should have included One-Time Inspection along with the other AMPs to complete the list. Explain if Indian Point has a justification for not including One-Time Inspection Program in the lists of applicable programs.

#### **AMR-3.4-3-Arora**

LRA Tables 3.4.2-1-IP2 and 3.4.2-1-IP3 (Main Steam System) include several items pertaining to carbon steel and stainless steel piping, piping components, and elements that are exposed to indoor air environment. Does this piping (and piping components and elements) have bare surface exposed to the indoor air or is this piping insulated? If the piping has insulation, it's not directly exposed to the indoor air and the applicable line items will required to be revised.

#### **AMR-3.4-4-Arora**

In LRA Tables 3.4.2-X and 3.3.2-19-X, for several line items pertaining to carbon steel piping, piping components, and piping elements, Indian Point has utilized the GALL Report line item 3.4.1-29 for managing flow-accelerated corrosion. The “Aging Effect Requiring Management” columns in these tables indicate “loss of material” as the Aging Effect. To be consistent with the terminology used in GALL Table 4, Item 29, the “Aging

Effect/Mechanism” should state “Wall thinning due to flow-accelerated corrosion” as the aging effect. All pertinent line items in the IP tables pertaining to the Flow-Accelerated Corrosion Program need to be corrected. Some examples of the IP2/IP3 tables to which this change applies are: 3.4.2-1-IP2, 3.4.2-1-IP3, 3.4.2-2-IP2, 3.4.2-2-IP3, 3.4.2-3-IP2, 3.4.2-3-IP3, 3.4.2-4-IP2, 3.4.2-4-IP3, and several 3.3.2-19-X tables.

**AMR-3.4-5-Arora**

Several components, listed as stainless steel piping, tubing, piping components, and piping elements, in LRA AMR tables 3.3.2-19-XX use line item 3.3.1-2 to manage the aging effect “cracking due to fatigue.” If these components are part of the Steam and Power Conversion System, why is the line item 3.4.1-1 not used in lieu of line item 3.3.1-2 to manage cracking due to fatigue? Also, explain why the term “Cumulative fatigue damage” not used as the Aging Effect to make the terminology consistent with the GALL Report?

Some IP2/IP3 tables to which the above questions are applicable are: 3.3.2.19-12-IP2, 3.3.2.19-23-IP2, 3.3.2.19-36-IP2, 3.3.2.19-14-IP3, 3.3.2.19-18-IP3, 3.3.2.19-22-IP3, 3.3.2.19-23-IP3, 3.3.2.19-24-IP3, 3.3.2.19-34-IP3, 3.3.2.19-35-IP3, 3.3.2.19-50-IP3 and 3.3.2.19-51-IP3.

#### **AMR-3.4-6-Arora**

Why are the notes listed in the last column of the LRA tables for Section 3.4 not applied in a consistent manner? To elaborate this inconsistency, some line items include the note “A” for a component, which implies that all the applicable parameters, such as, the component, material, environment, aging effect and the aging management program, for this line are consistent with the corresponding parameters of NUREG-1801. A note “C” is assigned to the same component type, sometimes even in the same table, a few lines later. The note “C” implies that the specific component is different from the GALL evaluated component, while all remaining parameters, such as, material, environment, aging effect, and the aging management program, are exactly same as the ones in the GALL Report. Some examples of the components which have been inconsistently “noted” in the LRA tables are: valve bodies, flow elements, tubing, piping, expansion joint, strainer housing, steam traps etc.

#### **AMR-3.4-7-Arora**

Each LRA Table 3.4.2-1-IP2 and 3.4.2-1-IP3, Main Steam System, includes one line item pertaining to carbon steel piping externally exposed to “indoor air” with the aging effect listed as “none” and Table 1 item listed as “3.4.1-28” with notes “I & 401” in the last column. Note “I” implies that the aging effect in NUREG-1801 for this component, material, and environment combination is not applicable and Note “401” implies that these components remain at high temperature during normal operation which precludes moisture condensation and the resulting corrosion. The next line item in these Tables is for the carbon steel pipe with internal exposure to “indoor air” with the aging effect listed as “loss of material” and Table 1 item listed as “3.2.1-32” and Note “E” in the last column. Note “E” implies that a different management program is credited for this line item. The aging management program included in these Tables for the second line item is “External Surfaces Monitoring.” The aging management program used in GALL

Report for line 3.2.1-32 is “Inspection of Internal Surfaces in Miscellaneous Piping and Ducting Components.”

The following three questions apply to the situation described above:

1. Do these two line items described above represent the same piping, one line covering the internal and the other the external environment? Describe the function of this piping in the main steam system.
2. What kind of indoor air is flowing through the piping that the high temperature stated in Note 401 is maintained in the piping? How the absence of corrosion is ascertained when the system cools down, e.g., during the plant shut down, refueling outages, and start up mode prior to attaining the normal operation high temperature mentioned in the Note?
3. Explain how the “External Surfaces Monitoring” Program stated in the Table is used by IP to monitor the loss of material on the “internal” surface of the subject piping?

#### **AMR-3.4-8-Arora**

Each LRA Table 3.4.2-1-IP2 and 3.4.2-1-IP3, Main Steam System, includes one line item pertaining to carbon steel bolting externally exposed to “indoor air” with the aging effect listed as “none” and Table 1 item listed as “3.4.1-22” with notes “I & 401” in the last column. Note “I” implies that the aging effect in NUREG-1801 for this component, material, and environment combination is not applicable and Note “401” implies that these components remain at high temperature during normal operation which precludes moisture condensation and the resulting corrosion.

The following questions apply to the situation described above:

1. Which component or equipment in the main steam system these bolts are installed on? Describe how the high temperature as stated in Note “401” is maintained during the normal operation. Also explain how the absence of corrosion is ascertained when the system piping and the equipment on which this bolting is installed cools down, e.g., during the plant shut down, refueling outages, and the start up mode prior to attaining the normal operation high temperature mentioned in the Note.
2. The GALL line item 3.4.1-22, as stated in the above tables, recommends the “Bolting Integrity Program” to manage the loss of material due to general, pitting and crevice corrosion in addition to loss of preload due to thermal effects and gasket creep and self loosening for the stated component, material, and environment combination. Explain how these aging effects are not applicable to the bolting in question. If IP is managing

this aging effect/mechanism under the other programs, please identify such programs.

#### **AMR-3.4-9-Arora**

In LRA Table 3.4.1, Item 3.4.1-11 states in the discussion column that this line item is consistent with NUREG-1801. IP plans to use "Buried Piping and Tanks Inspection" Program to manage "loss of material" aging effect as recommended by the GALL. The GALL Report recommends, under "Further Evaluation Recommended," that detection of aging effects and operating experience are to be further evaluated. Describe the operating experience that IP has in the area of handling buried steel piping, piping components, piping elements, and tanks (with or without coating or wrapping) exposed to soil and how this plant specific and industry operating experience is planned to be evaluated and utilized in the developing this "new" program.

#### **AMR-3.4-10-Arora**

LRA Table 3.4.1, Item 3.4.1-30, which pertains to steel piping, piping components, and piping elements, exposed to air outdoor (internal) or condensation (internal), has been used by IP for the condensate storage tanks for Units 2 and 3. The vapor space of these tanks is nitrogen blanketed per the discussion provided in the table for this line item. The specific "Note 402" applied to these tanks states that the tank vapor space is conservatively assumed to be condensation. The GALL recommends steel tanks to be managed for "loss of material due to general, pitting and crevice corrosion" under line item number 3.4.1-6. Explain if IP's aging management program for these steel tanks follows the recommendations of the GALL line item 3.4.1-6 also in addition to those of line item 3.4.1-30.

Questions from R. Morante

Q1 - Confirm that all component type/aging effect combinations that credit the SMP for aging management in Tables 3.5.2-1 thru -4 are included in the scope of the SMP and are inspected for the designated aging effect. Identify the document(s) available for audit that includes this information.

Q2 - Why is Note E specified for Table 3.5.2- 1 and 3.5.2-4 line items that reference IWE, IWL, and IWF as the aging management program? These are the AMPs that are specified in GALL. Note A would appear to be appropriate.

Q3 - In Tables 3.5.2-1 thru -4, why are the "Table 1 Item" and "NUREG-1801 Vol. 2 Item" columns blank for all cases where the "Note" column specifies "I, 501"? All of these Table 2 line items have applicable entries for these 2 columns. The implication by leaving them blank is that GALL does not address them. This is not the case. The applicant has taken exception to the GALL "Aging Effects Requiring Management". Revise the 3.5.2 Tables accordingly.

Q4 - Plant Specific Note 501 states “The IPEC environment is not conducive to the listed aging effects. However, the identified AMP will be used to confirm the absence of significant aging effects for the period of extended operation.” The Table 2 line items indicate “None” for the aging effects. Does the identified AMP confirm the absence of loss of material, cracking, and change in material properties? Revise the note accordingly.

Q5 - Plant Specific Note 502 states “Loss of insulating characteristics due to insulation degradation is not an aging effect requiring management for insulation material. Insulation products, which are made from fiberglass fiber, calcium silicate, stainless steel, and similar materials, in an air – indoor uncontrolled environment do not experience aging effects that would significantly degrade their ability to insulate as designed. A review of site operating experience identified no aging effects for insulation used at IPEC.” Discuss moisture/humidity effects on the insulating characteristics of the insulation material. Discuss the containment internal environment, in the area where the containment insulation is attached. Is the insulation exposed to moisture/humidity? How is this potential aging effect managed?

Q6 - For Table 1 items 3.5.1-57 and 3.5.1-41, confirm there are no HVAC components that are vibration-isolation mounted in the IP 2/3 LR scope.

Q7 - In reference to Table 1 item 3.5.1-54, confirm that the IWF program at IP 2/3 currently inspects for loss of mechanical function due to corrosion, distortion, dirt, overload, fatigue due to vibratory and cyclic thermal loads, and that IWF will continue to inspect for this condition during the LR period.

Q8 - In reference to Table 1 item 3.5.1-51, are the nominal yield strengths or the actual yield strengths below 150 ksi? Identify the document(s) available for audit that confirms the actual bolt material strengths.

Q9 - In reference to Table 1 item 3.5.1-48, describe the materials of construction for all water control structures in the IP 2/3 LR scope. Are there earthen intake and discharge canals? Does Entergy conduct 5-year underwater inspections of these structures?

Q10 - In reference to Table 1 item 3.5.1-34, are any water control structures in the IP 2/3 LR scope exposed to raw service water (ultimate heat sink)? How is increase in porosity and permeability, cracking, and loss of material due to aggressive chemical attack managed for these structures? Does Entergy conduct 5-year underwater inspections of these structures?

Q11 - In reference to Table 1 item 3.5.1-32, why is SMP not credited for accessible areas? Does IP 2/3 meet the criteria in ACI 201.2R-77? If not, how are inaccessible areas managed for aging?

Q12 - In reference to Table 1 item 3.5.1-31, why is SMP not credited for accessible areas? Does IP 2/3 meet the groundwater criteria for a non-aggressive environment? Does IP 2/3 have a program for sampling of below-grade concrete for signs of degradation? Provide the details of the program.

Q13 - In reference to Table 1 items 3.5.1-23,-24,-26,-27, why is the phrase "except Group 6" included here, considering that the SMP is being credited for managing aging of Group 6 structures?

Q14 - In reference to Table 1 item 3.5.1-26, is IP 2/3 located in moderate to severe weathering conditions (weathering index >100 day-inch/yr) ? If so, why is freeze-thaw not applicable?

Q15 - In reference to Table 1 item 3.5.1-6, IWE should be credited instead of IWL. Please correct.