

February 19, 2008

Mr. David A. Christian
President and Chief Nuclear Officer
Virginia Electric and Power Company
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: NORTH ANNA POWER STATION, UNIT NOS. 1 AND 2, REQUEST FOR
ADDITIONAL INFORMATION (RAI) REGARDING STEAM GENERATOR TUBE
INSERVICE INSPECTION REPORTS (MD7490 AND MD7491)

Dear Mr. Christian:

By letters dated November 15, 2007 (ML073200234), and October 9, 2007 (ML072820576), Virginia Electric and Power Company, Inc. submitted steam generator tube inservice inspection reports for the North Anna Unit 1, Fall 2007 refueling outage (RFO), and the North Anna Unit 2, Spring 2007 RFO. This was in accordance with the plant's technical specifications.

The NRC staff has reviewed the reports and has determined that additional information is required in order to complete their evaluation of the information provided. The NRC staff's request is enclosed.

You are asked to provide a response to the RAI within 30 days.

Sincerely,

/RA/

R. A. Jervey, Project Manager
Plant Licensing Branch II-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-338 and 50-339

Enclosure: RAI

cc w/encl: See next page

February 19, 2008

Mr. David A. Christian
President and Chief Nuclear Officer
Virginia Electric and Power Company
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: NORTH ANNA POWER STATION, UNIT NOS. 1 AND 2, REQUEST FOR
ADDITIONAL INFORMATION (RAI) REGARDING STEAM GENERATOR TUBE
INSERVICE INSPECTION REPORTS (MD7490 AND MD7491)

Dear Mr. Christian:

By letters dated November 15, 2007 (ML073200234), and October 9, 2007 (ML072820576), Virginia Electric and Power Company, Inc. submitted steam generator tube inservice inspection reports for the North Anna Unit 1, Fall 2007 refueling outage (RFO), and the North Anna Unit 2, Spring 2007 RFO. This was in accordance with the plant's technical specifications.

The NRC staff has reviewed the reports and has determined that additional information is required in order to complete their evaluation of the information provided. The NRC staff's request is enclosed.

You are asked to provide a response to the RAI within 30 days.

Sincerely,

/RA/

R. A. Jervey, Project Manager
Plant Licensing Branch II-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-338 and 50-339

Enclosure: RAI

cc w/encl: See next page

DISTRIBUTION:

Public	RidsAcrcsAcnwMailCenter	RidsOgcRp
LPL2-1 R/F	RidsNrrDciCsgb(AHiser)	RidsRgn2MailCenter(EGuthrie)
RidsNrrDorLpl2-1(MWong)	RidsNrrLAMO'Brien	RidsNrrDciCsgb(AObodoako)
RidsNrrPMSLingam	RidsNrrPMRJervey	RidsNrrDciCsgb(KKarwoski)

ADAMS Accession No. ML080380108

OFFICE	NRR/LPL2-1/PM	NRR/LPD2-1/LA	NRR/LPL2-1/BC
NAME	RJervey	MO'Brien	MWong
DATE	02/19/08	02/19/08	02/19/08

OFFICIAL RECORD COPY

North Anna Power Station, Units 1 & 2

cc:

Mr. David A. Christian
President and Chief Nuclear Officer
Virginia Electric and Power Company
Innsbrooks Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

Mr. C. Lee Lintecum
County Administrator
Louisa County
Post Office Box 160
Louisa, Virginia 23093

Ms. Lillian M. Cuoco, Esq.
Senior Counsel
Dominion Resources Services, Inc.
120 Tredegar Street, RS-2
Richmond, VA 23219

Dr. W. T. Lough
Virginia State Corporation Commission
Division of Energy Regulation
Post Office Box 1197
Richmond, Virginia 23218

Old Dominion Electric Cooperative
4201 Dominion Blvd.
Glen Allen, Virginia 23060

Mr. Chris L. Funderburk, Director
Nuclear Licensing & Operations Support
Dominion Resources Services, Inc.
Innsbrook Technical Center
5000 Dominion Blvd.
Glen Allen, Virginia 23060-6711

Office of the Attorney General
Commonwealth of Virginia
900 East Main Street
Richmond, Virginia 23219

Senior Resident Inspector
North Anna Power Station
U. S. Nuclear Regulatory Commission
P. O. Box 490
Mineral, Virginia 23117

Mr. Daniel G. Stoddard
Site Vice President
North Anna Power Station
Virginia Electric and Power Company
Post Office Box 402
Mineral, Virginia 23117-0402

Dr. Robert B. Stroube, MD, MPH
State Health Commissioner
Office of the Commissioner
Virginia Department of Health
Post Office Box 2448
Richmond, Virginia 23218

Mr. Mark D. Sartain, Director
Nuclear Safety & Licensing
Virginia Electric and Power Company
North Anna Power Station
P.O. Box 402
Mineral, VA 23117

REQUEST FOR ADDITIONAL INFORMATION
STEAM GENERATOR TUBE INSERVICE INSPECTION REPORTS
NORTH ANNA POWER STATION, UNIT NOS. 1 AND 2 (NORTH ANNA 1 AND 2)
DOCKET NOS. 50-338 AND 50-339

By letters dated November 15, 2007 (ML073200234), and October 9, 2007 (ML072820576), Virginia Electric and Power Company, Inc. (the licensee), submitted steam generator (SG) inspection reports for the North Anna 1 fall 2007 refueling outage (RFO) and the North Anna 2 spring 2007 RFO in accordance with the plant's technical specifications.

Question pertaining to North Anna 1:

1. One tube was plugged in Unit 1 since a permeability indication rendered a significant portion of the tube uninspectable. Please discuss how the integrity of this tube was assessed (i.e., did the tube satisfy the performance criteria) if it could not be fully inspected. For example, was an in-situ pressure test performed?

Questions pertaining to North Anna 1 and 2:

2. For each RFO and SG tube inspection since installation of the SGs, please provide the cumulative effective full power months that the SGs have operated.
3. It was indicated that the secondary-side inspections did not reveal any component degradation that would compromise tube integrity. Please discuss the results of the inspections of the secondary-side internals (e.g., any degradation/deterioration observed, any extensive deposits observed at the tube support plate openings).
4. Tube wear was listed as a potential degradation mechanism for the straight-leg and anti-vibration bar tangent points for Rows 8, 14, and 26. Please clarify why the only rows considered susceptible to this degradation mechanism are Rows 8, 14, and 26.
5. With respect to the design of your SGs, please confirm that the tubes are arranged in a square pitch/pattern and they were manufactured by Sandvik. In addition, please provide the radius of the Row 1 tubes and the tubesheet thickness (with and without clad).
6. It was indicated that the rotating coil probe was used to inspect freespan dents/bulges in Unit 1 and dents/dings/bulges in Unit 2 that measured greater than 2-volts (as determined by the bobbin coil). Please provide the information in Table 1 of the reports for these locations (e.g., these locations are potentially susceptible to primary water stress corrosion cracking and outside diameter stress corrosion cracking). Please discuss why freespan dings were not inspected in Unit 1. In addition, please discuss whether there are any dents/dings/bulges at non-freespan locations and whether these locations are susceptible to degradation (potential, relevant, existing). If so, discuss what examinations, if any, were performed at these locations.

Enclosure