

February 12, 2008

L-PI-08-007 10 CFR 50.73

U S Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Prairie Island Nuclear Generating Plant Unit 1 Docket 50-282 License No. DPR-42

LER 1-07-04, Technical Specification Required Shutdown Due to Both Emergency Diesel Generators Being Inoperable

Nuclear Management Company, LLC (NMC) herewith encloses Licensee Event Report (LER) 1-07-04. The LER describes the events surrounding completion of a Technical Specification required shutdown of Unit 1. Nuclear Management Company, LLC (NMC) reported the initiation of the Technical Specification required shutdown per 10 CFR 50.72 on December 21, 2007 (Refer to Event Number 43859).

Summary of Commitments

This letter contains one new commitment and no changes to existing commitments:

NMC will supplement this LER upon completion of the root cause evaluation for this event.

Michael D. Wadley

Site Vice President, Prairie Island Muclear Generating Plant

Nuclear Management Company, LLC

Machoe Wildelley

Enclosure

cc: Administrator, Region III, USNRC

Project Manager, Prairie Island, USNRC Resident Inspector, Prairie Island, USNRC Department of Commerce, State of Minnesota

ENCLOSURE

LICENSEE EVENT REPORT 1-07-04

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OMB NO. 3150-0104 EXPIRES: 08/31/2010																
LICENSEE EVENT REPORT (LER)							ho ba FC	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission,								
(See reverse for required number of							the	Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0066), Office of Management and Budget, Washington, DC 20503. If a means used								
digits/characters for each block)							to nu	to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.								
FACILITY NAME Prairie Island Nuclear Generating Plant Unit 1								2. DOCKET NUMBER					f 3			
4. TITLE Technic	al Sp	ecif	cation	Requi	red S	hutdown Du	e to Both E	merge	ncy Dies	el Ger	nerator	s Being	Inopera	able		<u></u>
5. EVENT DATE 6. LER NUMBER 7. REPOR							PORT DA	RT DATE 8. OTHER FACILITIES INVOLVED								
			-						T	FACILI				ET NUMBER		
MONTH	DAY	-	YEAR	YEAR	<u> N</u>	QUENTIAL REV UMBER NO		DAY	YEAR	FACILITY NAME DOCKET NUMBE					ET NUMBER	
12	21		2007	2007	_	04 – 0	02	12	2008							
9. OPE	RATIN	G M	ODE	-		11. THIS REPOR	T IS SUBMITTE	D PURSU	UANT TO TH	IE REQU	JIREMEN'	TS OF 10 C	FR §: (Ch	eck all th	hat ap	oply)
3				20.2201(b) 20.2203				203(a)(3	a)(3)(i)					2)(vii)		
Ū				20.2201(d)			20.2	20.2203(a)(3)(ii)							50.73(a)(2)(viii)(A)	
						203(a)(1)		203(a)(4)(2)(ii)(B)				2)(viii)(B)
						203(a)(2)(i)	_	6(c)(1)(i		50.73(a)(2)(iii)						
10. POV	VER L	EVE	L			203(a)(2)(ii)		6(c)(1)(i	ii)(A)	50.73(a)(2)(iv)(A)						
0										_				73.71(a)(4)		
Ū				20.2203(a)(2)(iv) 50.46(a					•	50.73(a)(2)(v)(B) 73.71(a)(5)					5)	
							'3(a)(2)(i							hatroat halaw ar in		
			_		20.2	203(a)(2)(vi)		'3(a)(2)(i		50.73(a)(2)(v)(D) Specify in Abstract below or in NRC Form 366A						
						12.	LICENSEE C	ONTAC			IONE NUI	ADED (In all		\-de\		
NAME TELEPHONE NUMBER (Include Area Code) Jeff Kivi 651.388.1121																
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT																
CAUSE SYSTEM			COMPONENT FACTURER		REPORTABLE TO EPIX		CAUSE	SYSTEM COM		COMPON	NENT FAC		R	REPORTABLE TO EPIX		
								\prod								
			14. SL	PPLEN	IENTA	L REPORT E	(PECTED			15	5. EXPE	CTED	MONTH	DA'	y 	YEAR
14. SUPPLEMENTAL REPORT EXPECTED						(ONO	SUBMISSION			03	28		2008		
ABSTRA	CT (Li	mit t	o 1400 sj	paces, i.	e., ap	proximately 15	single-spaced	typewrit	tten lines)						1	
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) On December 21, 2007, with the Unit 1 Train B emergency diesel generator (D2) out of service for planned maintenance, Nuclear Management Company, LLC (NMC) staff were conducting a required surveillance test																
						Bus 15) loa	•			•						
Unit 1 Train A emergency diesel generator (D1) was declared inoperable as a result. With both D1 and D2																
inoperable, Technical Specifications requires the affected Unit to be shutdown. Shutdown to Mode 3 was completed at approximately 0700 on December 21, 2007. Thus, this event is being reported in accordance																
												being r	eporte	d in a	cco	rdance
with 10 CFR 50.73(a)(2)(i)(A) as a Technical Specification required shutdown. Unit 1 resumed Mode 1 power operation at approximately 1600 on December 24, 2007, after the Bus 15 load																
sequencer (and D1) and D2 were returned to service.																

NRC FORM 366A (9-2007)	LICENSEE EVE	(LER)	(R) U.S. NUCLEAR REGULATORY COMMISSION						
CONTINUATION SHEET									
1.	FACILITY NAME	2. DOCKET		6. LER NUMBER		3. PAGE			
Prairie Island Nuclear	Generating Plant Unit 1	05000282	YEAR 2007	SEQUENTIAL NUMBER - 04	REV NO - 0	2 of 3			

EVENT DESCRIPTION

On December 21, 2007, with the Unit 1 Train B emergency diesel generator¹ (D2) out of service for planned maintenance, Nuclear Management Company, LLC (NMC) staff were conducting a required surveillance test on the Unit 1 Train A 4kV² Bus³ (Bus 15) load sequencer. The load sequencer failed the surveillance and the Unit 1 Train A emergency diesel generator (D1) was declared inoperable as a result. With both D1 and D2 inoperable, Technical Specifications requires the affected Unit to be shutdown. Shutdown to Mode 3 was completed at approximately 0700 on December 21, 2007.

EVENT ANALYSIS

The event resulted in Unit 1 being brought to Mode 3, thus, this event is being reported in accordance with 10 CFR 50.73(a)(2)(i)(A) as a Technical Specification required shutdown.

Impact on Safety System Functional Failure Performance Indicator

No actual loss of function occurred as a result of this event. The Unit 1 emergency AC buses remained energized at all times and D1 (although inoperable) was available for powering Bus 15 using manual operator actions under an approved procedure. Consequently, this event is not reportable per 10CFR 50.73(a)(2)(v).

SAFETY SIGNIFICANCE

Unit 1 emergency AC buses remained energized throughout the event. D1 was available for powering Bus 15 using manual operator actions had offsite sources to the Unit 1 emergency AC buses been lost during the event. Additionally, the cross-ties between Unit 1 and Unit 2 emergency AC buses were available to repower Unit 1 emergency AC buses from the Unit 2 emergency diesel generators. Thus, this event did not affect the health and safety of the public and the safety significance of this event is considered minimal.

CAUSE

The cause of the Bus 15 sequencer failure is under investigation. After completion of the root cause evaluation, NMC will supplement this LER.

³ EIIS Component Identifier: BU

¹ EIIS System Identifier: EK; EIIS Component Identifier: DG

² EIIS System Identifier: EB

NRC FORM 366A (9-2007) LICENSEE	EVENT REPORT	(LER)	U.S. NUCLEAR REGULATORY COMMISSION							
CONTINUATION SHEET										
1. FACILITY NAME	2. DOCKET NUMBER		6. LER NUMBER		3. PAGE					
Prairie Island Nuclear Generating Plant Unit 1	05000282	YEAR 2007	SEQUENTIAL NUMBER - 04	REV NO - 0	3 of 3					

CORRECTIVE ACTION

NMC staff conducted troubleshooting and replaced an input/output card on the Bus 15 load sequencer, after which the Bus 15 load sequencer successfully passed the surveillance. As a result, the Bus 15 load sequencer and D1 were returned to operable status. D2 was returned to operable status after completion of the planned maintenance.

Further Corrective Actions will be identified by the root cause evaluation. After completion of the root cause evaluation, NMC will supplement this LER.

PREVIOUS SIMILAR EVENTS

Review of Licensee Event Reports for Unit 1 and Unit 2 since 2005 found three previous Technical Specification required shutdowns. However, none of these were the result of a failed bus sequencer (two were for Unit 2 emergency diesel generator issues and one was for containment fan coil unit leakage.)