

February 21, 2008

Mr. Rick A. Muench
President and Chief Executive Officer
Wolf Creek Nuclear Operating Corporation
Post Office Box 411
Burlington, KS 66839

SUBJECT: WOLF CREEK GENERATING STATION - UPCOMING STEAM GENERATOR
TUBE INSERVICE INSPECTION (TAC NO. MD8099)

Dear Mr. Muench:

Inservice inspections (ISI) of steam generator (SG) tubes play a vital role in assuring that adequate structural integrity of the tubes is maintained. The reporting requirements of the plant Technical Specifications range from submitting a special report within 15 days following completion of each ISI of SG tubes, which identifies the number of tubes plugged and/or repaired, to submitting a special report within 180 days following completion of the inspection, which provides the complete results of the SG tube ISI. The special report containing the complete results shall include the following:

- The scope of inspections performed on each SG,
- Active degradation mechanisms found,
- Nondestructive examination techniques utilized for each degradation mechanism,
- Location, orientation (if linear), and measured sizes (if available) of service induced indications,
- Number of tubes plugged during the inspection outage for each active degradation mechanism,
- Total number and percentage of tubes plugged to date, and
- The results of condition monitoring, including the results of tube pulls and in-situ testing.

Based on discussions on February 15, 2008, with Mr. Steve Wideman, Wolf Creek Nuclear Operating Corporation has agreed to participate in a conference call with U.S. Nuclear Regulatory Commission (NRC) staff to discuss the results of the SG tube inspections during the upcoming Wolf Creek Generating Station refueling outage in spring 2008. A conference call will be arranged with members of your staff after the majority of the tubes have been inspected, but

R.A. Muench

- 2 -

before the SG inspection activities have been completed. Enclosed is a list of discussion points to facilitate this phone conference.

The NRC staff plans to document a brief summary of the conference call as well as any material that you may have provided to the staff in support of the call.

Sincerely,

/RA/

Balwant K. Singal, Senior Project Manager
Plant Licensing Branch IV
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-482

Enclosure: As stated

cc w/encl: See next page

R.A. Muench

- 2 -

before the SG inspection activities have been completed. Enclosed is a list of discussion points to facilitate this phone conference.

The NRC staff plans to document a brief summary of the conference call as well as any material that you may have provided to the staff in support of the call.

Sincerely,

/RA/

Balwant K. Singal, Senior Project Manager
Plant Licensing Branch IV
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-482

Enclosure: As stated

cc w/encl: See next page

DISTRIBUTION:

PUBLIC
LPLIV Reading
RidsAcrsAcnwMailCenter
RidsNrrDorlDpr
RidsNrrDciCsgb
RidsNrrDorlLpl4
RidsNrrPMBSingal
RidsNrrLAJBurkhardt
RidsOgcRp
RidsRgn4MailCenter
JBurke, NRR/DCI/CSGB

ADAMS Accession No. ML080500017

(*) E-mail dated 2/15/08

OFFICE	NRR/LPL4/PM	NRR/LPL4/LA	NRR/CSGB/BC	NRR/LPL4/BC
NAME	BSingal	JBurkhardt	AHiser (*)	THiltz, JND for
DATE	2/21/08	2/21/08	2/15/08	2/21/08

OFFICIAL AGENCY RECORD

Wolf Creek Generating Station

(2/2006)

cc:

Jay Silberg, Esq.
Pillsbury Winthrop Shaw Pittman LLP
2300 N Street, NW
Washington, D.C. 20037

Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 311
Burlington, KS 66839

Chief Engineer, Utilities Division
Kansas Corporation Commission
1500 SW Arrowhead Road
Topeka, KS 66604-4027

Office of the Governor
State of Kansas
Topeka, KS 66612

Attorney General
120 S.W. 10th Avenue, 2nd Floor
Topeka, KS 66612-1597

County Clerk
Coffey County Courthouse
110 South 6th Street
Burlington, KS 66839

Chief, Radiation and Asbestos Control
Section
Kansas Department of Health
and Environment
Bureau of Air and Radiation
1000 SW Jackson, Suite 310
Topeka, KS 66612-1366

Vice President Operations/Plant Manager
Wolf Creek Nuclear Operating Corporation
P.O. Box 411
Burlington, KS 66839

Supervisor Licensing
Wolf Creek Nuclear Operating Corporation
P.O. Box 411
Burlington, KS 66839

U.S. Nuclear Regulatory Commission
Resident Inspectors Office/Callaway Plant
8201 NRC Road
Steedman, MO 65077-1032

STEAM GENERATOR TUBE INSPECTION DISCUSSION POINTS

WOLF CREEK GENERATING STATION

DOCKET NO. 50-482

The following discussion points have been prepared to facilitate a phone conference to be arranged with the licensee to discuss the results of the steam generator (SG) tube inspections to be conducted during the upcoming spring 2008 Wolf Creek Generating Station refueling outage.

This phone call is scheduled to occur towards the end of the planned SG tube inspection interval, but before the unit completes the inspections and repairs.

The NRC staff plans to document a brief summary of the conference call as well as any material that is provided in support of the call.

1. Discuss any trends in the amount of primary-to-secondary leakage observed during the recently completed cycle.
2. Discuss whether any secondary-side pressure tests were performed during the outage and the associated results.
3. Discuss any exceptions taken to the industry guidelines.
4. For each SG, provide a description of the inspections performed including the areas examined and the probes used (e.g., dents/dings, sleeves, expansion-transition, U-bends with a rotating probe), the scope of the inspection (e.g., 100 percent of dents/dings greater than 5 Volts and a 20 percent sample between 2 and 5 Volts), and the expansion criteria.
5. For each area examined (e.g., tube supports, dent/dings, sleeves, etc.), provide a summary of the number of indications identified to-date of each degradation mode (e.g., number of circumferential primary water stress-corrosion cracking (PWSCC) indications at the expansion transition). For the most significant indications in each area, provide an estimate of the severity of the indication (e.g., provide the voltage, depth, and length of the indication). In particular, address whether tube integrity (structural and accident-induced leakage integrity) was maintained during the previous operating cycle. In addition, discuss whether any location exhibited a degradation mode that had not previously been observed at this location at this unit (e.g., observed circumferential PWSCC at the expansion transition for the first time at this unit).
6. Describe repair/plugging plans.
7. Describe in-situ pressure test and tube-pull plans and results (as applicable and if available).
8. Provide the schedule for SG-related activities during the remainder of the current outage.

ENCLOSURE

9. Discuss the following regarding loose parts:
 - what inspections are performed to detect loose parts
 - a description of any loose parts detected and their location within the SG
 - if the loose parts were removed from the SG
 - indications of tube damage associated with the loose parts
 - the source or nature of the loose parts, if known
10. Discuss the results of any secondary-side inspections.
11. Discuss any unexpected or unusual results.