Comparison of Structural Integrity Manual Phased Array Sizing Measurements Taken on Safety Nozzle "A" Versus LMT Manually Encoded Data

DRAFT

Comparison

- Objective
 - Evaluate Structural Integrity Depth Sizing
 Measurements using LMT Manually Encoded
 Data
 - Determine if any of the reported flaws are connected to inside surface
 - Determine origin of tip signals reported

Comparison

- Approach
 - Perform side by side comparison of sizing data taken on Safety nozzle A
 - Optimize views
 - Determine if target is present
 - Measure maximum extent
 - Determine if there is evidence present that the flaw is connected to the inside surface

Overview of LMT Analysis Views



3/13/2008

DRAFT

Overview of Structural Integrity Analysis View



Location 1 Comparison at 0"



Location 2 Comparison at 1.0"





Location 3 Comparison at 2.0"





Location 4 Comparison at 3.0"





Location 5 Comparison at 4.0"





Location 6 Comparison at 5.0"





Location 7 Comparison at 6.0"





Location 8 Comparison at 7.0"





Location 9 Comparison at 8.0"





Location 10 Comparison at 9.0"





Location 11 Comparison at 10.0"





Location 12 Comparison at 11.0"





Location 13 Comparison at 12.0"





Location 14 Comparison at 13.0"





Location 15 Comparison at 14.0"

 Not detected circumferential Measurement may be off on manual report <u>"A" Safety Circumferential Indication Profile Data</u>
 Location: 14 inches clockwise from "0" stamp
 Part Thickness used for calculation: 1.7 inches
 Indication through-wall depth at this location: 0.99 inches
 Estimated remaining ligament above the indication: 0.71 inches
 Angle used for measurement: 40 degrees



Location 16 Comparison at 15.0"





Location 17 Comparison at 16.0"





Part Thickness used for calculation: 1.7 inches

Indication through-wall depth at this location: 1.17 inches

Estimated remaining ligament above the indication: 0.53 inches

Angle used for measurement: 69 degrees





Location 18 Comparison at 17.0"

 Unable to resolve indication in this area suspect circumferential position may be off.
 From data it appears to be an additional feature of same flaw measured at 16.0" "A" Safety Circumferential Indication Profile Data Location: 17 inches clockwise from "0" stamp Part Thickness used for calculation: 1.7 inches Indication through-wall depth at this location: 1.41 inches Estimated remaining ligament above the indication: 0.29 inches Angle used for measurement: 65 degrees



Location 19 Comparison at 18.0"





Summary

- Tip signals reported by Structural Integrity appear to be associated with embedded stacked fabrication flaws
- None of the flaws appear to be connected to the inside surface and to each other
- Flaws in nozzles B and C have same characteristics as the flaws in Nozzle A