

Ross T. Ridenoure VP and Site Manager San Onofre Nuclear Generating Station

March 28, 2008

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555-0001

## Subject: Docket Nos. 50-361 and 50-562 Licensee Event Report No. 2006-004 San Onofre Nuclear Generating Station, Units 2 and 3

Dear Sir or Madam:

- 7

In compliance with 10CFR50.73(a)(2)(i)(B), this submittal provides Licensee Event Report (LER) 2006-004 to report an entry into a Mode without all applicable Surveillances being current. Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

If you require any additional information, please contact me.

Sincerely,

Units 2 and 3 LER No. 2006-004

cc: E. E. Collins, NRC Regional Administrator, Region IV C. C. Osterholtz, NRC Senior Resident Inspector, San Onofre Units 2 & 3

Mail Drop D45 P.O. Box 128 San Clemente, CA 92672 949-368-6255 PAX 86255 Fax: 949-368-6183 Ross.Ridenoure@sce.com

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION							NA	J APPROVED BY OMB: NO. 3150-0104 EXPIRES: 08/31/2010									
(5-2007)							R	Estimated burden per response to comply with this mandatory information collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send									
LICENSEE EVENT REPORT (I FR)							N	comments regarding burden estimate to the Records and FOIA/Privacy service Branch (T-5F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to									
(See reverse for required number of							in 11	infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB- 10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to									
	d	igits/charac	ters fo	or each block)				in Ci	npose inform onduct or sp	ation onsor	collection does , and a person	not display a c is not required	to re	ntly valid OMB control nu espond to, the informatic	mber, the NRC may not on collection.		
1. FACILITY NAME							2	2. DOCKET NUMBER				3.	PAGE				
San Onotre Nuclear Generating Station Unit 2								0	5000361		1 OF 4						
4. TITLE																	
Late sur	veillances	s on Lo	oss	of Voltage	Re	ela	ys resu	lts i	in SR 3	6.0.	4 violatio	on					
			<u> </u>														
5.	5. EVENT DATE 6. LER NUMBER		7. REPORT DATE			FACILITY NAME			DOCKET NUMBER								
MO	DAY	YEAR	YE	EAR NUMBER		10 10	MO	DAY	YEAR	s	San Onofre Unit 3		05000362				
03	24	2006		2006-004-0	<u>۱</u>		03	28	2008	FA	CILITY NAME		DC	CKET NUMBER			
	<b>Z</b> <del>4</del>	2000		2000-004-0	0			20	2000						4		
9. OPER MO	RATING DE	4		20 2201(b)	REF	UR	20 2203(a	a)(3)(i	<u>) PURSUAR</u>		50 73(a)(2)			50 73(a)(2)(ix)(A)	тарріу)		
40.00			┨──	20.2201(0)		20.2203(a)(a)		م) م)		50.73(a)(2)(ii)			50.73(a)(2)(x)				
LEV	/EL	n/a		20.2201(0)			50.36(c)(	<u>-/(-/</u> 1)(i)(A	·//		50,73(a)(2)	(iv)(A)		73 71(a)(4)			
				20.2203(a)(1)		50 36(c)(1)(i		<u>()()</u>		50,73(a)(2)	(v)(A)		73.71(a)(5)				
			<b> </b>	20.2203(a)(2)(ii)		50.36(c)(2	50.36(c)(2)			50.73(a)(2)	(v)(B)		OTHER				
				20.2203(a)(2)(iii)			50.46(a)(				50.73(a)(2)	(v)(C)		Specify in Abstract b	elow or in		
100-0-18 E		14. J		20.2203(a)(2)(iv)			50.73(a)(	2)(i)(A	۹)		50.73(a)(2)	!)(v)(D)					
				20.2203(a)(2)(v)		Х	50.73(a)(	2)(i)(E	3)		50.73(a)(2)(vii)						
				20.2203(a)(2)(vi)			50.73(a)(2	2)(i)(C	C)	50.73(a)(2)(viii)(A)							
				20.2203(a)(3)(i)			50.73(a)(	2)(ii)(/	A)		50.73(a)(2)	(viii)(B)					
					12.	LIC	CENSEE	CON	TACT FO	RŤ	HIS LER						
NAME			•••							TE		JMBER (Includ	ae A	rea Code)			
Ross Ridenoure, VP and Site Manager							MDC		94	19-368-62			PEDOPT				
0.11/05	OVOTEM	13.001		MANU-		R	EPORTABLE				EVETEM		<u>ат</u>	MANU-	REPORTABLE TO		
CAUSE	5151EW	COMPOR		FACTURER			TO EPIX	_	CAUSE	_	3131EW	COMPONEN	N I	FACTURER	EPIX		
	14	I. SUPPLE	EMEI	NTAL REPORT E	XPE	CTI	ED	1882.5	1		15. EX	PECTED		MONTH DAY	YEAR		
VES							Х	NO	SUBMISSION								
YES (If yes, complete EXPECTED SUBMISSION DATE)																	
	ndervolta	uuu, 3 aae rel:	avs	and seque	enc	a L ed	Lload re	-lav	rs on S	an	Onofre I	Nuclear (	iaų Ge	perating Stat	ion		
	SONGS)	Units 2	2 a	nd 3 had no	nt b	nee	en teste	ed p	er Sun	veil	lance Re	equireme	ent	(SR) 3.3.7.2			
	R 3.3.7.3	B and S	SR	3.8.1.18 wi	thir	n tl	ne reau	irea	d Freau	Jen	cv. This	resulted	d fi	rom a change	, in the		
a l	rocess u	sed to	scł	hedule and	tra	ick	the co	mpl	letion o	f th	ne LOVS	relays s	ur	veillances. Ir	2000,		
s	CE chan	ged fro	сm	refueling o	uta	ige	e testing	g to	on-line	e te	sting. T	he revise	əd	testing progra	am for		
s	cheduling	g and t	rac	king inadve	erte	ent	ly allow	/ed	some i	ndi	ividual co	omponer	nts	to exceed th	e SR		
Frequency.																	
	CE revie	wed th	ne t	hree year p	eri	od	preced	guit	the di	sco	overy dat	e, 1/29/2	200	05 through			
1	/29/2008	. On a	5/24	4/2006, SOI	NG	55	Unit 2 (	cna	ingea iv	/100			15	ore the LC	1V5		
	equentia Inite 2 an	d 3 C	ig i `on	relays. The	i Of Sim	1-11 aile	ne surv		ance li	acr	king prog	nam was	s C	pits over the s	ame		
	priod end	ling or	יוטי 1/ ר	29/2008	SIII R	3 (	1 moue	hihi	ts entry	vve v in	to a Mod	le withou	uu it t	he applicable	SRs		
	aving be	en met	t wi	ithin their sr		cifie	ed Fred	iuei	ncv. S	CE	is repor	tina this		currence in	0110		
	compliance with 10 CFR 73(a)(2)(i)(B).																
The program has been modified and all missed relay surveillances have been completed with																	
all response times within limits designated by TS.																	
1																	

NRC FORM 366A (9-2007)		U.S. NUCLEAR REGULATORY COMMISSION					
LICENSEE EVEN CONTINUA							
1. FACILITY NAME	2. DOCKET NUMBER		6. LER NUMBER		PAGE (3)		
San Onofra Nuclear Concreting Station (SONGS) Unit 2	05000361	YEAR	SEQUENTIAL NUMBER	REV NO	2 of 4		
San Onoire Nuclear Generating Station (SONGS) Onit 2	05000501	2006	004	00	2014		

Plant:	San Onofre Nuclear Generating Station (SONGS) Units 2 & 3
Event Date:	March 24, 2006
Reactor Vendor:	Combustion Engineering
Mode:	Mode 4- Hot Shutdown
Power:	n/a

### Background

San Onofre Unit 2 4kV class 1E buses [EB] are protected from loss of their supply power by undervoltage relays that generate a Loss of Voltage Signal (LOVS) for complete loss of voltage. The LOVS in conjunction with a Safety Injection Actuation Signal (SIAS) will transfer the 1E bus to the standby power source, the Emergency Diesel Generator (EDG)[EK]. LOVS without SIAS will transfer the 1E bus to the alternate preferred power source, if available. If the alternate preferred power source is not available, it will transfer the 1E bus to the EDG. In compliance with Surveillance Requirement (SR) 3.3.7.2 and SR 3.3.7.3, the LOVS undervoltage relays are to be calibrated and tested every 24 months.

The LOVS Time Delay Auxiliary relays sequentially load the safety related equipment to the 1E bus to prevent sudden loading of the EDG. Surveillance Requirement (SR) 3.8.1.18 requires verifying the timing of these sequenced load relays every 24 months.

The Engineered Safety Feature (ESF) Relays must be tested to verify Response Times under a similar program every 24 months on a Staggered Basis in compliance with SR 3.3.5.6.

#### **Description of Event**

On January 29, 2008, (discovery date), Southern California Edison (SCE) recognized that approximately 13 LOVS undervoltage relays and sequenced load relays had not been tested within their specified Frequency. SR 3.3.7.2, SR 3.3.7.3 and SR 3.8.1.18 prescribe an interval of 24 months (30 months with the 25 percent extension allowed by SR 3.0.2)

SCE determined this resulted from a change in the process used to schedule and track the completion of the LOVS relays surveillances. Prior to 2000, the undervoltage relays and the sequenced load relays were tested as a group during refueling outages, complying with the 24 month frequency. In 2000, the program was revised to test on-line. The individual component relay tests were distributed throughout the entire two year period ending 2002, ensuring the relays tested in the 2000 refueling outage were retested by 2002.

The on-line testing program was repeated during subsequent surveillance intervals (2002 to 2004 interval, 2004 to 2006 interval and the 2006 to 2008 interval). This program did not individually track the component relays. Consequently, this method of scheduling and tracking inadvertently allowed some individual components to exceed the specified SR Frequency.

SCE also identified that the Engineered Safety Feature (ESF) Relays had not been tested in the required Frequency due to a similar scheduling deficiency.

Surveillance Requirement 3.0.4 prohibits entry into a Mode of a Limiting Condition for

NRC FORM 366A (9-2007)		U.S. NUCL	EAR REGULATORY	COMMISSI	ON	
LICENSEE EVENT REPORT (LER) CONTINUATION SHEET						
1. FACILITY NAME	2. DOCKET NUMBER		6. LER NUMBER		PAGE (3)	
San Onofre Nuclear Generating Station (SONGS) Unit 2	05000361	YEAR	SEQUENTIAL NUMBER	REV NO	3 of A	
San Onone Nuclear Generating Station (SONGS) Onit 2	00000001	2006	004	00	3014	

operation (LCO) Applicability unless the LCO Surveillances have been met within their specified Frequency. To determine compliance of SR 3.0.4, SCE reviewed the three year period preceding the discovery date, January 29, 2005 through January 29, 2008, as required in 10 CFR 50.73(a)(1). SCE discovered that on March 24, 2006 (event date), SONGS Unit 2 entered Mode 4 from Mode 5. LCO 3.8.1 is Applicable in Modes 1, 2, 3 and 4. At that time, four of the LOVS timing relays for the sequential loading had not been verified in accordance with SR 3.8.1.18. SCE is reporting this in compliance with 10 CFR 73(a)(2)(i)(B).

The on-line surveillance tracking program for the LOVS relays and ESF relays was common to both Units 2 and 3. Consequently, similar mode changes were made on both units over the same period ending on January 29, 2008 (discovery date).

#### Cause of the Event

This event occurred due to an inadequate assessment of program impacts when moving from outage to on-line surveillance testing. The implementation plan did not have the formality and rigor that would have led to the inclusion of a review by personnel cognizant of surveillance scheduling prior to implementation.

#### **Corrective Actions**

3

Completed corrective actions are:

- 1) In accordance with SR 3.0.3, SCE completed a risk evaluation that allowed up to 146 days to complete the applicable SRs for the LOVS timing relays.
- 2) On March 10, 2008, SCE completed testing of those LOVS relays that had exceeded 30 months (24 month frequency and the SR 3.0.2 allowed extension period).
- 3) SCE verified that the ESF relays are currently within their specified Frequency.

Planned corrective actions are:

- 4) Cancel the existing Repetitive Maintenance Orders (RMO) used for "master tracking" of the LOVS and ESF relay surveillance testing and create RMOs for each individual relay.
- 5) Review current change management initiatives and reinforce expectations related to the importance of applying rigor and formality to those initiatives as outlined in SONGS procedure, "Change Management Guideline."

#### **Safety Significance**

All missed LOVS and ESF relay surveillance have been completed with all response times within limits designated by TS. Therefore, the relays remained capable of performing their intended safety function. Consequently, there was no safety significance to this event.

NRC FORM 366A (9-2007)	EAR REGULATORY	COMMISSI	ON					
LICENSEE EVEN CONTINUAT	LICENSEE EVENT REPORT (LER) CONTINUATION SHEET							
1, FACILITY NAME	2. DOCKET NUMBER		6. LER NUMBER		PAGE (3)			
Son Onofro Nuclear Constating Station (SONGS) Unit 2	05000361	YEAR	SEQUENTIAL NUMBER	REV NO	A of A			
San Onoire Nuclear Generating Station (SONGS) Onit 2	05000501	2006	004	00	+014			

# Additional Information

Over the last three years, SCE has not reported any other similar incidents of late surveillances due to an inadequate program for scheduling and tracking.