



**UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
SAM NUNN ATLANTA FEDERAL CENTER
61 FORSYTH STREET, SW, SUITE 23T85
ATLANTA, GEORGIA 30303-8931**

April 7, 2008

Virginia Electric and Power Company
ATTN: Mr. David A. Christian
President and Chief Nuclear Officer
Innsbrook Technical Center – 2SW
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

**SUBJECT: SURRY POWER STATION - NRC COMPONENT DESIGN BASIS INSPECTION
REPORT 05000280/2008006 AND 05000281/2008006**

Dear Mr. Christian:

On February 29, 2008, the U. S. Nuclear Regulatory Commission (NRC) completed an inspection at your Surry Power Station, Units 1 & 2. The enclosed inspection report documents the inspection findings, which were discussed on February 29, 2008, with Mr. Don Jernigan and other members of your staff.

The inspection examined activities conducted under your licenses as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your licenses. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

Based on the results of this inspection, the inspectors identified three findings of very low safety significance (Green), which involved violations of NRC requirements. Additionally, one licensee-identified violation which was determined to be of very low safety significance is listed in this report. However, because of their very low safety significance and because they are entered into your corrective action program, the NRC is treating these findings as Non-Cited Violations (NCVs) consistent with Section VI.A.1 of the NRC's Enforcement Policy. If you contest any of these NCVs you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the United States Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington DC 20555-0001, with copies to the Regional Administrator, Region II; the Director, Office of Enforcement, U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector at Surry Power Station.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system

VEPCO

2

(ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Binoy B. Desai, Chief
Engineering Branch 1
Division of Reactor Safety

Docket Nos.: 50-280, 50-281
License Nos.: DPR-32, DPR-37

Enclosure: Inspection Report 05000280, 281/2008006
w/Attachment: Supplemental Information

cc w/encl:
Chris L. Funderburk, Director
Nuclear Licensing and
Operations Support
Virginia Electric & Power Company
Electronic Mail Distribution

Donald E. Jernigan
Site Vice President
Surry Power Station
Virginia Electric & Power Company
Electronic Mail Distribution

Virginia State Corporation Commission
Division of Energy Regulation
P. O. Box 1197
Richmond, VA 23209

Lillian M. Cuoco, Esq.
Senior Counsel
Dominion Resources Services, Inc.
Electronic Mail Distribution

Attorney General
Supreme Court Building
900 East Main Street
Richmond, VA 23219

Letter to David A. Christian from Binoy Desai dated April 7, 2008.

SUBJECT: SURRY POWER STATION - NRC COMPONENT DESIGN BASIS INSPECTION
REPORT NOS. 05000280/2008006 AND 05000281/2008006

Distribution w/encl:

RIDSNRRDIRS

S. P. Lingam, NRR (PM: NA, SUR)

Richard Jervey, NRR

PUBLICLY AVAILABLE NON-PUBLICLY AVAILABLE SENSITIVE NON-SENSITIVE

ADAMS: YES ACCESSION NUMBER: _____

OFFICE	RII:DRS	RII:DRP	RII:DRS	RII:DRS	RII:DRS	Contractor	Contractor
SIGNATURE	RA	RA	RA	RA	RA	RA	RA
NAME	R.Berryman	S.Rose	W.Fowler	J.Hamman	G.Gardner	C.Baron	G.Skinner
DATE	03/31/2008	03/28/2008	03/21/2008	03/25/2008	03/20/2008	03/20/2008	03/24/2008
OFFICE	RII:DRP						
SIGNATURE	RA						
NAME	E.Guthrie						
DATE	04/07/2008						

OFFICIAL RECORD COPY DOCUMENT NAME: S:\DRS\Eng Branch 1\CBDI Documents\CDBI Final Inspection Reports\Surry CDBI 2008006 Report (RMB).doc

U. S. NUCLEAR REGULATORY COMMISSION

REGION II

Docket Nos.: 50-280, 50-281

License Nos.: DPR-32, DPR-37

Report No.: 05000280/2008006 and 05000281/2008006

Licensee: Virginia Electric and Power Company (VEPCO)

Facility: Surry Power Station, Units 1 & 2

Location: 5850 Hog Island Road
Surry, VA 23883

Dates: January 28, 2008 through February 29, 2008

Inspectors: R. Berryman, P.E., Senior Reactor Inspector (Lead)
S. Rose, Senior Reactor Inspector
W. Fowler, Reactor Inspector
C. Baron, Contractor
G. Skinner, Contractor

Accompanying Personnel: B. Collins, Reactor Inspector (trainee)
G. Gardner, Reactor Inspector (trainee)
J. Hamman, Reactor Inspector (trainee)

Approved by: Binoy B. Desai, Chief
Engineering Branch 1
Division of Reactor Safety

Enclosure

SUMMARY OF FINDINGS

IR 05000280/2008006, 05000281/2008006; 1/28/08 - 2/29/08; Surry Power Station, Units 1 and 2; Component Design Basis Inspection.

This inspection was conducted by a team of three NRC inspectors, three NRC inspectors who were in training, and two NRC contract inspectors. Three Green findings, all of which were non-cited violations (NCVs) were identified. The significance of most findings is indicated by their color (Green, White, Yellow, Red) using IMC 0609, "Significance Determination Process" (SDP). Findings for which the SDP does not apply may be Green or be assigned a severity level after NRC management review. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," (ROP) Revision 4, dated December 2006.

A. NRC-Identified and Self-Revealing Findings

Cornerstone: Mitigating Systems

- Green. The inspectors identified two examples of a Green non-cited violation of 10 CFR 50, Appendix B, Criterion III, Design Control, for failure to evaluate variations of emergency diesel generator (EDG) output frequency in electrical design loading calculations, and failure to consider worst case 4160 VAC bus voltage in safety related motor starting calculations. This finding was entered into the licensee's corrective action program as condition reports (CR) 091493 and 091494. Planned corrective actions included revision of the EDG loading calculations to incorporate the most limiting voltages and frequencies.

This finding is more than minor because it affects the Mitigating Systems Cornerstone objective ensuring the availability, reliability, and operability of the EDGs to perform the intended safety function during a design basis event and the cornerstone attribute of Design Control, i.e. initial design. The inspectors assessed the finding using the SDP and determined that the finding was of very low safety significance (Green) because the deficiencies did not result in any EDG being inoperable based upon additional analysis that showed that the EDGs had sufficient margin to accommodate the increased loading due to worst case acceptably high EDG output frequency; and all safety related motor loads remained operable since they were still capable of starting with the revised worst case low voltage values. (Section 1R21.2.12)

- Green. The inspectors identified a Green NCV of 10 CFR 50, Appendix B, Criterion XI, Test Control, for incorrect acceptance criteria in test procedure 1-EPT-0106-01, Main Station Battery 1A Service Test. This finding was entered into the licensee's corrective action program as condition report 091906. Planned corrective actions included revision of the main station battery test procedures to include the correct voltage at the one minute mark.

This finding is more than minor because it affects the Mitigating Systems Cornerstone objective ensuring the availability, reliability, and operability of the station batteries to perform the intended safety function during a design basis event and the cornerstone

attribute of Procedure Quality, i.e. maintenance and testing procedures. The inspectors assessed the finding using the SDP and determined that the finding was of very low safety significance (Green) because the deficiency did not result in station batteries being inoperable based upon a recent review of station battery discharge test results.

The inspectors determined that the lack of a thorough evaluation of condition report 022112, which addressed deficiencies in station battery test procedures such that resolutions addressed causes, was a significant cause of this performance deficiency. Failure to thoroughly evaluate problems such that resolutions address causes is directly related to the Corrective Action Program component of the cross-cutting area of Problem Identification and Resolution and the aspect of thorough evaluation of problems (P.1(c)). (Section 1R21.2.13)

- Green. The inspectors identified a Green non-cited violation of 10 CFR 50, Appendix B, Criterion III, Design Control, for failure to evaluate the most limiting differential pressure (dP) for opening valve 2-FW-MOV-260A, auxiliary feedwater (AFW) cross-tie motor-operated valve (MOV). This finding was entered into the licensee's corrective action program as condition report 091698. Planned corrective actions included internal inspection of the valve and revision of the evaluation that identified the most limiting dP for opening.

This finding is more than minor because it affects the Mitigating Systems Cornerstone objective ensuring the availability, reliability, and operability of the AFW system to perform the intended safety function during a design basis event and the cornerstone attribute of Design Control, i.e. initial design and plant modifications. The inspectors assessed the finding using the SDP and determined that the finding was of very low safety significance (Green) because the deficiency did not result in 2-FW-MOV-260A being inoperable based upon additional analysis which showed that the MOV had sufficient margin to accommodate opening against the worst case high dP.

The inspectors determined that the lack of control or understanding of the actual margin to maximum allowable dP to open 2-FW-MOV-260A was a significant cause of this performance deficiency. Failure to maintain design margins is directly related to the Resources component of the cross-cutting area of Human Performance and the aspect of maintenance of plant safety by the maintenance of design margins (H.2(a)). (Section 1R21.2.19)

B. Licensee-Identified Violations

One violation of very low safety significance, which was identified by the licensee has been reviewed by the inspectors. Corrective actions taken or planned by the licensee have been entered into the licensee's corrective action program. This violation and corrective action tracking number are listed in Section 4OA7 of this report.

REPORT DETAILS

1. REACTOR SAFETY

Cornerstones: Initiating Events, Mitigating Systems, Barrier Integrity

1R21 Component Design Bases Inspection (71111.21)

.1 Inspection Sample Selection Process

The team selected risk significant components and operator actions for review using information contained in the licensee's Probabilistic Risk Assessment (PRA). In general, this included components and operator actions that had a risk achievement worth factor greater than two or Birnbaum value greater than 1×10^{-6} . The components selected were located within the auxiliary feedwater (AFW) system, component cooling water (CCW) system, safety injection system, charging system, emergency diesel generator (EDG) support and electrical subsystems, 4160 VAC electrical system, alternate AC diesel generator (AAC Diesel) support and electrical subsystems, 125Vdc battery system, and reserve station service (RSS) transformer system. The sample selection included 19 components, five operator actions, and four operating experience items. Additionally, the team reviewed one modification by performing activities identified in IP 71111.17, "Permanent Plant Modifications," Section 02.02.a. and IP 71111.02, "Evaluations of Changes, Tests, or Experiments."

The team performed a margin assessment and detailed review of the selected risk-significant components to verify that the design bases have been correctly implemented and maintained. This design margin assessment considered original design issues, margin reductions due to modification, or margin reductions identified as a result of material condition issues. Equipment reliability issues were also considered in the selection of components for detailed review. These included items such as failed performance test results, significant corrective action, repeated maintenance, maintenance rule (a)1 status, RIS 05-020 (formerly GL 91-18) conditions, NRC resident inspector input of problem equipment, system health reports, industry operating experience and licensee problem equipment lists. Consideration was also given to the uniqueness and complexity of the design, operating experience, and the available defense in depth margins. An overall summary of the reviews performed and the specific inspection findings identified are included in the following sections of the report.

.2 Results of Detailed Reviews

.2.1 AAC Diesel (engine, fuel oil, lubrication, jacket water cooling, ventilation)

a. Inspection Scope

The team reviewed the Updated Final Safety Analysis Report (UFSAR), Design Basis Documents (DBDs), drawings, calculations, maintenance records, and operating procedures to verify the capability of the AAC Diesel to perform the intended function during a station blackout (SBO) event. Tank capacity calculations were reviewed to ensure sufficient fuel oil was available in the fuel oil day tank to support the required

mission time for the AAC Diesel. Cooling, lubrication, and air start capabilities were reviewed to verify that these systems were adequately sized. A walk down of the AAC Diesel and support systems was conducted to ensure that the installed systems matched the descriptions in the DBD. Design change history and related corrective actions were reviewed to assess potential component degradation and impact on design margins.

b. Findings

No findings of significance were identified.

.2.2 Check Valves SI-224 and 225 (Cold Leg Injection); and SI-25 and 410 (RWST Cross-Connect)

a. Inspection Scope

The team reviewed Technical Specifications (TS); UFSAR; design drawings and calculations; and plant procedures to verify the appropriateness of design assumptions, boundary conditions, and models. This review was also conducted to verify that the licensee's analytical methods were appropriate. The team verified that design assumptions and limitations were translated to operational and testing procedures. Plant personnel were interviewed and a component walk down was conducted to verify that potential degradation was being monitored or prevented. A system walk down was also conducted to verify that the observable material condition would support the design operation, component configurations were being maintained consistent with design assumptions, and the equipment was adequately protected from external events. The team also reviewed maintenance and corrective action history to verify that potential degradation was being monitored or prevented and that component replacement was consistent with qualification life.

b. Findings

No findings of significance were identified.

.2.3 EDG-1/2/3 (Mechanical)

a. Inspection Scope

The team reviewed the UFSAR, TS, TS Bases, and DBDs to identify the design basis of various support systems associated with the operation of the EDGs during design basis accident conditions. The EDG fuel oil sub-system was reviewed to verify its ability to provide sufficient fuel oil to meet the design basis of seven days of operation while fully loaded. Calculations and procurement controls were reviewed to verify that the acceptance of ultra low sulfur fuel oil (ULSFO) would not impact the capability of the EDGs to complete a seven day mission time. American Petroleum Institute (API) acceptance limits and underground fuel oil storage tank level instrumentation were reviewed to verify density and energy content changes associated with different API values would not impact the ability of operators to verify sufficient fuel oil availability in the underground storage tanks at higher API values.

The team reviewed calculations and design documents for the diesel fuel oil transfer system to verify its capability of performing the design function of providing adequate fuel from two underground storage tanks to the diesel room auxiliary and day tank. Calculations associated with fuel oil consumption rates, pumping requirements, and net positive suction head (NPSH) were reviewed to verify adequate fuel oil can be transferred for multiple EDG operation.

Calculations, EDG Owners Group recommendations and vendor manuals were reviewed to verify that EDG de-rating was not required. The EDG jacket water cooling system and diesel building air temperature calculations were reviewed to verify limiting jacket water exit temperatures would not be exceeded during times of elevated ambient air temperatures. Jacket water chemistry controls were reviewed to verify that system fluid additives did not conflict with assumptions used to validate that engine de-rating was not required.

The team reviewed design features for the diesel building ventilation system with regards to adverse weather such as tornados. Ventilation system drawings and documentation related to Regulatory Issue Summary 2006-23, Post Tornado Operability of Ventilating and Air-Conditioning Systems Housed in Emergency Diesel Generator Rooms, were reviewed to verify the system was capable of operating as designed during pressure transients experienced during tornado events. Walkdowns were conducted to verify system components are being maintained and that system alignment was consistent with current operation practices.

b. Findings

No findings of significance were identified.

.2.4 Charging Pump Lubricating Oil Coolers (1-CH-E-5A, B and C)

a. Inspection Scope

The team reviewed the UFSAR, DBDs, calculations and corrective actions documents to verify that the charging pump lubricating oil coolers could perform the design basis function of providing adequate heat removal for the inboard and outboard bearing oil and pump speed increaser gear box. Calculations were reviewed to verify the existence of adequate heat transfer capability between the lubricating oil and the charging pump service water system. Calculation inputs were reviewed and compared to the installed plant equipment to verify design inputs were correct. Maintenance and procurement controls were reviewed to verify that operational experience associated with tube corrosion was being effectively implemented. Control logic was reviewed to verify the capability of providing adequate service water flow control in order to maintain proper lube oil temperatures. Corrective action documentation was reviewed to verify that system conditions were being monitored and corrected as appropriate. Walkdowns were performed to verify that adverse material conditions were being addressed.

b. Findings

No findings of significance were identified.

.2.5 Charging Pump Seal Cooling System Surge Tank (1-CC-TK-3)

a. Inspection Scope

The team reviewed the UFSAR and DBDs to identify the level control design features and requirements of the charging pump seal cooling system surge tank. Control logic diagrams were reviewed to verify that level control met the design basis requirements. Calculations for charging pump cooling water (CPCW) pump available NPSH were reviewed to verify the level control system was providing the required water level to prevent cavitation of the CPCW pumps. CPCW pump curves were reviewed to verify adequate margin exists with respect to required NPSH. CPCW system flow calculations and modification records associated with the CPCW pumps were reviewed to verify that any component replacements had not adversely impacted the NPSH margins. Walkdowns were performed to verify that observable adverse material conditions were being addressed and that an appropriate tank level existed with respect to design calculations.

b. Findings

No findings of significance were identified.

.2.6 AFW Discharge Check Valves (1/2-FW-142, 157 and 172)

a. Inspection Scope

The team reviewed the UFSAR, DBDs and surveillance procedures to verify that the AFW pump discharge check valves could perform the required design function of preventing backflow. Completed surveillance test data was reviewed to verify that components were satisfying acceptance criteria and being properly maintained. System walkdowns were performed to verify that observable adverse material conditions were being addressed.

b. Findings

No findings of significance were identified.

.2.7 Low Pressure Injection Relief Valves (SI-RV-1845A, B and C)

a. Inspection Scope

The team reviewed the UFSAR, DBDs and work orders to verify that the low pressure safety injection pump discharge relief valves could perform the required design function of preventing over-pressurization of the low pressure safety injection discharge piping.

Design documents were reviewed to verify that the relief valve setpoints were consistent with bench test work order acceptance criteria and piping design pressure ratings. Completed bench testing results were reviewed to verify that satisfactory results were obtained and that procedural requirements associated with unsatisfactory test results were being performed. Corrective action documentation was reviewed to identify if any unanticipated relief valve lifting had occurred.

b. Findings

No findings of significance were identified.

.2.8 Reactor Coolant Pump (RCP) Thermal Barrier Cooling (CC-RV-116 and CC-TV-120)

a. Inspection Scope

The team reviewed the UFSAR, DBD's, correspondence letters and design change packages (DCPs) to identify the design requirements of the RCP thermal barrier heat exchanger CCW outlet isolation valves and the inlet pressure relief valves. Periodic testing and maintenance documents were reviewed to verify that the outlet isolation valves could perform their design function of isolating the outlet of the thermal barrier heat exchangers in the event of a tube leak to prevent contamination of the CCW system with primary water. Design documents were reviewed to verify that the selected valves' design pressures were adequate to provide proper isolation. Bench testing documentation was reviewed to verify that inlet relief valve settings were consistent with piping design pressures. Completed DCPs and current field drawings were reviewed to verify that design features were being maintained.

b. Findings

No findings of significance were identified.

.2.9 Motor Driven AFW Pumps and Motors (1/2-FW-P-3A and B)

a. Inspection Scope

The inspectors reviewed AFW system hydraulic calculations to verify that the performance and the required NPSH of the motor driven pumps were satisfied. The inspectors also reviewed the surveillance test acceptance criteria bases and test results to verify that the pumps would have sufficient capability at the minimum acceptable performance. In addition, the inspectors verified that the pumps had adequate protection for potential minimum flow and runout conditions. The inspectors reviewed the design of the pumps and associated rooms with regard to postulated high energy line breaks (HELBs) and internal missile hazards to verify that these hazards could be mitigated. The inspectors reviewed condition reports and corrective maintenance associated with the equipment to verify that degraded conditions were appropriately addressed. The inspectors also reviewed operating procedures and the control logic associated with the pumps and associated equipment to verify that the equipment was

capable of performing the intended functions. The inspectors reviewed the design of the alternate water supplies to verify the capability to provide adequate suction flow if the supply from the emergency condensate storage tank (ECST) was not available.

The inspectors reviewed pump power requirements during all postulated conditions, including runout conditions to verify that the power supplies could supply adequate power. The inspectors reviewed AC load flow and voltage calculations to verify that adequate motive power was available during worst case degraded voltage and service conditions. The inspectors reviewed wiring and logic diagrams to verify that motor control logic was consistent with the design bases. The inspectors reviewed power supply cable calculations to verify that feeder cable current limitations were not exceeded. The inspectors reviewed overcurrent protective device settings to verify that the motors were adequately protected and that they were not susceptible to spurious tripping during runout conditions. This included a review of the modification to overcurrent protection relays which allowed increased settings to account for runout conditions. The inspectors performed walkdowns of the pumps and associated equipment to verify that the configuration and material condition of the equipment was consistent with the design requirements.

b. Findings

No findings of significance were identified.

.2.10 AFW Flow Control Valves (FW-151 E and F)

a. Inspection Scope

The inspectors reviewed AC load flow and voltage calculations to verify that adequate motive power was available during worst case degraded voltage and service conditions. The inspectors reviewed motor control center (MCC) control circuit voltage drop calculations to determine whether motor-operated valve (MOV) contactors had adequate voltage to pick up when required. The inspectors reviewed wiring diagrams to verify that control logic was in conformance with the design bases.

The inspectors reviewed calculations and test data to verify the capability of these flow control valves to provide the required AFW flow to the steam generators under the most limiting accident conditions. This review included the MOV calculation inputs and results. The inspectors also reviewed the surveillance test acceptance criteria and test results to verify that the MOVs were capable of performing the intended function. The inspectors reviewed condition reports and corrective maintenance records to verify that material deficiencies were addressed appropriately. The inspectors reviewed operating procedures and the control logic associated with the equipment to verify that the valves would operate as designed. The inspectors also reviewed the operating procedures associated with manually closing the valves in the event of failure of the MOVs to remotely operate to verify that the procedures were appropriate. The inspectors performed walkdowns of the valves and associated equipment to verify that the configuration and observable material condition of the equipment was consistent with the design requirements.

b. Findings

No findings of significance were identified.

.2.11 RCP Seal Injection Isolation Valve (1-CH-MOV-1370)

a. Inspection Scope

The inspectors reviewed AC load flow and voltage calculations to verify that adequate motive power was available during worst case degraded voltage and service conditions. The inspectors reviewed MCC control circuit voltage drop calculations to determine whether MOV contactors had adequate voltage to pick up when required. The inspectors reviewed wiring diagrams to verify that control logic was in conformance with the design bases.

The inspectors reviewed calculations and test data to verify that 1-CH-MOV-1370 was capable of providing the required seal injection flow and isolation as required under the most limiting conditions. This review included the MOV calculation inputs and results. The inspectors reviewed condition reports and corrective maintenance associated with the valve. The inspectors reviewed operating procedures and the control logic associated with the equipment to verify that the valve would operate as designed.

b. Findings

No findings of significance were identified.

.2.12 EDG-1/2/3 (Electrical)

a. Inspection Scope

The inspectors reviewed static loading calculations to verify that the automatically sequenced and manual loads expected during worst case accident conditions would be within the specified ratings of the EDGs. The inspectors reviewed load sequencing logic and dynamic loading calculations to determine whether the transient loading expected during worst case conditions was within the capability of the generators. The inspectors reviewed EDG test procedures and results to determine whether they were consistent with licensing basis requirements and whether they demonstrated adequate performance. The inspectors reviewed permissible frequency variations to verify that they have been properly accounted for in equipment performance and diesel loading calculations. The inspectors reviewed EDG output breaker logic to verify that automatic functions were consistent with the design bases. The inspectors reviewed protective relay logic and set points to verify that they afforded adequate protection and would not cause spurious tripping of the EDG. The inspectors reviewed maintenance and corrective action documents to determine whether the EDGs had exhibited adverse performance trends. The inspectors performed a visual inspection of the EDGs to assess the observable material condition and the presence of hazards.

b. Findings

Introduction: The inspectors identified two examples of a Green non-cited violation (NCV) of 10 CFR 50, Appendix B, Criterion III, Design Control, for failure to evaluate variations of EDG output frequency in electrical design loading calculations, and failure to consider worst case 4160 VAC bus voltage in safety related motor starting calculations.

Description: Calculation EE-0035 determined static loading on all three EDGs for various accident and event scenarios to ensure that loads resulting from automatic and required manual actions would not exceed the ratings of the EDGs. This calculation did not make any allowance for acceptable frequency variations. An EDG output frequency higher than the nominal 60 Hz would cause an increase in real power loading on the EDGs. This is due to the fact that centrifugal loads such as pumps and fans run faster at higher frequency and therefore demand higher real power input. TS 4.6.A.1.b requires EDG testing during each reactor shutdown for refueling. Refueling outage test procedure 1-OPT-ZZ-001, ESF Actuation with Undervoltage and Degraded Voltage, allows a steady-state EDG output frequency of up to 60.33 Hz. The inspectors determined that the 0.33 Hz higher than nominal frequency allowed by test procedures would increase EDG loading by approximately 1%. This was not evaluated in the original calculations. In response to the inspector's inquiries, the licensee confirmed that sufficient margin existed to accommodate the additional loading potentially caused by acceptable frequency variations. The licensee initiated CR 091493 to revise the calculations.

In the second example, calculation EE-0034, Surry Voltage Profiles, determined the minimum voltage at the terminals of large motors that start automatically at the onset of a design basis loss of coolant accident (LOCA) for all three EDGs supplying both units. When large motors are started, the 4160 VAC bus voltage drop could be large enough to cause the degraded voltage relay to drop out. In order to stay connected to the offsite power supply, bus voltage must return above the relay reset set point prior to the expiration of the degraded voltage relay time delay. Calculation EE-0034 analyzed this scenario and applied a positive tolerance to the relay reset value, since this required a higher bus voltage (and higher corresponding switchyard voltage) for relay reset and was the limiting case for offsite power availability. However, negative tolerance of the relay reset feature which would permit a lower voltage on a 4160 VAC safety bus (and the switchyard), without transfer to the EDG was not considered. Specifically, the licensee failed to base EDG loading calculations on the worst case acceptable frequency allowed by test procedures, and failed to use worst case bus voltage afforded by the degraded voltage protection scheme in motor starting studies. This would represent a more limiting case for motor starting voltage. The licensee initiated CR 091494 to address this issue. The licensee performed subsequent analysis which demonstrated that safety related motors would still have adequate starting voltage.

Analysis: The two examples of failures to use appropriate inputs in 4160 VAC electrical design calculations were performance deficiencies. This finding is more than minor because it affects the Mitigating Systems Cornerstone objective ensuring the availability, reliability, and operability of the EDGs to perform the intended safety function during a

design basis event and the cornerstone attribute of Design Control, i.e. initial design. The inspectors assessed the finding using the SDP and determined that the finding was of very low safety significance (Green) because the deficiencies did not result in any EDG being inoperable based upon additional analysis that showed that the EDGs had sufficient margin to accommodate the increased loading due to worst case acceptably high EDG output frequency; and all safety related motor loads remained operable since they were still capable of starting with the revised worst case low voltage values. This finding was reviewed for cross-cutting aspects and none were identified since the performance deficiencies have existed since initial operation and are not indicative of current licensee performance.

Enforcement: 10 CFR 50, Appendix B, Criterion III, Design Control, states, in part, that measures shall be established to assure that applicable regulatory requirements and the design basis for structures, systems, and components are correctly translated into specifications, drawings, procedures, and instructions. Contrary to the above, the licensee failed to evaluate variations of EDG output frequency in electrical design loading calculations, and failed to consider worst case 4160 VAC bus voltage in safety related motor starting calculations. Because this finding is of very low safety significance and was entered into the licensee's corrective action program as condition report (CR) 091493 and CR 091494, this violation is being treated as a NCV, consistent with Section VI.A.1 of the NRC Enforcement Policy. This finding is identified as NCV 05000280, 05000281/2008006-01, Failure to Evaluate and Use Limiting Case 4160 VAC Bus Frequency and Voltage in Design Calculations.

.2.13 4160 VAC Transfer Bus F and Breakers 15F1, 15C1, 15H8, 25J9, and 25C1

a. Inspection Scope:

The inspectors reviewed 125VDC voltage drop calculations and battery test results to verify that circuit breaker controls would have adequate voltage to operate when required. The inspectors reviewed bus and breaker elementary diagrams to determine whether control logic was consistent with the design bases. The inspectors reviewed AC load flow and protective relay calculations to determine whether overcurrent protection was appropriate for accident loading. The inspectors reviewed system health, maintenance, and corrective action documents to determine whether the equipment had exhibited adverse performance trends.

b. Findings:

Introduction: The inspectors identified a Green NCV of 10 CFR 50, Appendix B, Criterion XI, Test Control, for incorrect acceptance criteria in test procedure 1-EPT-0106-01, Main Station Battery 1A Service Test.

Description: The inspectors identified that the licensee had accepted an incorrect acceptance criterion in a test procedure. The licensee had identified that test procedure 1-EPT-0106-01 did not evaluate battery voltage during critical periods of battery operation. Specifically, the first minute voltages were not measured. The licensee generated CR 022112 on October 10, 2007 to address this issue on all four station

battery test procedures. The licensee subsequently revised refueling outage test procedure 1-EPT-0106-01 to include recording and trending of first minute voltages. CR 022112 was then dispositioned as having been resolved. However, the procedure was revised to include an acceptance criterion of 105 volts during the first minute based on an incorrect assumption that it was acceptable for battery voltage to reach a minimum of 105 volts during the first minute of a discharge test. Calculation 07797.06-E-001, Voltage Drop Calculations for Battery Loads, took credit for a minimum of 112 volts during the first minute. Therefore, the first minute acceptance criterion of 105 volts would not have been adequate to assure the battery would supply adequate voltage to supplied loads for the required duration during a design basis event.

Analysis: The failure to use appropriate acceptance criteria for battery voltage at the one minute mark was a performance deficiency. This finding is more than minor because it affects the Mitigating Systems Cornerstone objective ensuring the availability, reliability, and operability of the station batteries to perform the intended safety function during a design basis event and the cornerstone attribute of Procedure Quality, i.e. maintenance and testing procedures. The inspectors assessed the finding using the SDP and determined that the finding was of very low safety significance (Green) because the deficiency did not result in station batteries being inoperable based upon a recent review of station battery discharge test results. Discharge test results at the one minute mark were greater than 112 volts.

The inspectors determined that the lack of a thorough evaluation of CR 022112, which addressed deficiencies in station battery test procedures such that resolutions addressed causes, was a significant cause of this performance deficiency. Failure to thoroughly evaluate problems such that resolutions address causes is directly related to the Corrective Action Program component of the cross-cutting area of Problem Identification and Resolution and the aspect of thorough evaluation of problems (P.1(c)).

Enforcement: 10 CFR 50, Appendix B, Criterion XI, Test Control, states, in part, that test programs shall be established to assure that all testing required to demonstrate that structures, systems and components will perform satisfactorily in service. Contrary to the above, the licensee did not establish adequate test control measures to assure that station batteries would perform as designed. Because this finding is of very low safety significance and was entered into the licensee's corrective action program as CR 091906. This violation is being treated as a NCV, consistent with Section VI.A.1 of the NRC Enforcement Policy. This finding is identified as NCV 05000281/2008006-02, Failure to use Appropriate Acceptance Criteria for Testing Battery Voltage at the One Minute Mark.

.2.14 RSS Transformer C (1-EP-RST-1C)

a. Inspection Scope:

The inspectors reviewed AC load flow calculations to determine whether the transformer had sufficient capacity to support its required loads under worst case accident loading and grid voltage conditions. The inspectors reviewed load tap changer design parameters, including target voltage, time delays, and operating time to determine

whether it was able to respond to prevent tripping of the under voltage relays during accident conditions. The inspectors also reviewed power sources and voltage available to the transformer tap changer. The inspectors reviewed transformer protective relaying schemes to verify that they would afford adequate protection and whether there would be any adverse interactions that would reduce system reliability. The inspectors reviewed maintenance procedures and records to determine whether maintenance was adequate to assure operability of automatic functions during accident conditions. The inspectors reviewed system health and corrective action documents to determine whether there were adverse equipment operating trends.

b. Findings:

No findings of significance were identified.

.2.15 AAC Diesel (Electrical)

a. Inspection Scope:

The inspectors reviewed the DBDs, UFSAR, AAC Diesel specifications, loading calculations, and name plate data to verify that the AAC Diesel was capable of performing the intended function. Protective relay trip setting calculations were reviewed to verify that devices were appropriately sized and coordinated. The inspectors reviewed performance and surveillance test data for the AAC Diesel to verify that applicable test acceptance criteria and test frequency requirements were satisfied and to verify that the AAC Diesel would satisfy design requirements. Component replacement histories for the AAC Diesel generator and associated relays and breakers were reviewed to verify that the equipment had not been modified in a way to degrade the capabilities of the AAC Diesel generator. Vendor manuals were reviewed to verify that vendor recommendations were implemented as appropriate. The inspectors reviewed related corrective actions to verify that appropriate actions have been taken for adverse conditions and to note any adverse trends. The inspectors conducted a field walk down of the diesel housing facility, electrical relay cabinets, output breaker control switches and breaker position indicating lights to assess observable material conditions and to verify that the installed configuration was consistent with system drawings and documentation.

b. Findings:

No findings of significance were identified.

.2.16 4160 VAC Breaker 15H7

a. Inspection Scope:

The inspectors reviewed DBDs, drawings, calculations, the UFSAR, breaker specifications and name plate data to verify that 4160 VAC breaker 15H7 was capable of performing the intended function. Logic diagrams, coordination calculations and coordination curves were reviewed to verify that breaker control logic would satisfy the

safety related functions. Short circuit and voltage drop calculations were reviewed to verify that operation and protection of the breaker would be satisfied under worst case operating conditions. The inspectors reviewed the trip characteristics and interrupting capability to verify that the breaker would be protected from postulated fault currents. The inspectors reviewed completed performance and surveillance test data for circuit breaker 15H7 to verify that applicable test acceptance criteria and test frequency requirements were satisfied and to verify that the breaker would satisfy design requirements. Component replacement histories were reviewed to verify that the equipment had not been modified in a way to degrade the capabilities of the breaker. Vendor manuals were reviewed to verify that vendor recommendations were implemented as appropriate. The inspectors reviewed related corrective actions to verify appropriate actions had been taken for adverse conditions and to note any adverse trends. A visual inspection of breaker panel 15H7 was performed to verify that output breaker control switches, breaker position indicating lights and general field conditions to assess observable material conditions and to verify that the installed configuration was consistent with system drawings and documentation.

b. Findings:

No findings of significance were identified.

.2.17 Turbine Driven AFW Pumps (1/2-FW-P-2)

a. Inspection Scope:

The inspectors reviewed AFW system hydraulic calculations to verify that the performance and the NPSH requirements of the turbine driven AFW pumps were satisfied. The inspectors also reviewed the surveillance test acceptance criteria bases and test results to verify that the pumps would have sufficient capability at their minimum acceptable performance. In addition, the inspectors reviewed the potential of the pumps causing an over-pressure condition in the downstream piping due to a postulated over-speed condition and verified that the pumps had adequate protection for potential minimum flow and runout conditions. The inspectors reviewed the design of the pumps and associated rooms with regard to postulated HELBs and internal missile hazards to verify that these hazards could be mitigated. The inspectors reviewed condition reports and corrective maintenance associated with the equipment to verify that degraded conditions were appropriately addressed. The inspectors also reviewed operating procedures and the control logic associated with the pumps and associated equipment to verify that the equipment was capable of performing the intended functions.

The inspectors reviewed the design of the alternate water supplies to verify the capability to provide adequate suction flow if the supply from the ECST was not available. The inspectors also reviewed the steam supply to the pumps and the capacity of the pumps to verify that the pumps could operate with minimum steam pressure. The inspectors performed walk downs of the pumps and associated equipment to verify that the configuration and observable material condition of the equipment was consistent with the design requirements.

b. Findings:

No findings of significance were identified.

.2.18 Emergency Condensate Storage Tank (1-CN-TK-1)

a. Inspection Scope:

The inspectors reviewed AFW system calculations to verify that the capacity and level of the ECST would satisfy system requirements. The inspectors also reviewed tank level setpoints to verify that the ECST would have sufficient capacity to support the AFW system under the most limiting design basis conditions when considering instrument uncertainties, allowance for vortexing, and operator action times. The inspectors reviewed the design of the tank and associated piping to verify that postulated HELBs and internal missile hazards were addressed appropriately. The inspectors reviewed condition reports and corrective maintenance associated with the ECST to verify that adverse material conditions were addressed appropriately. The inspectors also reviewed operating procedures associated with the tank and associated equipment to verify that they supported the intended functions.

The inspectors reviewed the design of the alternate water supplies to verify the capability to provide adequate suction flow if the supply from the ECST was not available. This review included piping located in the turbine building. The inspectors performed walkdowns of the ECST and associated equipment to verify that the configuration and observable material condition of the equipment was consistent with the design requirements.

b. Findings:

No findings of significance were identified.

.2.19 AFW Cross-Connect Valves (2-FW-MOV-260A/B)

a. Inspection Scope:

The inspectors reviewed AC load flow and voltage calculations to verify that adequate motive power was available during worst case degraded voltage and service conditions. The inspectors reviewed MCC control circuit voltage drop calculations to determine whether MOV contactors had adequate voltage to pick up when required. The inspectors reviewed wiring and logic diagrams to verify that control logic was in conformance with the design bases.

The inspectors reviewed calculations and test data to verify the capability of these cross-connect valves to provide AFW flow from the Unit 1 AFW pumps to the Unit 2 steam generators under the most limiting conditions. This review included the MOV calculation inputs and results. The inspectors also reviewed the surveillance test acceptance criteria and test results to verify that the MOVs were capable of performing the intended function. The inspectors reviewed operating procedures and the control logic associated

with the equipment to verify that the valves would operate as designed. The inspectors also reviewed the operating procedures associated with manually closing the valves in the event of failure of the MOVs to remotely operate to verify that the procedures were appropriate. The inspectors performed walkdowns of the valves and associated equipment to verify that the configuration and observable material condition of the equipment was consistent with the design requirements.

b. Findings:

Introduction: The inspectors identified a Green NCV of 10 CFR 50, Appendix B, Criterion III, Design Control, for failure to evaluate the most limiting differential pressure (dP) for opening valve 2-FW-MOV-260A.

Description: The inspectors reviewed engineering transmittal ET-CME-04-0018, Evaluate Potential Impact if Coefficient of Friction (COF) is assumed to be 0.20, which evaluated higher than expected COF values being discovered during MOV testing. This transmittal addressed the capability of motor operated valves, including 2-FW-MOV-260A, to operate with increased COF values. In the case of 2-FW-MOV-260A, the original calculations were based on opening the valve with an assumed COF of 0.15 and a maximum dP of 1440 psid. However, engineering transmittal ET-CME-04-0018, performed in 2007, addressed a maximum COF of 0.213 (based on August 2001 as-left test data) and assumed a maximum dP of only 500 psid. This engineering transmittal also referred to a previous engineering transmittal (ET-CME-01-0024, Evaluation of Negative Jog Margin Values due to Inclusion of Rate of Loading (ROL) and Stem Lubrication Degradation Corrections) that had used an assumed dP of 1000 psid. The inspectors noted that the reduced dP values did not appear sufficient to account for opening this valve with the AFW pumps in operation and questioned the bases of these values. Specifically, the licensee failed to base the maximum dP for opening 2-FW-MOV-260A on the worst case high value which would occur in the event of a HELB or fire causing a loss of AFW flow on Unit 2 concurrent with an automatic start signal of AFW pumps in Unit 1.

The licensee initiated CR 091698 on February 25, 2008 in response to this concern. The condition report stated that the assumed dP values were non-conservative and that the engineering transmittals had failed to recognize that the AFW pumps would automatically start in the event of a loss of off-site power (LOOP) event. Specifically, the existing design analyses did not fully address the required capability of valve 2-FW-MOV-260A to provide AFW flow from Unit 1 to Unit 2 in the event of a postulated HELB or fire which caused a loss of AFW on Unit 2. The CR also stated that 2-FW-MOV-260A may not have been capable of performing its design function. The licensee declared the valve inoperable at that time. During the inspection, the licensee performed an actuator overhaul to replace the torque carrying components that could have been fatigued due to previous testing with high dP. Subsequent analysis concluded that the valve would have been capable of opening against the maximum dP under accident conditions.

Analysis: The failure to evaluate valve 2-FW-MOV-260A to be capable of opening against the most limiting maximum dP of 1440 psid was a performance deficiency. This finding is more than minor because it affects the Mitigating Systems Cornerstone

objective ensuring the availability, reliability, and operability of the AFW system to perform the intended safety function during a design basis event and the cornerstone attribute of Design Control, i.e. initial design and plant modifications. The inspectors assessed the finding using the SDP and determined that the finding was of very low safety significance (Green) because the deficiency did not result in 2-FW-MOV-260A being inoperable based upon additional analysis which showed that the MOV had sufficient margin to accommodate opening against the worst case high dP.

The inspectors determined that the maintenance of design margins was a significant cause if this performance deficiency. Failure to maintain design margins is directly related to the Resources component of the cross-cutting area of Human Performance and the aspect of maintenance of plant safety by the maintenance of design margins (H.2(a)).

Enforcement: 10 CFR 50, Appendix B, Criterion III, Design Control, states, in part, that measures shall be established to assure that applicable regulatory requirements and the design basis for structures, systems, and components are correctly translated into specifications, drawings, procedures, and instructions. Contrary to the above, the licensee failed to use limiting inputs in design calculations. Because this finding is of very low safety significance and was entered into the licensee's corrective action program as CR091698 this violation is being treated as a NCV, consistent with Section VI.A.1 of the NRC Enforcement Policy. This finding is identified as NCV 05000280, 05000281/2008006-03, Failure to Use Limiting Case High dP in 2-FW-MOV-260A Design Calculations.

.3 Review of Low Margin Operator Actions

a. Inspection Scope

The team performed a margin assessment and detailed review of five risk significant and time critical operator actions. Where possible, margins were determined by the review of the assumed design basis and UFSAR response times and performance times documented by job performance measures (JPMs). For the selected components and operator actions, the team performed an assessment of the Emergency Operating Procedures (EOPs), Abnormal Operating Procedures (AOPs), Alarm Panel Procedures (APPs), and other operations procedures to determine the adequacy of the procedures and availability of equipment required to complete the actions. Operator actions were observed on the plant simulator and during plant walk downs.

The following operator actions were observed on the licensee's operator training simulator:

- Actions for a LOCA outside containment per 1-ECA-1.2, LOCA Outside Containment
- Actions to align alternate AC sources; transfer EDG 3 from unit 2 to unit 1 per 1-ECA-0.0, Loss of All AC Power, and loading 1J bus onto the AAC Diesel per 0-AP-17.06, AAC Diesel Generator - Emergency Operations

- Actions to initiate gravity feed cooling from the refueling water storage tank on a loss of residual heat removal cooling per 1-AP-27.00, Loss of Decay Heat Removal Capability, Attachment 8, Gravity Feed Cooling

Additionally, the team walked down, “table-topped” and investigated the following operational scenarios:

- Turbine Driven AFW pump operation during a loss of all AC and DC power, including alignment of alternate power from the portable generator per LFFG2, Large Fire, Flood Mitigation Guidelines TSC Response
- Alignment of backup sources for AFW suction per 1-FR-H.1, Response to Loss of Secondary Heat Sink, Attachment 1, Alternate AFW Sources

b. Findings

No findings of significance were identified.

.4 Review of Industry Operating Experience

a. Inspection Scope

The team reviewed selected operating experience issues that had occurred at domestic and foreign nuclear facilities for applicability at the Surry Power Station. The team performed an independent applicability review for issues that were identified as applicable to the Surry Power Station and were selected for a detailed review. The issues that received a detailed review by the team included:

- IN 86-14, Overspeed Trips of HPCI, RCIC and AFW Turbines
- IN 88-70, Check Valve In-Service Testing Program Deficiencies
- IN 00-21, Detached Check Valves Disc not detected by the use of Acoustic and Magnetic Non-Intrusive Test Techniques
- IN 2006-026, Failure of Magnesium Rotors in Motor-operated Valve Actuators

b. Findings

No findings of significance were identified.

.5 Review of Permanent Plant Modifications

a. Inspection Scope

The team reviewed one modifications related to the selected risk significant components in detail to verify that the design bases, licensing bases, and performance capability of the components have not been degraded through modifications. The adequacy of design and post modification testing of these modifications was reviewed by performing activities identified in IP 71111.17, Permanent Plant Modifications, Section 02.02.a. Additionally, the team reviewed the modifications in accordance with IP 71111.02, Evaluations of

Changes, Tests, or Experiments, to verify the licensee had appropriately evaluated them for 10 CFR 50.59 applicability. The following modification was reviewed:

- DCP 06-007, Emergency Switchgear Room – Chilled Water System – Trench Piping Replacement and DCP 07-007, Control Room AC CC Pipe Replacement Phase I & II

b. Findings

No findings of significance were identified.

4. OTHER ACTIVITIES

4OA6 Meetings, Including Exit

Exit Meeting Summary

On February 29, 2008, the team presented the inspection results to Mr. Don Jernigan, Surry Power Station Site Vice President, and other members of the licensee staff. The team returned all proprietary information examined to the licensee. No proprietary information is documented in the report.

4OA7 Licensee-Identified Violations

The following violations of very low safety significance (Green) were identified by the licensee and are violations of NRC requirements which meet the criteria of Section VI of the NRC Enforcement Policy, NUREG-1600, for being dispositioned as NCVs.

- 10 CFR 50, Appendix B, Criterion III, Design Control, requires that that measures shall be established to assure that applicable regulatory requirements and the design basis for structures, systems, and components are correctly translated into specifications, drawings, procedures, and instructions. UFSAR Table 15.2-1 lists the AFW pumps as being components that will not fail during a tornado since they are protected by tornado resistant structures. Contrary to this, turbine drive AFW pumps 1/2-FW-P-2 were not completely protected in that the steam exhausts from the turbines could have been blocked by tornado missile damage. This was identified in the licensee's corrective action program as CR 001132. The inspectors assessed the finding using the SDP and determined that the finding was of very low safety significance (Green) because it involved a severe weather initiating event and did not degrade more than one train of a multi-train safety system.

ATTACHMENTS: SUPPLEMENTAL INFORMATION

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee Personnel

T. Arnett, Rapid Response Electrical Engineer
B. Garber, Supervisor, Licensing
L. Gordon, Component Engineering
F. Grover, Manager, Operations
A. Harrow, Supervisor, Electrical Systems Engineering
M. Haduck, Outage Coordinator
J. Hartka, Unit Supervisor
E. Hendrixson, Director, Engineering-Surry
L. Hilbert, Manager Oversight
D. Ingell, Mechanical Design Engineer
D. Jernigan, Site Vice President
L. Jones, Manager, RP/Chemistry
M. Kacmarcik, Rapid Response Mechanical Engineer
P. Kershner, Engineer, Licensing
B. McCloskey, Mechanical Design Engineer
J. McGinnis, Component Engineering
R. Portlock, I&C Technician
J. Rosenberger, Maintenance Manager
D. Schappell, Manager, Nuclear Site Services
E. Shore, Supervisor, Mechanical Design (Inns)
C. Silcox, Systems Engineer
K. Sloane, Surry Power Station Nuclear Plant Manager
K. Stacy, Procedure Writer
M. Wilda, Supervisor, Component Engineering
M. Wilson, Manager, Nuclear Training

NRC

C. Welch, Senior Resident Inspector, Surry Power Station
D. Merzke, Acting Resident Inspector, Surry Power Station

LIST OF ITEMS OPENED, CLOSED, AND REVIEWED

Opened

05000280/2008006, 05000281/2008006-01	NCV	Failure to Evaluate and Use Limiting Case 4160 VAC Bus Frequency and Voltage in Design Calculations (Section 1R21.2.12)
05000280/2008006, 05000281/2008006-02	NCV	Failure to Use Appropriate Acceptance Criteria for Testing Battery Voltage at

2

the One Minute Mark (Section
1R21.2.13)

05000281/2008006-03

NCV Failure to Use Limiting Case High dP In
2-FW-MOV-260A Design Calculations
(Section 1R21.2.19)

LIST OF DOCUMENTS REVIEWED

Design Basis Documents and System Descriptions

SDBD-SPS-AFW, System Design Basis Document for Auxiliary Feedwater System, Rev.14
 SDBD-SPS-CH, System Design Basis Document for Chemical and Volume Control System, Rev. 5
 SDBD-SPS-EG, System Design Basis Document for Emergency Diesel Generator System Surry Power Station, Rev. 12
 SDBD-SPS-EP, System Design Basis Document Emergency Power System Surry Power Station, Rev. 10
 SDBD-SPS-SI, System Design Basis Document for Safety Injection System Surry Power Station, Rev. 13
 Virginia Electric and Power Company Surry Power Station Units 1 and 2 Station Blackout (SBO) Alternative Design, Serial No. 93-292, 05/10/1993

Procedures

0-AP-10.18, Response to Grid Instability (With 2 Attachments), Rev. 7
 0-AP-17.06, AAC Diesel Generator-Emergency Operations, Rev.19
 0-DRP-SBO, Attachment 20, 0-BFO-LI-3A/3B, Fuel Oil Day Tank Level Meter Calibration Data, Rev. 1
 0-DRP-SBO, Attachment 21, 0-BFO-LT-3, Fuel Oil Day Tank Level Transmitter Calibration Data, Rev. 1
 0-ECM-0302-03, 480 Volt K-Line Breaker Maintenance, Rev. 40
 0-ECM-0303-01, 4160 Volt Breaker Maintenance, Rev. 35
 0-FCA-14.00, Establishing Stable RCS Makeup Flowpaths, Rev. 6
 0-MOP-AAC-001, Removal from Service of the AAC Diesel Generator, Rev. 12
 0-MOP-AAC-002, Return to Service of the AAC Diesel Generator, Rev. 13
 0-MCM-1005-01, Rotating Spectacle Flange Closed or Open, Rev. 5
 0-OP-AAC-001, AAC Diesel Generator Operation, Rev. 15
 0-OPT-ZZ-012, Dynamic Voltage and Frequency Testing of EDG-3, Rev. 10
 0-OSP – AAC- 001, Quarterly Test Of 0-AAC-DG0M, Alternate AC Diesel Generator, Rev. 22
 1-AP-27.00, Loss of Decay Heat Removal Capability, Attachment 8, Gravity Feed Cooling, Revs. 15, 16 and 17
 1-AP-8.00, Loss of Normal Charging Flow, Rev. 9
 1-AP-9.02, Loss Of RCP Seal Cooling, Rev. 11
 1-E-0, Reactor Trip or Safety Injection, Rev. 58
 1-E-1, Loss of Reactor or Secondary Coolant, Rev. 28
 1-E-2, Faulted Steam Generator Isolation, Rev. 13
 1-E-3, Steam Generator Tube Rupture, Rev. 35
 1-ECA-0.0, Loss of All AC Power, Rev. 28
 1-ECA-0.1, Loss of All AC Power Recovery Without SI Required, Rev. 17
 1-ECA-0.2, Loss of All AC Power Recovery With SI Required, Rev. 14
 1-ECA-1.2, LOCA Outside Containment, Rev. 6
 1-EPT-0106-01, Main Station Battery 1A Service Test, Rev. 15
 1-FR-H.1, Response to Loss of Secondary Heat Sink, Rev. 24
 1-GOP-1.3, Unit Startup, RCS Heatup From 345°F To HSD, Rev. 39

1-GOP-2.5, Unit Cooldown, 351°F To Less Than 205°F, Rev. 24
 1-MOP-FW-002, Removal from and Return to Service of Turbine Driven AFW Pump 1-FW-P-2, Rev. 8
 1-MOP-FW-003, Removal from and Return to Service of AFW Pumps 1-FW-P-3A and 1-FW-P-3B, Rev. 6
 1-OPT-FW-001, Motor Driven Auxiliary Feedwater Pump 1-FW-P-3A, Rev. 23
 1-OPT-FW-001, Motor Driven Auxiliary Feedwater Pump 1-FW-P-3A, Rev. 26
 1-OPT-FW-002, Motor Driven Auxiliary Feedwater Pump 1-FW-P-3B, Rev. 21
 1-OPT-FW-002, Motor Driven Auxiliary Feedwater Pump 1-FW-P-3B, Rev. 25
 1-OPT-FW-003, Turbine Driven Auxiliary Feedwater Pump 1-FW-P-2, Rev. 31
 1-OPT-FW-003, Turbine Driven Auxiliary Feedwater Pump 1-FW-P-2, Rev. 34
 1-OPT-FW-004, AFW Valve Position Verifications, Rev. 4
 1-OPT-FW-006, Auxiliary Feedwater MOV Test, Rev. 11
 1-OPT-FW-008, AFW Check Valve Operability, Rev. 17
 1-OPT-FW-010, Turbine Driven AFW Pump Steam Supply Line SOV Operability Test, Rev. 12
 1-OPT-ZZ-001, ESF Actuation with Undervoltage and Degraded Voltage – 1H Bus, Rev. 24
 1-OPT-ZZ-012, Dynamic Voltage and Frequency Testing of EDG-1, Rev. 9
 2-FCA-5.00, Limiting Safeguards Area Fire, Rev. 11
 2-FR-H.1, Response to Loss of Secondary Heat Sink, Rev. 26
 2-OPT-FW-006, Auxiliary Feedwater MOV Test, Rev. 8
 2-OPT-ZZ-012, Dynamic Voltage and Frequency Testing of EDG-2, Rev. 7
 Annunciator Response Procedure 1B-F3, SFGDS Area Sump HI LVL, Rev. 1
 Annunciator Response Procedure 1J-F4, 110,000 GAL LO LEVEL, Rev. 3
 DNAP-3002, Dominion Nuclear Operating (OE) Program, Rev. 1
 ER-AA-102, Preventive Maintenance Program, Rev. 0
 ER-SU-5402, Periodic Test/Scheduling System Program, Rev. 0
 LFFG1, Surry Power Station Large Fire, Flood Mitigating Guidelines, Rev. 1
 LFFG2, Surry Power Station Large Fire, Flood Mitigating Guidelines, Rev. 3
 LFFG2, Large Fire, Flood Mitigation Guidelines TSC Response, Rev. 3
 SU-M-DSE-611, Surry Switchyard RSST “C” LTC and Transformer Maintenance, Rev. 6
 SU-M-DSE-616, RSST “C” LTC Controller Maintenance, Rev. 3
 SU-M-DCO-807H, Surry Switchyard – Train “A” (1H Bus) – SI/CDA Load Shed Reserve Transformer Step Timing Test, Rev. 0
 VPAP-1101, Test Control, Rev. 6
 VPAP-1102, Periodic Testing, Rev. 7

Completed Test Procedures

0-OPT-ZZ-012, Dynamic Voltage and Frequency Testing of EDG 3, Rev. 10, performed on October 15, 2006
 0-OPT-ZZ-012, Dynamic Voltage and Frequency Testing of EDG 3, Rev. 10, performed on October 24, 2007
 1-OPT-SI-007, Refueling Test of HHSI Check Valves to Cold Legs, Rev. 15, performed on May 8, 2006
 1-OPT-SI-007, Refueling Test of HHSI Check Valves to Cold Legs, Rev. 16, performed on October 30, 2007
 1-OPT-SI-007, Refueling Test of HHSI Check Valves to Cold Legs, Rev. 16, performed November 14, 2007

1-OPT-SI-012, Refueling Test of LHSI lines to Charging Pumps, Rev. 14, performed on November 15, 2007
 1-OPT-ZZ-012, Dynamic Voltage and Frequency Testing of EDG 1, Rev. 009, performed on May 17, 2006
 1-OPT-ZZ-012, Dynamic Voltage and Frequency Testing of EDG 1, Rev. 009, performed on October 25, 2007
 2-OPT-SI-007, Refueling Test of HHSI Check Valves to Cold Legs, Rev. 11, performed on October 20, 2006
 2-OPT-ZZ-012, Dynamic Voltage and Frequency Testing of EDG 2, Rev. 007, performed on April 27, 2005
 2-OPT-ZZ-012, Dynamic Voltage and Frequency Testing of EDG 2, Rev. 007, performed on October 16, 2006
 0-OSP-AAC-001, Quarterly test of 0-AAC-DG-0M, Alternate AC Diesel Generator, Rev. 19, performed on February 14, 2007, May 3, 2007, June 23, 2007, and October 21, 2006

Drawings

11448-ESK-3A, Elementary Diagram Control Switch Contact Diagram Surry Power Station – Unit 1, Rev. 5
 11448-ESK-3B, Control Switch Contact Diagrams Surry Power Station Unit 1, Rev. 2
 11448-ESK-5A, Elementary Diagram 4160-480 Substation Supply ACB's Surry Power Station Unit 1, Rev. 7
 11448-ESK-5K, Elementary Diagram 4160V Aux Stm Gen Feed Pumps Surry Power Station – Unit 1, Rev. 28
 11448-ESK-5K1, Elementary Diagram Aux Steam Generator Feed Pumps Surry Power Station – Unit 1, Rev. 6
 11448-ESK-6BF, Elementary Diagram 480V Circuit Motor Operated Valves 02-FW-MOV-260A & B Surry Power Station – Unit 1, Rev. 10
 11448-ESK-6BM, Elementary Diagram 480V Circuit Motor Operated Valves 1-SI-MOV-1842 & 01-CH-MOV-1370 Surry Power Station – Unit 1, Rev. 26
 11448-ESK-6BY, Elementary Diagram 480V Circuits Motor Operated Valves 01-FW-MOV-151E & F Surry Power Station – Unit 1, Rev. 18
 11448-ESK-11AA, Elementary Diagram Bus H Degraded and Undervoltage Sensing Surry Power Station – Unit 1, Rev. 7
 11448-ESK-11AA1, Elementary Diagram Surry Power Station – Unit 1, Rev. 2
 11448-ESK-11AB, Elementary Diagram Bus H Degraded and Undervoltage Protection Surry Power Station – Unit 1, Rev. 11
 11448-ESK-11AC, Elementary Diagram Bus H Degraded and Undervoltage Protection Surry Power Sta., Rev. 7
 11448-ESK-11AD, Elementary Diagram Bus J Degraded and Undervoltage Sensing Surry Power Station – Unit 1, Rev. 9
 11448-ESK-11AD1, Elementary Diagram Surry Power Station – Unit 1, Rev. 2
 11448-ESK-11AE, Elementary Diagram Bus J Degraded and Undervoltage Protection Surry Power Station – Unit 1, Rev. 14
 11448-ESK-11AF, Elementary Diagram Bus J Degraded & Undervoltage Protection Surry Power Sta., Rev. 6
 11448-FB-4C, Yard Fuel Oil Lines, Rev. 12
 11448-FB-038B, Fuel Oil Lines, Rev. 45

11448-FE-1A, Main One Line Diagram Surry Power Station – Unit 1, Rev. 27
 11448-FE-1A1, 4160 Volt System Unit 1 & 2 Surry Power Station, Rev. 18
 11448-FE-1A2, Electric Power Distribution One Line Integrated Schematic Surry Power Station, Rev. 26
 11448-FE-2E, Wiring Diagram Reserve Station Service and Intake Structure Transformers Surry Power Station – Unit 1, Rev. 17
 11448-FE-1A3, One Line Diagram Switchyard Layout Surry Power Station – Unit 1 & 2, Rev. 3
 11448-FE-1B, One Line Diagram 4160V Bus 1A & 1B 4160V Transfer Bus D & E Surry Power Station – Unit 1, Rev. 26
 11448-FE-1C, One Line Diagram 4160V Bus 1C & 1D 4160V Transfer Bus F Surry Power Station – Unit 1, Rev. 21
 11448-FE-1D, 4160V One Line Diagram Surry Power Station – Unit 1, Rev. 19
 11448-FE-1F, 480V One Line Diagram Surry Power Station – Unit 1, Rev. 23
 11448-FE-1L, 480V One Line Diagram Surry Power Station – Unit 1, Rev. 58
 11448-FE-1M, 480V One Line Diagram Surry Power Station – Unit 1, Rev. 67
 11448-FE-1P1, 480V One Line Diagram MCC 1J1-1A Surry Power Station – Unit 1, Rev. 67
 11448-FE-1Q, 480V One Line Diagram Emergency Switchgear 1H1 & 1J1 Surry Power Station – Unit 1, Rev. 11
 11448-FE-1X, 4160 One Line Diagram AAC System – Bus 0L Surry Power Station Unit 1, Rev. 1
 11448-FE-1Y, 4160 One Line Diagram AAC System – Bus 0M Surry Power Station Unit 1, Rev. 0
 11448-FE-1Z1, 480 Low Voltage Switchgear 0M1 Surry Power Station Unit 1, Rev. 0
 11448-FE-1Z2, AAC 125 V DC Surry Power Station Unit 1, Rev. 0
 11448-FE-1Z, 480 Volt MCC 0M1-1 Surry Power Station Unit 1, Rev. 0
 11448-FE-18V, Wiring Diagram Miscellaneous Circuits Surry Power Station – Unit 1, Rev. 14
 11448-FE-19AB Sheet 1 of 2, Elementary Diagram Emergency Diesel Generator No. 1 Generator Controls Surry Power Station – Unit 1, Rev. 10
 11448-FE-19AB, Elementary Diagram Emergency Diesel Generator No. 1 Generator Controls Surry Power Station – Unit 1, Rev. 10
 11448-FE-19AJ Sheet 1 of 2, Elementary Diagram Emergency Diesel Generator No. 3 Generator Controls Surry Power Station – Unit 1, Rev. 11
 11448-FE-21B, AC Elementary Diagram Station Service Transformers Surry Power Station – Unit 1, Rev. 14
 11448-FE-21BA, Elementary Diagram Reserve Station Service Transformer A Surry Power Station – Unit 1, Rev. 1
 11448-FE-21BB, Elementary Diagram Reserve Station Service Transformer B Surry Power Station – Unit 1, Rev. 1
 11448-FE-21BC, Elementary Diagram Reserve Station Service Transformer C LTC and Aux Control Cabinet, Rev. 1
 11448-FE-21C, AC Elementary Diagram Station Res. S.S & Intake Struct Trans Surry Power Station – Unit 1, Rev. 12
 11448-FE-21H, Elementary Diagram 4160V Circuits Surry Power Station – Unit 1, Rev. 11
 11448-FE-21J, Elementary Diagram 4160V Circuits Surry Power Station – Unit 1, Rev. 20
 11448-FE-21K, Elementary Diagram 4160V Circuits Surry Power Station – Unit 1, Rev. 20
 11448-FE-21Q, Elementary Diagram 4160V Bus 1H Bkr 15H3 & 15H8 Surry Power Station – Unit 1, Rev. 9

11548-FE-19AB, Elementary Diagram Emergency Diesel Generator No. 2 Generator Controls
 Surry Power Station – Unit 1, Rev. 9
 11548-FE-21H, Elementary Diagram 4160V Circuits Surry Power Station – Unit 1, Rev. 17
 11548-FE-21J, Elementary Diagram 4160V Circuits Surry Power Station – Unit 1, Rev. 19
 11548-FE-21Q, Elementary Diagram 4160V Bus 1H Bkr 25H3 & 25H8 Surry Power Station –
 Unit 1, Rev. 12
 11448-FM-046A Sheet 1 of 3, Emergency Diesel Generator #1, Rev. 20
 11448-FM-046A Sheet 2 of 3, Emergency Diesel Generator #1, Rev. 20
 11448-FM-071B Sheet 1 of 2, Circulating and Service Water System, Rev. 52
 11448-FM-071B Sheet 2 of 2, Circulating and Service Water System, Rev. 36
 11448-FM-072A Sheet 4 of 7, Component Cooling Water system, Rev. 23
 11448-FM-075C, Flow/Valve Operating Numbers Diagram Compressed Air System, sheet 3,
 Rev. 32
 11448-FM-084A, Sheet 1, Flow/Valve Operating Numbers Diagram Containment Spray System
 Surry Power Station Unit 1 Virginia Power, Rev. 41
 11448-FM-086A, Sheet 1, Flow/Valve Operating Numbers Diagram Reactor Coolant System
 Surry Power Station Unit 1 Virginia Power, Rev. 25
 11448-FM-086A, Sheet 2, Flow/Valve Operating Numbers Diagram Reactor Coolant System
 Surry Power Station Unit 1 Virginia Power, Rev. 35
 11448-FM-086A, Sheet 3, Flow/Valve Operating Numbers Diagram Reactor Coolant System
 Surry Power Station Unit 1 Virginia Power, Rev. 44
 11448-FM-088B, Sheet 2, Flow/Valve Operating Numbers Diagram Chemical & Volume Control
 System Surry Power Station Unit 1 Virginia Power, Rev. 42
 11448-FM-088B Sheet 3 of 3, Chemical and Volume Control System, Rev. 14
 11448-FM-088C, Sheet 1, Flow/Valve Operating Numbers Diagram Chemical & Volume Control
 System Surry Power Station Unit 1 Virginia Power, Rev. 23
 11448-FM-089A, Sheet 1, Flow/Valve Operating Numbers Diagram Safety Injection System
 Surry Power Station Unit 1 Virginia Power, Rev. 57
 11448-FM-089A, Sheet 3, Flow/Valve Operating Numbers Diagram Safety Injection System
 Surry Power Station Unit 1 Virginia Power, Rev. 48
 11448-FM-089B, Sheet 4, Flow/Valve Operating Numbers Diagram Safety Injection System
 Surry Power Station Unit 1 Virginia Power, Rev. 23
 11448-FM-089A Sheet 1 of 3, Safety Injection System, Rev. 57
 11448-FM-089A Sheet 2 of 3, Safety Injection System, Rev. 52
 11448-FM-089B Sheet 4 of 4, Safety Injection System, Rev. 23
 11448-FV-36A, Underground Fuel Oil Storage Tanks, Rev. 5
 C759C464, Centrifugal Pump Characteristics Rev. 1, June 4, 1981
 S-92052-3-V-810, Virginia Power Surry Power Station Diesel Generator Installation Fuel Oil
 Tank, Rev. 2

Calculations

07797.06-E-001, 125VDC Voltage Drop Calculation for Selected Safety Related and Non-safety
 Related Components, Rev. 0
 07797.15-E-001, Calculation of Cable Ampacities for 4kV Loads, Rev. 0, Add. 00B
 01039.1010-M-9, Nitrogen Accumulator Size for MS Admission Valve for TDAFW Pump, Rev. 0
 1039.3410-M-002, EDG Underground Fuel Oil Storage Tank 7 Day Usable Fuel Oil Supply,
 Rev. 0

1039.3410-M-3, EDG Base and Day Tank 3 Hour Usable F.O. Supply, Rev. 0
 9087-ES-1, Emergency Diesel Generator High Temperature Operation and Instrument Setpoints, June 29, 1993
 10139.3410-M-006, Fuel Oil Pumping Requirements from the Underground Storage Tanks to the Day Tanks, Rev. 0
 11448-292N, Charging Pump Cooling Water Pump, October 6, 1969
 13930.09-4, Voltage Drop Calculations for Class 1E Motor Loads, Rev. 1
 14257.29-E-1, Consolidation of MCC Control Circuit Calculations, Rev. 0, Add. 0A
 14257.29-E-1, MCC Control Circuit Voltage Drop, Rev. 0, Add. 00B
 14937.28-M-4, Emergency Condensate Storage Tank – Volume and Design Basis Check and Process & Instrument Location, Rev. 0
 EE-0029, Surry Station Electrical Load List, Rev. 1
 EE-0034, Surry Voltage Profiles, Rev. 3
 EE-0035, Emergency Diesel Generator Loading Analysis, Rev. 2, Add. 00D
 EE-0050, Equipment Response Times for Loss of Voltage Condition, Rev. 0, Add. 00E
 EE-0104, Loop Uncertainty Calculation for Emergency CST Level Indication, Rev. 0, Add. 00B
 EE-0315, Surry Reserve Station Transformer and Bus Protective Relay Setting Calculations, Rev. 0
 EE-0335, Completion of Setpoint Changes, Rev. 0, Addendum 00D
 EE-0335, EDG Negative Sequence Withstand Capability, Rev. 0
 EE-0335, Relay Setting of Feeder Breakers on 1H and 1J, Rev. 0, Addendum F
 EE-0335, Relay Setting of Feeder Breakers 1H and 1J, Rev. 0, Addendum 00G
 EE-0335, Reset 15H7 and 15J7, Rev. 0, Addendum 0C
 EE-0385, 4160V Undervoltage Relays Types SLV and NGV CSA, Rev. 1
 EE-0497, SR 480V Load Center Coordination, Rev. 2, Addendum 00B
 EE-501, Motor Terminal Voltage for Motor Operated Valves, Rev. 1, Add. 00K
 EE-502, 4.16kV Degraded Voltage & Loss of Voltage Relay Safety Limits, Rev. 1
 EE-0777, Surry ETAP Impedance Model, Rev. 0
 ME-0211, Thrust Band Calculation for Surry Safety Related Motor Operated Valves, Rev. 3
 ME-0229, Charging Pump Lube Oil Cooler Performance Capability, Rev. 0
 ME-0406, Evaluation of the Design Flow Requirements to the Charging Pump Seal Coolers and the Charging Pump Intermediate Seal Coolers, Rev. 0
 ME-0415, SBO Diesel Day Tank Level vs. Useable Fuel, Rev. 0
 ME-0415, Addendum 00A, SBO Diesel Day Tank Level vs. Useable Fuel, Rev. 0
 ME-0422, Charging Pump Lube Oil Cooler Heat Duty Analysis Addendum A/B, Rev. 0
 ME-0561, Emergency Diesel Generator Day Tank 1 Hour Fuel Oil Requirements, Rev. 0
 ME-0572, TDAFW Pump Operation at the Point the RHR System is Placed in Service (Surry Only), Rev. 0, Add. 00B
 ME-0597, Minimum Delivered AFW Flow and Acceptance Criteria for AFW Pump Operability Verification Testing, Rev. 4
 ME-0602, Maximum AFW Flow to the Steam Generators during a MSLB Event and AFW Pump NPSH Analysis, Rev. 1
 ME-0603, EDG 7 Day Fuel Oil Requirements, Rev. 0
 ME-0609, Charging Pump Cooling Water Pump Hydraulic Model, May 21, 2001
 ME-0665, Turbine Driven AFW Pump Maximum Overspeed Trip Setpoint, Surry 1 & 2, Rev. 1
 ME-0807, Maximum AFW Pump Flow and NPSHr Analysis for One AFW Pump Delivering Flow to Three Low Pressure Steam Generators, Rev. 1

ME-0813, Maximum AFW Pump Flow and NPSHr Analysis for One AFW Pump Delivering Flow to Two Low Pressure Steam Generators, Rev. 1
 SEO-1298, Diesel Fuel Oil Tanks Volume Table Calculation, Rev. 0
 SEO-1706, High Head Safety Injection Minimum Safety Flow Requirements, Rev. 0
 SEO-1793, CC Pump for CH Seal Cooling System Analysis, March 30, 1994
 SM-589, Emergency Condensate Storage Tank Sizing Calculations , Rev.1
 SM-970, RETRAN Boiloff Calculation to Support Loss of RHR Abnormal Procedure Guidance, Surry and North Anna Power Station, Rev. 1
 SM-0979, Reanalysis of the Surry Main Steamline Break Event Using the RETAN Model Version 1, Rev. 0

Corrective Action Documents

CR001000, Turbine Driven AFW Pump High Flow Issue
 CR001231, 1/2-FW-MOV-160A/260A May not Close IAW Caution Note in 1/2-OPT-FW-008
 CR001555, Measured COF Higher than the Default COF Assumed in Thrust Limits and Margin
 CR002056, 1-EE-RLY-PPD and 2-EE-RLY-PFDA2 relays require failure analysis, 10/04/2006
 CR002066, Unit 1 and 2 TDAFW Pump Steam Exhaust Missile Protection
 CR002218, Seal Injection flow alarms received on Unit 1, 10/07/2006
 CR002509, #3EDG frequency response during performance of 0-OPT-ZZ-012, 10/15/2006
 CR002511, EDG Data-Acquisition System failed to manually trigger as expected, 10/15/2006
 CR005609, ESI-EMD Owners Group Recommended Maintenance Program – Electrical for EDG's, 12/15/2006
 CR006069, IST Valves are being Stroke Tested more Frequently than Required
 CR008452, FW-260A Minor Anomalies Noted During MOV Test Being Report IAW NE-GL-0014, 03/08/2007
 CR008469, O-ring Protruding from Top of Handwheel Assembly
 CR008482, Critical Observation of 2-FW-MOV-260A
 CR010972, Review of EDG Air Compressor 1-EG-C-1 & 3-EG-C-1 downgrade classification to NSQ, 04/20/2007
 CR011243, Follow-up to CR10972 EDG Air Compressor downgrade classification, 04/20/2007
 CR013007, Tracking Item for DCP 06-046 non-priority drawing update, 06/04/2007
 CR013039, Found open coil for LWD relay, 06/05/2007
 CR013055, Relays out of specification high, 06/05/2007
 CR013310, 1-EE-P-1F Phase Currents, 06/17/2007
 CR015618, During extended run engine approached upper coolant temp limit of 190 degF, 07/09/2007
 CR016026, Relay 2-EE-RLY-LWD for EDG #2 failed to meet the As-Found Criteria, 07/16/2007
 CR016078, Motor Has High Amps, 07/17/2007
 CR021047, TDAFW Pump Runout Precautions during Station Blackout
 CR022019, Incomplete documentation for AAC Diesel fuel oil tank level indications & alarms
 CR022326, IST Design Basis for HHSI Check Valves to Cold Legs
 CR023038, Surry Self-Assessment – Operator Actions Review and recommendations
 CR023447, Scaffold Identified as Being too Close to a Safety Related Component
 CR023546, Grease Degradation found during Inspection
 CR024157, Exceeding Test Plan Limits on 1-CH-MOV-1370
 CR024228, High Running Current on 1-CH-MOV-1370
 CR028702, Quarterly AAC Diesel oil sample PM not completed before late date

CR089900, Setpoint/Alarm change for SPS 00-BFO-LI-3A/B
 CR091079, Off-site source operability not addressed during manual operation of RSST LTC
 CR091142, CDBI Report 308 on missed AAC quarterly lube oil sample
 S-2005-4988, 1-FW-MOV-151A closed stroke time higher than reference, 11/01/2005
 S-2006-0072-R1, DBD Discrepancies, 01/06/2006
 S-2006-0148, Diesel Generator Breaker Anomaly in Simulator, 01/12/2006
 S-2006-0883-R1, Missing wire in 1-EE-RLY-NFLDA, 03/09/2006
 S-2006-0892-R1, 1-EE-P-1A running current readings high, 03/10/2006
 S-2006-2707-E1, 43X2 relay cycled rapidly, 06/19/2006
 S-2006-2725-E1, Start failure relay check, 06/21/2006
 S-2006-2770-E1, Root Cause Evaluation Response, 06/25/2006

Work Orders

00269721 01, Protective Relay Maintenance, 2/15/94
 00308723 01, Inspection/Service 4160 Circuit Breaker – Outage, 9/20/95
 00419736 00, Lube Oil Sample Schedule for AAC Diesel Generator, 02/13/2008
 00606599 01, Functional Test of LTC Controller, May 5, 2006
 00753409 02, Implement DCP 06-042, November 4, 2007
 00764678 01, AAC fuel Oil Tank Level Transmitter, 08/17/2007
 00766383 01, Perform radiography for IST Program (SI-224), 10/30/2007
 00766385 01, Perform radiography for IST Program (SI-225), 10/30/2007
 00766389 01, Remove Bonnet for Bore scope Inspection (SI-410), 11/02/2007
 00773889 01, Perform Quarterly Oil Sample, 10/21/2007
 00776810 01, Repair Governor Cable, August 20, 2007
 381704 01, Replace Diaphragm in 1/2-CC-TV-120/220A, B, C, October 30, 1998
 381705 01, Replace Diaphragm in 1/2-CC-TV-120/220A, B, C, October 30, 1998
 441942 01, Remove Relief Valve, Bench Test, Repair, Replaced as Required, October 16, 2001
 441943 01, Remove Relief Valve, Bench Test, Repair, Replaced as Required, October 16, 2001
 441944 01, Remove Relief Valve, Bench Test, Repair, Replaced as Required, October 16, 2001
 470640 01, Replace Diaphragm in 1/2-CC-TV-120/220A, B, C, May 7, 2003
 470639 01, OVRHL Valves 1/2-CC-TV-120/220A, B, C, May 6, 2003
 470642 01, OVRHL Valves 1/2-CC-TV-120/220A, B, C, May 28, 2003
 725173 01, Test Relief Valve for IST Program, November 2, 2007
 725174 01, Remove Relief Valve, Bench Test, Repair, Replaced as Required, April 13, 2007
 725175 01, Remove Relief Valve, Bench Test, Repair, Replaced as Required, November 2, 2007
 727995 01, Service, Inspection and Diagnostic Testing/Mandatory PM for 1-SI-MOV-1862A, January 17, 2007
 733173-01, Service, Inspection and Diagnostic Testing for 1-SI-MOV-1862B, February 14, 2006
 745425 01, Remove Relief Valve, Bench Test, Repair, Replaced as Required, May 8, 2006
 745990 03, Test Valve IAW IST Program, November 4, 2006
 745990 02, Test Valve IAW IST Program, October 29, 2006
 762992 02, Rotate Spec Flange to Open at 1-RS-E-1D RS Inlet Line, November 18, 2007
 762993 02, Rotate Spec Flange to Open at 1-RS-E-1C RS Inlet Line, November 18, 2007

Design Change Packages

DCP 73-69, Add Cooling Fans to Reserve Station Transformer to Increase Capability From Existing 18,000 KVA to 24,000 KVA, dated June 27, 1973
 DCP 82-S05, Diesel Generator Exhaust Piping Modification, July 20, 1982
 DCP 84-060, Emergency Diesel Generator No. 3 Radiator Cooling Louvers, November 14, 1984
 DCP 85-21, RCP Thermal Barrier Mod, June 24, 1986
 DCP 89-08-3, RCP Thermal Barrier Component Cooling Check Valve Installation, May 31, 1989
 DCP 90-21-1, RCP Thermal Barrier Component Cooling System Modification, March 2, 1992
 DCP 92-052-3, Alternate AC (AAC) Diesel Generator Installation Surry Units 1 and 2
 DCP 99-103, Emergency Diesel Generator Lube Oil Modification, dated February 10, 2000
 DCP 03-022, Modification of EDG #3 Output Breaker 15j3 Closing Circuit Surry Unit 1 & 2, dated February 17, 2003
 DCP 04-065, Install 12 Second Ramp Bushing in TDAFW Pump Governors (1/2-MS-GOV-005), dated June 6, 2005
 DCP 05-020, Alternate Power Supply for Appendix Remote Monitoring Panels/Surry/Units 1 & 2, dated February 23, 2006
 DCP 06-007, Emergency Switchgear Room – Chilled Water System – Trench Piping Replacement, January 3, 2008
 DCP 07-007, Control Room AC CC Pipe Replacement Phase I & II, May 10, 2007
 060042, Replace Overcurrent Relays (50/51) for Motor Driven Aux FW Pumps/Surry/Units 1 & 2, dated October 19, 2006
 TM S2-06-040, Temporary Modification, May 12, 2006

Training Procedures

JPM 13.03, Locally Perform Non-essential SW Isolation (1-ECA-0.0 ATT 4), Rev. 10
 JPM 26.01, Reset the TDAFW Pump Trip/Throttle Valve, Rev. 13
 JPM 40.06, Initiate RHR Alternate Decay Heat Removal by Gravity Feed Cooling, Rev.6
 JPM 81.04, Load the AAC Diesel Onto the Unit One “J” Bus, Rev. 11
 JPM 4000087, Dump Air From Condenser Waterbox Vacuum Breakers, Rev. 9
 NCRODP-26-S, Feedwater System, dated January 17, 2007
 ND-95.2-LP-12, Loss of RHR Events, Rev. 10

Miscellaneous

38-A101-00003, Anchor/Darling Valve Company Maintenance Manual for Double Disc Type Gate Valves, Rev. 11
 86-5060, Station Commitment Assignment/Response Form NRC IEIN 86-14, May 23, 1986
 99-L553-F0001, General Limitorque Information, Rev. 15
 AAC Diesel Lube Oil Analysis Report, dated June 27, 2007
 AAC Diesel Fuel Oil Analysis Data, dated May-Nov 2007
 CO-AGREE-000IA1-2, Nuclear Switchyard Interface Agreement Communication Protocol, dated February 5, 2007
 Email A. Al-Hamdani to D. O’Connor, Communication Protocol IA1-2, dated February 12, 2008
 Email E. Croasdale to D. O’Connor, Voltage Drop Limit Documentation, dated February 12, 2008

ET CEE-99-0016, AAC System Qualification, North Anna and Surry Power Stations Units 1 & 2, Rev. 0

ET-CEE-07-0006, Changes to 0-AP-10.18 "Response to Grid Instability", Rev. 0

ET-CEE-02-0002, INPO SOER 99-1 Review; Recommendation #4 Review Overcurrent Trip Device Setpoints, Rev. 1

ET- CME 01-0024, Evaluation of Negative Jog Margin Values due to Inclusion of Rate of Loading (ROL) and Stem Lubrication Degradation Corrections, Rev. 0

ET-CME-04-0018, Transmit PRC & CDS From Technical Report ME-0092, Revision 2, and Evaluate the Potential Impact on SPS if COF is Assumed To Be 0.20, Rev. 0

ET-CME-05-0002, Resolution to PPR No. 2005-001 for AFW Makeup Line Issue, March 10, 2005

ET-MAT-05-0002, Interior Coating of Lube Oil Cooler Tubes for Corrosion Protection, October 31, 2005

ET S-98-0137, 0-AAC-DG-01, Operating Parameters Surry Power Station Units 1 & 2, Rev. 0

ET S-99-0264, EDG Fuel Consumption Assessment, Rev. 0

ET-S-05-0086, Evaluate CH Pump Lube Oil Coolers, November 9, 2005

ET-S-06-0143, Acceptability of Ultra Low Sulfur Diesel Fuel at Surry Power Station, Rev. 0

EWR 85-476, Charging Pump Lube Oil Cooler Protective Coating, August, 27, 1985

FS 2007-020, UFSAR/ISFSI SAR Change Request, January 10, 2008

FS 2007-024, UFSAR/ISFSI SAR Change Request, January 10, 2008

FS 2008-001, UFSAR/ISFSI SAR Change Request, January 28, 2008

J. O. No. 11448, Charging pump Cooling and Service Water Subsystem, December 31, 1970

NESML-Q-540, Charging pump lube oil cooler 2-CH-E-5A, January 20, 2006

NP-2422 Type 1 Study, Emergency Diesel Generator High Temperature Operation, May 11, 1995

NRC Letter 88-275, NRC Bulletin No. 88-04: Potential Safety-Related Pump Loss, July 11, 1988

NRC Letter 88-275A, NRC Bulletin No. 88-04: Potential Safety-Related Pump Loss, August 8, 1988

NRC Letter 88-275C, NRC Bulletin No. 88-04: Potential Safety-Related Pump Loss Supplemental Information, July 28, 1989

NRC Letter 88-275D, NRC Bulletin No. 88-04: Potential Safety-Related Pump Loss, June 18, 1990

NRC Letter 91-014, NRC Bulletin No. 88-04: Potential Safety-Related Pump Loss Completed Actions, January 18, 1991

NRC Letter 91-014A, NRC Bulletin No. 88-04: Potential Safety-Related Pump Loss Completed Actions, July 8, 1991

NRC Letter 91-014b, NRC Bulletin No. 88-04: Potential Safety-Related Pump Loss, December 9, 1992

OD 000026, Operability Determination, dated August 16, 2007

OE Evaluation Response-S-1995-0067-E1, IN 90-05: Undervoltage Protection Relay Settings out of Tolerance due to Test Equipment Harmonics, dated April 27, 1995

OEE000075, OPES000201 IN 2006 Failure of Magnesium Rotors in Motor Operated Valve Actuators, dated December 7, 2006

OPEX000256, IN 2006-29: Potential Common Cause Failure of Motor Operated Valves as a result of Stem Nut Wear, dated May 22, 2007

Plant Issue – S-2001-2487, MOV Stem Nut COF Measured on 2-FW-MOV-260A is Greater Than Assumed COF in Fundamental Calculation ME-0211, Complete October 21, 2001

Plant Issue – S-2004-2878, For GL 96-05 the MOV Program is Committed to Periodic Review and Update of Design Assumptions such as COF, Complete August 23, 2004

Plant Issue – S-2006-1810, AFW Operation, May 4, 2006

SAR 000305, NRC Component Design Basis Inspection (CDBI) Pre-Inspection Self-Assessment, dated October 25, 2007

Serial No. 89-406, Virginia Power Letter to NRC, October 25, 1990

Serial No. 89-572G, Consolidated Response to GL 89-13 Service Water System Problems Affecting Safety-Related Equipment, October 2, 1991

Serial No. 90-442, NRC Letter to Virginia Power, June 5, 1989

STD-MEN-0004, Pipe Class Design Standard, Rev. 13

S-PMTE-2008-0007, Request changing the classification of this task to “RM”

Technical Report EE-0101, Setpoint Bases Document Analytical Limits, Setpoints and Calculations for Technical Specification Instrumentation, Rev. 10

Technical Report ME-0025, NRC Generic Letter 89-13 Recommendations, January 25, 1990

Technical Report NE-1437, Mechanical Systems and Component Parameter Values Assumed in the Safety Analyses, Rev. 0

VTM 38-B851-00004, Installation Maintenance Instructions Medium Voltage Power Circuit Breakers

VTM-38-C112-00001, Technical Manual for Station Blackout Diesel Generator Set Caterpillar Model 3612, Rev. 16

VTM-38-E035, Operating Manual 999 System Generating Plant, Rev. 40

Westinghouse Letter VPA-03-242, Motor Acceleration and Time versus Current Curves, dated December 12, 2003

Corrective Action documents initiated due to CDBI activity:

CR089999, AP-27 attachment does not address charging pump suction MOVs

CR090208, Superseded EDG fuel oil calculation still shows up in DMIS

CR090210, Calculation 1039.3410-M-3 used wrong EDG fuel consumption value

CR090931, AP-27 attachment lacks clarity for gravity feed flow paths

CR091067, RSS Transformer load tap changer (LTC) timing test procedures do not include acceptance criteria

CR091079, Off-site source operability not addressed during manual operation of RSS transformer LTC

CR091142, Missed AAC diesel quarterly oil sample

CR091184, RSS transformer control power sources do not have redundancy

CR091493, Calculation EE-0034 does not consider worst case low voltage

CR091494, Calculation EE-0035 does not consider frequency variation

CR091676, Charging pump gear box heat load used in calculations

CR091698, 2-FW-MOV-260A non-conservative differential pressure for opening

CR091720, Could not locate vendor technical manual for 30kVA transformer

CR091809, AAC diesel testing periodicity

CR091877, Manual AFW isolation valves not included in in-service testing program

CR091878, Potential for ground on emergency bus when offsite power restored

CR091895, EDG voltage and frequency dynamic response

CR091904, Vendor technical manual for EDGs not updated

CR091906, Battery discharge test voltage acceptance criteria incorrect for first minute