

April 28, 2008

Mr. Randall K. Edington  
Executive Vice President Nuclear/  
Chief Nuclear Officer  
Mail Station 7602  
Arizona Public Service Company  
P. O. Box 52034  
Phoenix, AZ 85072-2034

SUBJECT: PALO VERDE NUCLEAR GENERATING STATION, UNIT 2 – RESULTS OF  
13TH STEAM GENERATOR TUBE INSPECTION (TAC NO. MD5982)

Dear Mr. Edington:

By letter dated February 9, 2007, and supplemented by letters dated May 3, 2007, and March 5, 2008, Arizona Public Service Company (APS, the licensee) submitted information pertaining to its 2006 steam generator (SG) tube inspections for the Palo Verde Nuclear Generating Station (Palo Verde), Unit 2, Facility Operating License No. NPF-51. These inspections were performed during the 13th refueling outage of Unit 2.

Based on a review of the material provided by APS, the U.S. Nuclear Regulatory Commission (NRC) staff concludes that the licensee provided the information required for SG tube inspections by the plant technical specifications. In addition, the NRC staff did not identify any issues that warrant follow-up at this time. The NRC staff's evaluation of the APS reports is enclosed.

Sincerely,

/RA/

Michael T. Markley, Senior Project Manager  
Plant Licensing Branch IV  
Division of Operating Reactor Licensing  
Office of Nuclear Reactor Regulation

Docket No. STN 50-529

Enclosure: Safety Evaluation

cc w/encl: See next page

April 28, 2008

Mr. Randall K. Edington  
Executive Vice President Nuclear/  
Chief Nuclear Officer  
Mail Station 7602  
Arizona Public Service Company  
P. O. Box 52034  
Phoenix, AZ 85072-2034

SUBJECT: PALO VERDE NUCLEAR GENERATING STATION, UNIT 2 – RESULTS OF  
13TH STEAM GENERATOR TUBE INSPECTION (TAC NO. MD5982)

Dear Mr. Edington:

By letter dated February 9, 2007, and supplemented by letters dated May 3, 2007, and March 5, 2008, Arizona Public Service Company (APS, the licensee) submitted information pertaining to its 2006 steam generator (SG) tube inspections for the Palo Verde Nuclear Generating Station (Palo Verde), Unit 2, Facility Operating License No. NPF-51. These inspections were performed during the 13th refueling outage of Unit 2.

Based on a review of the material provided by APS, the U.S. Nuclear Regulatory Commission (NRC) staff concludes that the licensee provided the information required for SG tube inspections by the plant technical specifications. In addition, the NRC staff did not identify any issues that warrant follow-up at this time. The NRC staff's evaluation of the APS reports is enclosed.

Sincerely,

/RA/

Michael T. Markley, Senior Project Manager  
Plant Licensing Branch IV  
Division of Operating Reactor Licensing  
Office of Nuclear Reactor Regulation

Docket No. STN 50-529

Enclosure: Safety Evaluation

cc w/encl: See next page

**DISTRIBUTION**

|                          |                     |                         |
|--------------------------|---------------------|-------------------------|
| PUBLIC                   | RidsNrrDorlLpl4     | RidsNrrDciCsgb          |
| LPLIV r/f                | RidsNrrPMMMarkley   | KKarwoski, NRR/DCI/CSGB |
| RidsAcrsAcnw&mMailCenter | RidsNrrLAJBurkhardt | AJohnson, NRR/DCI/CSGB  |
| RidsNrrDirsltsb          | RidsOgcRp           |                         |
| RidsNrrDorlDpr           | RidsRgn4MailCenter  |                         |

**ADAMS Accession No.: ML081150648**

(\*) SE input memo

|        |             |             |             |             |
|--------|-------------|-------------|-------------|-------------|
| OFFICE | NRR/LPL4/PM | NRR/LPL4/LA | NRR/CSGB/BC | NRR/LPL4/BC |
| NAME   | MMarkley    | JBurkhardt  | AHiser (*)  | THiltz      |
| DATE   | 4/28/08     | 4/28/08     | 4/14/08     | 4/28/08     |

**OFFICIAL AGENCY RECORD**

Palo Verde Nuclear Generating Station

04/14/2008

cc:

Mr. Steve Olea  
Arizona Corporation Commission  
1200 W. Washington Street  
Phoenix, AZ 85007

Mr. Douglas Kent Porter  
Senior Counsel  
Southern California Edison Company  
Law Department, Generation Resources  
P.O. Box 800  
Rosemead, CA 91770

Senior Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 40  
Buckeye, AZ 85326

Regional Administrator, Region IV  
U.S. Nuclear Regulatory Commission  
Harris Tower & Pavillion  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011-8064

Chairman  
Maricopa County Board of Supervisors  
301 W. Jefferson, 10th Floor  
Phoenix, AZ 85003

Mr. Aubrey V. Godwin, Director  
Arizona Radiation Regulatory Agency  
4814 South 40 Street  
Phoenix, AZ 85040

Mr. Scott Bauer, Director  
Regulatory Affairs  
Palo Verde Nuclear Generating Station  
Mail Station 7636  
P.O. Box 52034  
Phoenix, AZ 85072-2034

Mr. Dwight C. Mims  
Vice President  
Regulatory Affairs and Plant Improvement  
Palo Verde Nuclear Generating Station  
Mail Station 7605  
P.O. Box 52034  
Phoenix, AZ 85072-2034

Mr. John C. Taylor  
Director, Nuclear Generation  
El Paso Electric Company  
340 East Palm Lane, Suite 310  
Phoenix, AZ 85004

Mr. James Ray  
Public Service Company of New Mexico  
2401 Aztec NE, MS Z110  
Albuquerque, NM 87107-4224

Mr. Geoffrey M. Cook  
Southern California Edison Company  
5000 Pacific Coast Hwy Bldg D21  
San Clemente, CA 92672

Mr. Robert Henry  
Salt River Project  
6504 East Thomas Road  
Scottsdale, AZ 85251

Mr. Jeffrey T. Weikert  
Assistant General Counsel  
El Paso Electric Company  
Mail Location 167  
123 W. Mills  
El Paso, TX 79901

Mr. Eric Tharp  
Los Angeles Department of Water & Power  
Southern California Public Power Authority  
P.O. Box 51111, Room 1255-C  
Los Angeles, CA 90051-0100

Mr. Brian Almon  
Public Utility Commission  
William B. Travis Building  
P.O. Box 13326  
1701 North Congress Avenue  
Austin, TX 78701-3326

Ms. Karen O'Regan  
Environmental Program Manager  
City of Phoenix  
Office of Environmental Programs  
200 West Washington Street  
Phoenix AZ 85003

STAFF EVALUATION BY THE OFFICE OF NUCLEAR REACTOR REGULATION  
RELATED TO RESULTS OF 13TH STEAM GENERATOR  
TUBE INSERVICE INSPECTION  
ARIZONA PUBLIC SERVICE COMPANY, ET AL.  
PALO VERDE NUCLEAR GENERATING STATION, UNIT 2  
DOCKET NO. STN 50-529

1.0 INTRODUCTION

By letter dated February 9, 2007 (Agencywide Documents Access and Management System (ADAMS) Accession No. ML070510481), and supplemented by letters dated May 3, 2007 (ADAMS Accession No. ML071360096), and March 5, 2008 (ADAMS Accession No. ML080740050), Arizona Public Service Company (APS, the licensee) submitted information pertaining to its 2006 steam generator (SG) tube inspections for the Palo Verde Nuclear Generating Station (Palo Verde), Unit 2, Facility Operating License No. NPF-51. These inspections were performed during the 13th refueling outage of Unit 2. The U.S. Nuclear Regulatory Commission (NRC) staff issued a request for additional information dated January 9, 2008 (ADAMS Accession No. ML073460517), and the licensee provided additional information in the APS letter dated March 5, 2008.

Palo Verde Unit 2 has two Combustion Engineering System 80 SGs. There are 12,580 thermally treated Alloy 690 tubes in each SG. The tubes have an outside diameter of 0.75 inches and a wall thickness of 0.042 inches. Ferritic stainless steel egg-crate tube supports, diagonal bars, and/or vertical straps support the tubes at various locations.

2.0 REGULATORY EVALUATION

The licensee provided the scope, extent, methods, and results of its SG tube inspections in the documents referenced above. In addition, the licensee described corrective actions (i.e., tube plugging or repair) taken in response to the inspection findings.

The following observations are noted in regard to the licensee's 2006 inspections:

- One loose part (a small wire) was only detected through visual examination and not during the eddy current inspections. This wire was in SG 21. The small size of the wire may explain why it was not detected by the bobbin probe. The wire could not be retrieved and future trending of this location will be performed during the Unit 2 Refueling Outage 14 inspection.

- One sludge rock and one piece of flexitallic gasket could not be removed from SG 22. There was no tube wear associated with these foreign objects.
- The U-bends in the low row tubes (rows 1 through 3) were not inspected during the 2006 outage; however, the licensee has plans to inspect the U-bend region of these tubes during the next outage (U2R14).
- The maximum measured through-wall depth following cycle 13 (U2R13) was slightly greater than a projection performed following the previous inspection (U2R12) despite using a highly conservative growth rate to project the U2R13 results.

### 3.0 CONCLUSION

Based on a review of the information provided, the NRC staff concludes that the licensee provided the information required by their technical specifications. In addition, the NRC staff concludes that there are no technical issues that warrant follow-up action at this time since the inspections appear to be consistent with the objective of detecting potential tube degradation and the inspection results appear to be consistent with industry operating experience at similarly designed and operated units.

Principal Contributor: K. Karwoski

Date: April 28, 2008