

. _____

AREVA

.



Meeting Agenda

> Introductions

> NRC Notification – Letter Objectives

- Describe events and current status
 - Description of occurrence of fuel rod bow at North Anna
 - Definition of actions taken
- Provide Apparent Cause Analysis overview
 - Technical and programmatic causal factors
 - Extent of condition
- Provide overview of governing topical
- Discuss potential problem (difference between occurrence and topical)
- Action Plan Overview/Status
- > Preliminary water channel measurements North Anna 1
- > Summary
- > Q&A

ARE\





.068 in - Upper Spans

.0945 in - Bottom Span

> Alters design pitch dimensions, or water channel gap, between adjacent rods within a Advanced Mark-BW fuel assembly array which affects:

INST

TUBE

Local nuclear power peaking
Local heat transfer to coolant

ROD-TO-ROD .122 in - All Spans

TUBE

ROD

ROD-TO-INSTRUMENT TUBE

AREVA NP INC.







North Anna Unit 2 EOC 18 Fuel Rod Bow

 \sim





Actions Taken

AREVA NP INC.

AREVA



Actions Taken (cont.)

> Actions taken following North Anna Unit 1 observations

Actions Taken (cont.)

> Actions taken following North Anna Unit 1 observations

- Completed Deviation Determination
 - Event classified as a deviation; observed performance not expected.
- Defect Determination completed
 - Determined not a Defect as the condition does not create a substantial safety hazard.
 - Fuel system integrity is preserved during normal operation and would be during anticipated operational occurrences (AOOs),
 - Operation at Rated Thermal Power will not cause the core safety limits to be exceeded,
 - Fuel system integrity to facilitate control rod insertion when required is preserved,
 - The number of fuel rod failures is within the design for postulated accidents, and fuel coolability is always maintained.
 - Current technical specifications related to safety limits continue to be supported with the observed and expected bow.

AREVA NP INC.

AREV



Apparent Cause



AREVA



Grid Cell Size Change Due To End Grid Supplier/Process Change Mt Athos Road and NFI Supplied End Grids

- > Pronounced reduction in grid cell size and increase in variability
- > ~35% increase in corner and periphery cell slip loads
- > ~20% increase in slip loads due to M5



.









Governing Rod Bow Topical and Methodology







(cont.)





Fuel Rod Bow Topical Reports and SERs (cont.)

> BAW-10147P-A, Rev.01, Fuel Rod Bowing in Babcock & Wilcox Fuel Designs, May 1983.





> BAW-10147P-A, Rev.01, Fuel Rod Bowing in Babcock & Wilcox Fuel Designs, May 1983.





Fuel Rod Bow Topical Reports and SERs (cont.)

> BAW-10186P-A, Rev. 00, Extended Burnup ____Evaluation, June 1997.





Measured Water Channel Gap Data (Worst Span)











Action Plan Overview / Status



Action Plan Overview / Status

NP INC. Fuel Performa
Action Plan Overview / Status (cont.)

AREVA NP INC.

AREVA









North Anna 1 Water Channel Measurements

> Scope

- 8 Advanced Mark-BW fuel assemblies
- Bottom 3 spans 2 faces minimum
- > Status
 - 6 fuel assemblies measured
- > Preliminary Results
 - Well below 95/95 UTL of BAW-10147P-A Rev 01
 - Worst span water channel standard deviations near or slightly above observed limit of BAW-10186P-A Rev 00









Fuel Rod Bow Presentation Summary

Summary

- > AREVA continues to apply the methodology defined in BAW-10147P-A Rev 01 for the Advanced Mark-BW fuel
- Preliminary data indicate that the Advanced Mark-BW fuel is operating within the 95% tolerance limit (BAW-10147P-A Rev 01)
- AREVA is committed to understanding fuel rod bow behavior and implementing the necessary improvements to recover margin and improve performance

AREV



Q&A Open Discussion





Fuel Performance Meeting

AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008

2

April 8-9, 2008

AREVA NP Inc.

Lynchburg, VA



Fuel Performance Meeting April 9, 2008

- > 8:00 Welcome Gardner
 - Introduction and Purpose
 - Description of AREVA NP Inc.
 - Plans for Future Topical Reports
- > 8:30 BWR Fuel Designs and Methods N. Garner
 - Description of Current Fuel Designs
 - New Fuel Designs and Methods
- > 9:45 Break
- > 10:00 PWR Fuel Designs and Methods Uyeda/Lotz
 - Description of Current Fuel Designs
 - New Fuel Designs and Methods
- > 11:30 Lunch
- > 12:30 Recent Fuel Performance Experience Willse
- > 1:30 BWR Fuel and Hardware Testing Programs Montgomery
- > 2:00 Fuel Channel Performance Smith
- > 3:00 Break
- > 3:15 PWR Fuel and Hardware Testing Programs Montgomery
- > 4:00 M5 Experience Summary Montgomery
- > 5:00 Conclusion Gardner



Introduction and Purpose

Ronnie L. Gardner Manager, Site Operations & Corporate Regulatory Affairs

AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008

4

Introduction

> Introduction of participants

> Outline of discussion

- Current fuel designs
- New fuel designs and methods
- Recent experience
- Fuel development
- > **Objectives**
 - Understanding AREVA NP Inc.'s fuel design
 - Exchanging ideas and expectations on fuel issues
 - Open communication; ask questions



Description of AREVA NP Inc.





AREVA NP Inc. Executive Team

Tom Christopher President and CEO

Joe Zwetolitz

Vice President

Fuel America

Steve Hamilton

Vice President

AREVA NP CN, Ltd.



George Beam Sr. Vice President Nuclear Services



Andrew Cook Sr. Vice President Sales & Marketing



Jim Hicks Vice President Business Integration





Tom Franch

Sr. Vice President

Nuclear Eng. and

New Plants Eng.

Steve Blickenstaff Vice President



Bob Kibler Vice President HR & Facilities Information Systems Region Quality



Emily Mayhew Vice President



Ray Ganthner Sr. Vice President New Plants Deployment



David Guza **Chief Counsel** Legal



Bill Fox Vice President Charlotte Site & U.S. Region Safety



John Matheson Sr. Vice President **Projects Group**



Kevin McHenry Director Purchasing





Tom Stevens Sr. Vice President Federal Group



Tony Granda

Sr. Vice President

Equipment & IC&E



Fuel Performance Meeting Slides – April 9, 2008

8

AREVA

> World leader in the energy business

- N°1 in the entire nuclear cycle
- N°3 in electricity transmission and distribution

> Our mission

 Enabling everyone to have access to ever cleaner, safer and more economical energy

> Our strategy

- To set the standard in CO₂-free power generation and electricity transmission and distribution
 - Capitalize on our integrated business model to spearhead the nuclear revival:
 - Build one third of new nuclear generating capacities
 - Make the fuel secure for our current and future customers
 - Ensure strong and profitable growth in T&D
 - Expand our renewable energies offering.

AREVA NP INC.

AREV







AREVA NP INC. Fuel

Fuel Performance Meeting Slides – April 9, 2008

12

Front End division

- > Uranium ore exploration, mining and concentration
- > Uranium conversion and enrichment
- Nuclear fuel design and fabrication





AREVA NP INC.

AREV

Fuel Performance Meeting Slides – April 9, 2008



A

Back End division

15

> Treatment and recycling of used nuclear fuel

- > Cleanup of nuclear facilities
- > Nuclear logistics





AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008



Transmission & Distribution division

Supply of products, systems and services for

electricity transmission and distribution networks



Nuclear Fuel





Fuel Performance Meeting Slides – April 9, 2008







- > Constructed in 1968
- > Facility size: 200,000 square feet (Fuel & Nuclear Services)
- > Shipped over 15,000 fuel assemblies since 1971
- > Shipped over 2,500 incore detectors since 1983
- Fabrication and supply of fuel related components : B₄C and B₄C – Alumina pellets, incore detectors, control components, machined components and springs
- > Average workforce experience: 12 years
- > Nuclear Services Equipment & Refurbishment facilities on site
- > Pump and Motor Services facilities on site
- > Certifications: ISO 900, ISO 14001 and OHSAS 18001

Data as of April 2008

Operations

Horn Rapids Road Facility

- > Constructed in 1971
- > Facility size: 404,000 square feet
- > Shipped 43,167 fuel assemblies since 1971
 - BWR: 34,642
 - PWR: 8,525
- > 224 powder shipments since 1990
- > 350 pellets / rod shipments since 1989
- > One- millionth ATRIUM™ 10 rods produced September 2007
- > Average workforce experience: 15 years
- > Analytical and materials laboratories
- > Advanced fuel design testing facilities

Data as of April 2008







A

AREVA





Fuel Customers in Taiwan and Japan




Plans for Future Topical Reports

Fuel Performance Meeting Slides – April 9, 2008

26



Topical Reports - 2008 > Topical Reports planned for submittal - 2008 ♦ EMF-2209, Addendum 1, SPCB Additive Constants for ATRIUM-10 Fuel – April 2008 BAW-10133, Addendum 3, Revised Seismic Analysis – September 2008 ANP-102xx, Improved Structural Faulted Analysis Methods – September 2008 BAW-10255, Revision 3, Cycle-Specific DIVOM Methodology Using the RAMONA5-FA Code – November 2008 ANP-102xx, Revised BWR Safety Limit Methodology – December 2008 ANP-102xx, ACE Critical Power Correlation for ATRIUM 10XM – December 2008

AREVA NP INC.

AREV

Topical Reports - 2009

> Topical Reports planned for submittal - 2009

- ANP-102xx, S-RELAP5 for BWR Non-LOCA Transients – November 2009
- ANP-102xx, COBRA FLX Core Transient Thermal Hydraulic Program for PWRs – December 2009
- ANP-102xx, ARCADIA (ARTEMIS/APOLLO2A) Reactor System Analysis for PWRs – December 2009
- BAW-10247, Revision 1, Realistic Thermal-Mechanical Fuel Rod Methodology for BWRs (Extension to RXA clad) – December 2009
- ANP-102xx, High Burnup fuel Performance for PWR Designs > 62K Mwd/Mtu - December 2009

AREVA NP INC.

ARE\



Topical Reports - 2010

> Topical Reports planned for submittal - 2010

• EMF-2103, Revision 2, S-RELAP5 RLBLOCA Methodology – March 2010



AREVA BWR Fuel Designs and Methods

Norm Garner Product Manager, BWR Fuel

AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008

31



AREVA BWR Fuel Designs





ATRIUM™ 10x10 Fuel Designs Increasing Stability, Mass, and Critical Power Capability



Larger fuel rod diameter for ATRIUM™ 10XP & 10XM

- More efficient fuel-tomoderator distribution
- Proportional increase in cladding wall thickness for reliability
- Part-length fuel rod (PLFR) number and length selected to meet pressure drop and stability requirements
- PLFR placement selected to provide critical power and shutdown margin benefits

AREVA NP INC.

AREVA



Fuel Performance Meeting Slides – April 9, 2008

AREVA NP INC.

37





ATRIUM 10XM Spacer Grid ULTRAFLOW Type 62

- Structure and fuel rod support features continue proven reliability of the ATRIUM 10 ULTRAFLOW grid
- Extensive operational experience in both ATRIUM 10XP and ATRIUM 10XM fuel designs
 - >3800 in use, burnup to 52 GWd/MTU
 - LFAs since 2002
 - Reloads since 2005
 - Vaned egg-crate style grid with limited flow path obstruction
 - Solid strips reduce pressure drop and potential for debris capture
 - Structure is fabricated from Alloy 718 sheet for low pressure drop and dimensional stability throughout life



Advanced ATRIUM™ 10 Operational <u>Experience</u>

		ATRIUM™	First	Number Irradiated		Peak Burnup
Plant	Plant Type	Туре	Delivery	Bundles	Rods	GWd/MTU
C04	Siemens KWU	10XP	2002	60	5,460	52
C05	Siemens KWU	10XP	2006	136	12,376	5
C22	GE BWR/6	10XP	2003	16	1,456	40
		10XM	2005	4	364	21
C21	Siemens KWU	10XP	2004	92	8,372	24
C12	ASEA	10XP	2004	4	364	29
C24	ASEA	10XM	2006	4	364	7
C20	GE BWR/6	10XP	2005	32	2,912	12
C11	Siemens KWU	10XP	2006	112	10,192	12
C10	Siemens KWU	10XP	2006	20	1,820	12
Total as of January 2008				480	43,680	52

Extensive irradiation experience and PIE data provides confidence in ATRIUM[™] 10XM operational reliability



US Introduction of the ATRIUM[™] 10XM - LTA Plans



ATRIUM[™] 10XM Readiness for US Marke<u>t</u>

- > The ATRIUM 10XM is intended to replace the ATRIUM 10 as AREVA's mainline BWR fuel product for the US market
- > Significant operating experience base in Europe and evolutionary design of the ATRIUM™ 10XM supports a rapid progression to US reload supply





Improved Fuel Pellet Geometry <u> - Chamfer</u>ed Design for BWR 10x10 Fuel



- > AREVA ceramic experts have established a preferred global standard geometry for fuel pellets
 - Retains favorable outward land taper, dished end, and ~1.2 lengthto-diameter ratio of current pellet
 - Adds small edge chamfer at both ends
- Edge chamfer reduces pellet susceptibility to chipping
 - Supplements tightened MPS specifications and pending automated pellet inspections

Effective design response to reducing Missing Pellet Surface conditions

44

AREVA NP INC.

AREVA

Fuel Performance Meeting Slides – April 9, 2008



AREVA FUELGUARD™ Lower Tie Plate - Enhanced Design Developments



Step 1: Interim enhancement to limit wire length capable of passing through grid

- Reload delivery to Brunswick 1Q08
- Wire length limited by length that can pivot around bars on exit side of grid
- Extra bars will reduce passable wire length

Extra bars between standard FUELGUARD™ bars



Chromia Doped Fuel

- > Chromia doped fuel is fabricated by adding Cr₂O₃ into the pellet powder blend
- > Key benefits:
 - Increased pellet plasticity relieves stress on cladding under PCI conditions – power ramp capability at least comparable to benefit of liner vs. non-liner cladding
 - Large grain size and low resintering of Cr-doped fuel reduces release of fission gas to plenum – supports higher steady-state power while still meeting EOL fuel rod gas pressure criteria
 - Cr-doped pellets are stronger and less susceptible to chipping than standard UO2 pellets
 - In the event of a primary failure, pellet degradation is significantly reduced – limits secondary damage risk of cladding splits and/or fuel washout



Chromia Doped Fuel Program Status - Development Steps

- Development from late 1980's to late 1990's established optimal chromia addition concentration and pellet grain size characteristics
- Extensive qualification is underway, including poolside and hot cell PIE and ramp testing, to fully characterize benefits
- > Optimized Cr-doped fuel is bounded by standard fuel behavior and introduces no new failure mode risk



AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008



Fuel Channel Enhancements Observations from Channel Bow Investigations

- > Ideal fuel channel characteristics:
 - 1. Low general corrosion
 - 2. Low shadow corrosion sensitivity
 - 3. Low hydrogen pickup fraction
 - 4. Low fluence-induced growth
- > Zircaloy-2
 - Shadow corrosion sensitivity and higher hydrogen pickup than Zry-4 appear to be key to observations of abnormal bow

> Zircaloy-4

- Zircaloy-4 exhibits the desired low shadow corrosion sensitivity and low hydrogen pickup characteristics
- General corrosion is higher than Zircaloy-2, but satisfactory for current US burnups and chemistry practices
- Fluence-induced growth is satisfactory for current US burnups and operating strategies

New materials/processes can increase margin for current demands and support readiness for evolving demands

AREVA NP INC.

AREV







Fuel Channel Enhancements β-quench at Near-Final Geometry

- AREVA has developed a proprietary process to β-quench fuel channels
 - Eliminates sheet rolling texture and randomizes crystal alignment
 Ieading to near-zero fluence-induced growth
 - Channel is locally heated into βphase region and held a short time - inert cover gas (argon) precludes oxidation and scaling
 - 2. Channel is rapidly quenched to yield random crystallographic orientation
 - **3.** Final sizing and heat treatment for corrosion resistance (SPP size and distribution) is then completed



β-Quench Lead Fuel Channel Performance

Lead β -quench treated fuel channels are showing near-zero growth after three annual cycles

AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008







AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008



Support for Evolving Operating Domains

- > Generically approved methods have been revalidated for application in new domains
- > Extended Operating Domains have resulted in extensive interactions with the NRC & ACRS addressing both established and new methods
- > 2007 Susquehanna CPPU submittal provided first AREVA application for EPU:
 - Small penalty due to limited Gamma Scan Data (MCPRSL)
 - Small penalty to cover uncertainties in bypass boiling impact on OPRM set-point

Review and outcome recognized strength and thorough validation of AREVA methods

Major Developments in 2007

> 2007 saw significant methodology advances...

ACE/ATRIUM-10 critical power correlation approved

- RODEX4 draft Safety Evaluation Report Received
 - First statistically based Thermal-Mechanical methodology in the industry
 - Predicts both steady-state and transient response of fuel rods
- Enhanced Option III and DIVOM Methodology draft Safety Evaluation Report Received
 - Provides physically correct approach for extended flow domains



Continuing Developments in 2008

- > Steady progress on improvements...
 - MICROBURN-B2
 - Continued benchmarking and evaluation against current operation

• SAFLIM-3D

- Revised Safety Limit Methodology for use with the ACE correlation
 - MICROBURN-B2 based channel bow uncertainties developed for RODEX4 statistical methodology
- Programming complete and ready for testing
- AURORA-B (S-RELAP5 based transient methodology)
 - Single FORTRAN-90 executable for Non-LOCA, SBLOCA, RLBLOCA and BWR AOO – Reduced HU issues
 - RODEX4 models implemented
 - MB2-K extensions including enhancements to support reactivity insertion accident analysis
 - All major elements of the methodology are now in place and awaiting assessment



Redefines the online monitoring paradigm in support of Zero Fuel Failures by 2010



XEDOR Capability



RE

61


AREVA NP INC. Fuel Performance Meeting Slides – April 9, 2008



Programs to Be Completed in 2008 - New Innovations

- > 2008 Innovation
 - XEDOR
 - Complete qualification of method against ramp data base and fuel failure experience
 - Collaborate with reactor operators to optimize monitoring functions
 - Prepare training program to facilitate learning

AREVA BWR Codes & Methods - Conclusions

> AREVA is helping to transform the BWR industry

- Successfully validating current methods to support greater energy production from existing fleet
- Enhancing both the physical models and the calculational methodology to maximize fuel utilization
- Actively pursing advanced fuel designs and validation data to meet customer and regulator expectations
- Applying true innovation to address Zero Fuel Failures by 2010

AREVA is dedicated to exceeding

industry expectations

AREVA NP INC.

REV

Fuel Performance Meeting Slides - April 9, 2008



PWR Fuel Designs and Methods

Graydon Uyeda **PWR** Product Manager

Fuel Performance Meeting Slides - April 9, 2008

65



Outline of Presentation > Advanced Mark-BW Design Overview Design Features Operating Experience Planned Enhancements > Mark-B Design Overview > HTP Design Overview > New PWR Fuel Design Development



Overview of Advanced Mark-BW Assembly

Removable Upper End Fitting

- Alloy 718 Leaf Springs
- Quick Disconnect Feature
- M5[®] Fuel Rods
- M5 Guide Tubes
- M5 Instrument Tubes

TRAPPER™ Lower End Fitting





Design Features – Utilizes Alloy M5

- > Applicable Components:
 - Fuel Rods
 - Guide Tubes / Instrument Tubes
 - Intermediate Grids and Mid-Span Mixing Grids

> Performance with M5 (vs. Zircaloy-4)

- + 3 to 4x Lower Corrosion at High Burnup
 - Greater Margin at Higher Burnups
- <u>Very low sensitivity</u> to reactor duty factors (i.e., heat flux, temperatures and power)
- Licensed by the USNRC (December 1999)

Design Features – Spacer Grids

- > End Grids Alloy 718 (Low Cobalt)
 - Utilized at bottom and top positions
 - Non-vaned
- > Intermediate Grids M5
 - Optimized mixing vanes
 - Non-vaned version available for lower region
 - Wide support fretting resistance
 - Handling robustness
- > Mid-Span Mixing Grid M5
 - Added thermal performance



AREVA NP INC.

AREV

Fuel Performance Meeting Slides – April 9, 2008

70

Design Features – Lower End Fitting

> TRAPPER Plate

- Cast Frame and Web
 - Provides structural support
 - Accommodates attachment of guide tubes with secured cap screws
- No debris passing through TRAPPER has caused failures since introduction (over 2,500)
- Two Mesh sizes offered
- > FUELGUARD[™] Offered with Advanced Mark-BW(A)
 - No debris passing through FUELGUARD has caused failures since introduction (over 6,300)





AREVA NP INC.

AREV

Fuel Performance Meeting Slides – April 9, 2008

71



Mark-BW Operating Experience

> Current Mark-BW Experience Summary

<u>Unit</u> Accomblice	First Delivere	d <u>Batch</u>	<u>ies</u>	+ <u>LFA</u>	<u>s</u>
Assemblies					
 Catawba-1 	1991/2005	7	+	4	524
 Catawba-2 	1993	5			404
 McGuire-1 	1987/1991	7	+	4	512
◆ McGuire-2	1991	6			448
 North Anna-1 	1997/2004	3	+	4	193
 North Anna-2 	2004	3			189
◆ Sequoyah-1	1997	8			625
◆ Sequoyah-2	1997/1999	7	+	4	571
• <u>Trojan</u>	1990/1991	1	+		48
TOTAL		47	+	20	3,518

AREVA NP INC.

AREV



Planned Enhancements





Design Features – Fuel Rods

- > Application of M5
 - Increased Corrosion Protection
 - Reduced Hydrogen Pickup
 - Improved Growth Behavior
- Mark-B11
 - Reduced Diameter (0.416 inch) for 18 Month Cycle Operation
 - Long Lower End Cap in Lower Grid for Debris Protection
 - Stainless Steel Upper Plenum Spring
- Mark-B12 / Mark-B-HTP
 - Heavier Loaded Fuel Rod (0.430 Inch) for 24 Month Cycle Operation
 - Stainless Steel Upper and Lower Plenum Springs



AREVA NP INC.

AREVA

AREVA	Operating Experience – Mark-B Fuel Assemblies					
	> 9,800 Mark-B since 1972	Fuel Ass	semblies delivered			
	> Proven Experier (Typically 18 an	nce in ei d 24-Mo	ight US Reactors nth Cycles)			
	Unit	Batches	Fuel Assemblies			
	+ Oconee-1	25	1,487			
-	Oconee-2	24	1,441			
	Oconee-3	25	1,465			
	 Crystal River-3 	15+2*	997 + 169*			
	+ ANO-1	21+1*	1,277 + 56*	÷		
	 Davis-Besse 	16+1*	997 + 76*			
	 Three Mile Island 	-1 18	1,205			
	 Three Mile Island 	-2 3	177			
	 Rancho Seco 	9	493			
	ΤΟΤΑΙ	160	9.840			





Overview of Mark-B-HTP Fuel Assembly



 Removable Upper End Fitting

Alloy 718
 Cruciform Springs

- M5 Fuel Rods
- M5 Guide Tube
- M5 Instrument Tube

 FUELGUARD Lower End Fitting M5 HTP Grids (7x)

Alloy 718 Lower HMP Grid





Outline of Presentation

> Advanced Mark-BW Design Overview

> Mark-B Design Overview

> HTP Design Overview

- Design Features
- Operating Experience
- Planned Enhancements

> New PWR Fuel Design Development

Overview of HTP Fuel Assembly

Hold-down Springs

- <u>W</u> Leaf Springs
- CE 5 Coil Springs with Reaction Plate
- B&W Cruciform

Removable Upper End Fitting

- "Quick Disconnect"
- Fuel Rods
- Guide Tube
- Instrument Tube
- FUELGUARD Lower End Fitting



AREVA NP INC.

AREVA



HTP Spacer Grid Design Concept

- Balanced Stiffness and Damping Characteristics
- Highly Effective Energy Dissipation
- "Dual Line Contact" Rod Support System
- Robust Construction
- Low Flow Resistance
- Curved Flow Channels for Flow Mixing

Fuel Performance Meeting Slides – April 9, 2008

Design Features – Spacer Grids

- > HTP Grid
 - M5 (Zirc-4) Material
 - Curved Flow Channels
 - Welded to Guide Tubes
- > IFM Grid
 - Added Thermal Performance
 - M5 (Zirc-4) Material
 - Angled Flow Channels
 - Welded to Guide Tubes
- > HMP End Grid
 - Lower Grid Location
 - Alloy 718 Material
 - Straight Flow Channels
 - Capture Rings



AREV/



- Over 6,300 PWR assemblies delivered with FUELGUARD debris protection
- > Design Versatility
 - Same concept applied to various PWR Designs and BWRs



AREVA NP INC.

AREV



Operating Experience – HTP Fuel Assemblies

- > Over 6,800 HTP Fuel Assemblies loaded into 41 plants
- > Maximum achieved fuel assembly burn-up of 65 GWd/mtU
- > Worldwide <u>Zero</u> known Fretting Failures at HTP Spacer Positions
 - 18 Years of flawless operation (1,594,379 Fuel Rods)
- > Proven in a wide range of design variants and flow conditions
 - CE 14x14 and 15x15 (First in 1988)
 - Siemens KWU 15x15, 16x16 and 18x18 (First in 1989)
 - Framatome ANP 17x17 (First in 1993)
 - Westinghouse 14x14, 15x15 and 17x17 (First in 1994)
 - B&W 15x15 (First in 2003)
 - Currently Adapting for CE 16x16 HTP Design
 - Planned for EPR 14' 17x17 Design





Outline of Presentation

> Advanced Mark-BW Design Review

> Mark-B Design Review

> HTP Design Review

> New PWR Fuel Design Development







The GAIA Project – Innovation Process



Fuel Product Designs continue to evolve:

> Meet operational needs

> Increase fuel performance and reliability

> Increase design margins and safety

Questions?



PWR Core Engineering Methods

Thomas L. Lotz

Manager, PWR Core Engineering

AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008

93



Current Code Systems – Global Diversity

	<u>Lynchburg</u>	<u>Richland</u>	<u>Paris/Lyon</u>	<u>Erlangen</u>
Cross-Section	CASMO-3	CASMO-3	APOLLO-2	CASMO-3
Neutronic Simulator	NEMO	PRISM	SMART	PRISM
Kinetic Simulator	NEMO-K		SMART-K	PANBOX
Thermal-Hydraulics	LYNXT	XCOBRA-IIIC	FLICA-IIIF	COBRA-3CP
Fuel Rod	TACO3	RODEX2A	COPERNIC	CARO



The Future – and Beyond!

AREVA NP INC.

95





APOLLO2-A / ARTEMIS Features




COPERNIC3 Background

- > COPERNIC development began in 1994
- > Lyon and Lynchburg joint effort
- > Submitted in September 1999
- > Siemens/Framatome Joint Venture in 2001
- > COPERNIC reviewed and approved by NRC
 - SER for UO2 and UO2-Gd2O3 in June 2002
 - SER for MOX in January 2004
- > Limited implementation due to Joint Venture
- > New development needed to meet global needs





Reactivity Insertion Accident Analysis

- > Topical Report to be submitted by Dec. 2007
 - General Method for Application
- > Report Application will be specific to US EPR
- > Report will address RIA criteria and justification
- > Methology will include:
 - NEMO-K 3D kinetics
 - Improved LYNXT model
 - COPERNIC fuel properties
- > RIA Application Report to follow for other reactor types.



PWR Fuel Performance Experience

John T. Willse Manager, Fuel Reliability and Performance

Fuel Performance Meeting Slides – April 9, 2008



AREVA NP PWR Fuel Performance Status As Of 03/18/08





PWR Number of Failed Rods by Cause Past 10 years

AREVA PWR Fuel Failure Summary



Fuel Performance Meeting Slides - April 9, 2008

Definition of the film

PWR Ten Year Failure Rate



AREVA





AREVA NP BWR Fuel Performance Status As Of 03/18/08







Fuel Performance Meeting Slides – April 9, 2008



BWR And PWR Performance Are Connected

- > Same source of pellets
- > Same manufacturing techniques at different locations
- > For the last four years debris and PCI assisted by missing pellet surface has been the predominant failure mechanism
- > No PCI failures in any fuel rods manufactured after the implementation of the corrective measures to eliminate this failure mechanism





Millstone-2 Cycle 17 Fretting Failures and Design Resolution

AREVA NP INC.



Key Messages: Condition Understood and Implementing Proven Design Fix

- > CE14x14 plants have particularly high cross-flows near the baffle at the bottom and top regions of the core
- > The Millstone-2 fuel assembly design has been unique from the other CE14x14 plants – bottom grid design
- Combination of relaxed grid cells, clad diametral creep, and harsh flow conditions allowed rods to spin – resulting in failures
- > Implementation of mature Inconel HMP[™] grid in the lowermost position precludes rotation and failure

Inconel HMP lower grid with improved relaxation properties maintains rod contact.



History: High Cross-Flow Environment in CE14x14 Reactors

- Former non-HTPTM assemblies have experience random fretting failures on core periphery
- > CE14x14 reactors exhibit high cross-flow behavior in lower and upper core regions

High cross-flow impinging baffle wall

Larger gap between assembly and baffle

Inlet & outlet core plate holes interior to the assemblies





History: CE14x14 HTP Fuel Assembly at Millstone-2



AREVA NP INC.



History: Progression to Failure

- During 1st and 2nd cycles, Zircaloy grid springs relax
- In low power 3rd cycle, gap forms in the upper grid locations (long lower end cap prevents gap at bottom)
- Cross-flow causes rod vibration, grid wear, and gap in bottom grid
- With gaps at all elevations, rod spins due to hydraulic forces and wears grids and rod eventually to failure
 - Spinning necessary to get fretting failure with HTP spacer



Fuel Performance Meeting Slides - April 9, 2008

AREV/

Proprietary

ETO

INPO



Status: Mitigating and Preventive Actions

- > Root Cause Analysis completed
- > Estimate one failure in current cycle
- > Inconel (Alloy 718) HMP lower grid scheduled for Cycle 19 insertion (spring 2008)
 - Same HMP grid used at St. Lucie-1 and nearly identical to Ft. Calhoun
 - HMP grid design is consistent for all designs scaled for array
- > Finalizing a mitigating solution for resident fuel
 - Focus on high potential failure areas
 - Square upper end cap developed
 - Confirmatory PIE programs at other CE Plants





Conclusions – Proven Design Solutions

- > Failure mechanism is understood
- > AREVA has a proven and mature solution the Inconel HMP lower end grid



AREVA NP INC.

AREV



Background

- > Level 2 Condition report in late September 2007 at time of fuel examination
 - An Apparent Cause team with representatives from Entergy, AREVA, and EPRI identified the most likely causes of failure:
 - Massive internal contamination from hydrogenous or halogen material
 - Contamination leading to lack of bonding in the end cap welds
- > Condition report elevated to Level 1 in early November 2007 when ACA unable to identify cause
 - A Root Cause team was formed to evaluate the manufacturing processes for end caps, plenum springs, pellets, cladding, and rod loading
 - Identify credible sources of contamination
 - Develop corrective actions to prevent recurrence

AREV

Timeline of Events



AREVA NP INC.

AREVA



Investigation Status

- > ACA and RCA investigations have not led to a "smoking gun"
- > A number of potential causes can be eliminated because impossible or highly unlikely:
 - Fuel / Core shroud interface
 - Clad collapse
 - Water chemistry control
 - Clad vulnerability to corrosion
 - Handling damage
 - Pellet clad mechanical interaction : PCMI, classical/nonclassical PCI, hydride assisted
 - Debris
 - Accelerated corrosion of end cap welds
 - Undetected cladding flaw
 - Power flux

AREVA NP INC.

AREV

Investigation Status (cont.)

- > Other potential causes :
 - Primary hydriding due to contaminants inside the rod : unlikely based on substances found in the manufacturing areas
 - Flaw in end-cap material (stringer) : unlikely based on ingot manufacturing and inspection records
 - Lack of bonding within the end-cap weld

ARE\

Team's Recommendations

- > Team recommends further testing of failed rods to identify (or eliminate) potential failure causes to facilitate development of corrective actions
 - Hot Cell or poolside pressurized test of end segments would reveal any non-bonded weld regions
 - Would also reveal any end cap stringers, if present (low probability as failure cause)

AREVA evaluating this recommendation in relation with Entergy

Team's Recommendations (cont.)

- > Team recommends experimental weld samples and burst tests to expand knowledge base of USW contamination resistance or susceptibility
 - Some results exist, indicate that spring wire lubricant, detergent, and uranium can interfere with bonding.
 - Copper, other contaminants do not affect weld integrity.
 - Stainless Steel/Inconel used for spring pre-set on this contract should be tested (spring pre-set no longer done with new MAR upper-end welder)
- > Although not believed to be related to the PAL fuel failures, HRR and MAR will perform assessments of processing areas with regard to housekeeping and material control

NREV



Fuel Crud Deposits at Davis-Besse

Observations during Cycle 15 RFO

- > 37 Mark-B-HTP[™] fuel assemblies were observed with crud deposits on the perimeter rods
- > Most fuel rods observed with elevated levels of crud deposits operated adjacent to other fresh fuel assemblies during Cycle 15
- > The crud was primarily noted between the 2nd and 3rd spacer grids from the top of the assemblies, with lesser amounts sometimes visible between the 3^rd and 4th grids from the top



AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008





Fuel Performance Meeting Slides - April 9, 2008
Observations during 15 RFO

- > Three rods were pulled from a "limiting" fuel assembly and inspected for waterside oxide layer thickness and loss of cross-sectional area
 - No loss of cross-sectional area measured
 - Maximum measured oxide thickness which included some contribution from crud - was approximately 40 micrometers
- > Based on the fuel inspection for the crud deposits, all of the Mark-B-HTP fuel assemblies were determined to be acceptable for insertion into Cycle 16

What's Next?

> Actions being taken by AREVA NP

- Reviewing plant RCS chemistry records to determine any potential source for the elevated crud deposits on the fuel cladding
- Performing thermal-hydraulic modeling of the Cycle 15 core to determine any potential causes of the crud condition

ARE\



Conclusion

- > The completion of the transition to the new more robust designs will improve fuel performance significantly
- > Not all transitions will be completed by 2010
- > Some legacy failure mechanisms will continue for a few years
- > Fuel performance is going to improve

BWR Fuel and Hardware Testing Programs

Rose Montgomery

PIE Coordinator, Fuel Mechanical & Structural Design

AREVA NP INC.

AREV

Fuel Performance Meeting Slides – April 9, 2008

137

BWR Objectives

> Continued confirmation of existing and advanced design performance

> Purpose of the latest PIE data is to specifically support:

- Fuel Channel bow, bulge, shadow corrosion
- Water channel length & hydrogen uptake
- Reduction in the uncertainty application in RODEX creep collapse model for SRA cladding
- Implementation of RXA cladding
- Kobe channel performance
- High burnup SRA cladding performance
- Demonstrate Pambeouf cladding performance
- Support possible limit modifications for RIA



BWR Test Assembly Programs

> Atrium 10 XM (LaSalle 2)

- RXA cladding
- Cr-doped pellets

Fuel Performance Meeting Slides – April 9, 2008







Ŕ

Fuel Channel Performance

Mark H. Smith BWR Mechanical Analysis Engineer

AREVA NP INC.

AREV

Fuel Performance Meeting Slides – April 9, 2008

-

143

ş



AREVA NP INC.

BWR Fuel Channel Bow Issue – 2008 Update

- > A brief overview of the AREVA fuel channel distortion issue
- > Recent operating events
- > Update on fuel channel poolside measurement exams
- > Cell friction calculations
- > Summary



> Timeline

- Starting in 2002, AREVA develops fuel channel measurement equipment as part of an EPRI Fuel Reliability Program.
- March 2003 GNF reports new bow phenomena "affecting thick/thin" fuel channels in BWR/6 reactors
 - Bow caused by shadow corrosion
 - No signs of cell friction issues observed with AREVA fuel channels (yet)
- May 2004 AREVA fuel channel measurements:
 - May 2004 Susquehanna Unit 1
 - June 2004 Quad Cities Unit 2
 - Channel bow appears to be normal (EPRI report 1008097)

A AREVA

BWR Fuel Channel Bow Issue – 2008 Update A brief overview (cont.)

> Timeline

- May 2005 PPL reports signs of control rod friction in cells containing AREVA fuel channels.
- September 2005 GGNS discovers control rod friction at Grand Gulf during EOC 14 shutdown.
 - AREVA measures fuel channels at Grand Gulf. Several channels exhibit unexpectedly high bow.
- October 2005 PPL shuts Susquehanna Unit 1 down (MOC 14) for fuel channel replacement and examination with 41 STS (slow-to-settle) and 4 INOP control rods.
- > AREVA has taken a number of actions since this time.



- > Culmination of events
 - AREVA has conducted 13 channel measurement campaigns on a total of 906 fuel channels at 7 reactors.
 - Surveillance guidelines were developed to monitor susceptible control cells for signs of control rod friction.
 - Material coupons were acquired from fuel channels at LaSalle Unit 1 in June 2006 and Susquehanna Units 1 and 2 in February 2007 for hot cell examination.
 - Improvements in analysis methods for predicting cell friction are under development.
 - Majority of utilities switched back to using Zircaloy-4.

Ð



> Fuel channel bow

 "Classic" bow is attributed to the differential growth between opposite sides of the fuel channel due to fast neutron fluence.



proportional to the fast fluence gradient.



- > Fuel channel bow
 - Here is the Zry-4 measurement data as a function of fast fluence gradient.





- > Fuel channel bow
 - Here is the added Zry-2 measurement data as a function of fast fluence gradient.



þ



- > Fuel channel bow
 - Abnormal bow ("shadow corrosion-induced")
 - ◊ Early-in-life control
 - ◆ Potential abnormal bow above a given exposure





BWR Fuel Channel Bow Issue – 2008 Update Control Rod Friction Surveillance

- > Control rod friction surveillance
 - Identifies susceptible cells for sampling by periodic settletime testing
 - If cell friction is identified:
 - Additional testing is done on the cell to monitor friction so operator action can be taken if the friction becomes too high.
 - Preserve adequate scram insertion time
 - Avoid undue scram loads on fuel (lift off) or internals
 - Satisfy TS requirements for control rod operability
 - Ensure that the occurrence of abnormal bow is properly taken into account in the SLMCPR analyses.
 - Consideration of abnormal bow statistics in analyses.



BWR Fuel Channel Bow Issue – 2008 Update Control Rod Friction Surveillance (cont.)

> Control rod friction surveillance

• Utilities with C-lattice or S-lattice plants and AREVA Zry-2 fuel channels are following the surveillance guideline.

 To date, control rod friction problems attributed to channel bow have occurred in the plants underlined in the list above. Blue font indicates plants currently experiencing problems.



- > Recent operating events
 - OE25435 Unexpected Indications of Channel Bow (Grand Gulf)
 - Event date: August 22, 2007
 - Three control rods failed to settle following rod stroking in preparation for startup following a scram.
 - All three cells were <u>not</u> identified as susceptible according to the AREVA surveillance guideline.
 - The three cells are on the core periphery
 - Currently operating with four cells exhibiting friction that require additional surveillance



- > Recent operating events
 - OE25541 Channel Distortion in Non-Susceptible Core Cells with High Exposure AREVA Bundles at LaSalle County Station
 - Event date: September 2, 2006 and September 9, 2007
 - Three control rods discovered at LaSalle Unit 1 exhibit friction – failed settle testing. Subsequent testing at Unit 2 revealed one control rod that was slow-to-settle.
 - All four cells were <u>not</u> identified as susceptible according to the AREVA surveillance guideline.
 - Four cells are on the core periphery
 - Unit 1 EOC12 in February 2008:
 - Two peripheral cells declared INOP
 - Five other peripheral cells identified with friction
 - Unit 2 Cycle 12 currently has 1 INOP and 1 STS





Case study – Grand Gulf peripheral cell friction >

Fluence gradient history of Assembly SPJ032

Fuel Performance Meeting Slides - April 9, 2008



- > Case study Grand Gulf peripheral cell friction
 - Friction cell observations
 - Contains higher exposure fuel assemblies (4th of 18-month cycles)
 - Little early-in-life control (low EFID)
 - Accumulated fluence gradient is not high enough to explain the amount of bow to cause friction
 - Operation in a positive flux gradient location (core peripheral location with bow towards blade)
 - Fuel had operating on the core periphery in a prior cycle
 - Zry-2 fuel channels
- > Other cells at Grand Gulf and LaSalle Units 1 and 2 share the same common characteristics as above.



- > Interim control rod friction surveillance guideline
 - AREVA issued a new interim surveillance guideline to address the two Operating Events:
 - Bow does not appear to be "classic" fluence gradientinduced bow even when considering known "break-away" growth at higher fluence levels.
 - Apparent accelerated bow occurs at varying, higher exposures
 - Occurs primarily in high gradient (peripheral) locations
 - Guideline identifies additional susceptible control cells for surveillance



> Interim control rod friction surveillance guideline

Cells identified for Grand Gulf Cycle 16



- > Recent poolside exams
 - October 2006 Susquehanna Unit 2 MOC 13 shutdown, 26 80-mil FC (fuel channels), 2 100-mil FC, 32 GNF 80-mil FC
 - Purpose of exam was to characterize channels suitable for continued irradiation

- Measurement data similar to past data on susceptible fuel channels
 - Random occurrence of higher bow
 - A biased sample of measurements
- October 2007 Susquehanna Unit 1 MOC15 shutdown, 74 Zry-2 100-mil, 2 Zry-2 80-mil and 2 Zry-4 80-mil FC



- > Recent poolside exams
 - March 2007 Grand Gulf EOC 15, 34 114/67-mil AFC (Advanced Fuel Channels) and 5 114/67-mil AFC manufactured by Kobe Steel, Ltd.
 - Obtain additional data on Zry-2 bow behavior
 - Measure Kobe channels for qualification purposes
 - Data used to confirm current surveillance guideline
 - February 2008 LaSalle Unit 1 EOC12, 47 100-mil AREVA channels and 59 GNF channels
 - Evaluate channel bow in problem cells to formulate corrective/preventive actions for next cycle.
 - Improve surveillance for higher exposure Zry-2 fuel channels.



- > Recent poolside exams (continued)
 - Grand Gulf EOC 15 bow versus exposure





- > Recent poolside exams
 - Grand Gulf EOC 15 bow versus fluence gradient





- > Recent poolside exams
 - Grand Gulf EOC 15 M-E versus exposure



- > Recent poolside exams
 - Grand Gulf EOC 15 M-E versus EFID



> Recent poolside exams

- May 2007 Columbia Generation Station, 62 Zry-2 100-mil FC
 - Purpose of exam to confirm applicability of abnormal bow data from LaSalle units (also Zry-2 100-mil FC) to CGS.
 - FC selected with wide range of early-in-life control.



- > Recent poolside exams
 - CGS EOC 18 bow versus exposure

AREVA NP INC.

Fuel Performance Meeting Slides – April 9, 2008

169


BWR Fuel Channel Bow Issue – 2008 Update Fuel Channel Measurements (cont.)

- > Recent poolside exams
 - CGS EOC 18 bow versus fluence gradient



BWR Fuel Channel Bow Issue – 2008 Update Fuel Channel Measurements (cont.)

- > Recent poolside exams
 - CGS EOC 18 M-E versus exposure





- > Recent poolside exams
 - CGS EOC 18 M-E versus EFID



BWR Fuel Channel Bow Issue – 2008 Update Hot Cell Examinations

- > Poolside examinations have clearly shown that only fuel channels fabricated from Zry-2 have exhibited unexpected channel bow.
- > Zry-4 channels all have been shown to fall within limits of expected fuel behavior.
 - Standard modeling based on pressure and fluence history remains valid for Zry-4 fuel channels.
- > Mechanism of unexpected channel bow and basis for difference in Zry-2 and Zry-4 fuel channel behavior could not be determined from poolside data.



BWR Fuel Channel Bow Issue – 2008 Update Hot Cell Examinations (cont.)

> Hot cell examinations:

 AREVA NP performed several hot cell examinations of Zircaloy-2 and Zircaloy-4 fuel channel coupons derived from two plants in the U.S. (together with EPRI)





AREVA

BWR Fuel Channel Bow Issue – 2008 Update Cell Friction

- > Cell friction predictions
 - Currently, the AREVA fuel channel topical report, EMF-93-177(P)(A) Revision 1, describes the method for calculating control rod interference due to channel distortion
 - Closed-form solution for calculating channel bulge
 - Simple model for calculating control rod interference
 - A new method is under development
 - Finite element method to calculate bulge
 - More elaborate 3-D cell friction calculation



BWR Fuel Channel Bow Issue – 2008 Update Cell Friction (cont.)

- > Cell friction predictions
 - Model development continues need to take into account recent data on accelerated bow at higher exposures (OEs)
 - Prediction of abnormal bow remains problematic
 - To date, Zry-4 fuel channels exhibit predictable behavior
- > AREVA will submit a revised topical report that uses fluence gradient to characterize bow rather than exposure

 Improved model can be used to identify control cells for surveillance



BWR Fuel Channel Bow Issue – 2008 Update Intermediate and Long-term Plans

- > Short term Zry-4 material viewed as a short to medium-term solution
 - While Zry-4 exhibits higher corrosion than Zry-2, Zry-4 wall thinning is acceptable up to the current exposure limit





> Long term - AREVA has advanced materials and processes available for introduction:



BWR Fuel Channel Bow Issue – 2008 Update Summary

> Summary

- Zry-2 fuel channels will continue to be a challenge to manage until full transition to Zry-4 fuel channels
 - Core design to take into consideration potential bow problems
 - Increased surveillance of control cells
 - Fuel channel replacement depending on perceived risk
- There is a contribution of operating conditions to the channel bow issue but it is not well understood

- Material development
 - Efforts to introduce LTAs are in progress

PWR Fuel and Hardware Testing Programs

Rose Montgomery

PIE Coordinator, Fuel Mechanical & Structural Design

AREVA NP INC.

AREV

Fuel Performance Meeting Slides – April 9, 2008

181

1

Fuel & Hardware Testing Programs

> PWR Programs

- Objectives
- Test Assembly Programs
- 2006-2007 Poolside PIEs
- M5 Experience Summary
- M5 Assembly growth models
- Unexpected Mark-B12 M5 guide tube growth

ARE\

PWR Objectives

> Purpose of the latest PIE data is to specifically support:

- Mark-B-HTP
- Mark-B11A & B12 designs
- Mark-BW & Advanced Mark-BW designs
- CE designs
- MONOBLOC guide tube design in U.S. reactors
- Investigate M5 guide tube growth
- Investigate fuel assembly distortion
- Investigate fuel rod distortion



Fuel & Hardware Testing Programs

> PWR Programs

- Objectives
- Test Assembly Programs
- 2006-2007 Poolside PIEs
- M5 Experience Summary
- M5 Assembly growth models
- Unexpected Mark-B12 M5 guide tube growth



PWR Test Assembly Programs

- > Mark-BW(A) (Sequoyah)
 - Objective
 - Provide performance data on design features
 - 4 test assemblies
 - Welded cage design with upper & lower HMP inconel grids
 - M5 fuel rods and MONOBLOC guide tubes
 - Insertion 10/07
 - Expectation is three cycles of operation to an end of life average assembly burnup of about 55 GWd/mtU
 - Post Irradiation Examinations to be completed following each cycle



PWR Test Assembly Programs (cont.)

- > Advanced Mark-BW MOX (Catawba)
 - Objective
 - Provide performance data on MOX
 - 4 test assemblies
 - Standard Adv. BW design with M5 fuel rods, guide tubes, intermediate grids and MSMGs
 - Insertion 5/05
 - Expectation is three cycles of operation to an end of life average assembly burnup of about 52 GWd/mtU
 - Post Irradiation Examinations to be completed following each cycle with hot cell rod exams following second and third cycles

PWR Test Assembly Programs (cont.) > Zircaloy CE 14 assembly (Calvert Cliffs) • Objective • Demonstrate design performance in Calvert Cliffs

- High burnup demonstration
- Provide performance data on design features

4 test assemblies

- M5 fuel rods and zircaloy guide tubes
- Standard CE-type Welded cage design
- Insertion in 2005
- Expectation is three cycles of operation to an end of life peak pin burnup of about 68 GWd/mtU
- Post Irradiation Examinations to be completed following each cycle

ARE\

PWR Test Assembly Programs (cont.)

- > M5 CE 14 XL assembly (Palo Verde)
 - Objective
 - Demonstrate design performance in Palo Verde
 - Provide performance data on design features
 - 4 test assemblies
 - M5 fuel rods and guide tubes
 - Standard CE-type Welded cage design
 - Insertion scheduled for 10/08
 - Expectation is three cycles of operation to an end of life average assembly burnup of about 55 GWd/mtU
 - Post Irradiation Examinations to be completed following each cycle



Fuel & Hardware Testing Programs

> PWR Programs

- Objectives
- Test Assembly Programs
- 2006-2007 Poolside PIEs
- ◆ M5 Experience Summary
- M5 Assembly growth models
- Unexpected Mark-B12 M5 guide tube growth





AREV



2006-2007 PWR Poolside PIEs (cont.)

- > 20 to 48 GWd/mtU Advanced Mark-BW (N. Anna)
 - M5 fuel rods
 - M5 guide tubes
 - M5 intermediate grids with inconel upper & lower end grids
 - Assembly length (23 assemblies)

> 16 to 53 GWd/mtU Mark-B11A (Oconee 2 & 3)

- M5 fuel rods
- M5 guide tubes
- Zirc intermediate grids with inconel upper & lower end grids
- Assembly length (39 assemblies)

> 38 to 49 GWd/mtU Mark-B12 (Davis-Besse)

- M5 fuel rods
- M5 guide tubes
- zircaloy intermediate grids with upper & lower inconel grids
- Assembly length (15 assemblies)

AREV









Fuel & Hardware Testing Programs

> PWR Programs

- Objectives
- Test Assembly Programs
- ◆ 2006-2007 Poolside PIEs
- M5 Experience Summary
- M5 Assembly growth models
- Unexpected Mark-B12 M5 guide tube growth

AREVA NP INC.

.



M5 Experience Summary

- > PIE data from 19 plants, 36 rods evaluated in hot cell, BU 71 GWd/mtU
- > Corrosion well behaved at high burnup
- > Fuel Rod Growth
 - M5 fuel rod growth supports existing M5 model
 - U.S. data is consistent with worldwide data but is on the low side of the range
 - Rod growth slows above 40 GWd/MTU
- > Fuel Assembly Growth
 - Fuel assembly growth of Mark-BW & Advanced Mark-BW are higher than expected but within bounds of the design criteria
 - Mark-B12 batch 16 anomalous growth identified at TMI-1; Davis-Besse B12 growth rate consistent with non-batch 16 TMI-1 growth
 - Mark-B11A M5 fuel assembly growth is similar to non-batch 16 TMI-1 B12 and is somewhat higher than expected
 - Mark-B-HTP assembly growth measurements indicate low growth rates early in life with increasing rates later in life
 - Dependent on structure
















Fuel & Hardware Testing Programs

> PWR Programs

- Objectives
- Test Assembly Programs
- 2006-2007 Poolside PIEs
- M5 Experience Summary
- M5 Assembly growth models
- Unexpected Mark-B12 M5 guide tube growth















Fuel & Hardware Testing Programs

> PWR Programs

- Objectives
- Test Assembly Programs
- ◆ 2006-2007 Poolside PIEs
- M5 Experience Summary
- M5 Assembly growth models
- Unexpected Mark-B12 M5 guide tube growth



Unexpected Mark-B12 M5 Guide Tube Growth

- > History
- > Extent of condition
- > Status & Follow up measurements
- > Next Steps
- > Conclusions

AREVA

Unexpected Mark-B12 M5 Guide Tube Growth History: 01

> Measured 24 fuel assemblies in May '07

- Inspections planned for baffle interaction PIE
- Growth measurements added to increase database
- > All assemblies measured were of same batch
 - M5 fuel rods and guide tubes, Zr-4 intermediate grids
- > All assemblies at about 48 GWd/mtU
- > All assemblies exhibited a growth rate much higher than expected – even higher than expected for zircaloy
- > Increasing shoulder gap observed
 - Considered an anomaly for any structure with the same fuel rod cladding and guide tube material





Unexpected Mark-B12 M5 Guide Tube Growth History: 03

- > Issue resulted in hard contact with reactor internals
- > Actions taken
 - Fuel and reactor internals evaluations complete that assure continued safe operation
 - Measurements taken to confirm growth is within design limits for other fuel designs and reactors
 - Upper end fittings replaced on Mark-B12 fuel (TMI and D-B)
 - Extensive review of material characteristics

AREVA

Unexpected Mark-B12 M5 Guide Tube Growth Extent of Condition: 01

- > TMI was the lead plant for Mark-B12 and is finishing their 3rd Cycle with the FA's
- > Davis Besse will complete their 2nd Cycle with Mark-B12 FA's on December 30th
- > Oconee-2 will complete their 3rd Cycle with Mark-B11A (similar to B12) FA's on October 20th
- > Crystal River-3 will complete their 2nd Cycle with Mark-B HTP FA's on November 3rd



Unexpected Mark-B12 M5 Guide Tube Growth Status: 01

- > Current emphasis is on root cause analysis, material characterization and development of predictive growth tool
- > Recommend continued fuel growth measurements to confirm absence

Focusing on finding causes and implementing solution



Unexpected Mark-B12 M5 Guide Tube Growth Status: 02

- > Material/Chemistry Investigations Completed
 - Material composition of ingot
 - Microstructure of archive GT material
 - Texture of archive GT material
 - Guide tube oxide at TMI
 - Creep tests (uniaxial and biaxial) of archive GT material
 - Plant chemistry investigation
 - Measurements of FAs using same M5 ingot material at other reactors (OCO fuel rods – SQN & D-B not completed)
 - No single material related contributor identified to date
- > Assembly Design Investigations
 - Effects of increased slip load on FA growth
 - Using predictive tool to generate "relative" design behavior
 - Comparison with almost identical B11A design at OCO show that B12 growth at TMI is not expected based on GT stress conditions alone; increased slip load alone could not have caused condition



Unexpected Mark-B12 M5 Guide Tube Growth Status: 03

> Assembly Manufacture Investigations

- Review of as-built data (lengths, grid cells, certs, specs)
- Review of guide tube manufacturing process (Cezus)
- Archive component testing
 - Holddown spring tests in hot conditions completed
 - Grid slip load tests with Zr-4 and M5 fuel rods completed
- > International task force of global AREVA experts created, applying additional resources to
 - Explain the cause of high growth at TMI
 - Validate design sensitivities and key design attributes





Unexpected Mark-B12 M5 Guide Tube Growth Next Steps

- > Complete TMI and North Anna LTA GT segment Hot Cell Exams - 4/08
- > Complete creep tests on additional archive samples (Mark-B11 and Mark-B-HTP) – 3/08
- > Evaluate results and issue findings 4/08
- > Continue to monitor fuel behavior
 - Catawba 1 Advanced Mark-BW (MOX) 6/08
 - North Anna 2 Advanced Mark-BW 9/08
- > Incorporate results in design tools ongoing

Plan in place to identify causes



Unexpected Mark-B12 M5 Guide Tube Growth Conclusions

- > Fuel assembly growth was higher than anticipated and to-date is not fully explained
- > A comprehensive guide tube material examination program has not yet found an M5 material effect
- > RCA and technical investigations continuing to improve understanding and identifying solution
- > Monitoring operating experience and collecting PIE will validate solution

AREVA on track to resolving issue



Conclusion

Ronnie L. Gardner Manager, Site Operations & Corporate Regulatory Affairs

AREVA NP INC.

Fuel Performance Meeting Slides - April 9, 2008