



Fort Calhoun Station  
P.O. Box 550  
Fort Calhoun, NE 68023

April 30, 2008  
LIC-08-0057

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

References: 1) Docket No. 50-285  
2) Letter LIC-06-0095 from H. J. Faulhaber to Document Control Desk,  
dated September 5, 2006, LER 2006-002 Rev. 0

**Subject: Licensee Event Report 2006-002 Revision 1 for the Fort Calhoun Station**

In accordance with 10 CFR 50.73(a)(2)(v)(B), enclosed is a supplement to the subject report concerning inadequate design control resulting in potentially insufficient auxiliary feedwater flow. The purpose of this supplement is to provide the results of an updated root cause analysis.

This letter contains no commitments to the NRC. If you should have any questions, please contact me.

Sincerely,

T. R. Nellenbach  
Division Manager – Nuclear Operations

TRN/RMC/rmc

Attachment

c:  
E. E. Collins, NRC Regional Administrator, Region IV  
M.T. Markley, NRC Senior Project Manager  
J. D. Hanna, NRC Senior Resident Inspector  
INPO Records Center

IE22  
NRR

**LICENSEE EVENT REPORT (LER)**

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to [infocollects@nrc.gov](mailto:infocollects@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

<b>1. FACILITY NAME</b> Fort Calhoun Station	<b>2. DOCKET NUMBER</b> 05000285	<b>3. PAGE</b> 1 OF 7
---	-------------------------------------	--------------------------

**4. TITLE**  
Inadequate Design Control Results in Potentially Insufficient Auxiliary Feedwater Flow

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
07	07	2006	2006	002	01	04	30	2008		05000
									FACILITY NAME	DOCKET NUMBER
										05000

<b>9. OPERATING MODE</b>  1	<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)</b>									
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)						
<b>10. POWER LEVEL</b>  100	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)						
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)						
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)						
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)						
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)						
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER						
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A						

**12. LICENSEE CONTACT FOR THIS LER**

FACILITY NAME: Erick Matzke, Compliance Engineer	TELEPHONE NUMBER (Include Area Code) 402-533-6855
---	--

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

<b>14. SUPPLEMENTAL REPORT EXPECTED</b> <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	<b>15. EXPECTED SUBMISSION DATE</b>	MONTH	DAY	YEAR

**ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)**

During equipment train reviews by the Equipment Reliability Optimization Project in July, 2006, it was noted that the power supply to flow transmitter FT-1368 was from non-safety related Instrument Bus 1 (AI-42A). The flow transmitter performs a safety related function for recirculation valve FCV-1368, associated with the electric auxiliary feedwater pump (FW-6). Upon discovery, on July 7, 2006, FW-6 was declared inoperable.

A 1997 revision to a calculation originally prepared in 1989 concluded that the closure function of FCV-1368 was safety-related. However, engineering department procedures and processes did not provide clear direction as to the appropriate process to employ when a change to a credited design function and/or safety classification was discovered. Therefore, the lack of appropriate engineering processes is identified as the Root Cause of this condition.

FW-6 was declared operable on July 8, 2006, based on the design quality level of the power supplies to the recirculation valve components and compensatory actions taken.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)		
Fort Calhoun Nuclear Station	05000285	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	OF	7
		2006	- 002	- 01			

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

BACKGROUND

The Auxiliary Feedwater (AFW) system is provided for storage, pumping and delivery of makeup water to the steam generators in order to remove decay heat if the Main Feedwater (MFW) System is not available. The AFW system consists of one emergency feedwater storage tank; one motor-driven (FW-6) and one turbine-driven (FW-10) AFW pump; one non-safety-related, diesel-driven AFW pump (FW-54); one non-safety-related diesel fuel oil transfer pump and day tank; non-safety-related fuel oil piping and valves; remotely operated flow control valves; interconnecting piping to the MFW system and piping to the auxiliary feedwater nozzles in the steam generators. FW-6 and 10 are the safety related AFW pumps. The minimum flow recirculation valve for FW-6 is FCV-1368. The minimum flow recirculation valve for FW-10 is FCV-1369.

FW-54 is the startup auxiliary feedwater pump. FW-54 takes a suction from the condensate storage tank and discharges to the normal feedwater header. FW-54 and its associated equipment are not safety related.

The AFW system provides a redundant means of supplying one or both Steam Generators (SGs) with feedwater. Operation of the safety related portion of the AFW system is automatically initiated on a low steam generator water level or manually initiated as follows:

- Automatic initiation via an Auxiliary Feedwater Actuation Signal (AFAS).
- Automatic start signals to the safety-related pumps (FW-6 and FW-10).
- Manual initiation from the Control Room.
- Manual initiation from alternate shutdown panel for FW-10 and the AFW injection valves.
- Locally at each pump

The system is designed to add feedwater to either or both steam generators under any condition, including the loss of all electrical power along with the loss of the MFW system and the loss of the main steam piping downstream of the main steam isolation valves. The AFW system fulfills both safety-related and non-safety-related functions. See Figure 1.

EVENT DESCRIPTION

From original construction until 1998, the Updated Final Safety Analysis Report (USAR) Section 9 (Auxiliary Systems) Part 4 (Auxiliary Feedwater System) was unclear about the function of the safety related AFW pump recirculation valves (FCV-1368/1369). The text had stated, "The system can be operated without the recirculation valves." It was unclear if this meant without recirculation available, i.e., with the recirculation valves closed, or if it means without the recirculation valves available, i.e., failed open and unable to close on demand. The context of the USAR implied that the availability of the recirculation valves is irrelevant to the system performing its design function, so long as the fail position of the recirculation valves protects the pumps from damage. The valves (FCV-1368/1369) themselves have always been safety related from a pressure boundary and pump protection perspective, however, the ability of FCV-1368 to close on demand was not a recognized safety function.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)		
Fort Calhoun Nuclear Station	05000285	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	OF	7
		2006	- 002	- 01			

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

Maximum SG pressure was given as 1000 psig in the original USAR, and the pump was considered to have ample discharge head to provide adequate accident mitigating flow regardless of flow diverted through the recirculation path. The valve and its actuating logic circuitry were designed to be normally open, with no instrument air or power to the solenoid or its associated flow transmitter loop required. The valve was designed to fail open upon loss of air or power from the time of original construction. Until 1989 no analyses had been conducted to conclude that the recirculation valves should be required to close following an AFAS. The air supply and associated actuation circuitry were appropriately classified as non-safety related.

Stone and Webster Company (SWEC) prepared calculation 17321.01-PM-5 (FCS calculation number FC05365) in April, 1989. This assumed both AFW recirculation valves (FCV-1368/1369) are open and 200 gpm AFW flow required with SG pressure equal to 1015 pounds per square inch absolute (psia). In December of 1989 calculation FC05361 replaced FC05465. It also assumed that FCV-1368 and FCV-1369 were failed open and 200 gallons per minute (gpm) was available as required at 1015 psia in the SG.

In March of 1990, MR-FC-85-128 was installed, which included an update to FIC-1368 (the controller for FCV-1368) and its associated power supply components. To maintain system reliability, these were procured to safety related quality standards, though the need for the recirculation valve control loop to remain operable post-accident had not yet been identified.

In 1992, safety related air accumulators and check valves were added to the air supplies to each AFW recirculation valve. This work was part of modification MR-FC-88-017, which installed FW-54. This modification increased the overall reliability of the AFW system. The modification repeated the conclusion of the calculation of record, FC05361. FC05361 concluded that the AFW pumps could still fulfill their safety function with their recirculation valves open. However, the margin of safety would be increased if the recirculation valves were available assuming a loss of instrument air. Therefore, accumulators and check valves were added to the recirculation valve air supply. This enhanced their reliability. The parts were installed as safety related components.

Condition Report (CR) 199700457 written in April, 1997 questioned the bases of calculation FC05361 regarding SG pressure and required AFW flow. The calculation did not account for the Main Steam Safety Valve (MSSV) three percent setpoint tolerance or the additional three percent MSSV back pressure accumulation which made the maximum SG pressure higher than accounted for by the calculation.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)		
Fort Calhoun Nuclear Station	05000285	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4	OF	7
		2006	- 002	01			

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

Calculation FC05361 revision 4 was issued in May, 1997. This revision to FC05361 corrected errors in the previous revision and concluded that FCV-1368 needed to be closed to supply sufficient flow to the SGs during certain AFW demand scenarios. Revision 4 used the corrected value of 1056 psia maximum SG pressure, versus 1015 psia used in the original calculation. At this time, the ability to close FCV-1368 was recognized as a safety-related function. In 1998 the USAR was changed to explicitly state that the recirculation valve for FW-6 had to be closed to provide design flow at design pressure. Design engineering mechanical personnel preparing and reviewing the calculation consulted with design engineering electrical personnel as to the safety classification of the components controlling the FCV-1368 closing function. This consultation was brief, informal, and not documented. No formal multidisciplinary review of the calculation was conducted to comprehensively evaluate the safety classification of the control circuitry. It was concluded that FCV-1368's closing function was safety related based on the safety related air accumulators and safety related power supply to the solenoid controlling the FCV-1368 air supply.

During equipment train reviews by the Equipment Reliability Optimization Project (EROP) in July, 2006, it was noted that flow transmitter FT-1368 was supplied from non-safety related Instrument Bus 1 (AI-42A). CR 200602855 was issued.

On July 7, 2006, at 1700 CDT FW-6 was declared inoperable. At 1856 CDT on July 7, 2006, an eight (8) hour notification was made to the NRC Headquarters Operation Office (HOO) per 10 CFR 50.72 (b)(3)(v)(B). This report is being made per 10 CFR 50.73(a)(2)(v)(B).

**CONCLUSION**

Revision 4 to calculation FC05361, issued in May 1997, concluded that the FCV-1368 closure function was safety-related. However, engineering department procedures and processes did not provide clear direction as to the appropriate process to employ when a change to a credited design function and/or safety classification was discovered.

Further, had clear procedural direction existed at the time of discovery it is possible that such a review by appropriate engineering disciplines would have identified that the original analysis in calculation FC05365 did not incorporate the appropriate maximum SG pressure then existing in the USAR.

Therefore, the lack of appropriate engineering processes is identified as the Root Cause of this condition.

**CORRECTIVE ACTIONS**

FW-6 was determined to be operable on July 8, 2006, following further engineering evaluation. A safety-related power supply was provided to FCV-1368 during the 2006 refueling outage.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)		
Fort Calhoun Nuclear Station	05000285	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5	OF	7
		2006	- 002	01			

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

Procedure PED QP-3, "Calculation, Review and Approval" procedure was issued on March 4, 2008 to ensure that appropriate engineering processes are used when a design function/safety classification change is discovered.

Procedure changes to prevent recurrence of this type event have been implemented.

**SAFETY SIGNIFICANCE**

While the failure of instrument bus number 1 during an auxiliary feedwater demand could result in inadequate performance of FW-6 for the purpose of decay heat removal, the likelihood of such failure is very small. Electrical components designated as safety related are qualified in accordance with IEEE (Institute of Electrical and Electronics Engineers) 344-1975 (Seismic Qualification of Class 1E Equipment) and IEEE 323-1983 (Standard for Qualifying 1E Equipment for Mild and Harsh Environment). Additional research for the non-safety related control loop components for FCV-1368 has indicated that there is documentation to demonstrate that the non-safety related control loop components for FCV-1368 were purchased as safety related devices. Further, review of seismic documentation for the control loop components identified seismic qualification reports or equivalent documentation for all of the control devices. All of these devices are seismically mounted and are located in a mild environment. It has been concluded that the control loop devices were purchased and mounted as safety related devices and will perform in an acceptable manner, without failure, in the event of an auxiliary feedwater demand scenario.

Non-safety related instrument bus AI-42A and associated components including inverter #1, bypass transformer EE-4S, associated power and control cables and distribution circuit breakers are all designated as non-safety related. However, they are expected to perform reliably in a manner consistent with safety related counterparts for the following reasons: 1) all components are virtually identical to corresponding components in safety related instrument buses. Inverter #1 was designed and built to the same level of quality as the safety related inverters and is seismically mounted. 2) Inverter #1 is located such that separation is maintained from instrument power of the opposite train. 3) Non-safety related Instrument Bus #1 is mounted in a panel which is identical to safety related instrument bus panels. 4) Cables for Instrument Bus #1 are identical in quality to those used for safety related bus applications. 5) Inverters and breakers are maintained and tested to the same level of rigor as safety related devices. 6) Non-safety related bus components have historically performed at a high level since their installation in the mid 1980s. 7) The power source for Inverter #1 is DC Bus #1, a highly reliable source of power, backed up by a safety related battery, which also supplies the safety related inverters.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)		
Fort Calhoun Nuclear Station	05000285	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	6	OF	7
		2006	- 002	01			

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

In addition, the non-safety related components discussed above are tested and maintained in a manner similar to that of safety related components of the same function.

These arguments support the conclusion that continued high reliability of the non-safety related instrument bus is expected. In addition, for the period of time that this condition continues to exist, the likelihood of failure of the instrument bus during an auxiliary feedwater demand scenario is not significantly different from the safety related instrument buses; therefore, this condition did not have an impact on the health and safety of the public.

**SAFETY SYSTEM FUNCTIONAL FAILURE**

This event does result in a safety system functional failure in accordance with Nuclear Energy Institute (NEI) 99-02, "Regulatory Assessment Performance Indicator Guideline".

**PREVIOUS SIMILAR EVENTS**

LER 2006-S01 documents a similar design control problems.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)		
Fort Calhoun Nuclear Station	05000285	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	7	OF	7
		2006	- 002	01			

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

## AUXILIARY FEEDWATER DIAGRAM




Figure 1