August 2, 2005


Mr. W. D. Nash, General Manager BWX Technologies, Inc. P.O. Box 785 Lynchburg, VA 24505-0785

SUBJECT: INSPECTION REPORT 70-27/2005-203 AND NOTICE OF VIOLATION

Dear Mr. Nash:

The U.S. Nuclear Regulatory Commission (NRC) conducted a routine announced nuclear criticality safety (NCS) inspection at your facility in Lynchburg, Virginia, from July 11 through 15, 2005. The purpose of the inspection was to determine whether activities involving special nuclear material were conducted safely and in accordance with NRC regulatory requirements. An exit meeting was held at the conclusion of the inspection on July 15, 2005. The inspection observations and findings were discussed with you and members of your staff.

The inspection, which is described in the enclosure, focused on: (1) the most hazardous activities and plant conditions; (2) the most important controls relied on for safety and their analytical basis; and (3) the principal management measures for ensuring controls are capable, available, and reliable to perform their function relied on for safety. The inspection consisted of analytical basis review, selective review of related procedures and records, examinations of relevant NCS-related equipment, interviews with NCS engineers and plant personnel, and facility walkdowns to observe plant conditions and activities related to safety basis assumptions and related NCS controls. Throughout this inspection, observations were discussed with your managers and staff.



W. Nash -2-

Based on the results of the inspection, the NRC has determined that a Severity Level IV violation of NRC requirements occurred. The violation was evaluated in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions" (Enforcement Policy), NUREG-1600. The current Enforcement Policy is included on the NRC's web site at www.nrc.gov; select What We Do, Enforcement, then Enforcement Policy. The violation is being cited in the enclosed Notice of Violation (Notice) as a Severity Level IV violation, and the circumstances surrounding it are described in detail in the subject inspection report. The violation is being cited in the Notice because it was identified by the NRC during the inspection. The violation being cited as a Severity Level IV violation is a failure to document that nuclear criticality risk was identified and minimized for process ventilation equipment in areas of the facility not involved in solution processing.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice of Violation when preparing your response. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

In accordance with 10 CFR 2.790 of NRC's "Rules of Practice," a copy of this letter and the enclosure will be available in the public electronic reading room of NRC's Agency-wide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html.

If you have any questions concerning this report, please contact Lawrence Berg, of my staff, at (301) 415-6215.

Sincerely,

/RA/

Melanie A. Galloway, Chief Technical Support Group Division of Fuel Cycle Safety and Safeguards

Docket No. 70-27 License No. SNM-42

Enclosures: (1) Notice of Violation

(2) Inspection Report 70-27/2005-203

W. Nash -2-

Based on the results of the inspection, the NRC has determined that a Severity Level IV violation of NRC requirements occurred. The violation was evaluated in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions" (Enforcement Policy), NUREG-1600. The current Enforcement Policy is included on the NRC's web site at www.nrc.gov; select What We Do, Enforcement, then Enforcement Policy. The violation is being cited in the enclosed Notice of Violation (Notice) as a Severity Level IV violation, and the circumstances surrounding it are described in detail in the subject inspection report. The violation is being cited in the Notice because it was identified by the NRC during the inspection. The violation being cited as a Severity Level IV violation is a failure to document that nuclear criticality risk was identified and minimized for process ventilation equipment in areas of the facility not involved in solution processing.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice of Violation when preparing your response. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

In accordance with 10 CFR 2.790 of NRC's "Rules of Practice," a copy of this letter and the enclosure will be available in the public electronic reading room of NRC's Agency-wide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html.

If you have any questions concerning this report, please contact Lawrence Berg, of my staff, at (301) 415-6215.

Sincerely,

/RA/

Melanie A. Galloway, Chief Technical Support Group Division of Fuel Cycle Safety and Safeguards

Docket No. 70-27 License No. SNM-42

Enclosures: (1) Notice of Violation

(2) Inspection Report 70-27/2005-203

DISTRIBUTION: GWertz, RII

DAyres, RII

MLMoore

BGleaves

AShepard, RII

SCaudill, RII GMorell

ML052080238 *see previous concurrence

INDICATE IN BOX: "E"=COPY W/ATT/ENCL; "C"=COPY W/O ATT/ENCL; "N"=NO COPY								
OFFICE	TSG/FCSS	Е	TSG/FCSS	Е	TSG/FCSS	TSG/FCSS		
NAME	DMorey*		LBerg*		RCesaro*	MGalloway		
DATE	7/ 27 /05		7/ 27 /05		7/ 29 /05	8/ 02 /05		

OFFICIAL RECORD COPY

NOTICE OF VIOLATION

BWX Technologies, Inc. Lynchburg, VA

Docket No. 70-27 License No. SNM-42

During a U.S. Nuclear Regulatory Commission (NRC) inspection from July 11 through 15, 2005, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," NUREG-1600, the violation is listed below:

Safety Condition No. S-1 of Special Nuclear Material License No. 42 requires that material be used in accordance with the statements, representations, and conditions in the license application dated July 14, 1995, and supplements thereto.

The Appendix to Chapter 4 of the License Application requires that the identification and minimization of criticality risk will be documented in the nuclear criticality safety analyses of the systems.

Contrary to the above, on and before July 11, 2005, the licensee failed to document in nuclear criticality safety analyses that risk of criticality was identified and minimized in process ventilation systems other than in the uranium recovery area.

This is a Severity Level IV violation (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, BWX Technologies, Inc. (BWXT), is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with copies to the Regional Administrator, Region II, the NRC resident inspector at BWXT, and the Chief, Technical Support Group, Division of Fuel Cycle Safety and Safeguards, NMSS, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include: (1) the reason for the violation, or, if contested, the basis for disputing the violation or severity level, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previously docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an Order or Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other actions as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Enclosure 1

If you contest this enforcement action, you should also provide a copy of your response, with the basis for your denial, to the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, D.C. 20555-0001.

In accordance with 10 CFR 19.11, you may be required to post this Notice within two working days.

Dated this 2nd day of August 2005

)

U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF NUCLEAR MATERIAL SAFETY AND SAFEGUARDS

Docket No.:

70-27

License No.:

SNM-42

Report No.:

70-27/2005-203

Licensee:

BWX Technologies, Inc.

Location:

Lynchburg, VA

Inspection Dates:

July 11 - 15, 2005

Inspectors:

Lawrence Berg, Criticality Safety Inspector, NRC Headquarters

Dennis Morey, Senior Criticality Safety Inspector, NRC Headquarters

Approved by:

Melanie A. Galloway, Chief Technical Support Group

Division of Fuel Cycle Safety

and Safeguards

EXECUTIVE SUMMARY

BWX Technologies, Inc. NRC Inspection Report 70-0027/2005-203

Introduction

Staff of the U.S. Nuclear Regulatory Commission (NRC) performed a routine and announced nuclear criticality safety (NCS) inspection of the BWX Technologies, Lynchburg, Virginia, facility from July 11 through 15, 2005. The inspection included an on-site review of the licensee programs dealing with plant operations, criticality accident alarm systems, and the NCS program. The licensee programs were acceptably directed toward the protection of public health and safety and in compliance with NRC requirements. The inspection focused on risk-significant material processing activities including fuel fabrication and machining, areas, the uranium recovery area, and process ventilation systems.

Results

- A violation was identified for the failure to document that nuclear criticality risk was identified and minimized for process ventilation equipment in areas of the facility not involved in solution processing.
- NCS quarterly audits were adequate for maintaining acceptable levels of safety.
- Plant operations involving materials were conducted safely and in accordance with written procedures.

REPORT DETAILS

1.0 Summary of Plant Status

Routine fuel manufacturing operations and maintenance activities were conducted in the fuel fabrication areas. Uranium recovery, downblending, and other routine operations and maintenance activities were conducted in the

2.0 NCS Function (88015)

a. Inspection Scope

The inspectors reviewed NCS analyses to determine that criticality safety of risk-significant operations was assured through engineered and human performance (controls) with adequate safety margin/certainty, preparation, and review by capable staff. The inspectors reviewed selected aspects of the following documents:

NCS-1992-054, "Nuclear Safety Release for Ventilation Modifications ," dated May 13, 1992 NCS-1992-050, "NCS Evaluation for Ventilation Modifications ," dated May 7, 1992 NCS-2002-278, "NCS Evaluation dated October 18, 2002 NCS-2003-113, "NCS Analysis Supporting Phases 4 and 5 " dated July 15, 2003 NCS-2005-032, "NCS Analysis and 2," dated February 9, 2005 ", dated March 25, 1998 SER 98-016, "NCS Analysis Section 15.35.4, "Manufacturing," Integrated Safety Analysis, dated July 13, 2005 NCS-2001-325, " November 1, 2001 NCS-1999-049, "NCS Evaluation of HEPA [high-efficiency particulate-air] Filter ", dated March 13, 1999 Bank

b. <u>Obsérvations and Findings</u>

The inspectors determined that analyses were performed by capable NCS engineers, and independent reviews were completed for the evaluations by other qualified NCS engineers. With the exception of the violation discussed below, the inspectors determined that NCS controls for equipment and processes assured the safety of the operations.

The inspectors reviewed licensee evaluation and control of criticality risk in process ventilation systems. The inspectors noted that, in response to previous material accumulation events in the uranium recovery area, the licensee had performed separate criticality analysis of process ventilation systems in that area. The inspectors also noted

that the licensee integrated safety analysis summary contained a section on ventilation for the uranium recovery area. The inspectors noted that other areas of the plant did not include substantive discussion of ventilation in their respective criticality analyses and the licensee had not performed any broad analysis covering these ventilation systems.

The licensee stated that annual surveys of ductwork and HEPA housings along with surveys of discarded HEPA filters led it to conclude that an accumulation of material in the dry ventilation systems sufficient to support criticality was not credible. The inspectors determined that the ventilation surveys showed routine accumulation of material with accumulations in some areas.

Occasional accumulations had been observed. HEPA filter surveys gave similar results. The inspectors concluded that ventilation equipment in dry areas was exposed to more than contamination levels of material, and risk significant upsets were credible. The inspectors determined that licensee survey data indicated that there was no immediate safety concern. The inspectors noted that the licensee relied on upstream NCS controls to prevent accumulation of a critical mass of material in the dry ventilation systems. The inspectors determined that the licensee could not demonstrate with existing documentation that it had analyzed the dry process ventilation systems and minimized the risk of material accumulation.

The Appendix to Chapter 4 of the License Application requires that the identification and minimization of criticality risk will be documented in the nuclear criticality safety analyses of the systems. Contrary to the above, on and before July 11, 2005, the licensee failed to document in nuclear criticality safety analyses that risk of criticality was identified and minimized in process ventilation systems other than in the uranium recovery area. The failure to document the identification and minimization of criticality risk in the criticality safety analyses for ventilation systems other than in the uranium recovery area is **Violation (VIO) 70-27/2005-203-01**.

c. <u>Conclusions</u>

A violation was identified for the failure to document that nuclear criticality risk was identified and minimized for process ventilation equipment in areas of the facility not involved in solution processing.

3.0 Inspections, Audits, and Investigations (88015)

a. Inspection Scope

The inspectors reviewed results of the most recent NCS quarterly audit to assure that appropriate issues were identified and resolved. The inspectors reviewed selected aspects of the following documents:

 NCS-2005-082, "NCS Finding & Observation Summary - 1st Quarter 2005," dated May 3, 2005 NCS-2005-034, "Nuclear Criticality Safety Concern

", dated February 10, 2005

NCS-2005-104, "Triennial NCS External Assessment," dated May 2, 2005

b. Observations and Findings

The inspectors observed that the licensee NCS audits were conducted in accordance with written procedures. The inspectors noted that the audits were performed by NCS engineers who: (1) reviewed open NCS issues from previous audits; (2) reviewed the adequacy of control implementation; (3) reviewed plant operations for compliance with license requirements, procedures, and postings; and (4) examined equipment and operations to determine that past evaluations remained adequate. No safety concerns were noted.

The inspectors observed that the licensee's triennial external assessment of the NCS program had recently been completed and that the auditor had been excluded from one area of the plant where criticality safety controls were used to mitigate risk of inadvertent criticality. The inspectors noted that the previous external auditor had been excluded from the same area. The inspectors were concerned that routinely excluding the external auditors from the same plant area every time would reduce the value of the audit. The inspectors had no immediate safety concerns regarding the excluded area or the overall external audit. The licensee indicated that it understood the concern and would consider the issue when evaluating the access of future external auditors. The reevaluation on the external NCS auditor will be tracked as Inspection Follow-up Item (IFI) 70-27/2005-203-02.

c. <u>Conclusions</u>

NCS quarterly audits were adequate for maintaining acceptable levels of safety.

4.0 Plant Operations (88015)

a. <u>Inspection Scope</u>

The inspectors performed plant walkdowns to review activities in progress and to determine whether risk-significant material operations were being conducted safely and in accordance with regulatory requirements. The inspectors verified the adequacy of management measures for assuring the continued availability, reliability, and capability of safety-significant controls relied upon by the licensee for controlling criticality risks to acceptable levels. The inspectors performed walkdowns of fuel fabrication and machining, process areas, and plant-wide process ventilation systems.

The inspectors reviewed selected aspects of the following documents prior to performing the walkdowns:

•	NCS-1992-054, "Nuclear Safety Release for Ventilation Modifications"," dated May 13, 1992
•	NCS-1992-050, "NCS Evaluation for Ventilation Modifications
	," dated May 7, 1992
•	NCS-2002-278, "NCS Evaluation ,"
•	dated October 18, 2002
•	NCS-2003-113, "NCS Analysis Supporting Phases 4 and 5
	," Dated July 15, 2003
•	NCS-2005-032, "NCS Analysis Phase 1
	and 2," dated February 9, 2005
•	SER 98-016, "NCS Analysis ," dated March 25, 1998
•	Section 15.35.4, "Manufacturing," Integrated Safety Analysis, dated
	July 13, 2005
•	NCS-2001-325, " dated " dated
	November 1, 2001
•	NCS-1999-049, "NCS Evaluation of HEPA Filter Bank
	" dated March 13, 1999
Obser	vations and Findings
<u> </u>	anone and i manige

b.

The inspectors verified that controls identified in NCS analyses were installed or implemented and were adequate to assure safety. The cognizant NCS engineers were knowledgeable and had good interfaces with operators on the process floors. No safety issues were identified during the walkdowns.

Conclusions C.

Plant operations involving materials were conducted safely and in accordance with written procedures.

5.0 **Open Item Review**

IFI 70-27/2005-202-01

This item tracked correction of references						
and subcritical margin for	n the licensee plants of validation report .					
During a previous inspection, the inspector	rs reviewed the was a validation report,					
dated December 15, 2004, and noted that the minimum margins of subcriticality, Δk_{sm} ,						
specified in the report did not include the new limits recently approved by the NRC						
During the same previo	us inspection, the inspectors noted that the					
validation report referenced the	cross section libraries, but					
only included the k _{eff} limits for the	cross section library in Table 1 of the					
validation report. The licensee committed to correct these discrepancies in the						
validation report. During the current inspection, the inspectors reviewed the						
validation report and noted that the references had been corrected. This item is closed.						

IFI 70-27/2005-202-02

This item tracked development of a validation database for demonstrating compliance with the validated range of applicability (ROA). During a previous inspection, the inspectors were concerned that the lack of description regarding the range of tabulated parameters over which different materials were considered validated could lead to the performance of nonconservative calculations that were not covered by the existing validation. During the previous inspection, the licensee indicated that a validation database was in development in which an analyst could electronically enter parameter data to identify validation cases that were applicable to a given situation being calculated. During the current inspection, the licensee showed the inspectors a completed and usable database which could be used to establish compliance with the validated ROA. This item is closed.

IFI 70-27/2005-202-03

This item tracked review of non-benchmark quality validation cases to determine and analyze experimental uncertainties. During a previous inspection, the inspectors noted an unusually large spread in the calculated $k_{\rm eff}$ values, ranging from and noted that several of the cases with the highest and lowest $k_{\rm eff}$ values consisted of poorly described configurations for which experimental uncertainties were not readily available. In response to the inspectors' questions, the licensee stated that establishing the pedigree of validation cases, including use of poorly described configurations and the uncertainties associated with them was in progress at the time of the inspection. During the current inspection, the licensee indicated that the review would be complete by March 15, 2006. This item remains open.

IFI 70-27/2005-202-04

This item tracked examination of individual subsets of data to determine localized bias trends (including reason for low $k_{\rm eff}$ values). During a previous inspection, the inspectors noted an unusually large spread in the calculated $k_{\rm eff}$ values, ranging from which was approximately the same magnitude as the margin of subcriticality. During the previous inspection, the inspectors examined the descriptions of both the highest and lowest $k_{\rm eff}$ cases and observed that many of the cases with a large negative bias involved material forms and compositions that were significantly different from analyzed process conditions. In response to the inspectors' questions, the licensee stated that examining subsets of the data to determine the reasons for the large positive and negative biases was already in progress at the time of the inspection. During the current inspection, the licensee indicated that the review would be complete by September 30, 2005. This item remains open.

6.0 Exit Meetings

The inspectors presented the inspection scope and results to members of the licensee's management and staff during an exit meeting on July 15, 2005. The licensee acknowledged and understood the findings as presented.

SUPPLEMENTARY INFORMATION

1.0 List of Items Opened, Closed, and Discussed

Opened

VIO 70-27/2005-203-01

Failure to document the identification and minimization of criticality

risk in the criticality safety analyses for ventilation systems other

than in the uranium recovery area.

IFI 70-27/2005-203-02

Tracks the reevaluation

on the external NCS

auditor.

Closed

IFI 70-27/2005-202-01

Tracks correction of references to the

cross

section libraries and subcritical margin for licensee validation report.

IFI 70-27/2005-202-02

Development of the validation database for demonstrating

compliance with the validated ROA.

Discussed

IFI 70-27/2005-202-03

Reviewing non-benchmark quality validation cases; determining

and analyzing experimental uncertainties.

IFI 70-27/2005-202-04

Examining individual subsets of data to determine localized bias

trends (including reason for low k_{eff} values).

2.0 Inspection Procedures Used

IP 88015

Headquarters Nuclear Criticality Safety Program

Attachment

3.0 Partial List of Persons Contacted

BWXT

* W. Nash General Manager

* L. Duncan Manager, Nuclear Criticality Safety

* L. Morrell Manager, Licensing

* S. Schilthelm Manager, Safety and Licensing

* D. Ward Manager, Environment, Safety, Health, and Safeguards

M. Mitchell
L. Wetzel
B. Kidd
NCS Engineer
NCS Engineer
NCS Engineer

NRC

*D. Morey Senior Criticality Safety Inspector

*L. Berg Criticality Safety Inspector *N. Jordan Criticality Safety Inspector *G. Wertz Senior Resident Inspector

4.0 List of Acronyms

ADAMS Agency-wide Document Access and Management System

BWXT BWX Technologies, Inc.
CFR Code of Federal Regulations
HEPA high-efficiency particulate-air
inspection follow-up item
inspection procedure
LEU low-enriched uranium
NCS nuclear criticality safety

NMSS Office of Nuclear Material Safety and Safeguards

NRC U.S. Nuclear Regulatory Commission
ORNL Oak Ridge National Laboratory

PDR public document room

ROA range of applicability (also referred to as area of applicability)
SCALE standardized computer analyses for licensing evaluation

SNM special nuclear material

VIO violation

^{*}Participated in the exit meeting on July 15, 2005.