

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Bronson Methodist Hospital
601 John Street
Kalamazoo, MI 49007

REPORT NUMBER(S)

2. NRC/REGIONAL OFFICE
U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road
Suite 210
Lisle, Illinois 60532-4351

3. DOCKET NUMBER(S)
030-02146

4. LICENSEE NUMBER(S)
21-13125-01

5. DATE(S) OF INSPECTION
May 23, 2008

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

pdj

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Robert P. Hays		5/23/08

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Bronson Methodist Hospital		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
REPORT NUMBER(S) 2008-001			
3. DOCKET NUMBER(S) 03002146	4. LICENSE NUMBER(S) 21-13125-01	5. DATE(S) OF INSPECTION May 23, 2008	
6. INSPECTION PROCEDURES USED 87131 (10/24/02)		7. INSPECTION FOCUS AREAS 03.01-03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02240	2. PRIORITY 2	3. LICENSEE CONTACT Mark Watts, RSO	4. TELEPHONE NUMBER 269-341-6240
------------------------------------	-------------------------	---	--

Main Office Inspection Next Inspection Date: May 2010

Field Office 424 (525) South Park Street, Kalamazoo, MI

Temporary Job Site Inspection

PROGRAM SCOPE

The licensee was a medical institution located in Kalamazoo, Michigan and authorized by the license to use any byproduct material permitted by 10 CFR 35.100, 35.200, 35.300, 35.400, one 35.1000 source used for intravascular brachytherapy, and a irradiator for irradiation of blood components.

The previous routine inspection reviewed licensed activities at all locations listed on the license at that time with no violations or concerns identified. Since the previous inspection, the licensee had added another location of use to the license, 424 South Park Street, authorized to use any byproduct material permitted by 10 CFR 35.100, 35.200, or 35.300 and was the subject of this inspection. Licensed activities pertaining to the blood irradiator were also reviewed during this inspection and are detailed in inspection report no. 03002146/2008-002. At the 424 South Park Street facility, licensed activities had not been initiated because renovation work had not been completed at the time of the inspection. The inspection determined that the wrong numerical street address had been used for the location of use. The facility's actual address is 525 South Park Street. The RSO will submit an amendment request to correct the numerical address of the facility. The inspection also determined that no licensed activities have been conducted under 10 CFR 35.1000 since the previous inspection, therefore, no performance-based licensed activities were reviewed.