



**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**

1. LICENSEE <b>CRD &amp; Associates, Inc.</b> REPORT NUMBER(S) <b>2009-001</b>		2. NRC/REGIONAL OFFICE <b>Region III</b> <b>2443 Warrenville Road, Suite 210</b> <b>Lisle, IL 60532</b>	
3. DOCKET NUMBER(S) <b>030-35629</b>	4. LICENSE NUMBER(S) <b>24-24559-02</b>	5. DATE(S) OF INSPECTION <b>6/ 2 /2008</b>	
6. INSPECTION PROCEDURES USED <b>87124</b>	7. INSPECTION FOCUS AREAS <b>1 through 7</b>		

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) <b>03121</b>	2. PRIORITY <b>5</b>	3. LICENSEE CONTACT <b>Carl Rapp, RSO</b>	4. TELEPHONE NUMBER <b>314- 909-9600</b>
------------------------------------	-------------------------	--	---

Main Office Inspection \_\_\_\_\_ Next Inspection Date: 8/20/13

Field Office St. Louis International Airport

Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

The licensee is a small civil engineering firm employing ten individuals. The licensee is physically located at the St. Louis Lambert Airport. The licensee possessed three moisture/density gauges (serial Nos. 4452, 4459 and 4451) that are used occasionally for soil/asphalt compaction tests at the airport. The licensee had three (3) approved gauge users that successfully completed the manufacturer's training course. The licensee did not perform any service or maintenance activities on its gauges; these services were performed by the device manufacturer.

During this inspection, the inspectors toured the gauge storage area and surveyed the gauge storage room, interviewed selected licensee personnel, and reviewed selected records. Licensee personnel discussed and demonstrated security measures in the field, transportation procedures and emergency procedures. At the time of this inspection the gauges were not in use. Therefore, the inspectors were unable to conduct a field inspection. The licensee was aware of the double barrier rule (10 CFR 30.34(1)) and demonstrated to the inspectors how the gauges are stored and transported to the job site. Leak tests were current (April and October 2007) and records indicated that the sealed sources were not leaking.

No violations of NRC requirements were identified.