Exelon Generation Company, LLC Dresden Nuclear Power Station 6500 North Dresden Road Morris, IL 60450-9765 www.exeloncorp.com

10 CFR 50.73

Nuclear

Exel

SVPLTR # 08-0038

June 23, 2008

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

> Dresden Nuclear Power Station, Units 2 and 3 Renewed Facility Operating License Nos. DPR-19 and DPR-25 <u>NRC Docket Nos. 50-237 and 50-249</u>

Subject: Licensee Event Report 237/2008-003-00, "Control Room Emergency Ventilation Air Conditioning System Inoperable Due To Excessive Vibration"

Enclosed is Licensee Event Report 237/2008-003-00, "Units 2 and 3 Control Room Emergency Ventilation Air Conditioning System Inoperable Due To Excessive Vibration," for Dresden Nuclear Power Station, Units 2 and 3. This event is being reported in accordance with 10 CFR 50.73(a)(2)(v)(D), "Any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident."

Should you have any questions concerning this report, please contact Mr. Bob Rybak, Acting Regulatory Assurance Manager, at (815) 416-2800.

Respectfully,

SWarnak

David B. Wozniak Site Vice President Dresden Nuclear Power Station

Enclosure

cc: Regional Administrator – NRC Region III NRC Senior Resident Inspector – Dresden Nuclear Power Station

AIOZ TEZZ NRR

NRC FORM 366			U.S. NUCLEAR REGULATORY COMMISSION						APPROVE	ED BY OMB	: NO. 3150-010)4	EXPIRES:	06/30/2007			
(6-2004) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)									Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internel e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.								
1. FACILITY NAME							2. DOCK	DOCKET NUMBER 3. PAGE									
Drese	den Nu	iclear P	ower S	tation, Un	it 2					0500023	37	1 OF 3					
4. TITLE Control	Room	n Emerg	ency V	entilation	Air Co	nditionin	g Syster	m Inop	erable D	Due To E	xcessive V	ibration					
5. E	VENT D	ATE	6. LER NUMBER				7. REPORT DATE			8.	OLVED	VED					
MONTH	DAY	YEAR	YEAR	SEQUENTIA NUMBER	L REV NO.	MONTH	DAY	YEAR	Dresc	den Unit	3		05000249				
04	23	2008	2008	- 003	- 00	06	23	2008	B N/A	TY NAME			DOCKET	DOCKET NUMBER			
9. OPER	9. OPERATING MODE 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)																
1 10. POWER LEVEL 100			$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$)(3)(i))(3)(ii))(4))(i)(A))(ii)(A))(ii))(ii))(i)(A))(i)(B)	$ \begin{bmatrix} 50.73(a)(2)(i)(C) \\ 50.73(a)(2)(ii)(A) \\ 50.73(a)(2)(ii)(A) \\ 50.73(a)(2)(ii)(B) \\ 50.73(a)(2)(iii)(B) \\ 50.73(a)(2)(iii) \\ 50.73(a)(2)(iii) \\ 50.73(a)(2)(iv)(A) \\ 50.73(a)(2)(v)(A) \\ 50.73(a)(2)(v)(A) \\ 50.73(a)(2)(v)(B) \\ 50.73(a)(2)(v)(B) \\ 50.73(a)(2)(v)(B) \\ 50.73(a)(2)(v)(B) \\ 50.73(a)(2)(v)(B) \\ 50.73(a)(2)(v)(C) \\ 50.73(a)(2)(v)(C) \\ 50.73(a)(2)(v)(D) \\ 50.73(a)(2)(v)(D)$								
					1	2. LICENS	SEE CON	TACT FO	OR THIS L	LER			INAC FORM	300A			
FACILITY N Dresde	iame In Nucl	ear Pov	ver Stat	tion – Geo	orge Pa	apanic Jı	r.				TELE (81	рноне пимв 5) 416-28	ER (Include Ar 15	ea Code)			
			13. COM	IPLETE ON	E LINE I	FOR EAC	н сомро	NENT F	AILURE	DESCRIB	ED IN THIS R	EPORT					
CAUSE		SYSTEM	СОМРО	NENT FAC	ANU- TURER	REPOP TO E	RTABLE EPIX	C/	AUSE	SYSTEM	COMPONENT	MANU- FACTURE	R TC	ORTABLE DEPIX			
NA									NA								
14. SUPPLEMENTAL REPORT EXPECTED					FED		15. EXPECTE			MONTH	DAY	YEAR					
□ YE	S (If yes	s, complet	te 15. EX	PECTED SU	JBMISS		5)	\boxtimes	NO								
ABSTRA	CT (Lim	nit to 1400	spaces.	i.e., approxi	matelv 1	15 sinale-si	paced type	ewritten	lines)			-					

On April 23, 2008, at approximately 2300 hours (CDT), with both Units 2 and 3 operating at approximately 100 percent power, the Control Room Emergency Ventilation Air Conditioning System was in operation to perform a post maintenance test. During the activity, the Control Room Emergency Ventilation Air Conditioning System experienced excessive vibration. Technical Specification 3.7.5, "Control Room Emergency Ventilation Air Conditioning (AC) System," was entered. The system was restored to operable status on May 1, 2008. This event is being reported in accordance with 10 CFR 50.73(a)(2)(v)(D), "Any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident," as the Control Room Emergency Ventilation Air Conditioning System is a single train system.

The apparent cause is attributed to the lack of lubrication due to the oil in the compressor being displaced by refrigerant. Liquid refrigerant accumulates in the compressor due to liquid floodback during operation and flooded starts. Following the completion of the actions associated with the equipment apparent cause analysis, Plant Engineering will evaluate system operation to determine the effectiveness of the actions taken. Based on this evaluation, if it is determined that system reliability has not been improved, further actions will be developed and implement, as appropriate.

NRC F((1-2001)	DRM 366A		U.S. NUCLEAR RE	GULATORY COMMISSION						
(* === *)	LICENS	SEE EVENT R	EPORT (LER)							
	FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)	PAGE (3)						
			YEAR NUMBER NUMBE							
Dresd	en Nuclear Power Station Unit 2	05000237	2008 003 00	2 OF 3						
NARRA	TIVE (If more space is required, use additional copie	s of NRC Form 366	4) (17)							
 Dresden Nuclear Power Station (DNPS) Units 2 and 3 are General Electric Company Boiling Water Reactors with a licensed maximum power level of 2957 megawatts thermal. The Energy Industry Identification System codes used in the text are identified as [XX]. A. Plant Conditions Prior to Event: Unit: 02 Event Date: 04-23-2008 Reactor Mode: 1 Mode Name: Power Operation Power Level: 100 percent Reactor Coolant System Pressure: 1000 psig 										
Β.	Description of Event: On April 22, 2008 at 1300 hours, with both Units 2 and 3 operating at approximately 100 percent power, Operations personnel started the 'B' Control Room HVAC system [VI] for Dresden Operating Surveillance DOS 5750-04, Control Room Train B HVAC and Air Filtration Unit Surveillance. The system was required to operate for at least ten (10) hours to satisfy the surveillance requirements. Prior to the system start, the Electrical Maintenance Department (EMD) had completed Preventive Maintenance work order (PM) 1018688, which included obtaining a compressor oil sample and the compressor head valves being successfully tested for leakage. In addition to the DOS being performed to satisfy Technical Specification (TS) surveillance requirement (SR) 3.7.4.1, it was also being used to satisfy post maintenance testing requirements for the maintenance activities. On April 23, 2008, while the system was still in operation, the compressor was observed to be vibrating excessively. Vibration analysis confirmed the compressor was vibrating above acceptable limits. Consequently, the system was secured and declared inoperable. TS Action 3.7.5.A.1 was entered due to the inoperability.									

Subsequent troubleshooting revealed normal vibration levels during an uncoupled run of the compressor motor. Therefore, it was concluded that the compressor was the source of the excessive vibrations that had been observed. A work package was initiated to replace the compressor. The work was completed and the system was restored to operable status on May 1, 2008 at 0600 hours.

This event is being reported in accordance with 10 CFR 50.73(a)(2)(v)(D), "Any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident," as the CREVS is a single train system.

C. Cause of Event:

ņ

The failed compressor was shipped to the vendor to determine the failure mode. Upon disassembly, the following was observed: compressor piston rod broke, another rod heavily scored, dull piston skirts, heavily scored throw for rods #10, #11, and #12 and sharpened rings.

The cause of the event was attributed to premature degradation of compressor internals due to a lack of lubrication. Vendor failure analysis from inspection of the degraded compressor internals has determined the lack of lubrication is the result of liquid refrigerant floodback and flooded starts. Floodback occurs when a portion of the refrigerant returning to the compressor is in liquid form. Flooded Start describes a lack of lubrication when the compressor starts due to the oil being diluted

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION											
LICENSEE EVENT REPORT (LER)											
	FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)					PAGE (3)			
			YEAR		SEQUENTIA NUMBER	L.	NUMBE				
Dreso	den Nuclear Power Station Unit 2	05000237	2008		003		00	3	OF	3	
NARR	ATIVE (If more space is required, use additional copie	s of NRC Form 366	6A) (17)								
	by refrigerant, which migrates back to liquid refrigerant acts like a solvent an failure analysis and operating experie vulnerable. This was confirmed by the from the oil pump.	the compress d washes the nce, the pistor e failed rods #	sor during oil from th ns farthes 11 and da	the he b t aw ama	off cycle earings ay from ged rod	e ar . B the #1:	nd mixe ased or e oil pur 2, being	es with n the ve mp to b g the fa	the oil. endor's e most arthest a	The away	
	Although the cause could not be dete floodback and flooded starts.	rmined, the m	ost likely d	caus	se is attr	ibu	ted to t	he com	ibinatio	n of	
D.	<u>Safety Analysis:</u>										
	The Control Room Heating, Ventilatio HVAC Systems. One system is a non 5731, a return air fan, 2/3-5728, and t is the safety related "B" Train HVAC S 9400-100, an air filtration unit, 2/3-940 accordance with General Design Crite room habitability in the event of a Des Control Room between 70 and 80 deg	n and Air Con -safety related wo (2) 50 pero System (i.e. Cl 20-101, and a erion 19, "Con sign Basis Acc grees F.	ditioning (1 "A" Train cent RCUs REVS) cor RCU, 2/3 trol Room ident. The	HV/ s. Ti mpr -94(Ha sys	AC) Sys stem wit he secol ised of a 00-102. bitability stem is o	terr th a nd o an a This y," to des	n is des n air ha of the tw air hanc s syster o maint igned to	igned v andling wo HV/ Iling ur m is de ain the o main	with two unit, 2/ AC syst nit, 2/3- esigned control tain the	o (2) /3- tems in I	
	The safety significance of the event is the requirements of the TS. The oper established the plant's technical speci the capability to isolate and pressurize radiological or toxic gas event. Theref health and safety of the public and rea	a minimal. Dur rability of the s ifications. Add the control re fore, the conse actor safety.	ring this ev system wa ditionally, f oom envel equences	vent s re the lope of tl	t, DNPS store we CREVS in the e nis even	co ell v du eve t ha	ntinued vithin th ring this nt of a 1 ad minii	to ope ne com s event postula mal imp	erate wi pletion : mainta ited pact on	thin time ained the	
Е.	Corrective Actions:			•							
	The compressor was replaced and the system was successfully returned to service on May 1, 2008.										
	Engineering will verify performance of the system's thermal expansion valves and take additional actions, as appropriate.										
	Following the completion of the action Plant Engineering will evaluate syster Based on this evaluation, if it is deterr actions will be developed and implem	ns associated n operation to mined that sys ent, as approp	with the ed determine stem reliab priate.	quip e th pility	oment ap e effecti has not	opa ven t be	rent ca less of en imp	use an the act roved,	alysis, ions tał further	ken.	
F.	Previous Occurrences:										
	A review of DNPS Licensee Event Re which describes a freon leak that resu	ports (LERs) ulted in a CRE	for the las VS inoper	t thi rabil	ree year ity.	s id	lentified	I LER 2	2006-00)5-00	
G.	Component Failure Data:										
	NA										

-4