

Entergy Nuclear South Entergy Operations, Inc. 17265 River Road Killona, LA 70057-3093 Tel 504-739-6496 Fax 504-739-6698 tgaudet@entergy.com

Timothy J. Gaudet Acting Nuclear Safety Assurance Director Waterford 3

W3F1-2008-0049

July 24, 2008

U.S. Nuclear Regulatory Commission Attn.: Document Control Desk Washington, DC 20555

1.

SUBJECT: 60-Day Report for Waterford Steam Electric Station, Unit 3 Reactor Pressure Vessel Head and Pressurizer Inspection/Repair for the Spring 2008 Refueling Outage Waterford Steam Electric Station, Unit 3 Docket No. 50-382 License No. NPF-38

REFERENCES:

NRC letter to Entergy dated March 20, 2007, *Confirmatory Action Letter – Waterford Steam Electric Station, Unit 3 (TAC NO. MD4196)* (CAL No. NRR-07-006)

- Entergy letter to NRC dated February 21, 2007, Inspection and Mitigation of Alloy 600/82/182 Pressurizer Butt Welds (CNRO-2007-00005)
- 3. Entergy letter to NRC dated February 26, 2007, 60-Day Report for Waterford Steam Electric Station, Unit 3 Reactor Pressure Vessel Head and Pressurizer Inspection for the Fall 2006 Refueling Outage (W3F1-2007-0009)
- 4. Entergy letter to NRC dated July 27, 2004, Response to NRC Bulletin 2004-01 Regarding Inspection of Alloy 82/182/600 Materials Üsed In Pressurizer Penetrations and Steam Space Piping Connections (W3F1-2004-0058)

Dear Sir or Madam:

On March 20, 2007, NRC transmitted Confirmatory Action Letter CAL No: NRR-07-006 to Entergy to confirm commitments made regarding Alloy 82/182 butt welds in the Waterford Steam Electric Station, Unit 3 (Waterford 3) pressurizer. In Reference 2, Entergy committed to report the results of the mitigation actions taken on the remaining Alloy 82/182 Pressurizer butt welds associated with the pressurizer spray, surge, and relief lines to the NRC within 60 days following startup from the Spring 2008 refueling outage. In Reference 3, Entergy provided inspection results for the Fall 2006 refueling outage, as required by NRC Order EA-03-009, Reactor Pressure Vessel head inspection requirements, and commitments W3F1-2008-0049 Page 2 of 3

associated with the bare metal visual (BMV) inspections of the pressurizer penetrations, as stated in Entergy's response to NRC Bulletin 2004-01 (Reference 4).

Waterford 3 resumed operation on June 2, 2008 from the Spring 2008 refueling outage The results of the RPV head inspection (NRC Order EA-03-009), Bulletin 2004-01 Pressurizer bare metal inspections, and the mitigation actions taken on the remaining Alloy 82/182 Pressurizer butt welds associated with the pressurizer spray, surge, and relief lines are summarized in the attachment.

In summary, Entergy did not identify any boric acid leakage or primary water stress corrosion cracking of the reactor vessel head or the pressurizer during the inspections of welded connections. In addition, the remaining Alloy 82/182 Pressurizer butt welds had structural weld overlays installed.

This letter contains no additional NRC commitments. If you have any questions or require additional information, please contact Robert Murillo at 504-739-6715.

Sincerely,

Ydandet

TJG/RLW/

Attachment: 60-Day Report for Reactor Vessel Head and Pressurizer Inspection for the Waterford 3 Spring 2008 Refueling Outage

W3F1-2008-0049 Page 3 of 3

cc: Mr. Elmo E. Collins, Jr. Regional Administrator U. S. Nuclear Regulatory Commission Region IV 612 E. Lamar Blvd., Suite 400 Arlington, TX 76011-4125

> NRC Senior Resident Inspector Waterford Steam Electric Station Unit 3 P.O. Box 822 Killona, LA 70066-0751

U. S. Nuclear Regulatory Commission Attn: Mr. N. Kalyanam Mail Stop O-07D1 Washington, DC 20555-0001

Wise, Carter, Child & Caraway ATTN: J. Smith P.O. Box 651 Jackson, MS 39205

Louisiana Department of Environmental Quality Office of Environmental Compliance Surveillance Division P. O. Box 4312 Baton Rouge, LA 70821-4312

American Nuclear Insurers Attn: Library Town Center Suite 300S 29th S. Main Street West Hartford, CT 06107-2445

Morgan, Lewis & Bockius LLP ATTN: T.C. Poindexter 1111 Pennsylvania Avenue, NW Washington, DC 20004

Attachment

12 1

То

W3F1-2008-0049

60-Day Report for Reactor Vessel Head and Pressurizer Inspection for the Waterford 3 Spring 2008 Refueling Outage

Attachment to W3F1-2008-0049 Page 1 of 2

60-Day Report for Reactor Vessel Head and Pressurizer Inspection for the Waterford 3 Spring 2008 Refueling Outage

Waterford Steam Electric Station, Unit 3 (Waterford 3) is a Combustion Engineering (CE) designed unit with Alloy 600 reactor pressure vessel (RPV) head and pressurizer penetrations which are subject to NRC First Revised Order EA-03-009, NRC Bulletin 2004-01 and Confirmatory Action Letter CAL No. NRR-07-006 (Reference 1). Entergy performed inspections of the Waterford 3 RPV head and pressurizer during the Spring 2008 Refueling Outage 15 and completed the mitigation actions on the remaining Alloy 82/182 Pressurizer butt welds associated with the pressurizer spray, surge, and relief lines. The RPV head inspections were conducted in accordance with Section IV.C of the Order; the pressurizer inspections were conducted in accordance with Response 1(c) of Entergy's response to Bulletin 2004-01 (Reference 4); and the remaining Alloy 82/182 Pressurizer butt welds had structural weld overlays installed in accordance with Entergy letter CNRO-2007-00005 (Reference 2) and CAL No. NRR-07-006 (Reference 1). The following provides the results of the RF-15 inspections and repairs.

Inspection Area	Inspection Method	Extent of Inspection	Results
BMV Inspection of RPV Head	RPV Head BMV	Inspect the RPV head surface 360° around each penetration for boric acid.	BMV performed on 91 CEDM nozzles, 10 ICI nozzles, vent line, and general head condition. No boric acid deposits were identified.
[NRC Order]	Pressure Retaining Components	Inspect the CEDM and ICI housings for potential boric acid leakage.	No boric acid deposits were identified from welded connections.
NDE of CEDM Nozzles	UT/ECT of 91 CEDM nozzles	Inspect 2" above the J-weld to the blind zone of the CEDM nozzle.	91 CEDM nozzles were examined and analyzed from the ID using Westinghouse UT/ECT probes. No flaws were detected.
[NRC Order and NRC approved Relaxation]	UT of Nozzle Annulus (leak path)	Review interference fit in nozzle annulus above J-weld for leakage path.	As part of the CEDM ID exams a zero degree UT probe was used to establish that there was no leak path (wastage) from the nozzle annuli.
NDE of ICI Nozzles	UT/ECT of ICI Nozzles	Inspect 2" above the J-weld to the end of the ICI nozzle.	The 10 ICI nozzles were UT/ECT examined from the ID. A zero degree UT probe was used to establish that there was no leak path (wastage). No flaws were detected.
[NRC Order]	UT/ECT of ICI Nozzle Face	Perform UT/ECT exam of ICI nozzle face where ID delivered UT/ECT tooling does not provide inspection coverage.	An automated UT/ECT on the face of the ICI nozzles was _performed. No flaws were detected.
NDE of Vent Line [NRC Order]	ECT of wetted surface area	Perform ECT of entire wetted surface of vent line.	The ECT exam of the vent line did not reveal any flaws.

Table 1 Summary of Waterford 3 Spring 2006 Refueling Outage Alloy 600 Inspections

Attachment to W3F1-2008-0049 Page 2 of 2

60-Day Report for Reactor Vessel Head and Pressurizer Inspection for the Waterford 3 Spring 2008 Refueling Outage

Inspection Area	Inspection Method	Extent of Inspection	Results
Pressurizer Inspection	Heater Sleeve	Ν/Α	All J-welded nozzles on the pressurizer were replaced or repaired by the end of RF-13.
[Bulletin 2004-01]	Side Shell, Steam Space & Bottom Instrument Nozzle	N/A	All J-welded nozzles on the pressurizer were replaced or repaired by the end of RF-13.
	Pressurizer nozzle to safe end welds and large bore steam space welds BMV	Removed insulation and performed bare metal visual inspection.	BMV of large bore nozzles and safe ends did not reveal any leakage.
Pressurizer Inspection/Repair [Confirmatory Action Letter CAL No. NRR-07-006 and Entergy Letter CNRO-2007- 00005]	Pressurizer nozzle to safe end welds	 Removed insulation and performed bare metal visual inspection Install weld overlays. 	 BMV of nozzle to safe end welds did not reveal any leakage. Completed installation of structural weld overlays over the remaining PZR nozzle to Stainless Steel Safe-End alloy 82/182 butt welds. PZR to Safety Relief Valve (RC-317A), 6" PZR to Safety Relief Valve (RC-317B), 6" PZR to Safety Relief Valve (RC-317B), 6" PZR to Safety Relief (Capped), 6" PZR to Spray Line, 4" PZR to Surge Line, 12" Note: Additional structural weld overlays were also installed on: (a) Hot Leg 1 to Shutdown Cooling Line, 14"; (b) Hot Leg 2 to Shutdown Cooling Line, 14"; (c) Hot Leg 1 to Surge Line, 12"; and (d) Hot Leg 1 to Drain, 2"

Legend:

BMV = Bare Metal Visual CEDM = Control Element Drive Mechanism ECT = Eddy Current Examination ICI = Incore Instrument ID = Inside Diameter MNSA = Mechanical Nozzle Seal Assembly

NDE = Non-Destructive Examination

RPV = Reactor Pressure Vessel

TE = Temperature Element

UT = Ultrasonic Examination