

400 Chestnut Street Tower II

July 15, 1981

WBRD-50-390/81-55

WBRD-50-391/81-53



Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - PUMPS ALIGNED WITH UNCALIBRATED
DIAL INDICATORS - WBRD-50-390/81-55, WBRD-50-391/81-53 - FIRST INTERIM
REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
D. Quick on June 15, 1981 in accordance with 10 CFR 50.55(e) as
NCR 3299R. Enclosed is our first interim report. We expect to provide
additional information by September 1, 1981.

If you have any questions, please get in touch with D. L. Lambert at
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE27
5/11

ENCLOSURE

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2
PUMPS ALIGNED WITH UNCALIBRATED DIAL INDICATORS
WBRD-50-390/81-55, WBRD-50-391/81-53
10 CFR 50.55(e)
FIRST INTERIM REPORT

Description of Deficiency

Uncalibrated dial indicators were used to align pump couplings for the Component Cooling System, Chemical and Volume Control System, Safety Injection System, and Containment Spray System pumps. Procedure WBNP-QCP-1.12 states that calibrated instruments should be used by TVA's Division of Construction in performing this work.

Interim Progress

TVA is still in the process of reviewing the subject deficiency.