

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

September 8, 1982

WBRD-50-390/81-14

WBRD-50-391/81-13

U.S. Nuclear Regulatory Commission
Region II

Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - IMPROPERLY INSTALLED SUPPORT
ANCHORS - WBRD-50-390/81-14, WBRD-50-391/81-13 - TENTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector H. Dance on June 8, 1981 in accordance with 10 CFR 50.55(e) as NCR 3311R. NCR 3311R concerns improperly installed support anchors for the Watts Bar unit 2 reactor building. This is the same type of deficiency and corrective action program as NCR 2789R, which was initially reported to NRC-OIE Inspector M. Thomas on January 7, 1981. NCR 2789R was written for units 1 and 2, and interim reports were submitted on February 6 and June 23, 1981. Since these deficiencies are closely related, TVA has combined both NCR's into one report. Combined interim reports were submitted on July 8, August 13, September 27, and November 24, 1981 and January 25, March 30, and July 13, 1982. We expect to submit our next report by November 15, 1982.

82 SEP 11 11 11 AM '82
USNRC REGION II
ATLANTA, GEORGIA

TVA has completed its investigation of all items in this deficiency except the effects of oversize bolt holes on support base plates. TVA is continuing to investigate the oversize bolt holes. More information will be provided in our next report.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

OFFICIAL COPY

2027

8209160217 820908
PDR ADOCK 05000390
S PDR