

400 Chestnut Street Tower II

September 23, 1981

WBRD-50-390/81-14
WBRD-50-391/81-13

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - IMPROPERLY INSTALLED SUPPORT
ANCHORS - WBRD-50-390/81-14, WBRD-50-391/81-13 - FIFTH INTERIM REPORT

The subject deficiency reported to NRC-OIE Inspector H. Dance on June 8, 1981 in accordance with 10 CFR 50.55(e) as NCR 3311R. NCR 3311R concerns improperly installed support anchors for the Watts Bar unit 2 reactor building. This is the same type of deficiency and corrective action program as NCR 2789R, which was initially reported to NRC-OIE Inspector M. Thomas on January 7, 1981. NCR 2789R was written for units 1 and 2, and interim reports were submitted on February 6 and June 23, 1981. Since these deficiencies are closely related, TVA has combined both NCR's into one report. Combined interim reports were submitted on July 8 and August 13, 1981. We expect to submit our next report by November 24, 1981.

TVA has completed an NRC-OIE Bulletin 79-02 type inspection (August 29, 1981) for unit 1 anchors associated with NCR 2789R. The sample included cable tray supports, conduit supports, and duct supports. The inspection data is being evaluated.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE27
5/10

8109300377 810923
PDR ADOCK 05000390
S PDR