TENNESSEE VALLEY AUTHORITY

CHATTANOOGA. TENNESSEE 37401 400 Chestnut Street Tower II

March 30, 1982

WBRD-50-390/82-26 WBRD-50-391/82-23

U.S. Nuclear Regulatory Commission Region II Attn: Mr. James P. O'Reilly, Regional Administrator 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - INCORRECT LUBE OIL USED IN DIESEL GENERATORS - WBRD-50-390/82-26, WBRD-50-391/82-23 - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on February 25, 1982 in accordance with 10 CFR 50.55(e) as NCR W-88-P. Enclosed is our first interim report. We expect to submit our next report by June 21, 1982.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Regulation and Safety

Enclosure cc: Mr. Richard C. DeYoung, Director (Enclosure) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

OFFICIAL COPY

18

B204160231 B20330 PDR ADUCK 05000390 S PDR

An Equal Opportunity Employer

ENCLOSURE WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 INCORRECT LUBE OIL USED IN DIESEL GENERATORS NCR W-88-P WBRD-50-390/82-26, WBRD-50-391/82-23 10 CFR 50.55(e) FIRST INTERIM REPORT

Description of Deficiency

Chevron Delo 400 was used as a lubricant for the emergency diesel generator engines. Delo 400 has 1300 ppm zinc. However, lube oil with greater than 10 ppm zinc can be detrimental to the silver coating on the wrist pin bearings. The incorrect oil was initially installed by TVA Construction based on the recommendation of the operating division (TVA's Division of Nuclear Power). The operating division has continued to use Delo 400 in these engines. The root cause of this deficiency was the specification of Delo 400 lubricating oil without checking the vendor's specifications for chemical content.

Interim Progress

Watts Bar Construction reviewed WBNP-QCP-4.14, <u>Lubrication Control for</u> <u>Permanent Mechanical Equipment</u>, and found it to be adequate. TVA is continuing the investigation of this deficiency and will supply additional information in our next report.