

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, 6 EORISIA 30303

MAR 31 1951



Gentlemen:

The enclosed circular is forwarded for your information. No written response to this circular is required. If you have any quastions related to this matter, please contact this office.

Sincerely,

Jamas P. O'Reilly Director

Enclosures:

- 1. IE Circular No. 81-05
- 2. List of Recently Issued
- IE Circuiars



# Distribution for IE Circular No. 81-05

(INFORMATION)

# March 31, 1981

# Addresses

 Alabama Power Company Attn: R. P. McDonald Vice President-Nuclear Generation Post Office Box 2641 Birmingham, AL 35291

 Carolina Power and Light Company Attn: J. A. Jones Senior Executive Vice President and Chief Operating Officer 417 Fayetteville Street Raleigh, NC 27602

 Duke Power Company Attn: L. J. Dail, Vice President Design Engineering P. O. Box 33189 Charlotte, NC 28242

 Buke Power Company Attn: W. O. Parker, Jr. Vice President, Steam Production P. O. Box 2178 Charlotte, NC 28242

 Florida Power and Light Company Attn: R. E. Uhrig, Vice President Advanced Systems and Technology P. O. Box 529100 Miami, FL 33152

 Florida Power Corporation Attn: J. A. Hancock, Assistant Vice President Nuclear Operations P. O. Box 14042, Mail Stop C-4 St. Petersburg, FL 33733 In Reference To

50-348 Farley Unit 1 50-364 Farley Unit 2

50-325 Brunswick Unit 1 50-324 Brunswick Unit 2 50-400 Harris Unit 1 50-401 Harris Unit 2 50-402 Harris Unit 3 50-403 Harris Unit 4 50-261 Robinson Unit 2

50-491 Cherokee Unit 1 50-492 Cherokee Unit 2 50-493 Cherokee Unit 3 50-488 Perkins Unit 1 50-489 Perkins Unit 2 50-490 Perkins Unit 3

50-369 McGuire Unit 1 50-370 McGuire Unit 2 50-269 Oconee Unit 1 50-270 Oconee Unit 0 50-287 Oconee Unit 3 50-413 Catawba Unit 1 50-414 Catawba Unit 2

50-335 St. Lucie Unit 1 50-389 St. Lucie Unit 2 50-250 Turkey Point Unit 3 50-251 Turkey Point Unit 4

50-302 Crystal River Unit 3

# IE Gircular No. 81-05 March 31, 1981

# Addresses

- 7. Georgia Power Company Attn: J. H. Miller, Jr. Executive Vice President 270 Peachtree Street Atlanta, GA 30303
- Mississippi Power and Light Company Attn: N. L. Stampley Vice President of Production P. O. Box 1640 Jackson, MS 39205
- Offshore Power Systems Attn: A. R. Collier, President P. O. Box 8000 Jacksonville, FL 12211
- 10. South Carolina Electric and Gas Company Attn: T. C. Nichols, Jr., Vice President Power Production and System Operations P. O. Box 764 Columbia, SC 29218
- 11. Tennessee Valley Authority Attn: H. G. Parris Manager of Power 500A Chestnut Street Tower II Chattanooga, TN 37401

12. Virginia Electric and Power Company Attn: J. H. Ferguson Executive Vice President-Power P. O. Box 26666 Richmond, VA 23261 In Reference To

50-321 Hatch Unit 1 50-366 Hatch Unit 2 50-424 Vogtle Unit 1 50-425 Vogtle Unit 2

50-416 Grand Gulf Unit 1 50-417 Grand Gulf Unit 2

50-437 FNP 1-8

50-395 Summer Unit 1

50-438 Bellefonte Unit 1 50-439 Bellefonte Unit 2 50-259 Browns Ferry Unit 1 50-260 Browns Ferry Unit 2 50-296 Browns Ferry Unit 3 50-518 Hartsville Unit 1 50-519 Hartsville Unit 2 50-520 Hartsville Unit 3 50-521 Hartsville Unit 4 50-553 Phipps Bend Unit 1 50-554 Phipps Bend Unit 2 50-327 Sequoyah Unit 1 50-328 Sequoyah Unit 2 50-390 Watts Bar Unit 1 50-391 Watts Bar Unit 2 50-566 Yellow Creek Unit 1 50-567 Yello, Creek Unit 2 50-33% North Anna Unit 1 50-339 North Anna Unit 2 50-404 North Anna Unit 3 50-280 Surry Unit 1 50-281 Surry Unit 2

(ILFORMATION)

IE Circular No. 81-05 March 31, 1981

# Addresses

- In Reference To
- 13. Inscitute of Nuclear Power Operation Attn: R. W. Pack Lakeside Complex 1820 Waterplace Atlanta, GA 30339
- Southern Company Services, Inc. ATTN: O. Batum, Manager Nuclear Safety & Licensing Department
  P. O. Box 2625 Birmingham, AL 35202
- 15. Department of Energy Clinch River Breeder Reactor Flan: Project Office ATTN: Chief, Quality Improvement P. O. Box U Oak Ridge, IN 37830
- EDS, Nullear, Inc. ATTN: E. H. Verdery 330 Technology Park/Atlanta Norcross, GA 30092

SSINS No: 6830 Accession No.: 8011040282 IEC 81-05

# UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

#### March 31, 1981

## IE Circular Nu. 81-05: SELF-ALLIHING ROD END BUSHINGS FOR PIPE SUPPORTS

#### Background:

By letter dated July 24, 1980, Bechtel Fower Carporation notified NRC of generic deficiencies in pipe support sway struts furnished by Corner & Lada Inc., to the Callaway and Wolf Creek sites. The specific deficiencies identified involved the clamp end of the sway strut becoming loose and possibly being disengaged from the bushing. This could result in a large gap in the support system not accounted for in the original analysis. This deficiency was reported to NRC pursuant to 10 CFR Part 21 on May 14, 1980.

In another letter dated October 8, 1980, Bechtel Power Corporation notified NRC of generic deficiencies in pipe support end bushings at Midland Units 1 and 2 and at Palisates. In this report, self-aligning rod end bushings on the ends of sway structs and snubbers furnished by ITT Grinnell, Pacific Scientific, NPSI, and Corner & Lada were found to be partially or totally disengaged from the structural component. This report was identified as a 10 CFR Part 21 notification.

#### Discussion:

The problem of loose bushings in snubler and sway strut assemblies is potentfally generic to all sizes of all manufacturers' assemblies. However, the potential for complete disengagement of the bushing from the assembly is limited to those cases in which the assembly is attached to a clamp where the gap is sufficiently large to permit the padule to slide completely over the bushing.

The consequences of complete disengagement of the bushing would be to invalidate the original analytical assumption; used in the piping analysis, potentially creating an overstress condition in the piping or overloading the supports. This would be more significant for the seismic event since the gap would change the dynamic characteristics of the system and lead to impact loads that could damage the piping or supports.

The corrective actions taken by licensees have been to replace the defective struts or to "stake" the loose bushing in place. However, sume of the staked bushings subsequently became loose and had to be reworked. Another potential corrective action would be to shim the clamps where the potential for complete disengagement of the assembly from the bushing is possible. This method would prevent total disengagement even if the bushing became loose. If shims are used, consideration should be given to preventing any interference with required rotation of the assembly.

IEC 81-05 March 31, 1981 Page 2 of 2

# Recommended Actions for Holders of Operating Licenses or Construction Permits:

- Determine whether your facility uses pipe strut or snubber assemblies using bushings that could potentially become loose.
- Identify from design drawings or field inspections those supports using the strut or snubber assemblies identified in item I above where sufficient gap exists in the clamp attachment for complete disengagement of the bushing and the assembly.
- 3. Inspect where practical the snubber or strut assemblies identified in item 2 above to determine if any bushings are loose or disengaged. If a large number of supports are involved in this inspection, a statistical sampling may be appropriate to determine if your facility has a problem with loose or disengaged bushings.
- 4. If loose or disengaged bushings are found at your facility, take appropriate corrective actions to ensure that complete disengagement of the assembly from the bushing cannot occur.

No written response to this circular is required. If you need additional information with regard to this subject, please contact the Director of the appropriate NRC degional Office.

#### Attachments:

- 1. Sway Strut Acsembly: Figure 211
- 2. Recently issued IE Circulars

Attactment 1 March 31; 1981

IEC 81-05





Attachment 2 IEC 81-05 March 31, 1981

# RECENTLY ISSUED

Corcular		Date of	
No.	Subject	Issue	Issued to
8104	The Role of Shift Technical Advisors and Importance of Licensee Event Reports	4/1/81	All power reactor facilities with an OL or near-term OL
8103	Inoperable Seismic Monitoring Instrumentation	3/2/81	All power reactor facilities with an OL or CP
81-02	Performance of NRC-Licensed Individuals While on Duty	2/9/81	All power reactor facilities (research & test) with an OL or CP
81-01	Design Problems Involving Indicating Pushbutton Switches Manufactured by Honeywell Incorporated	1/23/81	All power reactor facilities with an OL or CP
80-25	Case Histories of Radiography Events	12/5/80	All radiography licensees
80-24	AECL Teletherapy Unit Malfunction	12/2/80	All teletherapy licensees
80-23	Pote tial Defects in Beloit Power Systems Emergency Generators	10/31/80	All power reactor facilities with OL or a CP
80-22	Confirmation of Employee Qualifications	10/2/80	All holders of a power reactor OL or CP architect-engineering companies and nuclear sceam system suppliers
80-21	Regulation of Refueling Crews	9/10/80	All holders of a power reactor OL or CP
30-20	Changes in Safe-Slab Tank Dimensions	8/21/80	All Part 50 and Part 70 fuel facility licensees

OL = Operating Licenses CP = Construction Permit