

James R. Becker Site Vice President and Station Director

Diablo Canvon Power Plant Mail Code 104/5/502 P. O. Box 56 Avila Beach, CA 93424

805.545.3462 Internal: 691.3462 Fax: 805.545.4234

August 11, 2008

PG&E Letter DCL-08-070

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Docket No. 50-275, OL-DPR-80 Docket No. 50-323, OL-DPR-82 Diablo Canyon Power Plant Units 1 and 2 Licensee Event Report 1-2008-001-00 Potential Accumulator Drain Line Actuation Following an SBLOCA Due to Solenoid Valve Failure

Dear Commissioners and Staff:

In accordance with 10 CFR 50.73(a)(2)(v)(D), Pacific Gas and Electric Company (PG&E) is submitting the enclosed licensee event report regarding the potential for draining one or more safety injection system accumulators following a small break loss-of-coolant-accident due to a postulated solenoid valve malfunction.

PG&E makes no regulatory commitments (as defined by NEI 99-04) in this letter.

This event did not adversely affect the health and safety of the public.

Sincerely,

8/11/08 Renneth Langdo James R. Becker

ddm/2246/A0731731 Enclosure cc/enc: Elmo E. Collins, NRC Region IV Michael S. Peck, NRC Senior Resident Inspector Alan B. Wang, NRR Project Manager INPO **Diablo Distribution**

A member of the STARS (Strategic Teaming and Resource Sharing) Alliance Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • WolfCreek



NRC FOF	RM 366			U.S. NUCLE	AR RI	EGULATOF	RY COMMI	SSION	APPROVE	D BY OMB	: NO. 3150-0	104	EXPIRES	: 06/30/2007
	LI	ICENS (See r digil	EEE\ everse ts/chara	VENT RE for require acters for e	POF d nur ach b	RT (LEF nber of llock)	२)		Estimated request: 5 licensing p estimate to Nuclear Re e-mail to in and Regula Budget, W collection of not condu information	burden pe 50 hours. If process and o the Reco egulatory Co nfocollects@ atory Affairs /ashington, does not dis- to or spons n collection.	r response to Reported less fed back to im- rds and FOIA ommission, Wa prrc.gov, and , NEOB-10202 DC 20503. If polay a currently sor, and a pe	comply with t ons learned at dustry. Send coi /Privacy Servicc ashington, DC 2 to the Desk Off 2, (3150-0104), C a means used y valid OMB comi rison is not rec	his mandat e incorpora mments reg Branch (T 0555-0001, icer, Office Office of Mar to impose a trol number, juired to re	ory collection ated into the arding burden -5 F52), U.S. or by internet of Information tagement and an information the NRC may spond to, the
1. FACIL	ITY NA	ME							2. DOCK		ER	3. PAGE	<u></u>	
	lo Car	iyon Ui							05	000275)			/
4. 111⊑ <u>Pot</u> €	ential /	Accum	ulator	Drain Lir	<u>1e A</u>	<u>ctuatior</u>	<u>ı Follov</u>	wing a	a LOC/	A Due t	to Solen	<u>oid Valve</u>	Failur	<u>e</u>
5. E	VENT D	ATE	6. I	LER NUMBEI	۲	7. R	EPORT D	ATE		8.	OTHER FA	CILITIES INV	OLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY .	YEAF	FACILIT	YNAME			DOCKET	NUMBER
06	11	2008	2008	- 001 -	00	08	2008	B Dial	olo Can	yon Unit	2	DOCKET 050	NUMBER)00323	
9. OPER	ATING I	MODE	11	. THIS REPO	RTIS	SUBMITTE	JANT T	O THE RE	QUIREM	ENTS OF 10	CFR§: (Che	ck all that	apply)	
10. POW	1 /er lev 100	/EL	□ 20.22 □ 20.22 □ 20.22 □ 20.2 □ 20.2 □ 20.2 □ 20.2 □ 20.2 □ 20.2 □ 20.2 □ 20.2 □ 20.2	201(b) 201(d) 203(a)(1) 203(a)(2)(i) 203(a)(2)(ii) 203(a)(2)(iii) 203(a)(2)(iv) 203(a)(2)(v) 203(a)(2)(vi)		2 2 2 2 5 5 5 5 5 5 5 5 5 5 5 5 5	(3)(i) (3)(ii) (4) (i)(A) (ii)(A) (ii)(A) (i)(A) (i)(B)		50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a)	(2)(i)(C) (2)(ii)(A) (2)(ii)(B) (2)(ii) (2)(iv)(A) (2)(v)(A) (2)(v)(A) (2)(v)(B) (2)(v)(C) (2)(v)(D)	□ 50.7 □ 50.7 □ 50.7 □ 50.7 □ 50.7 □ 73.7 □ 73.7 □ 73.7 □ 0TH Spe or in	73(a)(2)(vii 73(a)(2)(vii 73(a)(2)(vii 73(a)(2)(ix) 73(a)(2)(ix) 73(a)(2)(x) 73(a)(x) 73(a) i)(A) i)(B))(A) act below 366A	
CACULITY N	1 A B 407	·			1	2. LICENS	EE CONT	ACT F	OR THIS L	_ER	·		D (Isoludo A	
Ste	ven W	/. Hami	lton – १	Senior Re	gulat	ory Serv	vices Er	ngine	er			(805)	545-34	49
			13. COM	PLETE ONE	LINE	FOR EACH	I COMPO	NENT F	AILURE	DESCRIBI	ED IN THIS	REPORT	····	
CAU	SE	SYSTEM	СОМРОГ	NENT FACT	1U- URER	REPOR TO E	C.	AUSE	SYSTEM	COMPONEN	IT FACTURE	REP R T	ORTABLE O EPIX	
X		BP	_т\	/ A6	10	N								
		14	. SUPPL	EMENTAL R	EPOR	T EXPECT	ED			15. E	XPECTED	MONTH	DAY	YEAR
□ YE	S (If yes	s, complet	e 15. EXI	PECTED SUE	MISSI	ON DATE))		NO	SOR [DATE			
ABSTRA	CT (Lim	nit to 1400	spaces,	i.e., approxim	ately 1	5 single-sr	oaced type	written	lines)					

On June 11, 2008, at 14:05 PDT, with Units 1 and 2 in Mode 1 (Power Operation) at approximately 100 percent power, licensed plant operators entered Technical Specification (TS) 3.0.3 due to a potential solenoid valve failure mechanism that could initiate draining of the safety injection system (SIS) accumulators following a small break loss-of-coolant-accident (SBLOCA). Licensed plant operators made an eight-hour nonemergency event notification (EN 44287) in accordance with 10 CFR 50.72(b)(3)(v)(D) at 20:48 PDT.

Plant engineers identified four nonsafety-related solenoid valves that could malfunction due to a low minimum operating pressure differential (MOPD) following a SBLOCA. These valves could misposition in an intermediate position such that upon reestablishing supply air pressure they could open their associated safety-related valve resulting in a loss of SIS accumulator inventory. Emergency Operating Procedures (EOP) direct operators to reinstate the air supply to containment if isolated during a postulated SBLOCA scenario.

FACILITY NAME (1)	DOCKET NUMBER (2)									· .	LEF	NUMB	ER (6)	 		PAGE (3)			
	YEAR SEQUENTIAL NUMBER REVISION NUMBER																		
Diablo Canyon Unit 1	0	5	0	0	0	2	7	5	2008	-	0	0	1	0.	0	2	OF	7	
											•								1

I. Plant Conditions

Diablo Canyon Power Plant (DCPP) Units 1 and 2 were in Mode 1 (Power Operation) at approximately 100 percent power during the event.

II. Description of Problem

A. Background

During normal operation, the safety injection system (SIS)[BP] accumulator fill, vent, and drain system valves provide for control of accumulator water level via manual control switches located on the control operators console in the control room. Technical Specification (TS) 3.5.1, "Accumulators," requires, in part; that "Four ECCS accumulators shall be OPERABLE," with "borated water volume in each accumulator is greater than 814 ft³ and less than 886 ft³." Accumulator inventory can be decreased by opening the Drain Valves SI-1(2)-8876A, 8876B, 8876C, and 8876D for each of the four SIS accumulators. During normally operation, Valves SI-1(2)-8876A-D are maintained closed by de-energized nonsafety-related solenoid valves following a small break loss-of-coolant-accident (SBLOCA). 1(2)-SV-333, 342, 347, and 352 [LSV].

The containment air supply isolation Valve SI-2-8843 actuated by solenoid valve SV-527, provides isolation of the containment air supply pressure upon initiation of a containment isolation signal due to an SIS or manual safety injection (SI) initiation signal.

TS 3.6.1, "Containment," surveillance requirement (SR) 3.6.1.1, requires periodic testing in accordance with the Containment Leakage Rate Testing Program. Standard Temperature and Pressure (STP) M-7, "Integrated Leak Rate Test (ILRT) Type A," testing is performed in accordance with this program by isolating containment via closure of all automatically isolated penetrations and verification of manually isolated penetrations. The ILRT establishes containment air pressure of at least 45.12 psig (0.96P_a), in accordance with STP M-7. The ILRT performed during the Unit 2 fourteenth refueling outage (2R14) included isolation of SI-2-8843 (SV-527), and pressurizing the containment.

Following successful ILRT testing, operators proceeded to restore the containment air pressure supply. However, when operators went to open SI-2-8843 they found that the valve was in the open position with the control switch in the closed position.

FACILITY NAME (1)			DO	CKET	NUMBE	R (2)	1		LER NUMBER (6)								PAGE (3)			
									YEAR	SEQUENTIAL NUMBER					REVI NUM	SION IBER				
Diablo Canyon Unit 1	0	5	0	0	0	2	7	5	2008	1	0	0	1	-	0	0	3	OF	7	

A failure mechanism exists in which solenoid valves could be susceptible to a demand failure if the supply air pressure were to decrease below the minimum operating pressure differential (MOPD) and then be reestablished. Four nonsafety-related solenoid valves were identified that could misposition in an intermediate position, due to this failure mechanism, such that upon reestablishing supply pressure they could open their associated safety-related valve resulting in a loss of SIS accumulator inventory. Emergency Operating Procedures (EOP) direct operators to reinstate the air supply to containment if isolated during a postulated SBLOCA scenario.

B. Event Description

TEXT

On April 5, 2008, Action Request AR A0726408 identified a malfunction of solenoid valve (SV) SV-527, and its air-to-open containment Isolation Valve SI-2-8843, to maintain its intended position after restoration of the containment air supply pressure following completion of containment ILRT testing.

On June 6, 2008, AR A0731551, initiated an engineering review of the potential service conditions for nonsafety-related solenoid valves used as part of equipment restoration following postulated accidents.

On June 11, 2008, an evaluation identified four susceptible solenoid valves per unit that could malfunction due to MOPD resulting in the potential draining of one or more SIS accumulators following a SBLOCA.

On June 11, 2008, at 14:05 PDT, licensed plant operators entered TS 3.0.3 due to the potential solenoid valve malfunction that could initiate draining of one or more SIS accumulators following a SBLOCA.

Operations administratively cleared the instrument air to the subject SIS Accumulator Drain Valves SI-1(2)-8876A-D.

On June 11, 2008, at 16:06 PDT, Unit 2 plant operators verified that the manual isolation valves for the SIS accumulator drain lines were closed, exiting TS 3.0.3.

On June 11, 2008, at 16:10 PDT, Unit 1 plant operators verified that the manual isolation valves for the SIS accumulator drain lines were closed, exiting TS 3.0.3.

	LI	CENSE	EE	E\	/EN	1T	REF	0	R	Г (І	LER)	TE)	(T (00	ITI	NU/	ATIO	ON			
FACILITY NA	ME (1)				DOC	KET N	UMBER	2)			YFAR	1	LE	R NUME	BER (6) NUMBE		I REV	ISION		PAGE (3)
Diablo	Canvor	Unit 1	0	5	0	0	0	2	7	5	2008	-	0	0	1		NUN		4	OF	7
TEXT	Carijer			U		Ů	•	-	•						<u> </u>						
		On Jun hour no 10 CFR	e 1 ⁻ ner 8 50	1, 2 nei .72	2008 ger 2(b)	3, at ncy (3)(v	t 20:₂ even v)(D)	8 t n via	PD ioti a tł	DT, fica ne e	license ition (E emerge	ed pl N 4 ency	ant 428 ⁷ not	ope 7) in ifica	rato acc tion	rs m corda syst	ade ance :em	an e with (EN	eight n S).	-	
	C.	Status of to the E	of Ir Ever	nop nt	era	ble	Struc	tu	res	s, S	ystem	s, or	Co	mpo	nen	ts th	at∙C	ontri	ibute	ed	
		None.											•								
	D.	Other S	Syst	em	S OI	r Se	conc	ar	уF	un	ctions	Affe	cted	I							
		None.																		·	
	E.	Method	l of	Dis	cov	very															
		This co evaluat ILRT. A malfund valves o	ndit ion An e ctior of th	tion per exten n of	rfori ent f the SIS	is id mec of c e no acc	lentif d due ondit onsaf cumu	ed to ior ety lat	l di o a n e /-re ors	urin ma valu elato 3.	ig a pla Ifunction uation ed sole	ant e on ol iden enoic	ngir f SV tifie d va	neer /-527 d a p Ives	ing 7 fol pote cor	com lowii ntial itrolli	pone ng th for a ing t	ent fa ie 2F a sin he d	ailure R14 nilar rain	9	
	F.	Operate	or A	cti	ons															;	
		Plant of the SIS affected isolated licensed (EN 442	pera d dr d, pl d pl 287	ato cur ain ant ant	rs e nula line t op t op i ac	nter ators es. erat erat corc	red T s and Upoi tors e tors r dance	S in v xit nac v w	3.0 reri ted de vith).3 (atec fica I TS a r 10	due to d action ation th 3 3.03. noneme) CFR	failu ns to at th At 2 erge 50.7	ire to iso ie di 20:4 ncy 2(b)	o co late rain 8 Pl eve (3)(¹	mply the line: DT, nt n v)(D	y wit pote s we June otific	h TS ntia re pi e 11, atioi	3 3.5 Ily rope 200 n	5.1 fc erly)8,	pr	
	G.	Safety	Sys	ten	n R	esp	onse	5													
		None re	equ	irea	d.								•	•							
Ш.	Cause	e of the F	Prol	olei	<u>m</u>								•								
	A.	Immedi	iate	Ca	ause	Э															
		The init	tial	eva	lua	tion	of S	/ -!	527	7:											
		SV-527 the air o closed,	′ is ope wh	a 3 rate ich	-wa ed \ clo	y pi /alv ses	lot o e (A((or r	oei DV na	rate ') is inta	ed s s pc ains	SV. W orted to s close	'hen exh d) th	the naus ne A	SV st an OV.	coil d th Wł	is de e air nen f	e-en sup he S	ergiz ply r SV c	zed, port i oil is	is	

FACILITY NAME (1)			DO	CKET	UMBE	R (2)					LEF	R NUMB	ER (6)				F	PAGE (3)		
									YEAR	SEQUENTIAL NUMBER RE						SION	ION BER			
Diablo Canyon Unit 1	0	5	0	0	0.	2	7	5	2008	- . ·	0	0	1	-	0	0	5	OF	7	

TEXT

energized, the air supply is ported to the AOV actuator and the exhaust port is closed, which opens the AOV. The solenoid valve has a plunger (pilot seat cartridge and disc holder) that is actuated by the solenoid that directs the air to the appropriate port. The 3-way pilot operated SV requires that a minimum operating pressure differential (MOPD) be maintained between the pressure and exhaust ports to maintain proper position. During the 2R14 ILRT, the SV was de-energized so the exhaust port was aligned to the AOV actuator and the supply port of the SV was closed. In this configuration, the ILRT pressure would have been supplied to the pressure side of the AOV actuator through the SV exhaust port. It is believed that the ILRT pressure contributed to the movement of the plunger to an intermediate position.

The plunger failed to return to its normal position after the ILRT pressure was vented and the instrument air pressure was restored. It is believed that this was caused by age-related deterioration of the SV internal components. The SV had been in service over 23 years. Failure analysis found that the o-rings were hard and brittle, the diaphragms were stiff, and the plunger springs had taken a compression set. The SV malfunction occurred as result of the plunger being in an intermediate position with air being supplied to both the actuator and the exhaust port. When the exhaust port was blocked, the valve returned to its closed position. Subsequent operation of the valve was normal.

B. Cause

The cause of this SV malfunction was determined to be SV plunger movement due to insufficient MOPD in combination with age-related deterioration of the SV internal components. Were either condition not to have been present, the malfunction would not have occurred.

IV. Assessment of Safety Consequences

There were no safety consequences as a result of this event. Units 1 and 2 remained at full power and all systems were available to perform their intended safety function by isolation of the SIS accumulator drain valves that could have been adversely affected by the described condition. The limiting large break LOCA conditions are not adversely affected by the identified condition as the reactor coolant pressure decreases rapidly, with prompt accumulator actuation, before containment air supply pressure is restored in accordance with the EOPs.

Following a SBLOCA and isolation of the air supply to the containment, the pilotoperated SVs associated with the accumulator drain valves could experience a

FACILITY NAME (1)	DOCKET NUMBER (2) LER NUMBER (6)												. 1	PAGE (3)							
						•			YEAR		SEQUE	NTIAL	NUMBER		REVI NUM	sion IBER	DN ER				
Diablo Canyon Unit 1	0 .	5	0	0	0	2	7	5	2008	-	0	0	1	-	-0	Ó	6	OF	7		

TEXT

MOPD plunger misposition. Subsequent restoration of the air supply to the containment could result in inadvertently opening of the accumulator drain valves and the initiation of accumulator draindown. The accumulator level is monitored and displayed in the control room. Also, annunciator window PK-02-10 would alarm when the accumulator level reached 60.8 percent. One of the actions specified in response to an accumulator low-level alarm is to verify that the accumulator drain valves are closed. Given the restoration of air supply to the containment, it is anticipated that the SV would respond appropriately to a demand signal to close the accumulator drain valve using the switch in the control room.

The condition described is a low probability event involving a very specific set of SBLOCA conditions that would require several minutes between loss and restoration of air supply to the containment, but prior to SIS accumulator injection demand. PG&E has identified only one malfunction due to the combined insufficient MOPD / age-related failure mechanism. Thus, the simultaneous malfunction of multiple potentially affected solenoid valves in combination with the required SBLOCA conditions is considered an extremely low probability event.

Therefore, the event is not considered risk-significant and it did not adversely affect the health and safety of the public.

V. <u>Corrective Actions</u>

A. Immediate Corrective Actions

- 1. Plant operating and maintenance personnel entered containment and closed the SIS accumulator drain line manual isolation valves.
- 2. Plant personnel isolated the air supply to the four solenoid valves for the SIS accumulator drain valves in each unit and will maintain them under administrative clearance until the solenoid valves are replaced.
- B. Planned Corrective Actions
 - 1. PG&E plans to replace the suspect solenoid valves using a prioritized replacement plan that is under development. Reference AR A0734863.

FACILITY NAME (1)			DO	CKET N	UMBE	R (2)			LER NUMBER (6)								PAGE (3)			
t la sur transformation de la sur de la s	YEAR SEQUENTIAL NUMBER REVISION NUMBI										SION									
Diablo Canyon Unit 1	0	5	0.	.0	0	2	7	5	2008	.	0	0	. 1	-	0	0	7	OF	7	

TEXT

VI. Additional Information

A. Failed Components

Commercial grade ASCO model 8316 pilot-operated solenoid valves purchased prior to commercial power operation.

B. Previous Similar Events

None.