

Gentlemen:

The enclosed information notice provides early notification of an event that may have safety significance. It is expected that recipients will review the information notice for possible applicability to their facilities.

If you have any questions regarding this matter, please contact this office.

Sincerely,

James P. O'Reilly 👌

Regional Administrator

Enclosures:

- 1. IE Information Notice No. 82-02
- 2. List of Recently Issued
 - IE Information Notices





Distribution for IE Information Notice 82-02

January 27, 1982

Addresses

- Alabama Power Company Attn: R. P. McDonald Vice President-Nuclear Generation Post Office Box 2641 Birmingham, AL 35291
- 2. Carolina Power and Light Company Attn: J. A. Jones Senior Executive Vice President and Chief Operating Officer 41! Fayetteville Street Raleigh, NC 27602
- Duke Power Company Attn: L. C. Dail, Vice President Design Engineering P. O. Box 33189 Charlotte, NC 28242
- 4. Duke Power Company Attn: W. O. Parker, Jr. Vice President, Steam Production
 P. O. Box 2178 Charlotte, NC 28242
- Florida Power and Light Company Attn: R. E. Uhrig, Vice President Advanced Systems and Technology P. O. Box 529100 Miami, FL 33152

 Florida Power Corporation Attn: J. A. Hancock, Vice President Nuclear Operations
 P. O. Box 14042, Mail Stop C-4 St. Petersburg, FL 33733 (INFORMATION)

In Reference To

50-348 Farley Unit 1 50-364 Farley Unit 2

50-325 Brunswick Unit 1 50-324 Brunswick Unit 2 50-400 Harris Unit 1 50-401 Harris Unit 2 50-402 Harris Unit 3 50-403 Harris Unit 4 50-261 Robinson Unit 2

50-491 Cherokee Unit 1 50-492 Cherokee Unit 2 50-493 Cherokee Unit 3 50-488 Perkins Unit 1 50-489 Perkins Unit 2 50-490 Perkins Unit 3

- 50-369 McGuire Unit 1 50-370 McGuire Unit 2 50-269 Oconee Unit 1 50-270 Oconee Unit 2 50-287 Oconee Unit 3 50-413 Catawba Unit 1 50-414 Catawba Unit 2
- 50-335 St. Lucie Unit 1 50-389 St. Lucie Unit 2 50-250 Turkey Point Unit 3 50-251 Turkey Point Unit 4

50-302 Crystal River Unit 3

IE Information Notice No. 82-02 January 27, 1981

Addresses

- 7. Georgia Power Company Attn: J. H. Miller, Jr. Executive Vice President P. O. Box 4545 Atlanta, GA 30302
- Mississippi Power and Light Company Attn: N. L. Stampley Vice President of Production P. O. Box 1640 Jackson, MS 39205
- Offshore Power Systems Attn: A. R. Collier, President
 P. O. Box 8000 Jacksonville, FL 32211
- South Carolina Electric and Gas Company Attn: T. C. Nichols, Jr., Vice President Power Production and System Operations
 P. O. Box 764 Columbia, SC 29218
- 11. Tennessee Valley Authority Attn: H. G. Parris Manager of Power 500A Chestnut Street Tower II Chattanooga, TN 37401

12. Virginia Electric and Power Company Attn: R. H. Leasburg Vice President Nuclear Operations P. O. Box 26666 Richmond, VA 23261

(INFORMATION)

In Reference To

50-321 Hatch Unit 1 50-366 Hatch Unit 2 50-424 Vogtle Unit 1 50-425 Vogtle Unit 2

50-416 Grand Gulf Unit 1 50-417 Grand Gulf Unit 2

50-437 ENP 1-8

50-395 Summer Unit 1

50-438 Bellefonte Unit 1 50-439 Bellefonte Unit 2 50-259 Browns Ferry Unit 1 50-260 Browns Ferry Unit 2 50-296 Browns Ferry Unit 3 50-518 Hartsville Unit 1 50-519 Hartsville Unit 2 50-520 Hartsville Unit 3 50-521 Hartsville Unit 4 50-553 Phipps Bend Unit 1 50-554 Phipps Bend Unit 2 50-327 Sequoyah Unit 1 50-328 Sequoyah Unit 2 50-390 Watts Bar Unit 1 50-391 Watts Bar Unit 2 50-566 Yellow Creek Unit 1 50-567 Yellow Creek Unit 2 50-338 North Anna Unit 1 50-339 North Anna Uniu 2 50-404 North Anna Unit 3 50-280 Surry Unit 1 50-281 Surry Unit 2

IE Information Notice No. 82-02 -3-January 27, 1982

(INFORMATION)

Addresses

In Reference To

- 13. Institute of Nuclear Power Operation Attn: R. W. Pack Lakeside Complex 1820 Waterplace Atlanta, GA 30339
- 14. Southern Company Services, Inc. ATTN: O. Batum, Manager Nuclear Safety & Licensing Department
 P. O. Box 2625 Birmingham, AL 35202
- 15. Department of Energy Clinch River Breeder Reactor Plant Project Office ATTN: Chief, Quality Improvement P. O. Box U Oak Ridge, TN 37830
- EDS, Nuclear, Inc. ATTN: E. H. Verdery
 330 Technology Park/Atlanta Norcross, GA 30092

SSINS: 6835 Accession No.: 8107230046 IN 82-02

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

January 27, 1982

IE INFORMATION NOTICE NO. 82-02: WESTINGHOUSE NBFD RELAY FAILURES IN REACTOR PROTECTION SYSTEMS AT CERTAIN NUCLEAR POWER PLANTS

Discussion:

Westinghouse has notified the NRC of a higher-than-expected failure rate of Westinghouse type NBFD relay coils in reactor protection systems at certain power reactor plants. Investigation into the cause for failure revealed that, at high ambient temperature conditions, relay coils could fail due to the inductive voltage spike generated by the deenergization of the relay coil. It was also determined that the relay coil failures have been confined to normally energized relays used in the reactor protection systems where high ambient temperature conditions exist due to heat generated by the normally energized relays.

To date, no failures of NBFD relay coils have been reported in safeguard cabinets where these relays are normally in a deenergized state and temperature conditions are normal.

After reviewing the NBFD relay problem, Westinghouse issued technical bulletin NSD-TB-81-14 on December 7, 1981 to Westinghouse-designed power plants using BFD or NBFD relays in the reactor protection and safeguard systems. An extract of this bulletin is attached for your information and appropriate use. The bulletin provides interim test methods for verifying the operability of normally deenergized and energized NBFD relay applications and recommends replacement of NBFD relays manufactured prior to January 1, 1981. The bulletin also provides relay coil numbers as well as data codes to facilitate affected licensees' replacement efforts if required.

This information notice is provided as an early notelication of a potentially significant matter. It is expected that recipients will review the information for applicability to their facilities. No specific action or response is required at this time. If you have any questions regarding this matter, please contact the Regional Administrator of the appropriate NRC Regional Office.

Attachments:

1. Extract of Westinghouse technical bulletin NSD-TB-81-14, dated 12/7/81

2. Recently issued IE Information Notices

8107230046

Attachment 1 IN 82-02 January 27, 1982 Page 1 of 3

EXTRACT OF WESTINGHOUSE TECHNICAL BULLETIN NSD-TB-81-14

Subject BFD (NBFD) RELAYS	Number NSD-TB-8	1-14
System(s) REACTOR PROTECTION AND SAFEGUARDS SYSTEMS	Date December	7, 1981
Affected Plants All those utilizing BFD or NBFD relays in the above systems.	\$.0.(s) 385	
References NSD-TB-79-5, 76-16, & 76-2. NRC IE BULLETIN 79-25	Sheet 1	Of 3

BACKGROUND

This bulletin pertains to the modified Westinghouse BFD relays designated as NBFD with the style number 5072A49 (followed by the letter G and a two-digit number, depending on pole configuration) and with coil style number 1271C50G01. The NBFD relay was first made available in December 1976. The purpose of this bulletin is to describe a Potential Substantial Safety Hazard attributable to the Westinghouse NBFD relay in certain applications.

Westinghouse has been notified of NBFD relay coil failures which have occurred in the reactor protection cabinets at certain sites. As a result, Westinghouse initiated an investigation to determine the failure mechanism involved. It was concluded that at high ambient temperature, relay coils could burn open due to an inductively induced voltage spike generated upon de-energization of the relay.

NBFD relay coil failures have been confined to the normally energized relays in the reactor protection rack where high ambient temperature conditions exist due to heat generated by the normally energized relays.

NBFD relays located in the safeguards cabinets are normally de-energized, and are energized to provide safeguards actuation. To date, no failures of NBFD relay coils have been reported in the safeguards cabinet. NBFD relays located in the safeguards cabinets are not subject to high temperature conditions due to the normally de-energized state. Also cyclic tests performed quarterly at the relay vendor show no abnormal coil failure.

Since an undetected open coil condition in the safeguards actuation circuitry (however remote) would prevent actuation of functions important to safety, it was reported by Westinghouse as a potential safety hazard for those plants which utilize these relays in the safeguards cabinet.

Attachment 2 IN 82-02 January 27, 1982

RECENTLY ISSUED IE INFORMATION NOTICES

Information Notice No	Subject	Date of Issue	Issued to
82-01	Auxiliary Feedwater Pump Lockout Resulting from Westinghouse W-2 Switch Circuit Modification	01/25/82	All power reactor facilities holding an OL or CP
81-39	EPA Crosscheck Program - Low Level Radiodine in Water Test Program	12/23,′01	facilities holding an OL or CP
81-38	Potentially Significant Equipment Failures Resulting from Contamination of Air- Operated Systems	12/16 31	All power reactor facilities holding an OL or CP
81-37	Unnecessary Radiation Exposure to the Public and Workers during Events Involving Thickness and Level Measuring Devices	12/15/81	All power reactor facilities holding byproduct material licenses
81-36	Replacement Diaphragms for Robertshaw Valve (Model No. VC-210)	12/3/81	All power reactor facilities holding an OL or CP
81-35	Check Valve Failures	12/2/81	All power reactor facilities holding an OL or CP
81-34	Accidental Actuation of Prompt Public Notification System	11/16/81	All power reactor facilities holding an OL or CP
81-33	Locking Devices Inadequately Installed on Main Steam Isolation Valves	11/9/81	All power reactor facilities holding an OL or CP
B1-32	Transfer and/or Disposal of Spent Generators	10/23/81	All medical licensee

OL = Operating License CP = Construction Permit antly issued IE Information Notice will be included when IN No. and issued date are assigned.

Attachment 1 IN 82-02 January 27, 1982 Page 2 of 3

EXTRACT OF WESTINGHOUSE TECHNICAL BULLETIN NSD-TB-81-14 (continued)

INTERIM RECOMMENDATIONS

Westinghouse recommends the following interim measures for normally de-energized and normally energized NBFD relays.

(A) NORMALLY DE-ENERGIZED APPLICATIONS

In normally de-energized applications, test for continuity of the relay coil and amend applicable test procedures to require a continuity test following every energized/de-energize cycle of the relay, including cycles required by periodic test procedures.

Westinghouse plants with provisions for on-line test capability can utilize these provisions to verify continuity of the NBFD relay coils. Those plants which [do not] have on-line test capability should make use of portable test equipment to verify the continuity for each NBFD relay coil.

(a) Plants with on-line test capability:

Utilize established test procedures normally used during periodic on-line testing. These procedures which utilize the white test lamps provide indication of coil continuity.

(b) Plants without on-line test capability:

Utilize a volt-ohm meter to check resistance across the NBFD relay coil leads. If relays are connected in parallel, use the parallel resistance law to determine if any coil is open. If any parallel combination gives indication of an open coil, each individual coil must be checked to determine the failed coil.

(B) NORMALLY ENERGIZED APPLICATIONS

Although open relay coils in normally energized applications result in the system (i.e. reactor trip) falling into a safe state tending to trip the reactor, Westinghouse recommends the following: When the relay is energized (after a previous de-energization), visually verify that the armature has moved to the pulled-in position by observing the pushbuttons atop the contact assembly. The relay is energized if the pushbuttons protrude from the assembly by no more than 1/8 inch.**

**NOTE: Manual depression of pushbuttons should result in no inward movement of the armature of an energized relay and may be used if desired in lieu of visual verification.

Attachment 1 IN 82-02 January 27, 1982 Page 3 of 3

EXTRACT OF WESTINGHOUSE TECHNICAL BULLETIN NSD-TB-81-14 (continued)

LONG TERM RECOMMENDATIONS

Relays manufactured after January 1, 1981 incorporate additional (mylar) insulating material which has been confirmed by tests to resolve coil burnout by high voltage spikes generated when the relay coil current is interrupted. It is recommended that the utility consider installing this improved coil during the next scheduled outage.

Relay coils with improved insulating material manufactured after January 1981 bear the style number 1271C50G01 and a date code, visible on the unmounted coil. Those coils manufactured after October 28, 1981 bear the style number 1293C51G01 such that code date verification is unnecessary.

Contact your Westinghouse Nuclear Service Division representative...for additional information pertaining to replacement coils.

To preclude excessive heating of the NBFD relay coil and degradation of coil insulation, Westinghouse reaffirms its recommendations for review of station battery charging procedures, such that the NBFD relay coils should not be subject to battery equalization voltages in excess of the coil rating. Caution should be exercised to ensure that charging voltage be limited to 140 VDC and that charging at 140 VDC be limited to 24 hours duration if the previous charging period [occurred]...less than 30 days [previous].

APPLICABILITY

The information in this bulletin does not apply to Westinghouse plants using a Solid State Protection System.