



W. Miller

UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION II
101 MARIETTA ST., N.W., SUITE 8100
ATLANTA, GEORGIA 30303

FEB 15 1983

SSINS 9162

MEMORANDUM FOR: Edward L. Jordan, Director, Division of Engineering and Quality Assurance, IE
Richard W. Starostecki, Director, Division of Project and Resident Programs, RI
Charles E. Norelius, Director, Division of Project and Resident Programs, RIII
James E. Gagliardo, Director, Division of Resident, Reactor Project and Engineering Programs, RIV
Jesse L. Crews, Director, Division of Resident, Reactor Project and Engineering Inspection, RV

FROM: Richard C. Lewis, Director, Division of Project and Resident Programs

SUBJECT: POTENTIALLY GENERIC DEFICIENCY IN RUSKIN MANUFACTURING COMPANY FIRE DAMPERS

The enclosed potentially generic issue data sheet concerning nonfunctional fire dampers at Sequoyah and Watts Bar is forwarded for information per TI 2500/3.

R. C. Lewis
R. C. Lewis

- Enclosure:
1. Fire Damper Issue Data Sheet
 2. Sequoyah Special Report 83-02
 3. Watts Bar CDR 390/82-113, 391/82-106

CONTACT: W. H. Miller
242-5582

8508080737 850624
PDR FOIA
MCDEVIT85-264 PDR

ENCLOSURE 1

Data Sheet No.:RII:DPRP-83-04

POTENTIALLY GENERIC ISSUE DATA SHEET

Facility Sequoyah 1 and Watts Bar 1, 2 Docket No(s). 50-327, 50-390 50-391

Date of Event 1/27/83 Inspection or other Report Sequoyah Special Rpt 83-02 and Watts Bar CDR 390/82-113, 391/82-106.

1. Brief Description of Issue (Not required if included in supporting data).

During the preoperational tests of fire dampers at Watts Bar, vertical curtain type gravity operated fire dampers failed to close against normal operating air flow. Subsequent tests at Sequoyah confirmed this discrepancy. Refer to attached Sequoyah Special Report 83-02 and Watts Bar CDR 390/82-113, 391/82-106.

2. How Found (If appropriate)

Licensee identified the discrepancy while conducting operational tests of the dampers.

3. Why Considered Potentially Generic (i.e. - reference applicable criteria or give reason)

Fire dampers are provided in ventilation penetrations of fire barriers at practically all plants. The type dampers installed at Watts Bar and Sequoyah may also be located at other plants.

4. II W. H. Miller T. Conlon
Region Originator Section Chief/Branch Chief

5. Other Region Reporting That The Problem Has Also Been Identified By Them

Region _____, Chief _____, Reporting _____, Docket No. _____

6. Evaluation by IE:HQ

Bulletin / Circular / Information Notice /

Other _____

No further action required

RECEIVED
WATTS BAR
JUN 02 1983
D.V. OF CONSTR.

MASTER FILE

INSTRUCTION PROCEDURES
FOR
STORAGE, INSTALLATION, OPERATION & MAINTENANCE
OF
NIBD23 CURTAIN TYPE FIRE DAMPER/DOORS

THIS COPY
NOT FOR OFFICIAL USE
EXCEPT WHEN VALIDATED

N2M-1201
FILE: N3M-936 MAY 09 1983
PROJECT SON & WBN
CONTRACT 83K71-832769
DRAWING # E-511
SHEET 1
REVISION 0
UNIT 1 & 2

USE: ADDTL. NEGATOR CLOSURE
SPRING KITS ON HVAC
FIRE DAMPERS

RIJSKIN MANUFACTURING COMPANY
P. O. Box 129
Grandview, Missouri 64030

ACCEPTED FOR USE
TENNESSEE VALLEY AUTHORITY
DATE MAY 20 1983
(MECH. ENGR BR) BY E. A. CHANDLER
App'd By Ltr. # 32-139

VI
Reply to
M.F.'s 100-111 K

RUSKIN Manufacturing Company
RUSKIN. *air handling specialties*

ENGINEERING
 PROCEDURE NO. E-511

Rev. No. 0

Date: August 19, 1982

INSTALLATION INSTRUCTIONS - NIBD23
 CURTAIN TYPE FIRE DAMPER/DOOR

Page 1 of 7

- 1.0 Prior to installation, fire damper/doors should be removed from packaging and inspected for damage, obstructions, rust or corrosion.
- 2.0 Installation of fire damper/doors
- 2.1 Fire damper/doors are marked with sticker indicating appropriate "UP" direction. Install fire damper/doors with "UP" arrow pointing "UP".
- 2.2 Installation Instructions
- Damper/Doors shall be installed in accordance with the appropriate Ruskin "Installation Instruction" sheet (see attached forms II-IBD23 for Vertical Single or Dual Installation and Horizontal Installation) - or - in accordance with other "approved drawings, instructions or procedures" that may apply to a specific project. Any "approved drawings, instructions or procedures" issued by Ruskin, the Utility, or the Engineer describing installation for a specific project that may differ from the Standard Ruskin Installation Instructions should be followed.
- 2.3 Critical tolerances must be maintained after installation.
- 2.3.1 Dampers must be installed with frames straight, square and free of obstructions.

Written by: Ted Lasher

Approved by: Bob Van Becelaere

Date: 8/19/82

RUSKIN Manufacturing Company
RUSKIN. *air handling specialties*

ENGINEERING
 PROCEDURE NO. E-511

Rev. No. 0

Date: August 19, 1982

INSTALLATION INSTRUCTIONS - NIBD23
 CURTAIN TYPE FIRE DAMPER/DOOR

Page 2 of 7

2.3.2 Dampers shall be square within 3/8" when measured diagonally across corners.

NOTE: Other means of verifying squareness may be utilized if they accomplish similar results.

2.3.3 Frame to blade clearance must be 1/8" minimum to 7/16" maximum. To check this clearance, the following steps need to be followed:

2.3.3.1 Release blade package to a closed position.

2.3.3.2 Move blades to one side of frame and inspect other end for clearance, this should be checked in three (3) places: top, middle and bottom of blade package.

2.3.3.3 After inspection of clearance, blade package must be refolded, the fusible link replaced and the "S" hooks reconnected. "S" hooks may be crimped or uncrimped per drawing number 4875 (attached).

Written by: Ted Lasher

Approved by: Bob Van Becelaere Date: 8/19/82

RUSKIN Manufacturing Company
RUSKIN. *air handling specialties*

ENGINEERING
 PROCEDURE NO. E-511

Rev. No. 0

Date: August 19, 1982

INSTALLATION INSTRUCTIONS - NIBD23
 CURTAIN TYPE FIRE DAMPER/DOOR

Page 3 of 7

2.4 Ruskin's Quality Assurance Department verifies and documents that fire damper/doors destined for Nuclear Power Plants have dimensional tolerance as indicated in 2.3 above at the time of shipment. Installer must maintain these dimensional tolerances after installation for the fire damper/doors to be warrantable.

2.4.1 Ruskin reserves the right to spot check installed dampers to verify that dimensional tolerances have been maintained after installation and will be relieved of any warranty responsibilities if dampers are installed improperly.

2.5 Accessibility must be provided to all installed fire damper/doors.

2.5.1 Fire damper/doors require inspection after installation as well as periodic inspection at intervals during system operation and replacement of fusible link should duct temperatures accidentally cause fusible link to melt. All fire damper/doors must be provided with suitable access doors and duct clearances to allow accomplishment of these functions without removal of duct. (This is a basic requirement of the National Fire Code - NFPA90A.)

Written by: Ted Lasher

Approved by: Bob Van Beelaere

Date: 8/19/82



11-18023 1279
Replaces
Form 11-18023 178

INSTALLATION INSTRUCTIONS CURTAIN TYPE IBD FIRE DOORS SINGLE & MULTI SECTION VERTICAL INSTALLATION SINGLE DOOR REQUIREMENTS

Page 4 of 7

Openings in wall shall be $\frac{1}{4}$ " to $\frac{1}{2}$ " larger than overall size of fire door and sleeve assembly.



Sleeve gage shall be at least equal to the gage of the duct as defined by the appropriate SMACNA Duct Construction Standard, as described in NFPA80A, when one or more of the following Duct Sleeve Connections are used (Plain S Slip, Hemmed S Slip, Standing S Slip, Reinforced Standing S Slip, Inside Slip Joint, Double S Slip).

If any other Duct Sleeve Connections are used, the sleeve shall be minimum 16 gage for dampers up to 36" w x 24" h and 14 gage if width exceeds 36" or height exceeds 24".

Mounting angles shall be minimum of $1\frac{1}{2}$ " x $1\frac{1}{2}$ " x 14 gage and belted, tack welded, riveted, or screwed to sleeve at maximum spacing of 8" and with minimum of two connections in each side, top and bottom. Mounting angles shall overlap wall a minimum of one inch on all four sides.

Door shall be belted, tack welded, riveted, or screwed to sleeve on same spacing as angles.

If door is installed without connected duct work, 18 gage sleeve is recommended.



18023 Fire Door with 3 Hour UL Label for Installation in walls required to have 3 or 4 hour Fire Protection Ratings.

INSTALLATION INSTRUCTIONS COMPLY WITH WRITERS LABORATORIES SAFETY STANDARDS 565



RUSKIN

II-18023 1279
Replaces
Form II-18023 178

INSTALLATION INSTRUCTIONS CURTAIN TYPE IBD FIRE DOORS SINGLE & MULTI SECTION VERTICAL INSTALLATION DUAL DOOR REQUIREMENTS

Page 5 of 7

Openings in wall shall be $\frac{1}{8}$ " to $\frac{1}{4}$ " larger than overall size of fire door and sleeve assembly.



Sleeve gage shall be at least equal to the gage of the duct as defined by the appropriate SMACNA Duct Construction Standard, as described in NFPA90A, when one or more of the following Duct Sleeve Connections are used (Plain S Slip, Hemmed S Slip, Standing S Slip, Reinforced Standing S Slip, Inside Slip Joint, Double S Slip).

If any other Duct Sleeve Connections are used, the sleeve shall be minimum 16 gage for dampers up to 36" w x 24" h and 14 gage if width exceeds 36" or height exceeds 24".

Mounting angles shall be minimum of $1\frac{1}{2}$ " x $1\frac{1}{2}$ " x 14 gage and bolted, tack welded, riveted, or screwed to sleeve at maximum spacing of 8" and with minimum of two connections in each side, top and bottom. Mounting angles shall overlap wall a minimum of one inch on all four sides.

Door shall be bolted, tack welded, riveted, or screwed to sleeve on same spacing as angles.

If door is installed without connected duct work, 16 gage sleeve is recommended.



18023 Fire Door with 3 Hour UL Label for installation in walls required to have 3 or 4 hour Fire Protection Ratings.

NOTE: Dual Fire Doors are not always required. This information provided for those local jurisdictions that require Dual Fire Doors to comply with restrictive local codes.


INSTALLATION INSTRUCTIONS COMPLY WITH UNDERWRITERS LABORATORIES SAFETY STANDARDS 555





II-IBD23-1079
Replaces II-IBD23-879


**THREE HOUR UL CLASSIFIED
CURTAIN TYPE IBD FIRE DAMPERS
SINGLE & MULTI SECTION
HORIZONTAL INSTALLATION**
Page 6 of 7



The mullion between the sides of the dampers shall be either a 4 1/2 in. wide steel plate (14 MSG galvanized steel) or 1 1/2 by 4 1/2 in. tubular section (12 MSG galvanized steel). Mullion length shall be equal to length of two adjoining dampers.

The steel plate mullion shall be sandwiched between sides of dampers with frames welded at top and bottom with 1 in. long fillet welds spaced 7 in. O.C.

The tubular section mullion shall be welded to the sides of the damper frames with 1 in. long fillet welds spaced 6 in. O.C.



NOTES

Openings in floor or wall shall be 1 in. larger than overall size of the damper and sleeve assembly.

Sleeve gage shall be at least equal to the gage of the duct as defined by the appropriate SMACNA Duct Construction Standard and described in NFPA 90A when one or more of the following Duct-Sleeve Connections are used (Plain "S" Slip, hemmed "S" Slip, Standing "S" Slip, Reinforced Standing "S" Slip, Inside Slip Joint, and Double "S" Slip). If any other Duct-Sleeve Connections are used, sleeve shall

be minimum of 16 gage for dampers up to 36" w x 24" h or 14 gage if damper width exceeds 36" or height exceeds 24"

Mounting angles shall be a minimum of 2" x 2" x 10 gage or bolted with 1/2" - 20 bolts and nuts, 8" - C-C maximum minimum 2 bolts in each side, top and bottom or weld with 1" fillet welds on same centers. Mounting angles shall overlap wall a minimum of one and one-half inches on four sides.

Dampers shall be bolted or welded to sleeve on same spacing as angles.

INSTALLATION INSTRUCTIONS COMPLY WITH UNDERWRITERS LABORATORIES SAFETY STANDARDS 888



DETERMINATION OF REPORTABILITY
INFORMATION WORKSHEET FOR 10CFR50.55(e)

Plant WATTS B/R Item Number 5036

Title DAMPERS NOT ADEQUATELY SHOWN ON DESIGN TYPICAL DRAWINGS

NLS Engr FRANK WHITE Date 8/22/83 NLS Supv SPM Date 8/24/83

Determination under 50.55(e) - Reportable , Non-reportable () (Only true if A, B, and C1 below are affirmative and C2 is negative.)

A. The subject condition, had it remained uncorrected (could) ~~(could not)~~ have affected adversely the safety of operations of the plant.

Explanation: The Des has not generated typical drawings which reflect a) installation drawings for flow control operated dampers b) manufacturer's minimum space requirements between fire damper and the adjacent shaft and c) backing dampers. Some of the curtain-type fire dampers were installed per the drawing with fire clearance. Therefore, in the event of a fire, the fire could not be contained in its isolated area because the dampers may fail to close due to the zero clearance and the fire could spread through the HVAC system. See Book -

B. The item (is) ~~(is not)~~ considered significant as defined by 10CFR50.55(e).

No 1. The condition represents a significant breakdown of a portion of the Quality Assurance Program for the plant. TVA (), Vendor ()

YES 2. The condition represents a significant deficiency in final design as approved and released for construction such that the design does not conform to (issued design criteria) ~~(criteria and bases stated in the SAR) (conditions of the construction permit)~~.

Yes due to deficiency in final design 3. The condition represents (a significant deficiency in construction) ~~(significant damage) to a (structure) (system) (component) which will require extensive (evaluation) (redesign) (repair) or meet (issued design criteria) (criteria and bases stated in the SAR) (conditions of the construction permit) or to establish the adequacy of the (structure) (system) (component) to perform its intended safety function.~~

-> NO 4. The condition represents a significant deviation from performance specifications which will require extensive (evaluation) (redesign) (repair) to establish the adequacy of a (structure) (system) (component) to meet (issued design criteria) (criteria and bases in the SAR) (conditions of the construction permit) or to establish the adequacy of the (structure) (system) (component) to perform its intended safety function.

Explanation (Items B.1-B.4) This condition represents a significant deficiency in final design since the typical design drawings do not reflect the manufacturer's minimum space requirements for clearance. This also represents a significant deficiency in const due to design drawings that were used to install the dampers.

- C1. Does the affected unit(s) have a CP? Yes No
- 2. Does the affected unit(s) have an OL? Yes No

D. Are there implications to other matters not included on the NCR or to other plants?

2/20/83

~~We had similar type problem at SQW which was corrected. We do not have any deficiencies of this type at BLN or any other TVA nuclear plant. BLD has redesigned this problem in the past and designed the fire dampers accordingly. An investigation will be made to evaluate the applicability of this deficiency to SQW and BLN.~~

E. Basis of reportability statement:

Since item A (is) ~~(is not)~~ affirmative and/or item B (is) ~~(is not)~~ affirmative, the condition (is) ~~(is not)~~ reportable under 10CFR50.5(e).

2/20/83
 compartmentation and the fire could spread to

(A. Continued)

10CFR.50

The HVAC ductwork could lose safety-related equipment due to increased heat and pressure; thus adversely affecting the safe operation of the plant. Note: this ductwork (HVAC system) is located in Aux Bldg. A 100% inspection of all curtain-type fire dampers will be made.

- C1. Does the affected unit(s) have a CP? Yes No
- 2. Does the affected unit(s) have an OL? Yes No

D. Are there implications to other matters not included on the NCR or to other plants?

2/20/83
~~We had a similar type problem @ SQN which was corrected. We do not have any deficiencies of this type @ BLN or any other TVA nuclear plant. B&E has redesigned this problem in the past and designed the fire dampers accordingly. An investigation will be made to evaluate the applicability of this deficiency to SQN and BLN.~~

E. Basis of reportability statement:

Since item A (is) ~~(is not)~~ affirmative and/or item B (is) ~~(is not)~~ affirmative, the condition (is) ~~(is not)~~ reportable under 10CFR50.5(e).

(A. Continued)

2/20/83
 compartmentation and fire could spread to

10CFR.50

The HVAC ductwork could lose safety-related equipment due to increased heat and pressure; and thus adversely affecting the safe operation of the plant. Note: the ductwork (HVAC system) is located in Aux Bldg. A 100% inspection of all curtain-type fire dampers will be made.