J. R. Johnson Vice President – Farley Southern Nuclear Operating Company, Inc. Post Office Drawer 470 Ashford, Alabama 36312-0470

Tel 334.814.4511 Fax 334.814.4728



September 15, 2008

Docket Nos.: 50-348

NL-08-1357

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555-0001

> Joseph M. Farley Nuclear Plant – Unit 1 Licensee Event Report 2008-003-00 Emergency Diesel Generator 1-2A Lube Oil Heat Exchanger Leak

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(i)(A) and 50.73(a)(2)(v)(D), Southern Nuclear Operating Company (SNC) is submitting the enclosed Licensee Event Report.

This letter contains no NRC commitments. If you have any questions, please advise.

Sincerely,

J. R. Johnson // Vice President – Farley

JRJ/CHM

Enclosure: Unit 1 Licensee Event Report 2008-003-00

cc: <u>Southern Nuclear Operating Company</u> Mr. J. T. Gasser, Executive Vice President Mr. J. R. Johnson, Vice President – Farley Mr. D. H. Jones, Vice President – Engineering RTYPE: CFA04.054; LC # 14826

> <u>U. S. Nuclear Regulatory Commission</u> Mr. L. A. Reyes, Regional Administrator Mr. R. A. Jervey, NRR Project Manager – Farley Mr. E. L. Crowe, Senior Resident Inspector – Farley

J. R. Johnson Vice President – Farley Southern Nuclear Operating Company, Inc. Post Office Drawer 470 Ashford, Alabama 36312-0470

Tel 334.814.4511 Fax 334.814.4728

Joseph M. Farley Nuclear Plant – Unit 1 Licensee Event Report 2008-003-00 Emergency Diesel Generator 1-2A Lube Oil Heat Exchanger Leak

Enclosure

Unit 1 Licensee Event Report 2008-003-00

NRC FOR	RM 366			U.S. NUCLE	AR RE	GULATO	RY COMMI	ISSION	AP	PROVE	d by omb	NO. 315	0-010	4	EXPIRES	08/31/2010
LICENSEE EVENT REPORT (LER)					Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burder estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by interne e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Informatio and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management an Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC ma not conduct or sponsor, and a person is not required to respond to, th information collection					rry collection ted into the rrding burden 5 F52), U.S. or by internet f Information agement and n information the NRC may pond to, the						
1. FACIL	ITY NAM	^{1E} Farley	Nucle	ar Plant -	- Uni	it 1			2. I	DOCKE 05	T NUMBI	ER 8	3	. PAGE 1	of 5	
4. TITLE	ergeng		sel Ge	nerator 1-	2A I	uhe Oi	l Heat l	Excha	and	ner l	eak	•				
5. E		ATF	6.		2	7. R	FPORT D	ATE		<u>je. </u>	8.	OTHER	FACI	LITIES INVO		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAF	۲	FACILITY	NAME				DOCKET 050	NUMBER
07	21	2008	2008	- 003 -	00	09	15	08	1	FACILITY	NAME				DOCKET 050	NUMBER
9. OPER	ATING N	IODE	11	. THIS REPO	RT IS	SUBMITTI	ED PURS	JANT T	T O	HE RE	QUIREM	ENTS OF	10 C	CFR§: (Che	ck all that	apply)
10. POW	1 10. POWER LEVEL 100			201(b) 201(d) 203(a)(2)(i) 203(a)(2)(ii) 203(a)(2)(ii) 203(a)(2)(iii) 203(a)(2)(iv) 203(a)(2)(v) 203(a)(2)(vi)		□ 2 □ 2 □ 5 □ 5 5 □ 5 5 5 5 5 5 5 5 5 5 5 5 5 5	0.2203(a) 0.2203(a) 0.2203(a) 0.36(c)(1) 0.36(c)(1) 0.36(c)(2) 0.46(a)(3) 0.73(a)(2) 0.73(a)(2)	(3)(i) (3)(ii) (4) (i)(A) (ii)(A) (ii)(A) (i)(A) (i)(B)			50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a)	(2)(i)(C) (2)(ii)(A) (2)(ii)(B) (2)(ii) (2)(iv)(A) (2)(v)(A) (2)(v)(A) (2)(v)(C) (2)(v)(C) (2)(v)(D)		□ 50.7 □ 50.7 □ 50.7 □ 50.7 □ 50.7 □ 73.7 □ 73.7 □ OTH Spec	3(a)(2)(vii 3(a)(2)(vii 3(a)(2)(vii 3(a)(2)(vii 3(a)(2)(x) 3(a)(2)(x) 1(a)(4) 1(a)(5) IER ify in Abstra)(A))(B) (A) act below
					1		SEE CONT		OR		FR			or in	NRC Form	366A
NAME						Z. LIOLIN				11110 2			TELE	PHONE NUMBE	R (Include Ar	ea Code)
J.	. R. Jo	hnsor	n – Vic	e Preside	nt								3	34 899-5	156	
			13. CON	IPLETE ONE	LINE I	OR EACI	Н СОМРО	NENT F	FAIL	URE	DESCRIB	ED IN TH	IS RI	EPORT		
CAU	SE	SYSTEM	COMPO	NENT FACTU	NU- JRER	REPOR TO E	RTABLE EPIX	С	AUS	ε	SYSTEM	COMPON	NENT	MANU- FACTUREF	REPO	ORTABLE D EPIX
E		LB	Н	K A3	21	١	1									
		14	. SUPPL	EMENTAL RE	EPOR	Г ЕХРЕСТ	ED				15. E	(PECTE	D	MONTH	DAY	YEAR
☐ YE	S (If yes,	complet	e 15. EX	PECTED SUB	MISSI	ON DATE)	\boxtimes] NC	C	506	DATE				
ABSTRA On Em Oil app she B-T rep (TS cor pla Edd ind hyc the hou	CT (Limi July 2 Reserve proxima ell side Train El laceme 3) 3.8.1 nmenc ced in l dy curre ication drostati engine urs. EL	t to 1400 1, 2008 cy Diese voir. Th ately 30 drains. DG had ent. Th Condit ed at 09 Mode 3 ent and of leak cally tes cleane DG 1B v	spaces, water el Gene le Lube 0 gallor EDG ² been p e comb ions E 541 CS prior to pressu age. Fo sted wite d to re vas retu	<i>i.e., approxima</i> was discove rator (EDG o Oil sump le ns. An add 1-2A (an A- previously re ination of b and F. A te T on July 2 o 1058 hour ure testing v our addition th no indica move any r urned to ser	ately 1 ered i) 1-2/ evel v itiona Train emov oth d echnic 2, 20 rs. U vas p hal tuk tion c esidu rvice	n the Lu A [EK] du was foun I 65 gall EDG) w red from iesels be cal speci 08 in acc nit 1 rea erformed be were of leakag ial water on July 2	baced type be Oil [L uring invi- nd to be to ons of w vas decla service eing out fication cordance ched Mc d on the preven je. The c. EDG 2 28, 2008	A survition A survition arestigation three in ared in on Juli of servitic e with ode 3 a Lube tatively entire 1-2A w are 09	line mp ition ncl vas iop y 2 vice ed TS TS Oil y p die vas 21	and t n of a drain erable 0, 200 e requishut 3.8.1 046 h Heat lugge sel lu return hours	he Lube high lev bove the ed from on July 08 for a hired ent own fror Conditi hours. Exchan d. The be oil su hed to s	Oil He el alarr norma the Luk 21, 20 planne ry into n Mode on F, w ger with Lube O imp cor ervice c	at E n in l lev be C 08 a d ex Tech hich hich hich n two il He	xchanger the Rocke rel which r bil Heat Ex at 2058 ho haust hea nnical Spe o Mode 3 n required to tubes sh eat Exchar ts were dr uly 29, 200	[LB] of epresen changer urs. Un der cification was Unit 1 to owing nger was ained ar 08 at 200	ube ts it 1 n b be s id 00

Until the failed tubes can be removed and the leakage mechanism determined, monitoring of all EDG Lube Oil Sumps and Lube Oil Heat Exchangers has been increased.

NRC FORM 366A (9-2007)	LICENSEE CON	E EVENT REF	PORT (LI SHEET	ER) ^{U.S. NUC}	LEAR REG	ULATOF	RY COMMI	SSION
1.	FACILITY NAME	2. DOCKET	6. LER NUMBER 3. PAGE					
Iosenh M. Farley Nuclear Plant I Init - 1		05000 348	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	of	5
•••• p	,		2008	- 003 -	00	_	•	•
NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)								

Westinghouse -- Pressurized Water Reactor Energy Industry Identification Codes are identified in the text as [XX]

Description of Event

On July 21, 2008 water was discovered in the Lube Oil [LA] sump and the Lube Oil Heat Exchanger [LB] of Emergency Diesel Generator (EDG) 1-2A [EK] during investigation of a high level alarm in the Rocker Arm Lube Oil Reservoir. The Lube Oil sump level was found to be three inches above the normal level which represents approximately 300 gallons. An additional 65 gallons of water was drained from the Lube Oil Heat Exchanger shell side drains. EDG 1-2A (an A-Train EDG) was declared inoperable on July 21, 2008 at 2058 hours. Unit 1 B-Train EDG had been previously removed from service on July 20, 2008 for a preventive maintenance replacement of the exhaust headers. The combination of the planned 1B EDG outage and the emergent 1-2A EDG outage required entry into Technical Specification (TS) 3.8.1 Conditions E and F. A technical specification required shutdown from Mode 1 to Mode 3 was commenced at 0541 CST on July 22, 2008 in accordance with TS 3.8.1 Condition F, which required Unit 1 to be placed in Mode 3 prior to 1058 hours. Unit 1 reached Mode 3 at 1046 hours.

Unit 2 was affected by the 1-2A EDG being removed from service. However, there was no loss of safety function on Unit 2 because the B-Train EDG 2B was operable. Unit 2 remained in Mode 1, 100% power under TS 3.8.1 Condition B.

An eight hour non-emergency notification (EN # 44358) was made on July 21, 2008 in accordance with 10 CFR 50.72(b)(3)(v)(D) to report a condition that could have prevented fulfillment of a safety function due to both trains of EDGs being inoperable. A subsequent four hour non-emergency notification (EN # 44359) was made on July 22, 2008 in accordance with 10 CFR 50.72(b)(2)(i) to report the plant shutdown as required by Technical Specifications.

Eddy current and pressure testing was performed on the Lube Oil Heat Exchanger with two tubes showing indication of leakage. Four additional tubes were preventatively plugged. The Lube Oil Heat Exchanger was hydrostatically tested with no indication of leakage. The entire diesel lube oil sump contents were drained and the engine cleaned to remove any residual water. EDG 1-2A was returned to service on July 29, 2008 at 2000 hours. EDG 1B was returned to service on July 28, 2008 at 0921 hours.

NRC FORM 366A (9-2007)	LICENSEE CONT	EVENT REF	PORT (LE SHEET	ER) ^{U.S. NUC}	LEAR REG	ULATO	RY COMM	SSION
	1. FACILITY NAME	2. DOCKET	6. LER NUMBER 3. PAGE					
.losenh M. Farley Nuclear Plant Unit - 1		05000 348	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	of	5
••••p			2008	- 003 -	00	•	01	•

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Cause of Event

The loss of safety function and required shutdown of Unit 1 was caused by the unexpected leakage of the EDG 1-2A Lube Oil Heat Exchanger tubes in conjunction with EDG 1B being out of service for exhaust header replacement. The EDG 1-2A is a Fairbanks-Morse model PC2 V-12 diesel generator rated at 4,075 kw. The tube side of the heat exchanger is supplied by plant Service Water which is a raw water system coming from the plant Service Water Pond.

Based on SNC and industry experience these tube breaches were not predicted nor expected at this time in the existing tube bundle's life. This tube bundle had been in service for approximately 10 years and the known degradation mechanism of erosion had been adequately addressed via the application of an epoxy coating on the tubesheet and inside the inlet end of each tube. SNC and industry experience had found that with a properly applied protective coating preventing erosion, no other degradation mechanisms were known to exist within this heat exchanger. Regularly scheduled Eddy Current Testing (ECT) inspections were planned to begin within the next 5 years to monitor this heat exchanger's health as the tube bundle aged.

Since the leaking tubes could not be removed from the heat exchange at this time, the actual cause of the tube leakage has not been determined. While the individual tube pressure test identified pressure boundary breaches in two tubes, the exact nature of these breaches could not be determined. During this EDG outage, ECTs were performed on this heat exchanger three different times in an attempt to detect any flaw or defect. No flaws or defects were detected in any of the six tubes plugged.

Inspection on the heat exchanger tube bundle was performed in place using access ports. No source of degradation was identified. A replacement tube bundle was not available in the industry during this event. SNC is ordering replacements tube bundles. Since the required vendor support was not available to remove the damaged tubes for inspection and a replacement tube bundle did not exist in case the bundle was damaged during tube extraction, SNC chose to plug known leaking tubes. In addition SNC preventively plugged tubes and established interim actions to monitor the heat exchangers until the leakage mechanism is determined and appropriate actions developed. The interim actions given in the Corrective Actions section will minimize the likelihood of undetected leakage of water into the lube oil system that would adversely impact diesel generator performance.

NRC FORM 366A LICENSEE (9-2007) CON	EVENT REI	PORT (LI SHEET	ER) ^{U.S. NU}	CLEAR REG	ULATOR		SSION
1. FACILITY NAME	2. DOCKET		6. LER NUMBER			3. PAGE	
Joseph M. Farley Nuclear Plant Unit - 1	05000 348	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4	of	5
	00000 040	2008	- 003	- 00	-	01	U
NARRATIVE (If more space is required, use additional copie	s of NRC Form 366	A) (17)			I		
Safety Assessment							
This event had no adverse effect on the	he safety and	health of t	he public.				
The Farley onsite standby power sour continuous service rating of 1C EDG i 1-2A and 1-C are A-Train and EDGs 7 (2C), rated at 2,850 kW, that serves a supply B-Train power to either unit an generator 2C can provide backup pow place and operators are trained on sta emergency buses.	rce is provided is 2,850 kW ar 1B and 2B are is a station bla d power Loss ver to the buse arting the 2C d	I from four nd 4,075 k B-Train. Ickout dies of Site Po es supplied liesel gene	EDGs (1-2A W for EDGs Farley also h sel which car wer (LOSP) d by 1B EDG erator for alig	A, 1B, 2B, 1-2A, 1B has a fifth be manu loads. Th b. Proced pnment to	and 10 , and 2 diesel ually ali ne dies ures ar the B-	C). The B. EDC genera gned to el re in Train	G tor
During the time that EDG 1-2A and 1E available to supply power to Unit 1. E LOSP loads for Unit 1. Unit 2 B-Train Unit 2. During the time that two EDGs events occurred which challenged the were available. Therefore, the safety	B were inopera ither diesel ge EDG 2B was s were inopera off-site power and health of	able, EDG enerator w operable able on Un r supplies the public	1C and dies ould have be and available it 1 (July 21 and EDG 10 was not adv	el genera een able to e to suppo to July 29 and dies ersely aff	ator 2C o carry ort any 0, 2008 sel gene ected.	were the event c) no erator 2	on 2C
Corrective Action							
EDG 1-2A was declared inoperable at testing was performed on the Lube Oi leakage. Four additional tubes were p hydrostatically tested with no indication drained and the engine cleaned to rem returned to service.	nd Unit 1 was I Heat Exchan preventatively on of leakage. nove any resid	placed in oger with to plugged. The entire dual water	Mode 3. Ed wo tubes sho The Lube O e diesel lube . EDG 1-2A	dy current owing indi il Heat Ex oil sump was subs	t and p cation change conten sequen	ressure of er was ts were tly	
Until the leaking heat exchanger tubes mechanism and appropriate actions d	s can be extra leveloped, the	cted and a following	analyzed to c interim actio	letermine ns are in j	the lea place:	akage	
All diesel generator Lube Oil Sum	p levels are be	eing check	ed once eve	ry 12 hou	ırs.		
Diesel Generator Lube Oil Heat E once per 7 days.	xchangers and	d Lube Oil	Sumps are	being che	cked fo	or water	
Diesel Generator Lube Oil Heat E	xchangers she	ell side will	be checked	for water	prior to	o any	
Diesel Generator Lube Oil Sumps	will be sample	ed after so	heduled sur	veillance	runs.		
					PRINTED		

NRC FORM 366A LICENSEE		PORT (LE	ER) ^{U.S. NUC}	CLEAR REG	ULATOR		SSION
		SHEET					
	2. DOCKET	YEAR				3. PAGE	
Joseph M. Farley Nuclear Plant Unit - 1	ph M. Farley Nuclear Plant Unit - 1 05000 348						5
NARRATIVE (If more space is required, use additional copie	es of NRC Form 366	A) (17)					
Additionally the following correctives	action are sche	eduled:					
The failed tubes from EDG 1-2A L Completion Date: January 30, 200	_ube Oil Heat E 09	Exchanger	will be remo	oved for a	nalysis		
Analyze the removed tubes to det Completion Date: March 30, 2009	termine the cau	use of the	leakage mec	hanism.			
Results of the tube leakage analy maintenance program. Completion	sis will be inco on date: May 3	rporated ir 0, 2009	nto the servic	e water h	neat ex	change	r
Additional Information							
Previous Similar Events							
LER 2008-001-00 Unit 1 Emerger	ncy Diesel Gen	erator 1B	Exhaust Pip	e Failure			
LER 2008-002-00 Unit 1 TS 3.0.3	Entry Due to I	noperabili	ty of Residua	al Heat R	emoval	Syster	n

NRC Correspondence Routing and Information Sheet

			Applicable t	:o: 10 CFR 5/	0 Docket No.	10 CFR 72 No.					
NRC Due Date:	09-20-08	Hatch	U1-321	U2-366	1	72-36					
Author:	H. Mahan	F arley	U1-348 🗙	U2-364	LC # <u>14826</u>	72-42					
Lic Letter No.	NL-08-1357	Vogtle	U1-424	U2-425		N/A					
Subject of Letter:	Subject of Letter: LER 2008-003-00 for DG 1-2A Exhaust Leak										
Response to:	Response to:										
Review / Concurrence											
Person Ini		Is/Date		Pers	Initials/Date						

8			1 1			
1	Site Mgmt. Concurrence	2/CHM 09-04-08		4	Other	
2	PRB Concurrence	6 CHM 09-04-08		4	Other	
3	SRB Sub. Concurrence	NA		4	Other	

Nuclear Licensing / Management Routing

	Person	Initials/Date		Person	Initials/Date
1	Preparer	CHM 09-08-08	8	NL Manager	6 9-B-08
2	LE – Review	DWD 09-08-08	9	Vice President – Hatch	NA
3	NL AA Spelling/Format		9	Vice President – Farley	JRJ9-15-4
4	NL Manager – Hatch	NA	9	Vice President – Vogtle	NA
4	NL Manager – Farley		9	Vice President-Engineering	NA
4	NL Manager – Vogtle	NA	9	Vice President – Fleet Ops	NA
5	Safety Analysis (if applicable)	NA	9	Executive Vice President	NA
6	Allegations/Orders - Legal	/ AFT 09-05-08	10	Final Review – Preparer	7 9-15-08
7	VP Notification / Draft	76 CHM 09-08-08	11	NL AA – Date & Distribution	

General Distributions:

- □ All extra copies to be issued via email in PDF/Hyperlink format if possible (Except for State, issue hard copy)
- □ Allegation letters to JT Gasser and M Caston in Confidential envelope
- All letters to Executive: JT Gasser. Corp Licensing: MJ Ajluni, BD McKinney, RD Baker, NJ Stringfellow. Site Performance Analysis: WR Bayne, WG Copeland, KA Underwood. WH Sims, Submittals Review – FNP only.
- OPC (HNP & VNP only) Laurence Bergen, Ken Rosanski and Bob Masse.
- □ All LERs Draft LERs to AF Thornhill for review; LERevents@inpo.org as a WORD doc; JW Kale FNP LERs only.
- □ Special Reports JW Kale FNP only.
- □ Security/EP Security Coordinator/EP Supervisor/site EP Coordinators as appropriate
- NRR Project Managers: All TS Changes, RAI Responses and other items that require a response from the NRC. <u>Farley</u>: Richard A. Jervey (raj@nrc.gov) <u>Hatch</u>: Robert E. Martin (rem@nrc.gov) <u>Vogtle</u>: Richard A. Jervey (raj@nrc.gov)

Other Distributions and comments: (List all distribution NOT shown in General Distributions above)