



**MCGUIRE NUCLEAR STATION  
REGULATORY CONFERENCE  
September 18, 2008**

**Service Water Strainer Backwash System**

**AGENDA**  
**OPEN REGULATORY CONFERENCE**  
**MCGUIRE NUCLEAR STATION**  
**September 18, 2008**

- I. OPENING REMARKS, INTRODUCTIONS AND MEETING INTENT  
Mr. L. Reyes, Regional Administrator
- II. NRC REGULATORY CONFERENCE POLICY  
Mr. J. Moorman, Acting Deputy Division Director, Division of Reactor Projects (DRP)
- III. STATEMENT OF THE ISSUE WITH RISK PERSPECTIVES  
Mr. S. Rose, Acting Chief, Branch 1, DRP
- IV. SUMMARY OF APPARENT VIOLATION  
Mr. S. Rose, Acting Chief, Branch 1, DRP
- V. LICENSEE RISK PERSPECTIVE PRESENTATION
- VI. LICENSEE RESPONSE TO APPARENT VIOLATION
- VII. BREAK/NRC CAUCUS  
Mr. L. Reyes, Regional Administrator
- VIII. CLOSING REMARKS  
Mr. L. Reyes, Regional Administrator

# DRAFT APPARENT VIOLATION

10 CFR 50 Appendix B Criterion XVI, Corrective Action, states that measures shall be established to assure that conditions adverse to quality, such as deficiencies, deviations, and non-conformances are promptly identified and corrected. In the case of significant conditions adverse to quality, the measures shall assure that the cause of the condition is determined and corrective action taken to preclude repetition. This requirement is implemented through the Duke Quality Assurance Program Topical Report and procedure NSD 208, Problem Identification Process.

Contrary to the above, between 2003 and August 7, 2007, the licensee failed to correct a significant condition adverse to quality related to macro-fouling of the nuclear service water (RN) strainers, in that the corrective action failed to ensure that the design and licensing basis required ability for manual strainer backwash could be maintained even during accident conditions. More specifically, the 2003 plant modification that was implemented to address the macro-fouling concern (i.e., upgrade and reclassification of the strainer backwash function to safety-related): (1) utilized non-safety-related instrument air (VI) to maintain each RN pump's strainer backwash discharge valve open, but did not provide a means to manually open (or bypass) the discharge valve to support backwash operations upon a loss of VI; and (2) did not account for the impact on timely operator response from higher strainer macro-fouling rates (whether induced by fish or other potential sources) and expected (nuisance) strainer differential pressure alarms (without fouling) at the onset of high RN flow events (i.e., safety injection and loss of VI). As such, there was a lack of reasonable assurance that the RN system would be able to perform its safety-related function upon a safety injection or loss of VI event during periods of macro-fouling.

Note: The apparent violation discussed at this Regulatory Conference is subject to further review and change prior to any resulting enforcement action.