

BFN

The evaluation of this concern at BFN identified no specific safety-related deficiencies regarding Target Rock Valves. However, it was reported that the adjustment of the reed switches for these valves had been difficult, and no procedure was found to exist at BFN for the adjustment of these reed switches. Also, it was found that there is no capability at BFN to retrieve maintenance history without specific document numbers and previous maintenance history cannot be searched for trending history. These deficiencies regarding lack of maintenance procedures and inadequate maintenance history retrieval capability were identified to BFN line management in CATD 30303-BFN-01. BFN has responded as follows:

"FSV-84-8A, 8B, 8C, 8D are Target Rock valves equipped with magnetic reed switches. The reed switches close to make up a circuit to an indicating light to show whether the valve is open or closed.

An Electrical Maintenance (EM) procedure for adjusting the reed switches does not exist. Maintenance is usually performed via a maintenance request (MR) that the unit operator initiates which simply states the position indicator lights for the valve are not working properly. Adjusting the reed switches can be a tedious trial and error process. In the past it was considered to be within the skill of the craftsman, but now it is believed that a written instruction would be advantageous. Therefore, per EM assignment No. 5952, a new procedure will be written for the adjustment of magnetic reed switches on Target Rock valves. The due date for assignment 5952 is March 30, 1987.

The problem with the equipment history is that the MR tracking program has only been in effect about four years. Prior to that, history records were incomplete or non-existent. Equipment history is being maintained now; however, previous history cannot be recreated.

Planning and Scheduling and Document Control are two separate organizations and they each maintain records in the way that meets their respective needs and objectives. When trouble reports (TRs) were used, history records were not properly maintained and trending was not done. At the present time trending is done on a systematic basis by the Preventive Maintenance Section."

The Target Rock Valves concern was not evaluated at BLN because of the plant's early stages of construction. However, upon receipt and review of this report, BLN plant management should provide preventive measures as appropriate to guard against the occurrence of this concern.

6.1.3 Element 303.04 - Calibration of Ice Condenser Load Cells

CATD 30304-WBN-01 was sent to the DNE Licensing Section notifying them of the discrepancy between the WBN FSAR and Technical Specifications on minimum ice weight. WBN has responded as follows:

"Proposed changes to the WBN FSAR have been prepared by Westinghouse and has been submitted to TVA by WAT D 7136. These changes will bring the FSAR and Tech Spec into agreement. The proposed changes will be issued to Watts Bar Site Licensing by November 28, 1986. This change should be incorporated in the WBN FSAR by June 1, 1987."

6.1.4 Element 303.05 - Reliability, Design, and Maintenance of Radiation Monitoring Equipment

WBN

CATD 30305-WBN-01 noted that DNC draft procedures for housekeeping at TVA nuclear plants under construction contain no provision for inspecting instrument protective coverings after the instrument installation process is complete. WBN DNC personnel have responded as follows:

"DNC, Instrumentation Procedure QCP-3.06-9 provides the requirements for the inspection and documentation of instrument installation. The requirement to provide covers or protective barriers for instruments as stated in instruction QCI 1.36 (since moved to QCI-1.06) is contained in inspection procedure QCP-1.36 (R10, section 7.4.20)."

Since QCP-3.06-9 documents a permanent installation, it does not need a reference to the temporary covers required by QCI-1.06 or documented by QCP-1.36. To insure covers are installed in a timely manner, IEU will revise the unit SOP to instruct RE to notify PMU when instruments that require covers are installed."

TVA EMPLOYEE CONCERNS
SPECIAL PROGRAM

REPORT NUMBER: 30300

REVISION NUMBER: 2

PAGE 28 OF 30

The CATD number 30305-WBN-02 was not used.

30305-WBN-03
CATD 30305-WBN was sent to WBN indicating that certain plant areas had been inspected on housekeeping about every three months and that all housekeeping logs were available in Document Control. These conditions were noted as apparent violations of the NAA which specifies that plant areas be inspected at least once per month and that records be maintained. WBN line Management responded as follows:

"AI 1.8 Revision 11 dated January 16, 1987:

Paragraph 4.2: The performance of housekeeping inspection may vary from section to section but shall not be less than once a month. The supervisor responsible for an area shall ensure that the inspections are done for his entire area of responsibility.

Paragraph 4.5: Records which result from the implementation of this instruction shall be maintained as quality assurance records in accordance with AI-4.1.

AI-4.1 Revision 15 requires housekeeping inspection reports be maintained until superseded and housekeeping log reports be retained 1 year.

The revision to AI-1.8 clarifies inspection frequencies and no further corrective action is required."

SQN

CATD 30305-SQN-01 was sent to SQN line management requesting status of revisions to SIs to denote Technical Specification versus non-Technical Specification required monitors. SQN has responded as follows:

"SIs associated with radiation monitors will be revised to clearly distinguish between non Tech Spec and Tech Spec monitors."

CATD 30305-SQN-02 was issued requesting technical position on upgrading PING monitors to improve accuracy and reliability. SQN has responded as follows:

"Factory representative from Eberline monitor will be represented to assist in correcting inherent problem with PING monitor control room control terminal and also provide IM with class on troubleshooting techniques and system description."

CATD number 30305-SQN-03 was not used.

CATD 30305-SQN-04 was issued to SQN management to track the closure of CAQR No. SQN 070178 Revision 0 regarding shields on Amphenol connectors.

BLN

CATD number 30305-BLN-01 was not used.

CATD 30305-BLN-02 was issued noting that DNC draft procedures for housekeeping at TVA nuclear plants under construction contain no provision for inspecting instrument protective coverings after the instrument installation process is complete. BLN DNC personnel have responded as follows:

"BLN has an effective program for providing protective covers on instrument panels and installed equipment in general. A review of BNP-QCP-1.3 Preventive maintenance, confirms that instrument panels consistently require a protective cover. The site housekeeping procedures BNP-QCP-10.27, requires the Construction Superintendent(s) to ensure that:

- (a) installed equipment is adequately protected from adjacent construction activities such as welding, cutting, scaffolding, drilling, or other construction activity to prevent permanent equipment from being damaged by construction activity.
- (b) special attention is given to the protection of electrical equipment that has wire mesh or other types of openings in the tops for ventilation purposes, and makes provisions to shield these openings while still maintaining proper ventilation.
- (c) adequate protection is provided for any mechanical equipment exposed to the elements or adjacent construction activities."

6.2 Corrective Action at Subcategory Level

A CATD to address the subcategory level finding presented in section 4 was not issued for this report. Response to element-level CATDs seemed to indicate that adequate maintenance trending and maintenance history programs were now either under development or in use at WBN, SQN, and BFN.

No subcategory level CATD's are being sent to TVA corporate management to address the findings of this subcategory report as presented in Section 5.0 of this report because the NMRG report and Nuclear Performance Plan specifically target these findings.

7.0 ATTACHMENTS

Attachment A - Subcategory Summary Table

Attachment B - Listing of Concerns by Issue

Attachment C - Checklist for Root Cause Analysis

Attachment D - Summary of Symptoms and Root Causes

Attachment E - Graph of Symptoms versus Root Cause

Attachment F - Bar Charts of Symptoms

Attachment G - Bar Charts of Root Causes

Attachment H - CATDs

Attachment I - List of Evaluators by Element/Plant

ATTACHMENT A
SUBCATEGORY SUMMARY TABLE

REFERENCE - ECPS131J-ECPS131C
 FREQUENCY - REQUEST
 ONP - ISSS - RNM

TENNESSEE VALLEY AUTHORITY
 OFFICE OF NUCLEAR POWER
 EMPLOYEE CONCERN PROGRAM SYSTEM (ECP)
 LIST OF EMPLOYEE CONCERN INFORMATION
 SUBCATEGORY: 303 INSTRUMENTATION AND RADIATION MONITORING

PAGE - 1
 RUN TIME - 12
 RUN DATE - 10

CATEGORY: OP PLANT OPER. SUPPORT

CONCERN NUMBER	CAT	SUB CAT	PLT LOC	GENERIC APPL B B S W F L Q B	QTC/NSRS INVESTIGATION REPORT	P S R	CONCERN DESCRIPTION	REFERENCE SECTION CATEGORY - OP SUBCATEGORY - 303 Section/Issue
CWL-85-001	OP	303	SQN	N N N N K-FORM		NS	WHY ARE THE AIR MONITOR FLOW CONTROL S FOR 2-RE-90-100 NOT LISTED AS EITHER TECH SPEC OR COMPLIANCE INSTRUMENT?	3.5 303.05-3
IN -85-142-006 T50092	OP	303	WBN	N N Y N REPORT	I-85-327-WBN	NS	RMST IN UNIT 1 NARROW RANGE 1-LT-63-46 & 1-LT-63-49 READING WERE 6% OFF INST ENO (NAME KNOWN) DIRECTED INSTRUMENTATION MECHANIC TO ADJUST TO ZERO. THIS WOULD MAKE READING MATCH THE CONTROL ROOM. SIMILAR ON SIS ACCUMULATORS 1-4, ELEV 716. TWO TRANSMITTERS ON EACH ACCUMULATOR. THIS PRACTICE CAUSES FALSE READINGS IN CONTROL ROOM.	3.2 303.02-2
IN -85-281-003 T50059	OP	303	WBN	N N Y N K-FORM	I-85-208-WBN	SS	THE TWO LEVEL TRANSMITTER ON EACH OF THE COLD-LEG ACCUMULATORS WILL NOT READ THE SAME LEVEL DUE TO DIFFERENCE IN ELEVATION. TRANSMITTERS HAVE BEEN CALIBRATED AS PER SCALING DATA SHEET. WHEN PUT IN SERVICE TRANSMITTERS WILL READ A 5% DIFFERENCE IN LEVEL. WHEN THE ENGINEERS WERE TOLD ABOUT THE PROBLEM THEY SAID DON'T WORRY ABOUT IT ADJUST ONE UNTIL BOTH LEVEL INDICATORS READ THE SAME. (UNIT 1)	3.2 303.02-1
IN -85-640-002 T50062	OP	303	WBN	N N N N K-FORM		NS	ICE CONDENSER LOAD CELL AND DIGITAL READOUT WERE CALIBRATED TO (PLUS/MINUS) 1 LB. BY VENDOR WITH A 95% CONFIDENCE LEVEL THAT NET ICE WEIGHT RESULTS ARE (PLUS/MINUS) 1 LB.. TVA IS UNWILLING TO SPEND THE MONEY REQUIRED TO RETURN LOAD CELL TO VENDOR FOR CALIBRATION. (NO ADDITIONAL INFORMATION IS AVAILABLE).	3.4 303.04-1

CONCERNS ARE GROUPED BY FIRST 3 DIGITS OF SUBCATEGORY NUMBER.

REFERENCE - ECPS131J-ECPS131C
FREQUENCY - REQUEST
ONP - ISSS - RHM

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPs)
LIST OF EMPLOYEE CONCERN INFORMATION

PAGE -
RUN TIME -
RUN DATE -

CATEGORY: OP PLANT OPER. SUPPORT

SUBCATEGORY: 303 INSTRUMENTATION AND RADIATION MONITORING

CONCERN NUMBER	CAT	SUB CAT	PLT LOC	GENERIC APPL B B S W F L Q B	QTC/NSRS INVESTIGATION REPORT	P S R	CONCERN DESCRIPTION
IN -85-640-003 T50062	OP	303	WBN	N N N N K-FORM		NS	ICE CONDENSER LOAD CELL TEST WEIGHT IS LABELED 1780 LB. (PLUS/MINUS) .13 (OR SOME DECIMAL). WEIGHT WAS WEIGHED AGAINST LOAD CELL AND RESULTS EQUALLED 1784 LB.. TVA CENTRAL LAB IS INCAPABLE OF CALIBRATING TO LESS THAN (PLUS/MINUS) 6 LB. TEST WEIGHT IS THEREFORE LABELLED INCORRECTLY. (NO ADDITIONAL INFORMATION IS AVAILABLE)
IN -85-802-001 T50071	OP	303	WBN	Y N Y Y REPORT	I-85-286-WBN		BOTH UNITS 1 & 2, PROBLEM EXISTS WITH TARGET ROCK VALVES INSTALLED IN BOTH SAMPLING SYSTEM AND MAIN STEAM SYSTEM. TARGET ROCK VALVES IMPROPERLY ANNUNCIATE PART OF THE TIME AND READ SWITCHES ON VALVES REQUIRE CONSTANT ADJUSTMENT. VALVES IN SAMPLING SYSTEM LOCATED IN 3/8" STAINLESS STEEL LINES IN ANNULUS AND PRIMARY CONTAINMENT AREAS. VALVES IN MAIN STEAM SYSTEM LOCATED ON EITHER 2" OR 3" STAINLESS STEEL LINES IN SOUTH VALVE ROOM. C/I DID NOT SPECIFY LINE NUMBERS OR VALVE SERIAL OR MARK NUMBERS
IN -85-841-001 T50084	OP	303	WBN	Y N Y Y REPORT		NS	"OLD" PLANT INSTRUMENTATION (PROCURED 10-12 YEARS AGO) IS OFTEN NO LONGER MANUFACTURED/SPARE PARTS ARE DIFFICULT OR NOT POSSIBLE TO OBTAIN. PURCHASE REQUISITIONS FOR UNOBTAINABLE PARTS ARE CANCELLED, YET COGNIZANT MANAGEMENT (DEPARTMENT KNOWN) HAVE INSTITUTED NO ALTERNATIVES MEASURES TO OBTAIN SUBSTITUTIONS OF PARTS/REPLACEMENT ITEMS. THIS HAS THE POTENTIAL TO ADVERSELY IMPACT PLANT OPERATIONS. CI POSTULATED THIS CONCERN TO BOTH UNITS 1 & 2. MANAGEMENT (NAME KNOWN) IS AWA

REFERENCE SECTION
CATEGORY - 01
SUBCATEGORY - 303
Section/Issue
3.4
303.04-2

3.3
303.03-1

3.1
303.01-1

CONCERNS ARE GROUPED BY FIRST 3 DIGITS OF SUBCATEGORY NUMBER.

REFERENCE - ECPS131J-ECPS131C
 FREQUENCY - REQUEST
 ONP - ISSS - RHM

TENNESSEE VALLEY AUTHORITY
 OFFICE OF NUCLEAR POWER
 EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
 LIST OF EMPLOYEE CONCERN INFORMATION

PAGE - 2
 RUN TIME - 1
 RUN DATE - 1

CATEGORY: OP PLANT OPER. SUPPORT

SUBCATEGORY: 303 INSTRUMENTATION AND RADIATION MONITORING

CONCERN NUMBER	CAT	SUB CAT	PLT LOC	GENERIC APPL B B S W F L Q B	QTC/NSRS INVESTIGATION REPORT	P S R	CONCERN DESCRIPTION	REFERENCE SECTION CATEGORY - OF SUBCATEGORY - 30 Section/Issue
IN -85-973-001 T50156	OP	303	WBN	N N N Y K-FORM		NS	STEAM GENERATOR LEVEL INDICATORS DO NOT ACCURATELY SHOW THE FILL LEVEL OF THE STEAM GENERATORS. DURING A FLUSH THAT INCLUDED UNIT 1 STEAM GENERATORS, THE SHIFT ENGINEER STATED THAT THE STEAM GENERATOR (NUMBER NOT KNOWN) WAS FULL OF WATER. INSTRUMENTS IN ACCUMULATOR ROOM 04 (716' ELEV.) SHOULD THIS NOT BE THE CASE, AND THE LOCAL INSTRUMENT'S ACCURACY WAS CONFIRMED VIA NITROGEN FLOW. IF THE SHIFT ENGINEER'S INSTRUMENTS HAD BEEN OFF THIS MUCH (ESTABLISHED 40' OF WATER ERROR) DURING OPERATIONS, T	3.3 303.03-3
IN -86-079-001 T50117	OP	303	WBN	K-FORM	IN-86-079-001		"OUTDATED" INSTRUMENTATION INSTALLED IN BOTH UNITS 1 & 2 CREATES UNNECESSARILY HIGH EXPENDITURES AND DELAYS DUE TO PROBLEMS WITH OBTAINING SPARE PARTS. NEWER MODEL INSTRUMENTATION WOULD BE LESS EXPENSIVE TO MAINTAIN, AND WOULD PERFORM THE REQUIRED FUNCTIONS WITH A GREATER DEGREE OF ACCURACY AND RELIABILITY. DETAILS KNOWN TO QTC, WITHHELD DUE TO CONFIDENTIALITY. NUCLEAR POWER CONCERN. VARIOUS SYSTEMS, INCLUDING PRESSURE TRANSMITTERS/FIELD MONITORING. TIME FRAME - CURRENT. CI HAS NO FURTHER I	3.1 303.01-1
IN -86-079-002 T50117	OP	303	WBN	N N Y Y K-FORM		NS	QUESTIONABLE ADEQUACY OF SAFETY RELATED EQUIPMENT ACCURACY, AND QUESTIONABLE CALIBRATION PROCEDURES FOR THIS EQUIPMENT. DETAILS KNOWN TO QTC, WITHHELD DUE TO CONFIDENTIALITY. NUCLEAR POWER CONCERN, UNITS 1 & 2, SYSTEM WITHHELD; TIME FRAME - CURRENT. CI HAS NO FURTHER INFORMATION NO FOLLOWUP REQUIRED.	3.3 303.03-2

CONCERNS ARE GROUPED BY FIRST 3 DIGITS OF SUBCATEGORY NUMBER.

REFERENCE - ECPS131J-ECPS131C
 FREQUENCY - REQUEST
 ONP - ISSS - RHM

TENNESSEE VALLEY AUTHORITY
 OFFICE OF NUCLEAR POWER
 EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
 LIST OF EMPLOYEE CONCERN INFORMATION

PAGE - 4
 RUN TIME - 12
 RUN DATE - 10

CATEGORY: OP PLANT OPER. SUPPORT

SUBCATEGORY: 303 INSTRUMENTATION AND RADIATION MONITORING

CONCERN NUMBER	CAT	SUB CAT	PLT LOC	GENERIC APPL B B S W F L Q B	QTC/NSRS INVESTIGATION REPORT	P S R	CONCERN DESCRIPTION	REFERENCE SECTION CATEGORY - OP SUBCATEGORY - 303 Section/Issue 3.5 303.05-1
SQP-86-003-N04	OP	303	SQN	N N N N K-FORM		NS	NRC IDENTIFIED THE FOLLOWING CONCERN WHICH PERTAINS TO SQP-86-003-001 FROM REVIEW OF QTC FILE. "CI STATES MORE CABLES (IN ADDITION TO THE RADIATION MONITOR CABLE CITED IN SQP-86-003-001) MAY HAVE A SIMILAR PROBLEM IN PENETRATION 023. INTEGRITY OF ALL CONNECTORS AND ASSOCIATED HEAT SHRINK IS IN QUESTION. THIS CONCERN REFERS TO CABLES IN ADDITION TO THE RADIATION MONITOR CABLE CITED IN SQP-86-003-001.	3.5 303.05-1
SQP-86-003-N05	OP	303	SQN	N N N N K-FORM		NS	NRC IDENTIFIED THE FOLLOWING CONCERN FROM REVIEW OF QTC FILE. "SQP-86-003-001 IS POTENTIALLY REPORTABLE."	3.5 303.05-1
SQP-86-003-001 T50246	OP	303	SQN	N N N N K-FORM	I-86-205-SQN	SS	THE RADIATION MONITOR CABLE IS NOT INSTALLED PROPERLY. PENETRATION 23, LOWER CONTAINMENT, UNIT 02, MODIFICATIONS. (NAMES/DETAILS KNOWN TO QTC AND WITHHELD TO MAINTAIN CONFIDENTIALITY). NO FURTHER INFORMATION MAY BE RELEASED. NUCLEAR POWER CONCERN. CI HAS NO FURTHER INFORMATION.	3.5 303.05-1
HI -85-039-002 T50210	OP	303	WBN	N N N Y K-FORM		NS	RADIATION MONITORS AT WATTS BAR HAVE NOT BEEN MAINTAINED NOR WERE THEY OPERABLE, UNTIL MIDDLE OF 1984. NUCLEAR POWER CONCERN. CI HAS NO FURTHER INFORMATION.	3.5 303.05-5
XX -85-044-001 T50153	OP	303	BFN	N N Y N REPORT	I-85-557-BFN	NS	AT BROWN'S FERRY THERE WAS AN ACCIDENT OF RADIATION RELEASE ON THE REACTOR REFUEL FLOOR ON 6/26/85. CONCERN IS THAT CONTINUOUS AIR MONITORS (CAMS) DID NOT FUNCTION PROPERLY AND DID NOT REGISTER RADIATION LEVELS ACCURATELY. CAM'S ARE OBSOLETE AND SHOULD BE REPLACED BY MODERN INSTRUMENTS SUCH AS PARTICULATE IODINE NOBLE GASES (PING'S). CI HAS NO FURTHER INFORMATION. NO FOLLOW UP REQUIRED.	3.5 303.05-4

CONCERNS ARE GROUPED BY FIRST 3 DIGITS OF SUBCATEGORY NUMBER.

REFERENCE - ECPS131J-ECPS131C
FREQUENCY - REQUEST
ONP - ISSS - RNM

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
LIST OF EMPLOYEE CONCERN INFORMATION

PAGE - 5
RUN TIME - 12
RUN DATE - 10

CATEGORY: OP PLANT OPER. SUPPORT

SUBCATEGORY: 303 INSTRUMENTATION AND RADIATION MONITORING

CONCERN NUMBER	CAT	SUB CAT	PLT LOC	GENERIC APPL B B S W F L Q B	QTC/NSRS INVESTIGATION REPORT	P S R	CONCERN DESCRIPTION
XX -85-051-001 150153	OP	303	SQN	N N Y N K-FORM	I-85-613-SQN	SS	SEQUOYAH: THE RADIATION MONITOR (1-R M-90-104) HAS NOT BEEN MAINTAINED AN D IS NOT ALWAYS OPERABLE. ANY FURTH ER INFORMATION WOULD COMPROMISE CONF IDENTIALITY. NUC. POWER DEPT. CONCE RN. FOLLOW UP NOT REQUIRED.

REFERENCE SECTION
CATEGORY - OP
SUBCATEGORY - 303
Section/Issue
J. 7
303.05-2

16 CONCERNS FOR CATEGORY OP SUBCATEGORY 303

CONCERNS ARE GROUPED BY FIRST 3 DIGITS OF SUBCATEGORY NUMBER.

ATTACHMENT B

INSTRUMENTATION AND RADIATION MONITORING

List of Concerns by Element/Issue

The Instrumentation and Radiation Monitoring Subcategory (30300) is comprised of 16 concerns combined into five elements that address a total of 13 issues.

Element 303.01 - Difficulty in Obtaining Obsolete Equipment

Issue 303.01-1 Difficulty in Obtaining Obsolete Equipment

IN-85-841-001

IN-86-C79-001

Element 303.02 - Location of Cold Leg Accumulator (CLA) and Refueling Water Storage Tank (RWST) Level Transmitters

Issue 303.02-1 Inaccuracies in Safety Injection System (SIS) CLA Level Instrumentation at WBN

IN-85-281-003

Issue 303.02-2 Inaccuracies in Narrow Range Level Instruments for WBN Unit 1 RWST

IN-85-142-006

Element 303.03 - Accuracy of Safety-Related Instruments

Issue 303.03-1 Target Rock Valve Reed Switches Inaccurate

IN-85-802-001

Issue 303.03-2 Radiation Monitors Inaccurate

IN-86-079-002

Issue 303.03-3 Local and Remote Level Indicators Differ

IN-85-973-001

Element 303.04 - Calibration of Ice Condenser Load Cells

Issue 303.04-1 TVA Unable and Unwilling to Calibrate Ice Condenser Load Cell Properly

IN-85-640-002

Issue 303.04-2 Ice Condenser Load Cell Test Weight Incorrectly Labeled

IN-85-640-003

ATTACHMENT B

INSTRUMENTATION AND RADIATION MONITORING

List of Concerns by Element/Issue
(CON'T)

Element 303.G5 - Reliability, Design, and Maintenance of Radiation Monitoring Equipment

Issue 303.05-1 Improper Installation of Radiation Monitor Cables

SQP-86-003-001
SQP-86-003-N04
SQP-86-003-N05

Issue 303.05-2 Maintenance and Operability of Radiation Monitor

XX-85-051-001

Issue 303.05-3 Air Monitor Flow Controls Not Listed as Technical
Specification or Compliance Instruments

|R2
|

CWL-85-001

Issue 303.05-4 Improper Operation of Continuous Air Monitors (CAMs)

XX-85-044-001

Issue 303.05-5 Radiation Monitors Not Operable and Not Maintained

WI-85-039-002

Attachment C
Checklist for Root Cause Analysis

1. Procedure lacks specifics to perform task.
2. Personnel lack sufficient training in the applicability/use of procedure.
3. Lack of understanding regulatory requirements or commitments.
4. Lack of adequate system, process, or administrative controls to ensure commitments are reflected in procedures or processes.
5. Inadequate communication within functional group.
6. Inadequate communication between functional groups.
7. Management Assumed Risk.
8. Procedures incomplete or failed to incorporate all technical requirements.
9. Error in judgment by qualified individual.
10. Unqualified individual performing the task.
11. Insufficient time to perform task.
12. Inadequate prerequisites defined to ensure satisfactory completion of task.
13. Personnel performed task knowingly in violation of procedure/process.
14. Personnel error in following procedures.
15. Failed to identify root cause of previous deficiencies.
16. Failed to take appropriate action to preclude reoccurrence.
17. Inadequate process to detect adverse trends.
18. Inadequate acceptance criteria defined to ensure satisfactory task completion.
19. Management attentiveness to trends.
20. Lack of accessibility to documentation.
21. Inadequate controls for review of results to ensure compliance with commitments.
22. Timeliness of changes to commitments or changes to licensing/regulatory requirements.
23. Isolated incident.
24. Random error.
25. Other - i.e., equipment related failure.

ATTACHMENT D

SUMMARY OF SYMPTOMS AND ROOT CAUSES

Element 303.01 was investigated specifically for WBN and generically at SQN and BFN. No specific deficiencies were found in any of these investigations, and no symptoms for root cause analysis were tested.

For Element 303.02, the potential for negative findings at the subcategory level was exhibited by the following symptoms: (a) recurring instrument failure, and (b) lack of QA controls for vendor performance. The first symptom appeared in the evaluation for both WBN and SQN. The second symptom appeared only in the evaluation for WBN. As these symptoms were tested for root cause, the appropriate root causes and applicable plant sites were judged to be as follows:

- a. Inadequate communication between functional groups (ONP, QA at WBN)
- b. Failure to identify root cause of previous deficiencies (WBN, SQN)
- c. Failure to take appropriate action to preclude recurrence (WBN, SQN)
- d. Inadequate process to detect adverse trends (WBN, SQN)
- e. Management attentiveness to trends (WBN, SQN)
- f. Inadequate acceptance criteria defined to ensure satisfactory task completion (WBN)
- g. Inadequate controls for review of results to ensure compliance with commitments (WBN)

For Element 303.03 the potential for negative findings at the subcategory level was exhibited by the following symptoms: (a) recurring instrument failure, (b) lack of controls to govern maintenance activities (Target Rock Valves), (c) configuration control inadequate (Target Rock Valves), and (d) maintenance history retrieval inadequate. The first symptom appeared only in the evaluation for WBN. The second symptom appeared in the generic evaluation for both SQN and BFN. The third and fourth symptoms appeared only in the generic evaluation for BFN. As these symptoms were tested for root cause, the appropriate root causes and applicable plant sites were judged to be as follows:

- a. Lack of adequate system, process, or administrative controls to ensure commitments are reflected in procedures and processes (BFN)
- b. Inadequate communication between functional groups (plant operators, EMS at WBN)
- c. Procedures incomplete or failed to incorporate all technical requirements (SQN)
- d. Failure to identify root cause of previous deficiencies (WBN)

ATTACHMENT D

SUMMARY OF SYMPTOMS AND ROOT CAUSES
(CON'T)

- e. Failure to take appropriate action to preclude recurrence (WBN)
- f. Inadequate process to detect adverse trends (WBN, BFN)
- g. Lack of accessibility to documentation (BFN)

For Element 303.04 the symptom identified was inadequate configuration control of the FSAR with respect to Technical Specifications. The testing of this symptom pointed to the following root causes for WBN:

- a. Lack of understanding regulatory requirements or commitments
- b. Lack of adequate system, process, or administrative controls to ensure commitments are reflected in procedures or processes
- c. Inadequate controls for review of results to ensure compliance with commitments

For Element 303.05 inadequate housekeeping affecting instruments was identified as the symptom. The testing of this symptom revealed the following root causes for WBN:

- a. Lack of understanding regulatory requirements or commitments
- b. Lack of adequate system, process, or administrative controls to ensure commitments are reflected in procedures or processes

The analysis of the symptoms and root causes for these elements is depicted graphically in Attachments D, E, and F. Attachment D is a plot of each element's symptoms versus the root causes pointed out by the symptom. Root cause numbers on the horizontal axis correspond to the 25 items on the "Checklist for Root Cause Analysis" found in Attachment C.

Attachment E contains bar graphs showing the number of times each of the symptoms identified for the subcategory occurs for the various plants. Symptom numbers on the horizontal axis in this attachment correspond to the symptoms as listed in Attachment D. Attachment F contains bar graphs showing the number of times each root cause appears in the subcategory for the various plants.

Several observations can be made in studying these attachments. First, the "recurring instrument failure" symptom is the only symptom appearing in more than one element. Second, from Attachment E it can be seen that the only two symptoms occurring more than once among the three plants evaluated are: (a) "recurring instrument failure" (three occurrences), and (b) "lack of controls to govern maintenance activities (Target Rock Valves)" (two occurrences). Third, there are two root causes that appear more frequently than the others, as shown in Attachment F. These two root causes and their applicable plant

ATTACHMENT D





SUMMARY OF SYMPTOMS AND ROOT CAUSES
(CON'T)

sites are: (a) lack of adequate system, process, or administrative controls to ensure commitments are reflected in procedures or processes (WBN, BFN) and (b) inadequate process to detect adverse trends (WBN, SQN, BFN). The latter root cause was the only one which appeared at least once at each of the three plants evaluated for this subcategory. Also, six other root causes appear more than once among the three plants evaluated. These root causes and their applicable plant sites are as follows:

- a. Lack of understanding regulatory requirements or commitments (WBN)
- b. Inadequate communication between functional groups (WBN)
- c. Failure to identify root cause of previous deficiencies (WBN, SQN)
- d. Failure to take appropriate action to preclude recurrence (WBN, SQN)
- e. Management attentiveness to trends (WBN, SQN)
- f. Inadequate controls for review of results to ensure compliance with commitments (WBN)





OCCURRENCES VS SYMPTOMS

SUBCAT 303



OCCURRENCES VS ROOT CAUSES

SUBCAT 303



ATTACHMENT H

Corrective Action Tracking Documents (CATDs)

<u>CATD Number</u>	<u>Corrective Action Plan Approved</u>
30302-SQN-01	Yes
30302-SQN-02	Yes
30302-WBN-01	Tracking only
30303-SQN-01	Yes
30303-SQN-02	Yes
30303-WBN-01	Yes
30303-BFN-01	Yes
30304-WBN-01	Yes
30305-SQN-01	Yes
30305-SQN-02	Yes
30305-SQN-03	Number Not Used
30305-SQN-04	Tracking Only
30305-WBN-01	Yes
30305-WBN-02	Number Not Used
30305-WBN-03	Yes
30305-BLN-01	Number Not Used
30305-BLN-02	Yes

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No: OP-30302-SQM

1. Immediate Corrective Action Required: ☒ Yes ☐ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. OP 30302-001-SQM
4. INITIATION DATE 9/26/86
5. RESPONSIBLE ORGANIZATION: SQM
6. PROBLEM DESCRIPTION: ☒ QR ☐ NQR SI-3 records only one narrow range level channel for verifying compliance with tech spec RWST volume requirements and the specific channel used is not designated during performance of the SI. Because of this condition, channel calibration out of tolerance reports cannot be evaluated for impact on SI results nor can an audit be performed to verify past compliance. Additionally, NRS reviewed during the evaluation did not specify the work instructions used for loop calibration. These deficiencies are considered to represent a PRO. ☐ ATTACHMENTS
7. PREPARED BY: NAME G. D. Gaggner DATE: 9/26/86
8. CONCURRENCE: CEG-M W.R. Saggner DATE: 9/29/86
9. APPROVAL: ECTG PROGRAM MGR. Robert J. Fu DATE: 10/26

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN: PROPOSED CORRECTIVE ACTION
IS PROVIDED BY MEMORANDUM (REF 6401780)
DATED OCT. 17, 1986
THIS ITEM COMPLETED
DATE: 10-26-86
11. PROPOSED BY: DIRECTOR/MGR: Robert J. Fu ☒ ATTACHMENTS DATE: 10-26-86
12. CONCURRENCE: CEG-M: W.R. Saggner DATE: 11-5-86
SRP: _____ DATE: _____

ECTG PROGRAM MGR: _____ DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION


Applicable ECSP Report No: 303.02 SQN Revision 1

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. 30302 SQN 02
4. INITIATION DATE 10/14/86
5. RESPONSIBLE ORGANIZATION: Operations SQN
6. PROBLEM DESCRIPTION: ☒ QR ☐ NQR Problems exist with the function and calibration of level transmitters for the refueling water storage tanks.
7. PREPARED BY: NAME T. W. White DATE: 10/14/86
8. CONCURRENCE: CEG-H W. R. Suggins DATE: 10/14/86
9. APPROVAL: ECTG PROGRAM MGR. DATE: _____

☐ ATTACHMENTS

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN: We accept your proposed corrective action as presented with the exception of the problem with SI-3. The SI-3 problem remains open and is being tracked via CATD 30302 SQN 01.



11. PROPOSED BY: DIRECTOR/MGR: S53 860910 927 DATE: 10/14/86
12. CONCURRENCE: CEG-H: W. R. Suggins DATE: 10/14/86
SRP: _____ DATE: _____

ECTG PROGRAM MGR: _____ DATE: _____

☐ ATTACHMENTS

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

ECTG Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECTG Report No.: OP 303.02 Rev 1

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. 30302-WBN-01
4. INITIATION DATE 04/02/87
5. RESPONSIBLE ORGANIZATION: WBN Plant Manager, WBNP
6. PROBLEM DESCRIPTION: ☒ QR ☐ NQR DCR 633 for replacement of the cold leg accumulator level transmitters and DCR 678 for replacement of the refueling water storage tank level transmitters have not been implemented. Completion of these modifications is a requirement before fuel load (unit 1).
7. PREPARED BY: NAME William L. Dwyer ☐ ATTACHMENTS DATE: 04/02/87
8. CONCURRENCE: CEG-H W.H. Thomas F. Hurth DATE: 7/2/87
9. APPROVAL: ECTG PROGRAM MGR. John D. Rona DATE: 4/2/87
for

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN: Tracking only of DCR 633 AND DCR 678
11. PROPOSED BY: DIRECTOR/MGR: Tracking only ☐ ATTACHMENTS DATE: _____
12. CONCURRENCE: CEG-H: _____ DATE: _____
ECTG PROGRAM MANAGER _____ DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No: 303.03 SQM Revision 1

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. 30303-SQM-01
4. INITIATION DATE 11-08-86
5. RESPONSIBLE ORGANIZATION: Electrical Maintenance
6. PROBLEM DESCRIPTION: ☐ QR ☒ NQR
Recommendation was made to provide written instructions on
setting valve position indicator switches on Target Rock valves.

7. PREPARED BY: NAME T. W. White
8. CONCURRENCE: CEG-H W. R. [Signature]
9. APPROVAL: ECTG PROGRAM MGR. [Signature]

ATTACHMENTS

DATE: 11-08-86
DATE: 10-14-86
DATE: 9/7/87

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN: Commitment has been made to
prepare written instructions for setting valve position
indication switches for Target Rock valves to be accomplished
by 02-01-87.

CATD was prepared and approved. This CATD
was used after the [Signature] for completeness.

11. PROPOSED BY: DIRECTOR/MGR: S03 860922 804
12. CONCURRENCE: CEG-H: [Signature]
SRP: _____

ATTACHMENTS

DATE: 09/25/86
DATE: 10/14/86
DATE: _____
DATE: _____
DATE: _____
DATE: _____

ECTG PROGRAM MGR: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

2048T

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No: 303.03 SQN Revision 2

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. 303.03-SQN-02
4. INITIATION DATE 10-08-86
5. RESPONSIBLE ORGANIZATION: Operations 5-4-17
6. PROBLEM DESCRIPTION: ☒ QR ☐ NQR Questionable adequacy of calibration procedures for radiation monitors.

☒ ATTACHMENTS

7. PREPARED BY: NAME I. W. White DATE: 10-08-86
8. CONCURRENCE: CEG-H W.R. Pegg DATE: 10-14-86
9. APPROVAL: ECTG PROGRAM MGR. RRH DATE: 4/7/87

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN: Radiation monitor calibration procedures are being reviewed using the SI checklist for guidance. This corrective action is to be completed prior to plant startup and will be tracked at SQN by P2 activity 200011950.
CAP was received from report review. This CATD was issued after the fact for completeness.
CATD upgraded to QR to reflect Program Requirement 5-4-17 No SNOR will be requested since CAP indicates Release and it is being tracked as P2
WEL 5-4-87

☐ ATTACHMENTS

11. PROPOSED BY: DIRECTOR/MGR: S03 860922 804 DATE: 09/25/86
12. CONCURRENCE: CEG-H: W.R. Pegg DATE: 10/14/86
SRP: _____ DATE: _____

ECTG PROGRAM MGR: _____ DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No: OP 303.03

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. 30303-WBN-01
4. INITIATION DATE 10-28-86
5. RESPONSIBLE ORGANIZATION: WBN Plant Manager, Electrical Maintenance
6. PROBLEM DESCRIPTION: ☐ OR ☒ NQR The WBN response to NSRS report I-85-286-WBN stated WBN will review HI-57.30 to include vendor recommendations for Target Rock valve rod switch adjustment and that a maintenance trending program was being developed for WBN. Please provide the status of these corrective actions.

ATTACHMENTS

7. PREPARED BY: NAME G. D. Gardner DATE: 10-28-86
8. CONCURRENCE: CEG-H CEH 10-28-86 DATE: 11-10-86
9. APPROVAL: ECTG PROGRAM MGR. W. H. Hunt, Jr. DATE: 11-10-86

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN:

SEE ATTACHED

Enclosure TOG 861216 007

ATTACHMENTS

11. PROPOSED BY: DIRECTOR/MGR: W. H. Hunt, Jr. DATE: 11/10/86
12. CONCURRENCE: CEG-H: CEH 11-10-86 DATE: 11/10/86
- SRP: _____ DATE: _____
- ECTG PROGRAM MGR: _____ DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No: OP 303.03

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. OP 30303-001-BFN
4. INITIATION DATE 9/23/86
5. RESPONSIBLE ORGANIZATION: BFN Electrical Maint., Document Control
6. PROBLEM DESCRIPTION: ☐ QR ☒ NQR According to cognizant maintenance personnel at BFN and based on the results of evaluations at other plants, Target Rock valve reed switch adjustment is sensitive and difficult. No procedures exist at BFN for their adjustment. There is an apparent problem with the equipment history archives at BFN. Planning and Scheduling maintains a searchable data base because Document Control could not retrieve maintenance request data without specific document numbers. The previous maint. history cannot be searched for IE history trending. ☐ ATTACHMENTS
7. PREPARED BY: NAME G. D. Gardner DATE: 9/23/86
8. CONCURRENCE: CEG-B W. R. Jorgensen DATE: 9/25/86
9. APPROVAL: ECTG PROGRAM MGR. _____ DATE: _____

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN: _____

See Memorandum R33 861128 827

1374
11/4/86

- ☐ ATTACHMENTS
11. PROPOSED BY: DIRECTOR/MGR: R33 861128 827 DATE: 11-22-86
 12. CONCURRENCE: CEG-B: Thomas J. Huth for W. R. Jorgensen DATE: 12-08-86
SRP: _____ DATE: _____

ECTG PROGRAM MGR: _____ DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No: OP 303.04

1. Immediate Corrective Action Required: ☒ Yes ☐ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. OP 30304-001-WBN
4. INITIATION DATE 9-30-86
5. RESPONSIBLE ORGANIZATION: DNE Nuclear Licensing Section
6. PROBLEM DESCRIPTION: ☒ QR ☐ NQR Watts Bar Final Safety Analysis Report section 6.7 does not agree with the ice weight specified in the WBN Technical Specifications 3/4.6.5. This was previously identified to DNE by Immediate Action Notice 6-OP303 for which a response has not been received. This supersedes the previous notice.
7. PREPARED BY: NAME G. D. Gardner ☐ ATTACHMENTS
8. CONCURRENCE: CEG-H W. E. [Signature] DATE: 9-30-86
9. APPROVAL: ECTG PROGRAM MGR. [Signature] DATE: 10-1-86

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN:
Proposed changes to the WBN FSAR have been prepared by Westinghouse and has been submitted to TVA by WAT D 7136 (B45860908601). These changes will bring the FSAR and Tech spec into agreement. The proposed changes will be issued to Watts Bar Site Licensing by November 28, 1986. This change should be incorporated in the WBN FSAR by June 1, 1986.7.
JEN [Signature]
Per [Signature]
C.E. [Signature]
11. PROPOSED BY: DIRECTOR/MGR: B 20 86 1119 001 ☐ ATTACHMENTS
12. CONCURRENCE: CEG-H: Thomas T. [Signature] DATE: 11/19/86
SRP: _____ DATE: 11/25/86

ECTG PROGRAM MGR: _____ DATE: _____

DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE _____

TITLE _____

DATE _____

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No: 30305-SQM Revision 2

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. 30305 SQM 01
4. INITIATION DATE October 9, 1986
5. RESPONSIBLE ORGANIZATION: Operations
6. PROBLEM DESCRIPTION: ☐ QR ☒ NQR
Provide status of revision(s) to SI's to denote technical
specification vs nontechnical specification required monitors.

7. PREPARED BY: NAME T. W. White ☐ ATTACHMENTS
8. CONCURRENCE: CEG-H W. P. Long DATE: 10-09-86
9. APPROVAL: ECTG PROGRAM MGR. M. J. Murphy DATE: 10-13-86
DATE: 10-17-86

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN: SEE THE CAP TRANSMITTED
BY MEMORANDUM SPS 8500/503 86/124 SC/1

~~THIS ITEM
DATE 7-8-87~~

11. PROPOSED BY: DIRECTOR/MGR: H. B. Park ☐ ATTACHMENTS
12. CONCURRENCE: CEG-H: Thomas J. Huth DATE: 11-25-86
SRP: for VRL DATE: 12/4/86
DATE: _____
DATE: _____
DATE: _____
DATE: _____
ECTG PROGRAM MGR: _____ DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No: 303.05 SQW Revision 2

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. 30305 SQW 02
4. INITIATION DATE 10-09-86
5. RESPONSIBLE ORGANIZATION: Operations
6. PROBLEM DESCRIPTION: Provide positive/determination on upgrading PING's to improve accuracy and reliability.

7. PREPARED BY: NAME I. W. White ☐ ATTACHMENTS
8. CONCURRENCE: CEG-R W.R. 3 DATE: 10-09-86
9. APPROVAL: ECTG PROGRAM MGR. 11 MURKIN DATE: 10-14-86
DATE: 10-17-86

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN: SEE TMO CAP TRANSMITTED BY MEMORANDUM 553 20-900/503 8/124 801
7-8-8

11. PROPOSED BY: DIRECTOR/MGR: B.B. Bunkin 16 ☐ ATTACHMENTS
12. CONCURRENCE: CEG-R: Thomas J. Heath Jr. 64 DATE: 11-25-86
GRP: ... DATE: 12/3/86
DATE: ...
DATE: ...
DATE: ...
DATE: ...
DATE: ...
ECTG PROGRAM MGR: ... DATE: ...

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

2051T

_____ SIGNATURE	_____ TITLE	_____ DATE
--------------------	----------------	---------------

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No.: 303.05-SQN-04

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. 30305-SQN-04
4. INITIATION DATE 3/11/87
5. RESPONSIBLE ORGANIZATION: SQN Modifications
6. PROBLEM DESCRIPTION: ☒ QR ☐ NQR During preparations for installation of amphenol connectors on penetrations involving shielded cable, problems with vendor instructions were noted. CAQR No. SQP 870178 Revision 0 was issued. This CATD is for the purpose of tracking the CAQR.
7. PREPARED BY: NAME B. Heers, Jr. for 3/11/87 DATE: 3/11/87
8. CONCURRENCE: CEG-H Thomas F. Huth for 3/12/87 DATE: 3/12/87
9. APPROVAL: ECTG PROGRAM MGR. for 4/7/87 DATE: 4/7/87

☐ ATTACHMENTS

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN:

THIS ITEM COMPLETED
DATE: 7-8-87

☐ ATTACHMENTS

11. PROPOSED BY: DIRECTOR/MGR: TRACKING ONLY DATE: 3/12/87
12. CONCURRENCE: CEG-H: Thomas F. Huth for DATE: 3/12/87
- SRP: _____ DATE: _____
- _____ DATE: _____
- _____ DATE: _____
- ECTG PROGRAM MGR: _____ DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION


Applicable ECSP Report No.: 30305-WBN

1. Immediate Corrective Action Required: ☐ Yes ☒ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. 30305-WBN-01 (Duplicate) 4. INITIATION DATE 9-10-86
5. RESPONSIBLE ORGANIZATION: WBN DMC
6. PROBLEM DESCRIPTION: ☐ ☒ During the evaluation of employee concern WI-85-034-002 & DMC draft procedure (QCP 3.06-9) was reviewed which does not provide nor reference the protective coverings for instruments required by OCI-1.36 to mitigate damage to equipment during construction.

7. PREPARED BY: NAME G. D. Gardner ☐ ATTACHMENTS DATE: 9/10/86
8. CONCURRENCE: CEG-H W. R. Lagergren DATE: 9/10/86
9. APPROVAL: ECTG PROGRAM MGR. [Signature] DATE: 3/20/87

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN:



11. PROPOSED BY: DIRECTOR/HGR: [Signature] ☐ ATTACHMENTS DATE: 2/26/87
12. CONCURRENCE: CEG-H: [Signature] DATE: 3-3-87

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report No: OP 303.05

1. Immediate Corrective Action Required: ☒ Yes ☐ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. OP 303.05-003-WBN
4. INITIATION DATE 9-30-86
5. RESPONSIBLE ORGANIZATION: WBN Electrical Maintenance
6. PROBLEM DESCRIPTION: C QR ☒ NQR The NOAM specifies that the plant superintendent shall divide the plant into sections and assign these sections to individuals responsible for performing inspections. The frequency of the checks are required to be not less than once a month. AI-1.8 specifies that housekeeping inspections be not less than twice a month and individual areas, as assigned, shall be inspected quarterly. These requirements are not very clear on what is intended. A review of completed Attachment 2 for AI-1.8 was conducted on the Instrument Maintenance and Electrical Maintenance Sections for 1985 and 1986. The records obtained from Document Control indicate that inspections were conducted once to twice a month, but that a specific area was only being inspected about every three months. Additionally, not all housekeeping logs were found in Document Control. This is an apparent violation of NOAM requirements which specify that plant areas be inspected at least once per month and that QA records be maintained. The WBN Site Director was informed of this by Immediate Action Notice 14 OP303 and has not yet responded. This CATD supersedes the previous notice.

7. PREPARED BY: NAME G. D. Gardner DATE: 9-30-86
8. CONCURRENCE: CEG-H 10-6-86 DATE: 10-6-86
9. APPROVAL: ECTG PROGRAM MGR: 10-6-86 DATE: 10-6-86

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN: SEE ATTACHED JAF
11. PROPOSED BY: DIRECTOR/MGR: William E. Galt DATE: 5/30/87
12. CONCURRENCE: CEG-H: _____ DATE: _____
SRP: _____ DATE: _____

ECTG PROGRAM MGR: _____ DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

ECSP Corrective
Action Tracking Document
(CATD)

INITIATION

Applicable ECSP Report NO:

1. Immediate Corrective Action Required: ☒ Yes ☐ No
2. Stop Work Recommended: ☐ Yes ☒ No
3. CATD No. OP-30305-002 4. INITIATION DATE 9-10-86
5. RESPONSIBLE ORGANIZATION: ELN DMC
6. PROBLEM DESCRIPTION: ☐ Q2 ☒ NQR

During the evaluation of employee concern WI-85-039-002 at WAW a draft procedure (OCP 306-9) was reviewed regarding the requirements for installation and testing. This draft procedure provides no mechanism for providing or referencing the protective covering required by the Housekeeping OCE-136 to mitigate damage during construction. The situation does exist at Safate.

7. PREPARED BY: NAME G. E. Gortner ☐ ATTACHMENTS
8. CONCURRENCE: CEG-H W. R. Sanyal DATE: 9-10-86
9. APPROVAL: ECTG PROGRAM MGR. [Signature] DATE: 9-10-86

CORRECTIVE ACTION

10. PROPOSED CORRECTIVE ACTION PLAN

WORK COMPLETED
6-14-88

11. PROPOSED BY: DIRECTOR/MGR. [Signature] ☐ ATTACHMENTS
12. CONCURRENCE: CEG-H: W. R. Sanyal DATE: 3/31/87
SRP: [Signature] DATE: 4-6-87
DATE: _____
DATE: _____
DATE: _____
DATE: _____
ECTG PROGRAM MGR: _____ DATE: _____

VERIFICATION AND CLOSEOUT

13. Approved corrective actions have been verified as satisfactorily implemented.

SIGNATURE

TITLE

DATE

Attachment I

List of Evaluators by Element/Plant

Element 303.01

SQN

WBN

BFN

BLN

Gardner

Gardner

Gardner

N/A

Element 303.02

SQN

WBN

BFN

BLN

Gardner

Gardner
Aycock

N/A

N/A

Element 303.03

SQN

WBN

BFN

BLN

Gardner

Gardner

Gardner

N/A

Element 303.04

SQN

WBN

BFN

BLN

N/A

Gardner

N/A

N/A

Element 303.05

SQN

WBN

BFN

BLN

Gardner
Meers

Gardner

Gardner

N/A