



OCT 24 2008

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
One White Flint North
11555 Rockville Pike
Rockville, MD 20852-2738

Serial No. 08-0627
NSS&L/MLC R0
Docket No. 50-336
License No. DPR-65

DOMINION NUCLEAR CONNECTICUT, INC.
MILLSTONE POWER STATION UNIT 2
END OF CYCLE 18 STEAM GENERATOR TUBE INSPECTION REPORT

In accordance with the Millstone Power Station Unit 2 (MPS2) Technical Specification (TS), Section 6.9.1.9, Dominion Nuclear Connecticut, Inc., hereby submits, the End of Cycle (EOC) 18 Steam Generator Tube Inspection Report. The report is submitted within 180 days after initial entry into MODE 4 following completion of an inspection performed in accordance with TS 6.26, Steam Generator (SG) Program.

The report includes the following:

- a. The scope of inspections performed on each SG,
- b. Active degradation mechanisms found,
- c. Nondestructive examination techniques utilized for each degradation mechanism,
- d. Location, orientation (if linear), and measured sizes (if available) of service induced indications,
- e. Number of tubes plugged during the inspection outage for each active degradation mechanism,
- f. Total number and percentage of tubes plugged to date, and
- g. The results of condition monitoring, including the results of tube pulls and in-situ testing.

If you have any questions or require additional information, please contact Mr. William D. Bartron at (860) 444-4301.

Sincerely,

A. J. Jordan
Site VP – Millstone

A047
NLR

Enclosures: (1)

Commitments made in this letter: None.

cc: U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406-1415

Ms. C. J. Sanders
NRC Project Manager
U.S. Nuclear Regulatory Commission
One White Flint North, Mail Stop O8-B3
11555 Rockville Pike
Rockville, MD 20852-2738

NRC Senior Resident Inspector
Millstone Power Station

ENCLOSURE

Millstone Power Station Unit 2

End of Cycle 18 Steam Generator Tube Inspection Report

**MILLSTONE POWER STATION UNIT 2
DOMINION NUCLEAR CONNECTICUT, INC. (DNC)**

End of Cycle 18 Steam Generator Tube Inspection Report

Millstone Power Station Unit 2 (MPS2) is a two loop Combustion Engineering (CE) pressurized water reactor (PWR) with Babcock and Wilcox (B&W) replacement Steam Generators (SGs). Each SG was designed to contain 8523 U-bend thermally treated Inconel 690 tubes. One hot leg tubesheet hole in SG 1 was plugged during construction and the opposing cold leg hole was not drilled, thus SG 1 has 8522 tubes. The tubing is nominally 0.750 inches outside diameter with a 0.0445 inch nominal wall thickness. During replacement SG fabrication, the tubes were installed using a two-step hydraulic expansion process over the full depth of the 21.06 inch thick tubesheet. The tubesheet was drilled on a triangular pitch with 1.0 inch spacing. There are 141 rows and 167 columns in each SG. To minimize small radius U-bends, tubes in rows 1 through 3 were installed using a staggered arrangement. This resulted in the termination of tubes at different locations between the hot and cold legs. For these rows, the tube identification follows the hot leg row/column naming convention. Secondary side tube support structures include seven lattice grid supports on the vertical section of the tubes and twelve fan bar assemblies on the U-bend section of the tubes. All lattice grid supports are full supports. SG replacement was completed in the fall of 1992 during MPS2's Refueling Outage 11 (2R11). The new SGs have accrued 9.762 Effective Full Power Years (EFPY) of operation as of the End of Cycle (EOC) 18 (April 2008). The 910 MW unit operates with a hot leg temperature of 601 degrees Fahrenheit.

The MPS2 SG eddy current testing (ECT) conducted at EOC 18 was completed on April 24, 2008. Initial entry into Mode 4 following completion of the inspections occurred on May 12, 2008. The examinations, personnel, and equipment conformed to the requirements of NEI 97-06, Rev. 2, Steam Generator Program Guidelines; EPRI Pressurized Water Reactor Steam Generator Examination Guidelines, Rev. 6; and MPS2 Technical Specifications (TSs).

In accordance with MPS2 TSs, a SG tube inspection report is required. TS Section 6.9.1.9 states:

A report shall be submitted within 180 days after initial entry into MODE 4 following completion of an inspection performed in accordance with TS 6.26, Steam Generator (SG) Program. The report shall include:

a. The scope of inspections performed on each SG,

For both SG 1 and SG 2, a 100% full length bobbin coil examination was scheduled to be performed on all tubes from the tube end of the hot leg (TEH) to the tube end of the cold leg (TEC). This was accomplished for the majority of the tubes. The remaining tubes were examined from 07C to TEH, 07C to TEC, 07H to TEH, or 07H to TEC to complete the full length bobbin inspection. See Attachment 1, "Acronyms," for explanation of acronyms. See Attachment 2, "Millstone Power Station Unit 2 Steam Generator Arrangement," for illustration of steam generator component locations.

For both SG1 and SG 2, the rotating pancake coil (RPC) examinations included a 140 tube sample of hot leg tubesheet expansion transitions (TSH +3"/-3") in the periphery area of each SG. In addition, a total of 1012 (438 in SG 1 and 574 in SG 2) locations were examined with RPC. These locations included 2R15 and 2R16 historical locations which consisted of previously reported bulges (BLG), dings (DNG), dents (DNT), non-quantifiable historical indications (NQH), partial tubesheet expansion (PTE), possible loose part (PLP), percent through-wall indications (%TW), and volumetric indications (VOL). These locations also included 2R18 bobbin coil special interest (SI) locations of ding (DNG), dent (DNT) distorted expansion indications (DEI), deposit (DEP), loose part indications (LPI), non-quantifiable indications (NQI), possible loose parts (PLP), various hot leg and cold leg bounding locations, and tubes that were observed with flex gasket material protruding from the tube ends. The inspection summary is documented in Table 1.

Table 1 - Millstone 2R18 ECT Summary

| | SG 1 | SG 2 | Total |
|---|--------|--------|--------|
| Number of Tubes (SG 1 and SG 2) | 8,522 | 8,523 | 17,045 |
| Number of Tubes Inspected F/L w/Bobbin Probe | 8,522* | 8,523* | 17,045 |
| Previously Plugged Tubes | 0 | 0 | 0 |
| Number of Tubes Incomplete w/Bobbin Probe due to Obstruction | 0 | 0 | 0 |
| Number of Inspections w/MRPC (Total) | 578 | 714 | 1292 |
| •Hot Leg Transitions - Original Scope (tubes) | 140 | 140 | 280 |
| •Hot Leg Transitions - Scope Expansion (tubes) | 0 | 0 | 0 |
| •Hot Leg Misc. Special Interest - Diagnostic Exams and from Previous History (locations) | 75 | 92 | 167 |
| •Cold Leg Transitions - Original Scope (tubes) | 0 | 0 | 0 |
| •Cold Leg Transitions - Scope Expansion (tubes) | 0 | 0 | 0 |
| •Cold Leg Misc. Special Interest - Diagnostic Exams and from Previous History (locations) | 98 | 144 | 242 |
| •U-Bends – Original Scope (locations) | 0 | 0 | 0 |
| •U-bend. Special Interest – Diagnostic Exams and from Previous History (locations) | 51 | 97 | 148 |
| •PLP / SVI Bounding Special Interest (locations) | 214 | 241 | 455 |
| Tubes with Max FB Wear \geq 40 % | 0 | 0 | 0 |
| Tubes with Max FB Wear \geq 20% but <40% | 0 | 0 | 0 |
| Tubes with Max FB Wear <20% | 2 | 2 | 4 |
| Tubes with Max SVI / VOL / WAR \geq 40 % | 2 | 0 | 2 |
| Tubes with Max SVI / VOL / WAR \geq 20% but <40% | 2 | 10 | 12 |
| Tubes with Max SVI / VOL / WAR <20% | 3 | 1 | 4 |
| Tubes Plugged as a result of SVI / VOL / WAR \geq 37 % | 2 | 0 | 2 |
| Tubes Plugged as a result of no qualified sizing | 5 | 0 | 5 |
| Tubes Plugged as a result of FB Wear \geq 37 % | 0 | 0 | 0 |
| Tubes Plugged as a result of an Obstruction | 0 | 0 | 0 |
| Tubes Plugged on a discretionary basis (loose part wear with part not removed) | 1 | 2 | 3 |
| Total Tubes Plugged as a Result of this Inspection | 8 | 2 | 10 |

*For 102 tubes in SG 1 and 260 tubes in SG 2, the bobbin exam was a combination of two examinations from opposite legs with overlap at the upper support structure.

b. Active degradation mechanisms found,

Two mechanical tube degradation mechanisms – fan bar wear and foreign object wear were identified during this examination. There was no evidence of any corrosion-related degradation.

c. Nondestructive examination techniques utilized for each degradation mechanism,

Table 2 identifies the examination techniques utilized for each identified degradation mechanism.

d. Location, orientation (if linear), and measured sizes (if available) of service induced indications,

Table 3 identifies the service induced indications reported during the examination.

e. Number of tubes plugged during the inspection outage for each active degradation mechanism,

In SG 1, seven wear indications were reported. Five were located at the tubesheet interface and not in the freespan and were caused by a transient loose part. Since there was no qualified technique for sizing indications at this location, all five tubes were removed from service by plugging. Two additional indications were located above the cold leg secondary side tubesheet interface and were caused by loose part wear. The loose part that caused the wear could not be removed by Foreign Object Search and Retrieval (FOSAR). The maximum depth sizing for these two indications was 67% and 58%. Both tubes along with a third adjacent tube were removed from service by plugging and stabilization. These three tubes box the loose part that could not be removed.

In SG 2, a wear indication was located above the hot leg secondary side tubesheet interface and was caused by a loose part. The maximum depth sizing was 11% TW. The loose part, a piece of flexitallic gasket, was still present and could not be removed. The tube with the wear indication along with an adjacent tube also in contact with the foreign object, were both removed from service by plugging and stabilization.

f. Total number and percentage of tubes plugged to date, and

A total of eight tubes were plugged in SG 1 during this outage and none had been previously plugged. Eight of 8522 tubes or 0.094% of the tubes in SG 1 have been plugged to date. A total of two tubes were plugged in SG 2 during this outage and none had been previously plugged. Two of 8523 tubes or 0.024% of the tubes in SG 2 have been plugged to date.

g. The results of condition monitoring, including the results of tube pulls and in-situ testing.

No tubes were pulled and no in-situ pressure tests were performed. The condition monitoring assessment concluded that the structural integrity, operational leakage and accident induced leakage performance criteria were not exceeded during the operating interval preceding 2R18.

Table 2 – Degradation Mechanisms and Available Inspection Techniques

| Degradation Mechanism | Location | Likelihood of Near-Term Initiation | Detection Technique, ETSS Number | Best Estimate Technique POD | Sizing Technique, ETSS Number | Tech. Sizing Correlation (r^2) | Tech. Sizing Regression Coef. (slope, intercept) | Technique, Personnel Sizing Std Err (%TW) | 2R18 Sample Size |
|------------------------------|--|------------------------------------|----------------------------------|--|-------------------------------|------------------------------------|--|---|---|
| Wear | Tube to Tube Contact | Low | Bobbin, 96004.3 | 1.0 (>10%TW) | Bobbin, 96004.3 | 0.98 | 0.96, 2.92 | 3.52, 0.86 | 100%, full length bobbin in both SGs bobbin identified points of interest, +point / 0.115" exams in both SGs |
| | | | +Point, 96910.1 | 0.98 (>40%TW) | +Point, 96910.1 | 0.92 | 1.01, 4.3 | 6.68, NA | |
| | | | 0.115", 96911.1 | 1.0 (>21%TW) | 0.115", 96911.1 | 0.92 | 1.22, 0.07 | 7.49, 3.22 | |
| Wear | Tube at Fan Bar (existing mechanism) | Medium | Bobbin, 96004.3 | 1.0 (>10%TW) | Bobbin, 96004.3 | 0.98 | 0.96, 2.92 | 3.52, 0.86 | 100%, full length bobbin in both SGs bobbin identified points of interest, +point / 0.115" exams in both SGs |
| | | | +Point, 96910.1 | 0.98 (>40%TW) | +Point, 96910.1 | 0.92 | 1.01, 4.3 | 6.68, NA | |
| | | | 0.115", 96911.1 | 1.0 (>21%TW) | 0.115", 96911.1 | 0.92 | 1.22, 0.07 | 7.49, 3.22 | |
| Wear | Tube at Foreign Object (existing mechanism) | Medium | Bobbin, 96005.2 | 0.98 (>20%TW) | Bobbin, 96005.2 | 0.17 | 0.27, 28.42 | 13.36, 1.73 | 100%, full length bobbin in both SGs +point / 0.115" diagnostic exams |
| | | | +Point, 96910.1 | 0.88 (>40%TW) | +Point, 96910.1 | 0.92 | 1.01, 4.3 | 6.68, NA | |
| | | | 0.115", 96911.1 | 1.0 (>21%TW) | 0.115", 96911.1 | 0.92 | 1.22, 0.07 | 7.49, 3.22 | |
| Pitting | Tube at Secondary Side Sludge/Deposits | Low | Bobbin, 96005.2 | 0.98 (>20%TW) | Bobbin, 96005.2 | 0.17 | 0.27, 28.42 | 13.36, 1.73 | 100%, full length in both SGs |
| Thinning | Tube at support structures | Low | Bobbin, 96001.1 | 0.96 (>20%TW) | Bobbin, 96001.1 | 0.74 | 0.97, -6.61 | 13.20, 0.89 | 100%, full length in both SGs |
| Impingement | Tube at support structures | Very Low | NA | NA | NA | NA | NA | NA | NA |
| IGA/SCC (OD) | Tube Freespan, Non Dented Support Intersections, Sludge Regions | Very Low | Bobbin, 96008.1 | 1.0 (>20%TW) | Bobbin, 96008.1 | 0.55 | 0.74, 9.56 | 20.62, NA | 100%, full length in both SGs |
| SCC (OD) | Tube Freespan, Dented and Non Dented Support Intersections, Sludge Regions, Expansion Transition | Very Low | +Point, 21409.1 | 1.0 (>35%TW) | +Point, 21409.1 | 0.15 | 0.33, 25.61 | 17.88, NA | bobbin identified points of interest, +point exams in both SGs |
| Axial and/or circumferential | | | | 0.98 (axial) 0.95 (% degraded area) (circ) | (% degraded area) | (% degraded area) | (% degraded area) | | |
| SCC (OD) | Freespan including Dent > 5.0 volt | Very Low | Bobbin, 24013.1 | 0.95 (>60%TW), NA | | NA | NA | NA | 100%, full length bobbin in both SGs |
| SCC (OD) | Expansion Transition | Very Low | +Point, 21410.1 | 1.0 (>42%TW) | +Point, 21410.1 | 0.02 | 0.13, 60.1 | 24.50 | bobbin identified points of interest, +point exams in both SGs |
| | | | | 0.7 (<41%TW) | | | | | |
| Volumetric | Freespan | Medium | +Point, 21998.1 | 1.0 (>10%TW) | +Point, 21998.1 | 0.88 | 1.02, 5.81 | 6.28 | +point / 0.115" diagnostic exams |

Table 2 – Degradation Mechanisms and Available Inspection Techniques (continued)

| Degradation Mechanism | Location | Likelihood of Near-Term Initiation | Detection Technique, ETSS Number | Best Estimate Technique POD | Sizing Technique, ETSS Number | Tech. Sizing Correlation (r ²) | Tech. Sizing Regression Coef. (slope, intercept) | Technique, Personnel Sizing Std Err (%TW) | 2R18 Sample Size |
|--|---|------------------------------------|---|--|---|--|---|--|--|
| SCC (OD) | Dented Structural Supports | Very Low | +Point, 22401.1 +Point, 22842.1 | 1.0 (>53%TW) 1.0 (44%TW) | +Point, 22401.1 +Point, 22842.1 | 0.02 0.56 | 1.3, 74.55 0.52, 0.03 | 14.44 0.26 | bobbin identified points of interest, +point exams in both SGs |
| SCC (ID) Circumferential | Tube Expansion Transition, Within Tubesheet, Dents, Near Seal Weld, Plugs | Very Low | +Point, 20510.1 +Point, 96701.1 | 0.96 (>30%TW) 0.67(21-41%TW) 1.0 (>42%TW) | +Point, 20510.1 (%degraded area) +Point 96701.1 | 0.77 (% degraded area) 0.85 | 0.82, 2.83 (% degraded area) 0.84, 10.32 | 7.69 (% degraded area) 9.56 | +Point diagnostic exams |
| SCC (ID) Axial | Tube Expansion Transition, Within Tubesheet, Dents, Tack Expansion, Plugs, <2.0v Dents at TSP / Freespan | Very Low | +Point, 20511.1 Bobbin, 96012.1 +Point, 96703.1 | 1.0 (>37%TW) 1.0 (>17%TW) | +Point, 20511.1 (%degraded area) +Point, 96703.1 (% degraded area) (Axial Length) | 0.29 (% degraded area) 0.83 0.83 | 0.36, 18.91 (% degraded area) 0.90, 0.77 1.00, 0.13 | 7.60 (%degraded area) 10.06 0.28 | +Point diagnostic exams |
| SCC (ID) Axial and/or circumferential | Low Row U-bends | Very Low | +Point, 96511.3 | 1.0 (>27%TW) | +Point, 96511.3 | 0.22 | 0.34, 31.96 | 17.61, NA | bobbin identified points of interest, +point exams in both SGs |
| PWSCC Axial | Dents | Very Low | +Point, 96703.1 | 1.0 (>10%TW) | +Point, 96703.1 | 0.98 | 0.90, 7.56 | 15.28 | Bobbin identified points of interest |
| Wear (foreign object not present) (freespan) | Circumferential Groove Axial Groove Tapered Football Tapered Round Hole Flat Wear Tapered Wear 45 deg. Tapered Wear | Medium | +Point, 27901.0 +Point, 27902.0 +Point, 27903.0 +Point, 27904.0 +Point, 27905.0 +Point, 27906.0 +Point, 27907.0 | 1.0 (>31%TW) 1.0 (>8%TW) 1.0 (>21%TW) 1.0 (>32%TW) 1.0 (>7%TW) 1.0 (>11%TW) 1.0 (>13%TW) | +Point, 27901.0 +Point, 27902.0 +Point, 27903.0 +Point, 27904.0 +Point, 27905.0 +Point, 27906.0 +Point, 27907.0 | 0.98 1.0 1.0 0.98 1.0 1.0 0.98 | 1.05, -1.97 0.98, 1.89 0.97, 2.80 1.00, 0.48 1.09, -4.31 0.96, 1.67 1.05, -2.10 | 2.30 2.32 2.11 1.99 2.05 1.43 2.59 | Additional diagnostic wear techniques for loose part sizing |
| Corrosion Induced Tube Denting | Support Structures | Very Low | Bobbin, no specific ETSS | NA | NA | NA | NA | NA | 100%, full length in both SGs |
| Plug Installation Deficiencies | Plug/Tube Interface | Low | Engineering review plug installation parameters and plug video after installation; Use to date of I-690 welded plugs. | | | | | | SG 1 |

Table 3 – Service Induced Indications

SG 1

| ROW | COL | VOLTS | DEG | PCT | CHN | LOCATION | ELEV_FROM |
|------------|------------|--------------|------------|------------|------------|-----------------|------------------|
| 2 | 7 | 0.25 | 0 | 20 | P5 | TSH | -0.07 |
| 3 | 8 | 0.15 | 0 | 13 | P5 | TSH | -0.02 |
| 4 | 9 | 0.08 | 0 | 7 | P5 | TSH | -0.02 |
| 5 | 10 | 0.08 | 0 | 8 | P5 | TSH | -0.02 |
| 8 | 11 | 0.37 | 0 | 27 | P5 | TSH | 0.09 |
| 40 | 155 | 0.37 | 115 | 11 | P2 | F06 | -1.71 |
| 76 | 141 | 0.94 | 0 | 58 | 6 | TSC | 0.24 |
| 78 | 141 | 1.31 | 0 | 67 | 6 | TSC | 0.11 |
| 140 | 93 | 0.43 | 112 | 12 | P2 | F08 | -0.54 |

SG 2

| ROW | COL | VOLTS | DEG | PCT | CHN | LOCATION | ELEV_FROM |
|------------|------------|--------------|------------|------------|------------|-----------------|------------------|
| 37 | 120 | 0.31 | 78 | 9 | P2 | F07 | -0.7 |
| 28 | 5 | 0.25 | 0 | 29 | 6 | 01C | -2.59 |
| 29 | 4 | 0.19 | 0 | 25 | 6 | 01C | -1.86 |
| 40 | 81 | 0.17 | 79 | 30 | 6 | TSH | 0.12 |
| 59 | 10 | 0.16 | 0 | 23 | 6 | 01C | -6.8 |
| 98 | 143 | 0.11 | 0 | 26 | 6 | TSH | 8.51 |
| 99 | 80 | 0.43 | 76 | 11 | P2 | F06 | 1.31 |
| 118 | 41 | 0.15 | 0 | 11 | 6 | TSH | 12.43 |
| 119 | 42 | 0.17 | 80 | 29 | 6 | TSH | 12.78 |
| 123 | 46 | 0.13 | 64 | 27 | 6 | TSH | 17.61 |
| 124 | 45 | 0.20 | 75 | 31 | 6 | TSH | 19.23 |
| 125 | 48 | 0.3 | 81 | 37 | 6 | TSH | 19.38 |
| 126 | 49 | 0.34 | 93 | 39 | 6 | TSH | 19.82 |

Attachments

| Attachment | Title |
|------------|--|
| 1 | Acronyms |
| 2 | Millstone Power Station Unit 2 Steam Generator Arrangement |

Attachment 1

Acronyms

| | |
|-------|---|
| B&W | Babcock & Wilcox |
| BLG | Bulge |
| CHN | Channel |
| COL | Column |
| DEG | Degrees |
| DEP | Deposit |
| DNG | Ding |
| DNT | Dent |
| ECT | Eddy Current Testing |
| EFPY | Effective Full Power Years |
| ELEV | Elevation |
| ETSS | Examination Technique Specification Sheet |
| FB | Fan Bar |
| F/L | Full Length |
| FOSAR | Foreign Object Search and Retrieval |
| IGA | Intergranular Attack |
| LPI | Loose Part Indication |
| MBM | Manufacturing Burnish Mark |
| MP 2 | Millstone Unit 2 |
| NQH | Non-Quantifiable Historical Indication |
| NQI | Non-Quantifiable Indication |
| EXP | Over Expansion |
| PCT | Percent Through-Wall |
| PLP | Possible Loose Part |
| POD | Probability of Detection |
| PTE | Partial Tubesheet Expansion |
| %TW | Percent Through-Wall |
| RPC | Rotating Pancake Coil |
| SCC | Stress Corrosion Cracking |
| SG 1 | Steam Generator Number 1 |
| SG 2 | Steam Generator Number 2 |
| SLG | Sludge |
| SSI | Secondary Side Inspection |
| SVI | Single Volumetric Indication |
| TEC | Tube End Cold-leg |
| TEH | Tube End Hot-leg |
| TSC | Top of Tube Sheet Cold-leg |
| TSH | Top of Tube Sheet Hot-leg |
| VOL | Volumetric Indication |
| WAR | Wear Indication |

Attachment 2

Millstone Power Station Unit 2 Steam Generator Arrangement

Serial No. 16-127
Request for Withholding Proprietary Information
Enclosure 6
Page 2 of 2

Serial No. 08-0627
Docket No. 50-336
EOC18 SG Tube Inspection Report
Page 11 of 11

[REDACTED]