TECHNICAL EVALUATION REPORT

NRC DOCKET NO. 50-390, 50-391

NRC TAC NO. __

FRC PROJECT C5506 FRC ASSIGNMENT 37

FRCTASK 649

NRC CONTRACT NO. NRC-03-81-130

EVALUATION OF WATTS BAR UNITS 1 AND 2

CABLE PULLING AND CABLE BEND RADII CONCERNS

TER-C5506-645

Prepared for

ı

Nuclear Regulatory Commission Washington, D.C. 20555

FRC Group Leader: G. J. Toman NRC Lead Engineer: J. F. Knight/P. Gill

January 30, 1987

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, or any of their employees, makes any warranty, expressed or impiled, or assumes any legal liability or responsibility for any third party's use, or the results of such use, of any information, apparatus, product or process disclosed in this report, or represents that its use by such third party would not infringe privately owned rights.

Prepared by: l Author

 $1 - 27 - 5$ **Date**

Reviewed by:

Date: 1-29-87

Approved by:

Department D

Date:

FRANKLIN RESEARCH CENTER DIVISION OF ARVIN/CALSPAN 20th & RACE STREETS. PHILADELPHIA. PA. 19103

CONTENTS

ś

CONTENTS (Cont.)

POREWORD

This Technical Evaluation Report was prepared **by** Franklin Research Center **under a** contract with the **U.S.** Nuclear Regulatory Comission (Office **of Muclear** Reactor Regulation. Division of **WR** Licensing-A) for technical assistance **in** support of **NRC** operating reactor licensing actions. The technical evaluation was conducted in accordance with criteria established **by** the **NRC.**

Mr. **J. B.** Gardner and Mr. **W. A. Thue.** independent **cable** consultants, contributed to the preparation of this report.

 \mathbf{r} ł

I

ļ

Ľ i.

r

 $\mathbf{1}$

r. 1

ι

1. INTRODUCTION

1.1 SACKGROUND

The **Tennessee Valley** Authority **(TVA)** and Region **11** of the **U.S.** Nuclear Regulatory Comission (NRC) received reports of nmerous concerns from TVA employees and contractors relating to the adequacy of construction practices at **Watts Bar** Nuclear Plant. To handle these reports, **TVA** hired **a** contractor to collect and document the concerns while maintaining the confidentiality of the concerned individual. The resulting concerns were forwarded to the NRC for review **by TVA.** Under contract to the **NRC.** Franklin Research Center **(FRC)** reviewed and organised the concerns. The review revealed that **a** significant number of concerns centered **on** potential damage to electrical cables from deficient **cable** pulling techniques and from bending cables to less than the minimai bend radii recommended **by** the **cable** manufacturers and **by** industry standards.

1.2 **PURPOSE OF FRC'S EVALUATION**

To determine if significant cable abuse **had** occurred during installation. the **NRC** requested **FRC** to assemble **a** team of cable manufacturing and installa tion experts. The team was charged with:

- **o** determining if significant differences exist between accepted industry practices and those employed at the Watts **bar** plant
- **o** determining the extent that **TVA** cable installation procedures were in accordance with cable.practices and standards at the time **of** cable -installation
- **o** discussing cable pulling and bend radii concerns with **TVA** engineering and installation personnel
- **o** perfoming plant walkdowns to attain **a** general impression of the quality of the cable system installation
- **o** providing **a** Technical Evaluation Report (TM) describing the scope and nature of significant **cable** installatik i problems.

1.3 MIC S APPROACH **AND** CHRONOLOGY **OF THE EVALUATION**

The team's evaluation concentrated on the pulling of cables into and through conduits, and on temporary and permanent bend radii of the cables. In

-1-

addition to reviewing written Information provided **by** TVA, **a** meeting was **held** at TVA engineering headquarters in Knoxville, TN. on July **17, 1936.** to discuss sidewall bearing pressure and other cable pulling concerns. Prior to the July 17, 1986 meeting, TVA provided the FRC team with copies of the report [1]^a from their cable sidewall bearing pressure test program **as a** basis for discus sion during the meeting. Two site audits were also performed, one on July **18. 1986** and **a** second on September **9 and 10. 1986.** During both site audits, con versations were **held** with electricians who **had** installed cables under present **procedures** and under the procedures in effect during the **1978-1933** period when the bulk of the cables were installed. After the first site visit. TVA provided isometric drawings and further information relating to the conduits that TVA **had** determined to have the 82 worst-case cable pulls. After this new information was reviewed by the FRC team, the second site visit was deemed **necessary.**

following the meetings with TVA on July **17** and **18. 1936. 171C** prepared **a** formal **request** for additional information that **was forwarded** to TVA **by** the NRC on August **4. 1936.** TVA formally **responded** to this request for information on October **7. 1986** (2).

1.4 DESCRIPTION **Of** REPORT CONTENTS

ł

Section 2 of this TER provides a summary of the employee concerns that were the impetus for evaluating cable pulling and bend radii at the Watts Bar plant. Section **3** is an evaluation of the **adequacy** of TVA specifications and procedures for cable and conduit installation with respect to practices in the cable industry. Section 4 discusses cable pulling practices **as** they were described **by** TVA electricians and engineers who **were** involved with the work. **Sections 5 through 10 describe technical issues that were found to be signifi**cant during the evaluation. Section **11** describes observations **made** during audits of the Watts Bar conduit system. Section **12** describes the potential effects of the types of **cable abuse** that occurred at the Watts Dar plant. Section **13** describes TVA's proposed equipment failure trending program that will include cables. Section 14 presents the conclusions of the evaluation. and Section 15 provides recommendations for further action by TVA.

*Bracketed numbers refer to the references listed in Section **16.**

Section **3.2.1.2** then states that the maximum "force" on **a** cable shall nat exceed factors of **100** or 30C (depending an the cable type) times the specified bend radius in feet. In the absence **of** any reference to limiting tension to control sidewall bearing pressure (SWBP) during cable installation, this second limit can only **be** taken as an alternate type of tension limit, which is wrong and would give improper guidance. Further error and confusion follows in Section **3.2.l.2d** where the use of the **100** or **300** factors is said to **be** an "alternate" to'the **use** of a table of tension limits that **are based** upon the **0.008** x circular ails rule. Sidewall bearing pressure is never mentioned or dealt with **as such.** Apparently. the writer and **approvers** of the standard were not familar with the fact that the **0.008 x** circular ails limit and the 100 or **³⁰⁰**x the bend radius limit must **be** satisfied simultaneously.

G-38 R8 incorporates more cable pulling requirements than **G-38** R-2, but still contains errors and omissions of concern. An ambiguity exists in Section **3.2.1.6.1** in which five **cases** where **SNIP** is not required to **be** calculated **are** described. Nevertheless. Section 3.2.1.6.1.c **appears** to require the calcula tion of SHIP. The note under Section **3.2.1.6.1.e** concerning SNIP calculation is in error in that it overlooks the distinct possibility that different conduit bends in a run **may** have different radii.

Section **3.2.1.6.2** of **G-38** RB requires use of a **0.3** coefficient of fric tion, which is too low for many of the cable and lubricant combinations used at the Watts Bar plant. The **0.5** coefficient required for use in evaluating pullbys and pullbacks is also very nonconservative for cable and lubricant combinations used at the Watts Bar plant.

ŋ

Detailed trigonometric formulas required **by** Section **3.2.1.6.2** for the effect of cable weight through vertical bends contribute to the formidable appearance of the calculation, but represented **a meager** refinement in the result since the values **assumed** for the coefficients of friction **are** noncon servative and accurate to only one significant figure or **less.** The **example** calculation in Appendix D to G-38 R8 illustrates the point and shows that the complex trigonometric portion of the calculation represents **a** change of less than **1%** to the calculated tension. Repetition of pages of calcialational material in Section **3.2.1.6.3** from **3.2.1.6.2** for multiple cable pulls **makes** specification **G-38** R8 appear technically strong but detracts from its practical usefulness.

 $-B-$

3. EVALUATION Or **TVA SPECIFICATIONS AND** PROCEDURES

3.1 GWIERAL STATUS Or **CABLE** INSTALLATION PRACTICES **AVAILABLE** FRM THE **CABLE** INDUSTRY

×

A primary issue in the evaluation of the cable installation concerns relating to Watts Bar Units **I** and 2 is the extent to which TVA's **cable** instal **ling** procedures conformed to industry standards throughout the period of **cable** installation. in performing this evaluation, the evaluators arrived at the heightened awareness that no definitive source exists that contains a complete description of standard utility-industry practices for **cable** installation. The nature of cable conduit installations is such that the cables terminate in a limited number of types of relatively controlled configurations **(e.g.,** control and termination cabinets, motor control centers. and circuit breakers). However, the configurations of cable conduit runs are extremely variable with **large** variations in the geometry. location, and accessibility of pull points, **and** in the environments to which the conduits **are exposed.** Certain rules of thumb have been agreed upon in the cable industry, usually containing broad margins of safety to accommodate the inevitable **adverse** factors that frequently affect **cable** installation **(e.g..** adverse conduit configurations, awkward pull points, and insufficient lubrication).

Because the guidance available from the **cable** supply industry is general and not application-specific, major **users** or designers of cable systems usually develop their own in-house installation rules or standards to meet their particular needs **by** drawing on the recommendations **of** manufacturers speciali zing in utility type cables. **They** also rely upon experts to **make** design or on-the-spot construction decisions **based** upon their knowledge of cable **structures** and potential **modes** of cable failure. The experts may **be** from their own staff, from an engineering firm, or from the major cable suppliers.

In addition to the cable bending radius guidelines given in **some** ICM publications. **1WE** Stdo 432 and **\$90** contain some important cable installation guidelines for generating stations and nuclear stations, respectively. How ever, there are many installation elements not covered **by** these documents. Such sources **as** technical papers. panel discussions. and manufacturers' engineering information have dealt with most of the elements not covered **by** the standards and constitute the knowledge available to those involved in the

-4-

cable installation work. These **sources** form the basis of the term "industry practice" **as** used in this report. For the **nuclear** construction industry, the only unique aspect of installation practice to prevent cable abuse and **damage is** to **apply all** general guidelines with added conservatism.

Today, there is **a** definite **awareness** in the cable engineering community that the utilities industry's published guidance for **cable** installation is inconplete. and initial steps are being taken to fill some gaps in specific **areas** relating to cable installation abuse. The **task** is difficult because of the complexity of evolving cable materials and designs and the variety of installation conditions in practice. Unfortunately, those persons most aware of the inadequacy of the standards are also those most knowledgeable and informed about proper cable installation practices and, thus, personally have not felt the need for producing more detailed, up-to-date standards. Until such standards **are** produced jointly **by** users. designers, and manufacturers. there will **be** continued concern that abuse has occurred during installation **as** judged **by** various experts each having their own obviously different biases and opinions.

The following subsections relating to TVA Watts Bar cable installation specifications and procedures must **be** considered in light of the above discus sion. **Those** aspects of cable installation practice which would clearly **be** agreed upon **by a** majority of cable installation experts have been addressed.

3.2 TVA SPECIFIChTIONS **AND** PROCEDURES

The following is **a** list of the TVA procedures. standards, and specifi cations that were reviewed in the evaluation of Watts Bar **cable** pulling and bend radii concerns. The revisions of these documents that were in effect during the period when the bulk of the cable installation **was** performed **(1971-1983)** and the present revision were reviewed.

TER-CSS06-649

At the Watts Bar plant. the bulk of the cables were installed between **1973** and **1983.** Therefore, the evaluation of the procedures and practices concentrated on documents in effect during this period and documents in effect today. The primary source of installation instructions from August **1970** through September **1982** was Revision 2 of General Construction Specification **G-38 (0-38** 32) **131.** The present revision of this specification is Revision **8** (4) dated March **17. 1986.**

tion of Conduit and Junction **Boxes**

The aspects of cable installation where TVA specifications **lacked** guidance or differed markedly from industry practices in **1978** and **1986 are** pulling

-6-

tension, sidewall bearing pressure, bending radii, support of vertical **cable,** pulibys. pulling attachments, splice and repair locations, and **cable** jamming dangers.

When reviewing these specifications individually or considering them collectively, it was unclear to wham they were **addressed** and just which docu smints would **be** used in the field **by** electricians, foremen, construction engineers, or designers. Much partial duplication, mixing of practical how to's with complex trigonometric formulas, and references to other documents **made** it difficult to imagine how any worker could have used the specifications and procedures effectively. Enclosure 2 of Reference **2** provided scme insight into the use of the specifications and procedures. Specification **G-38** is the overall TVA corporate specification for cable installation. At the Watts Bar plant, Quality Control Instructions (QC~s) and Quality Control Procedures (QCPs) provided guidance from **G-38** for construction craft use. **TVA** stated in Enclosure 2 to Reference 2 that craft training modules were developed from information contained in the QCIs and **QCPs.** When systems were turned over to the operating group, further modification responsibilities were transferred from the construction department to the modifications department. Modifica tions to the cable system **are** governed **by** Modification and Addition Instruc tions (HAls) such **as KAX-3 (5)** for cable installation. MAI-4 **(6]** for cable termination, and PAI-13 **[7)** conduit **and** junction box installation. MAIs **3** and **¹³**include much of the information from **G-38** and G-40. but **are** organized simply **as** a long **set** of sections and attachments without benefit **of a** table of contents. Review of these MAIs indicates that they are not easy to use.

3.3 TECHNICAL ISSUES

3.3.1 Pulling Tension Related to Stretching and Sidewall Bearing Pressure

Confusing terms and conflicting requirements **are** given in Section **3.2.1.2 of 0-38** R2. **The term** "force" is **used** repeatedly in place of "tension" in the text. In citing the commonly used tension formula, **0.008** lb/circular mil x the area of the conductor in circular mils.* the term "force" is used.

 $-7-$

^{*}A circular mil is used to define cross-sectional areas **of** cables and is **a** unit of area equal to the **area** of **a** circle **0.001** inches in diameter.

Section **3.2.1.2** then **states** that the maximum "force" on **a** cable shall not exceed factors of 100 or 30C (depending on the cable type) times the specified bend radius in feet. In the absence of any reference to limiting tension to control sidewall bearing pressure (SNIP) during cable installation. **this second** limit can only **be** taken **as** an alternate type of tension limit. which is wrong and would give improper guidance. Further error **and** confusion follows in Section **3.2.1.2d** where the use of the **100** or **300** factors is said to **be** an "alternate" to the use of a table of tension limits that **are** based upon the **0.008** x circular mils rule. Sidewall bearing pressure is never mentioned or dealt with **as** such. Apparently. the writer and approvers of the standard were not familar with the fact that the **0.008 x** circular mils limit and the **100** or **300 x** the bend radius limit must **be** satisfied simultaneously.

G-38 RO incorporates more **cable** pulling requirements than **G-38** R-2, but still contains errors and omissions of concern. An ambiguity exists in Section **3.2.1.6.1** in which five **cases where** SNIP is not required to **be** calculated **art** described. **Nevertheless.** Section 3.2.1.6.1.c **appears** to require the calcula tion of SWBP. The note under Section **3.2.2.6.2.e** concerning SNIP calculation is in error in that it overlooks the distinct possibility that different conduit bends in **a** run **may** have different radii.

Section **3.2.1.6.2** of **G-38** R8 requires use of a **0.3** coefficient of fric tion. which is too low for many of the cable and lubricant combinations used **at the Watts** Bar plant. **The 0.5** coefficient required for **use** in evaluating pullbys an pullbacks **is** also very nonconservative for cable **and** lubricant combinations used at the Watts Bar plant.

Detailed trigonometric formulas required **by** Section **3.2.1.6.2** for the effect of cable weight through vertical bends contribute to the formidable appearance of the calculation, but represented a **meager** refinement in the result since the values **assumed** for the coefficients of friction **are** noncon servative and accurate to only one significant figure or **less.** The **example** calculation in A4ppendix **D** to **G-38** RU illustrates the point and **shows** that the complex trigonometric portion of the calculation represents a change of **less** than **1%** to the calculated tension. Repetition of **pages** of calculational material in Section **3.2.1.6.3** from' **3.2.1.6.2** for multiple cable pulls makes specification **G-38** R8 appear technically strong but detracts from its practical usefulness.

 $-8-$

In regard to controlling the tonsion during **a** pull, Section **3.2.1.7** uses the term "monitor" in the unusual **and misleading senses** of either to measure or to **simply** limit the tension. Either sense of the term is applicable any where in the TVA cable pulling practices, but the implied benefits of measuring are assumed when, in fact, there is no assurance that any measurement is done. In the total ancence of guidelines on use of mechanical pullers and on methods of attaching pull ropes to cables after the cables first emerge from pull points, any confusion or sloppiness in defining "monitoring" and how and when it is to **be** used can **lead** to undetected cable abuse.

Section **3.2.1.7.1** of **G-38** R8 contains an unfortunate error which is also contained in the figures on page **3-18;** it describes the tension limit **as** F. (from the **0.008** x circular ails rule), but **ignores** the tension limits from SN3P calculations.

TVA specification G-40 R2 provides no guidance aimed **at** limiting pulling tensions or sidewall bearing pressure **at** bends through proper design and installation of the conduit system.

The current revision, G-40 R9. does cont **-i some** guidance related to prevention **of** cable **abuse** in that it limits the total of bends in a pull to 360° and cautions that condulets must be sized to "accommodate" the cable. There is evidently no consideration given to coordinating the orientation of condulets with the actual direction in which **cables** will **be** pulled. Both revisions of G-40 also allow substitution of **901** condulets for **90*** conduit bends, creating many unnecessary pull points. This latter situation noted in the Watts Bar site visits gives rise to the concern that installers may have **pulled** thrwagh a number of **90*** condulets with consequent high risks **of catl.e damage.** None of the revisions of **G-38** contains a specific prohibition against pulling through 90° condulets.

OW-13 **reiterates** such of **the** information in **G-38** but **adds** that pull boxes should be installed in runs over 50 feet long with 180° of bends or in runs over 150 feet with 90° of bends. Those requirements are extremely restrictive when compared to industry practice and **may.** if used. result in **added cable abuse when cables are** pulled in. out of. or through **these extra boxes** rather than through conduit or conduit bands. The **extra** handling **at these** pull points could result in additional twisting. tangling. bending. and kinking that need not occur with fewer pull points.

-9-

In **sumary,** with respect to pulling tensions, the TVA **1979** standards were **very** inadequate with regard to **SNBP** and the **use** of **90*** condulets when compared to industry practice. The current TVA standards **(G-38 R8, QCP 3.05 R26, and NAIs-3 R6,** -4 **R4,** and **-13 R3)** fill most **gaps** concerning tensional SNIP, but contain **assumptions, errors, omissions, repetitions, and mixtures** of practical information with theory that give **rise** to continuing concerns **as** to whether the **use of** even **these** current standards for **cable** pulling will result in **cables that are** free from abuse.

3.3.2 Bending Radius

ņ

G-38 R2 provides no guidance on permanent bending radius **as** such. **A** table with recommended and minimum bending radius factors is contained in Section 3.2.1.2c on pulling forces, but there **is** no indication that it is applicable to other than conduit bends for tension concerns. Section **2.2.6** on cable bending equipment contains **an** instruction to follow the manufacturer's instructions, but presumably this refers to the manufacturer of the bending equipment. not the manufacturer of the cable.

TVA standard **DS E12.1.5. R1** provides guidance for **minimum** bends of non shielded multiconductor cables, but departs from industry practice in using factors of multiples of the outside diameter of largest internal conductor rather than the outside diameter of the overall cable. Another nonconserva tive guideline differing from any industry practice known to the **FYC** team is the permitted removal of the jackets of single conductor **cable** or of those of the individual conductors of multiconductor cable to facilitate making sharper bends. The potential for damaging the cable during such stripping **appears** to far **exceed** the risks in overbending the jacketed single or aulticonductor **cable.**

Section 3.2.1.3.4 of **0-38 R8 deals** with overbending during installation and handling. **In** etfect. it states that if overbending **is done** during instal lation. "restore the cable to acceptable radius.' **There are** so explicit, pub lished standards for temporary bends. but there is implied relief for medium voltage cables through published shipping-reel diameter tables contained in **1CEA/ND4A** cable standards. These published tables imply considerable relief for medium voltage cables but little for low voltage cables. Temporary overbending is a recognized cowmon problem. but there is no utility- or

-10-

industry-wide consensus on how to **addres.-** it in **a** definitive way. TVA's manner of dealing with the temporary bending is probably no better or worse than most other utilities.

TVA standard **DS E-13.6.2,** R1 addresses special bending problems **of** medium~ voltage shielded cables that occurred at the Watts Bar plant; these problems apparently are still in the process of being resolved **by** TVA. **KAl-13** R6, Section **S.6.h** instructs electricians to avoid reversing the bend of cables as wound an the reel, when possible. This instruction, which is particularly appropriate to very special situations relating to large, stiff, high voltage cables, is impractical for other general cable installations.

The memorandum from **W. S.** Raughley dated September 2. **1986 [8)** addresses the **bend** radii problem for mediur. voltage cable **as** well as coax type cables, showing an awareness of this issue on the part of TVA and an intent to rectify the attendant problems.

In summary. early TVA standards had far less guidance relating to permasent cable bends than was common in the industry at the time **as** evidenced **by** ICEA standards and manufacturers' information then available. Current TVA standards do **address key** issues, but unnecessary complexities and nonconser vative elements give **some** cause for continued concern.

3.3.3 Vertical Susort of **Cable** in Conduits

G-38 R2 gives guidance for vertical tray cable support. but provides no information for vertical conduits or on the dangers of using 90° condulets at or near the tops of runs. G-40 R2 contains no mention of vertical support of cables in conduits.

Section 3.2.1.9 of G-38 R8 states that cables in vertical conduits shall **be supported in accordance with National Electrical Code (NEC) article 300-19** but does not describe the NEC requirement. Section **3.2.1.9** then describes the allowable supporting devices such **as** Kellame support gripe and cost sealant. For supporting cable in conduit bodies (condulets). application of Raychem **MMR** nuclear jacket-repair wraparound sleeves is allowed. However, it is not clear how the Raychem sleeves provide support of the cable in the vertical run, nor is it certain that the manufacturer intends the sleeves to **be** used in

-11-

such an application. Section **3.2.1.9 does** not provide **a warning** that the predominant cause of cable damage from a 90° conduit located at or near the top of **a** vertical conduit is from indentation and cutting **of** the jacket and insulation **by** the sharp radius at the inside corner of most **90*** condulets.

The current G-40 **R9** specification gives preference to conduit binds at the top of vertical runs rather than use of 90° condulets and demands "provision for support" if **90*** condulets are used. Again, concern **seems** only to **be** related to the overall bend radius of the cable rather than the indentation of the jacket and insulation **by** the corner of **a 90*** condulet. **IS** E-13.6.2 **1986, *Me of** Conduit Bodies," has no reference whatever to vertical support **issues. NAX-3 R6** details the NEC-based guidelines and the **use** of **0-38** RO information and **adds** the statement that installations with long vertical runs are to have junction boxes at the top with support devices for the cables.

The memorandum from **W. S.** Raughley dated July **16, 1986 (9]** addresses ver tical support concerns, but still ignores the danger of indentation and cutting of the **cable** jacket and insulation at the corner of **90*** condulets used near the top of vertical runs. The need for **added** precautions appropriate to harsh (high temperature) envirorwent areas is not recognized. High temperature **increases** the probability for indentation and cutting of cable jackets and insulation at the corners of 90° condulets.

In sumary. **1978** time-frame TVA specifiations and procedures **had** no **guidance** for support **of** cables in vertical conduits. While current documents recognise some aspects of **90*** condulet danger near the top of vertical **runs,** only the current **MU-3** deals with it at **a** level equivalent to present utility **mad** industrial standard practice. Again, industry standards are far from detailed and complete. but guidance concerning good cable support practices is readily available **from** cable manufacturers.

3.3.4 **Fullbvs**

A pullby is the pulling **of** one or **sore** new cables past cables that are already in **a** conduit. In **a** pullby. the cable being pulled into the conduit will tend to ride across the existing cables **at** bends in the conduit. The moving cable and pull rope have **a** tendency to **saw** through the stationary cable if friction and pressures **are** high. **G-38 R2 did** not address pullbys.

-12-

G-38 R8, Section **3.2.1.2 does** address the subject and suggests avoiding pullbys where practical, but still allows them. It notes that precautions may **be** required to avoid **damage** from SWDP during **a** puilby. However, SWBP is not the prime cause of damage from pulibys; sawing and cutting of the stationary cable **by** the moving cable or rope is. Guidance provided in **G-38** R8 **does** cover **added** friction, the **use** of more lubricant, **a** requirement to avoid damage from the pull rope, and **stopping** the pull if tension suddenly **increases; however,** no specific methodology or criteria **are** given. **All** of **these** items do reflect current industry concerns,* but the large number of pullbys **at** the watts Bar plant, together with many plastic jacketed cables **mixed** with rubber jacketed cables, the complexity of many pulls, and the vagueness of precautions, lead to the conclusion that the Watts har pullby problems were frequent and significant and the "solutions" in the current **TVA** standards less effective than the practices used **by** most of the utility industry for station construction.

3.3.S Pulling Attachments

The earlier **G-38** R2 contains good detail on methods of fastening cables to pull ropes but does not call for use of the swivels. The use of swivels **was** introduced in **G-38** R4. in 1934.

The current **G-38** RI. Section **3.2.1.7.39** indicates **basket-weave** grips may **be** used to pull **cables** out of conduits for reuse. Another section instructs electricians to discard **extra** cable near pulling gripe. which may have been damaged during pulling. These instructions appear to **be** inconsistent, and the reuse of cable that requires application of grips to pull the cable back to an intermediate pull point would not **be** in accord. with WVA or industry practice of scrapping cable that **was** under pulling grips during **a** pull. During the **process** of pulling the cable back out of the conduit. the **basket-weave** grip **my** damage the insulation. but the current TVA standards ignore this possi bility **and allow reuse** of the cable.

Absent from **all** TVA standards reviewed is any guidance on how one attaches pull rope to cables at mid-run pull points to pull the balance of cable after the pulling line has emerged. (On-site personnel mentioned using **a** "rope with half hitches." a practice that can cause significant damage to the insulation during pulling.)

-13-

3.3.6 Splice **and** Repair Location

The earlier **0-38** R2, Section 3.4 limits the location of splices to cable trays and junction boxes but **does** not note any location limits for jacket **repairs. presumably cables** with repaired jackets could have been pulled into the conduits.

The current **G-38** R-8, Section **3.7** gives **a** now limitation of no repairs in medium voltage cable except for the jacket, but it allows splicing as an option for other cables, with no limits **as** to location or whether it is **1E** or non-1E cable. Low voltage cables have no restrictions on repair or splice location. Sections 3.4.2 to 3.4.7 on splicing also **have** no location constraints for splices.

Unless SD E12.5.9, referenced in G-38 R8, but not provided to FRC, has limitations, there appears to be little guidance limiting the location or protection of repairs or splices, which is at odds with most cable and splicing material manufacturers' specifications.

3.3.7 Jamming Danger

Neither **G-38** R2 or R8, nor any other TVA standard reviewed. indicates any **awareness** of **dangers** of jamming when **titree** or four cables are installed in **a** duct or conduit **(see** Section **7** of this report for **a** further discussion of jamming). Jamming has been recognized as an industry concern for decades and appears in~ most manufacturers' installation guides or in standards such **as** IEEE Std 690-84. The reason for the jamming concern is that while industry practice (including TVA) limits conduit filling to 40%. for three single conductor cables, the range of **31%** to **38%** filling is the range is which jamming danger exists. "Efficient" choice of conduit size thus invites the danger of jamming.

4. **EVALUATION** OF **CABLE PULLING** PRACTICES

4.1 **CABLE PULLING** PRACTICES

 \blacktriangle

As a result of dicussions with engineers and electrical workers at the Matte Bar plant. it is known that the bulk of the cables were installed in the following manner:

- a. Engineers prepared work orders for the pulls that included such information as termination points, conduit size, number and size of **cables,** and other basic essentials for **the cable** run.
- *b.* Electrical workers installed the conduit between the cable termination points specified **by** the work order. **They** had latitude in locating the conduit and in choosing and locating the conduit coqponents such **as condulets.**
- c. Usually another crew of electrical workers did the actual cable pulling after the conduit system was in place. This crew **had** the choice of the direction of pull and of the number of pull points that were actually used. Some pulls points **may** have been attained **by** disassembling the conduit and reassembling it after the pull **was** completed. However, this practice was not documented.
- **d. If** problems arose during the pull, engineering and quality control groups were **called** in to evaluate and resolve the situation.

This manner of installation indicates that the bulk of the pulls were made without the work really being engineered. Actual tension, sidewall bearing pressure forces, and bending radii were not known at the time of the pulls and cannot **be** establishii at this late date. As **&** consequence. it is not possible to state definitely whether the bulk of the cables were properly Installed.

It became obvious during the discussions with TVA personnel that most of the burden for quality depended on the skill of the workmen. The electricians **that were interviewed displayed a good** attitude and knowledge of the field requirements for proper installation.

4.2 CONTROL OF TENSION

Tension *control" or "monitoring" under TVA specifications and procedures means use **of** either a dynamometer or break link. or **simply** detecting changes in tension of the pull rope when pulling **by** hand. Discussion with installers

at the site indicated break links were almost universally used on mechanically assisted pulls. The **1979** through **1986** versions of **QCP** and **QCI 3.05** give adequate information on the testing. selection, and **use** of break links or break lines based upon the **0.008 x** circular mil rule for cable stretching. The current specifications such **as G-38** R8 now **deal** with SWBP limitations. However, the awareness and concern **shown by** electricians responsible for cable installation, together with FRC's inspection of cable ends at the plant and the inherent margin of safety of the cables to SWDP, leads to the belief that there are very few cables in place **likely** to have suffered significant crushing damage from tension around conduit bends (SWBP).

٠

ł

i

ţ

ļ

P ï.

L

l

There are voids in the TVA installation instructions which cause concern for cable **damage** during pulling beyond those that straightforward stretching or **SWDP** calculations would reveal. One of these is the methods used to **apply** tension to **a** midpoint on **a** cable during a pull. For long mechanically assisted pulls with many pull points, the pulling of cable beyond that point where the pulling rope emerges presents **a** field problem relating to providing **a** gripping method for mideable pulling that will not **damage** the cable. Instructions for pullbacks now specify the use of mesh grips. Use of such grips requires considerable care to prevent tearing and cutting damage to the jacket and insulation. Installers mentioned the use of **a** rope and **half** hitches for midpoint pulling, **a** practice that could damage the **cable.** With either basket grips or **half** hitches, and with tensions **even a** fraction of the **0.008** x circu lar mil rule limits, serious damage could result to the cable that ultimately will **be** located in the conduits and will **be** unobservable. The lack of detail an the mechanical devices used and the handling of the cable when it was pulled out of **and** into the numerous intermediate pull points leaves **a** great **deal** of uncontrolled latitude to the installers. The difficulty of preventing malticable crossovers, kinks, **and** twists in pull point loops and of preventing high tension in some conductors going through **900** cndulets with their sharp corners is felt to **be as** much or greater than the risks resulting from pulling tensions that give rise to excessive SWBP. The experience of installers and the encouragement **by** construction management to the installers to take pains to minimize these **damage** risks become major factors that are not truly **assessable** after completion of **cable** installation.

-16-

4.3 **USE** OF MID-COMDIT **PULL POINTS**

During the discussions with the electricians, the various types of pull points were described. Pull-boxes were usually installed at the direction of the engineering group. Condulets (straight and **900)** were installed at the option of the conduit installer when **a** pull would exceed **3600** of bends or prescribed length limits. **If** the pull rope broke during **a** pull and the cable could not **be** pulled into **a** conduit, the cable would **be** removed and **a** pull point **added.** In **som cases,** the conduit was disassembled to **make a** pull point and then reassembled with the cable in place. The actual use of pull points is not documented. For example, there is no record of whether **a** straight condulet was used **as a** pull point or if the cable was pulled straight through it.

During the first discussion with electricians on July 18, 1986, the descriptions of pull point **use** indicated that the cables were pulled completely out of **a** pull point and then inserted into the next segment and pulled again. This method **led** to concerns relating to condulet pull points. When cables are pulled out of **a** condulet and reinserted into the other side, the last portion of the loop of cable entering the condulet is subjected to very harsh banding. For many cables used at the Watts Bar plant, the bend radius is on the order of three to four times the diameter of the cable. Such **a small** bend radius exceeds the minimum allowable limit for any of the types **of** cable used at the Watts Bar plant.

The discussions with the Watts Bar electricians on September **9, 1986** provided further insight into use of pull points. In this discussion, they stated that, most often, cables were not pulled completely out of the condulet. Rather, electricians were stationed at each pull point to **"help"** the cable along **by** hand without pulling the cable out of the condulet. **If** needed, more lubricant **was added** at **a** pull point. Camunications between electricians was generally **by** voice **and** involved yelling to each other through the conduit.

While the first **method** of pulling **raises** concern relating to **excessive** bending **damage,** the effectiveness of the second **method** in providing **a** controlled pull is unclear. Certainly, the difficulty in performing **a** tension or SWBP calculation for the second method is increased inordinately. The tension carried from one segment of the pull to the next is not independent in the second method of pulling. The ability of the electrician to **"help"** the

-17-

cable along is questionable given the awkward location of many of the condulets and the limited space for hand holds in most condulets. If the electrician could truly **help** the cable along, was there any way in which to judge the pulling tension he was applying? And lastly, it is difficult to envision the simultaneous application of lubricant while helping **a** cable along in **a** condulet.

4.4 LUBRICANTS AND LUBRICATION

 \blacktriangle

ï

ı ί

٢ Ł.

A variety of cable pulling lubricants have been used at the Watts Bar plant. The bulk of the cables were pulled during the time that Yellow-77 or Y-er Ease was available for plastic and rubber jacketed cable, and dust with mica or soapstone was available for use on cables with braided coverings. At. the time of **a** cable pull, the decision to use lubrication, **as** well **as** the amount to use, **was** left to the electricians.

0-38 R2 provides **a** list of allowable lubricants but **does** not provide any guidance for their use. **G-38** R2 **states** that "lubricants should **be** used **...** when pulling cable into conduits." Most of the cable runs at the Watts Bar plant **are** comparatively short; hence, probably most of the pulls were made without the **use** of any lubricant during the **2970s.** The electricians appear to have been astute enough to use lubricants for the longer pulls where the pulling tension and sidewall bearing pressure were critical.

The **key** problem with lubricants at the Watts Bar plant is not their use or lack of use, but the way that they have been accounted for in subsequent calculations of tension and SWBP. In the calculations performed **by TVA** for the worst-case cable conduits at the Watts Bar plant, very low coefficients of friction were **assumed.** The static coefficient of friction is defined in its simplest terms **as** the factor which, when multipled **by** the normal force exerted **by the cable** on the conduit **by** virtue of its weight and the weight of other cables resting on it, yields the pulling tension required to start the **cable** or cables in motion. The dynamic coefficient of friction is basically the same except it is the tension required to **keep** the cable or cables in motion.

The static coefficient of friction is generally somewhat larger than the dynamic value. The importance of this fact is that the lowest tensions **are** obtained **by** pulling **a** cable in one continuous action. This is best accom plished with mechanical equipoent such **as** capstans. Evidence indicates that

-18-

controlled mechanical pulling was **seldom** the situation at the Watts Bar plant. Even with mechanical equipment, considerable planning is required to **make** one continuous pull. For example, one employee concern states that **a** come-a-long was used to pull the cable. Such **a** hand-operated, ratchet-driven device would produce **a** pulsing, stop-start pull having alternating high and low tensional forces **as** the friction cycled between static and dynamic. There is **a** high probability that most pulls were **made** using frequent stopping and starting; hence, the static coefficient is the best value to use in calculations.

Technical papers and reports, such as IEEE 84 T&D 375-2 [10] and EPRI EL-3333 [11]. provide values of static and dynamic friction. These data show that, on average, the static coefficient friction is about **10** percent greater than the dynamic. The static values for friction will **be** used in this dis cussion because of the starting and stopping type of pulling described above and the slight conservatism that is provided.

When cables are pulled into rigid steel conduit, both the jacket material **and** the type of lubrication (if any) have **a** significant effect on the friction value. **If** no lubricant is used, the static coefficients of friction from 1.4 (for Hypalon) to **0.55** (for polyvinyl chloride) are typical and represent materials actually used. The application of talcum powder to smooth, extruded jackets reduces the values to the range of from 0.42 to **0.62,** depending on the jacket material. It should **be** noted that talcum powder was used only on cables with braided jackets for which no comparative data are available. It is reasonable to expect **a** slightly higher coefficient of friction would apply for braided cables because much of the lubricant would **fall** into the voids in the braiding.

A type of lubricant that further reduces the friction is one that is **made** of bentonite clay an water. Typical values **are 0.25** to **0.50** for **these jackets** in rigid conduits. The **lowest values** for pulling compounds used prior to the **1980s are** obtained with **wax emulsion. and values** of **0.15** to **0.37 are shown** in the literature. These materials were not commonly used at the Watts Bar plant; Yellow **77** was.

The newer Polywater **J** and similar compounds reduce static friction coeffi cients to 0.15 to **0.18.** This was the material used in TVA's sidewall bearing pressure (SWBP) tests and now used for cable pulling at the Watts Bar plant.

-19-

The **above** information **shows** that large variations in the coefficients of friction could have existed under the differing conditions that occurred during pulls prior to the **use** of Polywater **J as a** lubricant. This is signifi cant in relation to the TVA plants for the following **reasons:**

- 1. The **seans** of application, type. and quantity of lubricant actually used in the past pulls are not fully known. The amount of lubricant that actually remained on the cables near the ends of multiple pull points with their "help-along" concept, described in Section 4.3. **leaves a** question regarding the effectiveness of the lubricant that **was used.** It **is** not clear that cables can be adequately lubricated **at** pull points where they **are helped** along **rathe..** than when they **are** pulled out and relubricated.
- 2. Pullbys **were** made when many cables **were** already in the conduits. Rather than making use of the coefficients of friction for jacket to **steel** interfaces, the higher values for the coefficient of friction between the two jacket materials must be used in the calculations.

Back calculations of pulling tensions may require the use of a very conservative coefficient of friction if the **facts are** not known regarding the actual use or type of lubricant. A value of 0.6 to 0.7 is suggested. For pullbys. an even higher coefficient of friction such **as** 1.0 should **be** used.

4.5 PULLING THROUGH FLCEIBLE **CONDUITS AND 900 CONDULETS**

L.

ì

Sidewall bearing pressure* (SNBP) is the radial force exerted on a cable **at a** bend when the cable is being pulled around a bend or sheave. Crushing damage to the cable insulation system is the concern. In the United States. the maximum allowable value is usually given in pounds per foot. The definition of **SWBP** can leave the erroneous impression that only the radius **of** curvature is involved. Crushing takes place depending on the length of the contact aurface. For example. 3z **a** cable is supported on **a** 1/4-inch surface of a **900** condulet while bent to a 1-foot radius, the maximum allowable sidewall bearing pressure is 1/48 of that indicated in the usual tables when only the 1-foot radius is considered. This reduction in allowable force relates to the sidewall force being concentrated on a 1/4-inch surface rather than on the entire bend associated with the 1-foot radius of the cable.

^{*}Note: Pressure is a misnomer in that sidewall bearing pressure **is** generally given the dimensions of force per unit length of a curved surface.

On **the** drawings for the **worst-case** cable conduits **at the Watts Bar** plant, flexible conduits were shown **as** being included in many pulls. (Inclusion **ef** flexible conduit in a pull **was** not part of the evaluation of "worst-case" pulls.) The electricians indicated that, in general, end-of-the-run flexible conduits **were** not included in **a** pull. However, some of the conduit runs contained mid-point flexible conduits, indicating that some pulls were made through flexible conduits. The inside surface of **a** flexible conduit has gaps between the contact **areas because** of the corrugations. Therefore, the entire surface of the cable running through **a** bend in **a** flexible conduit is not **supported. A** cable under tension that stops moving during **a** pull will tend to have its surface lock into the corrugations of the bends in **a** flexible conduit. When movement is resumed **by** pulling harder on the cable, the shear forces on the cable surface, which are equivalent to very high frictional forces, can severely tear the cable jacket and insulation.

pulling around **a 90*** condulet is **of** greatest concern because the total bearing surface supporting the bend is approximately 1/4 inch long. Consid erable damage is **likely** to occur if cables are pulled under tension around the inside **edge** of **a 90*** condulet. The large quantities of **90*** condulets used at the Watts Bar plant and the described method of helping cables along at 90° condulets leads to the assumption that some of the cable **was** actually being supported **by** the sharp corners of **90*** condulets during pulling. For **⁹⁰⁰** condulets that **are likely** to **have** been pulled through, **an assessment** would **be** required to determine if **damage** occurred when the cables **were** moved under tension over the sharp corner..

-21-

S. TENSION AND SIDEWALL BEARING PRESSURE CALCULATIONS

Previous sections of this report have **stated** that calculations for pulling tension and sidewall bearing **pressure at the Matts** Bar plant were **made** many years after the pulls **were** performed. Many of the crucial facts needed to make an accurate calculation, such **as** the effectiveness of the lubricants, the **use** of pull points, and direction of pull, are no longer available.

۰.

ł

ł 1

Ł.

I.

Li

I.

ļ

If **these facts were** known, reasonably accurate calculations could **be** performed. Without these facts, many assumptions are needed. An example of this **is TVA's** assumption for conduit No. **IPLC62E** that all of the **15** available pull points were actually used. **If** only **a** portion of **these available** pull points were used, the calculated tension and MWP values would **be** much higher than **those** shown in TVA supporting documents. Another example is conduit No. lPP **2188A** with only one mid-conduit pull point, **a** straight condulet. If this point was not used, the total bends would **be** over **750** degrees. **If** it **had** been used, the allowable bending radius of the cable would have been greatly exceeded when the final portion of the loop of cable entered the condulet.

As sLated in Section 4.4, the choice of **0.3** for the coefficient **of** fric tion for cable pulled with Yellow-77 is nonconservative for the calculations. **A** further complication is the method of manually helping **a** cable along at **a** pull point. The method described in Section 4.3 causes an additional concern for the accuracy of the present calculations which **assume'that** the tension in each segment of **a** conduit is independent of the tension in the next and last segments. Independence cannot **be** assumed for the help-a-long style of pulling.

The calculations were performed **by** TVA for the **32 worst-case** conduits after the pulling was completed to determine if SWBP and pulling tension **limits had been exceeded** for the **cables.** While the assumptions that were **used as a basis for these** calculations ware not fully **conservative, the** results **provided** an **adequate** focus for selection of **worst-case** conduits for evalua tion. However, future calculations performed before pulls at a made should entail consideration of higher coefficients of friction, actual pulling points. **and** the actual direction of the pull.

-22-

6. PULLSYS

Pulibys were not recognized in the **1979** version of **G-38** (M) **as a** subject of concern. **In** the current specification **(G-38** RO). they **are** permitted but not preferred. Judging from wide separation of cable installation dates shown for **some** conduits, the "preference" noted in the **G-38** R8 specification was often not a field option. The text in the TVA standards and the discussions at the site with engineers and electricians indicate that the preference to avoid pullbys stemmed from concern for the added friction, higher sidewall pressures, possibility of **cables** jamming during the pull, and the difficulty of getting a pull rope through the conduits. The electricians steted during interviews that examination of cable emerging from the conduit would give assurance that no damage had occurred.

ь

General practice at utilities, **as** revealed **by** discussions with utility engineers, recognizes saw-through of the coverings and insulation of in-place cables **by** the traveling pull rope or cable **as** the greatest risk in pullbys. It is not necessarily detectable from evaluation of emerging cable, observa tion of high tension or sudden rises in tension (or jamming), or even **by** performance of routine electrical tests after installation. Saw-through **was** recognized **by** one **WVA** electrician when he indicated in the on-site discussion. **"We** had **a** pull line that came out looking black." Unfortunately, the very abrasive nature of manila or certain braided synthetic pull lines can **be** severe. The pulling of rubber (thermo-setting) jacketed cables over thermo plastic jacketed/insulated cables maximizes the probability of saw-through damage **as** the frictional heat and wear **are** distributed along the cable being pulled but concentrated at particular locations on the in-place cable.

One favorable factor at the Watts Bar plant is that more recent pullbys have used Polywater J as the lubricant. If well applied, it provides a much better chance of the lubricant being effective much further into the conduit than does the earlier used Yellow-77. Yellaw-77 tends to wipe off the cable **a** short way into the conduit.

The net result of the above circumstances is that a realistic assessment of the presence or freedom **of** damage to cables from pullby saw-through can only **be wade by** removal for examination or **by** flooding the conduit with water

-z23-

and performing electrical **tests.** If saw-through damage **has** occurred and the conduits do become wet due to **a** harsh environment or condensation. there is danger that common **mode** failures may occur that could affect multiple systems.

Analysis of the 82 worst-case conduits will indicate those conduits in which the highest amount of puilby damage could have occurred. **If** the cables from such conduits were electrically tested under wet conditions or removed and examined for damage, conclusions could **be** drawn concerning whether or not pullby damage is **a** significant problem for the overall cable system at the Watts Bar plant.

TVA provided information regarding pullbys and harsh environments for the ⁸²**worst-case** pulls [2). Eleven of the conduits having pullbys, indicated through multiple cable pulling **dates, also were** located in harsh environ ments. It should also **be** noted that even in mild environments, wetting **of** the inside of the conduits is possible due to condensation. **One** conduit. No. lPP2lSSA. examined during the second site visit, was found to **be** wet. When **a** vertical condulet **was** opened, it **was** found to **be** filled with water for **half** of its height. This condition existed under **a** normal. non-accident environment.

Pullbys. which only recently have **been** recognized **by TVA as being** undesir **able, have apparently been so judged** only **because** of the **added** difficulty of the cable pull. The distinct hazard of sawing through the jacket and insula tion of the in-place cables **has** not been **realized** or addressed **by** TVA up to the present time.

 $\tilde{\omega}$

r ak

-24-

7. JAN RATIO

When the ratio of the inside diameter of **a** conduit to the cable diameter is close to **3.0, one** of the cables in a three- or four-cable pull **may** slip between two other cables, causing the cables to jam or wedge in the conduit **as** the cables **are** pulled around **a** bend. **The** jamming occurs when the summation of the **cable** diameters approximately matches the conduit diameter. **If** the summation of the cable diameters is somewhat larger than the conduit diameter, the cables cannot align with each other to cause the jamming. Jamming is most **likely** to occur when the cables are pulled around a bend rather than when being pulled in **a** straight run. The ratio of the diameter of the conduit to the diameter of the cable is called the jam ratio.

The limits on jam ratio must recognize variations in cables **as** well **as** ovality in the conduit at field bends. The generally recognised formulas are:

> **DD** (2.3; **)3.15**

ί.

where **D** is the diameter of the conduit and **d** is the diameter of the cable. **One of** the above two expressions must **be** satisfied to remove the concern for jamming.

TVA did not **take** jam ratio into account during the sizing of the conduit. As described in Section **3.** jam ratio is not considered in TVA specifications and procedures. To complicate jamming ratio evaluation, TVA lists cables from several manufacturers **as** having the **same** diameter. While **some** variation is taken int; account in the **above** equations, cables used in runs that **are close** to being in the jamming region should have their diameters measured indivi dually.

If the cables actually do jam. the tension can increase **by** a factor of **10.** This sudden increase probably would **be** noticed **by** the cable pulling crews. **Of** greater concern is the pull that just begins to jam. In this case. the tension **may** increase modestly and not **be** noticed **by** the installers.. Damage to the cable can therefore be more subtle because of crushing or high forces around bends. It is of greater concern to the safety of the plant **because the cables and** conduits in redundant trains **are likely** to have the same dimensional factors and similar conduit runs. Therefore, redundant systems could have experienced like cable damage.

 $-25-$

If records indicate that pulls were **made** where the cables and conduit ratios **are** close to the **above** limits, actual field measurements of **cable** and conduit dimensions should **be** made to determine whether Jamming **is** of concern. **if** calculation of the Jaming ratios indicates that the potential for Jamming **exists,** the worst **cases** for Jamming should **be** investigated to **assess** the general level of risk to the plant cable system.

3. CABLE SIDEWALL DEARING PRESSURE **TESTS**

The TVA test program for sidewall bearing pressure **(SNIP),** performed in April and **Nay 1986.** and its report **[11** dated May **1936** represented ideal condi tions and may have little direct applicability to the cables pulled during Watts Bar construction. Both situational and technical factors **lead** to this conclusion.

The situational **differences between the station** conditions **and those simulated by the test. are:**

- **1. The** method of applying lubricant **and the probable effectiveness are** totally different. **The special flooding** device, "Soaper." used in the test **was** not available for field installations and, more often than not, could not have been used because of the very difficult accessibility of cable **feed** and pull points durirq installation.
- 2. The Polywater lubricant specified for the test was not available at the time of most of the cable installation and is far superior to the lubricants that were actually used. The superiority involves both
the low coefficient of friction attained and its resistance to being wiped off the cable surface during pulling. This superiority is significant because damage to cables from severe drag forces is much more common than from radial (SWBP) pressure alone.
- **3.** There is no indication that the test conduits were thoroughly cleaned of lubricant between tests. Therefore, lubricant from prior test pulls probably **was present** in subsequent tests and **made** lubrication nearly perfect for the tests **--** far different than pulling into virgin dry conduits **a** occurred at the Watts Bar plant site.
- 4. Careful monitoring of cable tensions **as** performed during the tests **was seldom done** at the Watts har plant and apparently **was never** recorded in the field. Therefore, neither the magnitude nor instability of tensions can **be** compared between the tests and the (measurement) sense, not that of **TVA** standards where it implies only that some means is used to limit the tension.
- **S.** Nulticable pulls with **cables** of mixed usies **and** construction **as** commonly found at the Watts Bar plant were not included in the tests.
- **6. The** pulling source of the test was **especially engineered** to provide **as** smooth (continuous) **a** tension **as possible.** which **is** in **stark** contrast to the field where such **methods were** apparently **seldom,** if **ever, used.**
- **7.** Pullbys. recognized **by** the industry and **by** TVA in its recent change to **0-38 as potentially** damaging to in-place cables. **were** not **evaluated** or considered in the scope of the tests.
- **8.** Swivels used during the tests were apparently not commonly used at the Watts Bar plant. There were no requirements for **use** of swivels and no requirement to record the **use** of swivels when they were used.
- **9.** The **mixing** up, twisting, **and** crossing of cables **fed** in and out of many successive condulets or pull boxes, **as** probably occurred in Watts Bar cable pulls, was not evaluated during the test. As the number of random crossovers **increases,** the potential for damage at sidewall bearing points increases rapidly. It is one of the many reasons for conservatism in industry-recommended practices relating to the limits for SWBP but was absent in the tests.
- **10.** The steel conduits used in the tests develop low coefficients of friction with slight lubrication and are not **damaged by** cable or fiber pulling lines, whereas ducts of other materials (plastic, transits, fiber) are more readily **damaged** and. in turn, affect the friction and damage potential to cable. Duct materials other than steel were used in certain portions of the Watts Bar plant, but not evaluated in the test.

Several major technical **issues also** bring into question the applicability of the test results:

- **I.** The tension **necessary** to move the cable loop through the tzst rig **was** not measured so there is no means of determining or investigating the actual coefficients of friction. (The tension in the cable loop **was** monitored.)
- 2. There **was** no program to investigate the conditions necessary to **damage** cable, or what the **mode** of or symptoms of damage might **be** for the several cable constructions tested. **Had** such "fragility" tests **been made.** then it is **likely** that **a** reasonable engineering **assessment** could **be made as** to what actual **cable** pulling conditions and cable constructions represented the most limiting case that would **be** expected to **lead** to cable damage. **As** it **is.** it **seems** unfounded and illogical to **assume** that the test conditions represent the most adverse conditions in the plant.
- **3.** The quick-rise ac breakdown tests used **by** TVA to evaluate possible damage during the SWBP program consisted of a rapid continuous rise
in test voltage until breakdown occurred. However, ac stepped voltage tests having a 5- to 30-minute dwell time at successively higher steps in voltage until breakdown occurs are recognized in insulation science **as** well **as** cable engineering practice **a8smuch** more effective in searching for either manfacturing defects or installation **and** service- incurred **damage.** That is why. for instance, such tests are used in **AEIC** cable qualification tests (not nuclear qualification tests) as cited in their CS5- and CS6-1982 specifications. The distortion or partial disruption of insulation or shield systems due to **excessive** SWIP would **be** best detected **by** extending the time of standard industry **ac step tests.** Using **a** quick-rise test will tend to miss evidence of **damage** observable **by** longer term **ac** overvoltage testing.

The great majority of cable installation pulling **damage soon by** arnd reported to the FRC team members over the years has resulted from cable jamming, combined SWBP and drag around bends due to inadequate lubrication, scuff ing and cutting of cable **by** the conduit after the pull line **had** grooved the inside of conduit bends, saw-through of cable jackets and insulation during puilbys. and pulling cables over sharp or rough **edges at** the and of **a** conduit. Direct **SWOP damage** to cables in well lubricated duct bends or over **large sheaves** has not been **a** source of problems in the FRC team's experience. However, direct SNIP **damage** has been experienced where several small rollers were used in place of **a** large **sheave.** Therefore, the TVA tests for damage to well lubricated cables passing straight over smooth conduit bends represent a search for a damage threshold seldom experienced in practice and that is not representative of the Watts Bar conditions that would **likely** have inflicted damage on cables being installed there.

While the test has **yielded** interesting information on the tolerance of cables to direct radial SNIP, the results are probably qiuite the same **as** would **be** found **by** running cables over sheaves of similar geometry to that of the conduit bends. However, shear forces parallel to the direction of travel in the jacket and insulating material induced **by** high SNIP coupled with signifi cant friction coefficients (less than ideal lubrications **as** probably occurred under the conditions at the Watts **Bar** plant) can **be** expected to induce more and different damage effects than radial forces (SNIP) alone. These shear forces were not evaluated during the **TVA** test program.

9. BEND RADIUS CONCERNS

The recent industry research and development work in connection with cable installation has **focused** on sidewall bearing pressure and pulling tension. No definitive work has been done regarding bending radius because it was assumed that the limitations **of sidewall** bearing pressure dictated generous curves around bends during installation. Manufacturers' literature provides the minimum values for the radii to which Insulated cables **may be** bent for permanent training during installation. However. these limits do not necessarily **apply** to the radii for conduit bends, sheaves, or other curved surfaces around which the **cable** may **be** pulled under tension while being installed. During pulling, larger radii may **be** required to limit sidewall bearing pressure.

Published documentation for **smaller** allowable radii than the generally accepted values., which have been in use for years, is not available. It is known that tighter bends than those recommended by manufacturers have sometimes occurred in actual practice. The problem is to quantify the minimum allowable radius for specific types of **cable** and applications.

9.1 MINIMUM PERMANENT BEND RADIUS FOR 8-kV SHIELDED CABLES

۵

TVA uses 8-kY rated cables in its **5.9-i.V** electrical system. These cables have either crosslinked polyethylene (XPLE) or ethylene propylene rubber insulation over the conductor. The insulation is covered **by** an extruded semiconducting layer, which, in turn, is covered by a spiral-wound, copper**tape** shield or **a set of** spiral copper wires used **as a shield.** The shield is **covered by** the **cable** jacket. The purpose of the semiconduacting layer is to provide **a** means for draining **charges from** the insulation surface to the shield **such that corona discharge does** not occur. Corona discharge can cause insula tion damage **sand** eventual electrical failure. Overbending of **a** shielded. **1-kY** eable can cause **damage** to the Interfaces between the shield and the semicon ducting layer. the semiconducting layer and the insulation, and the insulation and the conductor. Gaps between the shield and the semiconducting layer should not cause any imediate problem since the semiconducting layer will allow charges to drain to the shield material surrounding the **gap.** Long-term deterioration could occur if the conductivity of the semiconducting layer

-30-

changes and it can no longer drain the charges; corona discharges can damage the insulation. Deterioration of the semiconducting layer depends on the conservatism of the cable **design** and the environment of the **cable.** Oil-laden environments will tend to cause dbterioration of the semiconducting layer. it should **be** noted that Yellow-77, which was used in pulling many cables at the Matte Bar plant, contains oil.

Disruptions **of** the interface between the insulation and the semicon ducting layer and between the insulation and the conductor would have **a** more immediate effect since corona discharge would occur immediately. These disruptions could occur from severe bending abuse or from more moderate abuse if the cable were not tightly **made (e.g.,** the semiconducting layer was not tightly' adhered to the insulation).

ł

I.

j

ı

With regard to testing of cable samples to **assess** the effects of cable bending abuse, corona discharge testing should detect the gross effects of dislodging the semiconducting layer from the insulation, and the insulation from the conductor. However. it will not detect the more subtle interruptions between the semiconducting layer and the shield. Therefore. corona discharge testing could be used to detect gross damage, but would not provide assurance that no age-related deterioration will occur. Corona discharge testing equipment is not suitable for in-situ use.

The cables with the highest probability for gross abuse are those Okonite **cables** that **may** have been bent to **a** radius 4.4 times the outside diameter of the cable. Okonite requests that these bends be remade to radii that are 8 times the cable diameter. Corona testing of **a** new Okonite specimen in **a** laboratory could **be** performed to determine **the** initial level of corona dis charge **and** the inception and extinction voltages when the cable was unbent. these parameters at **a** radius smaller than 4.4 times the cable diameter, and the parameters at **a** reformed radius **of I** times that **cable** diameter. **If** significant changes in corona discharge levels or inception and extinction **valtags** occur when the cable is overbent or when it is returned to **a** larger radius, it is indicative of **a** significant level of damage and corrective action should **be** taken (i.e.. replace the cable).

If a significant change in corona does not occur when the cable is overbent or returned to **a** larger radius, it indicates that gross damage did not occur imediately. However, age-related deterioration associated with

-31-

gaps between the shield and the semiconducting layer cannot **be** ruled out. Therefore, TVA should develop **a** program to evaluate all failures of **8-kV** cable when they occur to determine if the failure was associated with overbending and to determine if further corrective action is needed for like cables (i.e., determine the need for replacement of **all** similarly installed cables of the same manufacturer).

9.2 MINIMUM **SEND RADIUS** FOR LOW **VOLTAGE CABLES**

Low voltage cables are most affected **by** failure mechanisms associated with mechanical forces when subject to tight bends rather than **by** the corona discharge phenomenon that affects medium voltage cables. **A** sharp bend in low voltage **cable** puts **a** high compressive stress on the inside of the cable and tensile stress on the outside. In large cables, considerable force is required to sustain these bend stresses. When the forces are exerted on the **cable by** sharp corners of surrounding components, there is a risk of failure through indentation and rupture of the insulation, especially under high temperature conditions. For cables subject to accident environments, the stresses associated with tight bends will increase the probability of failure even when the cable is not restrained **by** sharp corners. The **added** mechanical stresses in the cable insulation from severe bends coupled with the harsh temperature and steam environments will tend to cause insulation failures **as** has been observed by FRC team members who have performed qualification tests.

9.*3 TEMPORARY **BENDS**

The discussions for permanent bends are generally applicable to temporary bends except that the mechanical stresses are relieved. For shielded cables. **6.9-ky** and higher, structural damage incurred **by** temporary sharp bends can **lead** to long-term electrical degradation and random failures. For low voltage **cables** with shields, the largest concern is the possible disruption of the shielding system. causing **a** loss of its effectiveness in controlling electri **cal** noise in the associated circuit.

While manufacturers are reluctant to give general relief for minimum bend radii for medium voltage cable. there is one obvious guideline for temporary bending which many manufacturers have agreed to and use continually. it is

-32-

the ICEA Publication A9-428, **NEMA WC6-1975** CR1980). "Drum Diameters of Reels for Wires and Cables." The H-2 tables of the current ICEA Specifications **S-68-516** Dec. 1914 (for EPR) and **S-66-524** Dec. 1984 (for XLPE) use the same exerpted information from **A9-428.** These guidelines for minimum drum diameters of various **cables imply** cable bending radii of five times the cable outer diameter for **0** to 2000 V, non-shielded cables, either single or multiconductor. **and seven** times **cable** outer diameter for tape-shielded cables over 2000 V. **A** footnote allows the outer diameter to **be** considered that of the shielding tape when it is covered with **a** rubber or plastic jacket. These same standards do impose permanently installed bending radii **as** currently used **by** TVA in **G-38,** R8 for cable training radii except that there is no provision in any **ICEA** standard for using the diameter **of** the insulation of the largest single conductor of **a** multiconductor cable **as a** multiplier.

There are two broad classes of insulation used in these cables: crystalline and amorphous. Polyethylenes are **examples** of the tougher, crystalline type at normal temperatures. whereas the rubber-like ethylene propylene rubbers are amorphous and more compliant. Unfortunately, many blends of materials **fall** in between. **Cable** manufacturers that have suggested relief for temporary TVA bends are those that supply the amorphous material only. The amorphous materials are more forgiving of bending stresses.

Temporary bending radii that are less than the published industry practice for permanent bends should **be** limited to those given **by a** specific manufacturer unless additional data can substantiate **&** lesser value.

9.4 **COMMENTS ON** PROPOSED **RESOLUTION** METHOD **FOR LOW VOLTAGE CABLE BEND** RADIUS **VIOLATIONS F'OR** HARSH ENVIRONMET **CABLE**

The primary concern for low voltage cables that are bent to less than the minimis allowable bend radii of four times the **cable** diameter is failure under accident environment conditions.

During the meeting with **TVA** in Knoxville. TN. on July **17. 1986** and again during the meeting **of** September **25s. 1936** at the Sequoyah plant. **TVA's** consul tant. **X.** Petty. **of** Stone **&** Webster Engineering Corporation. described the propsed method of resolution for bend radius violations for low voltage cable. This method assumes that the minimum bend radius that actually occurred in the Watts Bar plant **is** equivalent to one cable diameter as opposed to the required

-33-

radius of four times the cable diameter. TVA **has** obtained cable specimens that were subjected to a research qualification program. Elongation-at-break data were available for the insulation of the cable following pre-conditioning prior **to** accident condition exposure. TVA **had elongation-at-break tests** performed on the **samples** that had completed the program. TVA proposes to use the elongation-at-break data to evaluate the capability of insulation on a cable bent to a radius of one diameter to withstand an accident environment. The assumption made is that if the insulation is capable, after exposure to an accident condition, of elongation without break to an extent greater than the elongation of the outer surface of the insulation when the cable is bent to a radius one times its diameter, then it could have withstood the accident environment while bent to a radius of one diameter. However, the elongationat-break tests from before and after the accident exposure were performed at room temperature and not at accident simulation environment temperatures. At present, there are no known models for extrapolating the capability of cable insulation to withstand elongation stresses from room temperature conditions to an accident temperature condition while subjected to steam, pressure, and spray. The **modes** of cable failure during LOCA-type **tests** that have been observed **by** members of MR's team suggest that the **added** mechanical stresses from severe bends could substantially contribute to the promotion of failures **even** though the cable materials **were** found to **be** flexible after the test was completed. Therefore, for harsh environments, prudent practice should assure that Class **lE** low voltage cables are not bent beyond the radius recommended **by** the manufacturer.

-34-

10. SUPPORT **OF** VERTICAL **RUNS**

Support of cable in vertical conduit runs is not weil treated in TVA procedures. **So** guidance or concern **wasn** evident in **1979 0o-38** specification, and current TVA standards lack recognition of the extreme duress to cable under tension passing through 90° condulets that are located at or near the top of **a** vertical run. During the second site visit, **a 90*** condulet within containment was observed at the top of **a** vertical **rim** with high tension in the small cables. A 90° condulet was also observed in a horizontal run with high cable tension. Because the inside corners of standard condulets commonly have radii of **1/16** to **1/8** inch. tension in cables passing through the condulets causes potential for severe damage from indentation and cutting of the jacket and insulation. The overall bending radius of the cable in the condulet **may** appear quite reasonable due to the intrinsic stifiness of the cable, but compound flow and cut-through of the insulating material can result at normal ambients. The effect of **a** sudden harsh, high temperature environment may **be** to cause multiple common **mode** failures if many **cables** are in tension where they pass through **90*** condulets.

The vertical support limits of NEC Article **300-19** used **by** TVA in **0-38** R8 Section **3.2.1.9 &asume** adiequate support devices have been used on conduit bends at the top of the run. However. **90*** condulots some distance from the top of **a** vertical run **may** still cause damage to **a cable.** The issue of hori zontal conduit runs' ability to restrain movement and tensions from vertical **runs** is complex and debated in the industry. field reports of **damage** related to vertical runs have dealt primarily with large cables for several reasons. but the engineering principles **are** low n and appear to **be** applicable to **small** cables that are subjected to either thermal cycling or mechanical vibration. **Cables** creep with an effective coefficient of friction near zero when they are subjected to these cyclic stresses. Vertical cable runs try to creep downward and pull on the upper horizontal cable section and push on the lower hori sontal cable segment. Small cables snake in the lower horizontal run and pass the vertical tension through the upper horisontal run for distances beyond those that normal static or moving friction forces would **be** expected to permit. Therefore. tension in and forces acting on the cable at long distances from the top of vertical runs may **be** close to (and. in **some** cases. higher due to

 $-35-$

thermal cycling) the tension at the top of the vertical **run.** At present, **there is a** lack of **agreement** in the industry concerning the horizontal length of the cable that vertical runs influence. However, conservative engineering would certainly dictate that no **90*** conduleft with **sharp** inside corners **be** installed near the top of vertical runs within horizontal **distances** from the top of a vertical that **are as** long **as the** length of the vertical **run** itself. **^A900** condulet **my be** allowed closer to the top of **a** vertical run only if the vertical run is properly supported.

The **900** condulets carrying **cables** under tension represent **a** major poten tial for **damge** to cable in the Watts **Bar** plant, especially in harsh thermal and wet enviroments. Fortunately, the risk can **be** reduced through inspections to **determine** if tension **exists** in **cables** at the point of contact with the **90* condulet corner.** Corrective **measures,** when necessary. **are** often practical **and effective. Unfortunately. the creeping progression** of tension in **the** vicinity of vertical runs occurs over years of operation so that the potential for. **as well as** imdiate **evidence** of. tension should **be assessed** for installations that are a few years old **as** well **as** for **new** installations.

11. OBSERVATIONS OF **CABLE INSTALLATION DURING SITE** VISIT

During the visits to the Watts **Bar** plant **on** July **18, 1986** and September **9** and **10, 1986,** the **MRC** team members inspected terminations, pull **boxes,** and **comaulets** to observe the condition of cables at various points along the con duit runs. During the July **18, 1986** visit, the **FRC** team concentrated **on** 12 conduit **runs** that TVA determined to **be** the worst case with respect to sidewall bearing pressure violations. In addition, manhole No. 22 was inspected because it was specifically addressed in one of the employee concerns as being "interesting." Prior to the September **9** and **10.** i986 plant visit, **FRC** reviewed 82 isometric drawings that **TVA had** used to determine the 12 worst-case conduits. From the **82** isometric drawings, **FRC** determined other conduits that merited inspections because of configuration, cable types. and seeming difficulty **of** the pulls. The team also inspected the second section of manhole 22 and the switchgear terminations of 480-V and **6.9-kV** cables.

Most of the cable in the conduits cannot **be** inspected. However, **by** inspecting both terminations of the cable and any pull points, it might **be** possible to observa gross damage to the cable from pulling. **If** permanent bend radius violation existed, some of these might **be** also be observed. The purpose of the inspections was to **get** an overall feeling of **the** quality of the instal lation and to determine if gross damage had occurred on **a** consistent basis. **Power** (480-V and **6.9-kM).** control, and instrument cables were included in the sample.

š

.,

ù,

ž,

ч

The inspections yieloed **no** significant indications of cable abuse from Wulling at the terminations or aid-conduit **run** pull points that could **be** inspected. Some pull boxes, such **as those** for conduit No. **2PLC2763A,** were located in awkward, congested areas where covers could not **be** removed for inspection. **In** the **case** of one conduit (No. **1PP2188A)** containing shielded, **6.9-kV** cables, **a** straight condulet was opened for inspection. If the conduit was used **as a** pull point. overbending of the cables would have occurred. If it had not been a pull point, the overall cable pull would have included 778° of bends in **60** ft. causing **a** high potential for damage to the cable. Unfor tumately. the condulet was filled with fire stop foam. However, the condulet was also half way filled with water, indicating that condensation could occur in the Watts **Bar** conduits. The termination of the cable associated with this condulet showed **nc signs** of distress to the cable insulation.

-37-

Inspection of the termination of the 480-V power **cable** from conduit lPLC 2940A **at** Cabinet No. **l-3M-2l2-Al-A revealed a concern** not relating to cable pulling or bend radius. The cable from one **phase was** firmly against **a** different **phase** of the bare bus. **A** potential for an eventual **phase-to-phase** fault exists. Figure 1 is **a** picture of **this** configuration.

The site inspections heightened the concern relating to the number of 90° condulets used in the conduit system, especially those used at or near the tops of vertical runs. Figures 2 and **3 show** conditions typical of the concern. Although the radii of the bends of the cables do not exceed the limit for cable bends, the entire weight of the vertical portion of the cable is supported **by** the inside corner of the **900** condulet, causing **a** marked indentation. Under harsh temperature conditions, failure **of** the cable insulation is possible.

۸

ļ

ļ i

ί.

I.

i.

The **6.9-kV** cable terminationsi that were inspected did not show any signs of abuse from pulling or bending. However, at the switchgear end **of** the cables, where the cables entered the tray system. it **was** noted that the permanent bend radius for **a** number of cables appeared to **be** less than the minimum allowed under the TVA specifications. The bends appear to have radii on the order of six times the cable diazmeter. One such bend is shown in Figure 4.

The inspection of manhole 22 identified a number of concerns about the use of good installation practices. Many of the conduits entering the **manhole had** sharp rough **edges.** So bells **had** been installed to support the cable at **these edges. The** cables also ran across the **edges** of the trays with **no support** or padding. Many of the conduits **had** pull **ropes** in them for future use. While it wes **stated** that **these** pull **ropes** had been abandoned, their existence indicated that a large number of pullbys were expected and had occurred. Various views of the conduits and trays in manhole 22 are shown in Figures 5, **6. and 7.** During the July **13** visit, **9.** large figure eight loop of control cable **wns** found hanging over the ladder for the manhole. The full weight of the cable was supported **by** the two **sharp** edges of the ladder support. The cable **had** been pulled into one side of the manhole and it is assumed that the loop of cable would **be** pulled out of the other side of the manhole. 'rhe **cable** could have been carefully laid on top of one of the cable trays rather than looped on the ladder. On the ladder, it was being abused **by** the support points and anyone climbing on the ladder.

-38-

Figure 1. One Phase **of a** 480-V Cable Figure 2. Indented by the Bus of a Different Entering

Phase in Cabinet 1-BD-212-A1-A (at Conduit Phase in Cabinet 1-BD-212-Al-A (at (at intersection of arrows)

Figure 2. T Condulet with Cables Entering a Vertical Section of

Figure **3. 90*** Condulet at the Top of **a** Vertical Run Showing the Corner Supporting the Cable

Figure 4. Medium Voltage Cable Bend Radius of Approximately 6 Times the Cable Diameter

Figure **5.** view of Manhole 22 Showing Pull Ropes (Originally Installed for Future Use) Wrapped Around **a** Cable and Unsupported Cable Resting on **a** Sharp Conduit Edge

Figure **6.** View of Manhole 22 Showing Mixes of Cable Constructions Pulled in the Same Conduits

Figure **7.** View of Manhole 22 Showing Mixes of Cable Constructions in the Same Conduits and Additional Pull Ropes

12. FFECTS OF **CABLE INSWALLATION DAMAGE AND** EXCESSIVE **BENDS** ON FUNCTIONAL CAPABILITY

12.1 **JAMCET AND INSULATION** MATERIAL CUTTING. **TEARING. AND** SAWING DURING INSTALLATION

As described **in** previous sections, numerous conditions during installa tion can **lead** to cutting, tearing, and sawing damage of **cable** jacket and insulation materials. During pullbys, the moving cable and pull rope will tend to saw through **the** stationary cables if the moving cable **crosses the** stationary cable at a bend. When **mixes** of types and **sizes** of cables **are** pulled, smaller, softer cables **may** cross under the bulk of the cables **and be** crushed and torn **as** they **pass** around bends. When three or four cables **are** pulled into conduits where jaming is possible **(see** Section **7), a** full jam will break the pull rope or the cable, and **the** cable will **be** removed and the conduit will **be** reworked. However, the higher concern is when cables **just** begin to **jam,** and the insulation **and** jacket **are** subjected to shear **stresses** that can tear them. For most **cases,** damage from sidewall bearing pressure **by** itself is not of high probability. The EPRI **EL-3333** study **[111** and the TVA study [1]* indicate that the cables can withstand much higher sidewall bearing pressures than originally specified **by** manufacturers. However, sidewall bearing pressure would **be** of high concern if cables were pulled over the sharp inside corners of **90*** condulets. While it is hoped that such a condition did not occur, the large **number** of **90*** condulets used and the method of helping **^a** cable along **(sae** Section 4.3) through condulets indicates that some cables could have been pulled under **high** tension around the sharp corners of **90' condulets.**

ļ

ſ

Of the pulling conditions that **may** lead to imediate insulation **damage,** jaming of the **cables** is of highest **concern** for medium voltage **(6.9-kV)** cables at **the** Watts Bar plant. Kedium voltage cables **are** comprised of three single conductor cables at the Watts Bar plant. **One** three-phase circuit is allowed in **a** duct. This limitation eliminates the concern for pullbys and for mixed

-41-

^{*}Although this Technical Evaluation Report finds problems with the applica bility of the **TVA** study to plant conditions, **it** does not disagree with the basic results.

cable pulls. Since very **few go*** condulets **were** installed in medium voltage **cable** conduits, the concern-"or pulling the **cable** through such condulets is greatly reduced.

The damage to medium voltage cable from partial jamming will most probably **cause** disruptions between the shield and the insulation and between the con ductor and the insulation. Such disruptions will **cause** voids or discontinui ties in potential gradients. leading to corona discharges that could **cause** failure of **the** insulation. The condition would **lead** to significant degradation only in cables that **are** energized most of the time and would result in random failures rather than common **mode** failures. Such failures would tend to reduce the overall reliability of the electrical system.

Pullbys and mixed pulls would not **be** of concern for low voltage power cable of sizes greater than **8** AWG, which were also routed in individual conduits in groups of three single conductors. The effects of partial jamming **and** pulling cable around condulet corners would **be** the **same as** those for low voltage control and instrumentation cable noted below.

For low voltage control and instrumentation cables (up to 480 V). all of the conditions leading to cutting, tearing, and sawing **apply.** At low voltage levels, nearly or completely penetrated jackets and insulations could exist in dry conduits without electrical failure under normal plant conditions. Dry air is **a** good insulator and pierced insulation may not **be** distinguishable from perfect insulation under most available electrical **tests** for unshielded cables.

The key concerns relating to cutting, tearing, and sawing of low voltage power, instrumentation, and control cable **are** accident environments and moisture. Moisture accumulation can occur due to condensation under normal **power** plant conditions. **One** duct **was** found to be wet during the second site visit. With cuts or **tears** in the insulation, water would provide an electrical path between the conductors or between a conductor and the **steel** conduit. Under normal conditions, such failures would tend to **be** random rather than common **mode** since many conduits would not become moist **at** the **same** time. However, under accident temperature and steam conditions, electrical failures **associated** with previously undetected cuts and tears of insulation would represent a common mode failure mechanism and could affect the operation of a significant **amount** of equipment.

-42-

12.2 **DCCESSIVE SDWING OF CABLE**

12.2.1 Medium Voltage **Cable** Bending

Excessive bending of medium voltage cable can also disrupt the continuity of **the interfaces between the shield** and **the** insulation **and between the** insulation and the conductors. The disruption can **lead** to corona discharge and possible long-term failure. Such failures **are** of **a** higher probability in **cables** with crosslinked polyethylene insulation **since the** insulation is more susceptible to corona attack than is **ethylene propylene** rubber. **TVA** has **a** number of different types of medium voltage crosslinked polyethylene cable in **use at** the Watts Bar plant. With regard to temporary bending **of** the cable, some relief **my be assumed based** upon allowable real drum size contained in **TCZA** Standards **S-68-516** and **S-66-524** that allow **a reel** drum radius of seven times the cable shield diameter. However, case-by-case relief from standard permanent **bend** limits must **coam** from the manufacturer of the cable.

12.2.2 Low Voltage **Cable Beanding**

n

The primary concern for low voltage cable bent to **a** very tight radius (i.e., **a** radius of one diameter versus the recomended minimum of four times the diameter) is failure under harsh temperature **and** steam environments. **Under** normal plant environments, sharp bends in the cable should not cause sufficient tensile or compressive stress to cause mechanical failure of the **cable** coverings. However, under accident conditions, the behavior of the cable when bent to **a** radius of one to four diameters is not **known.** Mechanical failure of the jacket and insulation followed **by** electrical failure **my** occur.

12.3 SUPPORT **OF CABLES UNDER** TENSION **BY SMALL SURFACE AREAS**

The inside corners of **900** condulets provide **a** very **small** supporting **surface** to cables that **pass** over them. **If** the cable is **under** tension, the corner will **tend** to indent and cut the insulation and the conductors of **some cabae** will tend to creep through the insulation. The tension in the **cable may** result from the weight of long vertical runs of cable if the 90° condulet is located at or near the top of the run or it **may** result from residual pulling tension in constrained cables. NUREG/CR-4548 (121 provides some insight for ethylene propylene cables witn Hypalon jackets under such conditions and indicates that creep-through of the conductor would not **be** expected for **a**

-43-

period **of 5 years.** Rigorous extrapolation beyond **5 years** cannot *be made.* However, for accident conditions, creep-through or mechanical cracking followed **by** electrical shorting could **be** expected. The report recommends that cables **be** provided with large radius supports or **stress** relief. The report provides no information for other cable constructions. Published information indicates that crosslinked polyethylene and plastic insulations and jackets are more susceptible to mechanical deformation when subjected to temperatures greater than 100°C. The deformation properties of silicone rubber tend to be **less** dependent upon temperature, but depending on the specific compound **used may be** much more prone to creep than **are** ethylene propylene rubber insula tions. Therefore, crosslinked polyethylene. plastic, and silicone rubber insulated and jacketed cables subject to high temperature accident conditions should not **be** subjected to high mechanical stresses such **as** those resulting from cable tension at the corners of 90° condulets.

ì

13. TVA MONITORING PROGRAMS FOR **INSTALLED CABLES**

In Reference 2, TVA listed two types of planned monitoring of the installed **cables** at the Watts Bar plant. Periodic electrical testing will **be** performed on the cables of medium voltage motors and lowi voltage motors of **¹⁰⁰ hp** and greater. The type of testing is not described. The testing is **TVA's** standard practice and **has** not been initiated because of **cable** installation concerns. Although **a good** practice, electrical testing will probably not detect the types of damage or deterioration modes expected. Furthermore, no testing of low power, low voltage circuits is planned.

The second type of monitoring is **a** trend analysis program to track, consolidate, and categorize conditions **adverse** to quality. Such monitoring will **be** implemented at the Watts har plant **by** November **1996.** The trend analysis program will **be** used to identify trends **associated** with cabling **at** any TVA nuclear plant. The details of the **types** of parameters to **be** monitored **by** the program and the types of trends to **be** analysed **were** not provided **by TVA.**

ì

L

14. **CONCLUSIONS**

Evaluation of the **cable** pulling and bending practices at the Watts Bar plant reduced the concern for **some** types of potential problems and heightened the concern for others. The following summarizes the conclusions relating to each significant concern.

1. Standards **and Procedures**

Revision 2 of **G-38,** the controlling **standard** during the bulk of the cable pulling, did not reflect the state of knowledge in the industry at that time. Support of cables in vertical runs, control of pullbys, **and** prevention of jamming **are** not covered. Tension control limits for sidewall bearing pressure are not **labeled as** such and are described **as** alternate limits rather than limits that must be met simultaneously with the limit for cable stretching.

Revision S of **G-38,** the present version, rectifies many of the omissions from Revision 2. but **may be** confusing to the intended users **since** it contains a mix of practical statements and theory. While pullbys; are **addressed,** the requirements for their control **are** very weak. Support of **cable** in vertical runs when **90*** condulets **are** used near but not at the top of the run is not addressed nor is control of jamming of cables during pulling.

2. Pulling Practices

The procedures and controls in place during most of the conduit construction and cable pulling placed the bulk **of** the responsibility for the details on the electricians performing the work. The electricians and their foreman **chose** the routing, locations of pull points, and the types of pull points to **be** used. The cable installations were not engineered. Tension and sidewall bearing pressure calculations were not required at the time of the bulk of the **cable** pulling.

3. Calculation of Sidewall Bearing Pressure

The calculations performed in **1985** to determine the worst-case conduit runs did not take into account the type of lubricant used from **1976** to 1982, nor did they account for the lack of independence between pull segments **as** described **by** the electricians on September **9. 1936.** If the electricians **"helped"** the **cable** along at pull points rather than pulling the cable out of and then back into **a** pull point, the tensions between segments **are** not independent. Therefore, the calculations are not fully representative of the actual conditions. For such back calculations where there are many unknowns regarding lubrication methods. **a** coefficient of friction of **0.6** to **0.7** is suggested. For pullbys, an even higher coefficient, such **as 1.0,** should be used.

4. Sidewall Bearing pressure Damage

Based on the results of the TVA SWEP tests and those documented in EPRI **EL-3333,** SWBP damage is not considered to have been **a** signi ficant concern except for the **cases** wh.tre cable **was** pulled around the corner of **90*** condulets or through flexible conduits having tight bends. The number of 90° condulets and the described method of helping cables through pull points causes **a** concern to remain that some cables were pulled through 90° condulets and may have been damaged.

5. Pullby Damage

Pullbys did not occur on medium voltage and large-conductor, low voltage power cable. However. **a** large number of pullbys did occur on control and instrumentation cable runs. There is a great concern that the moving pull rope and cable could have **sawed** through insula tion of the stationary cables, causing the potential for circuit failure during conditions where the conduit is wet or exposed to high temperatures. Normal condensation in the conduits is expected to cause random failures. An accident condition could produce multiple common mode failures.

6. Jamming Damage

I

TVA's procedures contain no limits relating to prevention of jamming damage. While full jamming would break the pull rope or the cable being pulled, the higher concern is for cable that partially jams and pulls free. Tearing of the insulation and disruption of the interface between the shield and conductor interfaces with the insulation are of concern. The cables that **are** of highest concern **are** power cables that are pulled in groups of three and **are** prone to jamming.

7. Permanent Bending Damage and Stresses

For medium voltage cable, TVA is verifying the permanent bend radius of the cables and, where violations exist, restoring the cable to an appropriate radius.

For low voltage cable, TVA is attempting to show that the accident withstand capability of **a** cable will not **be** affected **by** bending it to **a** radius of one times its diameter. As described in Section 9.4 of this report, there is no available extrapolation technique for concluding that the cable's capability after an accident simulation can **be** used to show the cable's ability to withstand stress under the accident environment.

8. Support of Cables Under Tension in **90*** Condulets

Cables in **90*** condulets **at** or near the top of vertical runs may be supported **by** the sharp corner of the condulet. Random failures due to cutting of the insulation and conductor creep may occur during normal service, and multiple failures can be expected in accident conditions.

overall Conclusion

ţ.

i

ţ

In general. the evaluation of the Watts Bar cable installations indicated that the system was installed in **& less** orderly fashion than would **be** expected for **a** nuclear power plant. Although no outright cable damage **was** found, the controls on the installation process were such that damage could **have** occurred from jamming, pullbys, severe hending, and tension through 90° condulets. Long-term random and accident-related common mode failures are possible for these types of damage. Further testing and evaluation of a sample of cables in conduits where pullbys occurred, and where jamming may have occurred, is necessary to assure that significant damage **has** not occurred. **If** the evalua tion of the cables indicates that damage was significant, replacement of cables installed under similar conditions will **be** necessary.

15. RECOMMENIDATIONS

These recommendations are based on the conclusions contained in Section 14. The purpose of the recommendations is twofold. For **those types of** damage that **are** observable through testing **and** inspection, the **purpose is** to gain further **assurance** that installation **abuse** did not **lead** to significant amounts of damage. For those types of damage that **are more subtle and** could **lead** to age-related failures, the purpose is to prevent multiple failures **by** evaluating each individual failure to determine the cause and taking corrective action for **all** cables that are similar and have been similarly installed. The following recommendations are made to assure adequate reliability of the cable **system.**

1. MonitorinQ of Cable Failures

A prime recommendation resulting from the evaluation is that **each** cable failure that occurs **at** the Watts Bar plant in or near **a** conduit bend or sharp cable bend should **be** evaluated to determine the cause of the failure. If the failure is the result of cable pulling damage, the cables of the same type that were installed under similar conditions should **be** evaluated for replacement.

With regard to implementation of **a** cable deterioration trend analysis system at the Watts Bar plant, it is recommended that TVA treat each cable failure **as** being highly important until it canl **be** proven that the failure is not related to cable pulling or bending and does not indicate that the other cables in the plant **are** prone to the same mode of failure. The program should include **a** commitment to prompt corrective action for similar cable installations if the cause of failure is found to **be** related to installation **abuse.**

2. 90° Condulets and Vertical Runs

With regard to 90° condulets at or near the top of vertical conduits, installation **of** appropriate cable supports is necessary. The techniques described in Section **3.2.1.9** of **G-38** R8 **are** appropriate. For silicon rubber insulated cables, the worst-case conduit with **a** vertical cable run supported **by a 90'** corner of **a** condulet should **be** electrically tested via **a** dc high potential test to determine if insulation failure due to installation damage or conductor creep is **a** significant concern. If no electrical failure occurs, the cable should **be** resupported. If electrical failure does occur, the cable should be replaced and **a** further sample of worst-case should **be** tested to determine the scope of the problem.

3. Puilbys

To **evaluate the degree** of damage that occurred from puilbys, TVA should **analyze the** known puilbys to identify **the** conduit **having the highest susceptibility** to **cable sawing damage** during the puliby, **and remove the** cable from that conduit for inspection and testing to **reveal any presently** hidden **damage. If** significant damage **is** found in this cable, **a** commitment to appropriate remedial actions for cables in other conduits with pullbys is necessary.

4. Small Send Radii for Low Voltage Cable

TVA must take appropriate action, such **as** testing, to assure that low voltage power, control, and instrument cables that are bent to radii smaller than four times the cable diameter will not be subject to common mode failures when subjected to accident and post-accident environments.

5. Small Bend Radii for Medium Voltage Cable

TVA must determine those **S-kV** shielded power cables that are bent to radii smaller than those presently recommnended **by** the manufacturers of the cables and take action to assure that the cables will not **be** subject to long-term degradation that could interfere with the reliability of the **cables. A** possible means for detecting long-term degradation is periodic dc high potential testing of **a** sample of cables that had the worst-case bends.

6. Jamming

TVA must **evaluate** conduits containing **three** or four **cables whose diameters** when compared to those of the conduits could lead to jamming. For those conduits where janmming and partial jamming could have occurred, TVA must take further action to **assure** that significant damage has not occurred to the cable such that the cable's reliability is reduced or common mode failures could occur when the cables are subject to harsh (wet) environ ments. **One** possible means of providing such assurance is to remove cable from a conduit where a high probability for jamming would have been expected and to perform detailed electrical testing and physical evaluation.

7. Pulling Through 90° Condulets and Flexible Conduit

TVA must make **a** survey and **assessment** of flexible conduits with **a** signi ficant offset or **angle** of bend and of **90*** condulets to determine those that **were likely** to have **had cables** pulled through them under mechanical **assistance (e.g..** capstans. come-alongs). If such conditions **are** found.

a diagnostic and remedial program must be performed to determine the extent of the damage and to remove cables with significant levels of damage from service.

8. Revision of General Construction Specifications

ı

i

TVA should revise General Construction Specifications G-38 and G-40 to eliminate omissions and to remove unnecessary complexities and noncor servative elements. The revision should include discussions of jamning and of limiting tension with respect to SWBP. Limitations should **be** placed on **use** of **90*** condulets at or near the top of vertical conduit runs. Clear guidance on limiting pullbys and providing tighter control of pulls when pullbys must **be** performed should also **be** included. Controls on the use of **all** types of condulets in conduits should also **be** added for medium voltage cable and, to the extent necessary, for large low voltage cables to prevent abuse from bending during pulling.

16. REFERENCES

- **I.** Letter from **W. S.** Raughley (TVA) to **G.** Toman (FRC) dated July **10, 1986** forwarding an advance copy of the TVA report. **"Cable** Sidewall Bearing Pressure Tests." dated **May 30. 1986**
- 2. Letter from R. L. Gridley (TVA) to Mr. B. **J.** Youngblood (NRC) dated October **7, 1986.** which responded to **16** NRC questions relating to cable pulling **issues**
- **3.** TVA Division of Engineering Design. General Construction Specification No. **G-38,** "Installing Insulated Cables Rated **Up** to **¹⁵⁰⁰⁰**Volts Inclusive," Revision 2. August **3. 1978**
- 4. TVA Office of Engineering General Construction Specification No. **G-38.** "Installing Cables Rated **Up** to **15000** Volts," Revision **8.** March **17, 1986**

ŧ

I

ł

ţ \mathbf{r}

Г.

ļ

L

- **5.** Watts Bar Nuclear Plant, Modifications and Additions Instruction. **MAI-3.** "Installation and Inspection of Insulated Control, Signal, and Power Cables Units 1 and 2," Revision 6, January 15, 1986
- **6.** Watts Bar Nuclear Plant. Modifications and Additions Instruction, MAI-3. "Installation and Inspection of **Cable** Terminations," Revision 4. June **27, 1986**
- **7.** Watts har Nuclear Plant. Modifications and Additions Instruction, MMI-13, "Installation **of** Conduit and Junction **Boxes,** Revision **3.** September **5. 1986**
- 8. Internal TVA Memorandum from W. S. Raughley dated September 2. 1986. Subject: TVA Memorandum from **W. S.** Raughley dated September 2. **1986, "All** Nuclear Plants **-** Electrical Issues **- Class 1E Cable** Bend Radii. **"** (Forwarded **as** an Enclosure to Reference 2 above)
- **9.** Internal TVA Memorandum from W. **S.** Raughley dated July **16, 1986** Subject: **All** Nuclear Plants **-** Electrical **Issues -** Support of Cables in Vertical Conduits." (Forwarded **as an enclosure** to Reference 2 above).
- **10. G. C.** Weitz, 'Coefficient of Friction Measurement Between **Cable** Conduit Surfaces Under Varing Normal Loads," **IEEE** 84 T&D **375-2,** of Electrical and Electronic Engineers, New York. 1984 **and Institute**
- 11. D. A. Silver. G. W. Semon. L. R. Bush. "Maximum Safe Pulling Lengths for Solid Dielectric Insulated Cables." EPRI EL-3333. Electric Power Research Institute. Palo Alto. CA. February 1984
- 12. **M.** Steutzer. "Correlation of Electrical Reactor **Cable** Failures with Material Degradation." NUREG/CR-4548. U.S. Nuclear Regulatory Commission. Washington. **DC,** March **1986**

APPENDIX A

u
U

i.

 \mathbf{f} Ť.

Ł

Ì

SUMMARIES OF TVA EMPLOYEE CONCERNS RELATING TO CABLE PULLING AND **BEND** RADII

PRANKUN RESEARCH CENTER

DIVISION OF ARVIN/CALSPAN
20th & RACE STREETS, PHILADELPHIA, PA-19103

SUBBAY OF ENR.OYEE CONCERNS **PULLING PROCEDURES**

 E

SLIGHARY

1N-85-018-004

SURERVISOR MOLLD NOT FOLLOW CABLE RULING PROCEDURES (NORKED WITHOUT PERMITS).

IN-85-213-001

CONLING PULLING PROCEDURES NERE CHANGED AROUND 1981. ITEMS SUCH AS PULL TENSION NERE MODIFIED.

IN-85-295-003

CABLE RULLS LERE PERFORMED IN A "RUSHED" **NOVER. CABLES WHICH HERE PULLED** UNDER THE OLD "UNCONTROLLED" PROCEDURES MERE POSSIBLY NOT REDIEDKED.

IN-85-856-005

ŗ

Ī

THE PRACTICE TO USING BREAK ROPES WHEN PULLING CABLES DID NOT BECOME EFFECTIVE UNTIL 1984. ALL THE "BIS" PULLS OCCURED 3+YEARS ABO WITHOUT BREAK ROPE.

IN-85-935-001

70% TO 75% OF THE INSTALLED CABLE IS BAD AND SHOULD BE REPLACED. CABLE WAS NOT PULLED IN ACCORDANCE WITH PROCEDURES; BEND RADIUS MAS VIOLATED AND CABLE MAS NOT PROTECTED.

CABLES RULL ARE NOT ALWAYS PERFORMED TO THE REQUIREMENTS OF ACI. BREAK LINKS HERE NOT USED DURING CABLES PULLS.

SUNNAY OF ENALOYEE CONCERNS **PULLING PROCEDURES**

 E

ò.

I.

ţ ł

 \vert

4

Ţ L.

ſ ł

> \mathbf{r} ì

l

IN-86-254-001

BLETRICAL CABLES PULLED BY TRUCK OR

SUNARY

OT TP HEAVS NOT ALLOWED BY PROCEDURE.

--

IN-86-259-014

CABLE BROKE DUE TO IMPROPER PULLING RETHODS. CABLE WAS THEN SPLICED AND RULLED INTO CONDUIT.

IN-86-314-001

COMMON PRACTICE TO UTILIZE IMPROPER CABLE PULLING TECHNIQUES (WINCHES AND HAND) CONE-RLONGS).

SUNNAY OF ENPLOYEE CONCERNS **OVERFILLED CONDUITS**

 E

 $\ddot{}$

 \mathbf{L}

 $\overline{\mathbf{I}}$

ţ ì

 $\begin{array}{c} \vspace{2mm} \begin{array}{c} \vspace{2mm} \begin{array}{c} \vspace{2mm} \begin{array}{c} \vspace{2mm} \end{array} \end{array} \end{array} \end{array} \end{array}$

 \bar{t} $\mathfrak l$

 Γ

 $\prod_{i=1}^{n}$

 \mathcal{L} i

ļ

IN-85-255-001

SUNNAY

CONDUITS ARE OVERFILLED AND CABLES HAY HAVE BEEN DANGED. HAXINUM TENSION FOR PULLING CABLE MAS EXCEEDED.

IN-85-436-004

CONDUIT OVERFILLED. PULL TENSION MAS NOT NONITORED.

SUMMY OF BIA.OYEE CONCERNS 90 CONDULETS

 \mathbf{r}

 \mathbf{t}

Ŧ ł.

 \mathbf{f}

ł

ĭ İ.

17 Ĺ.

 $\prod_{i=1}^{n}$

 $\overline{1}$ E

BURGAY

EX-85-157-002

LL AND LR CONDOLETTE FITTINGS CAUSE TOO BREAT A BEND FOR THE CABLES.

SUMMAY OF ENPLOYEE CONCERNS **BEIG BADII**

 \mathbf{E}

EX-85-073-001

SUNGRY

CABLE BEID RADIUS HUST HAVE BEEN VIOLATED. IN CORE INSTRUENT ROOK. CABLES HERE SPLICED THEN STUFFED INSIDE THE **FITTING.**

IN-85-719-002

ELECTRICAL CABLES EXIT CABLE TRAY OVER A SHAP EDGE INTO A PENETRATION. THESE DRILES NAY ALSO VIOLATE KININUM SEND REQUIREMENTS.

IN-85-935-001

70% TO 75% OF THE INSTALLED CAPLE IS DAD AND SHOLD BE REPLACED. CABLE MAS **NOT PULLED IN RCCORDINGE WITH** PROCEDURES; BEND SOBIUS MAS VIOLATED AND CABLE WAS NOT PROTECTED.

WI-85-100-013

Ù,

Ï

 $\frac{1}{4}$

 \cdot ¥ CABLE BENDING RADII PROBLENS.

SUBVARY OF ENPLOYEE CONCERNS **KISCELLANEDUS**

E

UI-85-100-020

SUMARY

EXTREMELY BRD CARLE PROCTICES. CARLING IS ROUTED OUTSIDE TRAYS, COILED ON TRAY SUPPORTS OR FLOORS, TIED ON SIDES OF TRAYS AND SUPPORTS, AND TIED ON THE **ROTTOM OF TRAYS. WIRES BENT 90 DEBREES** INTO CONDUIT. PLASTIC CONDUIT DRIDGES BETWEEN CABLE TRAYS.

SURGRY OF ENR.OYEE CONCERNS UN-"SWEED" COLOUITS

 $E₀$

IN-85-425-004

SUNNAY

CONDUITS NOT SHABBED PRICK TO CABLE **RULING.**

IN-85-581-001

ü

 $\overline{}$

LARGE QUITITIES OF DROWICS WITER, RODK+GRAVEL IN CONDUITS. CONDUIT NOT **BURBED.**

SURVAY OF BIRLOVEE CONCERNS **PULI - BYS**

 E

 $IN-85-314-001$

SUMMY

DRILE IS PULLED DIE AT A TIME AND THEREFORE THE TENSION EXCEEDS THE NAXIMUM WELLE BLE TO TANGLING IN UNIT 2.

SUNNAY OF ENRLOYEE CONCERNS UICONTROLLED TENSION

 $\lambda_{\rm{max}}$ ۸

 $\ddot{\cdot}$

 $\ddot{}$

IN-25-005

NUMEROUS NON-SPECIFIC INSTANCES KERE WELATED REGARDING OVERSTRESS OF CABLE QURING PULLING OPERATIONS. SUFFICIENT SEVERITY TO CAUSE MULTIPLE INSTANCES OF 1 INCH MANILA BREAKING.

 $\ddot{}$

SUNNAY OF ENR.OYEE CONCERNS UNCONTROLLED TENSION

2003년 12월 20일
대한민국의 대한민국의 대
대한민국의 대한민국의 대

 \cdot \blacksquare

 \mathbf{i}

 $\mathbf i$

I $\pmb{\cdot}$

 $\ddot{\cdot}$ \mathbf{i}

 $\frac{1}{2}$ \mathbf{I} .

 \mathbf{I} .

l

 \downarrow

 $IN-85-978-001$

CABLES WERE PULLED USING CHERRY-PICKER **CRANES AND MACK TRUCKS.**

SUNNAY OF BIRLOYEE CONCERNS UICONTROLLED TENSION

52

ばら
きょん

٠

 \ddot{i}

ļ $\mathbf i$

l

 $\begin{bmatrix} 1 \\ 1 \end{bmatrix}$

 $\pmb{\cdot}$ $\ddot{\cdot}$

 \mathbf{f} \mathbf{l} .

 $\overline{1}$

ļ $\ddot{\mathbf{t}}$

 $\overline{\mathbf{I}}$

 \cdot

 \sim

 $1N-86-254-002$

cable break links here not used prior to 1984. CABLE NAY HAVE BEEN DANGED.

SUMMAY OF ENALOYEE CONCERNS UICONTROLLED TENSION

grennam (1969).
Fr

Ă.

IN-86-266-001

CABLE PULLING HAS BEEN ACCOMPLISHED BY TRUCKS AND WINCHES.

SURRAY OF ENPLOYEE CONCERNS UCONTROLLED TENSION

 \mathbf{E}

경찰

 $\ddot{\bullet}$

ſľ

I $\left| \cdot \right|$

DH-86-256-002

HANY CABLES HERE RULLED WITHOUT USING FUBE LINKS.

SUNGRY

 $IN-86-314-001$

COMON PRACTICE TO UTILIZE IMPROPER CIBLE PILLING TECHNIQUES (WINCHES AND HAND CDIE-ALDIES),