



Vermont Yankee
Cooling Tower
Update

October 14, 2008

■ ML083380490

Agenda

- **Introductions**
- **Basic Plant Overview**
- **Cooling Tower Overview**
 - **Normal Cooling Function**
 - **Safety Function**

- **Cooling Tower Events**
 - **Three Events**
 - August 2007
 - July 2008
 - September 2008
 - **Event Causes and Corrective Actions**
 - **Event Summary**


- **Long Range Planning**


Introductions

Introductions

- **Ted Sullivan, Entergy Site Vice President**
- **Chris Wamser, Gen. Manager Plant Operations**
- **John Dreyfuss, Director, Nuclear Safety Assurance**
- **Norm Rademacher, Director of Engineering**

Basic Plant Operation





Functions of the Cooling Towers ■



Cooling Tower Functions

- **Normal Cooling Function**
- **Safety Function**

Cooling Function

Cooling Function

- **Purpose**
- **Modes of Operation**
- **Design Overview**
- **Design Features**

Cooling Function - Purpose

- **Cool River Water prior to return to Connecticut River**
- **Maintain Environmental Conditions for river**
- **NPDES Thermal Discharge Permit**


Cooling Water

Modes of Operation


Cooling Water Modes

- **Open**
- **Closed**

Open Cycle



Closed Cycle




Modes of Operation - Summary

- **Cooling Tower operation is dictated by River Conditions**
 - **Season**
 - **River Flow**
 - **River Temperature**


Cooling Tower Design

Cooling Tower Design





WATER VAPOR HEAT REJECTED




- 1 Longitudinal Wind Baffle
- 2 Plenum Walkway
- 3 Drift Eliminators
- 4 Fill Area Outline
- 5 Transverse Partition Wall
- 6 Cold Water Basin
- 7 Louvered Wall
- 8 Optional Enclosures for Extended Fan Deck
- 9 Access Hatch
- 10 Fiberglass Flow Control Valve
- 11 Fiberglass Manifold
- 12 Oil Drain Line
- 13 Access Ladder (Typical)
- 14 Oil Fill and Sight Gauge
- 15 Pillow Block
- 16 Fiberglass Air Seal
- 17 Fiberglass Fan
- 18 Fiberglass Fan Stack
- 19 Plenum Air Seal
- 20 Safety Handrail
- 21 Inlet Flange (Not Shown)
- 22 Cased End Wall

**AIR
FLOW**

[go to page 25](#)







[Back to pg. 21](#)



[Back to pg. 21](#)

Cooling Tower Design Features

Design Features

- **Two 500' Long Towers**
 - **Tower 1 (East)**
 - **Tower 2 (West)**
- **11 Cells per Tower**
- **Each Cell has one fan and motor**
- **Water distribution system**



Design Features – Water Distribution

- **Two Distribution Headers per Tower**
- **90,000 GPM each**
- **Multiple Sections, “Bell and Spigot”
Joint Design**
- **Pipe Size Varies: 60” to 24”**
- **Water Deck / Distribution Valves**
- **Fill Material**





[Back to pg. 28](#)



[Back to pg. 28](#)

Design Features – Structural Support

- **Loads:**

- **Water (primary)**

- **Fan/motor (secondary)**

- **Saddle Configuration – HOLDS UP PIPE**

- **Columns – support water and fans**

- **Joints**





[Back to pg. 32](#)

Safety Function

Safety Function

- **Safety Related Cell 2-1**
- **Seismic Qualification Cell 2-2**
- **Alternate Cooling – Loss of Intake**
- **Independent from normal Cooling Function**


Seismic Design

Safety-related





Safety Related Cell CT2-1 Provides Backup Source of Cooling



Independent Safety Piping



Cooling Tower Events

Cooling Tower Events

- **August 2007: Cell 2-4 Failure**
- **July 2008: Support Saddle Failures**
- **September 2008: Distribution Header Leak**

Cell 2-4 Failure August 2007


Cell 2-4 Failure

- **Causes of Event**
- **Corrective Actions**


Cell 2-4 Failure – Cause of Event

- Two support columns failed
- Failure of B Columns caused Distribution Header to sag
 - Loosened slip joints and caused large leaks
- Additional water increased weight on remaining support columns
- Other Support columns overloaded and failed
- Resulted in a partial collapse







- 1 Longitudinal Wind Baffle
- 2 Plenum Walkway
- 3 Drift Eliminators
- 4 Fill Area Outline
- 5 Transverse Partition Wall
- 6 Cold Water Basin
- 7 Louvered Wall
- 8 Optional Enclosures for Extended Fan Deck
- 9 Access Hatch
- 10 Fiberglass Flow Control Valve
- 11 Fiberglass Manifold
- 12 Oil Drain Line
- 13 Access Ladder (Typical)
- 14 Oil Fill and Sight Gauge
- 15 Pillow Block
- 16 Fiberglass Air Seal
- 17 Fiberglass Fan
- 18 Fiberglass Fan Stack
- 19 Plenum Air Seal
- 20 Safety Handrail
- 21 Inlet Flange (Not Shown)
- 22 Cased End Wall



- 1 Longitudinal Wind Baffle
- 2 Plenum Walkway
- 3 Drift Eliminators
- 4 Fill Area Outline
- 5 Transverse Partition Wall
- 6 Cold Water Basin
- 7 Louvered Wall
- 8 Optional Enclosures for Extended Fan Deck
- 9 Access Hatch
- 10 Fiberglass Flow Control Valve
- 11 Fiberglass Manifold
- 12 Oil Drain Line
- 13 Access Ladder (Typical)
- 14 Oil Fill and Sight Gauge
- 15 Pillow Block
- 16 Fiberglass Air Seal
- 17 Fiberglass Fan
- 18 Fiberglass Fan Stack
- 19 Plenum Air Seal
- 20 Safety Handrail
- 21 Inlet Flange (Not Shown)
- 22 Cased End Wall



- 1 Longitudinal Wind Baffle
- 2 Plenum Walkway
- 3 Drift Eliminators
- 4 Fill Area Outline
- 5 Transverse Partition Wall
- 6 Cold Water Basin
- 7 Louvered Wall
- 8 Optional Enclosures for Extended Fan Deck
- 9 Access Hatch
- 10 Fiberglass Flow Control Valve
- 11 Fiberglass Manifold
- 12 Oil Drain Line
- 13 Access Ladder (Typical)
- 14 Oil Fill and Sight Gauge
- 15 Pillow Block
- 16 Fiberglass Air Seal
- 17 Fiberglass Fan
- 18 Fiberglass Fan Stack
- 19 Plenum Air Seal
- 20 Safety Handrail
- 21 Inlet Flange (Not Shown)
- 22 Cased End Wall




- 1 Longitudinal Wind Baffle
- 2 Plenum Walkway
- 3 Drift Eliminators
- 4 Fill Area Outline
- 5 Transverse Partition Wall
- 6 Cold Water Basin
- 7 Louvered Wall
- 8 Optional Enclosures for Extended Fan Deck
- 9 Access Hatch
- 10 Fiberglass Flow Control Valve
- 11 Fiberglass Manifold
- 12 Oil Drain Line
- 13 Access Ladder (Typical)
- 14 Oil Fill and Sight Gauge
- 15 Pillow Block
- 16 Fiberglass Air Seal
- 17 Fiberglass Fan
- 18 Fiberglass Fan Stack
- 19 Plenum Air Seal
- 20 Safety Handrail
- 21 Inlet Flange (Not Shown)
- 22 Cased End Wall

A


B

C


S




- 1 Longitudinal Wind Baffle
- 2 Plenum Walkway
- 3 Drift Eliminators
- 4 Fill Area Outline
- 5 Transverse Partition Wall
- 6 Cold Water Basin
- 7 Louvered Wall
- 8 Optional Enclosures for Extended Fan Deck
- 9 Access Hatch
- 10 Fiberglass Flow Control Valve
- 11 Fiberglass Manifold
- 12 Oil Drain Line
- 13 Access Ladder (Typical)
- 14 Oil Fill and Sight Gauge
- 15 Pillow Block
- 16 Fiberglass Air Seal
- 17 Fiberglass Fan
- 18 Fiberglass Fan Stack
- 19 Plenum Air Seal
- 20 Safety Handrail
- 21 Inlet Flange (Not Shown)
- 22 Cased End Wall



- 1 Longitudinal Wind Baffle
- 2 Plenum Walkway
- 3 Drift Eliminators
- 4 Fill Area Outline
- 5 Transverse Partition Wall
- 6 Cold Water Basin
- 7 Louvered Wall
- 8 Optional Enclosures for Extended Fan Deck
- 9 Access Hatch
- 10 Fiberglass Flow Control Valve
- 11 Fiberglass Manifold
- 12 Oil Drain Line
- 13 Access Ladder (Typical)
- 14 Oil Fill and Sight Gauge
- 15 Pillow Block
- 16 Fiberglass Air Seal
- 17 Fiberglass Fan
- 18 Fiberglass Fan Stack
- 19 Plenum Air Seal
- 20 Safety Handrail
- 21 Inlet Flange (Not Shown)
- 22 Cased End Wall



- 1 Longitudinal Wind Baffle
- 2 Plenum Walkway
- 3 Drift Eliminators
- 4 Fill Area Outline
- 5 Transverse Partition Wall
- 6 Cold Water Basin
- 7 Louvered Wall
- 8 Optional Enclosures for Extended Fan Deck
- 9 Access Hatch
- 10 Fiberglass Flow Control Valve
- 11 Fiberglass Manifold
- 12 Oil Drain Line
- 13 Access Ladder (Typical)
- 14 Oil Fill and Sight Gauge
- 15 Pillow Block
- 16 Fiberglass Air Seal
- 17 Fiberglass Fan
- 18 Fiberglass Fan Stack
- 19 Plenum Air Seal
- 20 Safety Handrail
- 21 Inlet Flange (Not Shown)
- 22 Cased End Wall



'B' Column
Failure Point

- 1 Longitudinal Wind Baffle
- 2 Plenum Walkway
- 3 Drift Eliminators
- 4 Fill Area Outline
- 5 Transverse Partition Wall
- 6 Cold Water Basin
- 7 Louvered Wall
- 8 Optional Enclosures for Extended Fan Deck
- 9 Access Hatch
- 10 Fiberglass Flow Control Valve
- 11 Fiberglass Manifold
- 12 Oil Drain Line
- 13 Access Ladder (Typical)
- 14 Oil Fill and Sight Gauge
- 15 Pillow Block
- 16 Fiberglass Air Seal
- 17 Fiberglass Fan
- 18 Fiberglass Fan Stack
- 19 Plenum Air Seal
- 20 Safety Handrail
- 21 Inlet Flange (Not Shown)
- 22 Cased End Wall

Cell 2-4 Failure – Causal Investigation

- **Root Cause:**

 - Support columns failed due to overload condition**

- **Other Causes:**

 - **Inadequate Inspection Methods of Wood Structure**
 - **Inadequate Preventative Maintenance**

- **Contributing Cause: Design of Fill Material**

Cell 2-4 Failure – Corrective Actions


- **Rebuilt Cell 2-4**
- **Completed Extent of Condition Inspections and Repairs**
- **Fully Revised Inspection Procedures and Acceptance Criteria**
- **Established 2008 Cooling Tower Project Plan**

Cell 2-4 Failure – Corrective Actions

- **Phase 1 of Long Range Plan – Completed May 2008**
 - **1/3 Replacement – (Bay 4)**
 - **New Structural Member Material: Fiberglass Reinforced Plastic (FRP)**
 - **New Fill Material**
 - **Extent of Condition Repairs**
- **Used External/Fleet Technical Expertise**
- **Long Range Plan**



2008 Cooling Tower Project (Phase 1)











July 2008 Event

July 2008 Event

■ Field Observation


- Leak in Distribution Header (Cell 1-1 East, ~60 gpm)
- Broken/Degraded Saddles (4 in tower 1, 2 in tower 2)


■ Cause of Event

- Wooden Saddle to FRP Connection
- Identified by VY Design Engineering prior to placing tower in service
 - Incorrect Technical Assessment by Engineering/Vendor
 - Limited to FRP/Wood Saddles

COOLING TOWER 1; CIRC. WATER SUPPORTS

TYPICAL DETAIL FOR CONNECTION TO FRP COLUMNS





[Back to pg. 64](#)

July 2008 Event

Corrective Actions

- Full extent of condition walkdowns
- Repaired all saddles/connections
- Revised design documentation

September 2008 Event

Distribution Header Leak – Initial Actions

- **Operations Field Observations:**
 - **Potential depression in fan deck**
 - **Leak in distribution header piping**
- **Cooling water to towers promptly secured**
- **Remained at 100% plant power output for ~ 6 hours**
- **Lowered power to 55% due to river flow**

Distribution Header Leak – Inspections

- Walkdowns performed using revised inspection procedures
- Leak NOT caused by structural problem
- Cause: Packing leak attributed to start/stop of cooling water pumps (not uncommon)
- Additional inspections - 8 degraded columns:
 - 1 Level 1 - replace; unrelated to leak
 - 3 Level 2 adjacent to Level 1 - replace
 - 4 Level 2 – address next maintenance window

Inspection Acceptance Criteria

- **Level 1: Replace immediately**

- **Level 2:**

- ✓ **If adjacent to Level 1, replace immediately**

- ✓ **Otherwise, replace next maintenance period**

- **Level 3: Inspect/monitor**

Distribution Header Leak – Corrective Actions

- Leak repaired
- Replaced support columns

Cooling Tower Event Summary

Cooling Tower Event Summary

- **Safety function not affected**
- **Maintained compliance with federal/state discharge permit**
- **No impact from power uprate**
- **Revised Inspection procedures/organizational sensitivity effective**
- **Substantial investment in reliability improvements**


Long Range Plan

Long Range Plan

- **Phased approach based on maintenance availability**
 - **Phase 1: Bay 4 Complete**
 - **Phase 2: Bay 2 Spring 2009**
 - **Phase 3: Bay 6 Spring 2010**


- **Other inspections/repairs based on revised methods/procedures**

Phase 1




Typical Cooling Tower Cell

Phase 2



Typical Cooling Tower Cell

Phase 3



Typical Cooling Tower Cell

