Exelon Generation Company, LLC Dresden Nuclear Power Station 6500 North Dresden Road Morris, IL 60450-9765 www.exeloncorp.com

Exelon Nuclear

ł

10 CFR 50.73

SVPLTR # 08-0067

December 31, 2008

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

> Dresden Nuclear Power Station, Unit 3 Renewed Facility Operating License No. DPR-25 NRC Docket No. 50-249

Subject: Licensee Event Report 249/2008-003-00, "Unit 3 Unplanned Control Rod Withdrawals"

Enclosed is Licensee Event Report 249/2008-003-00, "Unit 3 Unplanned Control Rod Withdrawals" for Dresden Nuclear Power Station, Unit 3. This event is being reported in accordance with 10 CFR 50.73(a)(2)(v)(D), "Any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident." There are no regulatory commitments contained in this submittal.

Should you have any questions concerning this report, please contact Mr. Stephen Taylor, Regulatory Assurance Manager, at (815) 416-2800.

Respectfully,

David B. Wozniak

Site Vice President Dresden Nuclear Power Station

Enclosure

cc: Regional Administrator – NRC Region III NRC Senior Resident Inspector – Dresden Nuclear Power Station

LOD NRR

NRC FO	RM 366	,		U.S. NUCL	EAR R	EGULATO	RY COMMI	ISSION	APPROVE	ED BY OMB	: NO. 3150-0	0104	EXPIRES:	08/31/2010
(9-2007)	(9-2007) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)								Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the					
1. FACIL	1. FACILITY NAME								2. DOCKET NUMBER 3. PAGE					
Dres	Dresden Nuclear Power Station, Unit 3								05000249 1 OF 4					
4. TITLE Unit	3 Unpla	anned (	Control	Rod With	Irawa	s								
5. E	VENT D	ATE	6.		R	7. R	EPORT D	ATE		8.	OTHER FA	<b>CILITIES INV</b>	OLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIA NUMBER	- REV NO.	MONTH	DAY	YEAF	N/A	YNAME			N/A	
11	03	2008	2008	- 003 -	00	12	31	200	B N/A	Y NAME			DOCKET	NUMBER
9. OPEF	ATING N	IODE	11	. THIS REPO	RT IS	SUBMITTE	D PURSU	UANT T	O THE RE	QUIREMI	ENTS OF 1	OCFR§: (Che	ck all that	apply)
4 10. POWER LEVEL 000			□       20.2201 (b)         □       20.2203(a)(1)         □       20.2203(a)(2)(i)         □       20.2203(a)(2)(ii)         □       20.2203(a)(2)(iii)         □       20.2203(a)(2)(iv)         □       20.2203(a)(2)(iv)         □       20.2203(a)(2)(v)         □       20.2203(a)(2)(v)         □       20.2203(a)(2)(v)				$ \begin{bmatrix} 20.2203(a)(3)(i) \\ 20.2203(a)(3)(ii) \\ 20.2203(a)(4) \\ 50.36(c)(1)(i)(A) \\ 50.36(c)(2) \\ 50.46(a)(3)(ii) \\ 50.73(a)(2)(i)(A) \\ 50.73(a)(2)(i)(B) \\ \end{bmatrix} $		$ \begin{bmatrix} 50.73(a)(2)(i)(C) \\ 50.73(a)(2)(ii)(A) \\ 50.73(a)(2)(ii)(B) \\ 50.73(a)(2)(iii) \\ 50.73(a)(2)(iv)(A) \\ 50.73(a)(2)(v)(A) \\ 50.73(a)(2)(v)(B) \\ 50.73(a)(2)(v)(C) \\ 50.73(a)(2)(v)(D) \\ \end{bmatrix} $		<ul> <li>50.73(a)(2)(vii)</li> <li>50.73(a)(2)(viii)</li> <li>50.73(a)(2)(viii)</li> <li>50.73(a)(2)(viii)</li> <li>50.73(a)(2)(ix)(x)</li> <li>50.73(a)(2)(x)</li> <li>73.71(a)(4)</li> <li>73.71(a)(5)</li> <li>OTHER</li> <li>Specify in Abstractor in NRC Form 3</li> </ul>		)(A) )(B) (A) ict below 366A	
FACILITY					1	2. LICENS	SEE CONT	TACT F	OR THIS I	LER	ITC		ER (Indudo A	raa Cada)
Dres	den Nu	uclear P	ower S	Station – G	eorge	Papanio	: Jr.				(	815) 416-28	315	lea Coue)
			13. CON	IPLETE ONE		FOR EAC	1 COMPO	NENT I	AILURE	DESCRIB	ED IN THIS	REPORT		
CAUSE SYSTEM		SYSTEM	СОМРО	NENT FAC	NU- URER	REPORTABLE TO EPIX		C	AUSE	JSE SYSTEM COMPONE		NT FACTURE	T MANU- REPO FACTURER TO	
N/	A								N/A					
		14	. SUPPL	EMENTAL P	EPOR	T EXPECT	ED			15. E	XPECTED	MONTH	DAY	YEAR
	S (If yes	, complet	€ 15. EXPECTED SUBMISSION DATE)					NO DATE		DATE				
ABSTR/	CT (Lim	it to 1400	spaces,	i.e., approxii	nately	15 single-s	paced type	ewritten	lines)					1
On November 3, 2008, at approximately 1036 hours (CST), with Unit 3 in a refuel outage, Dresden Nuclear Power Station operations personnel observed an unplanned withdrawal of control rod D-7. The control rod withdrawal stopped at position 06 with no actions taken by main control room personnel. An unplanned withdrawal of control rod E-6 to position 18 and control rod E-7 to position 16 also occurred and stopped with no actions by main control room personnel. All control rods were re-inserted to the full-in position per procedure on November 3, 2008, at approximately 1156 hours (CST). The root cause of the unplanned control rod withdrawals is attributed to latent procedure deficiencies in DOP 0500-05, "Discharging CRD Accumulators with Mode Switch in Shutdown or Refuel," Revision 4 that														
were not identified during an Operating Experience Review of the Significant Event Notification (SEN) 264, "Upplanned BWB Control Bod Withdrawals While Shutdown" per procedure LS-AA-115, "Operating														

"Unplanned BWR Control Rod Withdrawals While Shutdown," per procedure LS-AA-115, "Operating Experience Procedure." Corrective actions to address this event include procedure revisions to DOP 0500-05 and LS-AA-115.

• • •

NRC FORM	366A
(9-2007)	

# LICENSEE EVENT REPORT (LER) **CONTINUATION SHEET**

U.S. NUCLEAR REGULATORY COMMISSION

1. FACILITY NAME	2. DOCKET	6	6. LER NUMBER			3. PAGE	
Dresden Nuclear Power Station, Unit 3	05000249	YEAR	SEQUENTIAL RE NUMBER NO	:V ).	2	OF	4
	00000240	2008	- 003 - 00	0	-	0.	-

NARRATIVE

Dresden Nuclear Power Station (DNPS) Unit 3 is a General Electric Company Boiling Water Reactor with a licensed maximum power level of 2957 megawatts thermal. The Energy Industry Identification System codes used in the text are identified as [XX].

### Α. **Plant Conditions Prior to Event:**

Event Date: 11/3/2008 Unit: 03 Reactor Mode: 4 Mode Name: Cold Shutdown Reactor Coolant System Pressure: 0 psig

Power Level: 0 percent

### В. **Description of Event:**

On November 2, 2008, the DNPS Work Execution Center (WEC) Operations Field Supervisor performed a Pre-Job Brief (PJB) of a D3R20 Outage Activity, "Discharge CRD HCU ACCUM - Water Side Only," per procedure DOP 0500-05, "Discharging of CRD Accumulators with Mode Switch in Shutdown or Refuel." The PJB included the direction to perform conditional procedure steps for the Non-Licensed Operators (NLOs) to isolate all control rod drive (CRD) [AA] hydraulic control units (HCUs) [HCU] by closing 177 HCU insert valves (i.e., valve 3-0305-101) [V] and 177 HCU withdraw valves (i.e., valve 3-0305-102) with an operating CRD pump. On November 3, 2008, the NLOs began performing HCU valve closures for the outage activity.

On November 3, 2008, at approximately 1036 hours (CST), with Unit 3 in a refuel outage, DNPS main control room (MCR) personnel observed an unplanned withdrawal of control rod D-7. The control rod withdrawal stopped at position 06 with no actions taken by MCR personnel. An unplanned withdrawal of control rods E-6 to position 18 and E-7 to position 16 also occurred and stopped with no actions taken by MCR personnel.

On November 3, 2008, at approximately 1156 hours (CST), all control rods were re-inserted per procedure to the full-in position by manually opening the associated HCU insert valve.

An Event Notification System call was made on November 18, 2007, at 1608 hours (CST) for the above-described event. The assigned ENS event number was 44665.

This event is being reported in accordance with 10 CFR 50.73(a)(2)(v)(D), "Any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident."

### C. Cause of Event:

The root cause of the unplanned control rod withdrawals is attributed to latent procedure deficiencies in DOP 0500-05. "Discharging CRD Accumulators with Mode Switch in Shutdown or Refuel." Revision 4 that were not identified during an Operating Experience Review of the Significant Event Notification (SEN) 264, "Unplanned BWR Control Rod Withdrawals While Shutdown," per procedure LS-AA-115, "Operating Experience Procedure."

NRC FORM 366A (9-2007)	LICEN C	SEE EVENT I CONTINUATIO	REPORT ( N SHEET	(LER)	EAR REG	IULATO	RY COMM	IISSION
1. FACILITY	NAME	2. DOCKET		3. PAGE				
Dresden Nuclear Power S	tation Unit 3	05000249	YEAR	SEQUENTIAL NUMBER	REV NO.	3	OF	4
		00000240	2008	- 003 -	000	0	0.	•

## NARRATIVE

A Unit 2 start-up from an unscheduled mid-cycle forced outage in 2005 was delayed due to excessive nitrogen gas accumulation in HCU piping. This event prompted the development and issuance of Revision 4 to DOP 0500-05, which permitted isolation of any or all HCU accumulators by closing the HCU insert, and HCU withdraw valves to limit migration of nitrogen gas into HCU piping. The intended purpose was to shorten subsequent venting of drives after system restoration. The procedure did not contain any precautions, prerequisites, selection criteria or limitations for the quantity of HCUs to be isolated with an operating CRD pump. The root cause evaluation determined that the procedure lacked sufficient guidance for the intended use.

In 2007, the Institute of Nuclear Power Operations (INPO) issued SEN 264 that provided information based on recently reported historical events at several Boiling Water Reactors (BWRs) in Japan during outages, which occurred between 1978 and 2000. In each event, single or multiple control rods unexpectedly withdrew from the core without a deliberate command withdrawal signal. The SEN 264 stated in part:

"The unexpected rod withdrawals occurred during either isolation or restoration of multiple HCUs. With a CRD pump running and the majority of the HCUs isolated, CRD system pressures had increased sufficiently for some control rods to withdraw from the core when the associated HCU isolation valves were manipulated in a specific sequence."

"These events involved a scenario which was not well known within the industry, and other BWRs are potentially vulnerable if operated in a similar fashion without compensatory actions taken to address the anomalous operating conditions."

DNPS operations and engineering personnel reviewed the applicability of SEN 264 and concluded that although unlikely, the vulnerability exists at DNPS. Based on this conclusion, a procedure review was conducted in accordance with the requirements in procedure LS-AA-115, "Operating Experience Procedure," to identify procedures requiring revision to address the SEN 264 issue. The review identified procedures revisions were required to DOP 0300-08, "Control Rod Drive System Hydraulic Control Unit Isolation / Pump Isolation," DOP 0400-01, "Reactor Manual Control System Operation" and DGP 03-04, "Control Rod Movements." The procedure revisions made were considered adequate to address the SEN 264 issue and were completed in October 2007.

The RCR evaluation reviewed the cause of procedure DOP 0500-05 not being revised to address the SEN 264 issue and identified that the procedural requirements in LS-AA-115 to perform the procedure review provided insufficient guidance. LS-AA-115 did not require adequate technical rigor during the evaluation for effected procedures, did not require adequate documentation of the effected procedure evaluation, and lacked sufficient departmental, inter-departmental and cross-discipline reviews to ensure the issue under review is completely addressed.

# D. Safety Analysis:

The safety significance of the event is minimal. A detailed risk assessment was performed for this event and concluded that the risk of core damage was judged to be negligible due to the reactor

NRC F (9-2007)	ORM 366A LICEN	SEE EVENT	REPORT ( )N SHEET	(LER) U.S. NUCLEAR RE	EGULATORY COMMISSION				
	1. FACILITY NAME	2. DOCKET	6	3. LER NUMBER	3. PAGE				
Dresden Nuclear Power Station, Unit 3		05000249	YEAR 2008	SEQUENTIAL REV NUMBER NO.	- 4 OF 4				
NARR	ATIVE	<u> </u>	2000						
	remaining subcritical, no boiling in the Reactor engineering calculations dete percent. Therefore, the consequence the public and reactor safety.	core and red rmined the cc of this even	undant hea pre remaine t had minin	at removal methods ed sub-critical by app nal impact on the he	being available. proximately 4.5 alth and safety of				
E.	Corrective Actions:								
	All control rods were re-inserted per p associated HCU insert valve.	procedure to th	ie full-in po	osition by manually o	ppening the				
	Procedure DOP 0500-05 was revised rod withdrawal as described in SEN 2	to provide ad 264.	ministrative	e barriers to prevent	unplanned control				
	Procedure LS-AA-115 will be revised to require sufficient rigor, departmental, inter-departmental and cross-discipline reviews for high significance / risk OPEX items.								
	Procedure OP-DR-108-101-1002, "Op revised to require if a knowledge-base emergency condition at the discretion operator shall be obtained.	perations Depa ed procedure of of the superv	artment Sta conditional isor, then a	andards and Expect statement shall be a peer check by a se	ations," will be executed, in a non- econd licensed				
F.	Prev <u>ious Occurrences</u> :								
	A review of DNPS Licensee Event Re associated with unplanned control roc	ports (LERs) d withdrawal.	for the last	three years did not	identified any LERs				
G.	Component Failure Data:								
	N/A		-						
		٠							

\* • • •