

Dominion Nuclear Connecticut, Inc.
Millstone Power Station
Rope Ferry Road, Waterford, CT 06385



DEC 30 2008

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

Serial No. 08-0755
MPS Lic/TGC R0
Docket No. 50-423
License No. NPF-49

DOMINION NUCLEAR CONNECTICUT, INC.
MILLSTONE POWER STATION UNIT 3
LICENSEE EVENT REPORT 2008-005-00
CONTAINMENT PENETRATION NOT FULLY CLOSED DURING FUEL MOVEMENT

This letter forwards Licensee Event Report (LER) 2008-005-00 documenting a condition discovered at Millstone Power Station Unit 3, on November 5, 2008. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B), as a condition prohibited by technical specifications.

If you have any questions or require additional information, please contact Mr. William D. Bartron at (860) 444-4301.

Sincerely,

A. J. Jordan
Site Vice President - Millstone

Attachments: 1

Commitments made in this letter: None

JE22
NRR

cc: U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406-1415

Ms. C. J. Sanders
Project Manager
U.S. Nuclear Regulatory Commission
One White Flint North
11555 Rockville Pike
Mail Stop 08B3
Rockville, MD 20852-2738

NRC Senior Resident Inspector
Millstone Power Station

ATTACHMENT

LICENSEE EVENT REPORT 2008-005-00
CONTAINMENT PENETRATION NOT FULLY CLOSED DURING FUEL MOVEMENT

**MILLSTONE POWER STATION UNIT 3
DOMINION NUCLEAR CONNECTICUT, INC.**

NRC FORM 366 (6-2004)	U.S. NUCLEAR REGULATORY COMMISSION	APPROVED BY OMB NO. 3150-0104	EXPIRES 06/30/2007
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)		Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.	

1. FACILITY NAME Millstone Power Station - Unit 3	2. DOCKET NUMBER 05000423	3. PAGE 1 OF 3
---	-------------------------------------	--------------------------

4. TITLE
Containment Penetration Not Fully Closed During Fuel Movement

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	05	2008	2008-005-00			12	30	2008	FACILITY NAME	DOCKET NUMBER

9. OPERATING MODE	6	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)			
		20.2201(b)	20.2203(a)(3)(ii)	50.73(a)(2)(ii)(B)	50.73(a)(2)(ix)(A)
10. POWER LEVEL	000	20.2201(d)	20.2203(a)(4)	50.73(a)(2)(iii)	50.73(a)(2)(x)
		20.2203(a)(1)	50.36(c)(1)(i)(A)	50.73(a)(2)(iv)(A)	73.71(a)(4)
		20.2203(a)(2)(i)	50.36(c)(1)(ii)(A)	50.73(a)(2)(v)(A)	73.71(a)(5)
		20.2203(a)(2)(ii)	50.36(c)(2)	50.73(a)(2)(v)(B)	OTHER
		20.2203(a)(2)(iii)	50.46(a)(3)(ii)	50.73(a)(2)(v)(C)	Specify in Abstract below or in NRC Form 366A
		20.2203(a)(2)(iv)	50.73(a)(2)(i)(A)	50.73(a)(2)(v)(D)	
		20.2203(a)(2)(v)	X 50.73(a)(2)(i)(B)	50.73(a)(2)(vii)	
		20.2203(a)(2)(vi)	50.73(a)(2)(i)(C)	50.73(a)(2)(viii)(A)	
		20.2203(a)(3)(i)	50.73(a)(2)(ii)(A)	50.73(a)(2)(viii)(B)	

12. LICENSEE CONTACT FOR THIS LER

NAME William D. Bartron, Supervisor Nuclear Station Licensing	TELEPHONE NUMBER (Include Area Code) 860-447-1791 x4301
---	---

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED				15. EXPECTED SUBMISSION DATE		
<input type="checkbox"/>	YES (If yes, complete EXPECTED SUBMISSION DATE).	<input checked="" type="checkbox"/>	NO	MONTH	DAY	YEAR

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

With the plant in Mode 6 at 0% power on November 5, 2008, operators discovered that a valve (3FWS*V861) relied upon to be closed to meet Technical Specification requirements during fuel movement in containment was not fully closed. Plant Technical Specification (TS) 3.9.4.c requires that each penetration providing direct access from the containment atmosphere to the outside atmosphere be closed by an isolation valve, blind flange, or manual valve or be capable of being closed under administrative control during movement of fuel within the containment building. Valve 3FWS*V861 is a drain line isolation valve off the feedwater line to the "C" steam generator inside containment and was being credited as closed since a pathway to atmosphere outside containment existed due to maintenance activities on associated portions of the main steam system. The subsequent investigation determined that the valve had been in this condition during fuel movement inside containment that occurred from November 1, 2008 at 0430 until November 3, 2008 at 0915.

The cause of this condition was determined to be a combination of mechanical and physical factors making the valve difficult to operate to ensure full closure. The valve was subsequently closed. The valve will be inspected and repaired, as necessary, at the next appropriate opportunity.

Since the plant was in a configuration not allowed by the Technical Specifications, this event is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) as any operation or condition prohibited by the plant's Technical Specifications.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)		
Millstone Power Station - Unit 3	05000423	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	OF	3
		2008	- 005	- 00			

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

1. Event Description:

With the plant in Mode 6 at 0% power on November 5, 2008, operators discovered that a valve [V] (3FWS*V861) relied upon to be closed to meet Technical Specification requirements during fuel movement in containment was not fully closed. Plant Technical Specification (TS) 3.9.4.c requires that each penetration providing direct access from the containment atmosphere to the outside atmosphere be closed by an isolation valve, blind flange, or manual valve or be capable of being closed under administrative control during movement of fuel within the containment building. Valve 3FWS*V861 is a drain line isolation valve off the feedwater [SJ] line to the "C" steam generator [SG] inside containment and was being credited as closed since a pathway to atmosphere outside containment existed due to maintenance activities on associated portions of the main steam system. The subsequent investigation determined that the valve had been in this condition during fuel movement inside containment that occurred from November 1, 2008 at 0430 until November 3, 2008 at 0915.

Since the plant was in a configuration not allowed by the Technical Specifications, this event is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) as any operation or condition prohibited by the plant's Technical Specifications.

2. Cause:

Subsequent to maintenance activities on the secondary side of the "C" steam generator, operators proceeded to fill the steam generator. Operators identified that containment sump levels were rising and found that valve 3FWS*V861 was the source. Operators attempted to further close the valve and were not initially successful until significant mechanical leverage was applied.

The cause of this condition was determined to be a combination of mechanical and physical factors making the valve difficult to operate to ensure full closure. The packing on this valve was very tight and the valve handle has an extension necessary to clear an interference. The extent of condition review identified that a valve in series with 3FWS*V861 (3FWS*V862) is subject to similar mechanical and design factors and was also not fully closed. (3FWS*V862 was not being credited for compliance with TS 3.9.4.c.)

3. Assessment of Safety Consequences:

This condition is judged to be of very low safety significance. The requirements on containment penetration closure and operability ensure that a release of radioactive material within containment to the environment will be minimized. The fuel handling accident analyses assume that during a fuel handling accident some of the fuel that is dropped and some of the fuel impacted upon is damaged. Containment penetrations, including the personnel access hatch doors and equipment access hatch, can be open during the movement of fuel provided that sufficient administrative controls are in place such that any of these containment penetrations can be closed within 30 minutes. Following a Fuel Handling Accident, each penetration, including the equipment access hatch, is closed such that a containment atmosphere boundary can be established. The containment atmosphere boundary is established when any penetration which provides direct access to the outside atmosphere is closed such that at least one barrier between the containment atmosphere and the outside atmosphere is established. The design basis Fuel Handling Accident does not credit closure of containment and assumes all radioactivity released as part of the accident is exhausted directly to the environment within 2 hours. Under design basis conditions, offsite dose and dose to the control room operators are within regulatory limits.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Millstone Power Station - Unit 3	DOCKET (2) NUMBER (2) 05000423	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	OF 3
		2008	- 005	- 00		

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

In this case, a pathway to atmosphere existed via a hose connected to a 2" valve (3FWS*V861), through the feedwater line to the secondary side of the "C" steam generator, through the main steam line and to atmosphere through an open main steam isolation valve drain standpipe low point drain (3DTM*V117). Since operators were not aware that 3FWS*V861 was not fully closed, no administrative controls were in place to ensure the penetration could be closed within 30 minutes. This condition existed from November 1, 2008 at 0430 until November 3, 2008 at 0915, the period of time in which fuel movement inside containment was underway. There was no fuel handling accident.

4. Corrective Action:

Valve 3FWS*V861 and 3FWS*V862 were subsequently closed. The valves will be inspected and repaired, as necessary, at the next appropriate opportunity.

Additional corrective actions are being taken in accordance with the station's Corrective Action Program.

5. Previous Occurrences:

No previous similar events/conditions were identified.

Energy Industry Identification System (EIIIS) codes are identified in the text as [XX].