

February 6, 2009

ULNRC-05593

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Stop P1-137
Washington, DC 20555-0001



10CFR50.73(a)(2)(iv)(A)

Ladies and Gentlemen:

**DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
UNION ELECTRIC CO.
FACILITY OPERATING LICENSE NPF-30
LICENSEE EVENT REPORT 2008-006-00
REACTOR TRIP DUE TO TURBINE TRIP DURING POWER REDUCTION
FOLLOWING LOSS OF 'C' CONDENSATE PUMP**

The enclosed licensee event report is submitted in accordance with 10CFR50.73(a)(2)(iv)(A) to report an event of a reactor trip due to a turbine trip during power reduction following a loss of the 'C' condensate pump.

This letter does not contain new commitments.

Sincerely,

A handwritten signature in black ink, appearing to read "David W. Neterer".

David W. Neterer
Plant Director

KRA/nls

Enclosure

ULNRC-05593
February 6, 2009
Page 2

cc: Mr. Elmo E. Collins, Jr.
Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
612 E. Lamar Blvd., Suite 400
Arlington, TX 76011-4125

Senior Resident Inspector
Callaway Resident Office
U.S. Nuclear Regulatory Commission
8201 NRC Road
Steedman, MO 65077

Mr. Mohan C. Thadani (2 copies)
Licensing Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop O-8G14
Washington, DC 20555-2738

Index and send hardcopy to QA File A160.0761

Hardcopy:

Certrec Corporation
4200 South Hulen, Suite 422
Fort Worth, TX 76109

(Certrec receives ALL attachments as long as they are non-safeguards and may be publicly disclosed.)

LEREvents@inpo.org (must send the **WORD** version of the LER to this address)

Electronic distribution for the following can be made via LER ULNRC Distribution:

A. C. Heflin
F. M. Diya
D. W. Neterer
T. E. Herrmann
L. S. Sandbothe
S. A. Maglio
S. L. Gallagher
L. M. Belsky (NSRB)
T. B. Elwood
D. E. Dumbacher (NRC)
B. A. Brook (WCNOC)
Ms. Diane M. Hooper (WCNOC)
Mr. Dennis Buschbaum (TXU)
Mr. Scott Bauer (Palo Verde)
Mr. Stan Ketelsen (PG&E)
Mr. Wayne Harrison (STPNOC)
Mr. John O'Neill (Pillsbury Winthrop Shaw Pittman LLP)
Missouri Public Service Commission
Records Center (INPO)

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Callaway Plant Unit 1	2. DOCKET NUMBER 05000483	3. PAGE 1 OF 6
--	-------------------------------------	--------------------------

4. TITLE
Reactor Trip Due To Turbine Trip During Power Reduction Following Loss Of 'C' Condensate Pump

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
12	11	2008	2008	- 006 -	00	02	06	2009	FACILITY NAME	DOCKET NUMBER
									FACILITY NAME	DOCKET NUMBER

9. OPERATING MODE MODE 1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)			
10. POWER LEVEL 100%	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A	

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME T.B. Elwood, Supervising Engineer, Regulatory Affairs and Licensing	TELEPHONE NUMBER (Include Area Code) (573) 676-6479
--	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
B	SD	MO	A180	Y					

14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR
--	-------------------------------------	-------	-----	------

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

At 2254 on December 11, 2008 the 'C' condensate pump tripped. After confirming the trip, operators began a reduction in power and entered the Callaway off-normal procedure for Feedwater System Malfunction. However, the manual load reduction rate was approximately 31% in one minute, exceeding the procedural guidance of 5% per minute. At 2256 the control rods automatically stepped in and the condenser steam dumps opened as designed. Subsequently, steam generator (S/G) level deviation annunciators actuated for all four S/Gs and a turbine trip/reactor trip occurred at 2300. The turbine tripped on a Hi-Hi S/G level (P-14) feedwater isolation signal (FWIS) from the 'B' S/G, and the reactor trip immediately followed. Additionally, as a result of the P-14 FWIS, both main feedwater pumps tripped. Hence, a motor-driven auxiliary feedwater actuation occurred as expected.

Investigations were performed for the 'C' condensate pump motor failure and system actuations. The root cause of the motor failure was determined to be a ground fault. The root causes of the system actuations (including the reactor trip) were human performance errors which resulted in the excessively rapid load reduction. The corrective action to prevent recurrence of the motor failure was to install surge capacitors. Corrective actions for the human performance errors are discussed in Section III.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
Callaway Plant Unit 1	05000483	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 6
		2008	- 006	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

I. DESCRIPTION OF THE REPORTABLE EVENT

A. REPORTABLE EVENT CLASSIFICATION

10CFR50.73(a)(2)(iv)(A) requires reporting of any event or condition that resulted in a manual or automatic actuation of any of the systems listed in 10CFR50.73(a)(2)(iv)(B). The systems listed below are relevant to this LER:

- (1) Reactor protection system (RPS) including: reactor scram or reactor trip; and
- (6) PWR auxiliary or emergency feedwater system.

B. PLANT OPERATING CONDITIONS PRIOR TO THE EVENT

The plant was in MODE 1, Power Operation, at 100% power.

C. STATUS OF STRUCTURES, SYSTEMS OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT

No structures, systems, or components were inoperable at the start of the event which contributed to the event.

D. NARRATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES

At 2254 on December 11, 2008 the 'C' condensate pump [EIS system: SD, component: P] tripped due to a motor [EIS system: SD, component: MO] ground fault failure (turn-to-turn failure on the stator). At 2255 the operating crew noticed computer point MAJ0001, Main Generator Power, had turned yellow and was indicating approximately 1314 MWe. The operators immediately noticed that the 'C' condensate pump had tripped, commenced a reduction in power, and entered Callaway off-normal procedure OTO-AE-00001, Feedwater System Malfunction. However, the manual load reduction rate was approximately 31% in one minute, exceeding the procedural guidance of 5% per minute. At 2256 the control rods [EIS system: AA, component: ROD] automatically stepped in and the condenser steam dumps [EIS system: SB, component: RV] opened as designed. Level transients subsequently occurred in the steam generators (S/Gs) [EIS system: AB, component: SG], and level deviation annunciators actuated in the main control room for all four S/Gs. As a result of high level in the 'B' S/G, a turbine [EIS system: TA, component: TRB] trip/reactor trip occurred at 2300.

The turbine tripped on a Hi-Hi S/G level (P-14) feedwater isolation signal (FWIS) [EIS system: SJ, component: ISV] from the 'B' S/G, and the reactor trip immediately followed. Additionally, as a result of the P-14 FWIS, both main feedwater pumps (MFPs) [EIS system: SJ, component: P] tripped and hence a motor-driven auxiliary feedwater actuation [EIS system: BA, component: P] occurred as expected. The Auxiliary Building sample station Chemical and Volume Control System (CVCS) Letdown Gamma Detector [EIS system: IL, component: DET] went into Alert as a result of the transient (due to a pre-existing fuel defect) and a Loose Parts Monitor [EIS system: II, component: MON] alarmed, as expected, due to the control rods dropping. The 'B' and 'C' atmospheric steam dumps (ASDs) [EIS system: SB, component: RV] opened and re-closed at the time of the reactor trip.

Two root cause investigations were performed to determine causes and corrective actions for the pump motor failure and for the automatic actuations of the Main Feedwater Isolation, RPS & Auxiliary Feedwater System (AFWS). The pump motor failure which initiated the sequence of events was the result of one root cause associated with two causal factors. The investigation for the automatic

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
Callaway Plant Unit 1	05000483	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 6
		2008	- 006	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

actuations of the Main Feedwater Isolation, RPS & Auxiliary Feedwater System (AFWS) found that the event occurred due to two root causes with associated causal factors, as described in Section III below.

E. METHOD OF DISCOVERY OF EACH COMPONENT, SYSTEM FAILURE, OR PROCEDURAL ERROR

The 'C' condensate pump trip was discovered by the Reactor Operator (RO) while the operators were investigating the cause of why the "MWe High" indication, i.e. MAJ0001, Main Generator Power, was yellow. No other components or systems failed during this event, and there were no errors in the procedural guidance. However, human error caused the Balance of Plant (BOP) operator's action to exceed procedural guidance for reducing power (load) subsequent to the condensate pump trip.

II. EVENT DRIVEN INFORMATION

A. SAFETY SYSTEMS THAT RESPONDED

All safety systems functioned as designed. The Main Feedwater Isolation actuation (i.e. a FWIS), RPS actuation, and motor-driven Auxiliary Feedwater actuation all occurred as expected for such an event.

B. DURATION OF SAFETY SYSTEM INOPERABILITY

No safety systems were inoperable which contributed to this event.

C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT.

At no time was the plant in an unanalyzed condition. When the 'C' condensate pump tripped, both the 'A' and 'B' condensate pumps were available and capable of providing adequate flow and suction head for the feedwater pumps (notwithstanding the load reduction that was effected). Had only one condensate pump remained running at greater than 45-percent reactor power, the reactor would have been manually tripped.

The events described in this LER can be best characterized by comparison with the Loss of Load heatup event analyzed in the Callaway Final Safety Analysis Report (FSAR).

The plant conditions described in this LER were bounded by the Current Licensing Basis accident analysis for Loss of Load transient. The Loss of Load transient is less severe than a Turbine Trip event which is also analyzed in the Callaway FSAR, so the Turbine Trip accident analysis bounds the LER event. The Turbine Trip transient is evaluated with the following conservative conditions:

1. The power is reduced from full power to zero power, and the reactor is in manual control.
2. There is no credit taken for operation of the steam dump system or the atmospheric steam dumps.
3. The reactor does not trip until RCS conditions result in a trip.

The event described in this LER occurred with a total load loss of approximately 36 percent, from full power. The reactor was in automatic control, allowing the control rod banks to step in before the trip occurred. The atmospheric steam dumps did function as designed, which caused the steam generator levels to rise to the P-14 level, resulting in a reactor trip to coincide with the turbine trip. The reactor trip coinciding with turbine trip is a result of the P-9 automatic protective function.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2008	- 006	- 00	4 OF 6

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

The events described in this LER are bounded by the Current Licensing Basis analysis in the Callaway FSAR. Therefore, the events described in this LER do not represent any unanalyzed conditions, nor were they safety significant.

III. CAUSE(S) OF THE EVENT AND CORRECTIVE ACTION(S)

This event was evaluated in two parts, each using a seven-step root cause analysis process. The first Root Cause Team, analyzing the pump motor failure, concluded that there was a single Root Cause with two Causal Factors. The second Root Cause Team, analyzing the plant response & human performance during the event, concluded that there were two Root Causes with associated Causal Factors.

The 'C' condensate pump motor failure: The condensate pump motors are Allis Chalmers VersaPac three-phase wye-wound vertical induction motors rated at 3500 hp, 1184 rpm, and 4000 volts. Destructive examination performed by the vendor identified a causal factor for the failure as a winding failure in the 'C' condensate pump motor stator, along with the root cause of a voltage surge causing damage to the motor insulation. As described in Callaway LER 2008-008, following the 'C' condensate pump motor failure, the 'B' condensate pump motor failed on December 14, 2008, also due to a motor ground fault failure.

Voltage transients occur in most electrical systems and are usually caused by switching surges from breaker contactor switching. These surges often originate from normal switching actions within the plant and are less likely to occur from lightning strikes. Motors that run continuously have a higher probability of experiencing voltage surges caused by any type of electrical disturbance on the bus.

Fast rise time surges can cause severe voltage stress on the turn insulation due to the non-uniform distribution of voltage across the winding. Typically, the voltage becomes uniformly distributed across the turns for rise times that are longer than approximately 1 microsecond. Some equipment characteristics that may influence these effects include cable length, cable size, insulation condition, common bus electrical loads, and switching sequence. As such, it was identified that an additional causal factor is the close proximity (i.e., cable length ~150 feet) from the supplying electrical bus to the motors, which makes them more susceptible to voltage surges than other motors on the same busses.

During the extent of condition investigation of the similar failures for the 'C' and 'B' condensate pump motors, the 'A' condensate pump motor was sent offsite to a vendor for testing. The 'A' condensate pump motor was determined to not have the same degradation as the 'C' and 'B' condensate pump motors.

This issue has been entered into Callaway's corrective action program. The Corrective Action to Prevent Recurrence (CATPR) was to have surge capacitors installed at the condensate pump motor lead boxes to minimize the slope of the voltage transient wave front. By elongating the rise time of the surges, less of the full surge voltage will appear across any one coil or any two turns in the winding, thereby providing protection to the motor from future voltage surges. This will maintain the winding integrity and prevent a turn-to-turn fault. This action is complete for all of the condensate pump motors.

The human performance error: There were two root causes of the automatic actuations of the Main Feedwater Isolation, RPS and AFWS. When faced with quickly changing conditions, the operators did not clearly communicate by stating the objective and desired outcome to ensure mutual understanding and minimize mistakes. This led to taking actions outside of existing procedural guidance. The procedural guidance for loss of a condensate pump is accurate and provides clear guidance on the

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2008	- 006	- 00	5 OF 6

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

actions to take. Additionally, the training that operators received on a condensate pump trip demonstrated that a very small, if any, power reduction is required to ensure plant equipment is not damaged.

The two causal factors associated with root causes were identified as follows:

- (1) The rate and magnitude of power reduction was not in compliance with procedural requirements.
- (2) Operators have a knowledge deficiency regarding rapid load reductions and how to achieve them.

The corresponding root causes were:

- (1) Clear expectations and standards have not been established regarding operator directed actions necessary to stabilize the plant versus procedurally directed actions. There is a conflict between the desire to implement verbatim compliance with written instructions and the authority and responsibility of a licensed operator to take actions necessary to stabilize the plant and protect the health and safety of the public.
- (2) Lack of guidance on operation of the load limit potentiometer, combined with lack of experience performing rapid power reductions using the load limit potentiometer, caused load reduction in excess of procedure limits.

This issue has been entered into Callaway's corrective action program, and the CATPRs which are in progress are as follows:

- (1) CATPR: Establish clear expectations and standards regarding operator directed actions necessary to stabilize the plant versus procedurally directed actions.
- (2) CATPR: Create guidance on operation of load limit potentiometer and reinforce skills in training.

IV. PREVIOUS SIMILAR EVENTS

With respect to the 'C' condensate pump motor failure, no previous similar events have been identified. As for the human performance error root causes:

- Callaway LER 2004-001-00 addressed an event that had a similar cause of "failure to properly follow an approved plant procedure;" however, the contributing cause for that event involved identical name plate labels for two bus transfer selector switches, which does not apply to this event. The resulting discussion of the importance of human performance factors and attention to detail could not have been expected to prevent this event four years later.
- Callaway LER 2008-003-00 addressed an event that had similar issues with the operations crew clearly communicating and crew teamwork, but the individual coaching performed would not have prevented this event. Additionally, a remedial action taken to discuss the importance of crew teamwork and incorporate details of the event into future licensed operator training is not necessarily a CATPR and may not have been fully implemented as the event in LER 2008-003-00 only took place two months prior to this event.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2008	- 006	- 00	6 OF 6

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

- One event in the Callaway corrective action program documents an Institute of Nuclear Power Operations (INPO) Area for Improvement, from 2002, in which "Operations does not set and reinforce high standards in some activities. Specifically, Operations lags the industry in implementing tools to improve human performance." The CATPRs were to develop a 6-year plan for the performance of Self-Assessments and Benchmarking trips as well as conducting evaluations periodically with each crew to focus on maintaining and reinforcing high standards. The 6-year plan has only gone through a single cycle and may not have had time to be effective.

V. ADDITIONAL INFORMATION

The system and component codes listed below are from the IEEE Standard 805-1984 and IEEE Standard 803A-1983, respectively.

System:

- AA Control Rod Drive System
- AB Reactor Coolant System (PWR)
- BA Auxiliary/Emergency Feedwater System (PWR)
- II Loose Parts Monitoring System
- IL Radiation Monitoring System
- SB Main/Reheat Steam System (PWR)
- SD Condensate System
- SJ Feedwater System
- TA Main Turbine System

Component:

- DET Detector
- ISV Valve, Isolation
- MO Motor
- MON Monitor
- P Pump
- ROD Rod
- RV Valve, Relief
- SG Generator, Steam
- TRB Turbine