

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Cal Testing Services, Inc. d/b/a/ Calumet Testing Services 1945 North Griffith Boulevard Griffith, IN 46319 REPORT NUMBER(S) 2009-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351	
3. DOCKET NUMBER(S) 030-10856	4. LICENSEE NUMBER(S) 13-16347-01	5. DATE(S) OF INSPECTION March 16, 2009	

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	S. J. Mulay		3/16/09 

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Cal Testing Services, Inc., d/b/a/ Calumet Testing Svcs REPORT NUMBER(S) 2009001	2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532
---	--

3. DOCKET NUMBER(S) 030-10856	4. LICENSE NUMBER(S) 13-16347-01	5. DATE(S) OF INSPECTION March 16, 2009
---	--	---

6. INSPECTION PROCEDURES 87121	7. INSPECTION FOCUS AREAS
--	---------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3320	2. PRIORITY 1	3. LICENSEE CONTACT Arturo (Art) Bustos, RSO	4. TELEPHONE NUMBER 219-923-9800
-----------------------------------	-------------------------	--	--

Main Office Inspection Next Inspection Date: _____
 Field Office _____
 Temporary Job Site Inspection _____

PROGRAM SCOPE

This follow-up inspection was conducted to review the corrective actions implemented as a result of an inspection conducted on September 29-30, 2008, (ML 082970796) in which one violation of NRC requirements was identified for failure of a radiography crew to properly connect the drive cable to the source assembly which resulted in the inability to retract the source into the shielded position. The licensee responded to the inspection findings in a letter dated November 13, 2008, (ML 083360692).

Performance Observations

Interviews conducted with available staff indicated an adequate knowledge of the event and responses to pertinent questions/scenarios were answered appropriately and in agreement with stated corrective actions. Radiographers and assistant radiographers revealed that if problems or difficulties arise involving proper connections of the control and source assembly, the unit will be taken out of service with notification to the RSO.

Licensee representatives demonstrated a misconnect test to verify proper drive cable to source assembly connection with no problems noted. In addition, these checks have been incorporated into daily and quarterly maintenance checklists.

The inspection did not reveal similar occurrences subsequent to the event.

