Volume 2 of 5

ţ

\*

.

# TABLE OF CONTENTS - General

# VOLUME 1 of 5: Adjudication Files

- Form 1 Application for In Situ Permit to Mine
- Form 3 License to Mine Application
- Form 8 Surface Owner Consent Form
- Appendix A Surface and Mineral Rights within the Lost Creek Permit Area
- Appendix B Surface and Mineral Rights Adjacent to the Lost Creek Permit Area
- Appendix C Tabulation of Lands
- Appendix E Right of Ways
- Table ADJ-1 List of Regulatory Requirements

# VOLUME 2 of 5: Appendix D (D1 to D5)

- D1 Land Use
- D2 Brief History
- D3 Archaeological and Paleontological Resources (separate volume – requesting WDEQ confidentiality)
- D4 Meteorology, Climatology, and Air Quality
- D5 Geology

VOLUME 3a of 5: Appendix D (D6)

D6 Hydrology (through Attachment D6-2b)

# VOLUME 3b of 5: Appendix D (D6)

D6 Hydrology (through Attachments D6-3 and D6-4)

# VOLUME 4 of 5: Appendix D (D7 to D11)

- D7 Soils
- D8 Vegetation
- D9 Wildlife
- D10 Background Radiological Characteristics
- D11 Wetlands

# VOLUME 5 of 5: Operations Plan and Reclamation Plan

Operations Plan (OP) Groundwater Quality Restoration and Surface Reclamation (RP)

i

## TABLE OF CONTENTS - Detailed

# VOLUME 1 of 5: Adjudication Files

- Form 1 Application for In Situ Permit to Mine
- Form 3 License to Mine Application
- Form 8 Surface Owner Consent Form
- Appendix A Surface and Mineral Rights within the Lost Creek Permit Area
- Appendix B Surface and Mineral Rights Adjacent to the Lost Creek Permit Area
- Appendix C Tabulation of Lands
- Appendix E Right of Ways

Table ADJ-1 List of Regulatory Requirements

## VOLUME 2 of 5: Appendix D (D1 to D5)

Lan	d Use	D1-1
R	angeland and Grazing	D1-1
V	Vildlife Habitat and Hunting	D1-2
R	ecreation and Special Use Areas	D1-2
Ν	finerals and Energy	D1-2
Т	ransportation and Infrastructure	D1-3
Р	opulation Distribution	D1-3
Brie	f History	D2-1
Arc	haeological and Paleontological Resources	D3-1
(sep	arate volume – requesting WDEQ confidentiality)	
Met	eorology, Climatology, and Air Quality	D4-1
Ν	feteorology and Climatology	D4-1
4.1.1	Temperature	D4-2
4.1.2	Precipitation	D4-2
4.1.3	Humidity	D4-2
4.1.4	Wind	D4-3
4.1.5	Evaporation	
4.1.6	Severe Weather	D4-3
4.1.7	Local Air Flow Patterns and Characteristics	D4-4
A	ir Quality	D4-4
4.2.1	Background Conditions	D4-4
4.2.2	Air Quality Construction Permit	D4-6
	Lan R W R M T P Brie Arc (sep Met (sep Met 4.1.1 4.1.2 4.1.3 4.1.4 4.1.5 4.1.6 4.1.7 A 4.2.1 4.2.2	Land Use Rangeland and Grazing Wildlife Habitat and Hunting Recreation and Special Use Areas Minerals and Energy Transportation and Infrastructure Population Distribution Brief History Archaeological and Paleontological Resources (separate volume – requesting WDEQ confidentiality) Meteorology, Climatology, and Air Quality Meteorology and Climatology 4.1.1 Temperature 4.1.2 Precipitation 4.1.3 Humidity 4.1.4 Wind 4.1.5 Evaporation 4.1.6 Severe Weather 4.1.7 Local Air Flow Patterns and Characteristics Air Quality 4.2.1 Background Conditions 4.2.2 Air Ouality Construction Permit

# VOLUME 2 of 5: Appendix D (D1 to D5) continued

D5 Geo	ology	D5-1
D5.1 R	egional Geology	D5-1
D5.1.1	Stratigraphy	D5-1
D5.1.2	Structure	D5-2
D5.2 S	ite Geology	D5-2
D5.2.1	Stratigraphy	D5-3
D5.2.2	Structure	D5-4
D5.2.3	Ore Mineralogy and Geochemistry	D5-4
D5.2.4	Subsurface Exploration Activities	D5-6
D5.	2.4.1 Uranium Exploration	D5-6
D5.	2.4.2 Other Mineral Exploration	D5-8
D5.3 S	eismology	D5-8
D5.3.1	Historic Seismicity	D5-8
D5.	3.1.1 Town of Bairoil Area	D5-8
D5.	3.1.2 City of Rawlins Area	D5-9
D5.	3.1.3 City of Rock Springs Area	D5-10
D5.	3.1.4 City of Lander Area	D5-10
D5.	3.1.5 City of Casper Area	D5-11
D5.3.2	Uniform Building Code	D5-12
D5.3.3	Deterministic Analysis of Active Fault Systems	D5-12
D5.3.4	Maximum Tectonic Province Earthquake "Floating	
	Earthquake" Seismogenic Source	D5-13
D5.3.5	Short-Term Probabilistic Seismic Hazard Analysis	D5-14

# VOLUME 3a of 5: Appendix D (D6)

D6 H	lydrology.	D6-	·1
D6.1	Surface V	VaterD6-	-1
D6.1.	1 Draina	ge CharacteristicsD6-	·1
D6.1.	2 Surface	e Water UseD6-	.3
D6.1.	3 Surface	e Water QualityD6-	.3
D6.2	Groundw	ater Occurrence	.5
D6.2.	1 Region	al HydrogeologyD6-	.5
E	06.2.1.1	Lewis ShaleD6-	-7
E	06.2.1.2	Fox Hills Formation	-7
E	06.2.1.3	Lance Formation	-7
Ľ	06.2.1.4	Fort Union Formation D6-	-8
E	06.2.1.5	Battle Spring Formation- Wasatch Formation D6-	-8
E	06.2.1.6	Undifferentiated Tertiary and Quaternary Sediments D6-	.9
Ľ	06.2.2.2	Potentiometric Surface, Groundwater Flow Direction	
		and Hydraulic GradientD6-1	3

# VOLUME 3a of 5: Appendix D (D6) continued

D6.2.2	Site H	lydrogeology	D6-10
De	5.2.2.1	Hydrostratigraphic Units	D6-10
De	5.2.2.3	Aquifer Properties	D6-15
D6.3	Groundv	vater Use	D6-20
D6.4	Groundv	vater Quality	D6-22
D6.4.1	Regio	nal Groundwater Quality	D6-22
D6.4.2	Site C	roundwater Quality	D6-25
De	5.4.2.1	Groundwater Monitoring Network and Parameter	s D6-25
De	5.4.2.2	Groundwater Quality Sampling Results	D6-26
D6.5	Hydrolo	gic Conceptual Model	D6-31
D6.5.1	Regio	nal Groundwater Conceptual Model	D6-31
D6.5.2	Site C	roundwater Conceptual Model	D6-32
De	5.5.2.1	Hydrostratigraphic Units	D6-32
De	5.5.2.2	Potentiometric Surface and Hydraulic Gradients .	D6-33
De	5.5.2.3	Aquifer Properties	D6-35
· De	5.5.2.4	Water Quality	D6-35
De	5.5.2.5	Summary	D6-36

# <u>VOLUME 4 of 5: Appendix D (D7 to D11)</u>

D7 5	Soils	D7-1
D7.1	Introduction	D7-1
D7.2	Methods	D7-1
D7.2	.1 Review of Existing Literature	D7-1
D7.2	.2 Soil Survey	D7-2
D7.2	.3 Field Sampling	D7-3
D7.2	.4 Laboratory Analysis	D7-3
D7.3	Results and Discussion	
D7.3	.1 General characteristics	D7-3
D7.3	.2 Soil Mapping Unit Interpretation	D7-4
D7.4	Topsoil Suitability	D7-5
D7.5	Topsoil Protection	D7-5
D7.6	Geotechnical Investigations	D7-5
D7.7	Historical Surface Disturbances	D7-6
D8 '	Vegetation	
D8.1	Introduction	
D8.2	Description of the Study Area	
D8.3	Methods	
D8.3	.1 Vegetation Type Identification and Mapping	
D8.3	.2 Species Composition	
D8.3	.3 Sampling Design	

Lost Creek Project WDEQ-LQD Permit to Mine Application

Original Dec07; Rev3 Apr09

# VOLUME 4 of 5: Appendix D (D7 to D11) continued

D8.3.4	Sampling Times	D8-3
D8.3.5	Collection and Analysis of Vegetation Cover Data	D8-3
D8.3.6	Collection and Analysis of Tree and Shrub Density Data.	D8-4
D8.3.7	Cropland and Prime Farmland Description	D <b>8-</b> 4
D8.3.8	Plant Species of Special Concern	D <b>8-</b> 4
D8.4 R	esults	D8-5
D8.4.1	Description of Vegetation Types	D8-5
D8.4	4.1.1 Upland Big Sagebrush Shrubland Type	D8-5
D8.4	1.1.2 Lowland Big Sagebrush Shrubland Type	D <b>8-</b> 6
D8.4.2	Sample Site Locations	D8-8
D8.4.3	Weeds, Selenium Indicators, Endangered or Threatened	
Species	D8-8	
D8.4.4	Species Composition	D8-8
D8.4.5	Sample Adequacy	D8-9
D8.5 D	iscussion	D8-9
D8.6 C	onclusions	D8-10
D9 Wild	1life	D9-1
D9.1 H	abitat Description and Wildlife Species	D9-2
D9.2 M	lethods	D9-3
D9.2.1	File and Data Searches	D9-3
D9.2.2	Field Surveys	D9-3
D9.3 R	esults	D9-4
D9.3.1	Big Game	D9-4
D9.3.2	Upland Game Birds	D9-5
D9.3.3	Raptors	D9-6
D9.3.4	Waterfowl and Shorebirds	D9-7
D9.3.5	Passerine and Breeding Birds	D9 <b>-</b> 7
D9.3.6	Migratory Birds of High Federal Interest	D9-8
D9.3.7	Other Mammals	D9-9
D9.3.8	T&E and State-Listed Species of Concern	D9-9
D9.3.9	Reptiles and Amphibians	D9-10
D9.3.10	Fish and Aquatic Life	D9-11
D10 Back	kground Radiological Characteristics	D10-1
D10.1 B	ackground Gamma Radiation Survey and Soils Sampling .	D10-1
D10.1.1	Methods	D10-2
D10	1.1.1 Gamma Surveys and Mapping	D10-2
D10	.1.1.2 Cross-Calibration between NaI Detectors and the	
	HPIC	D10-4
D10	.1.1.3 Soil Sampling and Gamma Correlation Grids	D10-5
D10.1.2	Data Quality Assurance and Quality Control	D10-6

.

# VOLUME 4 of 5: Appendix D (D7 to D11) continued

D10	0.1.3 Result	S	
	D10.1.3.1	Baseline Gamma Survey	
	D10.1.3.2	Baseline Soil Sampling	
	D10.1.3.3	HPIC / NaI Cross-Calibration	
	D10.1.3.4	Three-Foot HPIC Equivalent Gamma Ex	posure Rate
	Manua		D10.0
	Iviappi	ng	D10-9
	D10.1.3.5	Soil Ra-226 Concentration Mapping	
D11	D10.1.3.5 Wetlands	Soil Ra-226 Concentration Mapping	
D11 D11.1	D10.1.3.5 Wetlands	ng Soil Ra-226 Concentration Mapping	D10-9 D10-10 D11-1 D11-1
D11 D11.1 D11.2	D10.1.3.5 Wetlands Introduct Methods	ng Soil Ra-226 Concentration Mapping	D10-9 D10-10 D11-1 D11-1 D11-1

# VOLUME 5 of 5: Operations Plan and Reclamation Plan

Operations Plan (OP)	OP-1
OP 1.0 Overview of Proposed Operation	OP-1
OP 1.1 Site Facilities Layout	OP-2
OP 1.2 Ore Deposits	OP-3
OP 2.0 Project Development, Maintenance, and Monitoring	OP-4
OP 2.1 Project Schedule	OP-4
OP 2.2 Additional Regulatory Requirements	OP-6
OP 2.3 Land Use	OP-7
OP 2.4 Cultural Resources Mitigation Program	OP-7
OP 2.5 Topsoil Management	OP-8
OP 2.5.1 Short-Term Topsoil Protection	OP-9
OP 2.5.2 Long-Term Topsoil Protection	OP-9
OP 2.6 Roads	OP-10
OP 2.7 Vegetation Protection and Weed Control	OP-11
OP 2.8 Wildlife Protection and Monitoring	OP-12
OP 2.8.1 Wildlife Protection Measures	OP-12
OP 2.8.1.1 Activity Restrictions	OP-12
OP 2.8.1.2 Road Use	OP-12
OP 2.8.1.3 Fencing and Screening	OP-13
OP 2.8.1.4 Transmission Line	OP-13
OP 2.8.1.5 Human Disturbance	OP-13
OP 2.8.1.6 Wildlife Enhancements	OP-13
OP 2.8.2 Wildlife Monitoring	OP-14
OP 2.8.2.1 Raptors	OP-14
OP 2.8.2.2 Sage Grouse	OP-15

# VOLUME 5 of 5: Operations Plan and Reclamation Plan continued

OP 2.9 Prevention and Remediation of Accidental Releases	OP-15
OP 2.9.1 Pipelines, Fittings, Valves, and Tanks	OP-16
OP 2.9.2 Wells	OP-16
OP 2.9.3 Buildings	OP-16
OP 2.9.4 Storage Ponds	OP-16
OP 2.9.5 Fuel Storage Areas	OP-18
OP 2.10 Air Monitoring	OP-18
OP 2.11 Groundwater Monitoring	OP-18
OP 2.11.1 On-Site Wells	OP-18
OP 2.11.2 Off-Site Wells	OP-19
OP 3.0 Mine Unit Processes, Instrumentation, and Control	OP-19
OP 3.1 Mine Unit Chemistry	OP-19
OP 3.2 Mine Unit Design	OP-20
OP 3.2.1 Injection and Production Well Patterns	OP-22
OP 3.2.2 Monitor Well Locations	OP-22
OP 3.2.2.1 Perimeter Monitor Wells	OP-23
OP 3.2.2.2 Observation Wells	OP-23
OP 3.2.2.3 Production Zone Monitor Wells	OP-24
OP 3.2.2.4 Overlying and Underlying Monitor Wells	OP-24
OP 3.3 Well Completion	OP-25
OP 3.4 Well Integrity Testing	OP-26
OP 3.5 Mine Unit Piping and Instrumentation	OP-27
OP 3.6 Mine Unit Control	OP-27
OP 3.6.1 Header House Control	OP-28
OP 3.6.2 Pattern Control	OP-29
OP 3.6.3 Projected Water Balance and Water Level Changes	OP-30
OP 3.6.3.1 Water Balance	OP-30
OP 3.6.3.2 Mine Unit Interference	OP-31
OP 3.6.3.3 Cumulative Drawdown	OP-31
OP 3.6.4 Excursion Monitoring and Control	OP-33
OP 3.6.4.1 Mine Unit Baseline Water Quality and Upper	
Control Limits	. OP-33
OP 3.6.4.2 Excursion Detection	OP-34
OP 3.6.4.3 Excursion Verification and Corrective	
Action	OP-34
OP 3.6.4.4 Ability to Control an Excursion	OP-35
OP 4.0 Plant Processes, Instrumentation, and Control	OP-36
OP 4.1 Ion Exchange (Resin-Loading) Circuit	OP-36
OP 4.2 Elution Circuit	OP-37
OP 4.3 Precipitation/Filtration Circuit	OP-37
OP 4.4 Major Process Equipment and Instrumentation	OP-38

# VOLUME 5 of 5: Operations Plan and Reclamation Plan continued

OP 5.0 Effluent Control Systems	OP-38
OP 5.1 Gaseous Emissions and Airborne Particulates	OP-39
OP 5.1.1 Non-Radioactive Emissions and Particulates	OP-39
OP 5.1.2 Radioactive Emissions	OP-40
OP 5.2 Liquid Wastes	OP-40
OP 5.2.1 Liquid Non-11(e)(2) Byproduct Materials	OP-41
OP 5.2.1.1 "Native" Groundwater Recovered during Well	
Development, Sample Collection, and Pump	
Testing	<b>OP-4</b> 1
OP 5.2.1.2 Storm Water Runoff	OP-41
OP 5.2.1.3 Waste Petroleum Products and Chemicals	OP-41
OP 5.2.1.4 Domestic Liquid Waste	OP-42
OP 5.2.2 Sources of Liquid 11(e)(2) Byproduct Material	OP-42
OP 5.2.2.1 Liquid Process Waste	OP-43
OP 5.2.2.2 "Affected" Groundwater Generated during Well	
Development and Sample Collection	OP-44
OP 5.2.2.3 Groundwater Generated during Aquifer	
Restoration	OP-45
OP 5.2.3 Disposal of Liquid 11(e)(2) Byproduct Materials	OP-45
OP 5.2.3.1 Storage Ponds	OP-45
OP 5.2.3.2 UIC Class I Wells	OP-46
OP 5.3 Solid Wastes	OP-46
OP 5.3.1 Solid Non-11(e)(2) Byproduct Materials	OP-46
OP 5.3.2 Solid 11(e)(2) Byproduct Materials	OP-47
Groundwater Quality Restoration and Surface Reclamation (RP)	<b>RP-1</b>
RP 1.0 Completion of Production Operations	RP-2
RP 2.0 Plans and Schedule for Groundwater Quality Restoration	RP-3
RP 2.1 Conditions in the Mineralized Zone Before and After	
Operations	RP-3
RP 2.2 Restoration Requirements	RP-4
RP 2.3 Groundwater Restoration Methods	RP-5
RP 2.3.1 Groundwater Sweep	RP-6
RP 2.3.2 Groundwater Treatment	RP-7
RP 2.3.3 Recirculation	RP-8
RP 2.4 Stabilization Phase	RP-9
RP 2.5 Reporting	RP-9
RP 3.0 Mine Unit Reclamation	<b>RP-10</b>
RP 3.1 Well Abandonment	KP-10
RP 3.2 Facility and Road Reclamation	KP-11

# VOLUME 5 of 5: Operations Plan and Reclamation Plan continued

RP 4.0	Reclama	ation and Decommissioning of Processing and S	Support
Faciliti	es		RP-12
RP 4.1	Remo	val and Disposal of Equipment and Structures .	RP-13
RP 4.2	Waste	e Storage, Treatment, and Disposal Facilities	RP-14
RP 4.3	Burie	d Piping and Engineering Control Structures	RP-14
RP 4.4	Road	S	RP-14
RP 4.5	Soil F	Replacement and Revegetation	RP-15
RI	<b>9</b> 4.5.1	Post-Operational Land Use	
RI	P 4.5.2	Surface Preparation	RP-15
RF	P 4.5.3	Soil Replacement	RP-16
RI	P 4.5.4	Seed Mix, Reseeding Methods, and Fencing	RP-16
RI	P 4.5.5	Revegetation Success Criteria	RP-17
RP 5.0	Financia	al Assurance	RP-17

#### FIGURES

<u>VOLUME 1 of 5: Adjudication Files</u> – No Figures

#### <u>VOLUME 2 of 5: Appendix D (D1 to D5)</u>

D1 Land Use

Figure D1-1a General Location of the Permit Area

Figure D1-1b Aerial Photo of the Permit Area

Figure D1-2 Land Ownership

Figure D1-3 BLM Grazing Allotments

Figure D1-4 Nuclear Fuel Cycle Facilities and Mines within 50 Miles

Figure D1-5 Regional Transportation Network

Figure D1-6 Significant Population Centers within 50 Miles

D3 Archaeological and Paleontological Resources

(separate volume – requesting WDEQ confidentiality)

D4 Meteorology, Climatology, and Air Quality

Figure D4-1 Meteorological Stations within 50 Miles of the Permit Area

Figure D4-2 Monthly Total Precipitation in the Project Region

Figure D4-3a to m Wind Speed and Wind Direction at the Lost Soldier Meteorological Station

Figure D4-4 Tornado Statistics by County

Figure D4-5 Air Particulate Sampling Locations

Figure D4-6 Passive Radiological Sampling Locations

D5 Geology

Figure D5-1 Regional Geologic Map

Figure D5-2a Geologic Cross Section Schematic of the Permit Area

Figure D5-2b General Stratigraphy of the Upper Battle Spring Formation

Figure D5-3 Historical Seismic Activities in Wyoming

Figure D5-4 UBC Seismic Zones

Figure D5-5 Active Fault Systems in the Vicinity of the Permit Area Figure D5-6 500-Year Probabilistic Acceleration Map of Wyoming

#### <u>VOLUME 3a of 5: Appendix D (D6)</u>

D6 Hydrology

Figure D6-1 Surface Drainage Map for the Lost Creek Permit Area Figure D6-2 Longitudinal Profile along Battle Spring Draw from the Northern Boundary

Figure D6-3a Photo of Crooked Well Reservoir Taken During Spring Snowmelt Runoff Looking West

#### <u>VOLUME 3a of 5: Appendix D (D6) continued</u>

Figure D6-3b Surface Water Permits within Three Miles of the Permit Area Figure D6-4 Storm Water Sampler Installed to Collect a One-Liter Sample of Snowmelt or Storm Surface Runoff. Figure D6-5 Locations of Storm Water and Spring Snowmelt Samplers Figure D6-6 Potentiometric Surface, Wasatch/Battle Spring Aquifers, Great **Divide Basin** Figure D6-7 Regional Hydrostratigraphic Units of Interest, Great Divide Basin Figure D6-8 Potentiometric Surface, Tertiary Aquifer System, Great Divide Basin Figure D6-9 Location Map, Lost Creek Monitor Wells Figure D6-10 Site Hydrostratigraphic Units, Lost Creek Project Figure D6-11a Potentiometric Surface, HJ Production Zone, November 2007 Figure D6-11b Potentiometric Surface, Overlying Aquifer (LFG), November 2007 Figure D6-11c Potentiometric Surface, Underlying Aquifer (UKM), November 2007 Figure D6-11d Potentiometric Surface, HJ Production Zone, August 1982 and October 2006 Figure D6-12 Location of Well Groups Used to Evaluate Vertical Hydraulic Gradients Figure D6-13 Location of Pump Tests Conducted in 1982 and 2006 Figure D6-14a Location of LC19M Pump Test and Monitoring Wells, 2007 Figure D6-14b Location of LC16M Test Wells, 2007 Figure D6-15 Drawdown in the HJ Aquifer at the End of the LC19M Pumping Test Figure D6-16 Drawdown in the HJ Aquifer Near the End of the LC16M Pump Test Figure D6-17 Spatial Distribution of Aquifer Transmissivity Figure D6-18 BLM Wells near the Lost Creek Permit Area Figure D6-19 BLM Battle Spring Draw Well No. 4451 Figure D6-20 BLM Boundary Well No. 4775 Figure D6-21 BLM Battle Spring Well No. 4777 Figure D6-22 BLM East Eagle Nest Draw Well Figure D6-23 Location of Historic Site Monitor Wells Lost Creek Project

WDEQ-LQD Permit to Mine Application Original Dec07; Rev3 Apr09

#### <u>VOLUME 3a of 5: Appendix D (D6) continued</u>

Figure D6-24 Location of Site Baseline Monitor Wells
Figure D6-25a Distribution of TDS, August 1982
Figure D6-25b Distribution of Radium-226, August 1982
Figure D6-25c Distribution of Uranium, August 1982
Figure D6-26a Distribution of Average TDS, September 2006 to May 2007
Figure D6-26b Distribution of Average Sulfate, September 2006 to May 2007
Figure D6-27a Piper Diagram – Average Water Quality at Individual Monitor Wells
Figure D6-27b Piper Diagram – Average Water Quality in Aquifers of Interest
Figure D6-28a Distribution of Average Uranium, September 2006 to May 2007
Figure D6-28b Distribution of Average Radium 226+228, September 2006 to May 2007

#### <u>VOLUME 4 of 5: Appendix D (D7 to D11)</u>

D7 Soils

Figure D7-1 Typical Soil Pit

Figure D7-2 Soil Sampling Locations

Figure D7-3 Existing Road Disturbance

Figure D7-4 Typical Two-Track Road within Lost Creek Permit Area

D8 Vegetation

Figure D8-1 Vegetation Map

Figure D8-2 Upland Big Sagebrush Shrubland

Figure D8-3 Lowland Big Sagebrush Shrubland

Figure D8-4 Intergraded Upland and Lowland Big Sagebrush Shrubland

#### D9 Wildlife

Figure D9-1 Wildlife Habitat Map

Figure D9-2 Pronghorn Range

Figure D9-3 Mule Deer Range

Figure D9-4 Elk Range

Figure D9-5 Moose Range

Figure D9-6 Sage Grouse Leks

Figure D9-7 Raptor Nests

Figure D9-8 Location of Pygmy Rabbit Burrows and Pellets

Lost Creek Project WDEQ-LQD Permit to Mine Application Original Dec07; Rev3 Apr09

Xİİ

## VOLUME 4 of 5: Appendix D (D7 to D11) continued

**Background Radiological Characteristics** D10 Figure D10-1 Scanning System Equipment and Configuration Figure D10-2 Correlation Grid Sampling Design Figure D10-3 Nal-Based Gamma Survey Results Figure D10-4 NaI Gamma Survey Results and HPIC Measurement Locations Figure D10-5 OHV Re-Scan Results Figure D10-6 Soil Sampling and Gamma Survey Results Overlay Figure D10-7 Ra-226 Soil Concentration and Gamma Exposure Rate Correlation Figure D10-8 Ra-226 and Uranium Soil Concentration Correlation Figure D10-9 Calibration Curves for HPIC versus Nal Detectors Figure D10-10 Three-Foot NaI Detector Height Data Figure D10-11 Three-Foot and 4.5-Foot NaI Detector Height Readings Correlation Figure D10-12 Calculated Three-Foot-HPIC-Equivalent Gamma Exposure Rates Figure D10-13 Kriged Estimates of the Three-Foot-HPIC-Equivalent Gamma **Exposure Rates** Figure D10-14 Regression Used to Predict Soil Ra-226 Concentrations Figure D10-15 Estimated Soil Ra-226 Concentrations Wetlands D11 Figure D11-1 Potential Wetlands Delineated by the National Wetland Inventory Figure D11-2 Photo of Crooked Well Reservoir in the Spring of 2006

#### VOLUME 5 of 5: Operations Plan and Reclamation Plan

OP Operations Plan
Figure OP-1 Regional Map of the Permit Area
Figure OP-2a Site Layout
Figure OP-2b Lost Creek Ore Trend
Figure OP-2c Road Design Features
Figure OP-3 Typical ISR Operation
Figure OP-4a Lost Creek Project Development, Production, and Restoration
Schedule

Figure OP-4b Proposed Restoration Equipment Schedule

#### VOLUME 5 of 5: Operations Plan and Reclamation Plan continued

OP **Operations Plan (continued)** Figure OP-5a Project Water Balance – Production Only Figure OP-5b Project Water Balance – Production with Ground Water Sweep (GWS) Figure OP-5c Project Water Balance – Production with GWS and Reverse Osmosis (RO) Figure OP-5d Project Water Balance - Production with RO Figure OP-5e Project Water Balance – GWS and RO, No Production Figure OP-5f Project Water Balance - RO Only, No Production Figure OP-6 Alkaline Uranium Leach Chemistry in the Aquifer Figure OP-7a Solution Flow Patterns Figure OP-7b Mine Unit Layout Figure OP-7c Vegetation and Soil Impacts Figure OP-8a Injection Well Construction Figure OP-8b Production Well Construction Figure OP-8c Monitor Well Construction Figure OP-9a Well Completion Techniques Figure OP-9b Restoration Well Completions Figure OP-10a Ion Exchange Process Flow Figure OP-10b Plant Process Flow

RP Groundwater Quality Restoration and Surface Reclamation Figure RP-1 Lost Creek Project Development, Production, and Restoration Schedule

Figure RP-2 Site Layout with Mining and Restoration Schedules Figure RP-3 Proposed Bond Schedule

## TABLES

#### <u>VOLUME 1 of 5: Adjudication Files</u>

ADJ Adjudication Files Table ADJ-1 List of Regulatory Requirements

#### VOLUME 2 of 5: Appendix D (D1 to D5)

- D1 Land Use Table D1-1 Hunting Statistics for Hunt Areas that Include the Permit Area Table D1-2 Population Data
- D3 Archaeological and Paleontological Resources (separate volume – requesting WDEQ confidentiality)
- D4 Meteorology, Climatology, and Air Quality

Table D4-1 Comparison of Temperature Data

Table D4-2 Monthly Maximum and Minimum Humidity Measured at the Lost Soldier Meteorological Station

Table D4-3 Monthly Pan Evaporation at the Pathfinder Dam

Table D4-4 Air Stability Data

 Table D4-5 Primary and Secondary Limits for National Ambient Air Quality

 Standards and the State of Wyoming

Table D4-6 Allowable Increments for Prevention of Significant Deterioration of Air Quality

Table D4-7 Reported Sources of Emissions near the Permit Area

Table D4-8 Reported Total Emissions near the Permit Area

Table D4-9 PM<sub>10</sub> Concentrations at Lost Creek

Table D4-10 Analytical Results for Passive Radon and Gamma Sampling

D5 Geology

Table D5-1 Permit Area Stratigraphy

Table D5-2 Abandonment Information for Historic Exploration Holes

#### VOLUME 3a of 5: Appendix D (D6)

D6 Hydrology

Table D6-1a Peak Flow Regression Equations

Table D6-1b Calculated Peak Flows for Battle Spring Draw

Table D6-2 Surface Water Permits within Three Miles of the Permit Area

Table D6-3 Historic Water Quality Results for Battle Spring from the

Sweetwater Mill Permit Application

ΧV

#### TABLES (continued)

#### VOLUMEa 3 of 5: Appendix D (D6 to D11)

D6 Hydrology (continued)

Table D6-4 Water Quality Results for Seven Storm Water/Spring Snowmelt Samples Collected on 17 April 2007

Table D6-5 Monitor Well Data

Table D6-6 Water Level Data

Table D6-7a Horizontal Hydraulic Gradients

 Table D6-7b Vertical Hydraulic Gradients

Table D6-8 1982 and 2006 Pump Test Results

Table D6-9a 2007 LC19M Long Term Pump Test Monitor Wells

Table D6-9b 2007 LC16M Long Term Pump Test Monitor Wells

Table D6-10a 2007 LC19M Long Term Pump Test Results

Table D6-10b 2007 LC16M Long Term Pump Test Results

 Table D6-11 Summary of Aquifer Characteristics

Table D6-12a Groundwater Permits within One-Half Mile of the Permit Area

Table D6-12b Groundwater Permits within Three Miles of the Permit Area

 Table D6-13 Lost Creek Project Groundwater Permits

 Table D6-14 Baseline Water Quality Monitoring Parameters

Table D6-15a Analytical Results of Baseline Monitoring

Table D6-15b State and Federal Ground Water Quality Criteria for Specified Parameters

Table D6-16 Distribution of Samples Exceeding EPA MCL for Radium 226+228

#### VOLUME 4 of 5: Appendix D (D7 to D11)

D7 Soils

Table D7-1 Soil Mapping Units Table D7-2 Soil Suitability Ranges

D8 Vegetation

Table D8-1 Areal Extent of the Vegetation Types

Table D8-2 Vegetation Sampling Locations and Site Information

Table D8-3 Cover Parameters of the Upland Big Sagebrush Shrubland

Table D8-4 Shrub, Semi-Shrub, and Cactus Densities of the Upland Big Sagebrush Shrubland

Table D8-5 List of Vegetation Species Observed

Lost Creek Project

WDEQ-LQD Permit to Mine Application

Original Dec07; Rev3 Apr09

#### TABLES (continued)

### VOLUME 4 of 5: Appendix D (D7 to D11) continued

 Table D8-6 Cover Parameters of the Lowland Big Sagebrush Shrubland

- Table D8-7 Shrub, Semi-Shrub, and Cactus Densities of the Lowland Big Sagebrush Shrubland
- Table D8-8 Prohibited and Restricted Noxious Weeds

Table D8-9 Evaluation of Sample Adequacy

- D9 Wildlife
  - Table D9-1 Wildlife Species Observed or Potentially Occurring in the Permit Area

 Table D9-2 Relative Abundance of Big Game Observations

 Table D9-3 Sage Grouse Lek Counts

 Table D9-4 Raptor Nest Locations

Table D9-5 T&E Wildlife Species Potentially Occurring in the Permit Area

Table D9-6 Wildlife Species of Special Concern

D10 Background Radiological Characteristics

 Table D10-1 Soil Sampling and Correlation Grid Results

Table D10-2 Gamma Exposure Rate Differences from Two NaI Detector Heights

### VOLUME 5 of 5: Operations Plan and Reclamation Plan

OP Operations Plan

- Table OP-1a Summary of Environmental & Operational Monitoring During Plant Construction, Mine Unit Development, & Related Site Development Activities
- Table OP-1b Summary of Environmental & Operational Monitoring During Operations
- Table OP-1c Summary of Environmental & Operational Monitoring During Restoration/Reclamation/Decommissioning Activities & Evaluation of Activities' Effectiveness

Table OP-2 Itemized Calculations on the Areas of the Expected Disturbance Table OP-3 Culvert Sizing

Table OP-4 Potentially Disturbed Acreage by Vegetation Type

Table OP-5 Surface Activity Timing Restrictions for Protection of Wildlife

 Table OP-6 Water Balance Summary

Table OP-7 Water Balance – Calculation Details

 Table OP-8 Baseline Water Quality Monitoring Parameters

Lost Creek Project

WDEQ-LQD Permit to Mine Application

Original Dec07; Rev3 Apr09

## TABLES (continued)

**VOLUME 5 of 5: Operations Plan and Reclamation Plan (continued)** 

RP Groundwater Quality Restoration and Surface Reclamation
 Table RP-1 Restoration Groundwater Quality Parameters
 Table RP-2 Typical Specification Data for Removal of Ion Constituents
 Table RP-3 Permanent Seed Mixture
 Table RP-4 Reclamation/Restoration Bond Estimate
 Table RP-5 Equipment and Tank List for Bond Estimate

## PLATES

### VOLUME 1 of 5: Adjudication Files

Appendix A Surface and Mineral Rights within the Lost Creek Permit Area
 Plate A-1 Surface Owners of Record within Lost Creek Permit Area
 Plate A-2 Uranium Mineral Owners of Record within Lost Creek Permit Area
 Plate A-3 Oil and Gas Mineral Owners of Record within Lost Creek Permit

- Appendix B Surface and Mineral Rights Adjacent to the Lost Creek Permit Area
  - Plate B-1 Surface Owners of Record within Half Mile Outside Permit Boundary
  - Plate B-2 Uranium Mineral Owners of Record within Half Mile Outside Permit Boundary
  - Plate B-3 Oil and Gas Mineral Owners of Record within Half Mile Outside Permit Boundary
- Appendix C Tabulation of Lands Plate C-1 Legal Land Description

Appendix E Right of Ways Plate E-1 Location and Access

#### VOLUME 2 of 5: Appendix D (D1 to D5)

#### D5 Geology

Plate D5-1a Geologic Cross Section A-A'
Plate D5-1b Geologic Cross Section B-C
Plate D5-1c Geologic Cross Section C-D
Plate D5-1d Geologic Cross Section D-E
Plate D5-1e Geologic Cross Sections F-F'
Plate D5-1f Geologic Cross Sections G-G'
Plate D5-1g Geologic Cross Sections H-H'
Plate D5-2a Lost Creek Shale Isopach Map
Plate D5-2c Sagebrush Shale Isopach Map
Plate D5-2d UKM Sand Isopach Map

Lost Creek Project

WDEQ-LQD Permit to Mine Application Original Dec07; Rev3 Apr09

### PLATES (continued)

## VOLUME 3a of 5: Appendix D (D6)

D6 Hydrology

Plate D6-1a Groundwater Permits within One-Half Mile of the Permit Area Plate D6-1b Groundwater Permits within Three Miles of the Permit Area

## VOLUME 4 of 5: Appendix D (D7 to D11)

D7 Soils Plate D7-1 Soil Survey Mapping Units

#### VOLUME 5 of 5: Operations Plan and Reclamation Plan

OP Operations Plan Plate OP-1 Plant Site Plan

## ATTACHMENTS

<u>VOLUME 1 of 5: Adjudication Files</u> – No Attachments

# VOLUME 2 of 5: Appendix D (D1 to D5)

D3	Archaeological and Paleontological Resources
	(separate volume – requesting WDEQ confidentiality)
D5	Geology
	Attachment D5-1 Typical Geophysical Logs
	Attachment D5-2 Locations, Total Depths, and Completion Dates of
	Historical Drill Holes
	Attachment D5-3 Communication with WDEQ LQD related to Drill Hole
	Abandonment

### VOLUME 3a of 5: Appendix D (D6)

D6 Hydrology
 Attachment D6-1 Surface Water Quality Laboratory Results
 Attachment D6-2a Evaluation of the LC19M Pump Test
 Attachment D6-2b Evaluation of the LC16M Pump Test

### VOLUME 3b of 5: Appendix D (D6)

D6 Hydrology Attachment D6-3 Well Completion Logs Attachment D6-4 Groundwater Quality Laboratory Results

# VOLUME 4 of 5: Appendix D (D7 to D11)

D7 Soils

Attachment D7-1 Soil Survey Work Plan and Correspondence Attachment D7-2 Field Notes/Soil Sample Point Photographs Attachment D7-3 Laboratory Analysis

D8 Vegetation
Attachment D8-1 Scope of Work
Attachment D8-2 Raw Data
Attachment D8-3 Sensitive Plant Probability

## ATTACHMENTS (continued)

## VOLUME 4 of 5: Appendix D (D7 to D11) continued

D9 Wildlife

Attachment D9-1 WGFD Wildlife Observations System Data
Attachment D9-2 Work Plan for Wildlife 2007
Attachment D9-3 BLM and WDEQ Correspondence
Attachment D9-4 MBHFI in Wyoming
D10 Background Radiological Characteristics
Attachment D10-1 Data Quality Assurance Documentation

Attachment D10-2 Data Quality Control Documentation

Attachment D10-3 Final Baseline Gamma Survey and Ra-226 Soil Maps

Attachment D10-4 HPIC-Adjusted Gamma Datasets (Electronic Dataset Only)

## VOLUME 5 of 5: Operations Plan and Reclamation Plan

OP Operations Plan

Attachment OP-1 UIC Class 1 Well Permit (to be provided) Attachment OP-2 Specifications for Storage Ponds

#### TABLE OF CONTENTS

D5	GeologyD5-1
D5.1	Regional GeologyD5-1
D5.1.1	StratigraphyD5-1
D5.1.2	Structure
D5.2	Site GeologyD5-2
D5.2.1	StratigraphyD5-3
D5.2.2	Structure
D5.2.3	Ore Mineralogy and GeochemistryD5-4
D5.2.4	Subsurface Exploration Activities
D5.2.4.1	Uranium ExplorationD5-6
D5.2.4.2	Other Mineral ExplorationD5-8
D5.3	SeismologyD5-8
D5.3.1	Historic SeismicityD5-8
D5.3.1.1	Town of Bairoil AreaD5-8
D5.3.1.2	City of Rawlins AreaD5-9
D5.3.1.3	City of Rock Springs AreaD5-10
D5.3.1.4	City of Lander AreaD5-10
D5.3.1.5	City of Casper AreaD5-11
D5.3.2	Uniform Building CodeD5-12
D5.3.3	Deterministic Analysis of Active Fault Systems
D5.3.4	Maximum Tectonic Province Earthquake "Floating
	Earthquake" Seismogenic Source
D5.3.5	Short-Term Probabilistic Seismic Hazard Analysis D5-14

#### FIGURES

Figure D5-1 Regional Geologic Map

Figure D5-2a Geologic Cross Section Schematic of the Permit Area

Figure D5-2b Stratigraphy Column, Upper Battle Spring Formation

Figure D5-3 Historical Seismic Activities in Wyoming

Figure D5-4 UBC Seismic Zones

Figure D5-5 Active Fault Systems in the Vicinity of the Permit Area

Figure D5-6 500-Year Probabilistic Acceleration Map of Wyoming

#### TABLES

Table D5-1 Permit Area Stratigraphy

Table D5-2 Abandonment Information for Historic Exploration Holes

### PLATES

Plate D5-1a Geologic Cross Section A-A Plate D5-1b Geologic Cross Section B-C Plate D5-1c Geologic Cross Section C-D Plate D5-1d Geologic Cross Section D-E Plate D5-1e Geologic Cross Section F-F' Plate D5-1f Geologic Cross Section G-G' Plate D5-1g Geologic Cross Section H-H' Plate D5-2a Lost Creek Shale Isopach Map Plate D5-2b HJ Sand Isopach Map Plate D5-2c Sagebrush Shale Isopach Map Plate D5-2d UKM Sand Isopach Map

#### ATTACHMENTS

Attachment D5-1 Typical Geophysical Logs

Attachment D5-2 Locations, Total Depths, and Completion Dates of Historical Drill Holes

Attachment D5-3 Communication with WDEQ LQD related to Drill Hole Abandonment

# D5 GEOLOGY

# D5.1 Regional Geology

The Great Divide Basin (Basin) is an oval-shaped structural depression, encompassing some 3,500 square miles in south-central Wyoming. The Basin is bounded on the north by the Wind River Range and Granite Mountains, on the east by the Rawlins Uplift, on the south by the Wamsutter Arch and on the west by the Rock Springs Uplift. The regional geologic map is shown in **Figure D5-1**. Geologic development of the Basin began in the Late Cretaceous and continued through much of the Early Eocene.

# D5.1.1 Stratigraphy

The earliest sedimentation in the Basin was the Paleocene (Early Tertiary) Fort Union Formation, which was unconformably deposited on the Lance Formation of Late Cretaceous age. The Fort Union Formation consists mostly of lacustrine shales, siltstones, and thin sandstones, which locally contain lignite beds. The thickness of the Fort Union Formation varies from place to place in the Basin, and it is approximately 4,650 feet thick in the Permit Area.

The Fort Union Formation is unconformably overlain by sediments of Eocene age, making up about 6,200 feet of basin fill. The western and southern portions of the Basin are covered by the Wasatch Group, which consists of sandstone, siltstone, limestone, conglomerate and lignite beds. The rocks in the Wasatch Group are believed to be of fluvial-lacustrine origin. Towards the north and northeast, the Wasatch Group rapidly grades into and inter-tongues with the equally thick, fine- to coarse-grained arkosic sandstones and conglomerates of the Battle Spring Formation, a typical alluvial fan complex. The source of the Battle Spring sediments is believed to be the ancestral Granite Mountains to the north. Pliocene pediment deposits and recent alluvium cover large areas of the surface in the Basin. <u>Table D5-1</u> and <u>Figure D5-2a</u> show the general stratigraphy of the Basin.

The upper portion of the Battle Spring Formation is the host to the uranium mineralization in the Permit Area. In the Permit Area, the top 700 feet of the Battle Spring Formation is divided into at least five horizons marked from top to bottom as BC, DE, FG, HJ, and KM. These horizons are separated from one another by various thicknesses of shale, mudstone and siltstone (**Figure D5-2b**).

# D5.1.2 Structure

The present physiographic feature of the Basin was generated by the Laramide Orogeny. During the Late Cretaceous and Early Tertiary, the structures surrounding the Basin were either rejuvenated or were formed, transforming the area into a bowl-shaped geological structure, the Basin. During this upheaval, the Wind River Mountains and Granite Mountains were uplifted on the north side of the Basin. The Rawlins Uplift formed to the east; the Wamsutter Arch formed to the south; and the Rock Spring Uplift formed to the west. All of these highs formed a ring around the Basin, turning the Basin into a bowllike structure with drainage being inward. The Continental Divide, extending from the south, splits into two and forms half circles on the east and west sides of the Basin, joining again as one topographic high on the north side of the Basin.

The Basin is asymmetrical with its major axis trending west-northwest. Several anticlines and synclines have been mapped within the Basin, and some of these features are oil-bearing (at much deeper levels than the uranium-bearing formations). Noteworthy among these structures is the Lost Soldier anticline in the northeastern part of the Basin, approximately 15 miles northeast of the Permit Area. The Battle Spring and Fort Union formations, as well as older rocks crop out in the anticline; and the formations on the southwestern flank of the anticline dip 20 to 25 degrees to the southwest. The dip gradually becomes gentler, and, at the Permit Area, it is merely three degrees to the west.

Contemporaneous with the uplift of the mountains surrounding the Basin, there were episodes of normal and thrust faulting within and around the Basin. Most of the major faults are located in the northern part of the Basin, with displacement ranging from a few feet to over 3,000 feet. But, toward the center of the Basin near the Permit Area, faulting seems to be only on a minor scale. For example, the displacement at the Lost Creek Fault (Fault) which traverses the mineralized area from west-southwest to east-northeast is zero to about 80 feet. More details about the Fault are given in Section D5.2.2.

# D5.2 Site Geology

The Permit Area is located near the north-central part of the Basin, where the Basin fills are predominantly the Eocene Battle Spring Formation and the Paleocene Fort Union Formation. Geological cross sections throughout the Permit Area are presented in <u>Plates</u> <u>D5-1a</u>, <u>b</u>, <u>c</u>, <u>d</u>, <u>e</u>, <u>f</u>, and <u>g</u>. <u>Attachment D5-1</u> contains copies of typical geophysical logs from the Permit Area.

## D5.2.1 Stratigraphy

The entire Permit Area is covered by the upper part of the Battle Spring Formation, which is the host to uranium mineralization. Generally, in the Basin, Battle Spring and Wasatch formations, which are time equivalent, interfinger with one another. In the Permit Area, the upper half of the lithologic units consists of Battle Spring Formation and the lower half is made up of Wasatch Formation. The total thickness of the Battle Spring and Wasatch formations under the Permit Area is about 6,200 feet. The Fort Union Formation is 4,650 feet thick beneath the Permit Area and unconformably underlies the Battle Spring/Wasatch formations. Deeper in the Basin and lying unconformably are various Cretaceous, Jurassic, Triassic, Paleozoic, and Precambrian basement lithologic units (**Table D5-1**). A schematic geologic cross section across the Permit Area is shown in **Figure D5-2a**, depicting all lithologic units present under the Permit Area.

The Battle Spring Formation in the Permit Area is part of a major alluvial system, consisting of thick beds of very fine- to coarse-grained arkosic sandstones separated by various layers of mudstones and siltstones. Conglomerate beds may exist locally. The uranium mineralization is associated with finer-grained sandstones and siltstones, which may contain minor organic matter in a few areas. At least five horizons with various amounts of mineralization have been identified. From the surface down, they have been named: BC, DE, FG, HJ, and KM. The two horizons with the most mineralization are HJ and KM, which have been further divided into upper, middle and lower sub-units of sandstones (UHJ Sand, MHJ Sand, and LHJ Sand; and UKM Sand, MKM Sand, and LKM Sand). Geological cross sections through the mineralized zones in the Permit Area are presented in <u>Plates D5-1a</u>, <u>b</u>, <u>c</u>, <u>d</u>, <u>e</u>, <u>f</u>, and <u>g</u>. Thickness (isopach) maps of the HJ Horizon and UKM Sand, as well as the shales above the HJ Horizon (Lost Creek Shale) and below the HJ Horizon (Sage Brush Shale), are presented in <u>Plates D5-2a</u>, <u>b</u>, <u>c</u>, and <u>d</u>.

The HJ Horizon is 110 to 130 feet thick, averaging about 120 feet. The thinner part of HJ is generally south of the Fault. A thicker part of the HJ Horizon runs parallel to the Fault, trending in a west-southwest to east-northeasterly direction. The mineralization is mostly concentrated in the middle part of the HJ Horizon and occurs as both roll front and tabular deposits. The subdivided sand units within the HJ Horizon are separated by discontinuous shale, siltstone and mudstones.

The UKM Sand lies under the Sage Brush Shale and is 20 to more than 60 feet thick, averaging about 40 feet. In the eastern part of the Permit Area, the unit is 20 to 50 feet thick; whereas the sand unit in the western portion of the permit area is 40 to more than 60 feet thick, indicating the development of a major paleo-channel. The mineralization occurs as both roll front and tabular deposits.

# D5.2.2 Structure

The geologic structure in the Permit Area is illustrated on the cross sections (<u>Plates D5-1a</u>, <u>b</u>, <u>c</u>, <u>d</u> and <u>e</u>) and isopach maps (<u>Plates D5-2a</u>, <u>b</u>, <u>c</u>, and <u>d</u>). In the Permit Area, the Battle Spring Formation dips gently to the northwest at roughly three degrees. This pattern is broken locally by a fault referred to as the Lost Creek Fault (i.e., the Fault). The Fault was initially interpreted to be a scissor fault, with a reversal of displacement direction occurring in the western third of the Permit Area. Recent interpretation has revealed that it is, instead, a sequence of sub-parallel faults with opposite displacement occurring in an en echelon configuration.

The 'main' fault trends east-westerly and dissects the eastern two-thirds of the Permit Area. Downward displacement occurs on the south block. Throw is approximately 70 ft to 80 ft within the eastern portion, decreasing to approximately 20 ft to 40 ft in the central portion, and eventually losing identity in the western one-third of the Permit Area.

A subsidiary, sub-parallel fault becomes apparent south of the main fault and in the general vicinity where the main fault loses identity. It continues westerly to the western edge of the Permit Area. Direction of throw on this fault is opposite to the main fault; i.e., downthrown to the north. Displacement ranges from approximately 40 ft to 50 ft in the east, decreasing to 20 ft to 30 ft to the west.

# D5.2.3 Ore Mineralogy and Geochemistry

The age of mineralization in the Battle Spring Formation is considered to be between 35 and 26 million years before present. Uranium mineralization in the Basin generally occurs either as tabular or C-shaped roll-front deposits. Oxygen-rich surface water, carrying dissolved uranium, entered various sandstones in the Basin. The water percolated down dip, oxidizing the sandstones on its way down dip. Upon reaching sites rich in organic matter, the water lost its oxidizing potential and deposited the uranium, forming the two types of mineralization mentioned above.

Tabular deposits may form at the interface between oxidizing and reducing conditions (the redox front), where oxidation, for all practical purposes, stops. Localized tabular deposits may also form up-dip from the redox front in an entirely oxidized zone, where carbonaceous materials have gathered and formed locally reducing conditions.

The C-shaped roll-front deposits normally form just at the redox front, where the water loses its oxidizing potential. The uranium precipitates and accumulates in a "C"-shaped deposit, with the concave side facing up-dip toward the oxidized sand. Uranium usually accumulates in finer-grained sandstones that carry various amounts of organic matter, which provides a reducing condition.

The alteration process not only changes the color, but also alters the mineralogy of the host sandstones. The color of unaltered, reduced sandstone is light to dark grey, with carbon trash, dark accessories, and traces of pyrite. Altered, oxidized, sandstone contains iron oxide staining (where former carbonaceous matter and pyrite were present), kaolinized feldspar, and has a pink to tan-buff, greenish-grey to bleached appearance. The presence of pyrite and carbonaceous material appear to be the major controlling factors for the precipitation of uranium mineralization. Thinning of sandstones and diminishing grain size probably slowed the advance of the uranium-bearing solutions and further enhanced the chances of precipitation.

The main uranium minerals are uraninite, a uranium oxide, and coffinite, a uranium silicate. Russell Honea (1979) and John V. Heyse (1979) studied several core samples by scanning electron microprobe (SEM), polished section and thin section. Their conclusions were that the host sands are fine- to coarse-grained, poorly sorted arkose. The uranium mineralization is of sub-microscopic size and can be seen only in SEM magnification. They are associated and at times intergrown with round pyrite particles. The uranium minerals identified are mostly uraninite and, possibly, coffinite. The uranium, besides occurring with pyrite, also occurs as a coating around sand grains and as filling of voids between grains. It also occurs as minute particles within larger clay particles.

The most recent study of the lithology and mineralogy was conducted by Hazen Research under the guidance of Dr. Nick Ferris, Ur-E geologist (Ferris, 2007, company report). He concluded that the rocks, represented by a core sample from a depth of 506 to 507 feet of Hole Number LC-64C, are composed of medium- to coarse-grained sand with interstitial clay and silt. Uranium occurrences are very fine-grained and micron-sized, and are mainly dispersed throughout some of the interstitial clays, and occur similarly in some of the interstitial pyrite as well. Because of the size of uranium mineral particles, it was not certain whether the uranium mineral was coffinite or uraninite. The sample tested, comes from the Upper KM Sand unit and may or may not be representative of the majority of the mineralization in the overlying HJ Horizon within the Permit Area.

Known mineralized intervals are found at depths ranging from near surface down to 1,150 feet below the surface in the Permit Area. It is possible that deeper mineralization may exist as well. The main mineralization horizons trend in an east-northeast direction for at least three miles, and are up to 2,000 feet wide. The thickness of individual

mineralized beds at the Permit Area ranges from five to 28 feet and averages about 16 feet. The mineralization grade ranges from 0.03 percent to more than 0.20 percent equivalent uranium oxide ( $eU_3O_8$ ). Four main mineralized horizons, from depths of 300 to 700 feet, have been identified. The richest mineralized zone occurs in the middle part of the HJ Horizon (MHJ Sand) and it is about 30 feet thick, 400 to 450 feet deep, and is believed to contain more than 50 percent of the total resource under the Permit Area.

# D5.2.4 Subsurface Exploration Activities

# D5.2.4.1 Uranium Exploration

Historic and current uranium explorations exist in several areas of the Basin. Historic exploration activities in the Permit Area can be summarized as follows:

- Pre-1976: Numerous companies held the property; uranium mineralization was discovered by Climax Uranium and Conoco.
- 1976: Texasgulf optioned property from Valley Development Inc.
- 1977 through 1979: Texasgulf optioned property from Valley Development Inc., delineated the main trend of the mineralization, obtained a 50-percent interest in the Conoco claims on the trend to the east, and exercised its option with Valley Development Inc.
- 1986: Power Nuclear Corporation acquired the properties.
- 2000: Power Nuclear Corporation sold its Lost Creek properties to New Frontiers Uranium, LLC.
- 2005: New Frontiers Uranium, LLC transferred its Wyoming properties and data including its Lost Creek property to NFU.
- 2005: Ur-Energy USA Inc. purchased NFU from New Frontiers Uranium, LLC on terms.
- 2007: Ur-Energy USA Inc. completes the acquisition of NFU from New Frontiers Uranium, LLC, and maintains NFU as a wholly owned subsidiary.
- 2007: Ur-Energy USA Inc. forms Lost Creek ISR, LLC (LC ISR, LLC) to develop the Lost Creek property into an ISR facility and transfers the Lost Creek property from NFU to LC ISR, LLC.

At least 560 uranium exploration holes had been drilled in Permit Area prior to 2000. The plates and table in <u>Attachment D5-2</u> present the locations and total depths of all the known historic drill holes drilled in the Permit Area. The information that LC ISR LLC has pertaining to historic drill hole abandonment and re-plugging is provided in <u>Table D5-2</u>, including total depths of holes.

There have been continuing efforts over the years to ensure that drill holes are properly abandoned. In the early 1980s, the Conoco/Texasgulf Joint Venture worked to correct a WDEQ LQD violation resulting from incorrect surface capping and hole abandonment. Copies of the memos to WDEQ LQD explaining the work are included as <u>Attachment</u> <u>D5-3</u>. WDEQ-LQD subsequently approved the hole abandonment and released the bond.

In 2006, LC ISR, LLC re-located and re-abandoned twelve historic holes (<u>Table D5-2</u>). A drill rig was placed on each hole, and the hole was reamed/washed to 650 fbs A mixture of BH Thermal Grout, exceeding WDEQ-LQD Rules and Regulations Chapter 8 requirements, was pumped into the hole as the drill stem was retrieved. No effort was made to determine the depth of historic drill mud but the rig did have to ream/wash out mud from each hole. The upper 25 feet of each hole was plugged with cement. An attempt to relocate three additional holes was unsuccessful. LC ISR, LLC supplied this information to WDEQ-LQD in a letter dated January 15, 2007 (<u>Attachment D5-3</u>). In 2008, geologists discovered four historic holes with failed surface caps (Holes TT31, TT80, TT96, and TT141). Drill rigs were put on each of the four holes so they could be re-plugged. In each case, the drill stem was lowered between 180 and 220 fbs before hitting significant resistance. The holes were washed out and re-plugged to surface using grout. Each hole was also re-capped. <u>Table D5-2</u> contains information pertaining to the re-abandonment of these four holes.

Some pumping tests have shown very minor communication between the overlying and underlying aquifers and the HJ horizon (Section 6.2.2.3). There are several possible reasons for this communication, one of which is leakage through an improperly abandoned drill hole(s). However, the consistent nature of the response, regardless of distance from the pumping well, suggests that leakage through an improperly abandoned hole(s) is not the most likely cause of communication. Other more likely causes are: pumping from other wells in the area; regional communication between aquifers; background trends; or leakage through the juxtaposed aquifers across the fault.

If additional, improperly abandoned drill holes are found in the future, LC ISR, LLC will plug the holes as described above. In particular, before operations begin in a mine unit, a field inspection will be performed to locate any historic holes with surface capping issues. If the inspection identifies any capping problems, the hole will be re-entered with a drill rig or tremie pipe and re-plugged with grout. A new cement surface cap will also be installed. Aquifer testing of the mine unit prior to operation will also help identify any improperly abandoned holes that could interfere with mine unit operation.

# D5.2.4.2 Other Mineral Exploration

Historic and current oil and gas exploration drilling are also in the region. There are no current oil and gas activities within the Basin that are completed in the same horizons as those discussed for ISR production in this application. The nearest significant gas fields are approximately ten miles to the southwest; therefore, no interference is anticipated between oil and gas production activities and ISR activities. There is no exploration of coal bed methane or other mineral resources within the Permit Area and the nearby region.

# D5.3 Seismology

The discussion of the seismology of the Permit Area and surrounding areas includes: an analysis of historic seismicity; an analysis of the Uniform Building Code (UBC); a deterministic analysis of nearby faults; an analysis of the maximum credible "floating earthquake;" and a discussion of the existing short- and long-term probabilistic seismic hazard analysis. The materials presented here are mainly based on the seismologic characterization of Sweetwater, Carbon, Fremont, and Natrona Counties by James C. Case and others from the Wyoming State Geological Survey (Case et al., 2002a, 2002b, 2002c and 2003).

# D5.3.1 Historic Seismicity

The Permit Area is located in the north-eastern portion of the Basin, in south-central Wyoming. Historically, south-central Wyoming has had a low to moderate level of seismicity compared to the rest of the State of Wyoming. As shown in <u>Figure D5-3</u>, most of the historical earthquakes occurred in the west-northwest portion of Wyoming. Significant historical earthquakes adjacent to the Permit Area are described below, and are organized by areas in which they occurred.

# D5.3.1.1 Town of Bairoil Area

Bairoil is located about 15 miles northeast of the Permit Area. Historically, there have been only a few earthquakes that have occurred within 20 miles of Bairoil. On August 11, 1916, a non-damaging intensity III earthquake occurred approximately 17 miles northwest of Bairoil. On June 1, 1993, a non-damaging magnitude 3.8, intensity III earthquake occurred four miles north of Bairoil, and was felt by some residents. On

December 10, 1996, a non-damaging magnitude 2.6 earthquake occurred approximately ten miles northwest of Bairoil. A few residents also felt that event.

Two recent earthquakes were recorded near Bairoil in 2000. On May 26, 2000, a magnitude 4.0 earthquake occurred, followed by another (magnitude 2.8) four days later, on May 30, 2000. Both earthquakes were located about 3.5 miles southwest of Bairoil. Most residents in Bairoil felt the first earthquake. No significant damage was associated with either seismic event (Cook, 2000).

# D5.3.1.2 City of Rawlins Area

Rawlins is approximately 38 miles southeast of the Permit Area. The first recorded earthquake that was felt and reported immediately southwest of Rawlins occurred on March 28, 1896. The intensity IV earthquake shook for about two seconds. On March 10, 1917, an earthquake (intensity IV) was recorded approximately one mile northeast of Rawlins. The earthquake was felt as a distinct shock that caused wooden buildings to noticeably vibrate. Stone buildings were not affected by the event (*Rawlins Republican*, 1917).

On September 10, 1964, a magnitude 4.1 earthquake occurred approximately 30 miles west of Rawlins. One Rawlins resident reported that the earthquake caused a crack in the basement of his home in Happy Hollow. No other damage was reported (*Daily Times*, 1964).

Small earthquakes were detected, on April 13, 1973, May 30, 1973, and June 1, 1973, approximately six miles west of Hanna. No one reported feeling these events. On July 11, 1975, Rawlins residents felt an earthquake (intensity II) event. On January 27, 1976, an earthquake (magnitude 2.3, intensity V) occurred approximately 12 miles north of Rawlins. Several people reported that they were thrown out of bed (*Daily Times*, 1976). On March 3, 1977, an earthquake (intensity V) was reported approximately 18.5 miles west-northwest of Encampment. Doors and dishes were rattled in southern Carbon County homes; but no significant damage was reported (*Laramie Daily Boomerang*, 1977).

On April 13, 1991 and April 19, 1991, magnitude 3.2 and magnitude 2.9 earthquakes, respectively, occurred near the center of the Seminoe Reservoir. A magnitude 3.1 earthquake occurred on December 18, 1991, southwest of the Seminoe Reservoir, approximately 15 miles northeast of Sinclair. No one reported feeling these Seminoe-Reservoir-area earthquakes. On August 6, 1998, a magnitude 3.6 earthquake occurred approximately 13 miles north of Rawlins. Residents in Rawlins reported hearing a sound and then feeling a jolt. On April, 1999, a magnitude 4.3 earthquake occurred

approximately 29 miles north-northwest of Baggs. It was felt in Rawlins; and residents reported that pictures fell off the walls.

# D5.3.1.3 City of Rock Springs Area

Rock Springs is located approximately 80 miles southwest of the Permit Area. The first recorded earthquake that was felt in Sweetwater County occurred on April 28, 1888. This intensity IV earthquake, which originated near Rock Springs, did not cause any appreciable damage. On July 25, 1910, an intensity V earthquake occurred at the same time that the Union Pacific Number One Mine in Rock Springs partially collapsed. On July 28, 1930, an intensity IV earthquake, with an epicenter near Rock Springs, was felt in Rock Springs and Reliance (*Casper Daily Tribune*, 1930). The earthquake awakened many residents; and some merchandise fell off of store shelves.

On March 21, 1942, a non-damaging, intensity III earthquake was felt in the Rock Springs area. This event was followed, on September 14, 1946, by an intensity IV earthquake. On October 25, 1947, a small earthquake with no assigned intensity or magnitude occurred southeast of Rock Springs. Two intensity IV earthquakes occurred in the Rock Springs area on September 24, 1948. The events rattled dishes in parts of Rock Springs.

A magnitude 3.9 event was recorded on January 5, 1964, approximately 23 miles south of Rock Springs. The University of Utah Seismograph Stations detected a non-damaging, magnitude 2.4 earthquake on March 19, 1968. This event was centered approximately 17 miles southeast of Rock Springs. A magnitude 3.2 event occurred on May 29, 1975, approximately 13 miles northeast of Superior. A week later, on June 6, 1975, a magnitude 3.7 earthquake was recorded in the same area. No damage was associated with any of the 1975 events.

The University of Utah Seismograph Stations recorded a non-damaging magnitude 2.7 earthquake on June 5, 1986. This event was located approximately 14 miles southwest of Green River, Wyoming.

On February 1, 1992, the University of Utah Seismograph Stations recorded a nondamaging magnitude 2.3 earthquake, approximately seven miles north of Rock Springs.

# D5.3.1.4 City of Lander Area

Lander is about 70 miles northwest of the Permit Area. A number of earthquakes have occurred in the Lander area. The first reported earthquake occurred on January 22, 1889, and had an intensity of III to IV. This was followed by an intensity IV event on

November 21, 1895, during which houses were jarred and dishes rattled. On November 23, 1934, an intensity V earthquake was centered approximately 20 miles northwest of Lander. For a radius of ten miles around Lander, residents reported that dishes were thrown from cupboards, and that pictures fell down from the walls. Cracks were found in buildings along two business blocks; and the brick chimney of the Fremont County Courthouse was separated by two inches from the building. The earthquake was felt at Rock Springs and Green River, Wyoming (*Casper Tribune-Herald*, 1934).

There were a series of earthquakes in the Lander area in the 1950s that caused little damage. On August 17, 1950, there was an intensity IV earthquake that caused loose objects to rattle and buildings to creak. On January 12, 1954, there was an intensity II event; and on December 13, 1955, there was an intensity IV event near Lander, with no damage reported.

On June 14, 1973, a small earthquake was reported about eight miles east-northeast of Lander. The earthquake has been recently interpreted as a probable explosion. On January 31, 1992, a non-damaging magnitude 2.8 earthquake occurred approximately 20 miles northwest of Lander. This event was followed, on October 10, 1992, by a magnitude 4.0, intensity III earthquake centered approximately 22 miles east of Lander.

# D5.3.1.5 City of Casper Area

Casper is located about 90 miles northeast of the Permit Area. Two of the earliest recorded earthquakes in Wyoming occurred near Casper. The first was on June 25, 1894, and had an estimated intensity of V. In residences on Casper Mountain, dishes rattled and fell on the floor and people were thrown from their beds. Water in the Platte River changed from fairly clear to reddish, and became thick with mud, due to the river banks slumping into the river during the earthquake. On November 14, 1897, an even larger event was felt. An intensity VI to VII earthquake, one of the largest recorded in central and eastern Wyoming, caused considerable damage to a few buildings. As a result of the earthquake, a portion of the Grand Central Hotel was cracked from the first to the third story. Some of the ceilings in the Grand Central Hotel were also severely damaged.

On October 25, 1922, an intensity IV earthquake was reported in the Casper area. The event was felt in Casper; at Salt Creek, 50 miles north of Casper; and at Bucknum, 22 miles west of Casper. Dishes were rattled and hanging pictures were tilted near Salt Creek. No significant damage was reported in Casper (*Casper Daily Tribune*, 1922). On December 11, 1942, an intensity IV earthquake was recorded north of Casper. Although no damage was reported, the event was felt in Casper, Salt Creek, and Glenrock (*Casper Tribune-Herald*, 1941). On August 2, 1948, another intensity IV earthquake was reported in the Casper area. No damage was reported (*Casper Tribune-Herald*, 1948). In
the 1950s, two earthquakes caused some concern among Casper residents. On January 24, 1954, an intensity IV earthquake near Alcova did not result in any reported damage (*Casper Tribune-Herald*, 1954). On August 19, 1959, an intensity IV earthquake was felt in Casper. Most recently, on October 19, 1996, a magnitude 4.2 earthquake was recorded approximately 15 miles north-northeast of Casper. No damage was reported.

## D5.3.2 Uniform Building Code

With safety in mind, the UBC provides Seismic Zone Maps to help identify which building design factors are critical to specific areas of the country. Five UBC seismic zones are recognized, ranging from Zone 0 to Zone 4. These seismic zones are, in part, defined by the probability of having a certain level of ground shaking (horizontal acceleration) in 50 years. The criteria used for defining boundaries on the Seismic Zone Map were established by the Seismology Committee of the Structural Engineers Association of California (SEAOC, 1986). The criteria they developed are as follows:

- Zone 4:  $\geq$  30 percent gravity (g) effective peak acceleration;
- Zone 3: 20 to  $\leq$  30 percent g effective peak acceleration;
- Zone 2: 10 to  $\leq$  20 percent g effective peak acceleration;
- Zone 1: 5 to  $\leq$  10 percent g effective peak acceleration; and
- Zone 0:  $\leq$  5 percent g effective peak acceleration.

The Seismology Committee of the Structural Engineers Association of California assumed that there was a 90 percent probability that the above values would not be exceeded in 50 years, or a 100 percent probability that the values would be exceeded in 475 years.

**Figure D5-4** shows the delineation of UBC seismic zones in Wyoming. The Permit Area is located in Seismic Zone 1. Since effective peak accelerations (90 percent chance of non-exceedance in 50 years) can range from five to ten percent g in Zone 1, it may be reasonable to assume that an average peak acceleration of 7.5 percent g could be applied to the design of a non-critical facility located near the center of Zone 1.

## D5.3.3 Deterministic Analysis of Active Fault Systems

There are two active fault systems in the vicinity of the Permit Area, the Chicken Springs Fault System and the South Granite Mountain Fault System (Figure D5-5).

The Chicken Springs Fault System, located six miles east of the Permit Area, is composed of a series of east-west trending segments. In 1996, the Wyoming State

Geological Survey investigated this fault system, and determined that the most recent activity on the system appears to be Holocene in age. Reconnaissance-level studies indicated that the fault system is capable of generating a magnitude 6.5 earthquake (Case et al., 2002a). A magnitude 6.5 earthquake on the Chicken Springs Fault System would generate peak horizontal accelerations of approximately 4.8 percent g at Rawlins (Case et al., 2002a). These accelerations would be roughly equivalent to an intensity V earthquake, which may cause some light damage. Bairoil, however, would be subjected to a peak horizontal acceleration of approximately 23 percent g, or an intensity VII earthquake (Case et al., 2002a). Intensity VII events have the potential to cause moderate damage.

The South Granite Mountain Fault System is located about 14 miles northeast of the Permit Area. This fault system is composed of several northwest-southeast trending normal and thrust faults in southeastern Fremont County and northwestern Carbon County. The active segments of the system have been assigned a maximum magnitude of 6.75, which could generate peak horizontal accelerations of approximately 20 percent g at Bairoil and 6.1 percent g at the Rawlins (Case et al., 2002a). These accelerations would be roughly equivalent to an intensity VII earthquake at the Bairoil and an intensity V earthquake at Rawlins. Bairoil could sustain moderate damage; whereas minor or no damage could occur at Rawlins.

## D5.3.4 Maximum Tectonic Province Earthquake "Floating Earthquake" Seismogenic Source

Tectonic provinces are regions with a uniform potential for the occurrence of earthquakes that are tied to buried faults with no surface expression. Within a tectonic province, earthquakes associated with buried faults are assumed to occur randomly, and, as a result, can theoretically occur anywhere within that area of uniform earthquake potential. In reality, that random distribution may not be the case, as most earthquakes are associated with specific faults. If all buried faults have not been identified, however, the distribution has to be considered random. "Floating earthquakes" are earthquakes that are considered to occur randomly in a tectonic province.

The US Geological Survey (USGS) identified tectonic provinces in a report titled "Probabilistic Estimates of Maximum Acceleration and Velocity in Rock in the Contiguous United States" (Algermissen et al., 1982). In that report, Sweetwater County was classified as being in a tectonic province with a "floating earthquake" maximum magnitude of 6.1. Geomatrix (1988) suggested using a more extensive regional tectonic province, called the "Wyoming Foreland Structural Province," which is approximately defined by the Idaho-Wyoming Thrust Belt on the west, 104 degrees West longitude on the east, 40 degrees North latitude on the south, and 45 degrees North latitude on the

north. Geomatrix (1988) estimated that the largest "floating earthquake" in the "Wyoming Foreland Structural Province" would have a magnitude in the 6.0 to 6.5 range, with an average value of magnitude 6.25.

## D5.3.5 Short-Term Probabilistic Seismic Hazard Analysis

The USGS publishes probabilistic acceleration maps for 500-; 1,000-; and 2,500-year time frames. The maps show what accelerations may be met or exceeded in those time frames by expressing the probability that the accelerations will be met or exceeded in a shorter time frame. For example, a ten percent probability that acceleration may be met or exceeded in 50 years is roughly equivalent to a 100 percent probability of exceedance in 500 years.

The 500-year map provides accelerations that are comparable to those derived from the UBC and from the deterministic analysis on the Green Mountain Segment of the South Granite Mountain Fault System. It was often used for planning purposes for average structures. Based on the 500-year map (ten percent probability of exceedance in 50 years), the estimated peak horizontal acceleration in the Permit Area is approximately 6.5 percent g, which is comparable to the acceleration expected in Seismic Zone 1 of the UBC (**Figure D5-6**). These accelerations (3.9 - 9.2 percent g) are roughly comparable to intensity V earthquakes which can result in cracked plaster and broken dishes, but minor or no construction damages (Case, 2002). All facilities, including the processing plant, pipelines and well structures, at Lost Creek will be designed and constructed to sustain an intensity V earthquake. In addition, the observations of injection, production, and pipeline pressures and associated monitor well measurements, necessary for the in situ operation, will provide short-term information about any unanticipated seismic impacts. The estimated acceleration in the Permit Area is 20 percent g on the 2,500 year map.

Lost Creek Project WDEQ-LQD Permit to Mine Application Original Dec07; Rev1 Feb08

D5-14



	REAL SAN
210	Lost Creek ISR, LLC Littleton, Colorado, USA
2 Ch 3	AATA INTERNATIONAL, INC. Fort Collins, Colorado, USA
3	Legend
$\sim$	Quatemary Alluvium
2 A	Mocene Rocks
~~~~	Vinite River Fm
n for	Bridger Fm
520 5	Ice Point Conglomerate
>>	Crooks Gap Conglomerate
	Green River Fm Wasatch Fm Battle Spring Fm
	Fort Union Fm
~	Cretaceous Rocks
	Cretaceous-Jurassic Rocks
M.	
	Fold Axis
	Faults (dashed where
	approximate) Large Stream Facies
2	Green River-Wasatch Fm Interfinger zone
	Lost Creek Permit Area
	FIGURE D5-1
1 2	Regional Geologic Map Lost Creek Permit Area
	Issued For: WDEQ-LQD 1.0 Drawn By: HA
1 ( 2 )	Issued/Revised: 09.17.08
	Drawing No: WDEQ-LQD 1.0 FIGD5-1 12.11.07
8891	0 4 miles





	· . ·	Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probir Program	ig & Re-		URE Replug	ging Progr	am
HoleID	N_nad83	E_nad83	S	. <b>T</b>	R	Elev	TD	Year	Company	Material	Cap	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
1-13	595656.1	2201396.2	13	25	93	6970	1000	1971	Conoco									1.00	
1D-17	596927.03	2214157.2	17	25	92	6965	502	1982	TG	Concrete									
1D-18	596222.05	2210916.2	18	25	92	6943	590	1982	TG	Concrete									
1D-20	595224.02	2213368.2	20	25	92	6933	530	1982	TG	Concrete									
1M-17	596928.02	2214133.2	17	25	92	6964	467	1982	TG	Concrete									
1M-18	596220.05	2210943.2	18	25	92	6943	450	1982	TG	Concrete									
1M-19	595179.06	2210943.2	19	25	92	6922	450	1982	TG	Concrete									
1M-20	595225.03	2213343.2	20	25	92	6933	440	1982	TG	Concrete									
1S-17	596929.03	2214105.2	17	25	92	6964	200	1982	TG	Concrete									
1S-18	596218.05	2210968.2	18	25	92	6943	357	1982	TG	Concrete									
1S-20	595226.02	2213318.2	20	25	92	6932	300	1982	TG	Concrete									
2M-19	595205.05	2210943.2	19	25	92	6923	680	1982	TG	Concrete									
3M-19	595229.07	2210942.2	19	25	92	6924	461	1982	ΤG	Concrete									
4-1	595685.1	2203263.1	13	25	93	6964	800							•					ļ
13-1	597151.11	2202677.1	13	25	93	7003	800												Į
13-2	597126.11	2203274.1	13	25	93	7002	800												
13-3	597154.09	2203861.2	13	25	93	7002	800					L						-	l
13-4	597110.09	2204605.2	13	25	93	6993	800					l							<b>↓</b>
19-1	594384.04	2206739.2	19	25	92	6925	800												<b>├───</b> ┃
24-1	594952.1	2204119.1	24	25	93	6966	008								_				<b>├───</b> ┃
24-2	594958.1	2204565.2	24	25	93	6949	800												
24-3	594950.1	2204989.2	24	25	93	6945	800												
24-4	594172.07	2202752.1	24	25	93	6941	800												
24-5	594173,09	2203324,1	24	20	93	6042	002									· .			
24-0	594157.06	2203001.2	24	25	93	6943	000					ł							
24-7	594369.06	2205556.1	24	25	93	6020	802							-					
24-0	594961 09	2200079.2	24	25	93	6952	640												
24-5	594957.09	2204408.2	24	25	93	6947	671												
59_1	598920.08	2208938 2	18	25	92	6969	300												
72-1	595290.07	2200050.2	10	25	92	6930	800												
77-1	593497.05	2209014 2	19	25	92	6918	790										1		
81-1	595513 1	2204371 1	24	25	93	6969	800										1 1		
81-2	594196.09	2204301 1	24	25	93	6936	795						1				1		<u> </u>
82-1	593038.07	2204412 1	24	25	93	6916	731					t	1				1		
82-2	593032.09	2204357.1	24	25	93	6916	795		· · · · ·										
82-3	593243.08	2204408 1	24	25	93	6918	1214												I
83-1	594198.09	2204502.2	24	25	93	6932	800												<b> </b>
83-2	594320.09	2204551.1	24	25	93	6934	600												
83-3	595286.1	2204563.2	24	25	93	6961	650												

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 1 of 15)

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probir Program	ng & Re-		URE Replu	ging Progr	am
HoleID	N_nad83	E_nad83	s	т	R	Elev	TD	Year	Company	Material	Сар	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
83-4	595521.1	2204570,1	24	25	93	6968	1200		1									í	
83-5	594510.08	2204496.1	24	25	93	6940	800						T					1	
84-1	593998.07	2204508.2	24	25	93	6929	800											1	
86-1	595611.08	2204417.2	13	25	93	6970	703				1								
86-2	595612.09	2204466.2	13	25	93	6970	800											1	
86-3	595613.08	2204371.1	13	25	93	6968	800	2										1	
86-4	597087.09	2204169.2	13	25	93	6997	800								-				
86-5	595719.1	2204365.2	13	25	93	6971	960			-	L							1	
88-1	595729.1	2204769.2	13	25	93	6967	600											1	
88-2	595725.1	2204565.2	13	25	93	6969	800								_			l .	
131-1	595892.05	2205988.1	13	25	93	6960	800											1	
131-2	595620.1	2204668.2	13	25	93	6970	760											1	
131-3	595619.08	2204758.1	13	25	93	6968	600	)										í l	
131-4	595730.09	2204769.2	13	25	93	6969	1200	l										1	
131-5	595524.09	2204770.2	24	25	93	6965	800											i	
135-1	594204.1	2204701.1	24	25	93	6932	1200											1	
139-1	593471.06	2205237.1	24	25	93	6920	780											1	I
139-2	593493.05	2205525.1	24	25	93	6920	1200											1	
139-3	593493.05	2205777.1	24	24	93	6916	800											I	
140-1	593492.06	2206063.1	19	25	92	6910	760	l.										I	
140-2	593491.05	2207525.2	19	25	92	6915	800											1	
140-3	593485.04	2207223.1	19	25	92	6914	1200												
557	598507.06	2211827.2	17	25	92	6985	650											I	
558	595807.03	2211804.2	18	25	92	6944	650												
844	591721	2212210.2	20	25	92	6864	560	1969	9							I			
A23	596854.02	2213320.2	17	25	92	6955	700	1970	Conoco					Γ					
A66	597490.06	2210635.2	18	25	92	6945	360	1970	Conoco									l	
A67	599898.06	2210516.2	18	25	92	7010	740	1970	Conoco										
A176	598445.08	2210978.2	18	25	92	6975	500	1970	Conoco									i i	
A177	598464.04	2212691.2	17	25	92	6980	500	1970	) Conoco									(	
A178	596051.03	2213327.2	17	25	92	6950	500	1970	Conoco									(	
A179	596451.02	2213324.2	17	25	92	6960	500	1970	Conoco				1					i	
A180	598481.99	2217895.2	16	25	92	6995	620	1970	Conoco									I	_
A181	596250.04	2213328.2	17	25	92	6955	520	1970	Conoco									Í	
A185	595260,01	2213348,2	20	25	92	6939	500/600		Conoco										
A186	598324.03	2217169.2	16	25	92	6995	620	1970	Conoco					1		T		i	
A187	594860.03	2213350.2	20	25	92	6935	500	1970	Conoco		1	1	·	1	1	1	1	í –	1 -
A188	595061.04	2213350.2	20	25	92	6935	500	1970	Conoco			t			1	1		í	
A189	598408.03	2216378.2	17	25	92	6995	620	1970	Conoco			1				1	1	i	Î
A190	595445.01	2213345.2	20	25	92	6935	500	1970	Conoco		,	1		r		1	1	i	1

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 2 of 15)



	[	Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probin Program	ig & Re- ∶		URE Repluç	ging Progr	am
HoleID	N_nad83_	E_nad83	s	т	R	Elev	TD	Year	Company	Material	Сар	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
A191	598352.02	2215596.2	17	25	92	6985	690	1970	Conoco			1							
A196	598399.04	2214795.2	17	25	92	6980	640	1970	Conoco										
A228	598495.05	2213839.2	17	25	92	6983	700	1970	Сопосо										
A399	598369.05	2215159.2	17	25	92	6990	520	1970	Conoco										
A400	598506.04	2212209.2	17	25	92	6980	580	1970	Conoco										
A426	598471.07	2211382.2	18	25	92	6980	600	1970	Conoco										
A442	598409.05	2213041.2	17	25	92	6985	600	1970	Conoco										
A443	598364.03	2214974.2	17	25	92	6990	520	1970	Conoco										
CG2-1	600404	2218314.2	16	25	92	7034	660	0											
D19	599857.04	2216739.2	17	25	92	7015	600	0								•			
D20	598325.08	2209390.2	18	25	92	6975	616	0											
D21	597485.04	2214405.2	17	25	92	6960	700	0										•	
D22	596360.06	2210438.2	18	25	92	6942	640	· 0											
D23	593865.04	2210460.2	19	25	92	6910	560	0											
D49	595115.01	2212805.2	20	25	92	6920	660	1970											
D50	595060.05	2210459.2	19	25	92	6921	600	· 0				1							
D51	592887.06	2210468.2	19	25	92	6895	780	0				· ·							
D52	593851.03	2211615.2	19	25	92	6905	540	0											
D53	599885.03	2213098.2	17	25	92	7010	600	0											
D54	599885.03	2215547.2	17	25	92	7010	600	· 0											
D55	597485.04	2215579.2	17	25	92	6980	780	0				1							
D75	597485.04	2213182.2	17	25	92	6960	600	1977							•				
D76	595083.02	2215205.2	20	25	92	6950	600	1977				1							
D96	595113.01	2214010.2	20	25	92	6935	540	1970											
D131	595100.02	2214398,2	20	25	92	6942	520	1977				1							•
D132	596555.07	2210458.2	18	25	92	6940	640	1977			·								
D144	596455.05	2210449.2	18	25	92	6943	540	0											
D149	595117.01	2213688.2	20	25	92	6935	540	1970								•			
D150	595105.04	2214195.2	20	25	92	6937	540	1970									· · ·		
D156	595125.02	2213586.2	20	25	92	6935	540	1970											
OH1	598115.02	2218381.2	16	25	92	6991	323	1968									1 1		
P1-16	595944.98	2217700.2	16	25	92	6945	680	1988	PNC	PlugGel									
P1-17	596669.02	2213891.2	17	25	92	6961	500	1987	PNC	PlugGel									
P1-18	595993.02	2211572.2	18	25	92	6939	560	1987	PNC	PlugGel							Couldn't		
P1-19	594450.06	2206714.2	19	25	92	6934	560	1987	PNC	PlugGel									
P1-20	595263.03	2212905.2	20	25	92	6927	560	1987	PNC	PlugGel							1		
P1-24	593705.05	2205770 1	24	25	93	6917	600	1987	PNC	PlugGel									
P2-16	596359,99	2217708.2	16	25	92	6942	600	1988	PNC	PlugGel									
P2-17	596435.04	2213125.2	17	25	92	6949	660	1988	PNC	PlugGel									
P2-18	595955 02	2211702.2	18	25	92	6949	500	1990	PNC	PlugGel		1					Couldo't		

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 3 of 15)

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probir Program	ng & Re-		URE Replu	gging Progr	am
HoleID	N_nad83	E_nad83	s	т	R	Elev	TD	Year	Company	Material	Cap	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
P2-19	593945.04	2206898.1	19	25	92	6920	720	1988	PNC	PlugGel									
P2-20	595325.01	2213920.2	20	25	92	6935	560	1987	PNC	PlugGel					1				
P2-24	593578.1	2204250.1	24	25	93	6925	560	1987	PNC	PlugGel									
P3-17	595903.01	2214910.2	17	25	92	6946	640	1988	PNC	PlugGel									
P3-18	596042.04	2211702.2	18	25	92	6944	500	1990	PNC	PlugGel									
P3-19	595757.06	2210925.2	19	25	92	6931	500	1992	PNC	PlugGel									
P3-20	595415.02	2212912.2	20	25	92	6934	520	1990	PNC	PlugGel									
P3-24	593083.08	2202706.1	24	25	93	6920	730	1988	PNC	PlugGel									
P4-17	596705.02	2214320.2	17	25	92	6964	633	1988	PNC	PlugGel									
P4-18	596141.03	2211693.2	18	25	92	6942	500	1990	PNC	PlugGel									
P4-19	595632.04	2210922.2	19	25	92	6929	500	1992	PNC	PlugGet									
P4-20	595465.03	2212912.2	20	25	92	6934	520	1990	PNC	PlugGel									
P5-17	596255.03	2212964.2	· 17	25	92	6945	650	1988	PNC	PlugGe									
P5-18	596192.03	2211689.2	18	25	92	6940	500	1990	PNC	PlugGel									
P5-19	595456.07	2210913.2	19	25	92	6933	500	1992	PNC	PlugGel									
P5-20	595565.04	2212915.2	20	25	92	6936	520	1990	PNC	PlugGel									
P6-17	596009.03	2212119.2	17	25	92	6946	500	1990	PNC	PlugGel									
P6-18	595856.06	2210922.2	18	25	92	6935	500	1992	PNC	PlugGet									
P6-19	595359.04	2210916.2	19	25	92	6933	500	1992	PNC	PlugGel									
P6-20	595615.01	2212916.2	20	25	92	6937	520	1990	PNC	PlugGel				•		•			
P7-17	596059.04	2212118.2	17	25	92	6948	500	1990	PNC	PlugGel		1							
P7-19	595801.06	2211125.2	19	25	92	6933	500	1992	PNC	PlugGel		· ·							
P7-20	595652.03	2212925.2	20	25	92	6935	520	1990	PNC	PlugGel									
P8-17	596208.04	2212115.2	17	25	92	6953	500	1990	PNC	PlugGel			T						
P8-19	595602.05	2211118.2	19	25	92	6936	500	1992	PNC	PlugGel		· · ·							
P9-17	596005.03	2211912.2	17	25	92	6947	500	1990	PNC	PlugGel								_	
P10-17	596207.02	2211923.2	17	25	92	6950	500	1990	PNC	PlugGel									
RD34	598491.02	2219625.2	16	25	92	6972	840	C	)										
RD125	595904.98	2219820.2	21	25	92	6955	480	1968											•
RD131	599905.02	2219820.2	16	25	92	7005	850	1968											
RD188	596037.02	2215568.2	17	25	92	6950	800	1968	i i										
RD189	597429.98	2217545.2	16	25	92	6975	800	1968	3										
RD210	596401.99	2221870.2	16	25	92	6980	600	1968	3								-		
RD301	596485.01	2218820.2	16	25	92	6945	600	1968											
RD343	594646.02	2214392.2	20	25	92	6947	650	1968	3										
RD345	596004.04	2214099.2	17	25	92	6950	650	1968	5										
RD392	595876.99	2218386.2	16	25	92	6940	600	1968	3										
RD393	596515	2221500.2	16	25	92	6963	200	1968	8										
RD404	598240	2218465.2	16	25	92	6985	550	1968	3	ľ									
RD412	598755.03	2214360.2	17	25	92	6997	700	1968	3			1							

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 4 of 15)



		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probin Program	ig & Re-	-	URE Replu	ging Progr	am
• HoleID	N_nad83	E_nad83	s	т	R	Elev	тр	Year	Company	Material	Cap .	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
RD436	595141.03	2211158.2	19	25	92	6925	670	1968									1		1
RD445	598456.01	2221499.2	16	25	92	6987	600	1968											
RD446	599729.04	2217176.2	16	25	92	7015	800	1968					•						Г
RE6	585415.01	2207290.1	30	25	92	6800	800												
TE1	593316.09	2204335.1	24	25	93	6920	720	1976	TG		None	Dry			Yes				
TE2	593169.09	2204479.2	24	25	93	6918	700	1976	TG		Octoplug	188	191		Yes				
TE3	594956.1	2204613.1	24	25	93	6946	680	1976	TG		? Too Deep				Yes				
TE4	595053.1	2204676.1	24	25	93	6950	680	1976	тg		Octoplug	205	401	ShurGel & QuickGel	Yes				
TE5	594853.1	2204660.1	24	25	93	6945	680	1976	TG		Sagebrush	Dry			Yes				
TE6	595558.08	2204518.1	24	25	93	6969	700	1976	TG		Octoplug	Dry		٢	Yes				·
TE7	595409.08	2204391.1	24	25	93	6943	700	1976	TG		Octoplug	Dry			Yes				
TE8	595511.1	2204170.1	24	25	93	6967	720	1976	TG		Octoplug	Dry			Yes				
TE9	594133.09	2202533.2	24	25	93	6939	820	1976	TG		Octoplug	210	276		Yes				
TE10	594052.08	2202729.1	24	25	93	6940	- 820	1977	TG		Octoplug	210	221		Yes	•			
TE11	594240,09	2203252.1	24	25	93	6948	720	1977	TG		Octoplug	Dry			Yes				
TE12	594097.1	2203400.1	24	25	93	6949	720	1977	TG		Octoplug	· 215	227		Yes				
TE17	595168.1	2204405.2	24	25	93	6961	1200	1977	TG		? Too Deep				Yes				ļ
TE18	593478.08	2204245.1	24	25	93	6923	775	1977	TG		None	Dry	-		Yes				
TE19	593073.08	2204571.1	24	25	93	6917	700	1977	TG		Octoplug	Dry			Yes				L
TE20	593051.09	2204215.1	24	25	93	6917	800	1977	TG		Octoplug	Dry			Yes				Ļ
TE21	593969,09	2202348,2	24	25	93	6936	1200	1977	TG		Octoplug	207	238		Yes				ļ
TE22	594260.08	2203457.1	24	25	93	6949	800	1977	TG		Octoplug	215	235		Yes				<b> </b>
TE23	593929.1	2203500.1	24	25	93	6945	800	1977	TG	···	Octoplug	210	228		Yes				<u> </u>
TE26	595582.1	2203010.2	24	25	93	6963	600	1977	IG		Octoplug	221	225		Yes				<u> </u>
TE27	595359.07	2203343.1 2203764.1	24 24	25 25	93	6963	640	1977	TG		Octoplug	Not Located 224	444	ShurGel &	Yes				
TE 20	504057.00	2204440 4		20		6050		1077	70		. o	D		QUICKGEI	V	· · · — —			───
1529	594657.08	2204119.1	24	25	93	6952	620	1977			None			· · ·	Yes		┼───┤		╂─────
1230	595096.08	2204232.1	24	25	93	6962	620	19//			Octopiug	Ury Not Loostod			res		+ +		<u> </u>
1531 TE22	505060 4	2203033.2	12	20	83	6070	700	1077				Not Located				<u> </u>	+		<b> </b>
TE32	596029.0	2203969 1	12	25	93	6972	800	1977	TG		2 Down Hole	NOT LOCATED			Yoe		<u>                                      </u>		<u> </u>
TE34	595508 04	2205700.2	24	25	- 02	6964	620	1977	TC	·····	Octoplug	222	228		Yee				<u> </u>
TE35	595544 11	2203700.2	24	25	93	6963	620	1977	TG		Octoplug	223	225		Yes		<u>                                     </u>		<u> </u>
TE36	595398 09	2203423 1	24	25	93	6962	620	1977			Octoplug	 Drv	200		Yes		<u>+</u> ──		t .
TE37	595327.08	2203351 1	24	25	93	6957	620	1977	TG		Octoplug	219	277		Yes		1 1		t
TE38	595462 07	2203643 1	24	25	93	6961	380	1977	TG		_o croping						<u>†                                     </u>		t
TE39	595123.09	2204273 2	24	25	93	6962	620	1977	TG		None	216	220		Yes		<u> </u>		1
TEAD	505054.08	2204202.1	24	25	03	6061	620	1077	TC			Not Located				· · · ·			t

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 5 of 15)

.

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probir Program	ng & Re-		URE Replu	gging Progr	am
HoleID	N_nad83	E_nad83	s	т	R	Elev	TD	Year	Company	Material	Сар	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
TE41	595721.1	2202859.1	31	25	93	6970	620	1977	TG			Not Located							
TE42	595433.1	2203177.2	24	25	93	6957	620	1977	TG		Permaplug	219	228		Yes				
TE43	595201.08	2203537.2	24	25	93	6956	620	1977	TG		Permaplug	218	226		Yes				
TE44	595234.09	2204071.1	24	25	93	6963	620	1977	TG		? Down Hole								
TE45	594991.08	2204357.2	24	25	93	6954	620	1977	TG		Octoplug	211	221		Yes				
TE46	594499.09	2204304.1	24	25	93	6943	1200	1977	TG		None	Dry			Yes				
TE47	594209.09	2204194.1	24	25	93	6940	760	1977	TG		Octoplug	204	248		Yes				
TE48	594349.1	2203883,2	24	25	93	6947	600	1977	TG		None	212	225		Yes				
TE49	594361.08	2203138.1	24	25	93	6938	600	1977	TG			Not Located							
TE50	594311.1	2202895.1	24	25	93	6940	800	1977	TG		Octoplug	209	234		Yes				
TE51	594282.09	2202540.1	24	25	93	6941	700	1977	тG		Octoplug	Blockage at about 100 ft.			Yes				
TE52	594068.09	2201824.1	24	25	93	6936	1200	1977	TG		Octoplug	209	247		Yes				
TE53	593827.08	2201824.1	24	25	93	6935	800	1977	TG		Octoplug	210	238	-	Yes		-		
TE56	593541.08	2202141.1	24	25	93	6930	700	1977	. TG		None	203	230		Yes			-	
TE57	593908,1	2202619.1	24	25	93	6938	1200	1977	TG		Octoplug	210	235		Yes				
TE58	593183.07	2202195.1	24	25	93	6921	1200	1977	TG	_		Not Located							
TE59	593222.08	2202557.1	24	25	93	6927	700	1977	TG			Not Located							
TE60	593526.09	2203012.2	24	25	93	6923	700	1977	TG			Not Located							
TE61	593722.08	2203363.1	24	25	93	6941	1200	1977	TG		Octoplug	209	225		Yes				
TE62	593126.07	2202936.1	24	25	93	6917	700	1977	TG			Not Located							
TE63	593804.08	2203657.1	24	25	93	6936	700	1977	TG		Octoplug	Dry			Yes				
TE64	593698.09	2203836.1	24	25	93	6931	680	1977	TG		None	195	224		Yes				
TE65	593638.08	2203697.1	24	25	93	6931	1203	1977	TG		Octoplug	Dry			Yes				
TE66	593619.08	2204003.2	24	25	93	6927	700	1977	TG		Octoplug	Dry			Yes				
TE67	593312.08	2204125.1	24	25	93	6921	719	1977	TG		Octoplug	191	389	ShurGel & QuickGel	Yes				
TE68	593833.09	2204381.1	24	25	93	6928	1202	1977	TG			Not Located							
TE69	593486.09	2204515.1	24	25	93	6922	793	1977	TG		Octoplug	191	209		Yes	2006	650	Grout	25' Cement
TE70	593246.07	2204209.1	24	25	93	6919	1202	1977	TG		Octoplug	189	252		Yes				
TE71	593393.07	2204517.1	24	25	93	6923	700	1977	TG		Octoplug	Dry			Yes	2006	650	Grout	25' Cement
TE72	593494.1	2204411.1	24	25	93	6924	700	1977	. TG		Octoplug	192	211		Yes	2006	650	Grout	25' Cement
TE73	593604.09	2204522.2	24	25	93	6926	700	1977	TG		Octoplug	Dry			Yes	2006	. 650	Grout	25' Cement
TE74	595632.08	2202770.2	24	25	93	6969	600	1977	TG		Octoplug	227	249		Yes				
TE75	595532.1	2202655.1	24	25	93	6968	600	1977	TG		Octoplug	229	270		Yes				
TE77	593783.08	2201859.1	24	25	93	6934	640	1977	TG		None	Dry			Yes				
TE79	594306.08	2201716.1	23	25	93	6939	700	1977	TG		None	214	308		Yes				
TE80	594169.09	2201859,1	24	25	93	6937	·680	1977	TG		Octoplug	Dry			Yes				
TE81	595311.1	2202715.1	24	25	93	6958	700	1977	TG		Octoplug	?	250		Yes				
ITE83	1 593457:08	2201861.1	23	25	93	6928	640	1977	TG		I Octoplua	207	I 326		l Yes				

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 6 of 15)



#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 7 of 15)

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ening, Probir Program	ng & Re-		URE Replu	gging Progr	am
HoleID	N_nad83	E_nad83	S	т	R	Elev	TD	Year	Company	Material	Сар	Water Leve (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
TG6-17	596105.04	2211920.2	17	25	92	6950	600	1978	TG		Permaplug	166	395	ShurGel & QuickGel	Yes				
TG6-18	596705.05	2210720.2	18	25	92	6947	660	1978	TG		Permaplug	166	306	6	Yes		1		
TG6-19	595105.07	2210720.2	19	25	92	6927	600	1978	TG		? Too Deep				Yes		1		
TG6-20	595505.03	2212720.2	20	25	92	6931	600	1978	TG						1		1		1
TG7-17	596105.04	2212320.2	17	25	92	6945	540	1978	TG		Permaplug	157	239		Yes				
TG7-18	596905.08	2210720.2	18	25	92	6949	660	1978	TG		Permaplug	167	224		Yes				
TG7-19	595305.06	2210720.2	19	25	92	6929	600	1978	TG		? Down Hole				· Yes				
TG7-20	595105.04	2213120.2	20	25	92	6932	520	1978	TG										
TG8-17	596305.03	2212320.2	17	25	92	6953	560	1978	TG		? Down Hole	*							
TG8-18	595914.04	2211508.2	18	25	92	6944	600	1978	TG		Permaplug	157	341	T	Yes				
TG8-19	595505.06	2210720.2	19	25	92	6926	600	1978	TG		Yes				Yes				
TG8-20	595505.03	2213120.2	20	25	92	6934	600	1978	TG										
TG <del>9</del> -17	595828.03	2212707.2	17	25	92	6936	560	1978	TG		Permaplug	151	163		Yes				
TG9-18	595905.05	2211120.2	18	25	92	6935	600	1978	TG			Not Located							
TG9-19	595505.06	2211120.2	19	25	92	6935	600	1978	TG		Permaplug	158	>450	ShurGel & QuickGel	Yes				
TG9-20	595305.03	2213120.2	20	25	92	6932	600	1978	TG		1								
TG10-17	596105.04	2212720.2	17	25	92	6941	600	1978	TG		Permaplug	153	313		Yes				
TG10-18	596305.07	2211120.2	18	25	92	6946	600	1978	TG		Permaplug	166	298		Yes				
TG10-19	595305.03	2211120.2	19	25	92	6932	500	1978	TG		Permaplug	154	283		Yes				
TG10-20	595305.03	2212720.2	20	25	92	6930	600	1978	TG										
TG11-17	596305.03	2212720.2	17	25	92	6949	600	1978	TG		Permaplug	159	186	5	Yes				
TG11-18	596711.06	2211120.2	18	25	92	6951	660	1978	TG		†	Not Located							
TG11-19	595705.05	2211120.2	19	25	92	6932	500	1978	TG		Permaplug	Dŋ			Yes				1
TG11-20	595305.03	2212320.2	20	25	92	6931	600	1978	TG	_	· · · · · · ·		i	1					
TG12-17	595826.03	2213108.2	17	25	92	6939	560	1978	TG		Permaplug	152	154		Yes		1		
TG12-18	597105.07	2211120.2	18	25	92	6959	660	1978	TG		Permaplug	173	206		Yes				
TG12-19	595705.02	2211520.2	19	25	92	6942	500	1978	TG		Permaplug	160	331		Yes				
TG12-20	595705.02	2213320.2	20	25	92	6938	600	1978	TG										
TG13-17	596105.04	2213120.2	17	25	92	6949	600	1978	TG		Permaplug	158	288		Yes				
TG13-18	595905.05	2211220,2	18	25	92	6936	500	1979	тg		Permaplug	154	379	ShurGel & QuickGel	Yes				· ·
TG13-19	595305.03	2211520.2	19	25	92	6932	540	1978	TG	_	? Down Hote	· ·	i — — —		Yes		1		1
TG13-20	595705.02	2213720.2	20	25	92	6942	600	1978	TG				l						
TG14-18	597105.04	2211520.2	18	25	92	6949	600	1978	TG			Not Located							· · · · · · · · · · · · · · · · · · ·
TG14-19	595505.03	2211520.2	19	25	92	6941	500	1978	TG		Permaplug	159	175		Yes				
TG14-20	595505.03	2213720.2	20	25	92	6941	540	1978	TG		1	[	1						1
TG15-17	596505.03	2213720.2	17	- 25	92	6961	600	1978	TG		Permaplug	167	341		Yes		1		1
TG15-18	596116.03	2211511.2	18	- 25	92	6943	500	1978	TG		Permaplug	156	238	1	Yes		1		

.

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 8 of 15)

		Locatio	on					. 1	Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probir Program	ig & Re-		URE Replug	ging Progr	am
HoleID	N_nad83	E_nad83	s	т	R	Elev	TD .	Year	Сотрапу	Material	Сар	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
TG15-19	595305.06	2210920.2	19	25	92	6930	580	1980	TG		? Too Deep				Yes				
TG15-20	595305.03	2213720.2	20	25	92	6938	540	1978	TG		[								
TG16-17	596505.03	2214120.2	17	25	92	6961	600	1978	TG		Permaplug	167	241		Yes				
TG16-19	595505.06	2210920.2	19	25	92	6930	580	1980	TG		×	Not Located							
TG16-20	595305.03	2214120.2	20	25	92	6938	600	1978	TG										
TG17-17	596105.04	2214520.2	17	25	92	6949	600	1978	TG		Permaplug	160	205		Yes				
TG17-19	595705.05	2210920.2	19	25	92	6929	580	1980	TG		? Too Deep		-		Yes	-			· · ·
TG17-20	595505.03	2214120.2	20	25	92	6940	540	1978	TG										
TG18-17	596505.03	2214520.2	17	25	92	6961	600	1978	TG		Permaplug	167	190		Yes				·
TG18-19	595305.03	2211320.2	19	25	92	6931	580	1980	TG		Yes				Yes				
TG18-20	595705.02	2214120.2	20	25	92	6943	600	1978	TG										
TG19-17	596105.04	2214920.2	17	25	92	6948	600	1978	TG		Permaplug	156	203		Yes				
TG19-19	595505.03	2211320.2	19	25	92	6940	580	1980	TG		? Too Deep				Yes				
TG19-20	595715.03	2214516.2	20	25	92	6948	600	1978	TG										
TG20-17	596505.03	2214920.2	17	25	92	6956	600	1978	TG		Permaplug	161	294		Yes				
TG20-18	595905.05	2210920.2	18	25	92	6935	580	1980	TG		? Too Deep		·		Yes				
TG20-19	595705.02	2211320.2	19	25	92	6935	580	1980	TG		? Too Deep				Yes				
TG20-20	595505.03	2214520.2	20	25	92	6941	540	1978	TG		· •							-	
TG21-17	596305.03	2214120.2	17	25	92	. 6954	600	1978	TG		Permaplug	163	357	ShurGel & QuickGel	Yes				
TG21-18	595905.01	2211320.2	18	25	92	6933	580	1980	TG		? Too Deep				Yes			• •	
TG21-19	595505.03	2211720,2	19	25	92	6936	580	1980	TG		? Down Hole				Yes				
TG21-20	595305.03	2214520.2	20	25	92	6949	516	1978	TG										
TG22-17	596705.02	2214120.2	17	25	92	6966	600	1978	, TG		Permaplug	- 171	248	•	Yes				
TG22-18	596105.04	2211320.2	18	25	92	6938	580	1980	TG		? Down Hole		•		Yes				
TG22-19	595705.02	2211720.2	19	25	92	6942	580	1980	TG		? Too Deep				Yes	•			
TG22-20	595305.03	2214920.2	20	25	92	6947	540	1978	TĠ		·			÷					
TG23-17	595905.01	2215320.2	17	25	92	6948	600	1978	TG	`	Permaplug	155	186	•	Yes	•			
TG23-18	595905,01	2211720,2	18	25	92	6942	580	1980	TG		None	· Dry			Yes		Couldn't		
TG23-19	595705.05	2210520.2	19	25	92	6936	580	1980	TG		? Too Deep		•		· Yes				
TG23-20	595505.03	2214920.2	20	25	92	6944	540	1978	TG	• •									
TG24-17	596105.04	2215320.2	20	25	92	6944	600	1978	TG		Permaplug	157	201		Yes			•	
TG24-18	596119.02	2211707.2	18	25	92	6948	580	1980	TG		? Too Deep				Yes				
TG24-19	595505.06	2210520.2	19	25	92	6931	580	1980	TG		1								
TG24-20	595705.02	2214920.2	17	25	92	6951	600	1978	TG		İ								
TG25-17	595905.01	2215720.2	17	25	92	6954	600	1978	TG		Permaplug	159	221		Yes				
TG25-18	596305.03	2211720.2	18	25	92	6942	580	1980	TG		? Too Deep				Yes		1		
TG25-19	595305.06	2210520.2	19	25	92	6931	580	1980	TG		? Too Deep				Yes				
TG25-20	595705.02	2215320.2	20	25	92	6949	600	1978	TG								1 1		
TG26-17	596105.04	2215720.2	17	25	92	6953	600	1978	TG		Permanlug	158	166		Yes	· · · · ·			

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 9 of 15)

~

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probir Program	ig & Re-		URE Replug	ging Progr	am
HoleID	N_nad83	E_nad83	S	т	R	Elev	TD.	Year	Company	Material	Сар	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
TG26-20	595505.03	2215320.2	20	25	92	6950	540	1978	TG										
TG27-17	596505.03	2215720.2	17	25	92	6960	600	1978	TG		Permaplug	163	271		Yes				
TG27-18	596005.03	2211699.2	18	25	92	6951	580	1980	TG		None	Dry			Yes				
TG27-20	595305.03	2215320.2	20	25	92	6951	540	· 1978	TG							-			•
TG28-17	596505.03	2215320.2	17	25	92	6956	600	1978	TG		Permaplug	162	. 225		Yes				_
TG28-20	595305.03	2215720.2	20	25	92	6956	540	1978	TG										
TG29-17	596305.03	2213720.2	17	25	92	6946	-600	1978	TG		Permaplug	161	238		Yes				
TG29-20	595505.03	2215720.2	20	25	92	6953	540	1978	TG										- A
TG30-17	596705.02	2214520.2	17	25	92	6964	600	1978	TG		Permaplug	<sup>•</sup> 168	243		Yes				
TG30-20	595705.02	2215720.2	20	25	92	6952	600	1978	TG						•				
TG31-20	595705.02	2216120.2	20	25	92	6957	600	1978	TG										
TG32-17	595905.01	2216120.2	17	25	92	6956	600	1978	TG		Permaplug	160	196		Yes				
TG32-20	595505.03	2216120.2	20	25	92	6953	540	1978	TG										
TG33-17	596105.04	2216120.2	17	25	92	6957	600	1978	TG		Permaplug	161	200		· Yes				
TG33-20	595305.03	2216120.2	20	25	92	6949	540	1978	TG										
TG34-17	595905.01	2216520.2	17	25	92	6958	600	1978	TG		Permaplug	158	275		Yes				
TG34-20	595705.02	2216520.2	20	25	92	6955	600	1978	TG								1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.		
TG35-17	595905.01	2216920.2	17	25	92	6954	600	1978	TG		Permaplug	152	333		Yes	-			
TG35-20	595505.03	2216520.2	20	25	92	6949	540	1978	TG					Resealed				-	
TG36-17	595905.01	2212120.2	17	25	92	6940	580	1980	TĠ		? Too Deep				Yes				
TG36-20	595305.03	2216520.2	· 20	25	. 92	6943	540	1978	TG										
TG37-17	596105.04	2212120.2	17	25	92	6947	580	· 1980	TG		Permaplug	161	317		Yes				
TG38-17	595905.01	2212520.2	17	25	92	6937	580	1980	TG	·	<ul> <li>Permaplug</li> </ul>	151	176		Yes				
TG39-17	596105.04	2212520.2	17	25	92	6941	580	1980	TG		? Too Deep			•	Yes				
TG39-20	595704.99	2216920.2	20	25	92	6950	600	1978	TG										
TG40-17	596305.03	2212520.2	17	25	92	6949	580	1980	TG		? Too Deep				Yes				
TG41-17	595905.01	2212920.2	17	25	92	6938	580	1980	TG		? Too Deep				Yes				
TG41-20	595504.99	2216920.2	20	25	92	6946	540	1978	TG										
TG42-17	596145.04	2212920.2	17	25	92	6942	580	1980	TG		? Too Deep				Yes				
TG42-20	595305	2216920.2	20	25	92	6941	540	1978	TG										
TG43-17	596305.03	2213120.2	17	25	92	6950	580	1980	TG		Permaplug	161	438	ShurGel & QuickGel	Yes				
TG43-20	595105.01	2216920.2	20	25	92	6939	540	1978	TG										
TG44-17	596505.03	2213520.2	17	25	92	6958	580	1980	TG		Permaplug	166	286		Yes				
TG44-20	592105	2212120.2	20	25	92	6879	460	1979	TG										
TG45-17	596505.03	2213920.2	17	25	92	6958	580	1980	TG		? Too Deep				Yes				
TG46-17	596705.02	2213920.2	17	25	92	6962	580	1980	TG		? Down Hole				Yes				
TG47-17	596505.03	2214320.2	17	25	92	6958	580	1980	TG		? Too Deep				Yes				
TG48-17	596305.03	2212120.2	17	25	92	6951	580	1980	TG		? Too Deep				Yes				
TG49-17	596005 03	2212520.2	17	25	92	6938	580	1980	TG		Permaplug	151	159		Yes				

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 10 of 15)

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probir Program	ig & Re-		URE Replu	gging Progr	am
HoleID	N_nad83	E_nad83	s	Ŧ	R	Elev	TD	Year	Company	Material	Сар	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
TG50-17	596205.02	2212520.2	17	25	92	6945	580	1980	TG		? Too Deep				Yes				
TG51-17	597105.04	2214720.2	17	25	92	6972	600	1981	TG		Concrete	<ul> <li>Did Not</li> </ul>							
TG52-17	599105.04	2215520.2	17	25	92	7001	600	1981	TG		Concrete	Did Not				-			
TG52-20	595305.03	2212120.2	20	25	92	6929	580	1980	TG										
TG53-20	595505.03	2212120.2	20	25	92	6933	580	1980	TG										
TG54-20	595705.02	2212120.2	20	25	92	6936	580	1980	TG										
TG55-20	595105.04	2212520.2	20	25	92	6926	580	1980	TG										
TG56-20	595305.03	2212520.2	20	25	92	6928	580	1980	TG										
TG57-20	595505.03	2212520.2	20	25	92	6932	580	1980	TG										
TG58-20	595705.02	2212520.2	20	25	92	6936	580	1980	TG										
TG59-20	595305.03	2212920.2	20	25	92	6928	580	1980	TG										
TG60-20	595505.03	2212920.2	20	25	92	6930	580	1980	TG										
TG61-20	595717.03	2212910.2	20	25	92	6939	580	1980	TG										
TG62-20	595505.03	2213320.2	20	25	92	6933	580	1980	TG										
TG63-20	_595305.03	2213520.2	20	25	92	6938	580	1980	TG										
TG64-20	595505.03	2213520.2	20	25	92	6938	580	1980	TG										
TG65-20	595705.02	2213520.2	20	25	92	6936	580	1980	TG										
TG66-20	595305.03	2213920.2	20	25	92	6935	580	1980	TG										
TG67-20	595505.03	2213920.2	20	25	92	6939	580	1980	TG										
TG68-20	595705.02	2213920.2	20	25	92	6941	580	1980	TG										
TG69-20	595305.03	2214320.2	20	25	92	6937	580	1980	TG										
TG70-20	595505.03	2214320.2	20	25	92	6941	580	1980	TG										
TG71-20	595705.02	2213120.2	20	25	92	6935	580	1980	TG										
TG72-20	595405.01	2212520.2	20	25	92	6930	580	1980	TG										
TG73-20	595805.03	2212520.2	20	25	92	6935	580	1980	TG										
TGC1-19	595405.04	2210920.2	19	25	92	6932	500	1980	TG		Permaplug	154	180		Yes				
TGC1A(45	595207.05	2210920.2	19	25	92	6927	140	1980	TG		? Angle Hole				Yes				
TGC1A(60	595205.05	2210920.2	19	25	92	6927	200	1980	TG		? Angle Hole				Yes				
TGC2-19	595565.07	2210920.2	19	25	92	6935	480	1980	TG		Yes				Yes				
TGC16	595905.05	2211170.2	18	25	92	6936	475	1979	TG										
TGC17	595905.05	2211160.2	18	25	92	6935	423	1979	TG		? Too Deep				Yes		•		
TGC18	595905.05	2211150.2	18	25	92	6935	<b>4</b> 4Ź	1979	тG		Permaplug	155	369	ShurGel & QuickGel	Yes			-	
TGC19	595905.05	2211130.2	18	25	92	6935	465	1979	TG		Permaplug	155	389		Yes				
TGC20	596005.06	2210920.2	18	25	92	6939	460	1980	TG		? Too Deep				Yes				
TGC21	595805.06	2210920.2	18	25	92	6933	477	1980	TG		? Down Hole				Yes				
TT1	594953.08	2204825.1	24	25	93	6945	680	1976	TG		None	Dry			Yes				
TT2	595475.1	2204952.2	24	25	93	6959	700	1976	TG		Octoplug	Dry			Yes				
TT3	595420.11	2204780.1	24	25	93	6962	720	1976	TG			Not Located							
TT4	593417.05	2205460.1	24	25	93	6919	. 600	1976	TG		Octoplug	Dry		·	Yes				

.

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 11 of 15)

.

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probir Program	ng & Re-		URE Repluc	ging Progr	am
HoleID	N_nad83	E_nad83	s	т	R	Elev	тр	Year	Company	Material	Сар	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
TT5	593395.04	2207708.2	19	25	92	6913	580	1976	TG		Sagebrush	174	356	ShurGel & QuickGel	Yes				
TT6	593412.03	2209201.2	19	25	92	6914	600	1976	TG		Sagebrush	Dry			Yes				
TT7	594288.07	2205245.2	24	25	93	6928	820	1976	TG		Octoplug	Dry			Yes				
TT8	594331.05	2206907.2	19	25	92	6923	740	1976	TG		Sagebrush	Dry			Yes				
ТТ9	595215.06	2209136.2	19	25	92	6928	600	1976	TG			Not Located							
TT13	593270.05	2205464.1	24	25	92	6914	500	1976	TG		Octoplug	Dry			Yes				
TT14	593468.04	2207633,2	19	25	92	6914	500	1976	TG		? Too Deep				Yes			•	
TT15	593316.06	2207796.1	19	25	92	6912	540	1976	TG		? Down Hole				Yes				
TT16	593275.04	2209357.1	19	25	92	6907	600	1976	TG		Octoplug	165	175		Yes				
TT17	594039.08	2204966.1	24	25	93	6927	1140	1976	TG		Octoplug	Dry			Yes				
TT18	593906.06	2208235.2	19	25	92	6923	1000	1976	TĢ		Octoplug	163	169		Yes				
TT19	595115.05	2209294.2	19	25	92	6921	600	1976	TG		None	Dry			Yes				
TT20	599133.06	2209282.2	18	25	92	6972	1160	1977	TG		Permaplug	210	270		Yes				
TT22	596083.09	2204681.1	13	25	93	6975	700	1977	TG		Octoplug	223	270		Yes				
TT23	596043.09	2205075.1	13	25	93	6974	600	1977	TG		Octopiug	226	261		Yes				
TT24	596008.08	2205501.1	13	25	93	6972	600	1977	TG		Octopiug	Dry		1	Yes				
TT25	593708.04	2205143.2	13	25	93	6923	700	1977	TG		Octoplug	184	196		Yes				
TT26	593470.05	2204871.2	24	25	93	6922	700	1977	TG		Octoplug	Dry			Yes				
TT27	593695.08	2204686.2	24	25	93	6929	700	1977	TG		Octoplug	Dry			Yes	2006	650	Grout	25' Cement
TT28	593844,08	2204869.1	24	25	93	6926	700	1977	TG		None	Dry			Yes				
TT29	593677.06	2206284.1	24	25	93	6913	700	1977	TG		Octoplug	Dry			Yes				
TT30	595509.06	2205700.2	19	25	92	6919	780	1977	TG		Octoplug	187	202		Yes				
TT31	594159.05	2207422.2	19	25	92	6923	600	1977	TG			Not Located			Yes	10/19/08	600	Grout	8' Cement
TT32	594439.04	2208146.2	19	25	92	6930	600	1977	TG		Octoplug	180	233		Yes				
TT33	593680.05	2209018.2	23	25	93	6911	600	1977	· TG		Octoplug	177	208		Yes				
TT34	594905.04	2209306.2	19	25	92	6921	600	1977	TG		None	Dry			Yes				
TT35	593362.06	2209532.2	19	25	92	6909	600	1977	TG		Octoplug	163	183		Yes				
TT36	593543.05	2209921.2	19	25	92	6910	600	1977	TG		Octoplug	164	187		Yes				
TT37	595908.06	2209670.2	19	25	92	6936	800	1977	TG			Not Located							
TT38	593926.04	2210194.2	19	25	92	6911	600	1977	TG		None	115	120	1	Yes				
TT39	595302.05	2209531.2	19	25	92	6930	600	1977	TG		Octoplug	Dry			Yes				
TT40	594804.05	2208920.2	19	25	92	6924	800	1977	TG		Octoplug	Dry			Yes				
TT41	594695.04	2209407.2	19	25	92	6916	600	1977	TG		Octoplug	151	174		Yes				
TT42	595128.04	2209429.2	19	25	92	6925	600	1977	TG			Not Located							
TT43	594180.05	2209901.2	19	25	92	6913	1000	1977	TG			Not Located							
TT44	593427.06	2209722.2	19	25	92	6912	600	1977	TG		Octoplug	Dry	·		Yes				
TT45	593611.04	2208653.1	19	25	92	6918	1000	1977	TG		Sagebrush	Dry			Yes				<u> </u>
TT46	593714.04	2208317.2	19	25	92	6920	1000	1977	TG		Octoplug	177	189	1	Yes				$\downarrow$
TT47	594087.06	2208151.2	19	. 25	92	6921	700	1977	TG		None	156	234	l	Yes				

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 12 of 15)

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probin Program	ig & Re-	<sup>9-</sup> URE Replugging Program			am
HoleID	N_nad83	E_nad83	s	T	R	Elev	TD	Year	Company	Material	Cap	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
TT48	593984.06	2207672.2	19	25	92	6920	1000	1977	TG		Octoplug	Dry			Yes				
TT49	593968.04	2207319.2	19	25	92	6919	1000	1977	TG		None	Dry			Yes		I		
TT50	594069.04	2206895.1	19	25	92	6919	900	1977	TG		Octoplug	Dry			Yes				
TT51	593748.03	2206819.2	19	25	92	6913	1000	1977	TG		? Too Deep				Yes				
TT52	593825.05	2206062.1	24	25	93	6919	1000	1977	ТG		Octoplug	179	376	ShurGel & QuickGel	Yes				
TT53	593280.06	2206263.2	24	25	93	6907	1000	1977	TG		None	Dry			Yes				
TT54	593634.04	2205782.1	24	25	93	6916	700	1977	TG			Not Located							
TT55	593362.06	2205643.1	24	25	93	6915	700	1977	ŤG		Octoplug	182	210		Yes				
TT56	593488.06	2205036.1	24	25	93	6921	700	1977	TG		Octoplug	Dry			Yes				
TT57	593065.04	2204994.1	24	25	93	6916	700	1977	TG		Octoplug	184	194		Yes				
TT58	593252.07	2204765.1	24	25	93	6919	700	1977	TG			Not Located							
TT59	593969.09	2204722.1	24	25	93	6928	1060	1977	TG		? Too Deep				Yes				
TT60	594406.09	2204986.1	24	25	93	6933	900	1977	· TG		Octoplug	189	210		Yes				
TT61	593485.07	2204631.1	24	25	93	6921	700	1977	TG		? Too Deep				Yes	2006	650	Grout	25' Cemen
TT62	595246.1	2205278.1	24	25	93	6948	820	1977	TG		? Down Hole				Yes				
TT63	595435.07	2209681.2	19	25	92	6933	600	1977	TG		Octoplug	Dry			Yes				
TT64	594910.06	2209108.1	19	25	92	6923	600	1977	TG		Octoplug	155	193		Yes				
TT65	594425.06	2208538.2	19	25	92	6928	600	1977	IG		? Too Deep				Yes	l			
1166	595025.04	2208968.2	19	25	92	6927	600	1977	TG			Not Located					-		
1167	594095.06	2207861.1	19	25	92	6922	700	1977				Not Located			No.		1		
1168	593868,06	220/115.1	19	25	92	6915	700	1977			Uctopiug				tes				
1169	593676.08	2204875.1	24	25	93	6924	700	1977			Ostashus	Not Located	100		Var				
1170	595144.09	2205263.1	24	25	93	6947	760	1977			Octopiug	198	199		· Ves				
11/1	595266.06	2205177.1	24	25	93	6051	760	1077			Octopiug	100	204		Vos				
TT72	505219 05	2205291.2	24	20	93	6047	760	1077			Octopiug	199	203		Vae			· ·	
TT74	595220.05	2203300.1	24 10	25	93	6929	007	1977		· · · · ·	Octopiug	155	170		Yes	l			-
TT75	595342.04	2210066.2	10	25	92	6927	000	1977	ТС		Octopidg	Not Located	,,,,		103				
TT76	593612.04	2209426.2	19	25	92	6921	600	1977			Sagebrush				Yes				
1777	593343.06	2208992.2	19	25	92	6909	000	1977	TG		Octoplug	167	180		Yes				r
TT78	595072.06	2209155 2	19	- 25	92	6925	600	1977	TG		Sagebrush	159	184		Yes				
TT79	594757.06	2208708 2	19	25	92	6931	600	1977	TG		Sagebrush	Drv			Yes				
1180	594528.06	2208397 2	19	25	92	6933	600	1977	TG		Octoplua	180	222		Yes	10/2/08	600	Grout	8' Cement
TT81	594292.04	2208019.2	19	25	92	6926	700	1977	TG		Octoplug	175	232		Yes				
TT82	594140.05	2207810.2	19	25	92	6923	700	1977	TG		Octoplua	176	214		Yes				
TT83	593627.05	2206946.2	19	25	92	6911	700	1977	TG		None	Dry			Yes				
TT84	593492.06	2206483.1	24	25	93	6908	700	1977	TG		None	Dry			Yes				
TT85	594997.05	2209563.2	19	25	92	6921	600	1977	TG		Octoplug	153	320		Yes				
TT86	595136.05	2210060.2	19	25	92	6921	600	1977	TG			Not Located							

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 13 of 15)

Lost Creek Project WDEQ-LQD Permit to Mine Application Original Dec07; Rev3 Apr09

`

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ening, Probir Program	ng & Re-		URE Replu	gging Progr	am
HoleID	N_nad83	E_nad83	s	т	R	Elev	TD	Year	Company	Material	Cap	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
TT87	595404.06	2209864.2	19	25	92	6932	600	1977	TG	•	Octoplug	161	190		Yes				
TT88	595437.07	2210272.2	19	25	92	6926	600	1977	TG			Not Located							
TT89	594598.05	2210127.2	19	25	92	6909	600	1977	TG		Octoplug	Dry			Yes				
TT90	595901.07	2210184.2	19	25	92	6937	600	1977	TG		Octoplug	Dry			Yes				
TT94	596605.07	2210420.2	18	25	92	6948	660	1978	TG		? Down Hole				Yes				
TT95	596205,05	2210420.2	18	25	92	6938	660	1978	TG		? Too Deep				Yes				
TT96	595805.06	2210420.2	18	25	92	6934	660	1978	TG		Sagebrush	Dry			Yes	9/26/08	600	Grout	8' Cement
TT97	595425.06	2210413.2	19	25	93	6927	600	1978	TG		? Down Hole				Yes		· ·		
TT98	595105.07	2208720.2	19	25	92	6912	700	1978	TG		? Down Hole				Yes				
TT99	594805.06	2208420.2	19	25	92	6916	700	1978	TG		Permaplug	Dry			Yes				
TT100	594605.04	2207820.1	19	25	92	6918	700	1978	TG		Permaplug	187	202	<u> </u>	Yes				
TT101	594405.04	2207420.2	19	25	92	6912	700	1978	TG			Not Located							
TT102	593705.05	2207120.1	19	25	92	6914	660	1978	· TG		Permaplug	177	203		Yes				
TT103	593705.05	2207520.2	19	25	92	6918	700	1978	TG		? Too Deep				Yes				
TT104	593705.05	2207920.1	19	25	92	6919	600	1978	TG		? Too Deep				Yes				
TT105	594305.06	2206520.2	24	25	93	6926	660	1978	TG		Permaplug	180	247		Yes				
TT106	594090.04	2206536.2	24	25	93	6924	700	1978	TG		Octoplug	178	200		Yes			1	
TT107	593624.04	2205535.2	24	25	93	6920	700	1978	TG		Octoplug	Dry			Yes				
TT108	594318.06	2205590.1	24	25	93	6924	700	1978	TG		Octoplug	176	182		Yes				
TT109	594105.04	2206720.2	19	25	92	6923	700	1978	TG		? Down Hole				Yes				
TT110	594768.05	2208715.2	19	25	92	6932	560	1978	TG		Octoplug	176	229	·	Yes				
TT111	595446.06	2210267.2	19	25	92	6928	500	1978	TG		Octoplug	155	170		Yes				
TT112	593905.04	2206520.1	24	25	93	6919	660	1978	. TG		? Too Deep				Yes				
TT113	594105.04	2206320,2	24	25	93	6921	660	1978	TG		Permaplug	176	214		Yes				
TT114	593705.05	2205520.1	24	25	93	6920	660	1978	TG		Permaplug	186	197		Yes				
TT120	593905.04	2208120.2	19	25	92	6920	600	1978	TG		. ? Too Deep				Yes				
TT121	593905.04	2207920,1	19	25	92	6919	600	1978	TG		Permaplug	172	243		Yes				
TT122	593905.04	2207720.1	19	25	92	6919	600	1978	TG		Permaplug	Dry			Yes				
TT123	593905.04	2207520.2	19	25	92	6919	600	1978	TG		Permaplug	Dry			Yes				
TT124	594305.06	2207520.2	19	25	92	6927	620	1978	TG		? Too Deep				Yes				
TT125	593705.05	2207720.1	19	25	92	6917	600	1978	TG		Permaplug	178	251		Yes				
TT126	594305.06	2207720.1	19	25	92	6927	600	1978	TG		Permapiug	179	382	ShurGel & QuickGel	Yes				
TT127	594305.06	2207920.2	19	25	92	6926	600	1978	TG		Permaplug	176	228		Yes		1		
TT128	593505.06	2207720,1	19	25	92	6916	600	1978	TG		? Too Deep				Yes				
TT129	594305.06	2208120.2	19	25	92	6926	600	1978	TG		Permaplug	176	197	· · · · · · · · · · · · · · · · · · ·	Yes				
TT130	593905.04	2205120.2	24	25	93	6927	700	1978	TG		Permaplug	Drv			Yes				
TT131	593905.04	2205320.1	24	25	93	6924	700	1978	TG		Permapluo	180	218		Yes		<u> </u>	l	
TT132	593705.05	2205320.1	24	25	93	6920	700	1978	ŤG	<u> </u>	Permapluo	184	203		Yes		1	1	
TT133	593905.08	2204920.1	24	25	93	6927	700	1978	ŤĠ		Permaplug	183	191		Yes		<b></b>		

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 14 of 15)

		Locati	on						Exploration	Original Plug	Original Plug	1983-19	84 TG Reope Plugging	ning, Probir Program	ng & Re-		URE Replu	gging Progr	am
HoleID	N_nad83	E_nad83	s	т	R	Elev	TD	Year	Company	Material	Cap	Water Level (ft.)	Mud Depth (ft.)	Resealing Material	Concrete Recap	Date	Plug Depth (ft)	Replug Material	Concrete Recap
TT134	593905.04	2205520.1	24	25	93	6921	700	1978	TG		? Down Hole				Yes				
TT135	593505.06	2205320.1	24	25	93	6922	700	1978	TG		Permaplug	Dry			Yes				
TT136	593505.06	2205120.1	24	25	93	6920	700	1978	·TG		Permaplug	187	394	ShurGel & QuickGel	Yes				
TT137	593305.06	2205320.1	24	25	93	6919	700	1978	TG		? Too Deep				Yes				
TT138	593305.06	2205120.1	24	25	93	6922	700	1978	TG		Permaplug	Dry			Yes				
TT139	593305.06	2204920.1	24	25	93	6922	630	1978	TG		? Too Deep				Yes				
TT140	594505.06	2208120.2	19	25	92	6923	600	1978	TG		? Too Deep				Yes			·	
TT141	594505.06	2207920.2	19	25	92	6924	600	1978	TG			Not Located				9/29/08	600'	Grout	8' Cement
TT142	594505.06	2207720.1	19	25	92	6922	620	1978	TG		Permaplug	184	243		Yes				
<u>TT143</u>	594505.06	2207520,2	19	25	92	6924	620	1978	TG		Permaplug	185	204		Yes				
TT144	594105.04	2207720.1	19	25	92	6922	620	1978	TG	•	Permaplug	Dry			Yes				
TT145	593905.04	2207520.2	19	25	92	6923	620	1978	TG		None	Dry			Yes				
TT146	593669.09	2204615.1	24	25	93	_ 6929	700	1978	TG		Permaplug	· 191	207		Yes	2006	650	Grout	25' Cement
<u>TT147</u>	593620.1	2204614.1	24	25	93	6927	560	1978	TG		Permaplug	195	236		Yes	2006	650	Grou	25' Cement
TT148	593620.1	2204604.2	24	25	93	6927	560	1978	TG		Permaplug	195	236		Yes	2006	650	Grout	25' Cement
TT149	593568.09	2204613.1	24	25	93	6925	700	1978	TG		Permaplug	193	239		Yes	2006	650	Grou	25' Cement
TT150	594105.04	2207420.2	19	25	92	6925	650	1978	TG		Permaplug	176	249		Yes				
TT151	594405.04	2208020.2	19	25	92	6927	660	1978	TG		Permaplug	179	294		Yes				
TT152	594400.06	2208121.2	19	25	92	6910	520	1978	TG		Permaplug	179	236		Yes				
TT153	594005.06	2207420.2	19	25	92	6923	650	1978	<u> </u>		Permaplug	175	210	· .	Yes				
TT154	594005.06	2207520.2	19	25	92	6924	700	1978	TG		? Down Hole				Yes				
TT155	594405.04	2208110.2	19	25	92	6924	490	1978	TG		Permaplug	179	272	L	Yes				
TT156	593620,1	2204594.1	24	25	93	6927	600	1978	тg		Permaplug	· 195	396	ShurGel & QuickGel	Yes	2006	650	Grout	25' Cement

,

. .

#### Table D5-2 Abandonment Information for Historic Exploration Holes (Page 15 of 15)

Copies of the following WDEQ/LQD plates are not included in this package, as they are the same as the plates submitted to NRC in February 2009 in response to NRC's November 2008 Request for Additional Information.

Plate	Number	
NRC Technical Report	WDEQ/LQD Permit Application	Title
2.6-1b	D5-1b	Geologic Cross-Section B-C
2.6-1c	D5-1c	Geologic Cross-Section C-D
2.6-1d	D5-1d	Geologic Cross-Section D-E
2.6-1e	D5-1e	Geologic Cross-Section F-F'
2.6-1f	D5-1f	Geologic Cross-Section G-G'
2.6-1g	D5-1g	Geologic Cross-Section H-H'
2.6-4a		Isopach Map of the FG Horizon
2.6-4b	D5-2a	Isopach Map of the Lost Creek Shale
2.6-4c	D5-2b	Isopach Map of the HJ Horizon
2.6-4d	D5-2c	Isopach Map of the Sagebrush Shale
2.6-4e	D5-2d	Isopach Map of the UKM Sand

# **ATTACHMENT D5-3**

ţ

0

# **Communication with WDEQ LQD related to Drill Hole Abandonment**

MIMED

OCT 27 '87

# Texasgulf Minerals and Metals, Inc.

P.O. Box 191 2755 State Highway 67 Victor, Colorado 80860

Cripple Creek and Victor Operations (303) 689-2977

September 16, 1987

Richard G. Stockdale State Engineer's Office Herschler Building Cheyenne, WY 82002

> Re: Permit Nos. U.W. 61528 through U.W. 61539

Dear Mr. Stockdale:

In response to your letter regarding the above referenced monitor wells, theses specific wells were abandoned by Texasgulf in 1985. these wells were installed to monitor ground water quality on mining claims under Texasgulf's control. The claims were subsequently dropped by the company. As part of the procedure, the monitor wells were abandoned.

Enclosed is specific data on how each monitor well was abandoned. In each case, as much of the casing pipe as possible was pulled and the hole filled with concrete.

If you have further questions, please contact us.

Sincerely,

C. Alan Jappe

C. Alan Tapp Manager Cripple Creek Operations

CAT/k1

xc: Gonzalo Tufino William Strait Files (2)



MITTE TEXASGULF INC

5932 NCINTYRE STREET DRESS

GOLDEN CO 80403

P. 03

AUGUST 1987 REVIEW

ERNIT	NAME OF	LOCATION	I	F WELL IS ABANDONED PLEASE	PROVIDE:	IF STILL
	WPTLT.	1/4 1/4, SEC-TVP-RGE	DATE	REASON	MECHOD	MONITORING
in 01,112,1	******		20.22	haiter i		SHOW LIFE
FI 61528	M-25-92-20-1S	NW1 NW1 20-25-92	11_6_85	Property Abandonment	Filled with Concrete	
1 61529	N-25-92-20-1M	NW2 NW2 20-25-92	11-6-85	Property Abandonment	Filled with Concrete	
8 61530	M-25-92-20-10	NWE NWE 20-25-92	11-6-85 木	Property Abandonment	Filled with Concrete	
-17 61531	M-25-92-19-3M	NET 19-25-92	11-7-87 85	Property Abandonment	Filled with Concrete	
1 61532	M-25-92-19-2M	NET NET 19-25-92	11-8-97 8-5	Property Abandonment	Filled with Concrete	
61533	M-25-92-19-1M	NET 19-25-92	11-8-87 55	Property Abandonment	Filled with Concrete	
₩ 61534	N-25-92-18-1M	SET SET 18-25-92	11-8-27 85	Property Abandonment	Filled with Concrete	
W 61535	M-25-92-18-15	SET 18-25-92	11-8-87 85	Property Abandonment	Filled with Concrete	
W 61536	M-25-92-18-1D	SET 18-25-92	11-8-87 55	Property Abandonment	Filled with Concrete	
W 61537	N-25-92-17-15-	SW1_SW1 17-25-92	11-7-85	Property Abandonment	Filled with Concrete	
W 61538	M-25-92-17-1H	SWE SWE 17-25-92	11-7-85	Property Abandonment	Filled with Concrete	
W 61539	M-25-92-17-1D	SWE SWE 17-25-92	11-7-85	Property Abandonment	Filled with Concrete	
<u>IW</u>						
JW						
JW						
JN						
<u>UW</u>						
(IW						
					· · · · · · · · · · · · · · · · · · ·	
Z <u>UW</u>						
8 <u>UW</u>						i
<sup>10</sup> <u>UN</u>	+					
<u>UW</u>						/{
UW						
01						
4 (19)		- <b>[</b>				
4 04						
10 TR2				L	f	;
			·····			
N UN	+	+				d
0 <u>UN</u>				·		
				}		l
2 34	Real Call 2	1 some sales of the				

C. Clan linge on most for forgally

9-17-87

APPROVED\_\_\_AUGUST 1982

# Texasgulf memo

Date	August 22, 1983		
То	D. C. Edmiston	Location	Golden
From	C. Alan Tapp	Location	Golden
Subject	Lost Creek/Conoco - 1983 F	, rogram Summa	ry

In a letter to Wyoming's DEG, November 24, 1982, Texasgulf outlined in detail its 1983 program for the Lost Creek/Conoco property. The program as outlined to Mr. Roy Spears presented a remedial plan, which once completed would rescind a Notice of Violation issued to Texasgulf on May 20, 1982. The program was initiated as outlined in June, 1983 and completed in late July, 1983. Approximately seventy-five percent of Texasgulf's Lost Creek/Conoco property was inventoried, the remainder will be completed in 1984.

Appendix B details Texasgulf's 1983 plan as presented to the DEQ. Basically, it involved inspecting down the hole conditions for every Texasgulf drill hole to determine the adequacy of past sealing efforts. Water levels and mud column depths were measured and recorded. Concrete caps were placed on all Texasgulf holes which were not originally capped with concrete or if the original concrete cap had failed. Appendix C listed the detailed results of the survey while Appendix D lists a section by section summary. Plate I indicates those sections inventoried this year and those scheduled for inventory in 1984.

In summary, 31 square miles of land were physically inspected this summer. This represents 269 individual drill holes in the survey. Approximately fifty-one percent of the holes inspected, of 138 holes, were previously capped with concrete caps. In almost all cases these were tested to determine how secure they were in the drill hole and not removed. An attempt was made to remove several concrete caps, but in every case the cap was well secured. Two concrete caps had failed and slipped down the drill hole and were recapped. D. C. Edmiston August 22, 1983

Approximately forty-one percent of the holes, or 111 holes, were recapped with new concrete caps. The old caps were usually permaplugs and in a few cases the old octoplug. These were either removed or breeched, when possible, so that water levels and mud columns could be measured. The old caps were left in the drill hole at a depth of five feet and a new concrete cap was installed at approximately two feet below the surface and backfilled to the surface.

After completing this survey, it was determined that nine drill holes and one from Texasgulf's 1982 inventory required resealing. One drill hole in Section 20, as determined from our October, 1982 inventory, was also inadequately sealed. Appendix E lists those holes resealed. All ten drill holes were resealed in late July using a mixture of water, Shur-gel, and Quick-gel. They were then recapped with concrete caps and backfilled to the surface. Mud specifications exceeded those required by the Wyoming DEQ. A sample of abandonment fluid submitted to NL Industries for testing yielded the following characteristics:

	Actual	Requirement
API filtrate	4.8 cc	13.5 cc
10 Min. Gel Strength	42 lbs./100 ft. <sup>2</sup>	20 lbs./100°ft. <sup>2</sup>

This same type of program will be conducted in 1984 on the remaining Lost Creek/Conoco property. Approximately ten square miles will be covered, containing around 500 drill holes. The 1984 program will be more time consuming since all drill holes will have to be recapped with concrete caps and the extensive number of holes left to be inventoried.

CAT/dd

cc: 03-002-006-04 C. Alan Tapp Page 2

# APPENDICES

- - -

۲.

Wyoming, Department of Environmental Quality Notice of Violation	Appendix A
Proposed Remedial Plan, November 24, 1982	Appendix B
Drill Hole Inspection Summary, 1983	Appendix C
Drill Hole Inventory by Section	Appendix D
Summary of Sealed Drill Holes	Appendix E

## APPENDIX A

Wyoming Department of Environmental Quality Notice of Violation May 20, 1982

i const

 $\left[ \right]$ 

RE ENEDI 03-002 -006-04

graha THEYENNE, WYOMING 82002

OF WYOMING

MAY 2 4 1982

Tg Proj.Eval Dept.

ED HERSCHLER GOVERNOR

and Lynn

Department of Environmental ualilu - Sent to Frank

LAND QUALITY DIVISION Enis

TELEPHONE 307-777-7756

401 WEST 19TH STREET

HE STATE

May 20, 1982

CERTIFIED MAIL RETURN RECEIPT REQUESTED Certified No. 73824

Mr. David C. Edmiston Vice - President, Special Projects Texasgulf, Incorporated 5926 McIntyre Street Golden, Colorado 80401

RE: Notice of Violation, Docket # 1085 - 82, Drilling Notification #47

Dear Mr. Edmiston:

Enclosed you will find an inspection report dated May 10, 1982, recommending a Notice of Violation and the Notice of Violation.

We expect Texasgulf, Inc. to respond to this Notice of Violation by June 18, 1982, by providing a detailed plan for correcting surface capping and sealing problems found during the May 7 - 10, 1982, inspection. A projected timetable should also be provided for completion of remedial work necessary to bring all sites drilled by Texasgulf in Township 24 North, Range 92 West, Township 25 North, Range 92 West, and Township 25 North, Range 93 West, in compliance with Wyoming Statute 35-11-404.

It is hoped this course of action will avoid a recommendation for enforcement action, which would be made after June 18, 1982, depending upon your response.

Should questions arise, please call me at (307) 777-7756.

Sincerely,

Roy<sup>V</sup>G. Spears Abandoned Drill Site Program Supervisor

RGS:mk

Enclosures: Notice of Violation Inspection Report

cc: Alan Guile

#### NOTICE OF VIOLATION

IN THE MATTER OF THE NOTICE ) OF VIOLATION ISSUED TO MR. ) DAVID C. EDMISTON, VICE- ) PRESIDENT, SPECIAL PROJECT ) TEXASGULF INC., 5926 McINTYRE) STREET, GOLDEN, CO 80401 ) Certified No. 73824, DN #47

DOCKET NO. 1085-82

#### NOTICE

#### NOTICE IS HEREBY GIVEN THAT:

- This notice is being sent to you pursuant to Wyoming Statute 35-11-701(c)(i), which requires that in any case of the failure to correct or remedy an alleged violation, the Director of the Department of Environmental Quality shall cause written notice to be issued and served upon the person alleged to be responsible;
- 2. On May 7 and 10, 1982, an inspection was conducted by a representative of the Land Quality Division, Department of Environmental Quality. Drill sites inspected were located in T.24N., R.92W., T.25N., R.92W., and T.25N., R.93W.;
- 3. Said inspection revealed that Drill Holes Numbered TC17, TG 19 18 25 92, TG 21 18 25 92 and 27 other holes identified in the report of said inspection, were not sealed as required by Wyoming Statute 35-11-404(c)(ii). Wyoming Statute 35-11-404(c)(ii) requires that drill holes which have encountered any groundwater shall be sealed;
- 4. Said inspection also revealed that Drill Holes Numbered TC 17, TG 19 18 25 92, TG 21 18 25 92 and 41 other holes identified in the report, were not properly surface capped. This in in violation of Wyoming Statute 35-11-404(c)(iii).
- 5. With this document, the Department of Environmental Quality is notifying Mr. David C. Edmiston of Texasgulf Inc. of the aforementioned violations.
- 6. Any person who violates any provision of the Environmental Quality Act or any rule, standard, permit, license or variance adopted thereunder is liable to a penalty of ten thousand dollars (\$10,000) for each day of violations, which penalty may be recovered in a civil action brought by the Attorney General in the name of the People of the State of Wyoming.

\_\_\_\_day of\_\_\_\_ \_\_\_\_\_, 1982. DATED this

Roger Shaffer for

Walter C. Ackerman, Administrator Land Quality Division Department of Environmental Quality

PLEASE DIRECT ALL INQUIRIES REGARDING THIS NOTICE OF VIOLATION TO Roy Spears, Abandoned Drill Site Program Supervisor, Department of Environmental Quality, Land Quality Division, 401 West 19th Street, Cheyenne, WY 82002, Telephone (307) 777-6192, OR Alan Guile, Abandoned Drill Site Inspector, 210 Lincoln St., Lander, WY 82520, Telephone (307) 332-3047.

#### INSPECTION REPORT

RE : Texasgulf, Inc. Drilling Notification No. 47

DATE OF TRIP: May 7 and 10, 1982

SUBJECT : Inspection of DN47

PARTICIPANTS: C. Alan Tapp - Texasgulf Alan Guile - Lander DEQ-LQD 弟

PREPARED BY : Alan Guile, Abandoned Drill Site Inspector, District IT C2821

On May 7 and 10, 1982, an inspection of the above was conducted.

Of the 94 holes reported in 1979, 16 holes or 17% were inspected. Of the 148 holes reported in 1980, 26 holes or 18% were inspected. Surface reclamation was adequate at all sites and therefore is not reported in the summary.

Summary of results - 1979

TC 18 NWNE, Section 34, T.25N., R.93W. TD 800 feet No cap. Dry hole. Violation Wyoming Statute 35-11-404(c)(iii)

TC 17 NWNE, Section 34, T.25N., R.93W. TD 800 feet No cap. Encountered water at -163 feet. No bottom at -295 feet. Violation of Wyoming Statute 35-11-404(c)(ii) and (iii).

TT 146 NWNE, Section 24, T.25N., R.93W. TD 700 feet Perma-plug. Water at -192 feet with bridge or bottom at -215 feet. Violation of Wyoming Statute 404(c)(ii) and (iii)

TT 149 NWNE, Section 24, T.25N., R.93W. TD 700 feet Perma-plug. Water at -191 feet with bridge or bottom at -247 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TT 148 NWNE, Section 24, T.25N., R.93W. TD 560 feet Perma-plug. Water at -196 feet with bridge or bottom at -201 feet. Violation of Wyoming Statute 404-(c)(iii).

TT 155 SENW, Section 19, T.25N., R.92W. TD 514 feet Perma-plug. Water at -179 feet with bridge or bottom at -256 feet. Violation of 404(c)(ii) and (iii).

TT 151 SWNW, Section 19, T.25N., R.92W. TD 660 feet Perma-plug. Water at -179 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 19 18 25 92 SESE, Section 18, T.25N., R.92W. TD 465 feet Perma plug. Water at -155 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 13 18 25 92 SESE, Section 18, T.25N., R.92W. TD 500 feet Perma-plug. Water at -154 feet with no bottom at -300 feet. Violation of Nyoming Statute 404(c)(ii) and (iii).

TG 47 20 25 92 NESW, Section 20, T.25N., R.92W. TD 460 feet Perma-plug. Water at -124 feet with bridge or bottom at -156 feet. Violation of Wyoming Statute 404(c)(ii) and (iii). Inspection Report Texasgulf, Inc. Drilling Notification No. 47 May 7 and 10, 1982 Page 2

TG 46 20 25 92 NESW, Section 20, T.25N., R.92W. TD 460 feet Perma-plug. Water at -125 feet with bridge or bottom at -167. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 49 20 25 92 NESW, Section 20, T.25N., R.92W. TD 460 feet Perma-plug. Water at -115 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 7 29 25 92 SESE, Section 29, T.25N., R.92W. TD 600 feet Perma-plug. Unable to check down hole conditions as Perma-plug slid down the hole. Violation of Wyoming Statute 404(c)(iii).

TG 6 29 25 92 SESE, Section 29, T.25N., R.92W. TD 600 feet Perma-plug. Water at -143 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 3 6 24 92 SENW, Section 6, T.24N., R.92W. TD 400 feet Perma-plug. Water at -175 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 2 6 24 92 SENW, Section 6, T. 24N., R. 92W. TD 400 feet Perma-plug. Water at -175 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

Summary of results - 1980

TG 21 18 25 92 SESE, Section 18, T.25N., R.92W. TD 580 feet Perma-plug. Water at -152 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 22 18 25 92 SESE, Section 18, T.25N., R.92W. TD 580 feet Perma-plug. Unable to check down hole as Perma-plug slid down hole. Violation of Wyoming Statute 404(c)(iii).

TG 20 18 25 92 SESE, Section 18, T.25N., R.92W. TD 580 feet Perma-plug. Perma-plug slid down hole. Violation of Wyoming Statute 404(c)(iii).

TG 19 19 25 92 NENE, Section 19, T.25N., R.92W. TD 580 feet Perma-plug. Water at -159 feet with bridge or bottom at -173 feet. Violation of Wyoming Statute 404(c)(iii).

TG 18 19 25 92 NENE, Section 19, T.25N., R.92W. TD 580 feet. Perma-plug. Perma-plug slid down hole. Violation of Wyoming Statute 404(c)(iii).

TG 15 19 25 92 NENE, Section 19, T.25N., R.92W. TD 580 feet. Perma-plug. Perma-plug slid down hole. Violation of Wyoming Statute 404(c)(iii).



Inspection Report Texasgulf, Inc. Drilling Notification No. 47 May 7 and 10, 1982 Page 3

....

÷...

ſ

TG 53 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Water at -149 feet with bridge or bottom at -163 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 50 17 25 92 SWSW, Section 17, T.25N., R.92W. TD 580 feet Perma-plug. Water at -157 feet with bridge or bottom at -291 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 49 17 25 92 SWSW, Section 17, T.24N., R.92W. TD 580 feet Perma-lug. Water at -151 feet with bridge or bottom at -165 feet. Violation of Wyoming Statute 404(c)(iii).

TG 73 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet. Perma-plug. Water at -150 feet with bridge or bottom at -162 feet. Violation of Wyoming Statute 404(c)(iii).

TG 38 17 25 92 SWSW, Section 17, T.25N., R.92W. TD 580 feet Perma-plug. Water at -150 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 52 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Water at -147 feet with bridge or bottom at -211. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 59 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Perma-plug slid down hole. Violation of Wyomaing Statute 404(c)(iii).

TG 60 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Water at -137 feet with bridge or bottom at -190 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 61 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Water at -147 feet with bridge or bottom at -238. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 37 21 25 92 NWNE, Section 21, T.25N., R.92W. TD 500 feet Unable to locate hole.

TG 41 21 25 92 NWNE, Section 21, T.25N., R.92W. TD 580 feet. Perma-plug. Water at -119 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 4 15 25 92 SESW, Section 15, T.25N., R.92W. TD 400 feet. Perma-plug. Water at -104 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c) (ii) and (iii).



./4

Inspection Report
Texasgulf, Inc.
Drilling Notification No. 47
May 7 and 10, 1982
Page 4

 $\mathcal{L}_{\mathbf{F}}$ 

TG 5 15 25 92 SESW, Section 15, T.25N., R.92W. TD 400 feet Perma-plug. Water at -91 feet with bridge or bottom at -238 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 3 22 25 92 NENW, Section 22, T.25N., R.92W. TD 580 feet Perma-plug. Water at ~99 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 4 32 25 92 NENW, Section 32, T.25N., R.92W. TD 260 feet Perma-plug. Water at -135 feet with bottom at -255 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 6 28 25 92 SWNW, Section 28, T.25N., R.92W. TD 340 feet Perma-plug. Water at -81 feet with bridge or bottom at -170 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 7 28 25 92 SWNW, Section 28, T.25N., R.92W. TD 340 feet Perma-plug. Water at -72 feet with bridge or bottom at -196 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 13 29 25 92 SESE, Section 29, T.25N., R.92W. TD 600 feet Perma-plug. Water at -134 feet with bridge or bottom at -187 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 27 6 24 92 NENE, Section 6, T.24N., R.92W. TD 240 feet Perma-plug. Water at -94 feet with bottom at -220 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 25 6 24 92 NENE, Section 6, T.24N., R.92W. TD 240 feet. Perma-plug. Water at -125 feet with bottom at -223 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

#### Conclusions .

Of the 42 holes inspected 41 (98%) had capping violations. The other hole was not located. Of the 35 holes in which down hole conditions were checked, 30 (86%) were in violation of sealing requirements.

It is recommended that a Notice of Violation be issued.

AG:tc

cc: -Roy Spears, Abandoned Drill Site Program Supervisor - Cheyenne DEQ-LQD -C. Alan Tapp, Senior Geologist Project Evaluation Department Texasgulf Inc. 5926 McIntyre Street Golden, CO 80401

# APPENDIX B

1

----

,

[

Proposed Remedial Plan

November 24, 1982
## Texasgulf Inc.

5926 McIntyre Street Golden, Colorado 80403 (303) 279-2636

Project Evaluation Department November 24, 1982

Department of Environmental Quality Land Quality Division 401 West 19th Street Cheyenne, Wyoming 82002

Attention: Mr. Roy Spears

Dear Mr. Spears:

On October 14, 1982, Texasgulf initiated a field program to inventory abandoned drill holes in Section 20, Township 25 North, Range 93 West of Sweetwater County, Wyoming. The inventory consisted of vegetation surveys in and around the drill sites and measurements of water levels and mud column depths for each hole. Seventy-nine drill holes were inventoried during the process, which was completed on October 22, 1982. The data generated by the inventory and Texasgulf's interpretation are enclosed. Our interpretations indicate that all holes exhibit statistical adequacy for reclamation, all holes are capped, and all holes were sealed according to D.E.Q. regulations which were in effect at the time they were drilled.

Results of studies by Texasgulf and a hydrologic consultant support the fact that on the Lost Creek/ Conoco property the Battlesprings Formation is one aquifer. A potentiometric map can be constructed for Section 20. This map depicts a relatively uniform water table which fits well with local and regional data, regardless of mud levels in drill holes.

An independent hydrologic evaluation of Texasgulf's raw drill hole data plus other sources of data was made by Hydro-Search, Inc. and is enclosed. Their final interpretation is that the Battlesprings Formation is one aquifer. In light of the compiled facts it is difficult to make any other interpretation.

As a result of local physical conditions present in each bore hole after sealing, drilling mud levels are subject to change. One drill hole inspected in Section 20, Tg-35-20, did not meet Texasgulf's sealing standards. This hole will be resealed in conjunction with the 1983 program. Department of Environmental Quality November 24, 1982

Page 2

Texasgulf's Lost Creek/Conoco property consists of approximately forty sections of land. Since our inventory covered only one section of our property, we cannot be certain other areas will show identical results. We will inventory other holes on our property in 1983 and make necessary corrections to bring any substandard findings to our standards. We will initiate the program outlined below during May of 1983 to cover about half of our property, or twenty sections. In 1984 the remainder of the property will be inventoried in the same manner.

- Beginning in May, 1983, Texasgulf will inspect about twenty sections in the Lost Creek/Conoco property in the same manner as performed in Section 20. The D.E.Q. will be provided the inventoried data.
- (2) Concrete caps will be installed in all inventoried holes in accordance with D.E.Q.'s recommendations.
- (3) During the inventory each drill site will be evaluated for reclamation success. Any found substandard will be reseeded in accordance to Wyoming Statute 35-11-404(c)(v).
- (4) Drill holes which we locate that do not meet drill holes abandonment standards will be identified and resealed at the end of the summer inspection program.

Sincerely,

C. Alan Tapp

Project Manager

CAT/dd

Enclosures

cc: D. C. Edmiston Lynn Graham 03-002-006-04

## APPENDIX C

Drill Hole Inspection Summary, 1983

	No. Holes Inspected	No. Dry Holes	No. Holes w/Concrete Caps	No. Holes Recapped
Sec. 5, T24N, R92W	12	0	10	2
Sec. 6	32	9	7	25
Sec. 1, T24N, R93W	1	1	0	1
Sec. 2, T25N, R91W	· 2	1	0	1
Sec. 2, T25N, R92W	6	1	3	2
Sec. 3	15	0	12	3
Sec. 4	4	0	4	0
Sec. 5	5	1	4	1
Sec. 8	3	0	1	2
Sec. 10	1 .	0	0	]
Sec. 11	15	2	9	6
Sec. 14	7	0	0	7
Sec. 15	1	0	Ó	1
Sec. 28	23	1	13	8
Sec. 29	26	0	7	17
Sec. 30	2	0	2	0
Sec. 31	20	0	17	3
Sec. 32	22	0	14	8
Sec. 33	29	0	25	* 1
Sec. 36	8	0	. 8	3
Sec. 16, T26N, R91W	14	3	2	7
Sec. 21, T26N, R92W	<sup>~</sup> 9	1	0	5
Sec. 24, T26N, R92W	3	0	0	2
Sec. 25	. 3	0	0	3
Sec. 29	3	1	0	]
Sec. 36	3	0	_0	1
Totals	269	21	138	. 111

<sup>1</sup> Some drill sites were inspected but the actual drill hole was not locatable. Not all holes insepcted were Texasgulf's.

erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita an erita

and the second second

-----

## APPENDIX D

## Drill Hole Inventory by Section

The second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second secon

(

Page 1 of 19

· · · · · · · · · · · · · · · · · · ·				, uge ,	0, 10	:
₩ a the st	Hole ID	Location	Original Cap	<u>Depth</u> Water	to Mud	Recapped w/concrete
			Sec. 5, T24N, R92W		:	-
	Tg 5-5	Sec. 5-24W-92W	Concrete Did not remove		:	
	Tg 2-5	Sec. 5-24W-92W	Concrete Did not remove			
	Tg 3-5	Sec. 5-24N-92W	Concrete Did not remove			
	Tg 4-5	Sec. 5-24N-92W	Concrete Did not remove			
	Tg 6-5	Sec. 5-24W-92W	Concrete Did not remove			· · · · .
	Tg 11-5	Sec. 5-24N-92W	Concrete Did not remove			
Tyawi Marin	Tg 1-5	Sec. 5-24N-92W	Perma-plug	185'	203'	Yes
	Tg 9-5	Sec. 5-24N-92W	Concrete on surface but could not locate hole			 
	Tg 10-5	Sec. 5-24N-92W	Octoplug			Yes
erenan y F F F F F F F F F F F F F F F F F F F	Tg 12-5	Sec. 5-24N-92W	Concrete cap surface Did not remove			
	Tg 8-5	Sec. 5-24N-92W	Concrete cap Did not remove			
	Tg 7-5	Sec. 5-24N-92W	Concrete cap Did not remove			
		·	<u>Sec. 6-T24W,R92W</u>			
	Tg 9-32	Sec. 32-25N-92W	Concrete Did not remove			:
- ( <b>27</b> 2	Tg 8-32	Sec. 32-25N-92W	Octoplug	197'	238'	Yes
ринц.	Tg hole approx. of Tg 20-29. So removed stake!	200' due north meone has	Concrete cap Did not remove	·		
	Tg 27-6	Sec. 6-24N-92W	Perma-plug	115'	219'	Yes

Page 2 of 19

			· .	- <b>J</b>		•	
	Hole ID	<u>Location</u>	<u>Original Cap</u>	<u>Depth</u> Water	to Mud	Recapped w/concret	<u>e</u>
	Tg 36-6	Sec. 6-24N-92W	2 Octoplugs	Dry	:	Yes	-
	Tg 6-6	Sec. 6-24N-92W	Perma-plug	185'	348'	Yes	
	Tg 35-6	Sec. 6-24N-92W	Concrete cap Did not remove			·	
	Tg 17-6	Sec. 6-24N-92W	Perma-plug	Dry	:	Yes	
	Tg 16-6	Sec. 6-24N-92W		Dry		Yes	
	Tg 33-6	Sec. 6-24N-92W	Concrete cap @+3' Did not remove				
	Tg 34-6	Sec. 6-24N-92W	Concrete was around collar of hole. How- ever, pushed bar down +5' and could not hit cement cap.	n t			
	Tg 15-6	Sec. 6-24N-92W	Perma-plug	Dry		Yes	
	Tg 14-6	Sec. 6-24N-92W	Perma-plug	180'	182'	Yes	
	Tg 13-6	Sec. 6-24N-92W	Perma-plug	Dry		Yes	
۰.	Tg 11-6	Sec. 6-24N-92W	Perma-plug	181'	281'	Yes	
	Tg 12-6	Sec. 6-24N-92W	Perma-plug	219'	349'	Yes	
	Unmarked	Sec. 6-24N-92W		Dry	• .	Yes	
	Tg 31-6	Sec. 6-24N-92W	Concrete Did not open				
	Tg 30-6	Sec. 6-24N-92W	Concrete Did not open			• •	
	Unmarked, stake removed	East of Tg 30-6		Dry		Yes	
	Unmarked, stake removed	Sec. 6-24N-92W North of Tg 31-6	Concrete Did not open				
	Unmarked, stake removed	Sec. 6-24N-92W northwest of hole above.	Perma-plug	Dry		Yes	,

;

.

.

Page 3 of 19

Hole ID	Location	Original Cap	<u>Depth</u> Water	<u>Mud</u>	Recapp <u>w/concr</u>
		<u>Sec. 6,T24N-R92W</u>			
Tg 25-6	Sec. 6-24N-92W	Perma-plug	125'	214'	Yes
Tg 20-6	Sec. 6-24N-92W	Perma-plug	122'	174'	Yes
Tg 8-6	Sec. 6-24N-92W	Perma-plug	199'	341'	Yes
Tg 7-6	Sec. 6-24N-92W	Perma-plug	228'?	355'	Yes
Tg 9-6	Sec. 6-24N-92W	Perma-plug	192'	212'	Yes
Tg 23-6	Sec. 6-24N-92W	Perma-plug	85'?	225'	Yes
Tg 24-6	Sec. 6-24N-92W	Perma-plug	?	113'	Yes
Tg 22-6	Sec. 6-24N-92W	Perma-plug	200'	209'	Yes
Tg 21-6	Sec. 6-24N-92W	Perma-plug	194'	232'	Yes
Tg 5-6	Sec. 6-24N-92W		Dry		Yes
		Sec. 1, T24N, R92W			
Tg l-l This hole has not been re- claimed	Sec. 1-24N-92W	Perma-plug	Dry	Mud pit is still open	Yes 1
·		Sec. 2,T24N,R92W		: •	
Open Hole - No I Conoco hole. Due corner Sec. 36 a recap but hole w	D. Probably an ol south of SW sect pprox. 40'. Tried as too large.	ld tion 1 to			
RD-464		Open	Dry		Yes
		Sec. 2, T25N-R92W			
Tg 2-2	Sec. 2-25N-92W	Perma÷p]ug	157'	307 '	Yes
Tg 6-2	Sec. 2-25N-92W	Concrete Did not disturb			

Page 4 of 19

.

1779 A.	Hole ID	Location	<u>Depth</u> Original Cap Water	to Recapped Mud w/concrete
	Tg 7-2	Sec. 2-25N-92W	Concrete to surface Did not disturb	
	Tg 5-2	Sec. 2-25N-92W	Concrete Did not disturb	
	Tg 4-2	Sec. 2-25N-92W	Dry	Yes
	Tg 8-2	Sec. 2-25N-92W	Couldn't find hole	•
			<u>Sec. 3,T25N,R92W</u>	
21-40y	Tg 7-3	Sec. 3-25N-92W	Concrete Did not remove	
6 arrad	Tg 5-3	Sec. 3-25N-92W	Concrete Did not remove	
	Tg 6-3	Sec. 3-25N-92W	Concrete Did not remove	
	Tg 8-3	Sec. 3-25N-92W	Concrete Did not remove	•
-	Tg 14-3	Sec. 3-25N-92W	Concrete Did not remove	
And the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second sec	Tg 1-3	Sec. 3-25N-92W	Perma-plug Cap slipped and could not breach to measure water.	Yes
prove.	TG 13-3	Sec. 3-25N-92W	Concrete Did not remove	
	Tg 12-3	Sec. 3-25N-92W	Concrete cap Did not remove	
	Old unmarked ho E-W fence towar	le north of Tg's d western end	Open	Yes
	Tg 3-3	Sec. 3-25N-92W	Concrete cap Did not remove	
	Tg 4-3	Sec. 3-25N-92W	Concrete Did not remove	
	Tg 2-3	Sec. 3-25N-92W	Cannot locate drill hole. Marker knocked down.	

.

## Page 5 of 19

	Hole ID	Location	<u>Original Cap</u>	<u>Depth to</u> Water Mud	Récar w/conc
	Tg 11-3	Sec. 3-25N-92W	Concrete cap Could not get through it. It was badly broken.	• , •	Yes
	Tg 10-3	Sec. 3-25Ń-92W	Concrete cap down approx. 3'. Could not remove it.	•	. '
	Tg 9-3	Sec. 3-25N-92W	Concrete cap Did not remove it. Cap down +4'.		
		5	Sec. 4, T25N, R92W		. *
	Tg 1-4	Sec. 4-25N-92W	Concrete cap @ 3'. Did not remove.		
	Tg 2-4	Sec. 4-25N-92W	Concrete cap @ appr 3'. Did not remove.	ox.	
	Tg 3-4	Sec. 4-25N-92W	Concrete tap @ appr 3'. Did not remove.	οχ.	
•	Tg 4-4	Sec. 4-25N-92W	Concrete cap @ appr +4'. Did not remove	OX.	
	· .	-	Sec. 5, T25N, R92W		
	Tg 3-5	Sec. 5-25N-92W	Concrete cap Did not remove		
	Unidentified ho Could not locat	le between Tg 3-5 e hole.	and Tg 2-5		
	Tg 2-5	Sec. 5-25N-92W	Concrete cap Did not remove. Cap @ approx. 3'		
	Tg 1-5	Sec. 5-25N-92W	Concrete cap at surface. Removed ar found 2' dirt on to of sage.bush. Reca	Dry nd op oped.	Ye:
	Tg 13-5	Sec. 5-25N-92W	Concrete Did not remove		.*

Page 6 of 19

	Hole ID	<u>Location</u>	Original Cap	<u>Depth t</u> Water	.o Mud	Recap w/conc
	•		Sec. 8, T25N, R92W		• '	
	Tg 1-8	Sec. 8-25N-92W	Concrete cap to surface. Good cap did not remove.			
	Capped unidentif central part of	ied open hole nea Section 8.	r			Yes
	Unreclaimed, uni drill hole in SE	dentified Conoco 考 of Section 9	Open but dry - Capped but did not fill.			Yes
			Sec. 10,T25N-R92W			
	Conoco Hole in N	IE圡 SE노 Sec. 10	Open Recapped			Yes
			Sec. 11,T25N,R92W		•	
	Tg 5-11	Sec. 11-25N-92W	Concrete cap Did not remove			
•	Tg ]-11	Sec. 11-25N-92W	Perma-plug	Water just on top.of mud.	86 '	Yes
	Tg 9-11	Sec. 11-25N-92W	Concrete cap Did not remove			
	Tg 6-11	Sec. 11-25N-92W	Concrete cap @ approx. 3'. Did not remove.			
	Tg 7-11	Sec. 11-25N-92W	Concrete cap @ approx. 4'. Did not remove.			
	Tġ 10-11	Sec. 11-25N-92W	Concréte cap Did not remove			
	Tg 2-11	Sec. 11-25N-92W	Perma-plug	123	308'	Ŷ
	Tg 11-11	Sec. 11-25N-92W	Concrete cap Did not remove			
	Tg 3-11	Sec. 11-25N-92W	Perma-plug	119'	213'	Ţ

raye / UI 13

						:
	Hole ID	Location	<u>Original Cap</u>	<u>Depth</u> Water	to Mud	Recapped w/concrete
	Tg 8-11	Sec. 11-25N-92W	Concrete cap Did not remove			• .
	Hole # 673	Sec. 11	Open hole	Dry		Yes
	Hole #109	Sec. 11	Open hole	Dry		Yes
Tenner	Tg 12-11	Sec. 11-25N-92W	Concrete cap @ approx. 3'. Did not remove.		:	
anta - i i i i i i i i i i i i i i i i i i i	Tg 13-11	Sec. 11-25N-92W	Concrete cap just under surface. Did not remove.			
	Tg 4-11	Sec. 11-25N-92W	Perma-plug	119'	244 '	Yes
Auren Perte		Se	c. 14,T25N,R92W			•
	Tg 6-14	Sec. 14-25N-92W	Perma-plug	128'	333'	Yes
	Tg 7-14	Sec. 14-25N-92W	Perma-plug	132'	354'	Yes
Subscur	Tg 5-14	Sec. 14-25N-92W	Perma-plug	119'	340'	Yes
	Tg 4-14	Sec. 14-25N-92W	Perma-plug	121'	354 '	Yes
	Tg 3-14	Sec. 14-25N-92W	Perma-plug	122'	353'	Yes
:: \$	Tg 2-14	Sec. 14-25N-92W(?)	Perma-plug	137'	357'	Yes
and a second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second sec	Tg 2-14	Sec. 14-25N-92@(?) NNW approx. 400' from above hole 539200-760000	Perma-plug	125'	348'	Yes
1 		Se	c. 15.T25NR92W			·
	Old Conoco hole	- NE눌 Sec. 15	Open hole			Yes
8 - 50 - 49 - 5 		Se	c. 28,T25N,92W		, ,	
	Stake has been re NE of northern e more or less 400	emoved. Hole is nd of last fence '.	Concrete cap Did not remove			
	Stake has been re due east of above or less.	emoved. Hole is e hole 200' more	Concrete cap Did not remove			

[

-----

Page 8 of 19

۰.

ļ	Hole ID	Loca	tion	Original Cap	ļ	<u>Depth</u> Water	to Mud	Recapped w/concrete
	Tg (?) Part of label is missing. Due north of above hole.	Sec.	28-25N-92W	Perma-plug		125'	131 <sup>±1.</sup>	Yes
	Tg 16-28	Sec.	28-25N-92W	Concrete Did not remove				
	Tg 19-28	Sec.	28-25N-92W	Concrete Did not remove		,		
	Label missing. He due south of Tg	ole ap 19-28	oprox. 400'	Concrete Did not remove				
	Tg 17-28	Sec.	28-25N-92W	Concrete Did not remove	•			
	Tg 22-28	Sec.	28-25N-92W	Concrete Did not remove				
	Tg 6-28	Sec.	28-25N-92W	Perma-plug		83'	164'	Yes
	Tg 7-28	Sec.	28-25N-92W	Perma-plug		71'	171'	Yes
	Unlabeled hole 2 from east from T not locate hole. down.	00' m g 7-28 Stake	ore or less 3-25-92. Could e was knocked					
	Label missing NE <sup>1</sup> 4	Sec.	28-25N-92W	Perma-plug		71'	233'	Yes
	Tg 10-28	Sec.	28-25N-92W	Concrete Did not remove				
	Tg_11-28	Sec.	28-25N-92W	Concrete cap Did not remove				
	Tg 12-28	Sec.	28-25N-92W	Concrete Did not remove		• •		
	Tg 1-28	Sec.	28-25N-92W	Perma-plug		133'	311	Yes
	Label missing. H 400' easterly fr	ole m om Tg	ore or less 1-28.	Perma-plug		138'	173'	Yes
	Label missing. H 400' easterly fr	ole m om Tg	ore or less 7-28	Perma-plug		1381	275'	Yes

 $\left[ \right]$ 

0 - KA

Arr HAM,

the second second second second second second second second second second second second second second second se

				I aye 3	51 13	
				Denth	to	Recapped
3	Hole 1D	Location	Original Cap	Water	Mud	w/concrete
	Tg 15-28	Sec. 28-25N-92W	Concrete Did not remove			
• • •	Tg 3-28	Sec. 28-25N-92W	Hole open @ surface. Perma-plug was side- ways.	Dry		Yes
	Stake missing. D Tg 3-28. More or	Due south of less 100-200'.	Concrete cap Did not remove			
	Site more or les above hole. Does have been drille	s 100' south of not appear to ed.				
	Tg 13-28	Sec. 28-25N-92W	Concrete cap Did not remove	÷.		
2		<u>Se</u>	ec. 29,T25N,R92W			
	Tg 3-29	Sec. 29-25N-92W	Perma-plug Slipped down hole	140'	323'	Yes
	Tg 5-29	Sec. 29-25N-92W	Perma-plug Slipped down hole	.Could not		Yes
		· .		water.	<b>C</b>	·
	Tg 4-29	Sec. 29-25N-92W	Perma-plug	154'	282'	Yes
3 3 mini	Tg 2-29	Sec. 29-25N-92W	Perma-plug	155'	247'	Yes
	Tg 10-29	Sec. 29-25N-92W	Perma-plug	154'	170'	Yes
5	Tg 9-29	Sec. 29-25N-92W	Perma-plug	150'	312'	Yes
a i i i i i i i i i i i i i i i i i i i	Tg 7-29	Sec. 29-25N-92W	Could not locate hole.	·		
Proventing Provide the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second s	Number is unkno hole approx. 20 Tg 7-29	wn. Unmarked TG O' due south of	Cap slid down hole			Yes
	Unmarked Tg hol south of Tg 7-2	e approx. 400÷500' 9	Perma-plug	135'	311'	Yes
	Tg 20-29 (Someone has pulled up our drill hole stak	Sec. 29-25N-92W es	Cement cap Did not remove		•	Yes
County -	unis yeary			•		

·

**[**\_\_\_\_\_;

Page 10 of 19

			Tage T	0 01 19	•
Hole ID	Location	Original Cap	<u>Depth</u> Water	to Mud	Recapped w/concrete
Tg 20-29	Sec. 29-25N-92W	Concrete cap Did not remove			÷
Due north of abo been removed.	ove hole. Stake has	Concrete Did not remove		· .	
Tg 27-29	Sec. 29-25N-92W	Concrete Cap had slipped down hole 5' more or less Repositioned and fil back up w/dirt. Did remove.	led not		
Tg 28-29	Sec. 29-25N-92W	Concrete cap @ surfa Did not remove	се		
Stake has been removed & does not have ID. Hol is SW of Tg 1-29	e	Perma-plug	132'	157'	Yes
Tg 1-29	Sec. 29-25N-92W	Perma-plug	142'	216'	Yes
Tg 8-29	Sec. 29-25N-92W	Perma-plug	143'	177'	Yes
Tg 19-29	Sec. 29-25N-92W	Octoplug w/"stuff" on top. Could not remove-slipped down hole.			
Tg 18-29	Sec. 29-25N-92W	Could not locate cap @ +5', no evidence of cement.			Yes
Hole WSW from Tg 18-29. Label missing.		Perma-plug	105'	332'	Yes
South of above H less. No stake.	nole 200' more or	Octoplug	102'	330 <b>'</b>	Yes
Tg 16-29	Sec. 29-25N-92W 200' more or less from above hole.	Could not locate cap @ +5'. Cap appeared to be in solid.	)		. ·
Tg 15-29	Sec. 29-25N-92W	Could not locate cap @ +5'. Solid cap.	)		

-

144.V

[\_\_\_\_]

 $\left[ \right]$ 

1 1	Hole ID	location	Original Cap	<u>Depth</u> Water	to	Recapped
	nore in		<u></u>	<u>ma der</u>	100	<u>, conci e ce</u>
	Tg 23-29	Sec. 29-25N-92W	Concrete Did not remove			
3 mm	Tg 22-29	Sec. 29-25N-92W	Concrete cap @ +5' Did not remove			, ,
	Tg 24-29	Sec. 29-25N-92W	Concrete cap had failed.	127'	181'	Yes
- Page 1	Tg 25-29	Sec. 29-25W-92W	Concrete Did not remove			
er en en en en en en en en en en en en en	Tg 26-29	Sec. 29-25N-92W	Concrete Did not remove			
p der Yre 1 1 1 1 1 1 1 1 1 1 1 1 1		<u>S</u>	ec. 31,T25N,R92W			
	Tg 3-31	Sec. 31-25N-92W	Concrete cap Did not remove			
	Tg 4-31	Sec. 31-25N-92W	Concrete cap Did not remove			
	Tg 2-31	Sec. 31-25N-92W	Concrete cap Did not remove			
<b>1</b>	Tg 22-31	Sec. 31-25N-92W	Concrete cap Did not remove			
	Tg 6-31	Sec. 31-25N-92W	Concrete cap Did not remove			Ÿ
	Tg 5-31	Sec. 31-25N-92W	Concrete cap Did not remove	•		
An orașe de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la compa	Tg 11-31	Sec. 31-25N-92W	Concrete cap Tried to remove but could not.			
	Tg 17-31	Sec. 31-25N-92W	Concrete cap Did not remove			
	Tg 7-31	Sec. 31-25N-92W	Concrete cap Did not remove			
	Tg 12-31	Sec. 31-25N-92W	Concrete cap Tried to remove but could not			•

· · ·

i an y a Digan y

Iaye H UI IS

. ,

. .

Page 12 of 19

					•
<u>Hole ID</u>	Location	Original Cap	<u>Depth</u> Water	<u>to</u> Mud	Recapped w/concrete
Tg31 Hole ID was partially missing	Sec. 31-25N-92W	Perma-plug	]4] <b>'</b>	184'	Yes
Hole due north o approx. 400-500' removed from con	f Tg 12-31-25-92 . Marker has been crete cap. No ID.	Concrete cap Did not remove		· ·	
Marker stake has east of hole Tg approx. +3'.	been rémoved. Due 11-31-25-92(?)	Concrete Did not remove			
No ID on hole st removed. Due wes	ake - has been t of last hole.	Cement cap @ +2' Did not remove			
	Se	c. 30,T25N,R92W			Υ.
Tg 1-30	Sec. 30-25N-92W	Concrete cap Did not remove			
No hole marker. removed. Due eas	Stake has been t from last hole.	Concrete cap @ approx. 3-4'. Did not remove.			· .
2	Se	c. 31,T25N-R92W			
Tg 15-31	Sec. 31-25N-92W	Concrete cap Cap is +3' thick. Tried to remove but could not.			
Tg+31 Due south approx 400' from last hole. Stake has been removed. O1 lathe by hole Tg 14-31-92.	Sec. 31-25N-92W	Octoplug @ +5' Could not breach it to measure for water	•		Yes
Unmarked hole. S removed. Due sou hole in Sec. #6,	take has been th of NE most T24-R92W.	Perma-plug	123'	210'	Yes
Due west of last stake has been r stake in hole -	hole. No marker emoved. (Small Tg 7-31-25-92)	Concrete cap Did not remove			
Approx. NNE 200' Stake has been r	from last hole. emoved.	Concrete cap			

 $\left[ \begin{array}{c} \\ \end{array} \right]$ 

Hole ID	<u>Location</u>	Original Cap	<u>Depth</u> <u>Water</u>	to Mud	Recapped w/concrete
Tg 20-31(?)	Sec. 31 or 30(?) 24N-92W	Concrete cap		,	
Tg 4-32	Sec. 32-25N-92W	Perma-plug slipped down hole. Could not probe.			Yes
Tg 12-25	Sec25N-92W (Missing sec. No Due to south of #5 200' more or less)	Concrete Did not remove			
Tg 13-25	Sec25N-92W (Missing sec. No Due north of Tg 4-32 200' more or less)	Concrete Did not remove			
Hole on west- central edge of Sec. 32. Label is missing.	Sec. 32-25N-92W	Perma-plug	146'	189'	Yes
Tg 11-32	Sec. 32-25N-92W	Concrete Did not remove			
	<u>Sec. 32,</u>	<u>125N-R92W</u>			
Tg 7-32	Sec. 32-25N-92W	Concrete Did not remove		•	
Tg 10-32	Sec. 32-25N-92W	Octoplug	129	228'	Yes
Tg 9-32	Sec. 32-25N-92W	Concrete Did not remove			
Tg 8-32	Sec. 32-25N-92W	Concrete Did not remove			
Tg 1-32	Sec. 32-25N-92W	Perma-plug	203'	254 '	Yes
Old Tg hole label is missing	Sec. 32-25N-92W (North central)	Perma-plug	144'	224 '	Yes
Tg 18-32	Sec. 32-25N-92W	Concrete Did not remove			

T\*share

......

Andrea -

1490 13 01 13

:

Page 14 of 19

:

	Hole ID	location	Original Cap	<u>Depth</u> Water	to Mud	Recapped w/concrete
-	To 19-32	Sec. 32-25N-92W	Concrete		<u>.</u>	
-			Did not remove			, ·
	Tg 5-32	Sec. 32-25N-92W	Perma-plug	153'	294 '	Yes
	Tg 5-32 (SW 400')Stake has been removed.	Sec. 32-25N-92W	Concrete Did not remove			
	Tg 14-32 (Due north of above hole)	Sec. 32-25N-92W	Concrete Did not remove			
	Due north of above hole. Stake has been removed.	Sec. 32-25N-92W	Concrete Did not remove	·.		
	Due north of above hole. Tg 17-32	Sec. 32-25N-92W	Concrete Did not remove			
	Tg 2-32	Sec. 32-25N-92W	Perma-plug	150'	215'	Yes
	Tg 4-32	Sec. 32-25N-92W(? (200' more or les due north of the above hole & 400' due north of Tg 2	?) Perma-plug s 20)	134'	249'	Yes
	· · · ·	<u>.</u>	Sec. 33, T25N-R92W			
	Tg 15-33	Sec. 33-25N-92W	Concrete Did not remove			
	Tg 16-33	Sec. 33-25N-92W	Concrete Did not remove			• • •
	Tg 4-33	Sec. 33-25N-92W	Concrete Did not remove			
	Tg 3-33	Sec. 33-25N-92W	Concrete Did not remove			
	Tg 2-33	Sec. 33-25N-92W	Concrete Did not remove			
	Tg 1-33	Sec. 33-25N-92W	Perma-plug	169'	216'	Yes
	Tg 5-33	Sec. 33-25N-92W	Concrete Did not remove	· ,		
			• •			

.

- 44,3

Construction of the second

Page 15 of 19

!

		· · ·			
<b>Y 1</b>	Hole ID	Location	Original Cap	<u>Depth to</u> Water <u>Mud</u>	w/concrete
	Tg 26-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 27-33	Sec. 33-25N-92W	Concrete Did not remove		
	Stake is missing three in central	, middle hole of part of Sec. 33	Concrete Did not remove		
	Tg 24-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 22-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 7-33	Sec. 33-25N-92W	Concrete Did not remove	• •	
	Tg 6-33	Sec. 33-25N-92W	Concrete Did not remove		. <i>*</i>
	Tg 17-33	Sec. 33-25N-92W	Concrete Did not remove	•	
	Tg's(?) No marke a Tg hole. Diffe	r on hole - not rent marker.			· .
	Tg 29-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 20-33	Sec. 33-25N-92W	Concrete Did not remove		
and and a second second second second second second second second second second second second second second se	Tg 19-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 18-33	Sec. 33-25N-92W	Concrete Did not remove	· ·	
a de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la constante de la consta	Tg 17-33	Sec. 33-25N-92W	Concrete Did not remove		
Forther Construction Forther Forther Forther Forther	Tg 8-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 9-33 Stake was pulled	Sec. 33-25N-92W			
	ground. Could not locate hole.		• • • •		

мауе то от ту

•

1

				Denth to	Recanned
Ho	ole ID	Location	Original Cap	Water Mud	w/concrete
Ho St	ole approx. 200 take has been re	' east of Tg-33. emoved. ID(?)	Concrete Did not remove	• -	
Ţġ	g 11-33	Sec. 33-25N-92W	Concrete Did not remove		
Ţ	g 12-33	Sec. 33-25N-92W	Concrete Did not remove		
T	g 13-33	Sec. 33-25N-92W	Concrete Did not remove		
Ng He	o ID. Stake has ole is east of	been removed. Tg 13-33	Concrete Did not remove		
T	g 21-33	Sec. 33-25N-92W	Concrete cap Did not remove		
		Se	c. 36,T25N,R92W		
Ţ	g 6-36	Sec. 36-25N-93W	Concrete cap Did not remove		
Т 	g 3-36	Sec. 36-25N-93W	Concrete cap Did not remove. Cou not locate cap at 5 Cement around edges hole and 0 collars. a second concrete ca	ld '. Of Put ap in.	
Т	g 2-36	Sec. 36-25N-92W	Concrete Did not remove	· · ·	
Т	g 1-36	Sec. 36-25N-92W	Concrete Did not remove		
T	g 4-36	Sec. 36-25N-93W(?)	Concrete Did not remove		
T	īg 8-36	Sec. 36-25N-92W(?) Dug up and no cap present-even though concrete was around collar.	Concrete cap?	99' 191'	Yes
			Octoplug approx. 2-3' down hole. It was turned sideways		

14 ( 1

• ••• . . .

e sinen

-

· { \_ \_ }

## Page I/ OT IY

ţ

				,		•
219999 21	Hole ID	<u>Location</u>	Original Cap	<u>Depth</u> Water	to Mud	Recapped w/concrete
	Tg 5-36	Sec. 36-25N-92W	Concrete cap Tried to remove but could not. At least 18" thick-maybe more	•		Yes
	Tg 7-36	Sec. 36-25N-92W	Concrete cap to surface. Did not remove.			
		Sec	. 16,T26N,R91W			
en reg .	Hole on southern endline @ sur- face.	Sec. 16-26N-91W	Concrete at surface Did not remove cap.	· .		
	NW across creek f	from above hole.	Capped-Not Tg hole			
с. (345) 	SW from stock por Draw-old Conoco h not find hole.	nd in Osborne nole - could				
	Due south from al	oove hole. No ID.	Recapped	Dry		
	Due south stock p small hill. Did r	oond @ top of not open.	Concrete			
·	South of above ho	ole - Conoco's (B-67	")			
ter and term	B-1115, south of (Conodo's)	above hole	Recapped	Dry	 • .	Yes
	South of B-115 ar (B-83) Conoco's (	oprox. 100' ?)	Octoplug Opened recapped			Yes
	B-112 - South of	B-83	Open	Dry		Yes
	South of B-112 #E badly caved arour Filled best we co	8-9. Could not locat nd it approx. 4' di ould.	te hole but iameter.			Yes
	Hole south of abo	ove hole - No ID	Open			Yes
	West of last fend is N-S northern m	ce next to diagonal nost hole - no ID -	road - fence no hole.			
karma i	South of above ho Left alone.	ole #75/30. Could no	ot move stake.	·	·	
	South of #26. #76	5/30. Recapped hole.				

[ ]

.

Page 18 of 19

Hole ID	Location	<u>Original Cap</u>	<u>Depth to</u> Water <u>Mud</u>	Recapped w/concr
		Sec. 21, T26N, R92W		• •
D-73 Conoco holė(?)	Sec. 21-26N-92	W	Dry	Yes
Unidentified hol	e on west edge	of Sec. 21	Open, water?	Yes
Due west of abov Could not locate	ve hole in Osbor holes (2) and	ne Draw - not Tg's.		
Due north of abo Could not locate	ove hole (in a f e hole.	ence N-S)		
In fence north f open and old - r	rom above hole. not Tg's.	Both were		Yes
North of above a locate hole - no	ind next to road ot Tg's.	. Could not		
West of above ho Completed Section	ole - not Tg's. on 21			Yes
An old Conoco ho for_Sections 20	ble next to $1/4$ & 21.	section marker		Yes
Due north approx Not Tg's and alm	<. 300' from the ready capped	above hole -		
		Sec. 24, T26N, R92W		· <del>:</del>
Unidentified hol mile north of To diameter approx couldn't - left	e next to creek holes. Hile ca 8-10' deep. Tr t open.	c. Approx. 1/2 aved 3-4' in ried to cap but	- · .	
Unidentified hol	e in NE/1/4 of	Séc. 24 - Open		Yes
Open hole due we	est of above hol	e.		Yes
	Hole ID D-73 Conoco hole(?) Unidentified hol Due west of aboy Could not locate Due north of aboy Could not locate In fence north f open and old - r North of aboye at locate hole - no West of aboye ho Completed Section An old Conoco ho for Sections 20 Due north approx Not Tg's and all Unidentified hol mile north of To diameter approx couldn't - left Unidentified hol	Hole IDLocationD-73Sec. 21-26N-92Conoco hole(?)Unidentified hole on west edgeDue west of above hole in OsborCould not locate holes (2) andDue north of above hole (in a fCould not locate hole.In fence north from above hole.open and old - not Tg's.North of above hole - not Tg's.West of above hole - not Tg's.West of above hole - not Tg's.West of above hole - not Tg's.Oue north approx. 300' from the Not Tg's and already cappedUnidentified hole next to creek mile north of Tg holes. Hile ca diameter approx. 8-10' deep. Tr couldn't - left open.Unidentified hole in NE/1/4 of Open hole due west of above hole	Hole 1DLocationOriginal CapSec. 21,T26N,R92WD-73Sec. 21-26N-92WConoco hole(?)Unidentified hole on west edge of Sec. 21Due west of above hole in Osborne Draw - Could not locate holes (2) and not Tg's.Due north of above hole (in a fence N-S) Could not locate hole.In fence north from above hole. Both were open and old - not Tg's.North of above and next to road. Could not locate hole - not Tg's.West of above hole - not Tg's. Completed Section 21An old Conoco hole next to 1/4 section marker for Sections 20 & 21.Due north approx. 300' from the above hole - Not Tg's and already cappedLnidentified hole next to creek. Approx. 1/2 mile north of Tg holes. Hlle caved 3-4' in diameter approx. 8-10' deep. Tried to cap but couldn't - left open.Unidentified hole in NE/1/4 of Sec. 24 - Open Open hole due west of above hole.	Hole 1DLocationOriginal CapDepth to WaterSec. 21,T26N,R92WD-73Sec. 21-26N-92WConoco hole(?)DryUnidentified hole on west edge of Sec. 21Open, water?Due west of above hole in Osborne Draw - Could not locate holes (2) and not Tg's.Open, water?Due north of above hole (in a fence N-S) Could not locate hole.Open, water?In fence north from above hole. Both were open and old - not Tg's.North of above hole - not Tg's.North of above hole - not Tg's.Kestion marker for:Section 21An old Conoco hole next to 1/4 section marker for:Sections 20 & 21.Sec. 24, T26N, R92WUnidentified hole next to creek. Approx. 1/2 mile north of Tg holes. Hile caved 3-4' in diameter approx. 8-10' deep. Tried to cap but couldn't - left open.Unidentified hole in NE/1/4 of Sec. 24 - Open Open hole due west of above hole.

•• ÷ •---. . ;

•----

; ; ;

| : | |----

....

;

1

.

Note: Numerous old Conoco holes were checked in Sec. 24. In most cases we could not locate holes. If they were capped, we left them along. If they were open, we recapped them with concrete.

.

#### Page 19 of 19

200'.

Dry

Hole ID	Location	<u>Original Cap</u>	<u>Depth</u> Water	<u>to</u> Mud	Recapped w/concrete
	Se	c. 25,T26N-R92W		、 :	-
Tg 2-25	Sec25-26N-92W	Perma-plug	154'	378'	Yes
Tg 3-25	Sec. 25-26N-92W	Perma-plug slid down	· · ·		Yes
Tg 1-25	Sec. 25-26N-92W	Perma-plug	193' Hit he fluid approx	282' avy @	Yes

#### Sec. 29, T26N, R92W

Tg 132-29 Sec. 29-26N-92W

Due north of hole Tg 132-29 approx. 400'. Could not locate hole.

Due north of #20 approx. 600'. Could not locate hole.

#### Sec. 36, T26N, R92W

RD 368

÷,

. ....

:

**.**...

÷

**....**,.

: •

: :

<u>...</u>

;

: • • • •

1.1

i - ..

#### Open Recapped w/concrete

Checked numerous old Conoco holes. No Tg holes. Recapped any open holes.

Open hole - no ID in south central Sec. 36. Too large to fill. Open approx. 3' in diameter + approx. 6' deep. Not Tg's.

Yes

Yes

### APPENDIX E

.

-

## Sealed Drill Holes and Abandonment Fluid Characteristics

# Resealed Drill Holes

	LOCATION
HOLE ID	NEL NEL Sec. 20, T25N, R92W
Tg-35-20-25-92	NE2, NL2, Sec. 14, T25N, R92W
Tg-1-14-25-92(?)	NW2, NW2, Sec. 14, T25N, R92W
Tg-2-14-25-92	NW2, NW2, Sec. 14, T25N, R92W
Tg-3-14-25-92	NW4, NW4, Sec. 14, T25N, R92W
Tg-4-14-25-92	NW2, NW2, Sec. 14, T25N, R92W
Tg-5-14-25-92	NW4, 1144, Sec. 14, T25N, R92W
Tg-7-14-25-92	NW2, SE2, Sec. 29, T25N, R92W
Tg-13-29-25-92(?)	NW1/2, SE1/4, Sec. 29, T25N, R92W
Tg-14-29-25-92(?)	SW1, NE14, Sec. 25, T26N, R92W
Tg-2-25-26-92	Un 47

August 1, 1983

AUG 1 5 1983

Fg Proj.Eval.Dept. Golden, CO 80403

Mr. Allen Tapp Texas Gulf Sulfer 5932 McIntyre Street Golden, Colorado 80403

Re: Sample of Abandonment Fluid

Dear Mr. Tapp:

Following is data concerning the sample of abandonment fluid you provided that was used to plug holes in Wyoming:

Mud Weight	8.7 ppg
API Filtrate	4.8 cc
Plastic Viscosity, cp	15
Yield Point, lbs/100 ft <sup>2</sup>	54
Initial Gel Strength, lbs/100 ft <sup>2</sup>	18
10 Min. Gel Strength, lbs/100 ft <sup>2</sup>	42

We now have testing equipment at our office. Please let me know when you have additional samples to be checked. Thanks for your business.

Sincerely,

Don Vesely

DPV/bb

Sealing fluid characteristics for 1983 program, con



## Texasgulf memo

Date	September 12, 1984		
То	E.J. Poole/I.L. Turner	Location	Golden
From	C.A. Tapp	Location	Golden
Subject	1984 Lost Creek and Conoco	Program	

Attached is the final report for the 1984 Lost Creek and Conoco program. As you are aware, this program was initially presented to the Wyoming D.E.Q. in 1982. Its purpose was to rescind a Notice of Violation issued to Texasgulf by the D.E.Q. for failure to properly abandon drill holes. That Notice of Violation has been rescinded by the State and our program as presented is now complete.

stopp

С. А. Т.

GCLC-77

/av Attachment: Report

## Texasgulf memo

Date	September 5, 1984		
То	E.J. Poole/I.L. Turner	Location	Golden
From	C.A. Tapp	Location	Golden
Subject	last Creek/Canaca - 1984	Program Sum	mary

Texasgulf has completed its 1984 program on the Lost Creek and Conoco properties in Sweetwater County, Wyoming. In a letter to Wyoming's D.E.Q., November 24, 1982, a two year program was outlined which would inventory Texasgulf drill holes, recapping and resealing those holes which were determined to be substandard. The 1983 phase of the program inventoried seventy-five percent of the two properties. A detailed summary of that program was sent to the Wyoming D.E.Q.

The 1984 program completes the plan as presented to the D.E.Q. in 1982. Basically it involved inspecting down the hole conditions for all locateable Texasgulf drill holes to determine the adequacy of past sealing efforts. Appendix A details all holes inspected during the 1984 program. Water levels and mud column depths were measured and recorded. Concrete caps were placed on all Texasgulf holes which were not originally capped with concrete or if the original concrete cap had failed. Down the hole conditions were evaluated and any holes which did not meet our standards for sealing were resealed. Appendix B lists those drill holes which were resealed this year.

One square mile, Sec. 20, T25N R92W, containing roughly 80 drill holes was inspected in 1982 and recapped with perma-plugs. A small ledge was cut around the bore hole and the perma-plug placed on that ledge before backfilling. During the D.E.Q.'s June, 1984 inspection, several of these holes were reviewed. Mr. Alan Guile, field inspector for the D.E.Q., felt all of these were adequately capped and Texasgulf would not have to recap them with concrete caps. E.J. Poole/I.L. Turner September 5, 1984

Page 2

Approximately nine square miles of land were inventoried in 1984. A total of 427 drill holes were inspected, of which 371 holes, eighty-seven percent, were recapped with concrete caps. Fifty-six holes could not be located for one of numerous reasons. It is interesting to note that seventy-two holes, seventeen percent, were dry. Table 1 summarizes our activities on the Lost Creek and Conoco properties.

#### TABLE 1

	Number of Holes	Number of Holes Recapped 1	Num	ber of Dry Holes	Number of Holes Resealed
1982	79	79 <sup>2</sup>			
1983	269	111		21	103
1984	427	371	:	72	27
Total	775	561	•	93	37

#### SUMMARY OF INSPECTION ACTIVITIES

Upon completion of the field inventory it was determined that twentyseven holes requred resealing. All holes were resealed late in August using a mixture of water, Shur-gel, and Quick-gel. After sealing the bore hole, they were recapped with concrete caps. Abandonment fluid specifications were tested in the field and exceeded those required by the Wyoming D.E.Q.

The inspection and resealing program of 1984 completes Texasgulf's program as outlined to the Wyoming D.E.Q. in November, 1982. All issues with the State pertaining to drill hole abandonment should be resolved at this time. However, one more inspection will probably be scheduled in the spring of 1985 to review the work completed this summer.

- 1 Some drill holes were unlocateable.
- $\frac{2}{2}$  Holes recapped with perma-plugs.

 $^3$  One hole from the 1982 program was resealed in 1983.

C. A. T.

/av Attachments - Appendix A & Appendix B

## APPENDIX A

;

\_\_\_\_\_

ţ

Hole ID	Original Cap	Water Depth	To Mud	Recapped w/concrete
TT-1	Open Hole	Dry		Yes
TT-2	Octoplug	Dry		Yes
TT-3	Could not locate dril	l hole.		
TT-4	Octoplug	Dry		Yes
TT-5	Sage Brush	174'	356 '	Yes
TT-6	Sage Brush	Dry		Yes
<b>TT-</b> 7	Octopilug	Dry		Yes
TT-8	Sage Brush	Dry		Yes
TT-9	Could not locate dril	l hole.		
TT-10	Cap was too deep to bi	reach.		Yes
TT-11	Octoplug	239 '	443 '	Yes
TT-12	Cap slipped down dril	hole.		Yes
TT-13	Octoplug	Dry		Yes
TT-14	Cap was too deep to b	reach.		Yes
TT-15	Cap slipped down the I	hole.		Yes
TT-16	Octoplug	165 '	175'	Yes
TT-17	Octoplug	Dry		Yes
TT-18	Octoplug	163'	169'	Yes
TT-19	Open Hole	Dry		Yes
TT-20	Perma-plug	210 '	270'	Yes
TT-21	Octoplug	Dry		Yes
TT-22	Octoplug	223'	270'	Yes
TT-23	Octoplug	226 '	261'	Yes
TT-24	Octoplug	Dry		Yes
TT-25	Octoplug	184 '	196 '	Yes
TT-25(?)	Perma-plug	184 '	246.1	Yes
TT-26	Octoplug	Dry		Yes
TT-27	Octoplug	Dry		Yes
TT-28	Open hole	Dry		Yes
TT-29	Octoplug	Dry		Yes
TT-30	Octoplug	י 187	202 '	Yes
TT-31	Could not locate dril	l hole.		
TT-32	Octoplug	180'	233 '	Yes
TT-33	Octoplug	177 '	208'	Yes

(

: .

[.....]

ł,

Hole	Ominical Can	Dept	<u>h To</u>	Recapped
<u> </u>	Uriniyat Cap	Water	MUG	W/concrete
TT-34	Open Hole	Dry		Yes
TT-35	Octoplug	163'	183'	Yes
TT-36	Octoplug	164 '	187 '	Yes
TT-37	Could not locate dri	ll hole.		
TT-38	Open Hole	115'	120'	Yes
TT-39	Octoplug	Dry		Yes
TT-40	Octoplug	Dry		Yes
TT-41	Octoplug	151 '	174'	Yes
TT-42	Could not locate dri	ll hole.		
TT-43	Could not locate dri	ll hole.		
TT-44	Octoplug	Dry		Yes
TT-45	Sage Brush	Dry		Yes
TT-46	Octoplug	177 '	189'	Yes
TT-47	Open Hole	156 '	234 '	Yes
TT÷48	Octoplug	Dry		Yes
TT-49	No Cap	Dry		Yes
TT-50	Octoplug	Dry		Yes
TT-51	Cap was too deep to	breach.		Yes
TT-52	Octoplug	179'	376 '	Yes
TT-53	No Cap	Dry		Yes
TT-54	Could not locate dri	ll hole.		
TT-55	Octoplug	182 '	210'	Yes
TT-56	Octoplug	Dry	,	Yes
TT-57	Octoplug	184 '	194 '	Yes
TT-58	Could not locate dri	11 hole.		
TT-59	Cap was too deep to	breach.		Yes
TT-60	Octoplug	189'	210'	Yes
TT-61	Cap was too deep to	breach.	·	Yes
TT-62	Cap slipped down dri	ll hole.		Yes
TT-63	Octoplug	Dry		Yes
TT-64	Octoplug	155 '	، 193	Yes
TT-65	Cap was too deep to	breach.		Yes
TT-66	Could not locate dri	ll hole.		Yes
TT-67	Could not locate dri	ll hole.		Yes
TT-68	Octoplug	Dry		Yes

a second

۰. ۱.

-----

ſ

Hole		Dep	th To	Recapped
	Original Cap	Water	Mud	w/concrete
TT 70			1001	N
11-70	Octopiug	190	199	res
TT-71	Octopiug	201	204	Yes
11-72	Octoplug	199'	203 '	Yes
11-73	Octoplug	195'	234 '	Yes
11-/4	Octoplug	156'	170'	Yes
TT-75	Could not locate dril	ll hole.		
TT-76	Sage Brush	Dry		Yes
TT-77	Octoplug	167.'	180'	Yes
TT-78	Sage Brush	159!	184 '	Yes
TT-79	Sage Brush	Dry		Yes
TT-80	Octoplug	180'	222 '	Yes
TT-81	Octoplug	175'	232 '	Yes
TT-82	Octoplug	176'	214 '	Yes
TT-83	Open Hole	Dry		Yes
TT-84	No Cap	Dry		Yes
TT-85	Octoplug	153'	320 '	Yes
TT-86	Could not locate dri	ll hole.		
TT-87	Octoplug	161'	190 '	Yes
TT-88	Could not locate dri	ll hole.		
TT-89	Octoplug	Dry		Yes
TT-90	Octoplug	Dry	· ·	Yes
TT-91	Octoplug	245 '	373'	Yes
TT-92	Octoplug	237 '	413 '	Yes
TT-93	Octoplug	221'	419 '	Yes
TT-94	Cap slipped down dri	11 hole.		Yes
TT-95	Cap was too deep to I	breach.		Yes
TT-96	Sage Brush	Dry		Yes
TT-97	Cap slipped down dri	ll hole.		Yes
TT-98	Cap slipped down dri	11 hole.		Yes
TT-99	Perma-plug	Dry		Yes
TT-100	Perma-plug	187 '	202 '	Yes
TT-101	Could not locate dri	ll hole.		
TT-102	Perma-plug	177 '	203 '	Yes
				. = =

i.....)

-----

[\_\_\_\_]

-

Hole		Depth	То	Recapped
ID	<u>Orinigal Cap</u>	Water	Mud	w/concrete
TT-103	Cap was too deep to brea	ach		Yes
TT-104	Cap was too deep to brea	ach.		Yes
TT-105	Perma-plug	180'	247 '	Yes
TT-106	Octoplug	178'	200 '	Yes
TT-107	Octoplug	Dry		Yes
TT-108	Octoplug	176'	182'	Yes
TT-109	Cap slipped down drill	nole.		Yes
TT-110	Octoplug	176'	229 '	Yes
TT-111	Octoplug	155'	170'	Yes
TT-112	Cap was too deep to brea	ach.		Yes
TT-113	Perma-plug	176'	214'	Yes
TT-114	Perma-plug	186'	197 '	Yes
TT-115	Perma-plug	251'	415'	Yes
TT-116	Could not locate drill	hole.		
TT-117	Cap slipped down drill	hole.		Yes
TT-118	Perma-plug	225 '	>475'	Yes
TT-119	Cap was too deep to bre	ach.		Yes
TT-120	Cap was too deep to bre	ach.	1	Yes
TT-121	Perma-plug	172'	243'	Yes
TT-122	Perma-plug	Dry	· · ·	Yes
TT-123	Perma-plug	Dry		Yes
TT-124	Cap was too deep to bre	ach.		Yes
TT-125	Perma-plug	178'	251'	Yes
TT-126	Perma-plug	179'	382 '	Yes
TT-127	Perma-plug	176'	228'	Yes
TT-128	Cap was too deep to bre	ach.		Yes
TT-129	Perma-plug	176'	197'	Yes
TT-130	Perma-plug	Dry		Yes
TT-131	Perma-plug	180′	218'	Yes
TT-132	Perma-plug	184'	203'	Yes
TT-133	Perma-plug	183'	191'	Yes
TT-134	Cap slipped down drill	hole.		Yes

.
Hole ID	Orinigal Cap	<u>Depth</u>	To Mud	Recapped w/concrete
TT-135	Perma-plug	Dry		Yes
TT-136	Perma-plug	187 '	394 '	Yes
TT-137	Cap was too deep to bre	ach.		Yes
TT-138	Perma-plug	Dry		Yes
TT-139	Cap was too deep to bre	ach.		Yes
TT-140	Cap was too deep to bre	ach.		Yes
TT-141	Could not locate drill	hole.		
TT-142	Perma-plug	184'	243 '	Yes
TT-143	Perma-plug	185'	204 '	Yes
TT-144	Perma-plug	Dry		Yes
TT-145	Open Hole	Dry		Yes
TT-146	Perma-plug	191'	207 '	Yes
TT-147	Perma-plug	195'	236 '	Yes
TT-148	Perma-plug	195'	236'	Yes
TT-149	Penma-plug	193'	239'	Yes
TT-150	Perma-plug	176'	249 '	Yes
TT-151	Perma-plug	179'	294 '	Yes
TT-152	Perma-plug	179'	2,36 '	Yes
TT-153	Perma-plug	175'	210'	Yes
TT-154	Cap slipped down drill	hole.		Yes
TT-155	Perma-plug	179'	272'	Yes
TT-156	Perma-plug	195 '	396 '	Yes

١

٠

.

Hole		Depth To	D	Recapped
ID	Orinigal Cap	Water	Mud	w/concrete
TE-1	Open Hole	Dry		Yes
TE-2	Octoplug	188'	191'	Yes
TE-3	Cap was too deep to brea	ich.		Yes
TE-4	Octoplug	205 '	401'	Yes
TE-5	Sage Brush	Dry		Yes
TE-6	Octoplug	Dry		Yes
TE-7	Octopilug	Dry		Yes
TE-8	Octoplug	Dry		Yes
TE-9	Octoplug	210'	276 '	Yes
TE-10	Octoplug	210'	221'	Yes
TE-11	Octoplug	Dry		Yes
TE-12	Octoplug	215'	227 '	Yes
TE-13	Could not locate drill I	nole.		
TE-14	Octoplug	296 '	395 '	Yes
TE-15	Octoplug	Dry		Yes
TE-16	Could not locate drill I	nole.		
TE-17	Cap was too deep to brea	ach.		Yes
TE-18	Open Hole	Dry		Yes
TE-19	Octoplug	Dry		Yes
TE-20	Octoplug	Dry		Yes
TE-21	Octoplug	207 '	238'	Yes
TE-22	Octoplug	215'	235 '	Yes
TE-23	Octoplug	210'	228'	Yes
TE-25	Octoplug	Dry		Yes
TE-26	Octoplug	221 '	225 '	Yes
TE-27	Could not locate drill	hole.		
TE-28	Octoplug	224 '	444 '	Yes
TE-29	Open Hole	Dry		Yes
TE-30	Octoplug	Dry		Yes
TE-31	Could not locate drill	hole.		
TE-32	Could not locate drill	hole.		
TE-33	Cap slipped down drill	hole		Yes
TE-34	Octoplug	223'	228 '	Yes

· •••

Hole	Ominical Can	Dep Matem	oth To	Recapped
_10	Urinigat Cap	water	Muu	w/concrete
TE-35	Octoplug	, 223 '	235'	Yes
TE-36	Octoplug	Dry		Yes
TE-37	Octoplug	219'	277 '	Yes
TE-39	No Cap	216'	220'	Yes
TE-40	Could not locate drill	hole.		
TE-41	Could not locate drill	hole.		
TE-42	Perma-plug	219'	228 '	Yes
TE-43	Perma-plug	218'	226 '	Yes
TE-44	Cap slipped down drill	hole.		
TE-45	Octoplug	211'	221 '	Yes
TE-46	No Cap	Dry		Yes
TE-47	Octoplug	204 '	248'	Yes
TE-48	No Cap	212.1	225 '	Yes
TE-49	Could not locate drill	hole.		
TE-50	Octoplug	209 '	234 '	Yes
TE-51	Octoplug	Obstruction	in hole @ about 1	00' Yes
TE-52	Octoplug	209'	247 '	Yes
TE-53	Octoplug	210'	238'	Yes
TE-54	Could not locate drill	hole.		
TE-55	Could not locatd drill	hole.		
TE-56	Open Hole	203'	230'	Yes
TE-57	Octoplug	210'	235 '	Yes
TE-58	Could not locate drill	hole.		
TE-59	Could not locate drill	hole.		
TE-60	Could not locate drill	hole.		
TE-61	Octoplug	209 '	225 '	Yes
TE-62	Could not locate drill	hole.		
TE-63	Octoplug	Dry		Yes
TE-64	Open Hole	<b>195 '</b>	224 '	Yes
TE-65	Octoplug	Dry		Yes
TE-66	Octoplug	Dry		Yes
TE-67	Octoplug	· 191'	389 '	Yes
TE-68	Could not locate drill	hole.		
TE-69	Octoplug	191'	209 '	Yes

1 1

 $\sum_{i=1}^{n}$ 

]

Page 8 of 14

Hole ID	Orinigal Cap	<u>Depth To</u> Water	<u>Mud</u>	Recapped w/concrete
<b>TE-</b> 70	Octoplug	189'	252'	Yes
TE-71	Octoplug	Dry		Yes
TE-72	Octoplug	192'	211'	Yes
TE-73	Octoplug	Dry		Yes
TE-74	Octoplug	227 '	249 '	Yes
TE-75	Octoplug	229'	270'	Yes
TE-76	Octoplug	211'	248'	Yes
TE-77	Open Hole	Dry		Yes
TE-78	Octoplug	Dry		Yes
TE-79	Open Hole	214'	308 1	Yes
TE-80	Octoplug	Dry		Yes
TE-81	Octoplug	?	250'	Yes
TE-82	Octoplug	212 '	253'	Yes
TE-83	Octoplug	207 '	326 '	Yes
TE-84	Octoplug	212'	241'	Yes
TE-85	Could not locate drill h	nole.		
TE-86	Open Hole	223'	275 '	Yes
TE-87	Octoplug	233'	238'	Yes
TE-88	Octoplug	216'	219'	Yes
TE-89	Octoplug	194'	230'	Yes
TE-90	Perma-plug	209 '	243 '	Yes
TE-91	Cap was too deep to brea	ach.		Yes
TE-92	Perma-plug	204 '	252 '	Yes
TE-93	Perma-plug	205 '	225 '	Yes
TE-94	Perma-plug	205'	227 '	Yes
TE-95	Could not locate drill I	nole.		
TE-96	Perma-plug	203'	207 '	Yes
TE-97	Cap slipped down drill I	hole.		
TE-101	Perma-plug	195'	199 '	Yes

		2				
	Hole ID	Orinigal Cap	Water	Depth To	Mud	Page 9 of 14 Recapped w/concrete
ł	TGC-1-15	Could not locate drill	hole.			
	TGC-2-15	Could not locate drill	hole.			
	TG-3-15	Could not locate drill	hole.			
	TG-4-15	Perma-plug	104'		200'	Yes
	TG-5-15	Perma-plug	90 '		233'	Yes
	TG-6-15	Perma-plug	94 '		229'	Yes
	TG-7-15	Perma-plug	، 99		115'	Yes
	TG-8-15	Open Hole	113'		200 '	Yes
	TG-9-15	Perma-plug	92'		245 '	Yes
	TG-10-15	Perma-plug	י 97		225 '	Yes
	TG-11-15	Perma-plug	100'		231 '	Yes
	TG-1-17	Perma-plug	160'		238'	Yes
	TG-3-17	Perma-plug	155'	1	160'	Yes
	TG-5-17	Perma-plug	151'		368 '	Yes
	TG-6-17	Perma-plug	166 '		395 '	Yes
	TG-7-17	Perma-plug	157'		239'	Yes
)	TG-8-17	Cap slipped down drill	hole.			
	TG-9-17	Perma-plug	151 -		163'	Yes
	TG-10-17	Perma-plug	153 !		313 '	Yes
	TG-11-17	Perma-plug	159'		186 '	Yes
	TG-12-17	Perma-plug	152'		154 '	Yes
	TG-13-17	Perma-plug	158'		288 '	Yes
	TG-15-17	Perma-plug	167'		341'	Yes
	TG-16-17	Perma-plug	167'		241 '	Yes
	TG-17-17	Perma-plug <sub>()</sub>	160'		205 '	Yes
	TG-18-71	Perma-pilug	167'		190 !	Yes
	TG-19-17	Perma-plug	156'		203 '	Yes
	TG-20-17	Perma-pilug	161'		294 '	Yes
	TG-21-17	Perma-plug	163'		357 '	Yes
	TG-22-17	Perma-plug	171'		248 '	Yes
	TG-23-17	Perma-plug	155'		186'	Yes
	TG-24-17	Perma-plug	157'		201 '	Yes

print .

 $\left[ \right]$ 

, ,

Hole ID	Orinigal Cap	<u>Water</u>	oth To Mud	Recapped w/concrete
TG-25-17	Perma-plug	159'	221 '	Yes
TG-26-17	Perma-plug	158'	166 '	Yes
TG-27-17	Perma-plug	163'	271 '	Yes
TG-28-17	Perma-plug	162 '	225 '	Yes
TG-29-17	Perma-plug	161'	238'	Yes
TG-30-17	Perma-plug	168'	243'	Yes
TG-32-17	Perma-plug	160'	196'	Yes
TG-33-17	Perma-plug	161'	200 '	Yes
TG-34-17	Perma-plug	158'	275 '	Yes
TG-35-17	Perma-plug	152'	333 '	Yes
TG-36-17	Cap was too deep to	breach.		Yes
TG-37-17	Perma-plug	161'	317 '	Yes
TG-38-17	Perma-plug	151'	176'	Yes
TG-39-17	Cap was too deep to	breach.	,	Yes
TG-40-17	Cap was too deep to	o breach.		Yes
TG-41-17	Cap was too deep to	o breach.		Yes
TG-42-17	Cap was too deep to	o breach.		Yes
T <b>G-</b> 43-17	Perma-plug	161'	438 '	Yes
TG-44-17	Perma-plug	166 '	286 '	Yes
TG-45-17	Cap was too deep to	o breach.		Yes
TG-46-17	Cap slipped down d	rill hole.		Yes
TG-47-17	Cap was too deep t	o breach.		Yes
TG-48-17	Cap was too deep t	o breach.		Yes
TG-49-17	Perma-plug	151'	159 '	Yes
TG-50-17	Cap was too deep t	o breach.	·	Yes
TG-51-17	Concrete cap. Did	not remove.		
TG-52-17	Concrete cap. Did	not remove.		
TG-1-18	Perma-plug	151'	156 '	Yes
TG-2-18	Perma-plug	156'	242 '	Yes
TG-3-18	Cap was too deep t	o breach.		Yes
TG-4-18	Perma-plug	164 '	176 '	Yes
TG-5-84	Perma-plug	159 '	168'	Yes
TG-6-18	Perma-plug	166 '	306 '	Yes

Page 11 of 14

Hole ID	Orinigal Cap	Water	Depth To Mud	Recapped w/concrete
TG-7-18	Perma-plug	167'	224 '	Yes
TG-8-18	Perma-plug	157'	341'	Yes
TG-9-18	Could not locate dr	ill hole.	· ·	
TG-10-18	Perma-plug	166'	298'	Yes
TG-11-18	Could not locate dr	ill hole.		
TG-12-18	Perma-plug	173'	206 '	Yes
TG-13-18	Perma-plug	154'	379 '	Yes
TG-14-18	Could not locate dr	ill hole.		
TG-15-18	Perma-plug	156'	238 '	Yes
TG-16-18	Cap slipped down di	ll hole.		
TGC-17-18	Cap was too deep to	breach.		Yes
TGC-18-18	Perma-plug	155'	369 '	Yes
TGC-19-18	Perma-plug	155'	389 '	Yes
TG-20-18	Cap was too deep to	breach.		Yes
TGC-20-18	Cap was too deep to	breach.		Yes
TG-21-18	Cap was too deep to	breach.		Yes
TGC-21-18	Cap slipped down dr	ill hole.		Yes
TG-22-18	Cap was too deep to	breach.		Yes
TG-23-18	No Cap.	Dry		Yes
TG-24-18	Cap was too deep to	breach.		Yes
TG-25-18	Cap was too deep to	breach.		Yes
TG-27-18	No Cap.	Dry		Yes
TG-1-19	Perma-plug	145 '	2231	Yès
TGC-1-19	Perma-plug	154 '	180'	Yes
TGC-1A-60-19	Angle hole. Could n	ot probe.		Yes
TGC-1A-45-19	Angle hole. Could r	ot probe.	•	Yes
TG-2-19	Perma-plug	143'	144 '	Yes
TGC-2-19	Could not breach ca	ıp		Yes
TG-3-19	Perma-plug	129'	139'	Yes
TG-4-19	Perma-plug	138'	<b>&gt;</b> 450 '	Yés
TG-5-19	Perma-plug(open)	145 '	215 '	Yes
TG-6-19	Cap was too deep to	breach.		Yes
TG-7-19	Cap slipped down dr	ill hole.		Yes
				-

Hole ID	Orinigal Cap	Water Dept	<u>h To</u> Mud	Recapped w/concrete
TG-8-19	Cap failed at surface.	Could not pr	obe.	Yes
TG-9-19	Perma-plug(open)	158'	7450'	Yes
TG-10-19	Perma-plug	154 '	283'	Yes
TG-11-19	Perma-plug	Dry		Yes
TG-12-19	Perma-plug	160'	331'	Yes
TG-13-19	Cap slipped down drill	hole.		Yes
TG-14-19	Perma-plug	159'	175 '	Yes
TG-15-19	Cap was too deep to br	each.		Yes
TG-16-19	Could not locate drill	hole.		
TG-17-19	Cap was too deep to br	each.		Yes
TG-18÷19	Cap failed at surface.	Could not pr	obe.	Yes
TG-19-19	Cap was too deep to br	each.		Yes
TG-20-19	Cap was too deep to br	each.		Yes
TG-21-19	Cap slipped down drill	hole.	· .	Yes
TG-22-19	Cap was too deep to br	each.		Yes
TG-23-19	Cap was too deep to br	each.		Yes
TG-24-19	Cap was too deep to br	each.		Yes
TG-25-19	Cap was too deep to br	each.		Yes
TG-1A-75-19	Angle hole. Could not	probe.	•	Yes
TG-1A-60-19	Angle hole. Could not	probe.		Yes
TG-1-21	Perma-plug	144'	316 '	Yes
TG-2-21	Perma-plug	142'	366 '	Yes
TG-3-21	Cap was too deep to bi	reach.		Yes
TG-4-21	Perma-plug	118'	414 '	Yes
TG-5-21	Cap was too deep to bu	reach.		Yes
TG-6-21	Perma-plug	129 '	142'	Yes
TG-7-21	Perma-plug	132'	296 '	Yes
TG-8-21	Cap slipped down dril	l hole.		Yes
TG-9-21	Perma-plug	116'	159'	Yes
TG-10-21	Cap was too deep to b	reach.	· · · ·	Yes
TG-11-21	Perma-plug	124 '	282 '	Yes
TG-12-21	Perma-plug	131'	279 '	Yes
TG-13-21	Perma-plug	121'	421 '	Yes
TG-14-21	Perma-plug	128'	259 '	Yes

Page Server 

.

Hole	Orinigal Can	Water Dep	th To Mud	Recapped
	ormiguit oup	Match	nud	W/CONCIECE
TG-14-21	Could not locate dr	ill hole.		
16-15-21	Perma-plug	128'	429 '	Yes
TG-17-21	Perma-plug	129'	145'	Yes
TG-18-21	Perma-plug	121 '	166'	Yes
TG-19-21	Perma-plug	133'	291 '	Yes
TG-20-21	Cap slipped down dr	ill hole.		Yes 🔿
TG-21-21	Perma-plug	109'	319'	Yes
TG-22-21	Perma-plug	115'	116'	Yes
TG-23-21	Cap slipped down dr	ill hole.		Yes
TG-24-21	Cap was too deep to	breach.		Yes .
TG-25-21	Perma-plug	100'	312'	Yes
TG-26-21	Open	Dry		Yes
TG-28-21	Perma-plug	127 '	131'	Yes
TG-29-21	Perma-plug	115'	308 '	Yes
TG-30-21	Cap slipped down dr	ill hole.		Yes
TG-31-21	Sage Brush	110'	113'	Yes
No ID	Drill site, but cou	ld not locate d	rill hole.	
TG-32-21	Perma-Plug	Dry		Yes
TG-33-21	Sage Brush	Dry		Yes
TG-34-21	Perma-plug	88 '	117 '	Yes
TG-35-21	Perma-plug	80'	115'	Yes
TG-36-21	Could not locate dr	ill hole.	•	
TG-37-21	Cap was too deep to	breach.		Yes
TG-38-21	Cap slipped down dr	ill hole.		Yes
TG-39-21	Perma-plug	88'	202 '	Yes
TG-40-21	Perma-plug	86 '	93'	Yes
TG-41-21	Cap was too deep to	breach.		Yes
TG-42-21	Perma-plug	112'	345 '	Yes
TG-44-21	Concrete cap. Did n	ot remove.		-
TG-45-21	Concrete cap. Did n	ot remove.		
TG-46-21	Could not locate dr	ill hole.		
TG-47-21	Concrete cap. Did n	ot remove.		
TG-48-21	Cap was too deep to	breach.		Yes
TG-49-21	Could not locate dr	ill hole.		

2 ·

 $\left( \begin{array}{c} \\ \end{array} \right)$ 

Page 14 of 14

Hole ID	Orinigal Cap	Water Depth To	Mud	Recapped w/concrete
TG-50-21	Concrete cap. Did not re	move.		•
TG-3-21(?)	Sage Brush	98'	218'	Yes
TGC-27-21	Could not locate drill h	òle.		
TGC-16-21	Could not locate drill h	ole.		
TG-1-22	Could not locate drill h	ole.		
TG-2-22	Perma-plug	97 '	279'	Yes
TG-3-22	Perma-plug	98'	284 '	Yes

TOTAL NUMBER OF HOLES INSPECTED:	427	100%
TOTAL NUMBER OF HOLES CAPPED:	371	87%
NUMBER OF DRY HOLES:	72	17%
NUMBER OF WET HOLES:	213	50%
NUMBER OF UNPROBED HOLES:	142	33%

/av

Contract of the second

1

-

# APPENDIX B

 $\left[ \right]$ 

 $\left( \begin{array}{c} \end{array} \right)$ 

 $\left[ \right]$ 

# RESEALED DRILL HOLES

12

	Hole Number		Location				
	TT-5	SW1/4,	NW1/4,	Sec.	19,	T25N,	R92W
•	TT-11	SW1/4,	SE1/4,	Sec.	7,	T25N,	R92W
	TT-52	SE1/4,	NE1/4,	Sec.	24,	T25N,	R93W
	TT-91	SW1/4,	SE1/4,	Sec.	7,	T25N,	R92W
	TT-92	SE1/4,	SW1/4,	Sec.	7,	T25N,	R92W
	TT-93	NW1/4,	NE1/4,	Sec.	18,	T25N,	R92W
	TT-115	NW1/4,	NE1/4,	Sec.	13,	T25N,	R93W
	TT-118	NE1/4,	NW1/4,	Sec.	18,	T25N,	R92W
	TT-126	SW1/4,	NW1/4,	Sec.	19,	T25N,	R92W
	TT-136	SW1/4,	NE1/4,	Sec.	24,	T25N,	R93W
	TT-156 .	SW1/4,	NE1/4,	Sec.	24,	T25N,	R93W
	TE-4	NW1/4,	NE1/4,	Sec.	24,	T25N,	R93W
	TE-14	NW1/4,	NW1/4,	Sec.	23,	T25N,	R93W
	TE-28	NE1/4,	NW1/4,	Sec.	24,	T25N,	R93W
	TE-67	SW1/4,	NE1/4,	Sec.	24,	T25N,	R93W
	TG-5-17	SW1/4,	SW1/4,	Sec.	17,	T25N,	R92W
	TG-6-17	SW1/4,	SW1/4,	Sec.	17,	T25N,	R92W
	TG-21-17	SE1/4,	SW1/4,	Sec.	17,	T25N,	R92W
	TG-43-17	SW1/4,	SW1/4,	Sec.	17,	T25N,	R92W
	TG-13-18	SE1/4,	SE1/4,	Sec.	18,	T25N,	R92W
	TGC-18-18	SE1/4,	SE1/4,	Sec.	18,	T25N,	R92W
	TG-4-19	SE1/4,	NE1/4,	Sec.	19,	T25N,	R92W
	TG-9-19	NE1/4,	NE1/4,	Sec.	19,	T25N,	R92W
	TG-2-21	NW1/4,	NW1/4,	Sec.	21,	T25N,	R92W
	TG-4-21	NE1/4,	NW1/4,	Sec.	21,	T25N,	R92W
	TG-13-21	NE1/4,	NW1/4,	Sec.	21,	T25N,	R92W
	TG-15-21	NW1/4.	NE1/4.	Sec.	21.	T25N.	R92W

Party -

.

## January 15, 2007

Melissa L. Bautz Senior Environmental Analyst State of Wyoming Department of Environmental Quality Land Quality Division 510 Meadowview Drive Lander, WY 82520

RE: Drilling Notification No. 334DN Amendment, NFU Wyoming, LLC

Dear Ms. Bautz,

NFU Wyoming, LLC, an affiliate of Ur-Energy USA, has completed the installation of 17 new monitoring wells within the Lost Creek Project area, T25N, R92 and 93W, Sweetwater County, Wyoming. These water wells were also permitted through the State Engineer's Office.

During the 2006 field activities, a total of 19 historic exploration holes near our new wells were found to be open. This includes seven holes drilled in 2005 by NFU Wyoming in which the plug gel did not sufficiently stabilize. These holes were reamed out, plugged with grout, and capped with 25 feet of cement to assure the quality and integrity of our hydrological testing results. This plugging method was approved by the WDEQ for use by NFU Wyoming in 2006. This part of the project constituted over 11,600 feet of reaming and plugging at an additional cost to NFU Wyoming of \$30,000.

For reclamation, each well and historic drilling site was then recontoured, the stockpiled topsoil was replaced, and the site was reserved. A detailed, site-specific vegetation survey conducted by Keammerer Ecological Consultants, Inc. in 2006 indicated that the vegetation types growing on the site are slightly different than the standard BLM recommended seed mix. The new mix and the seeding proportions are indicated on the completion reports. With the permission of both the WDEQ and the BLM, this new seed mix was used at each disturbed site in order to promote re-vegetation similar to the existing conditions.

Per the Reporting Requirements, Section 8, Form 9DN, "Department of Environmental Quality, Land Notification of Intent to Explore for Noncoal Minerals by Drilling", we are

attaching the following lists of information in duplicate to your office and the State Engineer's office with a copy to the U.S. BLM office in Rawlins.

- 1. A tabulation of the monitoring wells and historic plugged holes, including quadrangle location, northing and easting coordinates, elevation, total depth/depth plugged, date completed/plugged, land ownership, disturbance, reclamation, seed mix, seeding method, and seeding date.
- 2. A tabulation of the wells by ¼, ¼ Section, Township, and Range
- 3. A map on USGS quadrangle format showing the location of the wells and an outline of the general area of the exploration activities.

If you need any additional information, please do not hesitate to contact either myself of Dawn Schippe at 720-981-4588.

Sincerely,

Harold A. Backer VP US Operations

Cc: State Engineer's Office Mark Newman, U.S. BLM

### 2006 Drilling Program WDEQ Completion Report NFU Wyoming, LLC - Lost Creek Project - Sweetwater County Drilling Notification Number #334DN

#### Operator: NFU Wyoming, LLC Operator Address: 10758 W. Centennial Road, Suite 200, Littleton, CO 80127 Drilling Notification Number: 334DN

· · · · · · · · · · · · · · · · · · ·		WY State Plane, NAD 27					1		1		· · ·			
·	WY State Engineer	USGS 7.5 Minute	S 7.5 Minute West Central Zone		Pilot Hole							Seed Mix (Approved by WDEQ		
Hole ID	Permit Number	Quad	. N	Ę	TD	Date Completed	Capping Method	Plugging Method	Ownership	Disturbance	Reclamation	and BLM)	Seed Method	Seeding
·IC15M	U.W. 175260	Osbourne Well	534.823	744,546	350	9/13/2006	Monitoring Well was	Monitoring Well is	US Department of the	15' x 25'	Stockpiled topsoil and replaced	Total 19.5 lb/acre: Thickspike	Seed spread	12/22/2006
	0						installed and is	operational.	Interior US BLM	Disturbance, all	after completion of drilling and	wheatgrass 4 lb/acre; Western	with Kubota	
							operational. 4 1/2"	Schedule 40 PVC		drilled from	recontouring of site	wheatgrass 2 lb/acre; Indian	tractors and	
							diameter PVC well,	pipe anchored in		same pad	_	ricegrass 2 lb/acre; Prairie	Truax no-till	
							protruding	ground by cement				sandreed 2 lb/acre; Great Basin	seed drills;	
			)				approximately 2' out	(except LC29, 30,				wildrye 2 lb/acre; Big sagebrush	fertilizer will be	
							of ground with 1/2.	and 31M which are				1 lb/acre; Rubber rabbitbrush 1	spread in Spring	
							3/4, or 1 hp pump	gravel packed to 20'				Ib/acre; Winterfat (Ceratoides	2007	
							installed, Entire	below surface, above				lanata) 1.5 lb/acre; Slender		
							assembly protected	is 15' bentonite chips,		ļ		wheatgrass (Agropyron		
							by locking well cover	with 5' soll on top), 7				trachycaulum) 2.5 lb/acre;		
							anchored below	7/8" diameter drilled				Sandberg Bluegrass (Poa	,	
							ground surface.	hole.				secunda) 1.5 lb/acre		
LC16M	11W/ 175260	Osbourne Well	534,820	744,562	472	9/13/2006	Same as Above	Same as Above	Same as Above	1	Same as Above	Same as Above	Same as Above	12/22/2006
LC17M	UW 175260	Osbourne Well	534,840	744.562	575	9/13/2006	Same as Above	Same as Above	Same as Above	1	Same as Above	Same as Above	Same as Above	12/22/2006
1:C29M	U.W. 175260	Osbourne Well	534,837	744,547	171	9/21/2006	Same as Above	Same as Above	Same as Above		Same as Above	Same as Above	Same as Above	12/22/2008
	0.111 11 0200													
LC18M	U.W. 175261	Osbourne Well	535,318	743,362	350	9/21/2006	Same as Above	Same as Above	Same as Above	15' x 25'	Same as Above	Same as Above	Same as Above	12/21/2006
LC19M	U.W. 175261	Osbourne Well	535,317	743,378	463	9/21/2006	Same as Above	Same as Above	Same as Above	Disturbance, all	Same as Above	Same as Above	Same as Above	12/21/2006
LC20M	U.W. 175261	Osbourne Well	535,332	743,377	543	9/22/2006	Same as Above	Same as Above	Same as Above	drilled from	Same as Above	Same as Above	Same as Above	12/21/2006
LC21M	U.W. 175262	Antelope Reservoir	532,850	736,277	410	9/21/2006	Same as Above	Same as Above	Same as Above	15' x 25'	Same as Above	Same as Above	Same as Above	12/21/2006
LC22M	U.W. 175262	Antelope Reservoir	532,850	736,292	592	9/22/2006	Same as Above	Same as Above	Same as Above	Disturbance, all	Same as Above	Same as Above	Same as Above	12/21/2006
LC23M	U.W. 175262	Antelope Reservoir	532,835	736,292	634	9/22/2006	Same as Above	Same as Above	Same as Above	drilled from	Same as Above	Same as Above	Same as Above	12/21/2006
LC30M	U.W. 175262	Antelope Reservoir	532,836	736,276	236	9/21/2006	Same as Above	Same as Above	Same as Above	same pad	Same as Above	Same as Above	Same as Above	12/21/2006
LC24M	U.W. 175263	Osbourne Well	535,203	744,580	542	9/22/2006	Same as Above	Same as Above	Same as Above	15' x 25'	Same as Above	Same as Above	Same as Above	12/22/2006
LC25M	U.W. 175264	Osbourne Well	534,621	743,406	380	9/22/2006	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	12/21/2006
LC26M	U.W. 175265	Osbourne Well	534,832	748,203	436	9/22/2006	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	12/22/2006
LC27M	U.W. 175266	Osbourne Well	539,018	753,260	477	9/27/2006	Same as Above	Same as Above	State	Same as Above	Same as Above	Same as Above	Same as Above	12/22/2006
							[							101010000
LC28M	U.W. 175267	Battle Springs	524,437	733,364	563	9/22/2006	Same as Above	Same as Above	US DOI BLM	Same as Above	Same as Above	Same as Above	Same as Above	12/21/2006
LC31M	U.W. 175268	Battle Springs	524,434	733,380	191	9/22/2006	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	12/22/2006

٠;

Maintaining all completed water wells under State Engineer Permits listed above