



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
SAM NUNN ATLANTA FEDERAL CENTER
61 FORSYTH STREET, SW, SUITE 23T85
ATLANTA, GEORGIA 30303-8931

June 17, 2009

EA-09-121

Mr. Benjamin C. Waldrep
Vice President
Carolina Power and Light Company
Brunswick Steam Electric Plant
P.O. Box 10429
Southport, NC 28461

SUBJECT: BRUNSWICK STEAM ELECTRIC PLANT, NRC INSPECTION REPORT
05000325/2009009 AND 05000324/2009009 AND PRELIMINARY WHITE
FINDING

Dear Mr. Waldrep:

On May 13, 2009, the Nuclear Regulatory Commission (NRC) completed an in-office inspection of an unresolved item (URI) associated with the Brunswick Steam Electric Plant which was identified in NRC Inspection Report 05000325/2008010 and 05000324/2008010 (ADAMS Accession Number ML083470550) forwarded to you on December 12, 2008. Specifically, URI 05000325, 324/2008010-001, Verify cable routing locations affected by a design change error which resulted in a loss of emergency diesel generator (EDG) local control function, was identified as unresolved pending review of the EDG control wire routing to verify what areas were affected. The enclosed inspection report documents the inspection results, which were discussed on May 28, 2009, with you and other members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with the NRC's rules and regulations and with the conditions of your license. Based on the results of this inspection, a finding was identified involving the failure to correctly translate the design basis into Engineering Change (EC) 66274 to replace control relays on all four EDGs. Specifically, termination points for linking control power to the EDG lockout relay reset circuitry were incorrectly designated in EC 66274. This resulted in the wiring for the control relays being installed such that the EDGs could not be operated locally as required by the Safe Shutdown Analysis Report. On August 19, 2008, EC 66274 was revised to correct the wiring error. On August 21, 2008, all four EDGs were rewired, tested to demonstrate local control capability, and returned to service. Therefore, this finding does not represent an immediate safety concern.

This finding was assessed, based on the best available information, including influential assumptions, using the applicable Significance Determination Process (SDP). The dominant accident sequences involved are initiated by a fire situated such as to cause both a loss of offsite power and a forced main control room evacuation. For these dominant accident sequences, the performance deficiency will result in a station blackout to either or both Units.

The exposure period for this condition was one year. As a result, the finding was preliminarily determined to be a low to moderate safety significance (White). The preliminary Phase 3 SDP analysis is included as Enclosure 2.

The finding is an apparent violation of 10 CFR 50, Appendix B, Criterion III, "Design Control", for failure to correctly translate the design basis into specifications, drawings, procedures and instructions, and is being considered for escalated enforcement in accordance with the NRC's Enforcement Policy. In addition, this finding is considered to have a cross-cutting aspect related to accurate design documentation [H.2(c)], as described in the resources component of the human performance cross-cutting area. Accordingly, for administrative purposes, URI 05000325, 324/2008010-001 is considered closed. The current Enforcement Policy can be found on the NRC's website at <http://www.nrc.gov/about-nrc/regulatory/enforcement/enforce-pol.html>.

In accordance with Inspection Manual Chapter 0609, we intend to complete our evaluation using the best available information and issue our final determination of safety significance within 90 days of the date of this letter. The SDP encourages an open dialogue between the staff and the licensee; however, the dialogue should not impact the timeliness of the NRC's final determination. Before we make a final decision on this matter, we are providing you an opportunity to: (1) present your perspectives on the facts and assumptions used by the NRC to arrive at the finding and its significance at a regulatory conference; or (2) submit your position on the finding to the NRC in writing. If you request a regulatory conference, it should be held within approximately 30 days of the receipt of this letter, and we encourage you to submit supporting documentation at least one week prior to the conference in an effort to make the conference more efficient and effective. If a regulatory conference is held, it will be open for public observation. The NRC will also issue a press release to announce the conference. If you decide to submit only a written response, such submittal should be sent to the NRC within 30 days of the receipt of this letter. If you decline to request a regulatory conference or submit a written response, you relinquish your right to appeal the final SDP determination, in that by not doing either, you fail to meet the appeal requirements stated in the Prerequisite and Limitation sections of Attachment 2 of Inspection Manual Chapter 0609.

Please contact Ms. Rebecca Nease at (404) 562-4530 within 10 business days of the date of your receipt of this letter to notify the NRC of your intentions. If we have not heard from you within 10 business days, we will continue with our significance determination and enforcement decision and you will be advised by separate correspondence of the results of our deliberations on this matter.

Since the NRC has not made a final determination in this matter, no Notice of Violation is being issued for this inspection finding at this time. In addition, please be advised that the number and characterization of the apparent violation may change as a result of further NRC review. In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and Enclosure 1 will be made available electronically for public inspection in the NRC Public

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

CP&L

3

Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>. However, because of the security-related information contained in Enclosure 2, and in accordance with 10 CFR 2.390, a copy of Enclosure 2 will not be available for public inspection.

Sincerely,

/RA/

Kriss M. Kennedy, Director
Division of Reactor Safety

Docket Nos.: 50-325, 50-324
License Nos.: DRP-71, DRP-62

Enclosures: 1. NRC Inspection Report 05000325/2009009 and 05000324/2009009
w/Attachment: Supplemental Information
2. SDP Phase 3 Summary (**OFFICIAL USE ONLY - SECURITY-RELATED INFORMATION**)

cc w/encls.: (See page 4)

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

CP&L

4

cc w/encls:
Christos Kamilaris
Director
Fleet Support Services
Carolina Power & Light Company
P.O. Box 1551
Raleigh, NC 27602-1551

Edward L. Wills, Jr.
Plant General Manager
Brunswick Steam Electric Plant
Progress Energy Carolinas, Inc.
P. O. Box 10429
Southport, NC 28461-0429

R. J. Duncan, II
Vice President
Nuclear Operations
Carolina Power & Light Company
P.O. Box 165, Mail Zone 1
New Hill, NC 27562-0165

Thomas D. Walt
Vice President
Nuclear Oversight
Carolina Power and Light Company
P.O. Box 1551
Raleigh, NC 27602-1551

Gene Atkinson
Supervisor, Licensing/Regulatory Programs
Brunswick Steam Electric Plant
Progress Energy Carolinas, Inc.
P.O. Box 10429
Southport, NC 28461-0429

Allen K. Brittain
Manager, Nuclear Plant Security
Brunswick Steam Electric Plant
Progress Energy Carolinas, Inc.
P.O. Box 10429
Southport, NC 28461-0429

Michael J. Annacone
Director Site Operations
Brunswick Steam Electric Plant
Progress Energy Carolinas, Inc.
P.O. Box 10429
Southport, NC 28461-0429

Phyllis N. Mentel
Manager, Support Services
Brunswick Steam Electric Plant
Progress Energy Carolinas, Inc.
P.O. Box 10429
Southport, NC 28461-0429

Brian C. McCabe
Manager, Nuclear Regulatory Affairs
Progress Energy Carolinas, Inc.
P.O. Box 10429
Southport, NC 28461-0429

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

CP&L

5

Letter to Benjamin C. Waldrep from Kriss M. Kennedy dated June 17, 2009

SUBJECT: BRUNSWICK NUCLEAR PLANT, NRC INSPECTION REPORT
05000325/2009009 AND 05000324/2009009 AND PRELIMINARY WHITE
FINDING

Distribution w/encls:

C. Evans, RII EICS (Part 72 Only)
L. Slack, RII EICS (Linda Slack)
OE Mail (email address if applicable)
RIDSNNRRDIRS
PUBLIC
RidsNrrPMBrunswick Resource

(Letter and Enclosure 1)

PUBLICLY AVAILABLE NON-PUBLICLY AVAILABLE SENSITIVE NON-SENSITIVE
ADAMS: Yes ACCESSION NUMBER: _____ SUNSI REVIEW COMPLETE

(Letter and Enclosures 1 and 2)

PUBLICLY AVAILABLE NON-PUBLICLY AVAILABLE SENSITIVE NON-SENSITIVE
ADAMS: Yes ACCESSION NUMBER: _____ SUNSI REVIEW COMPLETE

OFFICE	RII:DRS	RII:DRS	RII:DRS	RII:DRP	RII:EICS	RII:DRS	
SIGNATURE	/RA/	/RA/	/RA/	/RA/	/RA/	/RA K Kennedy for/	
NAME	Rodriquez	MacDonald	Nease	Musser	Evans	Croteau	
DATE	6/5/2009	6/8/2009	6/9/2009	6/12/2009	6/12/2009	6/16/2009	6/ /2009
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES

OFFICIAL RECORD COPY DOCUMENT NAME: S:\DRS\ENG BRANCH 2\BRU EDG LOCK-OUT CHOICE LETTER W-ENCL.DOC

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

U.S. NUCLEAR REGULATORY COMMISSION

REGION II

Docket No.: 05000325, 05000324

License No.: DPR-71 and DRP-62

Report No.: 05000325/2009009 and 05000324/2009009

Licensee: Progress Energy - Carolina Power and Light (CP&L)

Facility: Brunswick Steam Electric Plant, Units 1 & 2

Location: 8470 River Road SE
Southport, NC 28461

Dates: September 2008 – June 5, 2009

Inspectors: R. Rodriguez, Senior Reactor Inspector
G. MacDonald, Senior Reactor Analyst

Approved by: Rebecca L. Nease, Chief
Engineering Branch 2
Division of Reactor Safety

Enclosure 1

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

SUMMARY OF FINDINGS

IR 05000325, 324/2009-009; 9/2008-5/22/2009; Brunswick Steam Electric Plant; Units 1 & 2; Other Activities.

The report transmits the results of the NRC's preliminary assessment of the failure to correctly translate the design basis into Engineering Change (EC) 66274 to replace control relays on all four Emergency Diesel Generators (EDGs). One apparent violation with potentially low to moderate safety significance (White) was identified. Additionally, this finding is considered to have a cross-cutting aspect related to accurate design documentation [H.2(c)], as described in the resources component of the human performance cross-cutting area. The significance of most findings is indicated by its color (Green, White, Yellow, or Red) using Inspection Manual Chapter (IMC) 0609, "Significance Determination Process" (SDP). Findings for which the SDP does not apply may be Green or assigned a severity level after management review. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process."

Cornerstone: Mitigating Systems

TBD. An apparent violation of 10 CFR 50, Appendix B, Criterion III, Design Control, was identified for failure to correctly translate the design basis into EC 66274 to replace control relays on all four EDGs. Specifically, termination points for linking control power to the EDG lockout relay reset circuitry were incorrectly designated in the EC. This resulted in the wiring for control relays being installed such that the EDGs could not be operated locally as required by the Safe Shutdown Analysis Report. Upon discovery, the licensee initiated Action Request (AR) 292232 and re-wired and tested each affected EDG. The local control function was restored to all EDGs on August 21, 2008.

The failure to correctly translate the design basis into EC66274 is a performance deficiency. This finding is more than minor because it is associated with the reactor safety mitigating system cornerstone attribute of protection against external events, i.e., fire. It also affects the cornerstone objective of ensuring the availability of systems that respond to events in that the EDGs could not be operated locally as required by the Safe Shutdown Analysis Report. This finding was assessed using the applicable SDP, which resulted in a calculated core damage frequency (CDF) risk increase over the base case between 1E-5 and 1E-6 per year. The dominant accident sequences involved are initiated by a fire situated such as to cause both a loss of offsite power (LOOP) and a forced main control room evacuation. For these dominant accident sequences, the performance deficiency will result in a station blackout (SBO) to either or both units. The exposure period for this condition was one year. As a result, the finding was preliminarily determined to be a low to moderate safety significance (White). The cause of the finding is considered to have a cross-cutting aspect related to accurate design documentation [H.2(c)], as described in the resources component of the human performance cross-cutting area.

Enclosure 1

REPORT DETAILS

4. OTHER ACTIVITIES

4OA5 Other

(Opened) Apparent Violation (AV) 05000325, 324/2009009-001, Inability to Operate the EDGs Locally as Required by the Safe Shutdown Analysis Report

a. Inspection Scope

The inspectors conducted a review and significance evaluation of the licensee's inability to operate the EDGs locally after implementation of EC 66274.

b. Findings

Introduction. An apparent violation of 10 CFR 50, Appendix B, Criterion III, "Design Control", was identified for failure to correctly translate the design basis into EC 66274 to replace control relays on all four EDGs. Specifically, termination points for linking control power to the EDG lockout relay reset circuitry were incorrectly designated in EC 66274. This resulted in the wiring for control relays being installed such that the EDGs could not be operated locally as required by the Safe Shutdown Analysis Report. Upon discovery, the licensee re-wired and tested each affected EDG. The local control function was restored to all EDGs on August 21, 2008.

Description. On August 18, 2008, EDG #4 failed to start during surveillance test OPT-12.14.L, "DG4 Local Control Operability Test." The failure resulted from an inability to reset a lockout condition while the Alternative Safe Shutdown (ASSD) key switch was in the LOCAL position. Troubleshooting activities performed in response to this failure determined that this inability was due to the reset relay (LOCR) being configured (wired) such that it was isolated from control power when the ASSD key switch was operated. This configuration was the unintended consequence of EC 66274 under which it was installed in June 2007.

At the Brunswick Steam Electric Plant, the EDGs are considered a safe shutdown system and must be capable of being controlled from both the Control Room and a remote location. The EDGs are required to power the electrical distribution system upon loss of power from the balance of plant buses. The AC emergency power system is equipped with key-locked isolation switches located on the local EDG control panels and on each emergency bus section. These switches allow isolation of the EDGs and emergency buses from the control circuit conductors routed through the control building. In the event that a fire forces an evacuation of the main control room or in any way affects control of the diesel generators and emergency buses from the main control room, safe shutdown equipment can be operated locally by placing these NORMAL/LOCAL switches in the LOCAL position.

Enclosure 1

Upon identification of this condition, AR 292232 was initiated and EC 66274 was revised to correct the responsible design flaw (Revisions 5 and 6). Work activities were undertaken to implement the necessary configuration changes on all four EDGs. These modifications consisted of re-wiring the LOCR relays such that they do not lose power when the ASSD key switches are operated. All four EDGs were successfully modified, tested and returned to service on August 21, 2008.

As previously stated, this condition was discovered during surveillance test OPT-12.14.L which was performed a little over a year after EC 66274 was implemented. The inspectors reviewed and assessed the post-modification testing completed after the implementation of the EC to determine why the testing did not identify the inability of the EDGs to perform their alternate safe shutdown function. The inspectors concluded that the inadequate post-modification testing was not a cause of the event, but a missed opportunity to detect the inadequate design change. A conceptual design error was transferred from the design modification package (EC 66274) into the post-modification testing process which resulted in the post-modification test not identifying the wiring error. The inspectors concluded that the post-modification testing issue did not constitute a separate performance deficiency.

Analysis. The failure to correctly translate the design basis into EC 66274 is a performance deficiency. This finding is more than minor because it is associated with the reactor safety mitigating system cornerstone attribute of protection against external events, i.e., fire. It also affects the cornerstone objective of ensuring the availability of systems that respond to events, in that the EDGs could not be operated locally as required by the licensee's Safe Shutdown Analysis Report. In addition, this finding is considered to have a cross-cutting aspect related to accurate design documentation [H.2(c)], as described in the resources component of the human performance cross-cutting area. Specifically, the licensee did not ensure that complete, accurate and up-to-date design documentation was available to assure nuclear safety.

Because the finding affects fire protection, its significance was assessed in accordance with NRC IMC 0609, Appendix F, "Fire Protection Significance Determination Process." However, IMC 0308, Attachment 3, Appendix F, "Technical Basis for Fire Protection Significance Determination Process for at Power Operations," states that IMC 0609, Appendix F, does not currently include explicit treatment of fires in the main control room. Therefore, a Phase 3 analysis was performed using the applicable sections of IMC 0609, Appendix F and NUREG/CR-6850, "Fire PRA Methodology for Nuclear Power Facilities." The CDF risk increase over the base case was calculated to be between 1E-5 and 1E-6 per year. The dominant accident sequences involved are initiated by a fire situated such as to cause both a LOOP and a forced main control room evacuation. For these dominant accident sequences, the performance deficiency will result in a SBO to either or both units. The exposure period for this condition was one year. As a result, the finding was preliminarily determined to be a low to moderate safety significance (White). The preliminary Phase 3 SDP analysis is included as Enclosure 2.

Enclosure 1

Enforcement. Appendix B of 10 CFR 50, Criterion III, “Design Control,” requires, in part, that measures shall be established to assure that applicable regulatory requirements and the design basis are correctly translated into specifications, drawings, procedures and instructions. Section 9.5.1 of the Updated Final Safety Analysis Report states, in part, that the effects of fire on safe shutdown systems have been evaluated in the Safe Shutdown Analysis Report. The Safe Shutdown Analysis Report, Calculation BNP-E-9.004, states, “The AC Emergency Power System is equipped with key-locked isolation switches located on the local diesel generator electrical panel and on each emergency bus section. These switches allow isolation of the diesel generators and emergency buses from the control circuit conductors routed through the Control Building. In the event that a fire forces an evacuation of the Control Room or in any way affects control of the diesel generators and emergency buses from the Control Room, safe shutdown equipment can be operated locally by placing these NORMAL/LOCAL switches in the LOCAL position.”

Contrary to the above, on June 7, 2007, the licensee failed to correctly translate the design basis into specifications, drawings, procedures and instructions. Specifically, termination points for linking control power to the EDG lockout relay reset circuitry were incorrectly designated in EC 66274. This resulted in the wiring for control relays being installed such that the EDGs could not be operated locally. Upon discovery, the licensee initiated AR 292232 and re-wired and tested each affected EDG. The local control function was restored to all EDGs on August 21, 2008. URI 05000325, 324/2008010-001, which was opened during NRC Inspection Report 05000325, 324/2008010 is considered closed. Pending final significance determination, this finding is identified as Apparent Violation (AV) 05000325,324/2009009-01, Inability to Operate the EDGs Locally as Required by the Safe Shutdown Analysis Report.

40A6 Meetings, Including Exit

On May 28, 2009, the NRC presented the inspection results to Mr. Benjamin Waldrep who acknowledged the findings.

ATTACHMENT: SUPPLEMENTAL INFORMATION

Enclosure 1

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee Personnel

B. Waldrep, Vice President
M. Annacone, Director of Site Operations
P. Mentel, Manager of Site Support Services
T. Sherrill, Licensing
R. Rishel, Corporate PRA Supervisor
R. Isbell, Corporate PRA
B. McCabe, Corporate Licensing Supervisor
A. Pope, Recovery Manager
S. Hardy, Fire Protection

NRC Personnel

P. O'Bryan, Brunswick Senior Resident Inspector
J. Circle, Senior Reliability and Risk Analyst

LIST OF REPORT ITEMS

Opened

05000325, 324/2009009-01 AV Inability to Operate the EDGs Locally as Required by the Safe Shutdown Analysis Report. (Section 4OA5)

Closed

05000325, 324/2008010-01 URI Verify cable routing locations affected by a design change error which resulted in a loss of Emergency Diesel Generator local control function.

Discussed

None.

Attachment

DOCUMENTS REVIEWED

Procedures

0AOP-36.2, Station Blackout, Rev. 37
0ASSD-00, User's Guide, Rev. 35
0ASSD-01, Alternative Safe Shutdown Procedure Index, Rev. 31
0ASSD-02, Control Building, Rev. 43
1ASSD-03, Train B Shutdown, Rev. 26
2ASSD-03, Train B Shutdown, Rev. 22
2ASSD-05, Reactor Building North, Rev. 40
AOP-32.0, Plant Shutdown From Outside Control Room, Rev. 45

Drawings

Brunswick Nuclear Plant Units 1 & 2 Electrical Power Distribution System, 11/21/2007
F-02501, Reactor Building General Arrangement Plan Below Grade El. 7'-0", Rev. 28
F-02502, Reactor Building General Arrangement Plan El. 20'-0", Rev. 27
F-02503, Reactor Building General Arrangement Plan El. 50'-0", Rev. 22
F-07008, Units 1 & 2 Control Building General Arrangement Plans, Rev. 50
F-01926, Diesel Generator Building Plans, Rev. 19
F-34099, Control Building, Unit 1, Trays and Conduits Sections, Sh.2, Rev. 24
F-3409, Control Building, Unit 2, Trays and Conduits Sections, Sh.2, Rev. 20
F-3664, Control Building, Units 1 & 2, Tray Sections, Elevation 23'-0", Rev. 8
F-3544, Reactor Building, Unit 2, Trays and Conduits, Sections and Details, Sh.3, Rev. 10
F-3645, Reactor Building, Unit 2, Plan, Tray Installation, Elevation 20'-0" East, Rev. 10
F-03527, Reactor Building, Unit 2, Plan, Trays and Conduits, Elevation 20'-0" East, Rev. 84
F-03526, Reactor Building, Unit 2, Plan, Trays and Conduits, Elevation 20'-0" West, Rev. 79
F-03495, Control Building, Unit 2, Plan, Trays and Conduits, Elevation 23'-0", Rev. 29
F-34095, Control Building, Unit 1, Plan, Trays and Conduits, Elevation 23'-0", Rev. 29
F-07008, Units 1 & 2, Control Building General Arrangement Plans, Rev. 51
F-36043, Reactor Building, Unit 1, Plan, Tray Installation, Elevation 17'-0" East, Rev. 3
F-36044, Reactor Building, Unit 1, Plan, Tray Installation, Elevation 20'-0" West, Rev. 7
F-36045, Reactor Building, Unit 1, Plan, Tray Installation, Elevation 20'-0" East, Rev. 6
F-02501, Reactor Building General Arrangement Plan Below Grade Elevation 17'-0", Rev. 28
F-02502, Reactor Building General Arrangement Plan Grade Elevation 20'-0", Rev. 27
F-02503, Reactor Building General Arrangement Plan Grade Elevation 50'-0", Rev. 22
F-03493, Control Building Electrical Arrangement Elevation 23'-0" and 49'-0", Rev. 50
F-36034, Control Building, Unit 1, Plan, Tray Installation, Elevation 23'-0", Rev. 7
F-38007, Control Building, Unit 1, Conduit Plan RPS System, Elevation 23'-0", Rev. 5
F-03807, Control Building, Unit 2, Conduit Plan RPS System, Elevation, 23'-0", Rev. 12
F-03826, Control Building, Units 1 & 2, Conduit Plan, Elevation 38'-0", Rev. 43
F-3643, Reactor Building, Unit 2, Plan, Tray Installation, Elevation 17'-0", Rev. 3
F-3644, Reactor Building, Unit 2, Plan, Tray Installation, Elevation 20'-0", Rev. 11
F-3645, Reactor Building, Unit 2, Plan, Tray Installation, Elevation 20'-0", Rev. 10
F-3646, Reactor Building, Unit 2, Plan, Tray Installation, Elevation 50'-0", Rev. 2

Attachment

Calculations

BNP-0081, Availability of Offsite Power to Emergency Bus E4 in Fire Area DG-07, 9/11/2008

BNP-0082, Offsite Power Availability for Fire Area DG-05, Unit 2 and to Confirm that 2-EDG3 Will not Spuriously Start, 9/11/2008

BNP-0084, Cables and routing that could cause spurious Diesel Generator Lockout, 10/7/2008

BNP-0086, Availability of Offsite Power in East Yard for Fire in the DGB Roof Area, 10/6/2008

BNP-0088, Cable routing of cables that could cause a spurious EDG start and for cables that Would disable that offsite power feed to 1-E2 and 2-E4, 10/2/2008

BNP-0090, Document the Cables and Routing that Could Cause a Loss of Diesel Generators to supply E-buses, 11/24/2008

BNP-0091, Cables that are routed in trays in cable spreading room that could cause a start of Diesel Generator 4 (2-DG4-GEN), 10/17/2008

BNP-0092, Document the Results of Limited ARC Evaluation Used to Identify Cables in Fire Zones CB-05 and CB-06 that Could Start EDG4 in Support of AR 292232, 10/17/2008

BNP-0093, Document the Cable Routing in Conduit that Could Cause a Start of the Diesel Generator 4 in the Cable Spreading Room, 10/15/2008

BNP-0094, Document the Cables that are Routed in Trays in the Cable Spreading Room that Could Cause a Start of Diesel Generator 2, 10/23/2008

BNP-0095, Document the Results of Limited ARC Evaluation Used to Identify Cables in Fire Zones CB-05 and CB-06 that Could Start EDG2 in Support of AR 292232, 10/23/2008

BNP-0098, Hot Gas Layer Analysis for the Cable Spreading Rooms A & B and the Reactor Building North, 12/2/2008

BNP-0100, Document the Fire Areas that Require the Local Operation of the EDGs, 12/4/2008

BNP-E-9.004, Safe Shutdown Analysis Report, Rev. 7

Miscellaneous Documents

Design Basis Document DBD-39, Emergency Diesel Generator System, Rev. 7

UFSAR 9.5.1, Fire Protection System, Rev. 18C

Attachment