



DAVE BAXTER  
Vice President  
Oconee Nuclear Station

Duke Energy  
ON01VP / 7800 Rochester Highway  
Seneca, SC 29672

864-873-4460  
864-873-4208 fax  
dabaxter@dukeenergy.com

July 20, 2009

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Oconee Nuclear Station  
Docket No. 50-287  
Licensee Event Report 287/2009-02, Revision 0  
Problem Investigation Process No.: O-09-3845

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), attached is Licensee Event Report 287/2009-02, Revision 0, regarding a reactor trip on Unit 3 which occurred on May 21, 2009. This report is being submitted in accordance with 10 CFR 50.73 (a)(2)(iv)(A).

This event is considered to be of no significance with respect to the health and safety of the public.

Attachment 1 is the LER. Attachment 2 lists the three regulatory commitments contained in this report.

Any questions regarding the content of this report should be directed to Sandra Severance at 864-873-3466.

Sincerely,

Dave Baxter, Vice President  
Oconee Nuclear Station

Attachments

Document Control Desk

Date: July 20, 2009

Page 2

cc: Mr. Luis Reyes  
Administrator, Region II  
U.S. Nuclear Regulatory Commission  
61 Forsyth Street, S. W., Suite 23T85  
Atlanta, GA 30303

Mr. John Stang  
Project Manager  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Mail Stop O-8 G9A  
Washington, D.C. 20555

Mr. Eric Riggs  
NRC Senior Resident Inspector (Acting)  
Oconee Nuclear Station

INPO (Word File via E-mail)

# LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Oconee Nuclear Station, Unit 3	2. DOCKET NUMBER 05000 287	3. PAGE 1 OF 7
--	-------------------------------	-------------------

4. TITLE  
Unit 3 Trip Due to Generator Phase Differential Lockout

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
05	21	2009	2009	- 02 -	0	07	20	2009		05000
									FACILITY NAME	DOCKET NUMBER
										05000

9. OPERATING MODE  1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)																																				
10. POWER LEVEL  042	<table style="width:100%; border: none;"> <tr> <td><input type="checkbox"/> 20.2201(b)</td> <td><input type="checkbox"/> 20.2203(a)(3)(i)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(C)</td> <td><input type="checkbox"/> 50.73(a)(2)(vii)</td> </tr> <tr> <td><input type="checkbox"/> 20.2201(d)</td> <td><input type="checkbox"/> 20.2203(a)(3)(ii)</td> <td><input type="checkbox"/> 50.73(a)(2)(ii)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(viii)(A)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(1)</td> <td><input type="checkbox"/> 20.2203(a)(4)</td> <td><input type="checkbox"/> 50.73(a)(2)(ii)(B)</td> <td><input type="checkbox"/> 50.73(a)(2)(viii)(B)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(i)</td> <td><input type="checkbox"/> 50.36(c)(1)(i)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(iii)</td> <td><input type="checkbox"/> 50.73(a)(2)(ix)(A)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(ii)</td> <td><input type="checkbox"/> 50.36(c)(1)(ii)(A)</td> <td><input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(x)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(iii)</td> <td><input type="checkbox"/> 50.36(c)(2)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(A)</td> <td><input type="checkbox"/> 73.71(a)(4)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(iv)</td> <td><input type="checkbox"/> 50.46(a)(3)(ii)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(B)</td> <td><input type="checkbox"/> 73.71(a)(5)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(v)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(C)</td> <td><input type="checkbox"/> OTHER</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(vi)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(B)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(D)</td> <td>Specify in Abstract below or in NRC Form 366A</td> </tr> </table>	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)																																		
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)																																		
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)																																		
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)																																		
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)																																		
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)																																		
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)																																		
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER																																		
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A																																		

12. LICENSEE CONTACT FOR THIS LER

NAME S. N. Severance, Licensing Engineer	TELEPHONE NUMBER (Include Area Code) (864) 873-3466
---	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

At 2014 on May 21, 2009, Oconee Nuclear Station Unit 3 experienced a reactor trip as a result of a generator lockout while escalating power following a refueling outage. The X phase differential relay (device 87U) actuated because a relay tap setting was configured incorrectly due to personnel error. This generator lockout resulted in a Reactor Protection System (RPS) actuation due to an anticipatory trip. The RPS received a Loss of Main Turbine Anticipatory Trip Signal and tripped the Control Rod Drive (CRD) breakers. The unit responded as expected. The Emergency Operating Procedure (EOP) was entered, subsequent actions completed, and a transfer to the unit shutdown procedure was made without complication. There were no significant equipment failures. Appropriate post-trip reviews were performed and recovery actions completed per station procedures. The Unit 3 87U differential relays' tap block settings were corrected on all three phases. Unit 3 reached criticality on May 22, 2009, and power escalation resumed. This event is considered to have no significance with respect to the health and safety of the public.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 3	05000287	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 7	
		2009	02	- 0		

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

EVALUATION:

BACKGROUND

This event is reportable per 10CFR 50.73(a)(2)(iv)(A) because a valid Reactor Protective System (RPS)[JC] actuation occurred, including reactor trip.

Prior to this event Oconee Unit 3 was exiting a planned refueling outage. The unit was in Mode 1, and power was at 42%. No other safety systems or components were out of service and no evolutions were in progress that would have contributed to this event.

The relay involved in this event is an ABB HU-4 (device 87U)[87], a protective high speed unit-connected differential relay. There are three HU-4 relays on each Oconee unit which monitor X, Y, and Z phases of current from the generator. The HU-4 relay provides a trip output during the detection of a current differential on the current transformer circuits associated with the main generator, auxiliary transformer, and the two associated switchyard power circuit breakers (PCBs). When a current differential is detected, the relay sends a trip signal to the 86GA and 86GB generator lockout relays, resulting in both a generator and reactor trip.

On the HU-4 relay, taps are provided in the relay restraint and operating circuits to compensate for main current transformer mismatch. The proper tap settings are calculated, and then the relay is configured for the specific application. This relay has four restraint windings with the tap settings blocks on the front of the relay designated as 4, 1, 2, 3 (top to bottom). The HU-4 relays are a part of the original plant design.

EVENT DESCRIPTION

On May 21, 2009 at 2014 hours, Oconee Nuclear Station experienced a trip of Unit 3. The sequence of events, including subsequent equipment failures and operator actions during recovery, is described below.

- In-progress, post-outage power escalation was held at 42% power to resolve unassociated equipment issue.

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 3	05000287	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 7	
		2009	02	- 0		

**17. NARRATIVE** (If more space is required, use additional copies of NRC Form 366A)

- Anticipatory turbine trip due to a generator lock out relay actuation, X phase.
- Generator Differential Lockout annunciated on the Electro-Hydraulic Control (EHC) First Out Panel and the Sequence of Events Recorder (SER).
- The Reactor Protective System (RPS) received a Loss of Main Turbine Anticipatory Trip signal and tripped the Control Rod Drive (CRD) Breakers, as designed. All control rod drop times were within expected limits.

**Post-Trip Response:**

No safety systems actuated, other than the RPS.

On the primary side, Reactor Coolant Pumps [AB][P] continued to operate and provide core cooling. RCS pressure, temperature, flow, and inventory remained within expected post-trip limits.

Secondary response was normal. Turbine Bypass Valves controlled steam generator pressure. Secondary systems remained in service and provided heat removal capability, and shutdown to Mode 4 was not necessary. The Unit was maintained in Mode 3 while post-trip reviews were completed, the cause of the event was identified, and it was determined to be safe to return the unit to service. No significant equipment failures that would have contributed to the event were noted following the trip or during the recovery activities.

The ENS notification was made at 2309 hours on May 21, 2009 and assigned Event Number 45088. The reactor reached criticality on May 22, 2009 without further complication.

**CAUSAL FACTORS:**

The root cause of the Unit 3 reactor trip was incorrect 87U relay tap setting configuration following preventive maintenance (PM) activities during the scheduled refueling outage. During the performance of the calibration PM on the protective Unit 3 main relays, the lead Duke Maintenance technician performing the PM made

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 3	05000287	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4	OF 7
		2009	02	- 0		

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

a decision to change the tap settings from the as-found setting. He noted that the as-found tap settings did not match the labeling on the relay card, but he reasoned that the relay card provided tap setting values and was not an accurate physical representation of the relay. He recognized that the as-left settings were not the same as the as-found settings, but he rationalized that the as-left tap settings from the previous PM were incorrect. The technician made this decision without stopping and verifying with Maintenance technical support, supervision, or Engineering. Changing the tap settings to different values caused the relay to actuate, resulting in a generator lockout which in turn caused the reactor trip.

The lead technician had performed this task multiple times in the past without error, even having performed the prior Unit 3 87U relay PM in 2006. The technicians did stop and discuss the difference, but they did not contact technical support or engineering. The technicians did not use appropriate self-checking to ensure that their intended actions were correct.

Other factors contributing to this event were procedural inadequacies, technical inadequacies, and configuration control weaknesses. No technical procedure existed for the calibration activity for the HU-4 type relay (87U). Although the need for a procedure had been identified, the request received a low priority based on the fact that the task was non-safety related and had been performed error free for numerous years. Additionally, the HU-4 relay card, used as a record for the relay settings, was unclear and misleading. The HU-4 relay has four restraint windings with the tap setting blocks arranged 4, 1, 2, and 3 top to bottom. However, the relay card was written as winding 1, 2, 3, and 4. The intent of the card was for the doer to position the settings "top to bottom"; however, in this occurrence, the information on the card was interpreted as being for the corresponding winding numbers. Meaning, the winding 1 setting on the card was for winding 1 on the relay as opposed to the winding 1 setting on the card (top winding) being for winding 4 on the relay (top winding).

This event also highlighted an organizational weakness within Maintenance with regard to configuration control of equipment. Equipment removal from and return to service is controlled in the configuration control procedure. Once the equipment has been isolated, inadequate procedural guidance exists to ensure that

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 3	05000287	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 7	
		2009	02	- 0		

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

parameter or setting changes implemented while equipment is out of service are appropriately documented prior to its return to service.

CORRECTIVE ACTIONS

Immediate:

- 1) Entered Emergency Operating Procedure (EOP) (EP/3/A/1800/001). Immediate manual actions were taken as prescribed by the EOP to place (and/or maintain) the plant in a safe and stable operating condition as quickly as possible.
- 2) Formed a Unit Threat Team.
- 3) Downloaded and reviewed Voltage Regulator data logger and concluded no fault current was being generated out of the generator at the time of the trip.
- 4) Reviewed auxiliary transformer 3T parameters with no anomalies noted.
- 5) Checked as-found tap settings on the unit differential relay (87U). Found two out of four set incorrectly.

Subsequent:

- 1) Used IP/0/A/0101/001 Maintenance Configuration Control Procedure to verify the relay taps were placed back in the correct position on all three phases of the Unit 3 87U differential relays.
- 2) Performed testing of relay on correct tap settings to ensure that it would not trip up to full load power.
- 3) Verified HU-4 tap settings for the X, Y, and Z phases on Units 1, 2, and 3 set correctly.
- 4) Verified HU and HU-1 relays used for Unit 3 transformer set correctly.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Oconee Nuclear Station, Unit 3	05000287	2009	02	0	6	OF 7

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

5) Performed Maintenance Management counseling for individuals involved in this event. Personnel corrective actions taken commensurate with each individual's culpability and the significance of the inappropriate action.

Planned:

- 1) Develop an IP procedure for the HU-4 relay calibration PM. Procedure should include as-found and as-left steps for tap settings.
- 2) Identify all protective relays that need to have tap settings added to the equipment database (EDB) in order to eliminate relay cards. Once the relays have been identified, initiate the appropriate documentation and corrective actions for the relay additions.
- 3) Identify all protective relay calibration PMs that do not have dedicated procedures. Prioritize and create additional corrective actions to develop the procedures.

See Attachment 2 for NRC Commitment items. There are no other NRC Commitment items contained in this LER.

SAFETY ANALYSIS

This event did not include a Safety System Functional Failure. The event was uncomplicated and challenged no accident mitigation systems.

Duke Energy used a risk-informed approach to determine the risk significance associated with this event, considering the following:

- A reactor trip initiating event.
- Actual plant configuration and maintenance activities at the time of the trip.

The Conditional Core Damage Probability (CCDP) associated with this event was evaluated to be less than 1E-06. The Conditional Large Early Release Probability (CLERP) associated with this event was evaluated to be < 1.0E-7.

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 3	05000287	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	7 OF 7	
		2009	02	- 0		

**17. NARRATIVE** (If more space is required, use additional copies of NRC Form 366A)

No fission product barriers were compromised by this event. Therefore, there was no actual impact on the health and safety of the public due to this event.

**ADDITIONAL INFORMATION**

A search of Oconee's corrective action database found no similar occurrences of this type of event with the same cause.

There were no releases of radioactive materials, radiation exposures or personnel injuries associated with this event.

This event is not considered reportable under the Equipment Performance and Information Exchange (EPIX) program.

**Attachment 2**  
**Oconee Nuclear Station**  
**LER 2009-02, Unit 3 Trip**  
**List of Commitments**

<b>Commitment</b>	<b>Commitment Date or Outage</b>
Develop an IP procedure for the HU-4 relay calibration PM. Procedure should include as-found and as-left steps for tap settings.	Prior to 1EOC25, Fall 2009
Identify all protective relay calibration PMs that do not have dedicated procedures.	September 2009
For protective relay PMs which do not have procedures, place Work Orders on hold until procedures are developed.	October 2009