NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201	U.S. NUCLEAR REGULATORY COMMISSION				
	AND COMPLIANCE INCRECTION				
1. LICENSEE/LOCATION INSPECTED;	T AND COMPLIANCE INSPECTION				
Patriot Engweering	2. NRC/REGIONAL OFFICE				
1359 N. ABERDEEN AGE	U.S. Nuclear Regulatory Commission Region III				
TERRE HAUTE IN 47804	IN 47809 Suite 210				
REPORT NUMBER(S) 2009/001	Lisle, Illinois 60532-4351				
3. DOCKET NUMBER(S) 4. LICENSEE NO. 30 - 378 78 13 - 82 72	· '				
030-23-378-78 13-82-72 LICENSEE:	5-01 8/26/09				
The inspection was an examination of the activities cond to compliance with the Nuclear Regulatory Commission (
2. Previous violation(s) closed.	50 .				
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	or as non-cited violations, are not being cited because they were self-				
identified, non-repetitive, and corrective action was or is being 1600, to exercise discretion, were satisfied.	taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-				
Non-Cited Violation(s) was/were discuss	ed involving the following requirement(s) and Corrective Action(s):				
1	at				
*					
Į.					
4. During this inspection certain of your activities, as described	below and/or attached, were in violation of NRC requirements and are being				
cited. This form is a NOTICE OF VIOLATION, which may be su (Violations and Corrective Actions)	Dject to posting in accordance with 10 CFH 19.11.				
**					
Licensee's Statement of Cor	rective Actions for Item 4, above.				
I hereby state that, within 30 days, the actions described by me to the corrective actions is made in accordance with the requirements of 10 CF date when full compliance will be achieved). I understand that no furth	inspector will be taken to correct the violations identified. This statement of R 2.201 (corrective steps already taken, corrective steps which will be taken er written response to NRC will be required, unless specifically requested.				
Title Printed Name LICENSEE'S	Signature Date				
REPRESENTATIVE					
NRC INSPECTOR E.L. KOLZER	EL Kuly 845/09				
NRC FORM 591M PART 1 (10-2003)	0				

NRC FORM 591M (10-2003) 10 CFR 2 201	PART 3	Docket File	Information	U.S. NUCLEAR REGULATORY COMMISSION
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
1. LICENSEE		2. NRC/REGIONAL OFFICE		
Patriot Engineering and Environmental REPORT 2009-001 NUMBER(S)		Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532		
3. DOCKET NUMBER(S) 030-37878		4. LICENSE NUMBER(S) 13-32725-01		5. DATE(S) OF INSPECTION 8/26/2009
6. INSPECTION PROCEDU 87124	JRES USED	7. INSPECTION FOCUS AREAS 03.01-03.07		
SUPPLEMENTAL INSPECTION INFORMATION				
1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICEN John Phillips	NSEE CONTACT	4. TELEPHONE NUMBER 812.466.5559
X Ma	ain Office Inspection	n Next Inspection Date: 8/2014		
Field Office				-
Temporary Job Site Inspection				

PROGRAM SCOPE

The licensee is an engineering firm that has five locations in Indiana. The company's main office is in Terre Haute, Indiana. The licensee possesses nine Seaman moisture density gauges (Radium-226) for use daily/weekly during the construction season (May-November) for soils engineering projects at the Terre Haute location. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer. Currently, the licensee employs seven authorized gauge users who have completed manufacturers training. The gauges are stored in a room in the licensee's office in Terre Haute, Indiana.

Performance Observations

At the time of this inspection, the gauges were not in use at a job site in Edwardsport, Indiana which was one and a half hours south of the office. The inspector asked an authorized user to demonstrate the handling and transport of the gauge. The authorized user possessed required shipping papers which contained all appropriate information and were accessible in the transport vehicle. Gauge/case were locked and chained to the rear of the vehicle during transport. The operator demonstrated an adequate level of understanding of emergency and handling procedures. Security during transport and at the job-site was described with no problems noted. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.

